



SDD Series Digital Dosing Additive Feeders

Part Number: 882.00276.00
Bulletin Number: BF3-600.2
Effective: 11/01/06

Write Down Your Serial Numbers Here For Future Reference:

_____	_____
_____	_____
_____	_____

We are committed to a continuing program of product improvement. Specifications, appearance, and dimensions described in this manual are subject to change without notice.

DCN No. _____

© Copyright 2006
All rights reserved.

Table of Contents

SECTION 1: INTRODUCTION	3
1.1 C150 Controller.....	5
1.2 Keys and Symbols	6
SECTION 2: QUICK START-UP.....	8
BASIC INPUT PARAMETERS – INJECTION MOLDING.....	12
BASIC INPUT PARAMETERS – EXTRUSION.....	16
SECTION 3: INITIAL INSTALLATION AND OPERATION	20
3.1 Initial Installation	20
3.2 Initial Operation	23
3.3 Injection Molding.....	24
3.4 Extrusion - Constant.....	29
3.5 Extrusion - Proportional (Extruder tracking, or follower)	34
3.6 Calibration	38
SECTION 4: ADVANCED OPERATIONS/CONTROL FUNCTIONS.....	41
4.1 Recipe Storage/Recall.....	41
4.2 Clearing the Totalizer	43
4.3 Acknowledging Alarms	43
4.4 Optional Equipment	44
SECTION 5: MAINTENANCE.....	46
5.1 Maintenance Intervals	46
5.2 Removing the Shear Plate (DD feeder only).....	46
5.3 Cleaning the “DD” Dosing Station.....	47
5.4 Changing the Dosing Disc in the “DT” Dosing Station	49
5.5 Removing/Replacing the Wiper in the “DT” Dosing Station	50
5.6 Cleaning the “DT” Dosing Station	49
5.7 Exchangeable Stations	52
5.8 Changing Fuses	53
APPENDIX A: TROUBLESHOOTING.....	54
A.1 General Troubleshooting.....	54
A.2 Malfunctions — Error Codes	54
A.3 Determining the Software Setup Factor	56
A.4 Recipe Formulas	56
APPENDIX B: BASIC PARAMETER SETTINGS.....	58
APPENDIX C: DISC DOSING FACTORS, DRAWINGS AND PARTS NUMBERS.....	63
APPENDIX D: SPARE PARTS LIST.....	76
APPENDIX E: Technical Assistance.....	79

Section 1: Introduction

This User's Manual is intended for use with the Digital Dosing Disc Additive Feeder. The feeder precisely meters and controls the addition of master batches, chemical additives, and regrinds to primary plastics. The Digital Dosing unit can meter both powder and granular material of various sizes. It can be used on extrusion, blow molding and injection molding machines. Depending on the application and throughput, two models are available: Single Station Digital Dosing Unit or Dual Station Digital Dosing Unit. See Figures 1 and 2. This manual covers the operation of both units.



***Figure 1. Single Station Digital Dosing Unit
(Shown with optional virgin supply hopper and controller mounting plate)***



***Figure 2. Dual Station Digital Dosing Unit
(Shown with optional virgin supply hopper and controller mounting plate)***

1.1 Controller

The Digital Dosing additive feeder consists of a controller(s), dosing motor(s), and feeder(s). The controller is used to:

- Configure the unit to the desired process.
- Calibrate the feeder
- Run, monitor, and stop the dosing process
- Enter, recall, and run recipes
- Troubleshoot problems via error codes

A keypad and LED display (see Figure 3) are used to enter, or change, data.

- The control system is switched on (position "1") with the On/Off switch. (A)
- The control system is operated through the keypad. (B)
- The individual operating modes are indicated by symbols. (C)
- Messages appear on a 5-digit LED display. (D)




Figure 3. Keypad and LED Display

1.2 Keys and Symbols



Recipe Storage/Recall: For saving, recalling or modifying recipes.



Stop: Stops the continuous operation of the feeder. Will reset the totalizer showing metered amount of additive to zero if depressed for two seconds.



Up-arrow: For increasing the set value in decimal increments.




Down-arrow: For decreasing the set value in decimal increments.




Arrow Key: For fast increasing/decreasing of the set value in larger increments. Must be pressed simultaneously with the up- or down-arrow.



Run: Starts the continuous operation (LED is lit up) or calibration mode (LED flashes)




Calibration Key: Switches from operation to calibration mode. LED flashes when calibration process has started.



Input: Selects the next screen for the input of program parameters.

Symbols



Lights when the run signal from the process machine is received by the Digital Dosing controller.



During operation, lights when the disc is dosing material. During calibration and recipe input/viewing, lights when a calibration weight is input or viewed.



(EXTRUSION ONLY) Lights when a screw speed signal is received from the extruder during proportional extrusion control (tracking, or following)



Lights when an alarm occurs.




Percent additive



Kilograms



Grams



Pounds



Minutes



Seconds

Section 2: Quick Start-up

Quick Start is intended to help you in starting up your Digital Dosing feeder quickly and easily. Please refer to the manual to go into greater detail.




Unpacking:

1. Unpack box, making sure all parts indicated on packing list are included.
2. Check all parts and equipment for any damage sustained during shipment.
3. If any damage is noted, contact manufacturer for replacement or service.
4. Make sure the following are present before proceeding:
 - Power source 110 or 220 volt, single phase, 50 or 60 hertz (verify voltage on Serial Number tag)
 - Proper mounting flange adapter for the feed throat
 - Dry (ZERO VOLTAGE) contact that closes during screw recovery of IMM
 - Gram scale to measure weight of additive material for calibration.

Mounting:

1. Mount the complete unit, including dosing hopper full of material, on the feed throat (may need an adapter for feed throat).
2. Identify the motor drive connector ("Amp" connector-black) and connect to motor.
3. Identify the communication cable (DB-9 plug-silver) and connect to DB-9 connector under motor drive assembly.
4. Identify power cord and plug into appropriate outlet.
5. **INJECTION MOLDING:** Identify the cycle/run cable (2-conductor cable-gray) for connection to a dry (ZERO VOLTAGE) contact that closes during the screw recovery cycle of the molding machine.
6. **EXTRUSION:** Identify the input cable (2-conductor cable-gray) for connection to 0-10 VDC or 0-20 mA signal that indicates speed (rpm) of the extruder.

Recipe Setup for Injection Molding:

1. Turn power switch to ON position.
2. Press Input  to display # 1, “Additive %”. Using arrow keys, set additive ratio.
3. Press Input  to display #2, “Shot size of current mold”. Using arrow keys, set the total shot size (parts and runners) of the current mold capacity in grams/pounds.
4. Press Input  to display # 3, “Screw recovery time”. Using arrow keys, set the screw recovery time (in seconds).
5. Press Input to display # 4, “Calibration weight for additive”. Enter the appropriate value from the range table below and proceed to calibration mode below for calibration of additive material.

DD Discs

Disc	Calibration Number Range
DD 30-030672	1.75
DD 30-051040	5.00
DD 30-051725	8.00
DD 30-051818	15.00




DT Discs

Disc	Calibration Number Range
DT 30-101820	32.00
DT 30-102025	38.00
DT 30-203012	100.00
DT 30-204010	175.00

DP Discs

Disc	Calibration Number Range
DP 30-050940	17.00
DP 30-250940	8.00






Recipe Setup for Extrusion:

1. Turn power switch to ON position.
2. Press  Input to display # 1, “Additive %”. Using arrow keys, set additive ratio.
3. Press  Input to display # 2, “Throughput of extruder”. Using arrow keys, set the total extruder throughput in g/min or lb/min.
4. Press  Input to display # 3, “Extruder screw speed”. Using arrow keys, set the extruder screw speed RPM expected during production.

NOTE: For Extrusion - Constant operation, the above step will be skipped.

5. Press Input to display # 4, “Calibration weight for additive”. Enter the appropriate value from the range table on page 9 and proceed to calibration mode below for calibration of additive material.


Calibration:

1. Press  “Calibration” button to start this procedure. Display will show - - - -
2. Place the plastic calibration cup on the scale and tare so that the weight of the cup (approx. 24 grams) is not calculated in the calibration procedure.
3. Remove cover of the calibration box, secured by two 5 mm Allen screws, under the dosing disc assembly and insert plastic cup provided in top of dosing hopper.
4. Press  “Run” and the dosing disc turns 1/4 turn. This fills all pockets of dosing disc. Dump the dosed material back into the dosing hopper without weighing and replace plastic cup in calibration box.
5. Press  “Run” and the dosing disc turns 1 complete revolution. Remove the calibration cup with the material and place on the gram scale. Enter the weight on the scale into the controller   using the arrow keys. Empty and replace calibration cup.
6. Repeat step # 5 four more times, each time entering the new weight from the scale into the controller using the arrow keys. Sometimes the values won’t change, or sometimes they may only change by a few tenths of a gram. The controller keeps a running average of all calibration weights entered.

7. After all five samples have been completed; press “run” once more and this will save the calibration weight of the material to the recipe. The calibration light will go out and the screen will now show the total amount of additive dosed. The Digital Dosing feeder is now ready to begin operation.
8. Please refer to “Operation Manual” for all supplementary information regarding general operation, cleaning/maintenance, and troubleshooting.
9. Make sure that there is a virgin material supply setup to begin processing. If you do not have a loader or hopper for the virgin material, or if any of the above procedures did not work properly, please contact **ACS Technical Support @ (800) 423-3183 (8 AM - 5 PM) CST.**

Basic Input Parameters for Digital Dosing Feeder with Injection Software (P1._ _ - Older units) or (P2._ _ - newer units)

Hold **Stop** and **Input** buttons until “7” flashes




- Enter the input number for the specific motor from the table below.
- This value sets the impulses of the encoder.

Manufacturer	Motor Color	RPM	Input Number
Bauer	Blue	6.4	11739
Bauer	Blue	11.5	6600
Bauer	Blue	35.5	2135
Bison	Black	2	65000
Bison	Black	6	25200
Bison	Black	12	14103
Bison	Black	38	4387



Press **Input** button

- When “8” flashes, enter **0.7** for Blue Bauer motor.
- Or, enter **0.5** for the black Bison or Colorblend S motor.
- This value sets the nominal current for the motor.



Press **Input** button

-When “9” flashes, enter the configuration value.

- Please see the list: “Determining Configuration Value” for more information.



Press **Input** button

- When “10” flashes, enter 1 if a blue Bauer motor is intended for use.

- If any another motor is intended for use, enter 0.




Press **Input** button

- When “11” flashes, enter **50**
- This value is the minimum input frequency.



Press **Input** button

- When “12” flashes, enter **5.56**
- This value is the span factor.




Press **Input** button

- When “13” flashes, enter the communication address.
- If Euromap17 is not intended to for use, enter 0.
- This value is the communication address. Only enter a value here if Euromap17 report is in use.



Press **Input** button

- When “14” flashes, enter **220**
- This value is for the material contents of the mixing hopper.
- Only in case of mounting on a micro mixing-hopper.



Press **Stop** to exit parameters, “18” will flash, then it automatically returns to the totalizer screen



Basic Input Parameters for Colorblend C-150 with Extrusion Software (E1.__ - Older units) or (E2.__ - newer units)

Hold **Stop** and **Input** buttons until “7” flashes




- Enter the input number for the specific motor from the table below.
- This value sets the impulses of the encoder.

Manufacturer	Motor Color	RPM	Input Number
Bauer	Blue	6.4	11739
Bauer	Blue	11.5	6600
Bauer	Blue	35.5	2135
Bison	Black	2	65000
Bison	Black	6	25200
Bison	Black	12	14103
Bison	Black	38	4387



Press **Input** button

- When “8” flashes, enter **0.7** for blue Bauer motor.
- Or, enter **0.5** for the black Bison or Colorblend S motor.
- This value sets the nominal current for the motor.



Press **Input** button

- When “9” flashes, enter the configuration value.
- Please see the list: “Determining Configuration Value” for more information.



Press **Input** button

- When “10” flashes, enter **1** if a blue Bauer motor is intended for use.
- If any another motor is intended for use, enter **0**.




Press **Input** button

- When “11” flashes, enter **50**
- This value is the minimum input frequency.



Press **Input** button

- When “12” flashes, enter **10**
- This value is the span factor.



Press **Input** button

- When “13” flashes, enter the communication address.
- If Euromap17 is not intended to for use, enter 0.
- This value is the communication address. Only enter a value here if Euromap17 report is in use.



Press **Input** button

- When "14" flashes, enter **220**
- This value is for the material content of the mixing hopper.
- Only in case of mounting on a micro mixing-hopper.



Press **Stop** to exit parameters, "18" will flash, then it automatically returns to the totalizer screen.



Section 3: Initial Installation and Operation

3.1 Initial Installation





Figure 4. Digital Dosing Unit Assembly

1. The Digital Dosing additive feeder is not affected by machine vibration, therefore best performance is achieved by mounting the unit directly to the feed throat of the molding machine or extruder (see Figure 4). The inlet into the process machine must be greater than 2" diameter; otherwise, an adapter might be necessary. If an adapter is necessary, it must be designed so that there are no edges where material can be trapped. The adapter must be smooth to promote even material flow. Consult factory for any special requirements.
2. Optimum mounting of the Digital Dosing feeder is shown in Figure 4, with the additive being dosed on the first screw flights.
3. The controller can be mounted on either side of the blender base to optimize operator interface. An optional remote mounting kit for the controller is available from the manufacturer to relocate the controller closer to the operator. The control unit must not be exposed to extreme heat (maximum temperature 45°C or 115°F) or excessive moisture.

4. Electrical connection to process machine:

- **Injection Molding:** Connect the cycle/run slave cable (thin two-conductor cable) to a set of DRY (NO VOLTAGE) contacts that CLOSE for the duration of screw recovery. See Figure 5, electrical diagram.



(Electrical diagram of connections)


Figure 5. Electrical Diagram

- **Extrusion - Constant:** Wire the cycle/run slave cable (thin two- conductor cable) to a set of DRY (NO VOLTAGE) contacts that CLOSE when the screw rotates. See Figure 5 for electrical diagram.
- **Extrusion - Proportional:** Wire the cycle/run slave cable to the extruder signal output that is proportional to the extruder speed. The signal output can be one of the following: 0-10 VDC or 0-20 mA. *Please refer to the labels on the cycle/run slave cable for the correct input to avoid damaging the controller.* Digital Dosing Additive Feeder should be configured from the factory for each specific input. See Figure 6 for analog inputs.

NOTE: *Voltage from Extruder needs to be isolated. Consult factory for other signal requirements. External signal converter may be required.*

NOTE: *Zero input corresponds to zero screw speed and no additive dosing. Maximum input corresponds to maximum screw speed.*

NOTE: *If a 0-10 kHz frequency input is used, it must be a square wave width and an amplitude of 12 VDC. The shape of the signal is important, especially above 7,000 Hz.*



(diagram of analog inputs)

Figure 6. Analog Inputs

5. Make sure the unit is turned OFF before plugging it in. The switch toward the rear of the controller unit should be in the OFF, or “O” position. Standard operation voltage is 110 or 220 VAC, 50/60 Hz, single-phase power. Special voltages are available, refer to voltage label on the feeder to determine the correct operating voltage.

Extruder Follower Interface Signal Converter

Isolating power sources and sensor signals is the most effective method for eliminating undesirable ground loop currents and induced electrical noise.

To determine the correct signal convert to use:

- Define whether a current (mA) or voltage (dc) signal from the extruder is available to utilize.
- The range should be either be 0-20 mA or 0-10 VDC, respectively.
- The controller has no specific requirement other than the signal being isolated and proportional to the speed of the extruder.

Signal Converter with AC Power Supply

Vendor: Phoenix Contact
 Order Designation: MCR-FL-C-UI-UI-DCI-24/230
 Supply Voltage: 20V to 253V AC/DC
 Input 4-20 mA, 0-10 VDC (Quantity: 1)
 Output 0-20 mA, 0-10 VDC (Quantity: 1)

Signal Converter with DC Power Supply

This module requires a separate 24 VDC power supply.

Vendor: Phoenix Contact
Order Designation: MCR-FL-C-UI-2UI-DCI-NC
Supply Voltage: 20 to 30V DC
Input 4-20 mA, 0-10V (Quantity: 1)
Output 0-20 mA, 0-10V (Quantity: 2)

24 VDC Mini Power Supply

A Phoenix Contact power supply for the Phoenix Contact signal conditioner listed above.

Vendor: Phoenix Contact
Order Designation: MINI-PS-100-240AC/24DC/1

Please note that the data given here has been taken from Phoenix Contact's online catalog. For comprehensive information and data, please refer to the user documentation at <http://www.download.phoenixcontact.com>.

3.2 Initial Operation

The control system is factory-programmed. Nevertheless, specific values need to be predefined or checked prior to operation (basic parameter settings). The input values will be saved and will still be available if the unit is switched off, or a power failure occurs. Please refer to Appendix B for these values. **Extrusion operations require a “span factor” to be entered into the basic settings.** Please refer to Appendix B.

Prior to putting your new Digital Dosing Additive Feeder on-line:

- You must enter a recipe and calibrate the feeder.
- Recipe parameters are different for Injection Molding, Extrusion - Constant, and Extrusion - Proportional operation. See each individual section for details.
- The calibration method is the same for all processes.
- Once the unit is online, recipes can be saved for later recall (10 maximum).

- This section will show how to calibrate the unit, bring the unit on line, enter a recipe, and store and recall recipes.



3.3 Injection Molding





During each molding cycle the Digital Dosing unit doses the correct amount of additive evenly throughout the screw recovery cycle. The Digital Dosing unit determines the correct amount of additive from the recipe and automatically adjusts the duration and speed of dosing by measuring the molding machine screw recovery time each cycle.

Recipe Input - Injection Molding



To enter a recipe for injection molding, the following process data is required:


- Percentage of additive
- Total shot weight in grams (includes parts and runner system)
- Screw recovery time of the machine in seconds
- Calibration weight in grams
- Step 1:

Press key	LED display	display
		"1" parts of the additive (colouring) in %


- Press Input  once.
 - The LED symbol % flashes.
 - "1" will quickly flash on the display, before a number in the format xxx.xx comes up on the display.
 - Enter the additive percentage by using the Arrow Keys   .
- (The range of values that can be entered is 0.01% to 50.00%. The arrow keys are used to change all process variables. The double arrow key allows the user to ramp up or down by larger increments.)

Step 2:


Press key	LED display	display
		"2" = shot weight in g or lb respectively

- Press Input  again.
- The symbols "g," or "lb", "min" and the screw symbol flash.
- After the "2" quickly flashes on the display, a number in the format xx.xxx will come up on the display.
- Enter the shot weight using the arrow keys. The range of values that can be entered is 001.0 to 6500 grams (0.01 to 14.30 pounds).

Step 3:

Press key	LED display	display
		



"3" = screw recovery time in seconds

- Press Input  a third time.
- The **screw** and "s" symbols flash.
- After "3" flashes quickly on the display, a number in the format xxx.xx will come up on the display.
- Enter the screw recovery time in seconds. This time represents the amount of time the molding machine screw is in recovery. **This value is an estimate.** The Digital Dosing unit measures the actual recovery time and automatically updates this value during operation. **NOTE: The range of values that can be entered in this field is 2.00 to 99.99 seconds.**

Step 4:



Press key	LED display	display
		“ 4 “ = calibration weight in grams or pounds




- Press Input  a fourth time.
- The symbols “g” or “lb” and  flash.
- After “4” quickly flashes on the screen, a number in the format xxxx.x will come up on the display.
- Enter the calibration weight in grams. **If the calibration weight is unknown, enter “valve” from (section 5.7 knowing you Disc size) to obtain a starting weight.**
- The range of values that can be entered in this field is 00.0 to 400.0.




Please note: Parameters 5 and 6 will only be displayed when a mixer and or a printer is configured.


Step 5:

Press key	LED display	display
		“5” maintained running time of the blending unit in seconds



- Press  again and the symbol “s” will light up and the number “5” will be displayed **if you have a blending unit and have invoked this option.**
- After “5” flashes on the display, a number in the format xxx.xx will come up on the display.
- Enter the maintained running time of the blending unit in seconds using the arrow keys. This is how long the blender will run after each dosing cycle and should be adjusted for the best possible blend. Too little time may not produce good dispersion; too much time can cause separation, especially with heavy concentrates.


Step 6:

Press key	LED display	display
		*6" printer Only if a printer (optional) is available
 		enter printer parameters 0 = no printing 1 = printing setpoints 2 = printing parameters 3 = page change 4 = printing each event 5 = printing alarms



- Pressing  again, will activate the printing option **if it is available**.
- After the “6” flashes on the screen, a number in the format xxx.xx will come up on the display.
- By using the arrow keys, you can choose your printer parameters.









Step 7:



Press key	LED display	display
		total throughput in kg

1. Pressing  again will first display the number “18” and then will display the total throughput in kilograms (totalizer).



Operation - Injection Molding

1. Ensure that the unit is properly installed (Section 3.1), a recipe is entered (section 3.3.1), and the feeder is calibrated (Section 3.6), before attempting to begin operation.
2. If desired, clear the totalizer by holding the Stop key () continuously for five seconds until the display is reset to "00.00."
3. Place the Digital Dosing feeder into operation by pressing the Run key ().
The green LED will light when the unit is ready to dose.

Press key	LED display	display
		totalizer
		throughput
		rotational speed of the dosing motor
		nominal current of the motor in %

Start the molding machine. The Digital Dosing feeder will not dose material until the molding machine screw recovers. If the unit is installed properly, the process machine symbol  will light on the controller during screw recovery. The disc symbol  will light when the Digital Dosing unit is dosing material.

- The totalizer will increase after each cycle by the amount of material dosed.

- To stop the dosing process, press .
- While the unit is dosing, the current recipe can be viewed, but not modified by pressing . The recovery time displayed in the current recipe is the average of the last five shots measured from the molding machine. To change the recipe, the unit must be taken off line by pressing the stop key. The run LED will then go out.

NOTE: See Appendix A, Troubleshooting, for information on problems or errors encountered and their resolution.



3.4 Extrusion – Constant (Standard)


In Extrusion Constant operation, the Digital Dosing unit doses material at a constant rate that does not change with extruder speed. The dosing process begins at the startup of the extruder. How close the actual extruder speed is to the input recipe will determine the accuracy of the blend. **If the process requires the additive to be dosed in proportion to the process speed, then the Digital Dosing unit must be configured for Extrusion Proportional operation (go to Section 3.5).**




Recipe Input – Extrusion - Constant

To enter a recipe for Extrusion Constant, the following process data is required:



- Percentage of additive
- Total throughput rate of the extruder during production
- Calibration weight in grams
- Step 1:



Press key	LED display	display
		"1" parts of the additive (colouring) in %

- Press  once.
- The % symbol will flash.
- After "1" flashes on the screen, a number in the format xxx.xx will come up on the display.

- Enter the additive percentage by using the Arrow Keys   . The range of values that can be entered is 0.01 to 50.00%. The arrow keys are used to change all process variables. The double arrow key allows the user to ramp up or down at a faster rate.



Step 2:



Press key	LED display	display
		"2" throughput of the extruder in g/min or lb/min

- Press  again.
- The symbols "g," or "lb," "min", and  flash.
- After "2" flashes quickly on the display, a number in the format xxx.xx will come up on the display.
- Enter the total extruder throughput in grams per minute or pounds per minute. The range of values that can be entered is 001.0 to 6500 grams per minute (00.01 to 14.30 lb/m).

Extrusion Constant, parameter "3" is skipped.



Step 3:


Press key	LED display	display
		"4" = calibration weight in grams or pounds

- Press  a third time.
- The machine displays a flashing , "g" or "lb" and a number "4" flashes on the display
- After the "4" flashes on the display, a number in the format xxxx.x will come up.
- Enter the calibration weight in grams. **If the calibration weight is unknown, enter the appropriate "value" from Section 2, based on your disc size, to obtain a starting weight.**
- The range of values that can be entered in this field is 00.00 to 400.0.




Note: Parameters 5 and 6 will only be displayed when a mixer and or a printer is configured.


Step 4:

Press key	LED display	display
		"5" maintained running time of the blending unit in seconds



- Press  again and the symbol "s" will light up and the number "5" will be displayed **if you have a blending unit and have invoked this option.**
- After "5" flashes on the display, a number in the format xxx.xx will come up on the display.
- Enter the maintained running time of the blending unit in seconds using the arrow keys. This is how long the blender will run after each dosing cycle and should be adjusted for the best possible blend. Too little time may not produce good dispersion; too much time can cause separation, especially with heavy concentrates.

Step 5:

Press key	LED display	display
		"6" printer Only if a printer (optional) is available
 		enter printer parameters 0 = no printing 1 = printing setpoints 2 = printing parameters 3 = page change 4 = printing each event 5 = printing alarms

- Press  again. This will activate the printing option if it is available and the number "6" will be displayed.
- After the "6" flashes on the screen, a number in the format xxx.xx will come up on the display.
- By using the arrow keys, you can choose your printer parameters. **If you have not activated this option, skip to the next step.**







Step 6:

Press key	LED display	display
		total throughput in kg

6. Press  again.

7. The number “18” will be displayed before the total throughput in kg is displayed.

Operation – Extrusion - Constant

1. Ensure that the unit is properly installed (Section 3.1), a recipe is entered (Section 3.4.1), and the feeder is calibrated (Section 3.6), before attempting to begin operation.
2. If desired, clear the totalizer by pressing  continuously for 5 seconds until the display is reset to “00.00.”
3. Place the Digital Dosing unit into operation by pressing . The green LED will light when the unit is ready to dose, but the Digital Dosing unit will not feed until the extruder begins operation.
4. Start the extruder. The Digital Dosing unit will begin dosing material as soon as the extruder starts. If the unit is installed properly, the process machine symbol  will light on the controller when the extruder starts. The disc symbol  will light when the Digital Dosing unit is dosing material.
5. To stop the dosing process while the extruder is operating, press . The Digital Dosing unit will automatically stop dosing when the extruder stops.
6. While the unit is dosing, depending on software revision, the current recipe can be viewed but not modified, by pressing . In some software versions, the percent additive can be changed while the unit is dosing.

NOTE: See Appendix A, *Troubleshooting*, for information on problems or errors encountered and their resolution.



3.5 Extrusion – Proportional (Extruder Follower Option)





Recipe Input – Extrusion Proportional

To enter a recipe for Extrusion Proportional, the following process data is required:





- Percentage of additive
- Expected throughput of the extruder during production
- Extruder screw speed during production
- Calibration weight in grams



Step 1:

Press key	LED display	display
		"1" parts of the additive (colouring) in %

- Press the Input key, , once.
- The % symbol flashes.
- After "1" flashes quickly on the display, a number in the format xxx.xx will come up on the display.
- Enter the additive percentage by using the Arrow Keys   . The range of values that can be entered is 0.01% to 50.00%. The arrow keys are used to change all process variables. The double arrow key allows the user to ramp up or down at a faster rate.


Step 2:



Press key	LED display	display
	 or  	"2" throughput of the extruder in g/min or lb/min

- Press  again.
- The machine displays a flashing "g" or "lb", a flashing "min" and .

- After “2” flashes quickly on the display, a number in the format xxx.xx will come up on the display.
- Enter the expected extruder throughput during production in grams per minute or pounds per minute. The range of values that can be entered is 001.0 to 6500 grams per minute (00.01 to 14.30 lb/m).

Step 3:



Press key	LED display	display
		“3” rotational speed of the extruder

- Press  a third time.
- The machine displays a flashing screw .
- After “3” flashes quickly on the display, a number in the format xxx.xx will come up on the display.
- Enter the extruder screw speed (rpm) corresponding to the throughput entered in step 2.

Step 4:



Press key	LED display	display
		“ 4 “ = calibration weight in grams or pounds




- Press  a fourth time.
- The machine displays a flashing  and “g”.
- After “4” flashes quickly on the screen, a number in the format xxx.xx will come up on the display.
- Enter the calibration weight in grams. **If the calibration weight is unknown, enter the appropriate “value” from Section 2, based on your disc size, to obtain a starting weight.**
- **Upon completion of the calibration procedure, the calibration weight will automatically be updated into the recipe.** The range of values that can be entered in this field is 00.00 to 400.0.




Please note: Parameters 5 and 6 will only be displayed when a mixer and or a printer is configured.


Step 5:

Press key	LED display	display
		"5" maintained running time of the blending unit in seconds


- Press  again and the symbol "s" will light up and the number "5" will be displayed **if you have a blending unit and have invoked this option.**
- After "5" flashes on the display, a number in the format xxx.xx will come up on the display.
- Enter the maintained running time of the blending unit in seconds using the arrow keys. This is how long the blender will run after each dosing cycle and should be adjusted for the best possible blend. Too little time may not produce good dispersion; too much time can cause separation, especially with heavy concentrates.

Step 6:







Press key	LED display	display
		"6" printer Only if a printer (optional) is available
 		enter printer parameters 0 = no printing 1 = printing setpoints 2 = printing parameters 3 = page change 4 = printing each event 5 = printing alarms

- Press  again. This will activate the printing option if it is available and the number "6" will be displayed.
- After the "6" flashes on the screen, a number in the format xxx.xx will come up on the display.
- By using the arrow keys, you can choose your printer parameters. **If you have not activated this option, skip to the next step.**

Step 7:

- Press  a fifth time to return to the totalizer.

Operation – Extrusion – Proportional (Extruder Follower Option)

- ☑ Ensure that the unit is properly installed (Section 3.1)
 - ☑ A recipe is entered (“Recipe Input-Extrusion Proportional” Section)
 - ☑ The feeder is calibrated (Section 3.6), before attempting to begin operations.
1. If desired, clear the totalizer by pressing  continuously for 5 seconds until the display is reset to “00.00.”
 2. Place the Digital Dosing unit into operation by pressing the Run key ().
The green LED will light when the unit is ready to dose, but will not feed until the extruder begins operation.
 3. Start the extruder. The Digital Dosing unit will begin dosing material as soon as the extruder starts. If the unit is installed properly, the process machine symbol  will light on the controller when the extruder starts. The disc symbol  will light when the Digital Dosing is dosing material
 4. To stop the dosing process while the extruder is operating, press . The Digital Dosing unit will automatically stop dosing when the extruder stops.
 5. While the unit is dosing, depending on software revision, the current recipe can be viewed but not modified, by pressing . In some software versions, the percent additive can be changed while the unit is dosing. The actual extruder screw speed will be displayed in the third recipe register.

3.6 Calibration

All feeders must be calibrated before any blending recipes can run using the Digital Dosing additive feeder.

NOTE: The calibration weight (metered material weight for one revolution of the dosing disc) must be determined separately for each material to be dosed since calibration weight differs from material to material.

The following equipment is needed for calculating the calibration weight:

- Scale with a minimum accuracy of 0.01 grams
- The weighing container which is included in the equipment delivery

Follow these procedures:

1. Remove one of the square covers and insert the calibration container provided.
2. Fill the dosing hopper with a minimum of six (6) inches of material.
3. Note weight of weighing container (= tare weight) or tare scale to zero

NOTE: The Digital Dosing station may only be operated if all sample chutes are in place or a collecting bin is in the calibration box.


Determining the Calibration Weight


Step 1:



- To start the calibration process, press the calibration key.



Step 2:





- Once the sample container is in position, press .
- The disc will rotate 1/4 revolution and dispense material into the sample container. After the disc stops, the screen will remain blank.


- **This sample should be returned to the material hopper without weighing.**
This sample is used only to ensure that all disc pockets are completely filled.
- Replace container in calibration box (or under material outlet tube)




Step 3:

Press key	LED display	display
		If calibration weight "0" in the recipe: The dosing motor turns for one revolution at half of the maximum rotational speed.

- Press  to take a sample for weighing.
- The disc will rotate one full revolution. After the disc has stopped rotating, a number in the format "xx.xx" will appear on the screen along with a flashing  and "g."

Step 4:

Press key	LED display	display
 		"proportioning" and entry of the weight


- Enter the weight, in grams using the Arrow Keys   
- Empty and replace weighing container in calibration box (or under material outlet tube)

Step 5:

- Repeat steps 3 and 4 four (4) more times.
- Notice that the displayed calibration weight may change after each sample weight is entered.
- **The value is an average of all the weights entered. No calculations are required.** It can happen that the calculated speed is either too high or low causing alarm A0009. Check the recipe and settings and modify if necessary.

Section 4: Advanced Operations/ Control Functions

4.1 Recipe Storage and Recall

A maximum of ten (10) recipes can be stored and retrieved with the Digital Dosing controller in the Recipe Storage/Recall mode. Recipes are stored using a two-digit identification number. Pressing  at any time will exit the Recipe Storage/Recall mode.

Recipe Storage

To store the current recipe:

Press key	LED display	display
-----------	-------------	---------




"L (= load)" and the most recently called up recipe number



"S (= save)" and the most recently saved recipe number

Step 1:

- Press the Recipe Storage/Recall key (). A two-digit number (01 through 10) will appear on the screen. This is the recipe I.D. number.


Step 2:


- Use the Arrow keys    to select the desired recipe number.

NOTE: A new recipe stored under the ID number of an existing recipe will overwrite the existing recipe number without warning.

Step 3:

Press key _____ LED display _____ display _____




- Press and hold the button  until the totalizer display returns to the screen.
- The recipe is now stored under the selected ID number.

Recipe Recall

Step 1:


Press key _____ LED display _____ display _____




- Press the stop button to stop any current applications.

Step 2:

Press key _____ LED display _____ display _____





- Press the Storage/Recall key () once.
- A two-digit recipe ID number will appear on screen.

Step 3:

- Use the Arrow Keys    to select the desired recipe number.


Step 4:





- Press and hold  until the totalizer appears on the screen.
- The recipe is now active and can be run or edited.

NOTE: *The recalled recipe now becomes the active recipe.*

4.2 Clearing the Totalizer

- The totalizer displays the total amount of additive dosed since the last time the totalizer was cleared.
- The totalizer can be cleared by pressing Stop  continuously for 5 seconds until the display is reset to “00.00.” The totalizer can be configured to read throughput in grams or pounds.
- See Appendix A to learn how to change the unit of measure.


4.3 Acknowledging Alarms

- When an alarm occurs, the Alarm symbol  flashes red and the dosing process stops.
- If the Digital Dosing is equipped with an audible alarm or flashing light, it will also be activated.
- Alarms are acknowledged by pressing .
- The alarm will also initiate an error code.
- See Appendix A for Troubleshooting suggestions for various alarms.
- The alarm condition **must be corrected** prior to beginning operation again.

4.4 Optional Equipment, Level Switches and Communications Options

Optional equipment for the Digital Dosing Additive Feeder includes:

Alarms

Several alarm options are available for the Digital Dosing feeder. The standard unit comes with a flashing alarm symbol  on the faceplate. Options include both audible horns and flashing lights. An optional no voltage alarm relay can be connected to the user's central alarm system.

Level switches (probes)

To adjust the level switches:

1. Turn the controller ON.
2. Fill the dosing station until the level sensor is one-third covered.
3. Remove the small plastic screw (M3) on the back of the level sensor (see Figure 7).




Figure 7. Level Sensor Screw

4. Turn the trim-pot until the yellow control lamp just switches off.

NOTE: Turning the trim-pot to the left decreases the switching sensitivity; turning it to the right increases the switching sensitivity.

5. Fill the dosing station until the level probe is two-thirds covered. The yellow control lamp should now switch on again. If not, repeat Step 4.
6. Reinstall the plastic screw (M3).

NOTE: The sliding switch under the cover must be set on "0".

Communication Protocol Interfaces

The Digital Dosing unit can be controlled remotely through the EUROMAP E17 or MODBUS RTU protocol. Contact Sales and Service concerning this option at 810.720.7300.

Section 5: Maintenance


5.1 Maintenance Intervals

Daily:	Check warning signs on equipment for good legibility and completeness.
Weekly:	Check function of the “On/Off” Switch.
Every 3 months:	Check shear plate in “DD” dosing station, and wiper in “DT” dosing station.
Every 6 months:	Check that all electrical and mechanical connections are tight. Check adjustment of the level probes (optional).
Annually:	Check dosing disc in dosing station DD/DT.
Each time after material is changed:	Clean the dosing station. Check shear plate or wiper. Check dosing disc.

5.2 Removing the Shear plate (DD feeder only)

Removing the shear plate

1. Empty the dosing station.
2. Open the profile clamp (B) on the dosing hopper.
3. Remove the dosing hopper from the dosing unit.
4. Open the safety screws at the toggle-type fasteners.
5. Open the toggle-type fasteners on the dosing motor.



6. Remove the dosing unit from the dosing motor.
7. Remove the cover from the connecting piece (D).
8. Loosen the two screws (C) on the underside of the dosing unit housing (E).
9. Remove the shear plate (A).


Installing the shear plate

1. Place the new shear plate in the dosing unit housing.
2. Ensure that the shear plate is positioned correctly.
3. Screw the shear plate in place by means of 2 hexagon socket screws (M5 x 16).
4. Turn the dosing disc to check for smooth movement.
5. Mount the cover on the connecting piece.
6. Position the dosing unit on the dosing motor (note guide pins).
7. Close the toggle-type fasteners on the dosing motor.
8. Mount the safety screws.
9. Position the dosing hopper on the dosing unit.
10. Mount the profile clamp.
11. Mount the screw at the profile clamp.

5.3 Cleaning the “DD” Digital Dosing Station


Dismantling the Dosing Station

1. Empty the dosing station.
2. Switch the control unit off by means of the on/off switch.
3. Disconnect from main voltage.
4. Open the profile clamp on the dosing hopper.



Dosing unit (top view)

5. Remove the dosing hopper from the dosing unit.
6. Dismantle the dosing unit and remove the shear plate (D).
7. Loosen the two hexagon socket screws (B, M6 x 30) on the top side of the dosing disc (A).
8. Loosen the center hexagon socket screw (C, M6 x 12) and replace by an M6 x 60 screw.
9. Lift the dosing disc (A) from the dosing unit housing (B) by this screw.
10. Clean the shear plate using a cotton cloth.
11. Clean the dosing hopper and the dosing disc in soapy water.
12. The dosing unit housing may also be cleaned with soapy water.
13. Ensure that soapy water does not enter ball bearings.
14. Dry all parts thoroughly.



Dosing unit (side view)

Installing the Dosing Station

1. Place the dosing disc in the dosing unit housing.
2. Remove the screw (M6 x 60).
3. Screw the dosing disc in place by means of 2 hexagon socket screws (M6 x 30).
4. Mount the center hexagon screw (M6 x 12).
5. Install the shear plate and then the dosing unit.
6. Turn the dosing disc to check for smooth movement.
7. Position the dosing hopper on the dosing unit.
8. Tighten the profile clamp.

5.4 Changing the Dosing Disc in the “DT” Digital Dosing Station

Removing the Dosing Disc

1. Empty the dosing station.
2. Switch the control unit off by means of the on/off switch.
3. Dismantle the dosing unit and remove the shear plate.
4. Loosen the two hexagon socket screws (M6 x 30) on the top side of the dosing disc.
5. Loosen the center hexagon socket screw (M6 x 12) and replace by a M6 x 60 screw.
6. Lift the dosing disc from the dosing unit housing by this screw.

Installing the Dosing Disc

1. Change and place the dosing disc in the dosing unit housing.
2. Remove the screw (M6 x 60).
3. Screw the dosing disc in place by means of 2 hexagon socket screws (M6 x 30).
4. Mount the center hexagon socket screw (M6 x 12).
5. Install the shear plate and then the dosing unit.
6. Turn the dosing disc to check for smooth movement.
7. Position the dosing hopper on the dosing unit.
8. Tighten the profile clamp.

See Appendix D: Spare Parts List on page 61 for disc part numbers.

Installing Different Types of Dosing Discs

Dosing discs of the same type, and thickness (72 pocket), may be exchanged for each other without any problems. If dosing discs with a different compartment number or thickness are installed, this has to be entered in the control system!


DD Discs

Disc	Calibration Number	Number of pockets
DD 30-030672	1.75	72
DD 30-051040	5.00	40
DD 30-051725	8.00	25
DD 30-051818	15.00	18

1. Enter the (preliminary) calibration value of the newly installed dosing disc
2. Execute “calibration” to determine the final calibration value.

5.5 Removing / Replacing the Wiper in the DT Dosing Station

1. Empty the dosing station.
2. Open the profile clamp (C) of the dosing container.
3. Remove the profile clamp (C)
4. Remove the dosing container (B) along with the dosing hopper (A).
5. Loosen the 3 plastic screws on the wiper.
6. Remove the wiper and holding plate.
7. Install the new wiper along with the holding plate.




DT 30

8. Tighten down the 3 plastic screws. Make sure that the wiper is fitted parallel to the dosing plate (**Use only *plastic* screws to avoid damage to the extruder or molding machine screw should the mounting screws ever come loose.**)
9. Install the dosing container along with the dosing hopper on the dosing housing (pay attention to the guide pins).
10. Mount the profile clamp.
11. Mount the screw at the profile clamp.

5.6 Cleaning the DT Dosing Station

1. Empty the dosing station.
2. Switch the control unit off by means of the on/off switch.
3. Disconnect from mains voltage.
4. Open the profile clamp (C) of the dosing container.
5. Remove the profile clamp (C).
6. Remove the dosing container (B) along with the dosing hopper (A).
7. Open the safety screws at the toggle-type fasteners.
8. Open the toggle-type fasteners.
9. Remove the dosing housing (D) from the mixing hopper.
10. Clean the dosing housing (D) with a paintbrush.
11. Clean the dosing container (B) and the dosing hopper (A) in soapy water.
12. Dry all parts thoroughly.
13. Mount the dosing housing onto the dosing motor.
14. Observe that the guide pins are locked into position.
15. Close the toggle-type fasteners.



Toggle-type fastener

16. Mount the safety screws.
17. Install the dosing container along with the dosing hopper on the dosing housing (pay attention to the guide pins).
18. Mount the profile clamp.
19. Mount the screw at the profile clamp and tighten.

5.7 Exchangeable Stations

Dosing discs of the same type may be exchanged for each other without any problems. If dosing discs with a different compartment number are installed, this has to be entered in the control system.

1. Enter the (preliminary) calibration value of *the freshly installed* dosing disc

DT Discs

Disc	Calibration Number	Number of Pockets
DT 30-1018 20	32.00	20
DT 30-1020 25	38.00	25
DT 30-2030 12	100.00	12
DT 30-2040 10	175.00	10

DP Discs

Disc	Calibration Number	Number of Pockets	Disc Thickness
DP 30-0509 40	17.00	40	0.5 mm
DP 30-2509 40	8.00	40	2.5 mm

2. Execute "calibration" to determine the final calibration value.

5.8 Replacing Fuses


1. Stop the continuous operation.
2. Wait until the dosing unit has stopped.
3. Switch off the device with the on/off switch.
4. Cut off the voltage supply.
5. Wait at least one minute before starting to work at the unit or controller.

6. Never try to repair a defective fuse.

7. Open the screws (A) and remove the lid (B).

8. Remove the blind lid (C) and open the screws.

9. Move the lid (D) aside.



10. Remove the defective fuse from the fuse carrier.

11. Install the new fuse (while observing the value).

12. Mount the lid (D).

13. Fasten the screws and the blind lids (C).

14. Mount the lid (B).

15. Mount the screws (A).

See Appendix D for fuse part numbers.




Appendix A: Troubleshooting

During setup and use of the Digital Dosing Additive Feeder, personnel may experience difficulties. Some of the problems encountered may be resolved using the following techniques.

A.1 General Troubleshooting - Unit Will Not Operate

- Check all connections and process wiring. Note that the process machine input **MUST** be wired to a DRY contact for Injection Molding (Section 3.1) and Extruder - Constant Applications (Section 3.1). For Extrusion - Proportional Applications (Extruder Follower OPTION) see Section 3.5.
- Ensure the correct Configuration Codes have been entered to configure the Digital Dosing unit for the process and installation, see Section 2.

A.2 Malfunctions - Error Codes

When a malfunction or error occurs, the controller displays the Alarm symbol  and an error code. The code consists of an “A,” followed by an error number. The control unit will not operate until the malfunction or error has been corrected. To acknowledge and clear the alarm, press the Stop key (). Once the malfunction is corrected, press  to begin dosing operations.

NOTE: Stop  **will not correct a malfunction or error.**

Following is a table with the error codes, possible reasons for each code, and solutions to the problems presented.

ERROR CODES

Code	Definition	Possible Reason/Solution
A001	Strap "safety switch" is missing.	Manufacturer Service.
A002	The nominal current of the dosing motor (=100%, see name plate) is being exceeded for more than 2 seconds by 30% or for a maximum of 0.5 seconds by 80%.	Dosing motor defective or jammed. Check the dosing motor and exchange it if necessary. Check whether the dosing disc is jammed by material and remove the material if necessary.
A003	The nominal current of the dosing motor (=100%, see name plate) is being exceeded for more than one minute.	Dosing motor defective or jammed. Check the dosing motor and exchange it if necessary. Check whether the dosing disc is jammed by material and remove the material if necessary.
A004	Excess temperature. The temperature within the controller housing is > 85°C	Check whether the cooling plate at the back of the controller is sufficiently cooled down. Use fan if necessary.
A005	The encoder (pulse generator) does not emit any pulses for approximately 2 seconds.	If dosing motor does not turn, check whether the dosing disc is jammed by material and remove the material if necessary. If disc is free, check the dosing motor, exchange if necessary. If motor operates, but alarm persists, check speed encoder output. Replace as necessary.
A006	For approximately 4 seconds, there is a deviation of the motor speed of more than 20% from the nominal rotational speed.	Defect at the dosing motor. Check dosing motor, exchange if necessary. Check whether the dosing disc is jammed by material and remove the material if necessary. Power supply part or control out of order. Manufacturer Service.
A007	Dosing motor stops or doesn't work.	Brake at the dosing motor out of order. Control system out of order. Manufacturer service.
A008	The screw retract time of the processing machine is shorter than 0.1 seconds.	The unit cannot be operated in combination with this processing machine.
A009	The calculated speed of the motor is either too high or too low.	Check basic parameter settings and recipe, modify if necessary. May require changing to different sized dosing disc.
A0010	The feed station is not able to meter the desired recipe.	Check basic parameter setting and recipe, modify if necessary. May require changing to different sized dosing disc.
A0011	The raw material probe is not covered	Refill Material.
A0012	The additive probe is not covered.	Refill material.
A0014	Power failure interrupted run cycle.	Clear alarm after power restored.
A0015	EEPROM data loss, EEPROM not programmed.	Manufacturer Service.
A0016	No communication between HOST and unit.	Check cable fittings. Manufacturer Service.

A.3 Determining the Software Setup Factor

The Digital Dosing control unit is configured via a Software Setup Factor (binary code). To determine the Software Setup Factor answer the following questions: If the answer is “yes” enter the code number in the selection column. If the answer is “no” enter “0” in the selection column. When all the questions have been answered and the selection column is completed, add up the total for the selection column. The total is the Software Setup Factor.

A.4 Recipe Formulas

The following formulas can be used to determine if a recipe is appropriate or possible.

Injection Molding

For injection molding applications, compute the dosing disc speed and total number of disc revolutions using the following formulas. Recipe limitations are listed in the table following the equations.

$$\text{Disc RPM} = \frac{(\text{Shot Weight} - \text{g}) \times (\text{Additive} - \%) \times 0.6}{(\text{Disc Calibration Weight} - \text{g}) \times (\text{Recovery Time} - \text{s})}$$

$$\text{Disc Revolutions per Shot} = \frac{(\text{Shot Weight} - \text{g}) \times (\text{Additive} - \%) \times 0.01}{(\text{Disc Calibration Weight} - \text{g})}$$

Recipe Limitations for Injection Molding

Motor Assembly Speed (rpm)	Maximum	
	Speed (rpm)	Number of Disc Revolutions
11.5	11.5	4.6
35.5	35.5	14.8

Extrusion

For extrusion applications compute the dosing disc speed using the following formula.
Recipe limitations are listed in the table following the recipe.

$$\text{Disc RPM} = \frac{(\text{Additive} - \%) \times (\text{Total Extruder Throughput} - \text{lb} / \text{hr})}{13.22 \times (\text{Disc Calibration Weight} - \text{g})}$$

Recipe Limitations Extrusion

Motor Assembly Speed (RPM)	Maximum Speed (RPM)
11.5	11.5
35.5	35.5

Appendix B: Basic Parameter Settings


Extrusion Mode:

You need an extruder signal that is proportional to the extruder speed to operate in the Extrusion - Proportional mode. You can use any of the following:

- Frequency signal (must be 12 VDC square wave)
- 0 - 10 VDC signal
- 0 - 20 mA current signal

Determine the frequency output in the lower working area (A) of the extruder. Record the data. Min. input frequency = _____ Hz

Determine the frequency output in the upper working area (B) of the extruder. Record the data.



Max. input frequency = _____ Hz

If a **voltage** signal is available (0 - 10 VDC) calculate the frequency output of the extruder for the lower / upper working area using the formula:

$$\text{Frequency [Hz]} = \frac{\text{Input voltage [V]} \times 10000 \text{ [Hz]}}{10 \text{ [V]}}$$

Note the data:

Min. input frequency = _____ Hz

Max. input frequency = _____ Hz

If a **current** signal is available (0 - 20 mA) calculate the frequency output of the extruder for the lower / upper working area using the formula:

$$\text{Frequency [Hz]} = \frac{\text{Input current [mA]} \times 10000 \text{ [Hz]}}{20 \text{ [mA]}}$$

Note the data:

Min. input frequency = _____ Hz

Max. input frequency = _____ Hz

Calculate the **span factor** using the formula:

$$\text{Span factor [Hz / rpm]} = \frac{\text{Frequency [Hz]}}{\text{Rotational speed of the extruder [rpm]} \times 10}$$

Note the data:

Span factor = _____

Determining the Configuration Value Extrusion (Constant or Proportional):

Mark the functions required. Use the numerical value indicated and insert it in the empty field if applicable. Total the figures for configuration value.

Optional raw material level probe installed	1	_____
Optional additive level probe installed	2	_____
Optional blending unit installed	8	_____
Totalizer displayed in lb (kg default)	16	_____
Extruder throughput (1 kg-6.5 Kg/min) (2.2 lbs/min-14.3 lbs/min)	0	_____
Extruder throughput (10 kg-65 kg/min) (22 lbs/min-143 lbs/min)	32	_____
Extruder throughput (0.1 kg-0.65 Kg/min) (0.22 lbs/min-1.43 lbs/min)	128	_____
<i>(NOTE: the throughput selections determine placement of the decimal point on the display)</i>		
External run/stop signal controls dosing	64	_____
Mounting on Micro mixing hopper	256	_____
Alarm output is switched in case of power failure	512	_____
Extrusion proportional . . . (extruder follower)	1024	_____
Extrusion Constant	3072	_____
Printer available	16348	_____
Configuration value:		_____

Example:

- Level probes: raw material and additive probes installed

- Throughput: 8000 g/min
- Totalizer displayed in lbs
- Extrusion mode

. Raw material probe	1	<u>1</u>	
. Additive probe	2	<u>2</u>	
. Blending unit	8	—	
. Totalizer displayed in lb.	16	<u>16</u>	
. Extruder throughput (1 kg-6.5 Kg/min)(2.2 lbs/min-14.3 lbs/min)		0	—
Extruder throughput (10 kg-65 kg/min).....(22 lbs/min-143 lbs/min).	32	<u>32</u>	
Extruder throughput (0.1 kg-0.65 Kg/min)(0.22 lbs/min-1.43 lbs/min)....	128	—	
. External run/stop signal controls dosing	64	—	
. Mounting on a Micro mixing-hopper.	256	—	
. Alarm output switched in case of power failure	512	—	
. Extrusion mode	1024	<u>1024</u>	
. Printer available	16348	—	
Configuration value:		<u>1075</u>	

Injection Molding:

Mark the functions required. Use the numerical value indicated and insert it in the empty field if applicable. Total the figures for configuration value.

Optional raw material level probe installed	1	—
Optional additive level probe installed	2	—

Optional blending (mixing) unit installed8	___
Totalizer displayed in lb (kg default)	16	___
Shot weight (1 kg-6.5 Kg)(2.2 lbs-14.3 lbs)	0	___
Shot weight (10 kg-65 kg)(22 lbs-143 lbs)	32	___
Shot weight (0.1 kg-0.65 Kg)(0.22 lbs-1.43 lbs)	128	___
<i>(NOTE: The shot weight selections above determine placement of the decimal point on the display)</i>		
External run/stop signal controls dosing	64	___
Mounting on Micro mixing hopper	256	___
Alarm output is switched in case of power failure	512	___
Printer available	16348	___
Configuration value:		___

Example:




- Level probes: additive probe installed
- Shot weight: 8 kg
- Totalizer displayed in lb




Raw material probe	1	___
------------------------------	---	-----

Additive probe	2	<u>2</u>
Blending unit	8	—
Totalizer displayed in lb.	16	<u>16</u>
Shot weight up to 6.5 kg	0	
or		
Shot weight 6.5 to 65 kg	32	<u>32</u>
External run/stop signal controls dosing	64	—
Mounting on a Micro mixing-hopper.	256	—
Alarm output switched in case of power failure	512	—
Printer available	16348	—
Configuration value:		<u>50</u>



Appendix C: Dosing factors, equipment drawings and part numbers

Disc Dosing Factor Table 1: Disc Guide

Disc	Disc Nomenclature Used in the Controller	Minimum/Maximum Disc Revolution	Weight Per Disc Revolution (35 lbs/cu. ft.)	Min. Throughput with 100% Continuous Running (35 lbs./cu. ft.)	Max. Throughput with 100% Continuous Running (35 lbs./cu. ft.)	Weight Per Disc Revolution (44 lbs./cu. ft.)	Min. Throughput with 100% Continuous Running (44 lbs./cu. ft.)	Max. Throughput with 100% Continuous Running (44 lbs./cu. ft.)
 <p>DD30-030672</p> <p>Default Calibration # 1.50 grams/rev</p>	P030672	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	1.53 g/Rev. 0.02 g/Hole	0.04 lb/hr 0.02 kg/hr 0.10 lb/hr 0.045 kg/hr 0.19 lb/hr 0.09 kg/hr	1.30 lbs/hr 0.59 kg/hr 2.32 lbs/hr 1.05 kgs/hr 7.16 lbs/hr 3.25 kgs/hr	1.95 g/rev. 0.027 g/hole	0.04lb/hr 0.02 kg/h 0.12 lb/hr 0.05 kg/hr 0.26 lb/hr 0.12 kg/hr	1.65 lb/hr 0.75 kg/h 2.89 lb/hr 1.31 kg/hr 9.00 lb/hr 4.10 kg/hr
 <p>D30-051040</p> <p>Default Calibration # 4.0 grams/rev</p>	051040	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	4.24 g/Rev. 0.11 g/Hole	0.11 lb/hr 0.05 kg/hr 0.27 lb/hr 0.12 kg/hr 0.55 lb/hr 0.25 kg/hr	3.59 lbs/hr 1.63 kgs/hr 6.33 lbs/hr 2.87 kgs/hr 19.80 lbs/hr 9.00 kgs/hr	5.39g/rev. 0.13 g/hole	0.15 lb/hr 0.07kg/h 0.35 lb/hr 0.15 kg/hr 0.70 lb/hr 0.32 kg/hr	4.56 lb/hr 2.07 kg/h 8.00 lb/hr 3.62 kg/hr 25.30 lb/hr 11.50 kg/hr
 <p>D30-051725</p> <p>Default Calibration # 7.3 grams/rev</p>	051725	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	7.37 g/Rev. 0.30 g/Hole	0.20 lb/hr 0.09 kg/hr 0.48 lb/hr 0.22 kg/hr 1.00 lb/hr 0.44 kg/hr	6.23 lbs/hr 2.83 kgs/h 11.0 lbs/hr 4.99 kgs/hr 34.60 lbs/hr 15.70 kgs/hr	9.38g/rev. 0.38 g/hole	0.24 lb/hr 0.11 kg/h 0.61 lb/hr 0.27 kg/hr 1.25 lb/hr 0.57 kg/hr	7.90 lb/hr 3.60 kg/h 14.0 lb/hr 6.36 kg/hr 44 lbs/hr 20 kosher

 <p>DD30 051818 Default Calibration # 13.5 grams/rev</p>	051818 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	13.42 g/Rev. 0.75 g/Hole	0.35 lb/hr 0.16 kg/hr 0.85 lb/hr 0.39 kg/hr 1.76 lb/hr 0.80 kg/hr	11.40 lbs/hr 5.15 kgs/hr 19.60 lbs/hr 8.89 kgs/hr 63.00 lbs/hr 28.60 kgs/hr	17.08 g/rev. 0.95 g/hole	0.44 lb/hr 0.20 kg/h 1.12 lbs/hr 0.51 kg/hr 2.20 lbs/hr 1.00 kgs/hr	14.5 lbs/hr 6.56 kgs/h 25.63 lbs/hr 11.62 kgs/hr 80.25 lbs/hr 36.4 kgs/hr
 <p>DT30 101820 Default Calibration # 28 grams/rev</p>	101820 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	28.00 g/Rev. 1.40 g/Hole	0.75 lb/hr 0.34 kg/hr 1.85 lb/hr 0.84 kg/hr 3.7 lb/hr 1.68 kg/hr	23.70 lbs/hr 10.75 kgs/hr 42.23 lbs/hr 19.15 kgs/hr 131.50 lbs/hr 59.70 kg/shr	35.63 g/rev. 1.78 g/hole	1.00 lbs/hr 0.43 kg/h 2.31 lbs/hr 1.05 kgs/hr 4.70 lbs/hr 2.14 kgs/hr	30.1 lbs/hr 13.68 kgs/h 52.78 lbs/hr 23.94 kgs/hr 167.3 lbs/hr 75.9 kg/shr
<p>DT30-102025 Sure-Shot disc No Picture Default Calibration # 33 grams/rev</p>	P102025 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	33.60 g/Rev. 1.3 g/Hole	0.87 lb/hr 0.40 kg/hr 2.18 lb/hr 0.99 kg/hr 4.36 lb/hr 1.98 kg/hr	27.94 lb/hr 12.67 kg/hr 49.77 lb/hr 22.57 kg/hr 154.90 lb/hr 70.29 kg/hr	42.75 g/rev. 1.71 g/hole	1.12 lbs/hr 0.50 kg/h 2.77 lbs/hr 1.26 kgs/hr 5.55 lbs/hr 2.52 kgs/hr	35.56 lbs/hr 16.12 kgs/h 63.34 lbs/hr 28.72 kgs/hr 197.25 lbs/hr 89.46 kgs/hr
 <p>DT30 203012 Default Calibration # 95 grams/rev</p>	203012 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM) 0.5 Rev./min (11.5 RPM) 1.0 Rev./min (35.5 RPM)	95.09 g/Rev. 7.92 g/Hole	2.51 lb/hr 1.14 kg/hr 6.28 lb/hr 2.85 kg/hr 12.50 lb/hr 5.70 kg/hr	80.50 lbs/hr 36.50 kgs/hr 143.28 lbs/hr 65.00 kgs/hr 446.54 lbs/hr 202.50 kgs/hr	118.72 g/rev. 9.89 hole	3.13 lbs/hr 1.42 kgs/h 7.80 lbs/hr 3.54 kgs/hr 15.65 lbs/hr 7.1 kg/shr	100.53 lbs/hr 45.6 kgs/h 178 lbs/hr 80 kgs/hr 557 lbs/hr 252.9 kgs/hr

DT30 204010F  Default Calibration # 150 grams/rev	204010 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM)	151.15 g/Rev.	4.00 lb/hr	128.00 lbs/hr	188.72 g/rev.	5.0 lbs/hr	160 lbs/hr
		0.5 Rev./min (11.5 RPM)	15.12 g/Hole	1.80 kg/hr	59.00 kgs/hr	18.87 hole	2.25 kg/h	72.5 kgs/h
		1.0 Rev./min (35.5 RPM)		10.00 lb/hr	227.74 lbs/hr		12.43 lbs/hr	283 lbs/hr
				4.53 kg/hr	103.28 kgs/hr		5.64 kgs/hr	129 kgs/hr
				20.00 lb/hr	705.00 lbs/hr		25.00 lbs/hr	886 lbs/hr
			9.00 kg/hr	320.00kgs/hr		11.30 kgs/hr	402 kgs/hr	

DP30 050940  Default Calibration # 15 grams/rev	P050940 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM)	15.64 g/Rev.	0.41 lb/hr	13.20 lbs/hr	19.53 g/rev.	0.51lb/hr	16.50 lbs/hr
		0.5 Rev./min (11.5 RPM)	0.39 g/Hole	0.187 kg/hr	6.00 kgs/hr	0.49 g/hole	0.23 kg/h	7.50 kgs/h
		1.0 Rev./min (35.5 RPM)		1.00 lb/hr	22.62 lbs/hr		0.12 lb/hr	28.65 lbs/hr
				0.45 kg/hr	10.62 kgs/hr		0.57 kg/hr	13.80 kgs/hr
				2.00 lb/hr	73.40 lbs/hr		2.60 lbs/hr	91.70 lbs/hr
			0.94 kg/hr	33.30 kgs/hr		1.17 kgs/hr	41.60 kgs/hr	
DP30 250940  Default Calibration # 7.8 grams/rev	P250940 # of Holes Diameter Disc Thickness	0.2 Rev./min (6.4 RPM)	7.82 g/Rev.	0.20 lb/hr	13.2 lbs/hr	9.76 g/rev.	0.26b/hr	8.25 lbs/hr
		0.5 Rev./min (11.5 RPM)	0.20 g/Hole	0.093 kg/hr	3.00 kgs/hr	0.245 g/hole	0.115 kg/h	3.75 kgs/h
		1.0 Rev./min (35.5 RPM)		0.46 lb/hr	10.55 lbs/hr		0.60 lb/hr	13.57 lbs/hr
				0.21 kg/hr	4.78 kgs/hr		0.27 kg/hr	6.15 kgs/hr
				1.00 lb/hr	36.70 lbs/hr		1.30 lbs/hr	45.85 lbs/hr
			0.47 kg/hr	16.65 kgs/hr		0.58 kg/hr	20.80 kgs/hr	

Specification Sheet

DIGITAL DOSING UNIT TECHNICAL PARAMETERS

Disc Dosing Factor Table 2

<i>Maximum Number of Feed Stations</i>	<i>One (1) for Granule Processing</i>
<i>Maximum Product Temperature</i>	<i>80°C (or 176°F)</i>
<i>Weight (Approximately)</i>	<i>20 kg (44 pounds)</i>
<i>Connected Loads</i>	<i>0.11 kW</i>
<i>Operating Voltage</i>	<i>115/1/60 or 230/1/50-60</i>
<i>Special Voltage</i>	<i>On Request</i>
<i>Option</i>	<i>Hopper Level Probe (Additive)</i>
<i>Option</i>	<i>Hopper Level Probe (Virgin)</i>

Starter Calibration Parameters

DD Discs

Disc	Calibration Number
DD 30-030673	1.75

	Parameters	Default Units	Description
1	Additive %	Percent	Using the arrow keys, set additive ratio.
2	Shot size of the current mold	Grams/pounds	Using the arrow keys, set the shot size of the current capacity in grams/min or pounds/min.
3	Screw recovery time	Seconds	Using the arrow keys, set the screw recovery time (in seconds)
4	Calibration weight for additive	Grams	Enter a value from the tables below and proceed to calibration mode to set the calibration value.
18	Totalizer (display only)	Grams/pounds	

Digital Dosing unit parameter setup 1-4 for extrusion - contant

	Parameters	Default Units	Description
1	Additive %	Percent	Using the arrow keys, set additive ratio.
2	throughput	Grams/pounds	Using the arrow keys, set to the throughput of the extruder capacity in grams/min or pounds/min
3	Not used		
4	Calibration weight for additive	Grams	Enter a value from the tables below and proceed to calibration mode to set the calibration value.
18	Totalizer (display only)	Grams/pounds	

Digital Dosing unit parameter setup 1-4 for extrusion proportional

	Parameters	Default Units	Description
1	Additive %	Percent	Using the arrow keys, set additive ratio.
2	throughput	Grams/pounds	Using the arrow keys, set to the throughput of the extruder capacity in grams/min or pounds/min
3	Extruder speed	RPM	Using the arrow keys, set the RPM
4	Calibration weight for additive	Grams	Enter a value from the tables below and proceed to calibration mode to set the calibration value.
18	Totalizer (display only)	Grams/pounds	


Set-up of Factory Set Operating Parameters

Digital Dosing unit parameter setup 7-14


Parameter	Bison - Black motor				Bauer - Blue motor			Comments
	RPM	2	6	12	38	6.4	11.5	
7	65000	25200	14103	4387	11739	6600	2135	These values refer to the pulses of the encoder
8	0.5				0.7			Nominal motor current
9	Ext		Inj		Ext		Inj	(see separate calculation sheet for parameter #9)
	1040		16		1040		16	
10	0				1			Factory set, do not change
11	Ext		Inj		Ext		Inj	Ext = minimum input frequency w/follower only Inj = Minimum # of machine cycles per dosing
	50		50		50		50	
12	Ext		Inj		Ext		Inj	

	10	5.56	10	5.56	Ext = Span factor (sf) calculated using: $\text{sf} = 1000/\text{rpm}@10\text{vdc}$ sf = 1000/rpm @20ma
13	Ext	Inj	Ext	Inj	
	0	0	0	0	Communication address used with Euromap 17 (use 1 instead of 0)
14	Ext	Inj	Ext	Inj	
	220	220	220	220	For use with Micro mix hopper (use 1 instead of 220)

Station 1 Digital Dosing Unit




SIDE VIEW




TOP VIEW

Station 2 Digital Dosing Unit




SIDE VIEW



TOP VIEW

General Wiring Diagram for Bauer Motor



See details below

J8 ALARM OUTPUT

1. NEUTRAL
2. EARTH
3. LINE (110 VAC/220 VAC DEPENDING ON INCOMING POWER)
4. NO LINE (110 VAC/220 VAC DEPENDING ON INCOMING POWER)
5. NC LINE (110 VAC/220 VAC DEPENDING ON INCOMING POWER)

J9 MIX MOTOR CONTROL

1. NEUTRAL
2. EARTH
3. LINE (110 VAC/220 VAC DEPENDING ON INCOMING POWER)
4. NO LINE (110 VAC/220 VAC DEPENDING ON INCOMING POWER)
5. NC LINE (110 VAC/220 VAC DEPENDING ON INCOMING POWER)

J10 EXTERNAL COMMUNICATIONS (RS485/RS422)

(NOTE: COMMUNICATION BOARD P/N 83693 REQUIRED)

1. +5 VDC
2. COMMON
3. TX+
4. TX-
5. RX+
6. RX-

J11 EXTERNAL CONTROLS

1. RUN ENABLE (+15 VDC CONTINUOUS="STOP", 0 VDC="RUN")
2. +15 VDC
3. ALARM ACKNOWLEDGE (+15 VDC MOMENTARY ACKNOWLEDGES ALARMS)
4. +15 VDC

J12 EXTERNAL CONTROLS

1. NOT USED
2. +15 VDC
3. EXTERNAL INPUT
 - 3.1 INJECTION MOLDING (+15 VDC INITIATES FEEDING)
 - 3.2 EXTRUSION SIMPLE (+15 VDC CONTINUOUS RUNS FEEDER)
 - 3.3 EXTRUSION 0-10 VDC (0-10 VDC RUNS FEEDER)
 - 3.4 EXTRUSION 0-20mA (0-20mA RUNS FEEDER)
4. COMMON

J13 LEVEL SENSORS

1. +15 VDC (VIRGIN)
2. SIGNAL (VIRGIN)
3. COMMON (VIRGIN)
4. +15 VDC (ADDITIVE)
5. SIGNAL (ADDITIVE)
6. COMMON (ADDITIVE)

J14 LEGACY INPUTS

1. +15 VDC
2. DIVERTER VALVE SWITCH (COLORBLEND STANDARD)
3. CALIBRATION SWITCH
4. SPEED INPUT (BISON FEEDER MOTORS)
5. SAFETY SWITCH (COLORBLEND STANDARD)
6. COMMON

J15 POWER INPUT SINGLE PHASE POWER ONLY


1. LINE (110 VAC/220 VAC)
2. EARTH
3. NEUTRAL

J16 FEEDER MOTOR POWER

1. COMMON
2. 180 VDC MAXIMUM

J17 ENCODER INPUT

1. COMMON
2. SIGNAL
3. +5 VDC



Dosing Unit Electrical Schematic Chart for Bauer (blue) motors only

Drawing No.	Description of Drawing	Voltage
CT102020	C150 CONTROLLER INJECTION	110
CT102021	C150 CONTROLLER EXT-S SIMPLE EXTRUSION	110
CT102022	C150 CONTROLLER EXT-V EXTRUSION 0-10 V INPUT	110
CT102023	C150 CONTROLLER EXT-C EXTRUSTION 0-20 mA INPUT	110
CT102024	C150 CONTROLLER INJECTION	220
CT102025	C150 CONTROLLER EXT-S EXTRUSION SIMPLE EXTRUSION	220
CT102026	C150 CONTROLLER EXT-V EXTRUSION 0-10 V INPUT	220
CT102027	C150 CONTROLLER EXT-C EXTRUSION 0-20 mA INPUT	220

Note:

- 1. If changes to the controller are required, please consult factory.**
- 2. Request any additional drawings needed at that time.**

Dosing Unit Electrical Schematic Chart for Bison (black) motors only

Drawing No.	Description of Drawing	Voltage
CT101674	C150 CONTROLLER INJECTION	110
CT101675	C150 CONTROLLER EXT-S SIMPLE EXTRUSION	110
CT101676	C150 CONTROLLER EXT-V EXTRUSION 0-10 V INPUT	110
CT101677	C150 CONTROLLER EXT-C EXTRUSTION 0-20 mA INPUT	110
CT101753	C150 CONTROLLER INJECTION	220
CT101750	C150 CONTROLLER EXT-S EXTRUSION SIMPLE EXTRUSION	220
CT101751	C150 CONTROLLER EXT-V EXTRUSION 0-10 V INPUT	220
CT101752	C150 CONTROLLER EXT-C EXTRUSION 0-20 mA INPUT	220

Note:

- 1. If changes to the controller are required, please consult factory.**
- 2. Request any additional drawings needed at that time.**

Appendix D: Spare Parts List

Dosing Disc/Shear Order Numbers


Dosing disc	
72 chambers	CT 100562
49 chambers	CT 21710
25 chambers	CT 21711
18 chambers	CT 2057
Dosing disc, wear-resistant	
40 chambers	CT 28214
25 chambers	CT 27141
18 chambers	CT 27142
Shear for DD style unit	
18, 25, 40 pocket disc	CT 21392
72 pocket disc	CT 100875

Replacement Motor Order Numbers

Bauer Gear Motors	
6.4 RPM	CT34300
11.5 RPM	CT102241
35.5 RPM	CT34299

Control System Order Numbers

Fuse	Size	Voltage	Amps	Type	Part Number
F1	5X20	250 V	5 A	Metric	A0571836
F2	1/4X1	1/4-250 V	4 A	Time Delay	CT99107
F3	5X20	250 V	0.5 A	Time Delay	CT96398
F4	5X20	250 V	0.5 A	Metric	CT102258
F5	5X20	250 V	0.5 A	Metric	CT102259
F7	5X20	250 V	0.5 A	Metric	A0571836



-Notes-

Technical Assistance

Parts Department

Call toll-free 7am–5pm CST: [800] 783-7835

The ACS Customer Service Group will provide your company with genuine OEM quality parts manufactured to engineering design specifications, which will maximize your equipment's performance and efficiency. To assist in expediting your phone or fax order, please have the model and serial number of your unit when you contact us. A customer replacement parts list is included in this manual for your convenience. ACS welcomes inquiries on all your parts needs and is dedicated to providing excellent customer service.

Service Department

Call toll-free 24 hours at: [800] 783-7835

We have a qualified service department ready to help. Service contracts are available for most products.

Sales Department

Call [262] 641-8610 Monday–Friday, 8am–5pm EST

Our products are sold by a worldwide network of independent sales representatives. Contact our Sales Department for the name of the sales representative nearest you.

Contract Department

Call [262] 641-8610 Monday–Friday, 8am–5pm EST

Let us install your system. The Contract Department offers any or all of these services: project planning; system packages including drawings; equipment, labor, and construction materials; and union or non-union installations.

Sterling
2900 S. 160th Street
New Berlin, WI 53151
262-641-8610