HI 93124 Portable Logging Haze Meter





Dear Customer,

Thank you for choosing a Hanna product.

Please read this instruction manual carefully before using the meter.

This manual will provide all necessary information for a correct use.

If you need additional technical information, do not hesitate to e-mail us at **tech@hannainst.com** or contact your nearest technical office.

This instrument is in compliance with the **C€** directives.

TABLE OF CONTENTS

Warranty	3
Preliminary Examination	3
Principle of Operation	4
General Description	4
Functional Description	5
Specifications	6
Operational Guide	7
Taking measurements	7
Sources of interference	8
Log-on-demand	8
Cleaning logged data	8
Viewing logged data	9
Viewing and setting date and time	9
RS232 connection	9
Calibration	10
Calibration procedure	
Viewing calibration date	
Standard suspension	11
Tips for accurate operation	12
LCD error codes	13
Battery Replacement	14
Accessories	14
CE declaration of conformity	15

WARRANTY

All Hanna Instruments meters are warranted for two years against defects in workmanship and materials when used for their intended purpose and maintained according to instructions.

This warranty is limited to repair or replacement free of charge. Damage due to accidents, misuse, tampering or lack of prescribed maintenance are not covered. If service is required, contact the dealer from whom you purchased the instrument. If under warranty, report the model number, date of purchase, serial number and the nature of the problem. If the repair is not covered by the warranty, you will be notified of the charges incurred. If the instrument is to be returned to Hanna Instruments, first obtain a Returned Goods Authorization number from the Customer Service department and then send it with shipping costs prepaid. When shipping any instrument, make sure it is properly packaged for complete protection.

PRELIMINARY EXAMINATION

Remove the instrument from the packing material and examine it to make sure that no damage has occurred during shipping. If there is any damage, notify your Dealer.

HI 93124 is supplied complete with:

- Glass Cuvet & Cap (2 pcs.)
- 1.5V AA alkaline batteries (4 pcs.)
- Instruction manual
- Rugged carrying case


Note: Save all packing material until you are sure that the meter functions correctly. All defective items must be returned in its original packaging with the supplied accessories.

PRINCIPLE OF OPERATION

HI 93124 has been designed to perform turbidity measurements according to the EBC (European Brewery Convention) Standard.

The instrument functions by passing a beam of infrared light through a cuvette containing the sample being measured. The light source is a High Emission Infrared LED with a wavelength peaking at 890 nm, ensuring that the interference caused by colored samples is minimum.

A sensor, positioned at 90° with respect to the direction of light, detects the amount of light scattered by the undissolved particles present in the sample.



The microprocessor converts such readings into EBC values.

GENERAL DESCRIPTION


Beer clarity is a parameter constantly controlled in brewery, and to assure a consistent product quality, the brewmaster needs more than visual inspection.

Several substances can cause haze in beer, but the most frequently encountered problem is due to a cross-linking of polyphenol and protein. These materials probably exist in equilibrium in beer and manifest themselves as a haze when the polyphenol polymerizes.

A range of stabilization treatments is available for avoiding haze problems, and the product has to be controlled on several steps during brewing process, in particular after filtration and before the beer enters the single tanks.

HI 93124 is a portable Haze meter, especially designed for application in brewery. The instrument is also provided with a log-on-demand feature, which allows the user to store up to 199 samples into the internal memory.

FUNCTIONAL DESCRIPTION



- 1) RS232 connector
- 2) Measurement cell
- 3) Liquid Crystal Display
- ON/OFF key, to switch the meter ON and OFF; CLR key, to clear log memory (with ALT)
- 5) GLP key, to display last calibration date and time; CAL key, to enter calibration mode (with ALT)
- 6) ALT key, to activate alternate functions
- READ key, to perform measurements; DATE key, to display (toggle) current date and time (with ALT)
- 8) STO key, to store sample after reading; VIEW key, to view log memory (with ALT)

SPECIFICATIONS

Range	0 to 10.00 EBC
	10 to 250 EBC
Resolution	0.01 EBC or 1 EBC
Accuracy	± 0.20 EBC $\pm 3\%$ of reading (0.00 to 10.00 EBC) ± 1 EBC $\pm 5\%$ of reading (outside)
Typical EMC Deviation	±1% F.S.
Light Source	Infrared LED @890 nm
Light Source Life	Life of the instrument
Light Detector	Silicon Photocell
Power Source	4 x 1.5V AA alkaline batteries
Battery Life	60 hours or 900 measurements
Auto-off	After 5 minutes of non-use
Environment	0 to 50°C (32 to 122°F); RH max 95% non-condensing
Dimensions	220 x 82 x 66 mm (8.7 x 3.2 x 2.6")
Weight	510 g (1.1 lb.)

OPERATIONAL GUIDE

The instrument is supplied complete with batteries. Before starting operations, install the batteries while paying attention to their polarity (see also "Battery Replacement" section). To maximize the battery life the meter automatically switches off after 5 minutes of non-use. For reactivating it, simply press the ON/OFF key.

TAKING MEASUREMENTS

- \bullet $\,$ Turn the meter ON by pressing the ON/OFF key.
- At start-up the meter will show the full display for a few seconds, followed by the indication of the remaining battery percentage.



- When the LCD displays "----" the meter is ready to measure.
- Fill a clean cuvette up to 0.5 cm (one quarter inch) from its rim with the thoroughly agitated sample.



• Allow sufficient time for bubbles to escape before securing the cap.

Note: Do not over-tighten the cap.

- Wipe the cuvette thoroughly with a lint-free tissue (HI731318) before inserting into the measurement cell.
 - The cuvette must be completely free of fingerprints and other oil or dirt, particularly in the area where the light goes through (approximately the bottom 2 cm/1 inch of the cuvette).



 The mark on the cuvette cap should point towards the LCD.





 Press the READ key and the LCD will display a blinking "SIP" (Sampling In Progress). The measured value will appear after approximately 25 seconds.








SOURCES OF INTERFERENCE

- Presence of floating debris and coarse sediment which settle out rapidly will give false readings.
- The infrared light source used for HI 93124 Haze meter can effectively minimize
 errors due to coloured dissolved substances. This effect, named "true colour",
 is a common interference for most commercially available instruments operating
 in the range of visible light.
- Air bubbles and the effect of vibrations that disturb the surface of the sample will give false results.
- Dirty glassware could also affect readings along with scratched or edged cuvette.

LOG-ON-DEMAND

The meter can store up to 199 measurements in the internal memory. Press
the STO key: the last measured value will be stored and the display will show
the reference number of the stored sample.





 When the maximum number of samples (199) is reached, the LCD will display the "FULL" message to warn the user that next value will overwrite the oldest sample recorded.



All samples will be shifted (reference number reduced by one) and the ref. number one will continue to indicate the oldest value. To confirm storing of the current sample, press the STO button again.

CLEARING LOGGED DATA

 For clearing all data stored in memory, press ALT + CLR keys: the meter will ask for confirmation by displaying the "CLr" message.



Press ALT + CLR again to clear memory or any button to abort the operation.

VIEWING LOGGED DATA

- Press ALT + VIEW keys: the last sample will be displayed.
- Press the "right arrow" key to scroll among turbidity value, date and time of the sample.
- Press the "up/down arrow" keys to view next sample and use the "right arrow" to scroll the date and time.
- Press ALT+VIEW again to exit and return to measurement mode.

VIEWING AND SETTING DATE AND TIME

VIEWING

Press ALT + DATE to toggle between date and time.

SETTING

- Press and hold ALT + DATE for 3-4 seconds.
- Press the "up/down arrow" keys to set the year.
- Press the "right arrow" to scroll to month & day, then use the "up/down arrow" keys to set the date.
- Press the "right arrow" again to scroll to time, then use the "up/down arrow" keys to set the time.
- Press the "right arrow" again to save and exit from setup mode.

Note: Press ALT + DATE to exit without saving.

RS232 CONNECTION

To communicate with the instrument through the **HI92000** software, simply connect the 9-pin serial port of the PC to the 5-pin connector of the meter, by using the **HI920011** cable (optional).

The meter will maintain its full functionality, being also able to perform data transfer while operating.

Notes:

- RS232 communication is not allowed during calibration.
- The auto-off feature is disabled when the meter is connected to a PC.

CALIBRATION

If repeated measurements differ more than an acceptable value, check if the meter calibration status by measuring a standard solution.

Anyway, it is recommended to perform a monthly calibration of the meter, or more frequently for greatest accuracy.

To check the date of last calibration, simply press the GLP/CAL key. Press again to togale between date and time.

CALIBRATION PROCEDURE

 Turn the meter on and wait for the display to show dashes "----".



Press ALT + CAL keys, the "CAL" message will blink on the display 3 times, then
the meter enter the calibration mode asking for the 0 EBC standard.





 Fill the measurement cuvette with HI 93124-0 standard (@ 0 EBC).



Note: In order to minimize any error introduced by the cuvette, it is recommended to use the same cuvette during calibration and for measurements.

 Insert the cuvette with the O EBC standard solution (or turbidity-free dilution water) into the measurement cell and press the CAL key. "SIP" and "CL" will start blinking.



 After approximately 30 seconds the instrument will ask for the 2.5 EBC standard solution.



 Repeat the same procedure with HI 93124-1 standard solution (@ 2.5 EBC): fill the cuvette the HI 93124-1 standard, insert into the measurement cell and press the CAL key again. After approximately 30 seconds, the meter will display "125", asking for the 125 EBC solution to be placed in the cuvette holder.



Note: At this point the user can exit the calibration mode and save the two-point calibration by pressing ALT + CAL keys.

- To perform a three-point calibration, place a cuvette filled with HI 93124-2 standard solution (@ 125 EBC) in the cuvette holder.
- Press the CAL key. "SIP" and "CL" will start blinking.
- After approximately 30 seconds, the display will show "---".



Now the meter is calibrated and ready for use.

VIEWING CALIBRATION DATE

To display the last calibration time and date, press the GLP button to toggle through date and time. If the display shows "FS", the instrument has factory calibration settings loaded and no date will be displayed.



STANDARD SUSPENSION

Hanna Instruments supplies **HI 93124** with the AMCO-AEPA-1 standards which has a long shelf life at all concentrations (approximately six months, if free from contamination). In addition, no special handling or disposal is required and a much higher stability of suspended particles has been observed.

On the other hand, the formazine-based standards are very toxic, carcinogen and unstable (particles flocculate and settle quickly). Lower concentrations change value within a few days or hours after dilution from stock solutions.

The consistency of **HI 93124** readings by using both standards has been separately established by Advanced Polymer Systems and Hanna Instruments.

Additional documentation about the formazine standard and more complex calibration procedures is available upon request.

TIPS FOR ACCURATE OPERATION

The instructions listed below should be carefully followed during testing and during calibration.

- All glassware that comes into contact with standards should be maintained clean. Wash with H193703-50 cleaning solution and rinse with H193124-0 or turbidity free water.
- For consistent readings, it is recommended to perform measurement immediately after collecting sample.
- To obtain a representative sample, gently mix the liquid before samples are taken. Do not shake (to prevent air bubbles) and do not let the sample settle.
- Rinse the cuvette twice with 5 ml of the liquid to be tested for removing the effect
 of dust or any previous liquid. Gently pour the liquid down the side of the cuvette
 to reduce air bubbles.
- Try to tighten the cuvette cap always to the same degree.
- Before inserting the cuvette into the instrument, wipe it with soft, lint-free tissue.
 Handle cuvettes so that no fingerprints can get on the areas where light passes (approximately 2 cm/1 inch from the bottom of the cuvette).
- Discard the sample soon after the reading is taken to avoid permanently clouding the glass.

If any problem is experienced during measurements, please contact your dealer or the nearest Hanna Instruments Customer Service Department.

LCD ERROR CODES

Every time the meter is switched on, the RTC (Real Time Clock) and the internal memory (EEPROM) are tested.

If an error occurs, the corresponding error code will be displayed.

Here below are listed the error codes:

No cover error; check cuvette position

688

Calibration error; check calibration standard solution

Err

Real Time Clock error (*)

Errē

EEPROM error (*)

Erra

Internal communication error (*)

5--4

Internal Bus error (*)

5--5

(*) Contact the nearest Hanna Instruments Customer Service Department.

BATTERY REPLACEMENT

In order to minimize the battery consumption, the meter is equipped with an autoshut off function which switches the meter off after 5 minutes of non-use.

The meter is powered by 4 alkaline batteries (1.5V AA), which are constantly monitored by the meter to ensure reliable readings.

A "LO BAT" indication will appear on the display when the batteries become weak and require replacement; the instrument can perform only 50 more measurements.



A "0% LO BAT" message will appear on the display when the batteries level is too low for performing measurements; the message appears for a few seconds, then the meter automatically shuts off; immediately replace the batteries.



Battery replacement must only take place in a non hazardous area using 4 alkaline batteries, 1.5V AA size.

Turn the meter off, unscrew the 2 screws on the back of the instrument and remove the battery cover. Substitute the rundown batteries with new ones, while paying attention to their polarity. Reattach the battery cover and tighten the 2 screws.

ACCESSORIES

HI 93124-0	Calibration solution, O EBC, 30 mL bottle
HI 93124-1	Calibration solution, 2.5 EBC, 30 mL bottle
HI 93124-2	Calibration solution, 125 EBC, 30 mL bottle
HI 93124-03	EBC Haze calibration set (HI 93124-0, HI 93124-1, 93124-2)
HI731318	Tissue for wiping cuvettes (4 pcs)
HI 731321	Spare measurement cuvettes (4 pcs)
H192000	$Windows^{\circledR}\ compatible\ application\ software$
HI920011	5 to 9-pin RS232 connection cable
HI 93703-50	Cleaning solution, 230 mL bottle

14

CE DECLARATION OF CONFORMITY



Recommendations for Users

Before using this product, make sure that it is entirely suitable for the environment in which it is used.

Operation of this instrument in residential area could cause unacceptable interferences to radio and TV equipments, requiring the operator to take all necessary steps to correct interferences.

Any variation introduced by the user to the supplied equipment may degrade the instrument's EMC performance.

To avoid electrical shock, do not use this instrument when voltages at the measurement surface exceed 24VAC or 60VDC.

To avoid damages or burns, do not perform any measurement in microwave ovens

Hanna Instruments reserves the right to modify the design, construction and appearance of its products without advance notice.

15

Ш

SALES AND TECHNICAL SERVICE CONTACTS

Australia:

Tel. (03) 9769.0666 • Fax (03) 9769.0699

China:

Tel. (10) 88570068 • Fax (10) 88570060

Egypt:

Tel. & Fax (02) 2758.683

Germany:

Tel. (07851) 9129-0 • Fax (07851) 9129-99

Greece:

Tel. (210) 823.5192 • Fax (210) 884.0210

Indonesia:

Tel. (21) 4584.2941 • Fax (21) 4584.2942

Japan:

Tel. (03) 3258.9565 • Fax (03) 3258.9567

Korea:

Tel. (02) 2278.5147 • Fax (02) 2264.1729

Malaysia:

Tel. (603) 5638.9940 • Fax (603) 5638.9829

Singapore:

Tel. 6296.7118 • Fax 6291.6906

South Africa:

Tel. (011) 615.6076 • Fax (011) 615.8582

Taiwan:

Tel. 886.2.2739.3014 • Fax 886.2.2739.2983

Thailand:

Tel. 66.2619.0708 • Fax 66.2619.0061

United Kingdom:

Tel. (01525) 850.855 • Fax (01525) 853.668

USA

Tel. (401) 765.7500 • Fax (401) 765.7575

For e-mail contacts and complete list of Sales and Technical offices, please see **www.hannainst.com**

MANC124 R1 05/05