



This guide is intended for users of indicator i 30. It allows a quick start of the device. For the electrical connection and installation, refer to the following manuals:

- Wiring block diagram: 04-50-00 DD
- Installation Manual: 04-52-00 MI

Before first use, check the parameters for the application in configuration mode.

Safety

For devices connected through a power outlet, standard NF EN 60 950 calls for the base of this outlet to be installed near the equipment and to be easily accessed. For equipment connected permanently to mains, an easily accessible cut-off device must be included to the permanent installation.



Contents

Fo	re	w	n	rd

Documentary conventions	2
Recommendations	2
Overall view	
Keyboard	3
Navigation principle	4
Screen	5
Help area - Detail of the indication of valid keys	6
Basic parameters	6
Operator functions	
Introduction	7
Switching-on	7
Reset	8
Taring	8
Initial reset	8
Reminder of gross	9
Visualization of information	9
Metrological screen	10
Operator Parameter	
Introduction	11
Manually entry of a tare value (preset tare)	11
High resolution display	12
Reminder of gross	12
Consult DSD	13
Operator configuration	
Introduction	14
Configuration the parameters	14
Saving	15
Error messages	

Foreword

Documentary conventions





Important warning concerning the safety of persons.



Remark concerning the preservation and proper maintenance of the equipment.



Note designed to:

- Facilitate reading the manual;
- Implement the equipment optimally.

Terminology and abbreviations

Menu options or parameters are noted :

OPERATOR / OPTION 1 / OPTION 2... / PARAMETER

or

INSTALLER / OPTION 1 / OPTION 2... / PARAMETER

In this manual, the functions are all executed in OPERATOR mode, the notations are abbreviated as follows :

OPTION 1/OPTION 2.../PARAMETER

Recommendations

For optimum equipment accuracy and preservation:

- Do not subject the weighing instrument (the scale) to shocks or overloads.
- Do not store a load on the weighing instrument; discharge it as soon as the weighing has been completed.
- Never use solvents or abrasives products for cleaning.



Overall view

Keyboard



	Function	
	On / Off	Press and hold to turn the indicator on.
M	Application / Metrology	Toggles between the two operating modes.
MENU +	Configuration mode	Keep these keys pressed to turn on the power indicator in configuration mode.
ESC	Exhaust	Exit a menu or the entry in progress without taking it into account.
MENU	Menu	Allows entering configuration mode by pressing and holding the power on key.
	Confirmation	Entry in a menu or take the current entry into account.
	Directional keys	Navigating in the menu or list options. Indication < > in the help area.
•••	Reset	
ETP	Taring	
B/G	Reminder of gross	

Navigation principle

 The navigation keys allow moving through menus and lists of predefined values. They are active when the symbols () are displayed in zone 3 of the screen (See "Screen", page 5.):



Scroll through the options at the same level (or the possible values).



2. Confirm the selected option (or the selected value).

• In the same case, for the consultation of recorded values :





Scroll through the displayed information.

Entering an alphanumeric value :





Reach the previous or next position in the string to enter.





Enter a character: select next or previous character in alphabetical (or numeric) order.

· In case of navigation error:



Exit a menu, a section or option (up one level).


Reach the backup option (configuration mode) :



Go back up to the highest configuration menu level to achieve the backup option. Actuate the button repeatedly, if necessary.



Screen



		Function		
	Title / Symbol	Use		
1.	Weight areas	Display digital data: weight, number of pieces, calculated data.		
2.	User area	Indications to the attention of the user.		
3.	Help area	 NET indication if tare taken into account. Addition to unit. Indication of valid keys. See details below. 		
4.	kg g t lb	Unit.		
5.	D	 Application mode: Symbol D displayed. The displayed weight is not a metrological reference. Metrological mode No symbol. The displayed weight is not a metrological reference. 		
6.	W1 W2	Measuring range: Range 1 or 2 is active.		
	~	The weight is unstable.		
	> 0€	The weight is in the zero and stable zone.		
7.	•	Confirmation of the touch of a button.		

Help area - Detail of the indication of valid keys

0 - 9	Numeric entry.
O - Z	Alphanumeric entry.
1 - 6	Numeric entry between two specified values (ex. : between 1 and 6).
()	Indication of a menu (even if there is only one option).
ESC	Output of a screen showing data in display only.

Basic parameters

Language

PARAMETERS / LANGUAGE

Choose French or English.

Display device

PARAMETERS / JISPLAY / ECO MOJE allows adjusting the self-termination:

ON	Turn off the backlight after 30 seconds of inactivity, weight to zero.
OFF	Not self-extinguishing backlight.

- PARAMETERS / JISPLAY /BRIGHTNESS allows adjusting the backlight intensity: 3 termination levels.
- PARAMETERS / JISPLAY / COLOR allows setting the screen background colour: 7 possible colours.



The choice of a colour other than white no longer allows displaying the application mode text in colour.

Date and time

PARAMETER / DATE/TIME

Changing this parameter does not result in requesting a backup. It occurs automatically after setting the time.




Operator functions

Introduction

The operator functions are available from the moment power is applied to the indicator.

Switching-on

 The instrument performs a self-test.
 Check the proper operation of the display screen (no defective segments).



2. The software version is displayed.



The self-test is completed, the instrument initiates the measurement and it is ready for use.



Reset

The reset function allows ensuring the instrument reset when the load receiver is empty and the weight displayed is not zero, (This function is limited to $\pm\pm2\%$ of the maximum instrument range from the initial zero in regulated use or to a configuration value outside the legal metrology).

 Empty receiver, the weight displayed is different from zero.



2. Select the reset function (). The weight displayed is reset.



Taring

The taring function allows storing the weight of the load in place on the receiver (container) as the tare value and then get the net weight of the product (displayed weight = current weight - tare). Thus the NET weight is viewed as positive when loading and negative in case of unloading).

1. Place the container on the load receptor.



Select the taring function ().
 The weight displayed is the net weight.



Initial reset

This reset can be done when the indicator turns on. To do this, when switching on, the user presses button until the unit starts. This zero is the reference to other reset devices.



Reminder of gross

1. The result of a weighing is displayed in net.



2. Press key BG.


The screen changes colour (cyan) and the result is displayed as gross weight for a few seconds.



Visualization of information

Press the **1** and **1** keys to scroll through the available information.

- 1. Bridge name,
- 2. Status of lights,
- 3. Time,
- 4. Message from lock.




Metrological screen

The following information are only accessible from the metrology menu ()

1. Press key 🖸 to view the metrological data.

The corresponding information are:

- MAX : Maximum device range (A).
- e : level (B).
- Event.Cnt (C).





Operator Parameter

Introduction

Once in the metrological screen (), press key to access the parameterization operator. Then use the key and keys to access the different functions available.

☐ Manually entry of a tare value (preset tare)

This function allows you to manually enter a tare value for the net weight display from 0 to MAX (0 to cancel the preset tare).

1. Select the preset tare function PT and confirm it (1).



2. The current value of the tare weight is displayed.



- Enter the new tare value by pressing the arrow keys.
 - et Change the value of the selected digit.
 - and: : Move from one digit to another.



4. Confirm the new value ().

The value is taken as the tare value. The weighing result is now viewed on the Net.



High resolution display

1. Switch to metrology mode ().



- 2. Press key and scroll through the various functions with the arrow keys.
- 3. Select the HR function then confirm (■).
- The result is displayed with the precision associated with high resolution during a few seconds in Legal Metrology and remains permanent outside Legal Metrology.





Reminder of gross

1. Switch to metrology mode ().



- 2. Press key and scroll through the various functions with the arrow keys.
- **3.** Select the \mathbb{B} - \mathbb{G} function then confirm (\mathbb{L}).
- The screen changes colour (cyan) and the result is displayed as gross weight for a few seconds in Legal Metrology and is permanent outside Legal Metrology.







Consult DSD


- **1.** Switch to metrology mode ().
- 2. Press key and scroll through the various functions with the arrow keys.



3. Select the \$\mathbb{I} 5 \mathbb{I}\$ function then confirm (\begin{align*} \blue{\mathbb{L}} \end{align*}).




4. Select the READ ISD function then confirm (1).



or select function REF. ISI then confirm

This reference allows identifying a bridge.



6. Enter the number of the record to see the keys and then confirm.

Remark: Enter 0 to display the last recording.

∏ kg 0-9

7. Confirm again to display the information corresponding to the file.



Operator configuration

Introduction

Simultaneously press keys + 0 at power-on or at restart of the indicator to access the operator configuration.

Configuration the parameters

These parameters are accessible from the configuration menu.

1. Access to the configuration menu.

LOGIN / OPERATOR / APP.

For MEASUREMENT and PARAMETERS menus, refer to the installation guide (04-52-00 MI).

- 2. Fill the BRIDGE NAME parameter.

 This parameter allows you to assign a name to the bridge of up to 10 characters.
- 3. Fill the LOCK MSG parameter.

 This parameter allows choosing the message to be displayed when the presence threshold is reached and the LOCK entry is active.
- 4. Fill the LOCK WT parameter.

This parameter is active when the LOCK entry is active:

- YE5⇒ the weight is displayed in red on the screen.
- N□⇒ the weight is not displayed.
- 5. Fill the PRES THRES parameter.

The following two parameters are configured by the installer.

- **6.** Fill the LIGHT 1NAME parameter. This parameter allows you to assign a name to the entry light.
- Fill the LIGHT2NAME parameter.
 This parameter allows you to assign a name to the exit light.



Saving

When the configuration parameters have been changed, the backup can be done in two ways :

- By going back to the highest level in the configuration menu:
- by pressing key ...



The SRVE option screen is displayed for about 1 s, then the choice whether or not to confirm the modified parameters is proposed.




Select ND to return to the configuration menu without saving the modified parameters.



Select YE5 to return to the configuration menu after saving up the modified parameters.

Error messages

- 1. Instrument under-loaded.
 - · Check the load receptor.
 - · Reset to zero.
- 2. Instrument overloaded.
 - Remove part of the load.



- 3. Command denied
 - · Example: Taring with unstable weight



4. Reset denied

The weight limit for this function has been exceeded.

· Remove the load and press the reset key.





Head Office & Plant PRECIA-MOLEN BP 106 - 07000 Privas - France Tel. 33 (0) 475 664 600 Fax 33 (0) 475 664 330

E-MAIL webmaster@preciamolen.com

RCS: 386 620 165 RCS Aubenas

