CONTENTS

PRECAUTIONS	2
INSTALLATION	
Load Cell Connections	2
Setting up the platform	3
LCD Display and function of each key	. 4
FUNCTIONS	
Numeric Keys and Decimal Key	4
ZERO	. 4
TARE	4
Accumulation	5
Accumulation Display	. 5
Clearing Accumulation	6
Clearing Input Value	6
$\lceil + floor$	6
Unit Switch Key	7
Unit Price Memory	7
SPECIAL OPERATION	
Unit Price Memory Setting	. 8
Initial Unit Selection	. 8
Parameter Function Setting during Operation	9
PARAMETER SETTING	
Parameter Setting	10
Parameter Values	
APPENDICES	
Product Type Specifications	11
List of Error Messages	
RS232 Output	

[PRECAUTIONS]

DO NOT use the scale or indicator


- ◆ Please fully charge the battery after unpacking the scale.
- Install the equipment on a level and stable surface.
- ◆ Do not use the equipment in an environment with strong wind, vibration or electromagnetic wave (e.g. near an air conditioner outlet, fan outlet or a heavy machine).
- ◆ Operation temperature: -10°C~40°C, and try not to use in the environment with rapid temperature changes. Please use independent power socket to avoid interference (transformer is built-in).
- ♦ Warm up the equipment for 15 minutes before use.
- **Recharge the battery**: Please charge the battery when battery symbol appears on the LCD display, which means the battery is running out. During charging, the charge indicator will light up in red; when charging is completed, it turns green. (It takes about 8 hours to fully charge the battery.)

Leveling Adjustment

The electric scale shall be placed on an even place. Check the level gauge of the scale to see if the scale is in a level position. If not, adjust the adjustable feet of the scale.


[INSTALLATION]

Load Cell Connection




	PIN	SIGNAL
	1	E+
LOAD CELL	2	E-
CONNECTION	3	S+
	4	S-
	5	SHIELD

Setting up the platform



- Run the Load Cell wire on the erecting pole holder (1) through the erecting pole (2), insert the erecting pole (2) into the hole in the erecting pole holder (1), then lock the two screws (6) tight.
- Run the Load Cell wire through the lower bracket (3), and insert the lower bracket (3) into the erecting pole (2), then lock the screw (7) tight.
- Run the Load Cell wire through the upper bracket (4), and connect the display head (5), then insert the upper bracket (4) into the slot (9) till 1/2 position. [Be sure to place the wire outside the upper bracket]
- Place the Load Cell wire inside the wire groove (10), assemble the lower bracket (3) and the upper bracket (4), and then fully insert the upper bracket (4) into the slot (9), lock the upper bracket (4) and the lower bracket (3) by use of knob lever (8), and insert pin (11).
- Use the knob lever (8) to adjust the display head to the optimum position and lock tight.

LCD Display and function of each key



[FUNCTIONS]

Numeric Keys and Decimal Key

Keys 0 ~ 9 and • are used to key in the show value in the Unit Price Window or other functions.

<u>ZERO</u>

When there is residual value in the Total Weight Window, press ZERO key and the Total Weight Window will show ZERO.

TARE

- 1. Place the tare object on the weighing pan.
- 2. Press TARE key.
- 3. Tare cancellation: Press TARE key to cancel.

Accumulation

a. When accumulating the prices of more than one kind of object, input the unit prices and place the objects on the weighing pan until they are stable, press M+ key to perform accumulation, the Total Weight Window, Unit Price Window and Total Price Window will show MLL.XX, ---- and XXXXXX in turn, which means total data, no display and total price respectively. Press any Numeric key to input the next unit price or press CE key to return to normal weighing mode.

- b. Accumulation can only be performed in the stable mode (±0.1e).
- c. If the total data is over 10, the Unit Price Window will show LLL.ou, which means the total data is over the range. Accumulation will not be performed, and the scale will return to normal weighing mode in one second.
- d. When the digit number of total price (incl. decimals) is beyond the display range, the Total Weight Window will show will show beyond the display range. Accumulation will not be performed, and the scale will return to normal weighing mode in one second.
 - * When the price is zero, accumulation will not be performed.

Accumulation Display

- a. When accumulation is performed, press MR key to display accumulation data, the Total Weight Window, Unit Price Window and Total Price Window will show LL.XX, ---- and XXXX in turn, which means total data, no display and total price respectively. Press MR key once again, the Unit Price Window will show LL.XX and XXXXX in turn, which mean total number of data of this count and unit price of this count. The Total Weight Window and Total Price Window will show XXXX and XXXX in turn, which mean weight of this count and total price of this count.
- b. Press any Numeric key to input the unit price or press CE key to return to normal weighing mode.
 - Display of a single record includes decimals, display of total price does not include decimals (rounded).

Clearing Accumulation

a. Clearing a single record

Press MR key till the Unit Price Window shows RLL.XX, press MC key to clear this record.

b. Clearing all records

Press MR key till the Total Weight Window, Unit Price Window and Total Price Window show RLL.XX, - - - - and XXXXX respectively, press MC key to clear all accumulation records and the scale will return to normal weighing mode automatically.

Clearing Input Value

To clear the number shown in the Unit Price Window, press MC key and the Unit Price Window will show 0.

$\llbracket + floor$

- a. In the price calculation mode:
 - 1. E.g.: the Total Weight Window, Unit Price Window and Total Price Window show

 - 3. Input the known price to be added (25), the Total Weight Window, Unit Price Window and Total Price Window will show [75], [25] and [35] respectively.
 - 4. Press ZERO key to return to price calculation mode.
- b. In the accumulation display mode:

 - 2. Input the known price to be added (25), the Total Weight Window, Unit Price Window and Total Price Window will show [75], [75] and [XXX+25] respectively.
 - 3. Press ZERO key to return to accumulation display mode.
- c. In non-weighing mode:
 - 1. The Total Weight Window, Unit Price Window and Total Price Window will show **XXXXX**, and number in turn.

2.	Press +	key, the Total Weight Window, Unit Price Window and T	otal Price
	Window will	I show REE, I and I in turn.	

- 3. Input the known price to be added (25), the Total Weight Window, Unit Price Window and Total Price Window will show [75], [25] and [25] respectively.
- 4. Press ZERO key to return to non-weighing mode.
 - Input values repeatedly and press + key, the input values will be added continuously.

Unit Switch key

In the normal non-weighing mode without accumulation, press UNIT key, the windows will show In E and XX in turn, which means unit, setting and corresponding number respectively. Press Numeric key to select the unit of corresponding number; the scale will return to normal weighing mode in one second. (The unit selection is price unit selection)

* Press ZERO key to directly return to weighing mode without switching.

Unit Switch Table							
Numeric Key Unit in Weight Window Unit in Unit Price Window							
1	Kg	/Kg					
2	lb	/lb					
3	Kg	/100g					

Unit Price Memory

In normal non-weighing mode with unit price memory function off, press PLU key, the Unit Price Window will show PLU, press Numeric key to select unit price memory group; when the Unit Price Window shows PLU XX, it indicates the memory group selected, and in one second, the values saved in this memory group will be displayed.

- In normal non-weighing mode with unit price memory function on, press Numeric key to switch memory groups and press CE key to exit.
- * This function shall be effective after saving unit prices.

[SPECIAL OPERATION]

Unit Price Memory Setting

a.	Hold down any Numeric key to turn power on: the Total Weight Window, Unit Price
	Window and Total Price Window will show PLU, UP and SEL in turn.
b.	Press Numeric key to select unit price memory group, the Total Weight Window, Unit
	Price Window and Total Price Window will show [XXXXX and XX in turn, which
	indicates unit price memory setting, unit price to be memorized and memory group
	respectively.
c.	Press Numeric keys and • key to input unit price to be memorized.
d.	Press PLU key to confirm, the Total Weight Window, Unit Price Window and Total Price
	Window will show \[\frac{\beta \left{Lii}}{\text{lip}} \] and \[\frac{\sqrt{E} \text{L}}{\text{lip}} \] in turn.
	※ Repeat steps b and c until setting is completed.
e.	After setting is completed, press ZERO key to return to normal weighing mode.
<u>Initi</u>	al Unit Selection
a.	Power on while holding down MC key: the Total Weight Window, Unit Price Window and
	Total Price Window will show 58, and in turn.
b.	After pressing 1 1 3 2 keys: the Total Weight Window, Unit Price Window
	and Total Price Window will show 552, 1132 and in turn.
C.	After pressing MC key: the Total Weight Window, Unit Price Window and Total Price
	Window will show เกาะ , โระโ and XX in turn.
d.	Press 1 key to switch units (the unit selection is price unit selection): Depending on
	the region:
	Model for the Mainland: kg 500g 100g
	Model for export: kg lb 100g
	Model for Taiwan: kg tg 100g
	Model for Hong Kong: kg lb 100g hkj
e.	After pressing MC key: the Total Weight Window, Unit Price Window and Total Price
	Window will show 5££,

f. Press ZERO key to return to normal weighing mode.

Parameter Function Setting during Operation

- a. In normal weighing mode, hold down MC key for 3 seconds to enter into parameter setting; the Total Weight Window, Unit Price Window and Total Price Window will show SEE, and FUNL in turn.
- c. Press 3 key: the Total Weight Window, Unit Price Window and Total Price

 Window will show 5663, off and off respectively. Auto power-off time setting: off / 5 / 10 / 30 / 60, press 3 key to set. off: cancel auto power-off /auto power-off in 5 minutes / auto power-off in 10 minutes /auto power-off in 30 minutes/auto power-off in 60 minutes
- d. Press ZERO key to return to normal weighing mode.

[PARAMETER SETTING]

Parameter Setting

Turn power on by holding down ZERO key to enter into parameter setting; the Total

Weight Window, Unit Price Window and Total Price Window will show TEL, TIPLE

and FlinE in turn. Press ZERO key to return to normal weighing mode.

Parameter Values

Function	Display	Operating Instructions
Backlight	on / oFF / onoFF	Press 0 key: the Total Weight Window, Unit Price Window and Total Price
		Window will show [5] Window will show [5] Window will show [5] Light and [6] and [6] in turn; press [0] key to set.
Filter	1/2/4/8	Press 2 key: the Total Weight Window, Unit Price Window and Total Price
		Window will show [FILE] and [in turn; press 2 key to set.
		* The bigger the number is, the higher filter performance is and the slower the
		display speed is.
Auto	off / 5 / 10 / 30 / 60	Press 3 key: the Total Weight Window, Unit Price Window and Total Price

power-off		Window will show FFF, and FFF in turn; press 3 key to set.
Baud	2400bps / 4800bps	Press 5 key: the Total Weight Window, Unit Price Window and Total Price
rate	/ 9600bps	Window will show 1775, 2000 and 2000 in turn; press 5 key to set.
Data	Co / St	Press 9 key: the Total Weight Window, Unit Price Window and Total Price
output		Window will show [FFE], [FFE.5]E and [FE] in turn; press [9] key to set.
mode		※ When output mode is St, input unit price before placing weight and the price
		will then be output normally; when output mode is Co, the display speed is
		slower.

[APPENDICES]

Product Type Specifications

Ma. Oan /	Model							
Max. Cap / Resolution	JPF	P-3K	JPF	P-6K	JPP	-15K	JPP-30K	
resolution	3kg	3kg	6kg	6kg	15kg	15kg	30kg	30kg
DIV.(kg)	0.0005	0.001	0.001	0.002	0.002	0.005	0.005	0.010
DIV.(lb)	0.001	0.002	0.002	0.005	0.005	0.010	0.01	0.02
DIV.(tg, tl)	0.00.01	0.00.02	00.00.1	00.00.1	00.00.1	00.00.2	00.00.2	00.00.2
DIV.(hkj, hkl)	0.00.01	0.00.02	00.00.1	00.00.1	00.00.1	00.00.2	00.00.2	00.00.2
May Can /				Мо	del			
Max. Cap / Resolution	JPP-	-60K	JPP-	150K	JPP-	300K	JPP-	600K
rtocolation	60K	60K	150K	150K	300K	300K	600K	600K
DIV.(kg)	0.010	0.020	0.02	0.05	0.05	0.10	0.10	0.20
DIV.(lb)	0.02lb	0.05lb	0.05lb	0.10lb	0.10lb	0.20lb	0.2lb	0.5lb
DIV. (tg, tl)	00.01	00.01	00.01	00.01	00.02	00.02		
DIV.(tg)							0. 2	0.5
DIV. (hkj, hkl)	00.01	00.01	00.01	00.01	00.02	00.02		
DIV.(hkj)							0.2	0.5
Internal Resolution				Over 6000	00 (SPAN)			
Display Spec.		LCE) module re	quires back	dight, 5, 5,	5 Digits. (E	L)	
Dimensions (mm)				666 x 43	30 x 910			
Power Supply			AC110V/22	20V incl. 6	SV4A lead-a	cid battery		
Resolution	1/6000, 1/3000, 1/7500							
Weighing Unit	Kg, Lb, tg, hkj							
Operating Temperature	-10°C~40°C							
Option				RS:	232			

List of Error Messages

In case of	Error Message	Troubleshooting					
Power on	Err2,	Initial zero point over 30%.					
Power on	Err3,	Check if there is A/D malfunction or LOAD CELL malfunction.					
Power on		Switch power off and power on again; if the error message appears again, switch power off and perform calibration again.					

Power on	Battery symbol shown	Charge the battery.
Normal weighing mode	Err5	Checking if the weighing object is over the max. capacity +9e.

Error Message	Problem							
Err2	Check if there is any object on weighing pan, which may cause interference.							
Err3	Over or below A/D resolution range							
Err4	EEPROM Chksum error							
Err5	Overload (max. capacity +9e)							
ACC.ov	Accumulation over 10 data							
over	Display value over display range							
Battery symbol	Low battery							

RS232 Output

RS232 Output Format

RS232 transmission format parameters are as follows:

Baud Rate: 2400bps / 4800bps / 9600bps

Data Bit: 8
Stop Bit: 1
Parity: NONE
Code: ASCII

Bit Format:

LSB						MSB				
	0	1	2	3	4	5	6	7	8	
Start Bit									Parit	Stop Bit

Data Format

1. kg					
G/N . W . :			k g CR	LF	
Weight					
U . P . :			\$ / k g		CR LF
Unit price					
P r i c e	:		\$		CR LF

Price

Example:

G.W.:5.000 kg N.W.:4.000 kg U.P.:100 \$/kg Price:400 \$

