

THIS INFORMATION PROVIDED BY AUTOMATIONDIRECT.COM TECHNICAL SUPPORT IS SUPPLIED "AS IS", WITHOUT ANY GUARANTEE OF ANY KIND. These documents are provided by our technical support department to assist others. We do not guarantee that the data is suitable for your particular application, nor do we assume any responsibility for them in your application.

PRODUCT FAMILY: SureServo


Number: AN-SERV-009

Subject: Sureservo with CLICK PLC

Date issued: May-20-2009

Revision: First Edition

This is a similar example as the application note AN-SERV-007 but with a Click PLC. This simple example demonstrates how to use a Sureservo to control a linear movement. It is shown how to program a Click PLC, the servo drive and operator interface. The machine is shown in the simple diagram below:



This is a device that moves horizontally a 1000 lb tool car, with the help of a chain and sprockets, through a maximum distance of 830 mm from the Home position, at a desired distance entered by an operator. This could be for example, a device similar to a garage door opener but could also be a picking machine or an X-Y table where only the X axis is shown.

The mechanical department has defined that the sprocket is a 26 teeth, ANSI 40 sprocket and the maximum speed of motion is 1.0 m/second. The acceleration and deceleration time is 0.6 s. The load is 1000 lb and the friction on the wheels has a coefficient of about 0.1.

Typically the operator will set the information of the target position on the operator interface, and he will need to move it in the range of 0 to 830 mm from the Home position, with the best precision possible (Considering that the chain does not have stretching).

At the start of the job, when the servo system is enabled, the machine shall go to the Home position, located at 100 mm from the driving sprocket; the Home is determined by a proximity sensor. There are also overtravel limit switches.

We have selected to use a PLC C0-05DD1-D and an operator interface EA7-T10C allowing the operator to control the target position of the tool.

See mechanical considerations on the application note AN-SERV-007. From there it can be seen that the motor to be used is one of 1 kW.

Use of MODBUS with *Sureservo*

A characteristic of the *Sureservo* drive is the possibility of linking the registers of the servo as slave to a PLC as a master using MODBUS RTU.

What happens if we desire to change the desired position by a distance selected by an operator?

The desired displacement can be set through an operator interface by selecting one of the eight positions in the preset target positions. Or can be set in the memory of the PLC by MODBUS and the operator interface will just write the desired displacement amount.

The Click PLC can use port 2 with up to 115.2 kBaud. Software allows the programming of instructions SEND and RECEIVE in a very simple way.

The writing of the target positions is one of many possibilities; it has, of course, the possibility to read the status, the current position, the current torque, the speed as a number (and not only through one analog signal). With these data we can change other parameters such as the acceleration and deceleration, the torque and speed limits, etc.

A group of status registers (P0-04 to P0-08) are available in the *Sureservo* drive as well as a group of block data transfer registers (P0-09 to P0-16).

These consecutive register blocks can be used to group miscellaneous drive parameters together allowing you to read and write the desired parameters in one communication block instead of having to use a read or write instruction for each parameter. These are used extensively in this application note.

You can easily create a control system with servo using a serial MODBUS network. Let us see in the next pages one way to implement this control project.

Control concept

In this example we will need to run the motor with a target position, given by the operator, directly in mm, entered in the operator interface. This value should be scaled to transform the desired linear distance into revolutions and fractions of a revolution on the servo shaft.

The operator would see where the tool is located at any given time.

The acceleration, maximum speed and deceleration are fix values.

The home search is done by an operator command from the C-more panel.

The brake is released when the servo is enabled.

The motion in this case is ideally suited to be absolute motion with internal registers. This will define the parameter P1-01 as 1 or 101 and parameter P1-33 as 0.


Steps for the execution of the control

This is the sequence of operations that shall be followed in this example to get the system up and running:

- Define the control hardware to be used
- Select and set the communication parameters.
- Read the status of the servo through MODBUS, using the RECEIVE instruction.
- Measure the communication speed in transactions per second.
- Be sure that the servo is set to write data in RAM memory only.
- Make the details of the block transfer parameters.
- Define the values of parameter group P0.
- Define the value of P3-08.
- Define the main parameters in the servo.
- Define the factor of revolutions versus displacement.
- Some C-more programming concepts defined
- Define the digital inputs to be used for commanding the servo.
- Operator would order the system to search for the home position. When the Home is found and the servo is stopped, the current count shall be "zeroed".
- Reading the servo status from PLC.
- Operator shall write the desired target position and send to the PLC.
- Create the scaling of the displacement versus rotation of the servo shaft.
- Test the program together with the servo.
- Add the revolutions and counts of displacement and scale it to show the current displacement.
- Read servo output data (To be used the status data in P4-09 to create logic for the operation)
- Test the program and correct any errors.
- Prepare documentation to describe to the operator what it is necessary to operate the machine. Create operating instructions on the C-more panel as screen text data on the Operator panel, accessible from the main page.

Hardware design: One possibility is to link the PLC to the servo and operator interface with cables as shown in the following figure, using RS-232 with the cable SVC-232RJ12-CBL-2. The power supply shown here could be, for example, PS24-075D or it could be the one from the Click family, the part C0-01AC.

Connect the servo to the PLC on port 2, wire the inputs and outputs to the Ziplink module and use port 1 of the PLC for programming it.





Select and set the communication parameters:

Set P3-00 parameter to the desired slave address. In this case we will use the value 2, that is, servo drive slave 2.

Then set a value 3 in P3-01, that defines the transmission rate as 38400 kbps (Kilo bits per second). This value also must be set in the configuration of PLC port 2. P3-02 defines the protocol and the configuration of the same port. In this case, let us select 8. Finally, we set the P3-05 value for RS-232 with a value of 0. This servo configuration is done with the keypad of the servo drive. Notice that the PLC can communicate at a higher baud rate of 115.2 kbps.

The communication parameters in the PLC are configured with the CLICK programming software and we show here the values, in the figure below. To get to this dialog box you have to click on the menu SETUP and then select COMM PORT SETUP. Then select the SETUP button.

See more details on the port 2 set up in the CLICK user manual. Then we must connect the PLC with the servo drive.



First, set a value of 10 in the P2-08 parameter with the keyboard to configure all the values of the servo as default values.

It may appear errors ALE14, ALE15 and ALE13 on the servo drive display, and this would be normal if not wired properly. You may need to wire the overtravel limit switches to get rid of the alarms or simply disable the inputs, for now.

The fault ALE14 in the servo display indicates that the overtravel limit switch is activated, and this is true, since of P2-15 default (that corresponds to the DI6 input function) it set as 22, P2-16 (that corresponds to the DI7 input function) is set as 23 and P2-17 (that corresponds to the DI8 input function) is set as 21.

In order to clear the faults press the “arrows up and down” keys on the keypad simultaneously clearing any error that may be there, or it is also possible to power cycle the servo drive to get the same function.

Next, be sure that the value of the motor code is set in the P1-32 parameter.

Read status from servo on the PLC

Set up the PLC according to the code in next page. This is a simple RECEIVE instruction that will be executing as often as possible.

Connect the port 2 of the PLC to the servo, as shown previously.

When the servo brake is released by applying 24 VDC to the coil of the servo brake (Yellow and orange wires on the power cable) and the axis of the motor turns freely, the data that is contained in the memories P0-00 up to P0-08 can be seen changing.

We will attempt to read data from the servo with MODBUS RTU.

These memories have addresses 40001 up to 40009, as it is in the table below. Note

Parameter	Value	MODBUS address	PLC memory	Description
P0-00	2105	40001	DS1	Software version
P0-01	14	40002	DS2	Fault code
P0-02	0	40003	DS3	Display code
P0-03	1	40004	DS4	Analog monitor
P0-04	0	40005	DS5	Status monitor 1
P0-05	0	40006	DS6	Status monitor 2
P0-06	0	40007	DS7	Status monitor 3
P0-07	0	40008	DS8	Status monitor 4
P0-08	0	40009	DS9	Status monitor 5

that the CLick PLC addressing has 6 digits.


The parameters P0-04 to P0-08 should be changed to be able to read data that makes sense.

The adjacent second table shows what is to be set on each parameter with the help of the keypad.

Parameter	Value	MODBUS address	PLC memory	Description
P0-00	2.105	40001	DS1	Software version
P0-01	14	40002	DS2	Fault code
P0-02	0	40003	DS3	Drive Status
P0-03	1	40004	DS4	Analog monitor
P0-04	1	40005	DS5	Current revolutions
P0-05	0	40006	DS6	Current counts
P0-06	6	40007	DS7	Current rpm
P0-07	11	40008	DS8	Current % torque
P0-08	13	40009	DS9	DC Bus voltage

In order to be able to read the data from the servo drive and to verify that the connections are correct, we suggest to run the program shown in the following diagram:

Ladder code for Reading data from Servo



This is the explanation of the operation:

On the first scan, the RECEIVE instruction is executed. Data in memory 40001 thru 40008 are read and the content is copied from DS1 to DS8.

C1 is a bit in the PLC that turns ON when there is communication. It is called "Receiving" and indicates when the PLC is transmitting data through the communication in port 2, and turns OFF when the data transmission is completed.

Let us say that the PLC scan takes 2 ms; when beginning the transmission the contact C1 closes indicating that the rung is true to allow the transmission be executed. When establishing the transmission, C1 turns ON; when the transaction completes, C1 is OFF again and C2 is turned ON; then another transaction begins and thus it follows continuously.

Typically the transmission takes more than the PLC scan time. In this case it is approximately 20 ms. We will see later how to measure this value.

Also, the functions in P0-04 to P0-08 parameters allows to monitor what it is desired to see in the PLC and later in the operator panel.

When the parameter changes have been done, you can move the shaft of the servomotor if the brake is released and it will be possible to observe with Data View that the DS6 memory shows the same number as the display on the servo when the shaft of the motor moves. See the figure below. showing the Data View information, with nicknames.

This allows checking that the communication has been established.

Data View -[DataView1]				
Edit		Fill Down		Write All New Values
No.	Address	Nickname	Current Value	View
001	DS1	version	2105	Inte
002	DS2	Fault code	0	Inte
003	DS3	Drive status	0	Inte
004	DS4	Analog monitor	0	Inte
005	DS5	Current revs	8	Inte
006	DS6	Current counts	9078	Inte
007	DS7	Current RPM	0	Inte
008	DS8	Current torque	0	Inte
009	DS9	DC bus voltage	313	Inte
010				


Export

Measuring transactions per second

How can we measure the PLC scan time and how many transactions are happening per second?

Scan time:

Using the menu **PLC>Online Project Information**, as in the adjacent figure, to monitor the scan time.




At this time you should have about 2 ms current scan time.

See at the left figure the dialog box where it is indicated the scan time.

Transactions per second:

As we know, when a communication transaction begins, C1 will turn ON, and then we can count how many times this contact closes in 1 second, for example with a simple counter. Remember that a counter counts whenever there is a transition of the input from OFF to ON. See the diagram of the figure below with the corresponding ladder code and the explanations in each line.



The edge contact SC7 closes one scan every second; the copy instruction copies the current value of the count into DS1001

Every time C1 closes, the count increases by one. The current count of CT1 is loaded into CTD1.

The count is reset every second.

Here the RECEIVE instruction reads 9 words from addresses 40001 to 40009 in the servo and transfer the data into DS1 to DS9.

C1 turns ON while transmitting data and OFF when stopped.

You can read DS1001 in Data View and can see that the result is about 50 counts every second. Since there are 1000 milliseconds in a second, 1000/50 ms is approximately 20 ms. See the adjacent figure. This it is a good method to determine the transmission speed.

When already proven the comm link between the PLC and the servo, we should look at what algorithms to do in the PLC to be able to give the servo the proper values on the different parameters. Remember that we are still in the stage of creation of the program on the master PLC. Also it is necessary to define what data and how much data will be written to the servo drive.

Data should be written in such a way to avoid that SEND and RECEIVE instructions execute at the same time. For that purpose we should do an interlock between the reading and the writing. Note that only one transaction per time is possible. The PLC will be reading or writing only once at the time, in sequence.

No.	Address	Nickname	Current Value	Write
001	DS1	version	2105	Ir
002	DS2		0	Ir
003	DS3		0	Ir
004	DS4		0	Ir
005	DS5	Revolutions	2	Ir
006	DS6	Counts	2346	Ir
007	DS7	speed	0	Ir
008	DS8	torque	0	Ir
009	DS9	DC voltage	311	Ir
010				
011	DS1001		50	Ir

Defining the block transfer parameters

Let us go now to the detail of block transfer registers.

Block transfer parameters P0-09 to P0-16 are “configurable”, that is, the parameters can be changed to read or write any desired address in the servo drive. Parameters P0-09 to P0-16 may be changed to our convenience or left as they are.

For reasons to be described later, let us define P0-09 to P0-13 as follows:

Parameter	Value	Function	MODBUS address	PLC memory	Description
P0-09	21E	As par. P2-30	40010	DS10	Default is P4-07- Input status
P0-10	409	As par. P4-09	40011	DS11	Default is P1-09 -Velocity command 1
P0-11	10F	As par. P1-15	40012	DS32	Default is P1-15 -Target 1 revolutions
P0-12	110	As par. P1-16	40012	DS33	Default is P1-16 -Target 1 counts
P0-13	407	As par. P4-07	40013	DS34	Default is P2-36 -Target 1 velocity

In this case, we will be using some of the parameters for other functions explained after this section. In this example it is convenient to define P0-09 as P2-30, P0-10 as P4-09, P0-11 as P1-15, P0-12 as P1-16 and P0-13 as P4-07. The rest can continue to be the default value.

Notice that the values there are to be written only by the keypad and this is not reported by the report that **Sureservo PRO** software generates.

However, when the values are written there and the servo drive is power cycled, the setting is retained in EEPROM memory.

The final servo setting is shown in the parameter table at the end of the document. Note that, as an option to reduce the transactions per second figure, we can eliminate parameters P0-00 to P0-03 on the reading. We can also decide to read up to P0-13, thus transferring less than 18 words.

We will change the RECEIVE instruction to read from P0-04 to P0-10, for now, according to the following table, for convenience in the programming, for reasons to be seen later in this document.

Parameter	Value	Function	MODBUS address	PLC memory	Description
P0-04	1	Current revolutions	40005	DS5	Current revolutions
P0-05	0	Current counts	40006	DS6	Current counts
P0-06	6	Current rpm	40007	DS7	Current rpm
P0-07	11	Current % torque	40008	DS8	Current % torque
P0-08	13	DC Bus voltage	40009	DS9	DC Bus voltage
P0-09	21E	As par. P2-30	40010	DS10	Used as 5 to avoid writing EEPROM
P0-10	409	As par. P4-09	40011	DS11	To read output data thru MODBUS

Explanation on the setting of block transfer parameter P0-09

It is necessary to consider the following: The servo drive has two types of memory: RAM and EEPROM. In RAM memory data can be written at any time but the memory EEPROM can only be written to a limited number of times, of the order of 100,000 times.

The parameters that do not change in time are written typically in EEPROM memory and with this memory it is not necessary to maintain the drive powered. When powering the servo drive, these values will be still stored in the memory.

This is not possible with RAM memory and the data only stays stored if the servo drive is powered ON. If we want to write continuously to the drive memory, we should set the value of P2-30 parameter as 5; but this value is not retained in memory EEPROM.


Clearly it is not possible that the setting of this value be done by the machine operator when the servo powers on. Therefore it is necessary to write a value of 5 to this memory when the drive powers ON or otherwise the servo will eventually reach the limit of writings and the device will not be functional anymore.

One of several ways is to use a compare instruction reading the content of P2-30 parameter and on the basis of that value execute a subroutine with a SEND instruction writing to that parameter a value of 5. That is, if the reading of that parameter shows that the value is not 5, we execute a SEND instruction to force a 5 into the same memory.

See the code on the next page for this explanation.

It can be created an interlock with C4 such that this function is not executed anymore when P2-30 (MODBUS address 40543 [or 21E in hexadecimal format] has a 5 in its content.

For that, we will configure P0-09 (Modbus address 40010) with the keyboard (By default with value 407) as 21E, that causes that this parameter be defined as P2-30. Then we will include the reading of parameter P0-09 in the RECEIVE instruction.



Notice that we had to force a value of 5 into the content of the register that corresponds to P2-30. For that, we have to set a register (DS501) with a constant 5. In order to test this step, turn off the servo and P2-30 will reset to off. Then, when turning the servo on, you can monitor DS10 with Data View to see the value there. We added rung 1 for settings we will need later.

You will observe that the PLC did not take notice that the servo was powered off. Then, it is necessary to create an interlock in such a way that the PLC resets C4 when the servo goes from “servo not ready” to “servo ON”. For this we should read the output status thru MODBUS. We will discuss this later.



Note that the transactions per second value went down.

Explanation on setting of parameter P3-08

For this step, we have to set P3-08. Let us determine what the value of parameter P3-08 has to be.

The values of virtual or real digital inputs are defined by the content in P4-07.

P3-08 is a “mask” parameter that allow us to control digital inputs with MODBUS. Each one of the parameter bits has a predefined function or defined with other parameters.

If any of the eight less significant bits on P3-08 is a 1, digital inputs DI1 to DI8 are used as *virtual* digital inputs with MODBUS; we call them *virtual* digital inputs as opposed to real digital inputs. We can imagine each bit of P3-08 as a permissive to use MODBUS for each one of the defined functions.

The 8 most significant bits have preassigned functions.

Therefore, before defining P3-08, we have to arbitrarily define the digital inputs to be defined in P4-07. See following table for the selected values for this specific example:

Bit order	Digital input	Code	Description.	P3-08 assigned value
0	DI1	101	Servo Enable	1
1	DI2	104	Clear command	1
2	DI3	124	Home sensor	0
3	DI4	0	Disabled	0
4	DI5	0	Disabled	0
5	DI6	22	Reverse overtravel limit switch, opens on overtravel	0
6	DI7	23	Forward overtravel limit switch, opens on overtravel	0
7	DI8	21	External fault stop, opens on fault	0
8	DI9	108	Command Trigger - predefined	1
9	DI10	111	PCS0 - Bit de selection 0 de position - predefined	1
10	DI11	112	PCS1 - Bit de selection 1 de position - predefined	1
11	DI12	113	PCS2 - Bit de selection 2 de position - predefined	1
12	DI13	102	Alarm reset- predefined	1
13	DI14	127	Home search command - predefined	1
14	DI15	137	JOG Forward- predefined	1
15	DI16	138	JOG Reverse - predefined	1

}

3

}

0

}

F

}


F

This results in a binary string as 1111 1111 0000 0011, which corresponds to FF03. In this case, we must set P3-08 as FF03. The default value is 0.

By now we have the MODBUS RTU read function working but we have not configured the parameters for position operation.


The parameter P3-08 has to be written to the servo with the keypad when P2-30 is set to 0. The servo register stores FF03 when the servo drive is powered cycled.

Let us go back to the ladder program. The following step shows the definition of a constant 5 into DS501, an arbitrary register used for storage only.



Notice that in order to force a 5 into DS501 we use a MATH instruction. we could have used a copy instruction to get the same result.

We can also increase the number of addresses to be read from the servo drive in rung 5, to include from P0-05 to P0-11. See the change done in the next figure.



Main parameter setting

We will enable the servo with a *virtual* digital input; we have to connect the home sensor directly to servo and we will define acceleration and deceleration, the operation mode and other constants that are listed next (others are left as default):

- P1-01 Operation mode, that by default is 0, set as 1 (Pr mode).
 - P1-32 Selection of the stop mode, changed to 1 from value 0.
 - P1-33 set as 0, absolute mode
 - P1-34 Acceleration time: it was defined as 600 ms.
 - P1-35 Deceleration time: 600 ms to arrive at 0.
 - P1-36 S-curve: set as 30 arbitrarily.
 - P1-47 Home search definition : set as 223.
 - P1-48 Home search fast speed; set as 600 rpm arbitrarily.
 - P1-49 Home search creep speed; set as 60 rpm arbitrarily.
 - P1-50, Revolutions offset from home sensor.
 - P1-51, Count offset from home sensor.
 - P1-55, left as 2174 rpm.
 - P2-10, DI1, set as 101, that is, servo enable
 - P2-11, DI2, set as 104, clear command, to zero the counts after home position.
 - P2-12, DI3, set as 124, defined as a home sensor normally open, that closes when the Home sensor is detected
 - P2-13, DI4, set as 0, disabled.
 - P2-14, DI5 , set as 0, disabled
 - P2-15, DI6, set as 22, as reverse overtravel limit; it is a normally closed contact.
 - P2-16, DI7 , set as 23, as forward overtravel limit; it is a normally closed contact.
 - P2-17, DI8, set as 21, as external fault stop; it is a normally closed contact.
- Note from the tables on the next page that the bits 8 to 15 are predefined functions.
- P2-18 , DO1, as 102, that is the output Servo ON.
 - P2-19 , DO2, as 109, that is the output Home completed.
 - P2-20 , DO3, as 105, that is the output At position.
 - P2-21 , DO4, as 107, that is the output Active fault.
 - P2-22 , DO5, as 101, that is the output Servo Ready.
 - P2-36 Position 1 velocity set to 2174 rpm.
 - P2-50 Clear command, set to 1.
 - P3-08 DI control mask set to FF03

The concept of absolute position control will be so that, after the operator enables the servo drive with an output from the PLC linked to DI1.

The servo system can make the home search after the operator touches one button in the touch screen panel (as one option; in the example on AN-SERV-007 this is done with a timer after enabling the servo).

When the servo finds the home position, we will zero the position (0 revs and 0 counts) and then at any time the PLC will be able to write the absolute target position on P1-15 and P1-16.

P4-07 is the value that contains the digital inputs. Recall that we have arbitrarily associated the following digital inputs to P4-07:

Bit order	Digital input	Code	Description.	Assigned value in P3-08	PLC bit
0	DI1	101	Servo Enable	1	C101
1	DI2	104	Clear command	1	C102
2	DI3	124	Home sensor	0	N/A
3	DI4	0	Disabled	0	N/A
4	DI5	0	Disabled	0	N/A
5	DI6	22	Reverse overtravel limit, opens on overtravel	0	N/A
6	DI7	23	Forward overtravel limit, opens on overtravel	0	N/A
7	DI8	21	External fault stop, opens on fault	0	N/A
8	DI9	108	Command Trigger - predefined	1	C109
9	DI10	111	PCS0 - Bit de selection 0 de position - predefined	1	N/A
10	DI11	112	PCS1 - Bit de selection 1 de position - predefined	1	N/A
11	DI12	113	PCS2 - Bit de selection 2 de position - predefined	1	N/A
12	DI13	102	Alarm reset- predefined	1	C113
13	DI14	127	Home search command - predefined	1	C114
14	DI15	137	JOG Forward- predefined	1	C115
15	DI16	138	JOG Reverse - predefined	1	C116

PLC bits are the corresponding bits to be created to link the commands from the C-more panel.

We have defined the P0-11 parameters and subsequent in such way than they are the values of position in P1-15 (P0-11), P1-16 (P0-12) and the digital inputs with P0-13 (that is, P4-07). Therefore, the code of line 9 so that it is written in 3 consecutive registers and the MODBUS function code will be 16 instead of 6.

In this way, we should set the parameters as follows, with the keypad:

P0-11 will be desired revolutions with the value $10F_{\text{hex}}$ equivalent to P1-15. This is the value by default.

P0-12 will be desired counts with the value 110_{hex} equivalent to P1-16. This is the value by default.

P0-13 will be the word with the digital inputs with the value 407_{hex} equivalent to P4-07.

The next ones are not important in this specific example.

You may select other block transfer parameters, if it is necessary in your application.

The parameters P0-04 to P0-13 are now set as follows:

	Parameter	Value	MODBUS address	PLC memory	Description
1	P0-04	1	40005	DS5	Current revolutions
2	P0-05	0	40006	DS6	Current counts
3	P0-06	6	40007	DS7	Current rpm
4	P0-07	11	40008	DS8	Current % torque
5	P0-08	13	40009	DS9	DC Bus voltage
6	P0-09	21E	40010	DS10	Set not as default, as parameter P2-30
7	P0-10	409	40011	DS11	Set not as default, as parameter P4-09
8	P0-11	10F	40012	DS12	Set as position command 1, revolutions
9	P0-12	110	40013	DS13	Set as position command 1, counts
10	P0-13	407	40014	DS14	Set as P4-07, digital input word

The idea is to be able to read parameters P0-04 to P0-09, read and write into P0-09 and write into P0-11 to P0-13.

P0-10 is used to read the digital output status at any time.

P0-11 and P0-12 are configured to be able to write the revolutions and the counts desired, that will correspond to the target position.

We have selected a set of memories beginning in DS5 on the PLC for the purpose of receiving the data coming from P0-04 to P0-11.

Factor of revolutions versus displacement

The PLC will have to make some math to relate the linear distance to revolutions and counts. This is what we will explain now.

Since the circumference of the sprocket is about 330.995 mm or close to 331 mm and we use a gearbox or ratio 12:1. we can obtain the factor with the following relationships: 12 revolutions of the servo will result in a distance of 331 mm. That is, one mm of displacement will be $12.0/331$ revolutions or 0.03625 revolutions, that corresponds to 362.5 counts.

If the operator wants to move to an arbitrary number of, let's say, 234 mm, the total counts will be about $234 \times 12 / 331 = 8.4833$ revolutions. This is less than one revolution on the gearbox output.

If the operator wants to move to another arbitrary number of, let's say, 687 mm, the total counts will be about $687 \times 12 / 331 = 24.9063$ revolutions. This is more than one revolution on the gearbox output.


The error for the total displacement (830 mm) can be determined with the following: We know that $830 / 330.995 = 2.500037651$. When we calculate $830 / 331 = 2.50755287$ and then the error is 0.3 % that is negligible in this case.

This is the math we have to implement in the PLC. Notice that there are integer revolutions and fractions. The revolution value (8 or 24 respectively in the examples above) should go to the parameter P1-15. The counts (4833 or 9063 respectively) will go to the parameter P-16.

The operator will only define the millimeters to be displaced from the Home position.


Now, recall that we have an operator interface that will write a number, such as 687 in the PLC to an arbitrary memory DS30.

This integer number has to be scaled by $120000/331$ and separated into 2 numbers. The ladder code below explains how to do this.



C-more programming

It could be important for operation to show the operator the current target. We will create a numeric display on the operator interface that shows the value, similar to the adjacent figure.



It may also be important to the operator to show the current position. The servo will report the current revolutions and the counts.

We will have to scale those values into mm to show the current position.


It is time to describe the C-more operator interface programming

We will describe here how to program the objects on the operator interface.

Open the C-more program and create a new project by clicking on button **“Start a project”**.


Give a project name (for example, **AN-009**) then select the HMI; the HMI type will be the one you are using. In this application note, we used a 10 inch C-more panel. The PLC protocol will be **Automation Direct MODBUS(CLICK)** and the baud rate will be 38400 kbps, the default for the port 1 Click 1 PLC and then click **OK**.

The next screen will show up:



Next, we will create a numeric display object to show the current position. Click on the menu **Object** and then select **Indicator** and then **Numeric display** and click on it. The cursor will turn into a cross and then drag it by holding the left mouse button and form a rectangle with it.

When you finish the dragging, the numeric display dialog box will show up and then you can fill up the data. See it on the adjacent figure. The main features are explained below:



Label: This is the text that shows on top or bottom to identify the numeric display. We elect not to use any label in this case.

Text Size: Click on the down arrow to select the Text Size of the number to be displayed. In this case we will select 16.

Data Type: Click on the down arrow to select the type of data that will be displayed. In this case we will select SIGNED DECIMAL.

Number of Digits: Click on the Up or Down arrows to select the number of Total and Fractional digits to be displayed. set as TOTAL 3 & FRACTIONAL 0.

Suffix: Click on the field to enter a common Suffix value that will always be displayed. In this case we will select **mm**.


Data Display Tag: Click on the down arrow to select a Tag Name. In this case we will select **Current position**. Click on the button at the right with 3 dots and other dialog box will show up, as in the adjacent figure. Fill up according to the data on the adjacent figure.



The other fields are not important at this time. You can read more on the online help. Click on the button **ADD** to return to the main dialog box and then click OK.

Note that the object is displayed where you have made the rectangle. Drag it to the top right of the screen. You should see the following

You can set now a Static text to describe what you have on the rectangle. Let us call **CURRENT POSITION**.




For this action, we will click on the menu **Object** and then select **Text** and after that **Static text ...** and click on it. The cursor will turn into a cross and then drag it by holding the left mouse button and form a rectangle with it.


When you finish the dragging, the dialog box will show up and then you can fill up the text to be shown. In this case, we will write **CURRENT POSITION**.

Drag it to the left of the numeric display, if necessary; you can also give other size and shape.

We will do a similar row with the current target. For this, we can copy both objects and then modify them, as follows (See the figure below to follow the explanation):




Drag a line from the top left to the right under the numeric display and then go to the menu Edit and hit "**Copy**". Then get other submenu "**Paste**".



A copy will show up over the original set, offset and showing dots on the corners. Drag it to under the existing one.

Now we can right-click on the bottom text object and a submenu will show up. Click on the submenu Object Properties as shown below. When this is done, the dialog box will show up and then you can change the text to **Current Target**.




Associate this tag to DS30. You can relocate the objects to align with the upper ones.

In the same way, you will change the properties of the numeric display to show now the current target related to DD1 and the number of digits can be changed to 3. You may change the frame to other, to distinguish from the previous one.

In the same way, you can continue to set other objects, as follows:

Target entry, as numeric entry, other object that allows to enter a number to be transferred to the PLC, related to DD1.

The result and the tags related to each object are shown on the following figure



This project can be downloaded to the panel for testing purposes by clicking on the button “**Send** Project to Panel”.


You can also simulate the behavior of the panel on the PC by clicking the button “**Simulate** panel”. This function provides the possibility to show what you will see on the panel. For example, you can click on the numeric entry object and the display will show a keypad that can be clicked to enter a number, as you do on the panel. More instructions are found in the On-line Help of the software.

The screenshot displays a simulation interface with several components:

- A button labeled "CURRENT POSITION" with a value of "231 mm".
- A button labeled "Desired target" with a value of "639 mm".
- A "TARGET ENTRY" field containing "639 mm".
- A "Simulation" window showing a "Tag List" table.

Tag Name	PLC Address	Data Type	Value
C5	C5	Discrete	OFF
C6	C6	Discrete	OFF
OLD TARGET	DS12	Signed int 16	231
TARGET	DS30	Unsigned int 16	639
TARGET ENTRY	DD1	Unsigned int 32	639

We should calculate the current position in DS20, arbitrarily defined, after reading the revolutions and fractions from the servo drive. See the ladder code on the figure of next figure, that shows how to implement this.



We know that the current revolutions are in DS5 and the current counts in DS6. We executed a calculation to get the current position in mm.

Current position checking: First let us check that the PLC calculation of the current position in DS20 is correct. Move the shaft of the servo in such a way that there are 12 revolutions (We know that 12 revolutions will correspond to 331 mm). If DS20 in Data View shows 331, this is doing the calculation correctly.

The operator will enter the target in to the numeric entry associated to DD1.

The desired target position is what the operator has entered into the servo. In order to transfer it, the operator should press the “Send target to servo ” momentary pushbutton associated to C5. We will test later that the panel communication link is working together with the servo. The way to do that is to force some values, but we have not done all the set up so far.

Definition of the commands to the servo

Next, we have to program the different digital inputs and outputs of the servo drive. Recall that we have previously defined the functions of the operator interface as follows:

Bit order	Digital input	Code	Description.	Assigned value in P3-08	PLC bit
0	DI1	101	Servo Enable	1	C101
1	DI2	104	Clear command	1	N/A
2	DI3	124	Home sensor	0	N/A
3	DI4	0	Disabled	0	N/A
4	DI5	0	Disabled	0	N/A
5	DI6	22	Reverse overtravel limit, opens on overtravel	0	N/A
6	DI7	23	Forward overtravel limit, opens on overtravel	0	N/A
7	DI8	21	External fault stop, opens on fault	0	N/A
8	DI9	108	Command Trigger - predefined	1	C109
9	DI10	111	PCS0 - Bit de selection 0 de position - predefined	1	N/A
10	DI11	112	PCS1 - Bit de selection 1 de position - predefined	1	N/A
11	DI12	113	PCS2 - Bit de selection 2 de position - predefined	1	N/A
12	DI13	102	Alarm reset- predefined	1	C113
13	DI14	127	Home search command - predefined	1	C114
14	DI15	137	JOG Forward- predefined	1	C115
15	DI16	138	JOG Reverse - predefined	1	C116

Momentary indicator Button 1 => C101 Servo enable; it shall be set by the operator.

Momentary Button 2=> C109 Move trigger; The trigger shall be commanded by the operator.

Momentary Button 3 => C113 Alarm reset; this should be commanded by operator

Momentary Button 4 => C114 Home search; this should also be commanded by operator

Momentary Button 5 => C115 Jog forward; this should be commanded by operator

Momentary Button 6 => C116 Jog reverse; this should be commanded by operator


These commands shall be transferred to the servo with a word in the PLC that is linked to P4-07, with MODBUS addressing of 41032.

We have to add a JOG forward and a JOG reverse in this project, for the rare case that the tool car gets the overtravel limit switch activated or any need to test the motion.

With these considerations we will implement more ladder code in the PLC.

Let us create the buttons.


Button 1- Put the cursor over the Indicator button on the right pane, where it says **Object list** and select it then drag it to the left bottom side of the screen 1; it will pop up the **Indicator button** dialog box. Fill with the data shown on the figure




below:

The button will activate in toggle mode the bit C101. **Servo enable button** tagname is associated to C101; **Enabled** light tagname is associated to C201 for now.

The button has been programmed; you can transfer the program to the panel and see how it looks. It should be similar to the next figure:



In the same way, create the rest of the buttons, AS SIMPLE MOMENTARY PUSHBUTTONS, associating the tag name to the defined C bits. The screen program will look similar to the following figure:



This can be saved to the C-more panel and it seems a good time to test the functionality together with the PLC.

Of course, having only 2 communication ports presents small problems. The port 2 will be used for the panel, and then we will have to remove the cable to the servo. We will not have the servo linked to the PLC, but we can connect the panel to the port 2 of the servo with the cable EA-2CBL.

Since we have commands in the ladder program to write to a slave in port 2, the PLC expects a slave connected to it. The C-more panel is a master by itself. There will be communication errors if we do not disable the communications. One temporary way to do that is to use normally closed contacts with SC1 in the rungs where there is a SEND and a RECEIVE instruction. This is what we have done in our test.

In order to test the proper function, let us write a number in the numeric entry, such as 687, and we will observe that the word DD1 will get the same number. You should activate the button SEND TARGET TO SERVO for that to execute. The math in the section **Factor of revolutions versus displacement** takes the value of desired target (in mm) into DS32 for the corresponding revolutions and the register DS33 for the counts.

For example, by entering 331 mm, we can see with Data View that DS32 is 12 and DS33 is 0, that corresponds to the ratio explained earlier. You can test with any other acceptable value. See the following figure with Data View for this case.

Address	Nickname	Current Value	New Value	Write	Viewing Format
D51001		0			Integer
D5501		5			Integer
C5	Send target to servo	On	On Off		Bit
DD1	Target in mm	331	331		Integer
DS5	Revs	0			Integer
DS6	Counts	721			Integer
DS7	Speed	-13393			Integer
DS8	Torque	0			Integer
DS9	DC bus voltage	-3083			Integer
DS10	P2_30	5			Integer
DS11		8			Integer
DS12	Target A revs	2			Integer
DS13	Target A counts	253			Integer
DS14	Target A speed	400			Integer
DS15		253			Integer
DS16		400			Integer
DS17		100			Integer
D530	Current target	331	830		Integer
D531	target in thousand revs	0			Integer
D532	Desired revs	12			Integer
D533	Desired counts	0			Integer

The pushbuttons can be tested by creating the elements in Data View 2 and seeing that the C bits will turn ON or OFF depending on the touch of the buttons.

See the figure below for an example in Data View.

<input type="checkbox"/>	C101	Servo enabled	Off	On	Off	<input type="checkbox"/>	Bit
<input type="checkbox"/>	C109	Trigger bit	Off	On	Off	<input type="checkbox"/>	Bit
<input type="checkbox"/>	C113	Alarm reset bit	Off	On	Off	<input type="checkbox"/>	Bit
<input type="checkbox"/>	C114	Home search bit	Off	On	Off	<input type="checkbox"/>	Bit
<input type="checkbox"/>	C115	JOG FWD bit	Off	On	Off	<input type="checkbox"/>	Bit
<input type="checkbox"/>	C116	JOG REV bit	Off	On	Off	<input type="checkbox"/>	Bit

The servo enable button is a toggle switch, that is, the bit C101 will be turned ON one time and then turned OFF when touched again.

The others, including the JOG commands, are momentary pushbuttons that are ON only when the object is touched.

If you want to see the action in the PLC, you can physically test them by relating, temporarily, the bits to a physical output of the PLC. When the output is ON, the corresponding LED will turn ON.

These actions test the objects that have been created in the C-more panel.

These actions complete the test of the C-more and the PLC, for now.

Reading servo output status from PLC

Let us go back to continue making the PLC program. Put the cable going to the Servo back, and the SC1 N.C. contacts on rungs where there is a SEND or RECEIVE commands shall be removed.


When the communication has been established, we can see that the baud rate is 47 kbps in the register DS1001 using Data View.

We are reading the outputs in P0-11, or in other words, P4-09.

Let us analyze what do we want to have here with the help of the following table:


Parameter	Value	Description	Action expected
P2-18	102	DO1 defined as Servo ON	ON when servo is enabled
P2-19	109	DO2 defined as Homing completed	ON after the Home as been found
P2-20	105	DO3 defined as At position	ON every time servo reaches the target
P2-21	107	DO4 defined as Active fault	ON every time the servo has a fault
P2-22	101	DO5 defined as Servo ready	ON when servo is powered and no faults

Each of the first 5 bits of this word represents the status of the digital outputs (DO's). we use the UNPACK COPY instruction to get the data, as follows:



Note that P4-09 was read with MODBUS and transformed into hexadecimal DH1. Then the content of DH1 was unpacked to C201 to C216. Of course, only bits C205 to C210 are used.

How did we test this relationship? In order to turn the outputs ON, we can use the parameter P4-06. See the figure at the right to see the next explanation.



P4-06 shall be set to 1 to force DO1 to ON. When the ENTER key is pressed, the servo display will show OP 01, and the bit C201 of the PLC will turn ON. In the same manner, when set to 2, and then when the ENTER key is pressed, the servo display will show OP 02 and the bit C202 of the PLC will turn ON and so on.

The effect will be seen on the register DS11 on in C201 to C205 with the help of Data View. See the adjacent figure.

122	<input checked="" type="checkbox"/>	C201	DO servo on	Off
123	<input checked="" type="checkbox"/>	C202	DO Home completed	Off
124	<input checked="" type="checkbox"/>	C203	DO at position	On
125	<input checked="" type="checkbox"/>	C204	DO active fault	Off
126	<input checked="" type="checkbox"/>	C205	DO servo ready	On

We are now ready to implement more logic in the PLC.

We can add some indicators on the c-more screen, as shown below:




Virtual digital input programming

Recall that we want to set the digital inputs with the help of parameter P4-07, that is written by the C bits defined previously in the C-more panel.

We will read continuously the status of the servo but and we will continuously write the digital inputs as well as the desired target position.

There are 2 positions and one word with the digital inputs to be written. The 2 word position information are calculated in DS32 and DS33 and are to be written into registers P1-15 and P1-16 respectively. These registers are not consecutive, but with the help of block transfers, we are able to set one SEND writing to P0-11 and P0-12.

We will interlock the RECEIVE instruction with the C bit C8, as in the following figure, to avoid that the SEND and RECEIVE functions operate at the same time.




In a similar way, we can write the word to change P4-07 to P0-13. P4-07 will take some values depending on the digital inputs active at any given time.

The rung for the receive instruction has been modified and can be seen in the final version for the ladder code at the end of the document.

We should prepare the corresponding data to make it logical, with the ladder code in the following figure.

When the servo is enabled, the PLC output Y4 shall be turned ON to release the brake. See the logic in the ladder code of the next figure.

See the figure below for the following explanations:




In order to put the bits into one word, we can use PACK COPY instruction. The bits C301 to C316 can be PACK COPYed to DH2.


The PACK COPY mode of the COPY Instruction combines the status of up to 16 Source C Bit Memory Addresses and copy the combined status into a Destination Data Register (DH2).

The **Source** field represents the range of the Bit Memory Addresses C301 to C316, bits that are related to the commands, as shown on the ladder diagram of figure above.

Destination: Identify the ending Destination Memory Address (DH1 in this case). DH2 will be the memory to be transferred to the servo register 401032 (P4-07).




Now we have to set a word DH2 that has to be transferred to the servo which will have the bits related to the virtual digital inputs defined in the range C301 to C316. When this relationship is defined we can SEND the data to the register that corresponds to P4-07. See the code in the figure below



This is the minimum code that we need. remember to add the END instruction.

We can now test the program together with the operator panel.

In order to be sure that there is communication, we will add a numeric display showing the transactions per second, as in the figure below:




Testing the program

The Click programming software can be now disconnected from the PC to make the port 1 of the PLC free.

Power up the C-more panel and be ready to run the servo motor. Be sure that the motor is not connected to the load and it is firmly secured to a bracket, to avoid that the motion may cause some injury or damage to property.

Note that the transactions per second may be in the order of 25 ms (0 if there is no communication); if there is no communication, turn off and on the RUN/STOP switch on the PLC in order to, temporarily, make it work. Obviously something else has to be done there. We will look after this test to fix the problem.



Touch the button **Servo enable** on the operator panel, that should be gray; at the touch the button turns green. The virtual digital output C301 in the PLC will turn ON. The brake will be released with the help of the PLC output Y4. The shaft of the motor shall be locked since now the servo is enabled and you will hear a typical sound of current flowing through the windings of the servomotor. Touch again the **Servo enable** button on the operator panel to disable the servo. The shaft of the motor should be loose again if the brake is released.

Touch the button **Servo enable** on the operator panel for next operations.

Press the button **Home search** on the operator panel. The virtual digital output C309 will turn ON. The shaft of the motor shall not be locked anymore and the Home search will begin to move backwards to detect the position on the home sensor.

The output DO2 will turn ON when the **Home is completed** and this will activate the PLC input C202. After the **Home is completed**, there is no need to do home search again, unless you want to return to the zero position.

The indicator at the top of the screen will turn on accordingly.. For example, after doing home search and the the home has been found, the screen will display a screen as the following figure.

When the Home is completed, the PLC clears the current counts (And revolutions) to get the 0 counts at this time and allow a proper indication of the current position.



This is done by commanding the clear command through MODBUS. We have transferred the C bit data to the servo through MODBUS. This is

one way to implement it. Another is to use a real input on the drive.

At this time we can test again the program.

Write a number such 800 mm in the numeric entry "Target entry" by touching the object. The numeric keypad will show up. Then write "800" and press "ENT". We have loaded the number 800 in the PLC-memory and the PLC will scale into revolutions and send to the servo into parameters P1-15 and P1-16.

It is checked that the number is not greater than 829 mm. If greater or equal than 829, it clamps the value and forces a 830 on the target. The scaled data has been transferred to the servo and then the servo is ready to move from the home position to the desired position indicated as 800 mm.



When this is done, we can then trigger the motion with the button. The servo should move forward to the corresponding number of revolutions and counts.

The numeric display for current position should show the displacement in real time.

To come back to other lower position, we can repeat the action.

Write a number such as 8 mm in the numeric entry "Target entry" by touching the object. The numeric keypad will show up. Then write "8" and press "ENT".

We have loaded the number 8 in the PLC. The PLC transforms the new data into the proper desired revolutions; we can then trigger the motion with the button TRIGGER.

The servo will move backwards to the corresponding number of revolutions and counts.

While the servo is enabled, the operator can use the buttons Jog Forward or Jog reverse to move in one or other direction, for example, to test the overtravel limits.

When connected to the machine, it might be necessary to tune the servo. This can only be done when the machine is connected. The program *Sureservo PRO* is very useful for this operation.

This shows one simple positioning method. Of course, it will depend on the ingenuity of the programmer to make more complicated logic and to utilize more features of the C-more panel.

Recall that we have a problem when the system is initially powered up. The communication was not established until the PLC went into program mode and then back to run mode.

One option is simply to have the servo powered up 1 second before the PLC is powered up. It seems that the servo does not accept communications before 1 second after it is powered up. This will require a hardwired timer turned on 1 second after the digital output Servo Ready is ON (DI5).

On the next pages we show the list of parameters and the final ladder code.

List of parameters on the servo drive


Parameter	Value
P0.00 - Software Version	2105
P0.01 - Drive Fault Code	0
P0.02 - Drive Status (Front panel display)	0
P0.03 - Analog Monitor Outputs	0
P0.04 - Status Monitor 1	1
P0.05 - Status Monitor 2	0
P0.06 - Status Monitor 3	6
P0.07 - Status Monitor 4	11
P0.08 - Status Monitor 5	13
P0.09 - Block transfer parameter 1	21E
P0.10 - Block transfer parameter 2	409
P0.11 - Block transfer parameter 3	10F
P0.12 - Block transfer parameter 4	110
P0.13 - Block transfer parameter 5	407


P1.00 - External Pulse Input Type	2
P1.01 - Control Mode and Output Direction	101
P1.02 - Velocity and Torque Limit	0
P1.03 - Output Polarity Setting	0
P1.04 - Analog Monitor Output Scaling 1 (CH1)	100
P1.05 - Analog Monitor Output Scaling 2 (CH2)	100
P1.06 - Analog Velocity Command Low-pass Filter	0
P1.07 - Analog Torque Command Low-pass Filter	0
P1.08 - Position Command Low-pass Filter	0
P1.09 - Preset Velocity Command / Limit 1	100
P1.10 - Preset Velocity Command / Limit 2	200
P1.11 - Preset Velocity Command / Limit 3	300
P1.12 - Preset Torque Command / Limit 1	100
P1.13 - Preset Torque Command / Limit 2	100
P1.14 - Preset Torque Command / Limit 3	100
P1.15 - Position 1 Command (Revolutions)	2
P1.16 - Position 1 Command (Counts)	253
P1.17 - Position 2 Command (Revolutions)	0
P1.18 - Position 2 Command (Counts)	0
P1.19 - Position 3 Command (Revolutions)	0
P1.20 - Position 3 Command (Counts)	0
P1.21 - Position 4 Command (Revolutions)	0
P1.22 - Position 4 Command (Counts)	0
P1.23 - Position 5 Command (Revolutions)	0
P1.24 - Position 5 Command (Counts)	0
P1.25 - Position 6 Command (Revolutions)	0
P1.26 - Position 6 Command (Counts)	0
P1.27 - Position 7 Command (Revolutions)	0
P1.28 - Position 7 Command (Counts)	0
P1.29 - Position 8 Command (Revolutions)	0
P1.30 - Position 8 Command (Counts)	0
P1.31 - Motor Code	21
P1.32 - Motor Stop Mode Selection	1
P1.33 - Position Control Mode	0
P1.34 - Acceleration Time (Internal Indexer)	600
P1.35 - Deceleration Time (Internal Indexer)	600
P1.36 - Accel / Decel S-Curve	30
P1.37 - Inertia Mismatch Ratio	5
P1.38 - Zero Velocity Output Threshold	10
P1.39 - Target Velocity Output Threshold	3000
P1.40 - Max Analog Velocity Cmd or Velocity Limit	3000
P1.41 - Max Analog Torque Cmd or Torque Limit	100
P1.42 - On Delay Time of Electromagnetic Brake	20
P1.43 - Off Delay Time of Electromagnetic Brake	20
P1.44 - Electronic Gear Numerator 1	1
P1.45 - Electronic Gear Denominator	1
P1.46 - Encoder Output Scaling Factor	1
P1.47 - Homing Mode	0223
P1.48 - Homing Velocity 1 - Fast Search Velocity	600
P1.49 - Homing Velocity 2 - Creep Velocity	60
P1.50 - Home Position Offset (Revolutions)	2

P1.51 - Home Position Offset (Counts)	0
P1.52 - Regenerative Resistor Value	40
P1.53 - Regenerative Resistor Capacity	60
P1.54 - In Position Window	100
P1.55 - Maximum Speed Limit	2174
P1.56 - Output Overload Warning Threshold	120
P2.00 - Position Loop Proportional Gain (KPP)	35
P2.01 - Position Loop Gain Boost	100
P2.02 - Position Feed Forward Gain (KFF)	5000
P2.03 - Smoothing Constant of Position Feed Forward Gain	5
P2.04 - Velocity Loop Proportional Gain (KVP)	500
P2.05 - Velocity Loop Gain Boost	100
P2.06 - Velocity Loop Integral Compensation (KVI)	100
P2.07 - Velocity Feed Forward Gain (KVF)	0
P2.08 - Factory Defaults and Password	0
P2.09 - Debounce Filter	2
P2.10 - Digital Input Terminal 1 (DI1)	101
P2.11 - Digital Input Terminal 2 (DI2)	104
P2.12 - Digital Input Terminal 3 (DI3)	124
P2.13 - Digital Input Terminal 4 (DI4)	0
P2.14 - Digital Input Terminal 5 (DI5)	0
P2.15 - Digital Input Terminal 6 (DI6)	0
P2.16 - Digital Input Terminal 7 (DI7)	0
P2.17 - Digital Input Terminal 8 (DI8)	0
P2.18 - Digital Output Terminal 1 (DO1)	102
P2.19 - Digital Output Terminal 2 (DO2)	109
P2.20 - Digital Output Terminal 3 (DO3)	105
P2.21 - Digital Output Terminal 4 (DO4)	107
P2.22 - Digital Output Terminal 5 (DO5)	101
P2.23 - Notch Filter (Resonance Suppression)	1000
P2.24 - Notch Filter Attenuation (Resonance Suppression)	0
P2.25 - Low-pass Filter (Resonance Suppression)	2
P2.26 - External Anti-Interference Gain	0
P2.27 - Gain Boost Control	0
P2.28 - Gain Boost Switching Time	10
P2.29 - Gain Boost Switching Condition	10000
P2.30 - Auxiliary Function	0
P2.31 - Auto and Easy Tuning Mode Response Level	HEX 44
P2.32 - Tuning Mode	0
P2.33 - Reserved	0
P2.34 - Overspeed Fault Threshold	5000
P2.35 - Position Deviation Fault Window	30000
P2.36 - Position 1 Velocity	2174
P2.37 - Position 2 Velocity	400
P2.38 - Position 3 Velocity	1000
P2.39 - Position 4 Velocity	1000
P2.40 - Position 5 Velocity	1000
P2.41 - Position 6 Velocity	1000
P2.42 - Position 7 Velocity	1000
P2.43 - Position 8 Velocity	1000
P2.44 - Digital Output Mode	0

P2.45 - Index Mode Output Signal Delay Time	1
P2.46 - Index Mode Stations	6
P2.47 - Position Deviation Clear Delay Time	0
P2.48 - Backlash Compensation (Index Mode)	0
P2.49 - Jitter Suppression	0
P2.50 - Clear Position Mode	1
P2.51 - Servo Enable Command	0
P2.52 - Dwell Time 1 - Auto Index Mode	0
P2.53 - Dwell Time 2 - Auto Index Mode	0
P2.54 - Dwell Time 3 - Auto Index Mode	0
P2.55 - Dwell Time 4 - Auto Index Mode	0
P2.56 - Dwell Time 5 - Auto Index Mode	0
P2.57 - Dwell Time 6 - Auto Index Mode	0
P2.58 - Dwell Time 7 - Auto Index Mode	0
P2.59 - Dwell Time 8 - Auto Index Mode	0
P2.60 - Electronic Gear Numerator 2	1
P2.61 - Electronic Gear Numerator 3	1
P2.62 - Electronic Gear Numerator 4	1
P2.63 - Velocity and Position Deviation Scaling Factor	0
P2.64 - Advanced Torque Limit Mixed Mode	0
P2.65 - Special Input Functions	HEX 0
P3.00 - Communication Address	2
P3.01 - Transmission Speed	3
P3.02 - Communication Protocol	8
P3.03 - Communication Fault Action	0
P3.04 - Communication Watchdog Time Out	0
P3.05 - Communication Selection	0
P3.06 - Reserved	0
P3.07 - Communication Response Delay Time	0
P3.08 - Digital Input Software Control Mask	HEX FF03
P4.00 - Fault Record - Most recent (N)	14
P4.01 - Fault Record (N-1)	11
P4.02 - Fault Record (N-2)	11
P4.03 - Fault Record (N-3)	11
P4.04 - Fault Record (N-4)	13
P4.05 - JOG Function	100
P4.06 - Force Outputs Command	0
P4.07 - Input Status	0
P4.08 - Reserved	0
P4.09 - Output Status	20
P4.22 - Analog Velocity Input Offset	0
P4.23 - Analog Torque Input Offset	0


Final version of the ladder code





Sprocket click

Main Program(Page 3 of 4)



Page 3 of 4 (Total Pages)

