

**ATM-A Series**  
**5 DIGIT MICRO PROCESSOR SIGNAL**  
**ISOLATED TRANSMITTER**

**USER'S MANUAL (V1.0)**

**健昇科技股份有限公司**

**JS AUTOMATION CORP.**

新北市汐止區中興路 100 號 6 樓

6F., No.100, Zhongxing Rd.,

Xizhi Dist., New Taipei City, Taiwan

TEL : +886-2-2647-6936

FAX : +886-2-2647-6940

<http://www.automation.com.tw>

<http://www.automation-js.com/>

E-mail : [control.cards@automation.com.tw](mailto:control.cards@automation.com.tw)

# Contents

1. Features .....	2
2. Specifications .....	2
3. Front panel & Key functions.....	3
4. General Mode Operating Procedures.....	4
5. Programming Mode Operating Procedures .....	5
6. Error Code of Self-Diagnosis.....	6
7. Calibration Operating Procedures.....	6
8. Dimensions .....	7
9. Wiring Connection .....	8
10. Ordering information .....	9


## 1. Features

- Versatile Input selection : DC / AC / PT-100 / Potentiometer / Resistor / Load Cell
- Versatile output selection : 4~20mA , 0~20mA , 0~5V , 0~10V
- Accuracy:  $\pm 0.1\%$  F.S. (Others) ;  $\pm 0.2\%$  F.S. (AC)
- Surge test of AC 2000V/ 1min between input / output / power
- High stability, non-flammable case (PC), high safety

## 2. Specifications

- Input selection : DC / AC / PT-100 / Potentiometer / Resistor / Load Cell
- Output selection : 4~20mA , 0~20mA , 0~5V , 0~10V
- Accuracy :  $\pm 0.1\%$  F.S. (Others)  
 $\pm 0.2\%$  F.S. (AC)
- Display Screen : High brightness red LED; 10.16mm(0.4")
- Display Range : -19999~99999
- Zero Adjustment :  $\pm 9999$  ; Span Adjustment :  $\pm 9999$
- Parameters Setting : Push buttons
- Back Up Memory : EEPROM
- Over Range Indication : doFL/ioFL or -doFL/-ioFL
- Analog Output Resolution : 15 bit
- Output Ripple :  $\leq \pm 0.1\%$  F.S.
- Output Response Time : < 250 msec (0~90%)
- Output Capability : Voltage Output: < 20Ma  
Current Output: < 10V
- Isolation : Input / Output / Power / Case
- Insulation Resistance :  $> 100M\Omega$  with 500Vdc
- Surge Test : 2KVac/1min
- Input Impedence : Current:  $\geq 0.2A$  at 100mV;  $< 0.2A$  at 1V  
Voltage:  $> 2V$  for  $20K\Omega/V$ ;  $\leq 2V$  for  $> 200M\Omega$
- Temperature Coefficient : 100ppm/degree C (0~60 degree C )
- Operating Temperature : 0-60 degree C
- Operating Humidity : 20 to 90% RH (non-condensing)
- Storage Temperature : -10-70 degree C
- Storage Humidity : 20 to 90% RH (non-condensing)
- Power Supply : AC 110, AC 220V
- Installation : Socket / Plug-in

### 3. Front panel & Key functions



Key Name	Symbol	Descriptions
Reset Key	<b>Z</b>	1. Press this key to enable the reset function & reset indicator (Z) is light; press this key again to disable the reset function & reset indicator (Z) is dark.
Enter Key & Save Key	<b>ENT</b>	1. In the measuring status, press this key can enter to parameter pages. 2. In the parameter setting, press this key can save the value & go to next page.
Shift Key	⇐	1. In the parameter setting, press this key can move the cursor left.
Up Key & Display Value Adjusting Key	↑	1. In the measuring status, press this key for 3 sec can enter to display adjustment of "ZERO" & "SPAN" 2. In the parameter setting, press this key can increase the digits.
Down Key & A/O Adjusting Key	↓	1. In the measuring status, press this key for 3 sec can enter to analog output adjustment. 2. In the parameter setting, press this key can decrease the digits.

1. The following block charts are parameters codes, parameter codes & parameters will alternate flashing if the parameters can be modified.
2. To modify the parameters, please press ⇐ ↑ ↓, and press ENT to save the parameters after the modification.
3. Please don't forget the new pass code after modification.
4. In any pages, pres ↑ & ↓, or don't press any keys for 2 minutes that will back to measuring status.







## 4. General Mode Operating Procedures

Block Charts	Display	Descriptions	Default
<b>Display : "ZERO" &amp; "SPAN" Adjustment</b>			
	Measuring Status	Present value for measurement.	
	Display (dZEro) Adjustment (dZEro)	Press $\leftarrow$ to select adjusting speed rate, press $\uparrow$ $\downarrow$ to modify the zero value. PS: To use this function to adjust the real zero value.	00000
	Display Span Adjustment (dSPAN)	Press $\leftarrow$ to select adjusting speed rate, press $\uparrow$ $\downarrow$ to modify the span value. PS: To use this function to adjust the real span value.	00000
<b>Analog Output: "ZERO" &amp; "SPAN" Adjustment</b>			
	Measuring Status	Present value for measurement.	
	A/O Zero Adjustment (AZEro)	Press $\leftarrow$ to select adjusting speed rate, press $\uparrow$ $\downarrow$ to modify the A/O zero. PS: To use this function to adjust the real A/O zero.	00000
	A/O Span Adjustment (ASPAn)	Press $\leftarrow$ to select adjusting speed rate, press $\uparrow$ $\downarrow$ to modify the A/O span. PS: To use this function to adjust the real A/O span.	00000

## 5. Programming Mode Operating Procedures


Block Charts	Display	Descriptions	Default
	Measuring Status	Present value for measurement.	
	Pass Code (P.Cod)	Press $\leftarrow$ $\uparrow$ $\downarrow$ to enter pass code.	00000
		Pass code is correct that will enter to parameter groups. Pass code is wrong that will back to measuring status.	
	Decimal Point Setting (dP)	Pass $\uparrow$ $\downarrow$ to select decimal point (0, 1, 2, 3, 4). EX: if the value shows "0.00" that means the decimal point is 2 digits.	
	Display Low Scale Setting (dSPL)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to modify display low scale for the input signal zero value. EX: If the input signal is 4~20mA; 4mA is shown display 0.00, this parameter must be set for 000.00.	Customers specify
	Display Hi Scale Setting (dSPH)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to modify display high scale for the input signal span value. EX: If the input signal is 4~20mA; 20mA is shown display 100.00, this parameter must be set for 100.00.	Customers specify
	Display Average Setting (AvG)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to modify display average (1~99). PS: Please use this function for stable display value when input signal is unstable.	00005
	Display Low Cut Setting (LCUt)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to modify display low cut to 0 (0~99).	00000
	A/O Polarity Setting (PoLAr)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to modify output is positive pole or negative pole. PS : Voltage output ,NO: positive pole output (0~+10V) YES: positive & negative pole output (-10~+10V)	no
	A/O Low Scale Setting (AnLo)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to adjust A/O low scale to correspond to the display value. EX : A/O is 0~10V, the display is 10.0 to output 0V, this value must be set for 10.0.	00000
	A/O Hi Scale Setting (AnHi)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to adjust A/O hi scale to correspond to the display value. EX : A/O is 0~10V, the display is 90.0 to output 10V, this value must be set for 90.0.	99999
	Pass Code Setting (CodE)	Pass $\leftarrow$ $\uparrow$ $\downarrow$ to modify pass code (0~19999). PS: Please don't forget the new pass code after modification.	00000
	Key Lock Setting (LoCK)	Pass $\uparrow$ $\downarrow$ to lock the keys, using key lock function only can view the parameters, but cannot modify any values. PS: no (unlock) ,YES ("ENT" unlock , others lock).	no

## 6. Error Code of Self-Diagnosis

Display	Descriptions
	Input signal is over 120% of input range.
	Input signal is under -20% of input range.
	Input signal is over 180% of input range or meter error.
	Input signal is over display range (99999).
	Input signal is under display range (-19999).
	EEPROM reading/writing suffers the interference (about 1 million times).


※Please check the wiring connection is correct first, if the problem still exist, please return the meter to the factory.

## 7. Calibration Operating Procedures

	Display	Descriptions	Default
	Measuring Status	Present value for measurement Press ENT & ⇐ together for 3 sec will enter to calibration operating procedures.	
	Input Low Scale Calibration (inLo)	1. Input standard low scale signal. 2. Press ⇐ ⇑ ⇓ to calibrate input low scale.	
	Input Hi Scale Calibration (inHi)	1. Input standard hi scale signal. 2. Press ⇐ ⇑ ⇓ to calibrate input hi scale	
	System Setting Page (SYS)	1. Finish calibration operating procedures will enter to system setting group. 2. Press ⇑ & ⇓ together to back to measuring status.	

Warning: Calibration of this meter requires a standard signal with 0.01% accuracy or better and an external meter with 0.005% accuracy or better.


## 8. Dimensions






## 9. Wiring Connection


- Voltage (V), Current (A)(AC, DC)




- 4 Wire Sensor or Load cell  
Load Cell or  
4 Wire Sensor




- Temperature (RTD)




- 2 Wire Sensor




- 2 Wire Resistor



- 3 Wire Sensor



- 3 Wire Potentiometer



## 10. Ordering information

ATM-A - Code 1 - Code 2 - Code 3 - Code 4

Code 1	Input Type	Code 2	Type	Range	Code 2	Load Cell	Code 3	Aux. Power	Code 4	Analog Output			
D	DC	V1	Voltage	0~50mV	L1	1mV/V EX.5V	A	AC 110V	1	4~20mA			
		V2		0~5V	L2	2mV/V EX.5V			2	0~20mA			
		V3		1~5V	L3	3mV/V EX.5V			3	0~5V			
		V4		0~10V	L4	1mV/V EX.10V	4	0~10V					
		V5		0~36V	L5	2mV/V EX.10V	O	Option					
		V6		0~300V	L6	3mV/V EX.10V							
		V7		0~600V	LO	Option							
		V0		Option									
		A		AC AVG	A1	Current	0~20μA						
					A2		0~200μA						
A3	0~2mA												
A4	0~20mA												
A5	0~200mA												
M	AC TRMS	A6	Current	4~20mA									
		A0		Option									
P	3 Wire Potentiometer	P1	Potentiometer	500Ω~10KΩ									
		P2		10KΩ~100KΩ									
I	2 Wire Resistor	P3	Potentiometer	100KΩ~1MΩ									
		P0		Option									
		I1		Resistor	0~10Ω								
I2	0~100Ω												
I3	0~1KΩ												
T	RTD (PT-100)	I4	Resistor	0~10KΩ									
		I5		0~100KΩ									
		I0		Option									
		T1		RTD (PT-100)	-50~50℃								
T2	0~50℃												
T3	0~100℃												
T4	0~200℃												
L	Load Cell	T5	RTD (PT-100)	0~400℃									
		T6		0~600℃									
		T0		Option									
2	2,3 Wire Sensor												
4	4 Wire Sensor												

- 1 : 2 wire type offers excitation power DC24V for 2 wire (Loop Power) pressure, temperature, humidity sensors using.
- 2 : 3.4 wire type offers excitation power DC24V for 3, 4 wire (Loop Power) pressure, temperature, humidity sensors using.