

2014 Strain Gauge Module

Content

1	2D STRAIN GAUGE MODULE	3
2	THE AMPLIFICATION IN A 2D STRAIN GAUGE MODULE	4
3	HOW TO PUT THE STRAIN GAUGE MODULE INTO SERVICE	6

Symbols used in the text



These paragraphs contain tips and practical advice for working with the 2D system



In the paragraphs highlighted with this symbol, you will find additional information and it is very important that you follow the instructions given.



Documentation reference

- A user manual reference number is provided so the user can seek further assistance


1 2D Strain Gauge Module

The 2D Strain Gauge Module is available for two or four full strain gauge bridges. It contains programmable chips to amplify the incoming strain gauge signals and a CPU which translates the analog data from the strain gauges into CAN data. These CAN data can then be sent via CAN bus to a logger for recording the data.


2 The amplification in a 2D Strain Gauge Module

The amplifier chip in a 2D Strain Gauge Module offers three different parameters to adjust the amplification:

- Bridge offset
- Amplification
- Output offset



You can find these three values in tab *Parameter*, field *Parameter* of your channel:



Amplification

The amplification can be set from 10 to 1000 (whole numbers). The entered value is directly used as amplification with an accuracy of ± 2 @1000. An amplifier adjustment is not required.

Section 3 Step 1 describes how to find the right amplification.

Output offset

The output offset (in *WinIt* offset) is used to adjust the output voltage of the amplifier. It is possible to correct single side used bridge sensors or burdened sensor bridges.

The inserted value is directly used as a voltage and it is independent of the amplification. The value is added to the amplified bridge signal. Values from 0.0 to 5000.0 mV can be set.

Section 3 Step 2 describes how to find the right offset value.

Bridge offset (additional parameter)

The bridge offset (in *Winlt* additional parameter) is used to correct the offset of the sensor. There is the possibility to compensate negative and positive offsets of the used bridge. The usable values are between 0 and 28. The default value is 14. This means that no compensation is used.

The next table shows the different parameters and their bridge adjustments.


Parameter	Bridge adjustment [mV]	Parameter	Bridge adjustment [mV]
0	-59.50	15	4.25
1	-55.25	16	8.50
2	-51.00	17	12.75
3	-46.75	18	17.00
4	-42.50	19	21.25
5	-38.25	20	25.50
6	-34.00	21	29.75
7	-29.75	22	34.00
8	-25.50	23	38.25
9	-21.25	24	42.50
10	-17.00	25	46.75
11	-12.75	26	51.00
12	-8.50	27	55.25
13	-4.25	28	59.60
14	0		

Section 3 Step 2 describes how to find the right offset value.

3 How to put the strain gauge module into service


This section gives you a step by step instruction on how to set the right parameters to the strain gauge module. It is assumed that you have already installed the 2D software on your PC and the full strain gauge bridges are installed ready to use. To find the right settings and to calibrate your full strain gauge bridges you need a defined weight to put a stress on the components to be measured.

To put your system into service you need to connect the full strain gauge bridges to the strain gauge module and the strain gauge module to a logger. The system needs an external power supply. To change the setting you connect the logger to your PC via USB cable.



Start the program *Winlt* (*WinARace* ⇒ <Communication (F2)>).


Select the strain gauge module in the system tree and go to the analog channels.



There you can see the input channels of the strain gauges – *AN#1*, *AN#2* (in this example it is a strain gauge module for only two full strain gauge bridges). This view is important, as you can check the digits-values of the channels easily.

Step 1: Finding the right amplification

The amplification is important to get the right measurement range. If the amplification is too high (3), you have a good resolution, but the measurement range in digits is not enough. And if the amplification is too small (1), then the measurement range is too big or rather the measurement data could be more accurate. Therefore you need to find an amplification which is adequate for your requirements (2).



Orange (1): the amplification is too small

Green (2): the amplification is adequate

Red (3): the amplification is too high

Double click on the channel you want to adjust, e.g. AN#1, and check the tab *Parameter*.

In the beginning the additional parameter has to be “14”, as it means there is no bridge-offset, and the offset should be 2500 mV. You can start with the given amplification or change it, if you already know in which range the amplification should be. If you change anything confirm your changes with **<Apply>**.

To find the right parameters for the first full strain gauge bridge (e.g. AN#1) you take a note of the digits of the unstressed component and the component stressed with the defined weight in loading direction.

Nr	Record	Name	Sample	Sensor info	Multiplicator	Digits	Offset
1	<input checked="" type="checkbox"/>	AN#1	25		1,000	27434	0,000
2	<input checked="" type="checkbox"/>	AN#2	25		1,000	27553	0,000
3	<input checked="" type="checkbox"/>	Uext	400		0,0003	39411	0,0000
4		Temp	25		0,100	287	0,000

Calculate the difference between those two values (stressed and unstressed).

Now you check if the measurement range is okay or if you have to adjust the amplification:

$$\text{measurement range} = \frac{65535 \text{ digits}}{\text{difference between stressed and unstressed}} * \text{stressing force}$$

For example:

- Unstressed component value: 32770 digits
- Stressed component value: 34400 digits
- Difference: $34400 \text{ digits} - 32770 \text{ digits} = 1630 \text{ digits}$
- Defined weight: 10 kg
- Stressing force: $10 \text{ kg} * 9,81 \frac{\text{m}}{\text{s}^2} = 98,1 \text{ N}^1$
- ⇒ $\text{measurement range} = \frac{65535 \text{ digits}}{1630 \text{ digits}} * 98,1 \text{ N} = 3944 \text{ N}$


If you're expecting forces in both directions of about 1500 N (±1500 N) you need a measurement range of at least 3000 N!

¹ The acceleration of gravity ($g=9.81\text{m/s}^2$) may differ, depending on your location.

Now you have three options:

1. The measurement range is **too small**: You have to reduce the amplification in tab *Parameter*. Afterwards you do the same procedure as before.
Example: Your measurement range is 1200 N, your amplification is 1000; you need a measurement range of at least 6000 N \Rightarrow adjust your amplification to 200 and start again
2. The measurement range is **too big**: You should increase the amplification in tab *Parameter*. Afterwards you do the same procedure as before.
Example: Your measurement range is 8000 N, your amplification is 250; you need a measurement range of at least 4000 N \Rightarrow adjust your amplification to 500 and start again
3. The measurement range is **adequate**: Your amplification is set, go on with step 2!


To change the amplification select the channel you want to adjust and select tab *Parameter*. Enter the new amplification value in the corresponding field.



Confirm your changes with <Apply>.

Step 2: Adjusting the additional parameter and offset

For this step it is important to know which forces you are expecting (only in one direction; in either directions, regular or irregular arranged), as it defines the zero-point on the digit-scale.




Example: You are expecting forces in both directions and those forces are similar to each other. Then it is advisable to put the zero-point in the middle of the measurement range. To get the zero-point in the middle of your measurement range you need to put the digits of the unstressed component in the middle of the digit-measurement range. The digit-measurement range is from 0 to 65535 digits, so the middle is 32767 digits.

You have two options to get the digits to your required value (for example 32767 digits):

1. For **rough** adjustment you use the **additional parameter**.
2. For **fine** adjustment you use the **offset**.

The additional parameter changes the bridge offset. It is used for rough adjustment as it is amplified, too.


To change the additional parameter select the channel you want to adjust and select tab *Parameter*. Enter the new value in the corresponding field.



Confirm your changes with **<Apply>**.

When the digit value of the channel is as near as it gets to your required digit value (for example 32767 digits) with the additional parameter, you start adjusting the offset.

To change the offset select the channel and go to tab *Parameter*. There you can enter values between 0 and 5000 mV in the offset field. The target is to get the digit value of the channel near your required digit value (for example 32767 digits).




Confirm your changes with **<Apply>**.

Step 3: Adjusting the formula

When the values for amplification, offset and additional parameter are set, you change the formula of the channel. The formula is used to set the zero-point to your required value of the measurement range and to adjust the multiplier.

Example: If you adjust the additional parameter and the offset in tab *Parameter* to be in the middle of the digit measurement range, the zero-point of your measurement range will be in the middle as well. With the offset of the formula you shift the zero-point of the scale (y-scale in the diagram below). And the multiplier will change the range value.



For changing the formula you select the channel in the system tree and select tab *Analysis*. There you can choose between the “new formula” and the “old formula” (click on **<Old Formula>** or **<New Formula>** respectively).

New formula:

System Logger
 Logger
 BC-SG2
 Interfaces
 Channels
 Analog
 01 AN#1
 02 AN#2
 03 Vext
 04 Temp

General **Analysis** Fixpoint-Formula Parameter Data type Telemetry Sensor

Calibration
 Value f(x) Multiplier Fixdigits Offset
 32767,0 = 1 * 32767 + 0
 Zero position
 Calibration
 Old Formula

Graph
 Show Graph

Display
 Color

Lower limit
 0,0
 Upper limit
 0,0

Member of group
☐ Start ☐ Group 9
☐ Engine ☐ Group 10
☐ Suspension ☐ Telemetry
☐ Timediff ☐ TeleScope
☐ Temperature ☐ TeleSave
☐ Pressure ☐ Group 14
☐ ACC ☐ Group 15
☐ Brake-Press ☐ Group 16

Old formula:

System Logger
 Logger
 BC-SG2
 Interfaces
 Channels
 Analog
 01 AN#1
 02 AN#2
 03 Vext
 04 Temp

General **Analysis** Fixpoint-Formula Parameter Data type Telemetry Sensor

Calibration
 Value f(x) Multiplier Digits Offset
 32767,0 = 1 * (32767 - 0)
 Zero position
 Calibration
 New Formula

Graph
 Show Graph

Display
 Color

Lower limit
 0,0
 Upper limit
 0,0

Member of group
☐ Start ☐ Group 9
☐ Engine ☐ Group 10
☐ Suspension ☐ Telemetry
☐ Timediff ☐ TeleScope
☐ Temperature ☐ TeleSave
☐ Pressure ☐ Group 14
☐ ACC ☐ Group 15
☐ Brake-Press ☐ Group 16

Enter the new values for multiplier and offset in the fields.

Confirm your changes with **<Apply>**.

Example: You want the zero-point to be in the middle of the measurement range and you're expecting forces from -3000 N to +3000 N. In tab *Parameter* you have already set the right parameters and now you want to change the formula of the channel in tab *Analysis*.

You can choose between the "new formula" and the "old formula". To get the right value of the range you enter the multiplier. The range is from 0 to 65535 (like the digits). As you don't need such a big range, you can scale it down. In this example you need the range to be at least 6000 (from -3000 to +3000). Therefore the multiplier will be 0.1 in the new formula or 1/10 in the old formula.

Next you enter the offset of the formula. You want to have the value of your channel to be 0, as it is unstressed. In the old formula you simply enter the value of the current digits (in this example 32767), as the digits and the offset are subtracted before they are multiplied with the multiplier. In the new formula the digits are multiplied with the multiplier before the offset is added. Therefore you have to enter the value of the multiplied digits, in this case -3276.7.

Step 4: Calibrate the strain gauge channel

After adjusting the formula of the channel you need to calibrate it.

Select the channel in the system tree and select tab *Fixpoint-Formula*. Click on **<Calibrate>**.

System Logger
Logger
BC-SG2
Interfaces
Channels
Analog
01 AN#1
02 AN#2
03 Vext
04 Temp

General | Analysis | **Fixpoint-Formula** | Parameter | Data type | Telemetry | Sensor

Value calculation with Fixpoint-Formula

	Min theoretical	Current	Max theoretical
Input [V]	0.0000	1.8665	5.0000
Complies digits at ADC	0	24464	65535
Value on CAN bus		24464	
Multiplier	1		
Divisor	1		
Digits at ADC	24464		
Offset	0		
Physical value after calibration formula	-3276.7		
Multiplier	1		
Divisor	10		
Digits	24464		
Offset	-3276.7		
Physical value after calibration formula	-3276.7		

Number of different possible values = $65535 \cdot 1 / 1 = 65535$ with a resolution of 0.1

Reset to identity
Invert range
Set Zero
Calibrate

Select **<Rule of Three Automatically>** in the next window.

Channel Calibration: AN#1

Rule of Three Manually


Clicking this button will start the rule of three dialog. In this dialog you have to enter physical values corresponding to two voltage- or digits-values to calibrate the sensor.

Rule of Three Automatically

Clicking this button will start the sampling of the channel to find the minimum and maximum value for this channel. After the sampling the rule of three dialog opens and you have to enter the corresponding physical values for the sampled minimum and maximum.

Depending on the direction of the force, it may be, that the digit-value of the stressed component is below the digit-value of the unstressed component. Please pay attention to that. Now you click on **<Refresh Minimum>** when the component has the lower digit value (unstressed or stressed with the Strain Gauge Module

defined weight). After that you set the second state (stressed or unstressed) and click on **<Refresh Maximum>**. Then click **<OK>**.



Channel-calibration

Move the sensors to minimum and maximum position and click OK!


Refresh Minimum Refresh Maximum

	Minimum	Maximum	Delta	Change
01 AN#1	Scanning 27005,0 / 27005	Scanning 27020,0 / 27020	15	<input checked="" type="checkbox"/>

OK Cancel Reset

Enter the values in the next window.

For example "0" as the lower physical value, as the component is unstressed, and "98.1" as the upper physical value, as the component is stressed with a weight of 10 kg (=98.1 N).



Calibration of channel 01 AN#1

Unit: ☐ Fixpoint digits ☐ Digits ☒ Volt

Lower physical value

Value: 26958 at Volt: 2.056764

Upper physical value


Value: 27020 at Volt: 2.061494

OK Cancel

Click on **<OK>** and confirm the calibration with **<Apply>**.

Step 5: Set the channel to zero

Before you use the system you should set the strain gauge channels to zero. Therefore it is useful to use the auto-zero function. You can enable this function in tab *General* of the channel.



System Logger

- Logger
- BC-SG2
 - Interfaces
 - Channels
 - Analog
 - 01 AN#1
 - 02 AN#2
 - 03 Vext
 - 04 Temp

General Analysis Fixpoint-Formula Parameter Data type Telemetry Sensor

Name: AN#1

Dimension:

Short cut:

Channel-Type: Analog

Channel-Mode

Recording: ☒

Use table: ☐

Internal linearization: ☐

Auto zero: ☒

Alarm enabled: ☐

Error-info enabled: ☐

Then you simply hit the auto-zero button and the channels, which have the auto-zero function enabled, will be set to zero.

