
FABRICATION PROCEDURES REVISION 1.0











INDEX

i
i
1
2
2
3
2
5
ć
7
8

LEGAL DISCLAIMER

General Documentation Disclaim

This manual is intended as a manufacturing and installation advisory document. For correct specifications, sizing of profiles and structural information please consult the StarFront Application. If the information you require is not available through the StarFront Application, please contact a Wispeco Technical Representative before proceeding. It is advisable to have all sizing and performance criteria checked by a qualified structural engineer to ensure that all performance and compliance will be met.

All information, recommendations or advice contained in this documentation is given in good faith to the best of Wispeco's knowledge and is based on current procedures in effect.

Since the actual use of this documentation by the user is beyond the control of Wispeco, such use is within the exclusive responsibility of the user. Wispeco cannot be held responsible for any loss incurred through incorrect or faulty use of this documentation. Training of Wispeco systems is important for ensuring correct procedures in the manufacturing of products.

Great care has been taken to ensure that the information provided is correct.

Ensure that you have the latest available manual. The revision number and date can be checked on the latest StarFront version.

This Guide may be reproduced in whole or in part in any form or by any means provided the reproduction or transmission acknowledges the origin, revision number and copyright date.

Specifications concerning products and applications

This manual is based on standard configurations only. As there are many configurations not covered in this manual, contact a Wispeco Technical Consultant with regard to a configuration not represented herein.

AutoDesk drawings (CAD Symbol Library) are available on request and can be issued with the consent of the Wispeco Technical Department.

All mechanical joints must be sealed with Crealco Silicon. Failure to correctly seal the joints can affect the performance of the system. Information on joint sealing can be found in the Cleaning θ Maintenance Manual available for download from the Wispeco website.

All drawings in the Wispeco Documentation are shown NOT to scale are used for illustrative purposes only. For correct sizing and machining of system profiles refer to the Wispeco StarFront Aplication.

Wispeco cannot accept responsibility for the use of standard products since Wispeco does not know where these products are being installed.

The hardware recommended in this documentation is suitable for use in most atmospheric environments. When hardware is used in severe coastal environments the manufacturer of the hardware must be consulted.

The use of non-specified hardware or incorrect mechanical fasteners can adversely affect the mechanical and weathering performance of the system and we strongly advise against deviations. A Wispeco Consultant can advise you of any hardware issues and limitations with regard to this system.

The use of anti-magnetic stainless steel screws and aluminium pop rivets is recommended to reduce galvanic corrosion in harsh environments.


Fixing lugs on frames must be positioned as per the user manual and used in accordance to the AAMSA specifications. When profiles are screwed together the screw centrers must also be according to the user manual or as specified by an engineer.


All glass used within Wispeco products must comply with SAGGA regulations. Laminated glass must not stand in water.

By continuing to use this documentation you acknowledge that you understand and accept the legal disclaimer.

Installation Procedures 1

Spigots (Pre-site installion procedure)






- 1.1 Establish transome centres
- 1.2 Fit pre-cut spigots using 5.5 x 70 St. St. Tek screws.
- 1.3 Ensure spigots are correctly positioned on the V-groove of the mullion
- 1.4 Ensure correct orientation of the Spigot

Note: Fasten the spigot to the mullion using the open port as this will allow minor adjustments to be made before complete fxation using the closed port.


3.1 Ensure the correct placing of the spigot , especially for the bottom transome.





Pre-Site Procedure

Sill





- 1.1 Ensure sill is cut to length and ensure weep holes are machined as per manual (See page 13).
- 1.2 Fit Euro butterfy gasket as shown.
- 1.3 Fit & silicone end caps to both sides of sill.
- 1.4 Ensure that water can freely fow through drainage holes (no burs or debris).

Installation Procedure

Sill Installation






- 2.1 Place the sill into position on site as required. Ensure sill is level and free of debris before fxing.
- 3.1 Ensure silicone is placed over all fxings to ensure no water ingress under the sill.
- 4.1 Seal the entire sill perimeter with the appropriate silicone sealant, paying attention to all joints and especially where the sill terminates.




- 5.1 Where sills need to be joined together, care must to be taken to keep them frmly together while fxing.
- 5.2 Ensure that both sill ends receive silicone to seal appropriately.
- 6.1 Ensure proper care is taken to seal between the end caps & structue.






Installation Procedure 3

Mullion Brackets (top & bottom)




Bracket Assembly

- A. Base Plate
- B. Expansion Profle (top & bottom)
- C Pressure plate screws
- D. Anchors as specifed by engineer



1.1 The Mullion Bracket allows for adjustment of the mullion once the holes and fxation is in place.



1.1 Note the correct positioning of the sill in relation to the mullions.


Installation Procedure

Mullion






- 1.1 Position mullions over sill as required & place into position. Ensure expansion profle with base plate is ftted into mullions (top & bottom) prior to positioning mullions over sill.
- 1.2 Ensure the gap between the top of the mullions & soft is at least 35 mm to accept the compensating angle.
- 1.3 Mullions should be approximatley 1 mm of the sill.




Installation Procedures 5

Mullion Jig Assembly




- The Spigot Clamp is a clamping and alignment tool which allows for on-site placement and alignment of the spigots to the mullions. The magnetic faceplate allows for the integration of laser levelling from one mullion to the next, or for spirit levelling while the mullion is being afxed. The rapid clamps allow for quick placement and rapid release.
- Alignment Block Alignment of the spigot to the v-groove of the mullion
- 1.2 Magnetic Attachment Face Attachment face for Levels and laser alignment accessories
- 1.3 Clamping Block Clamps the spigot in place and ensures no movement when screwing in the TEK Screws
- 1.4 Extension Rods The rods come in diferent sizes for the diferent mullion sizes.
- 1.5 Rear Clamp The rear clamp is a quick release connector to connect two spigot clamps together, ensuring that they are both alighned.



- 2.1. The Spigot Clamp is pre-loaded with a spigot and placed in the gasket plate on the front of the mullion.
- 2.2. The Rear plates connect using the two clamps

Installation Procedures 6

Transome









- 1.1 Ensure spigots are correctly positioned before ftting transomes.
- 1.2 The transomes should be fitted with the transome end caps & appropiate pvc glazing spacer.
- 2.1 Slide transomes over spigots until frmly located.
- 2.2 Ensure compression on Transome End Cap is sufcient to ensure a consistent seal. If there is not enough compression the system will allow water ingress into the joint.
- 2.3 Apply Silicone to Transome End Cap if the joint is in question.
- 3.1 Fix transomes to spigots using No. 6.3 x 20 St. St. self drilling tek screws. ((Holes must be 20 mm from transome ends)
- Fit appropriate pre-cut glass support profles as required for single or double glazing glass with glass support blocks. The glass supports must be min 100mm from edge of transome.




NOTE:

The glass setting blocks must be a minimum of 27 mm long for a square metre of glass. Between 1 & 2 sq/m glass, the setting block to be cut to 54 mm, & for glass between 2 & 3 sq/m, the setting blocks to be 81 mm long.


5.1 Ensure for each transome that that the gaskets are cut & positioned correctly.

Note: See diagram for correct fitting & vulcanising gaskets to the transome end caps.

Glazing



jelly is applied to both the front and rear gaskets. This allows for easier positioning of the glass in the curtain wall opening as well as allows glass to seat better onto the gaskets.



1.1. Before the fitting of glass, it is recommended that petrolleum 2.1. The glazing panels can now be placed into the openings. Ensure care is taken to position glass correctly & squarely within each opening & onto the glass setting blocks.



3.1. Once glass is in place, the vertical pressure plates calcular Fix vertical pressure plates using correct screws with a torque be positioned over the pvc spacer. Ensure the appropriate gaskets have been inserted.





5.1. Once the vertical pressure plates are fixed, the horizontal 6.1. The vertical covers can now be clipped in over the pressure plates, pressure plates can be fxed into place, remember to allow 2 mm gap between horizontal pressure plates & vertical




pressure plates as the vertical covers will not clip on properly.



NOTE: Very important to silicone seal along the entire length of the sill once the bottom transome has been ftted.




followed by the transome covers. Remember to position the horizontal covers correctly with the weep holes on the underside. Always ensure that the vertical covers are fitted past the transomes.



8.1. Before ftting the top row of glass panels, the 50 x 50 x 6 comp. angle needs to be ftted.

Transome Pad Gaskets

Installation Procedures





- 1.1. Before fitting the gaskets, ensure that the channel which house the gaskets are clean. Ensure that the gaskets are cut an extra 3 mm on each end, and correctly inserted into the gasket channel of the mullions and transomes.
- 1.2. Ensure that the ends are properly cleaned and free from any
- 1.3 Test the joint before applying the glue, do not stretch the gasket
- 2.1. Butt the transome gasket to the corresponding profle on the gasket pad. Place one drop of 3M Vulanising Glue into the but joint and hold in place until the glue is properly bonded.
- 2.2. Place the mullion gasket against the side wall of the gasket pad profle, ensure the mullion gasket can tuck in under the transome



A. Insert the Transome Clip end cap into the Transome clip-on cover.

B. Insert the transome Clip-on cover into the rear transome assembly.

