User's Manual

Calibration Unit PGT120



Wolfgang Warmbier Untere Gießwiesen 21 D-78247 Hilzingen/Germany

www.warmbier.com



1 Introduction

The Calibration Unit contains resistors to test the limits of the Personal-Grounding-Tester PGT 120. It works without battery or any external power supply.

To measure the PGT 120 - test voltage you need a DC-voltmeter with an impedance of $\geq 10 \text{M}\Omega$.

Notice: Remove <u>all</u> connections from the measuring inputs of the PGT!


Keep the calibration unit at a dry place.

After taking the Calibration Unit from a cold into a warm environment, let it warm up to prevent from condensation, otherwise it will affect on accuracy.

2 Test voltage measurement

To check the test voltage, set the marked lever of the rotary switch to \simega and connect:

- the central jack of the calibration unit to the 3 mm snap of the PGT 120 (same symbols). Use the DK3-socket adaptor which is included.
- The left jack of the calibration unit to the black 4 mm banana socket of the PGT 120
- (wrist strap test, same symbols ooo).



Use a DC-voltmeter with impedance Ri \geq 10M Ω , preferably measuring range 2V.

Connect the right jack of the Calibration Unit also to minus-input of the voltmeter and the central jack of the Calibration Unit to plus-input.

Select the test voltage 30V, 50V and 100V with DIP-switches 4 and 5 and press the left contact electrode for each measurement.

DIP-switch settings

	, -	
Switch 4	Switch 5	Test voltage
OFF	OFF	30 V
OFF	ON	50 V
ON	ON	100 V

Page 2 / 7 Edition: April 2008



The test voltage is calculated by reading x 100. Example: reading = $0.97V \Rightarrow$ test voltage = 97.0V

3 Preparation


Starting point for all measurements are the following DIP switch settings. The calibration is performed with the customers test voltage setting (DIP-switch 4 and 5) If desired, the test can be repeated with the other available test voltage settings.

ON	7					
OFF		6		3	2	1

4 Wrist strap verification


To check the limits of the wrist strap test connect:


- the middle jack of the calibration unit with the 3 mm snap of the PGT 120 (same symbols). Use the DK3-socket adaptor which is included.
- the left jack of the calibration unit with the black 4 mm banana socket of the PGT 120. (wrist strap test, same symbols 600).



Set the marked lever of the rotary switch in succession to the positions mentioned below. Press the <u>left</u> contact electrode for each measurement.

Display LED





35M H		
≎	0	0
0		
0	0	0


Page 3 / 7 Edition: April 2008



5 Footwear test verification (single shoe) - right


To check the limits of the footwear test connect:


- the middle jack of the calibration unit with the 3 mm snap of the PGT 120 (same symbols). Use the DK3-socket adaptor which is included.
- the left jack of the calibration unit with the red 4 mm socket on the rear side of the PGT 120 (footwear electrode, same symbols).




Set the marked lever of the rotary switch in succession to the positions mentioned below. Press the <u>right</u> contact electrode for each measurement.










Display LED

5.1 DIP-switch settings: Upper limit 70 M Ω

Switch 3	_	ON	7			3		
ON	7	OFF		6			2	1

Set the marked lever of the rotary switch in succession to the positions mentioned below. Press the <u>right</u> contact electrode for each measurement.



Display LED


Page 4 / 7 Edition: April 2008



6 Footwear test verification (single shoe) - left

To check the limits of the footwear test connect:


- the middle jack of the calibration unit with the 3 mm snap of the PGT 120 (same symbols). Use the DK3-socket adaptor which is included.
- the left jack of the calibration unit with the yellow 4 mm socket on the rear side of the PGT 120 (footwear electrode, same symbols •).



6.1 DIP-switch setting for upper limit 35 $M\Omega$

Switch 3	_	ON	7					
OFF	7	OFF		6		3	2	1

Set the marked lever of the rotary switch in succession to the positions mentioned below. Press the <u>right</u> contact electrode for each measurement.



33	IVI ON	L	
0		0	≎
	0		
0		0	0

35M OK

	35	M Hi		
Ī	0		≎	≎
		0		
	0		0	0


Display LED

6.2 DIP-switch setting for upper limit 70 M Ω

Switch 3	_	ON	7			3		
ON	7	OFF		6			2	1

Set the marked lever of the rotary switch in succession to the positions mentioned below. Press the <u>right</u> contact electrode for each measurement.

70M OF	(
0	0	≎
0		
0	0	0



Display LED


Page 5 / 7 Edition: April 2008



7 Footwear test in series

To check the limits of the footwear test connect:


- the middle jack of the calibration unit with the red 4 mm socket on the rear side of the PGT 120
- the left jack of the calibration unit with the yellow 4 mm socket on the rear side of the PGT 120



7.1 DIP-switch setting

Switch 6		ON	7	6		3		
ON	7	OFF					2	1

Set the marked lever of the rotary switch in succession to the positions mentioned below. Reset the instrument after each measurement by disconnecting the left wire:



7.2 DIP-switch setting for upper limit 70 M Ω (only for PGT 120 with serial No. 00260 and above) :

Switch 3	_	ON	7	6				
OFF	7	OFF				3	2	1

Set the marked lever of the rotary switch in succession to the positions mentioned below. Reset the instrument after each measurement by disconnecting the left wire:

70M OI	K		70N	l Hi		
0	0	0	0		≎	≎
\$	}			0		
0	0	0	0		0	0
Display	/ I FD					

Page 6 / 7 Edition: April 2008




8 Calibration Unit verification

Recommended calibration cycle: 3 years

To check the resistors, connect a suitable Ohmmeter to the central jack and the left jack of the Calibration Unit and set the **marked** lever of the rotary switch in succession to the marked positions. The corresponding resistor values and tolerances can be taken from the drawing below.

Also connect the Ohmmeter to the central and right jack of the Calibration Unit. Nominal value must be: 24,4 k Ω ±1%



Page 7 / 7 Edition: April 2008