



Setup of Moored Instruments


- In this module we will discuss:
 - SeatermV2 and Seaterm, the user interface
 - Status reports, header listings, and data formats
 - Preparing for deployment
 - Conversion of data to a format used by SBE Data Processing



Setting up Moored Instruments: Seaterm V2 and Seaterm

- Seaterm V2 and Seaterm


- Set up an instrument for deployment
- Transfer data from an instrument to user's computer
- Do data conversion for SBE 37 and SBE 39 to allow further processing with Seasoft's data processing software (SBE Data Processing)





Seaterm232: for RS-232 Instruments

Menus →




**Status
bar** →



Connecting to Instrument

- The first time Seaterm232 is used, it asks for Com port and baud rate




- Then, it attempts to connect, and if successful fills *Send Commands* window with appropriate set of commands

Select
command

Description

Arguments
for command

Actual
command





Check Onboard Instrument Calibration Coefficients

Confirm calibration coefficients are programmed and are from most recent calibration

- Type command in Command Window: **DC**
(DisplayCoefficients)
or
- In Send Commands window, under Status, select *Display Calibration Coefficients* and click Execute button

In this example, coefficients have not been programmed into instrument, and must be entered.

DC

SBE37SM-RS232 v4.1 9077

temperature: not set

TA0 = 0.000000e+00

TA1 = 0.000000e+00

TA2 = 0.000000e+00

TA3 = 0.000000e+00

conductivity: not set

G = 0.000000e+00

H = 0.000000e+00

I = 0.000000e+00

J = 0.000000e+00

CPCOR = -9.570000e-08

CTCOR = 3.250000e-06

WBOTC = 0.000000e+00

pressure S/N 3537457, range = 508 psia not set

Etc.....



Checking Instrument Status

Confirm status of your instrument -- show date/time, battery voltage, minimum pump delay, etc.

- Type **DS** to display status in Command window.
Or
- In Send Command window, click *Status*, click *Display Status and Configuration (or Setup) Parameters* and click Execute button at bottom of window



Checking Instrument Status:

SBE 16*plus* V2 Example

DS

SBE 16plus V 2.5 SERIAL NO. 6001 24 Feb 2012 14:11:48

[DateTime=]

vbatt = 10.3, vlith = 8.5, ioper = 62.5 ma, ipump = 21.6 ma, iext01 = 76.2 ma,

status = not logging

samples = 0, free = 3463060

sample interval=15 seconds, number of measurements per sample=1 [SampleInterval=,NCycles=]

pump=run pump during sample, delay before sampling=2.0 sec,

delay after sampling = 0.0 seconds [PumpMode=,DelayBeforeSampling=, DelayAfterSampling=]

transmit real-time = yes

[TxRealTime=]

battery cutoff = 7.5 volts

pressure sensor = strain gauge, range = 1000.0

[PType=, PRange=]

SBE 38=no, SBE 50=yes, WETLABs = no, OPTODE = no, SBE63 = no,

Gas Tension Device=no [SBE38=,SBE50=, WetLabs=,Optode=,SBE63=,GTD=,DualGTD=]

Ext Volt 0 = yes, Ext Volt 1 = no

[Volt0=,Volt1=]

Ext Volt 2 = no, Ext Volt 3 = no

[Volt2=,Volt3=]

Ext Volt 4 = no, Ext Volt 5 = no

[Volt4=,Volt5=]

echo characters = yes

[Echo=]

output format = raw HEX

[OutputFormat=]

serial sync mode disabled

[SyncMode=]



Checking Instrument Status: SBE 37-SM RS-232 Example

ds

SBE37SM-RS232 v4.1 SERIAL NO. 9077 15 May 2012 17:10:48

vMain = 13.37, vLith = 2.86

samplenum = 9, free = 559231

not logging, stop command

sample interval = 15 seconds

data format = raw Decimal

This will output in frequency (Output Format=0)

output salinity

transmit real-time = yes

This will transmit data real-time to screen while running

sync mode = no

pump installed = yes, minimum conductivity frequency = 3045.5

*This value is for
higher salinity
waters*



Setting Date and Time in SeatermV2

To set the clock to Local time or UTC, click Command menu, and select your time preference

OR

In Command window: type **DateTime=mmddyyyymmss**
(real-time clock month, day, year, hour, minute, second)

OR

In Send Commands Window: Click *General Setup*, click *Set Date and Time*, enter the date and time (mmddyyyymmss), and click Execute button



Pump Settings

In Command window, type: **MinCondFreq=x**
where x = minimum conductivity frequency (Hz)

OR

In Send Commands window, click *Pump Setup*, click *Set Minimum Conductivity Frequency (Hz) to Enable Pump*, enter frequency, and click Execute button.



Files Created with Autonomous Moored CTDS

- Moored Instruments
 - Older versions of firmware upload data in format that can be directly converted in Seaterm
 - These do NOT require a *.con* or *.xmlcon* file (configuration file)
 - Use any configuration file...software uses internally stored coefficient data to compute engineering values
 - New Versions upload HEX Files that are then converted with SBE Data Processing
 - These DO require a *.xmlcon* (configuration file) to convert from Hexadecimal to Engineering



Upload Types

- Moored instruments
 - All data as a single file:
All scans
 - By scan number range:
Enter beginning scan
number and number of
scans to upload
 - ALWAYS SAVE THE
COMPLETE RAW
XML FILE as a
backup

Upload Data

Upload Data | Header Form

Upload format
☐ Text ☒ Binary

Block size [bytes]
100000

Memory summary
Bytes 216
Samples 18
SamplesFree 5592387
SampleLength 12
Profiles 0

Upload data options
☐ All data as a single file ☒ By scan number range
☐ All data separated by cast ☐ From a single cast
☐ By cast number range

Scan range
Beginning with scan # 1
Number of scans to upload 10

Baud rate for upload
Not applicable unless device type = SBE54.

Upload file
C:\SBE39plus_03906502_2013_10_30.XML
Browse...

Help Upload Cancel



Activity: Setting up, Logging, and Uploading Data

- Use SeatermV2 to view status, then set up your SBE 37-SM MicroCAT, start and stop logging, and upload data; see notes for instructions



Converting Sensor Output to Scientific Units

- SBE 16*plus* and 16*plus* V2 report data in scientific units or as frequencies and voltages
 - Data uploaded as .hex, use Data Conversion
- Older SBE 16 stores and reports data as frequencies and voltages
 - Data uploaded as .hex, use Data Conversion
- Newer SBE 37s – SeatermV2 uploads SBE 37 data to .xml file, converts to .hex file, and creates .xmlcon configuration file
 - Use Data Conversion to convert to engineering units using calibration data in .xmlcon file.
 - If you only have .xml data file, use *Convert .xml Data File* in SeatermV2 *Tools* menu to convert to .hex file
- SBE 39*plus* – SeatermV2 uploads SBE 39*plus* data to .xml file, converts to .asc file (for plotting in Plot39)
 - You can also convert to .cnv file



Converting SBE 39 and Older SBE 37 Data

- For SBE 39 and older SBE 37 MicroCATs, use older terminal program Seaterm
 - Click *Upload* button
 - Upload in engineering units in ASCII (*.asc*) format
 - Click *Convert* button to convert *.asc* file to *.cnv* file



SBE 16*plus* V2 Headers

DH1,2

hdr 1 30 Oct 2007 09:12:07 samples 1 to 34, int = 60, stop = stop cmd

hdr 2 30 Oct 2007 12:30:33 samples 35 to 87, int = 60, stop = stop cmd

Displays:

- Header number
- Date and time for when header was written
- First and last sample for header
- Interval between samples
- Reason logging was halted

Note: GetHeaders:1,2 is the equivalent of DH1,2



SBE 16 Data Format

- Data is in hexadecimal format, T and C only
- Adding auxiliary sensors adds bytes to the scan

S>dd31,10

8A7503DB

8A7D03DB

8A9203DB

8A8D03DB

8ABB03DB

8AD803DB

8AE103DB

8AF603DC

8B0503DC

8B0603DB

S>



SBE 16*plus* Data Formats

- Raw data in hexadecimal
0442F20A8A7309B04A4D2C28730D24
04429D0A8A6F09B0494D4828730D42
0442210A8A6C09B04A4D3A28730D60
- Converted data in hexadecimal
32505C0F51F601867A28730D24
3253760F51EA01867A28730D42
3257F70F51E101867A28730D60
- Raw data in decimal
279282, 2698.449, 634954, 1.5073, 03 Jul 2001, 11:57:24
279197, 2698.434, 634953, 1.5094, 03 Jul 2001, 11:57:54
279073, 2698.422, 634954, 1.5084, 03 Jul 2001, 11:58:24
- Converted data in decimal
22.9737, 0.00402, -0.037, 03 Jul 2001, 11:57:24
22.9817, 0.00401, -0.038, 03 Jul 2001, 11:57:54
22.9932, 0.00400, -0.038, 03 Jul 2001, 11:58:24



SBE 16*plus* V2 Data Formats

- Raw data in hexadecimal
0442F20A8A7309B04A4D2C28730D24
04429D0A8A6F09B0494D4828730D42
- Converted data in hexadecimal
32505C0F51F601867A28730D24
3253760F51EA01867A28730D42
- Raw data in decimal
279282, 2698.449, 634954, 1.5073, 03 Jul 2001, 11:57:24
279197, 2698.434, 634953, 1.5094, 03 Jul 2001, 11:57:54
- Converted data in decimal
22.9737, 0.00402, -0.037, 03 Jul 2001, 11:57:24
22.9817, 0.00401, -0.038, 03 Jul 2001, 11:57:54
- Converted data in XML
<?xml?><datapacket><hdr><mfg>Sea-Bird</mfg><model>16plus</model>
<sn>1606001</sn></hdr><data><t1> 22.9737 </t1><c1> 0.00402 </c1>
<p1> -0.037 </p1><dt>2007-11-07T07:34:35</dt></data></datapacket>



SBE 37 Data Formats

- **Firmware version < 3.0** (SM, SMP, SI, SIP)

Format=1: 23.0161, 0.00002, 0.076, 08 Mar 2008, 17:10:23

Format=2: 23.0161, 0.00002, 0.076, 03-08-2008, 17:10:23

- **Firmware version \geq 3.0** (SM, SMP, SI, SIP, IM, IMP)

OutputFormat=1:

23.0161, 0.00002, 0.076, 08 Mar 2008, 17:10:23

OutputFormat=2 (SM, SMP, SI, SIP) or 4 (IM, IMP):

```
<?xml version="1.0"?><datapacket><hdr><mfg>Sea-Bird</mfg>
<model>37SM</model><sn>03709999</sn></hdr>
<data><t1> 23.0161</t1><c1> 0.00002</c1><p1> 0.076</p1>
<dt>2008-03-08T 17:10:23</dt></data></datapacket>
```



SBE 39 Data Format

```
S>
S>dd1,8
start time = 03 Oct 2001 14:41:12
sample interval = 5 seconds
start sample number = 1

25.4562, -0.031, 03 Oct 2001, 14:41:12
25.4581, -0.031, 03 Oct 2001, 14:41:17
25.4625, -0.029, 03 Oct 2001, 14:41:22
25.4642, -0.029, 03 Oct 2001, 14:41:27
25.4682, -0.029, 03 Oct 2001, 14:41:32
25.4715, -0.029, 03 Oct 2001, 14:41:37
25.4750, -0.029, 03 Oct 2001, 14:41:42
25.4704, -0.029, 03 Oct 2001, 14:41:47
S>
```




Activity: Converting and Plotting Time Series Data

- Use Seaterm (**not** SeatermV2) to convert data from an older SBE 37, and then use Derive and Sea Plot to calculate and plot salinity and density; see notes for instructions

Auxiliary Sensors

- CTD status response (**DS**) in SeatermV2 indicated if auxiliary sensor channels are enabled or disabled
 - If channel is not enabled, CTD will not supply power to sensor or acquire data from sensor





Auxiliary Sensors:

WET Labs ECO-FL Example

- ECO-FL can be used for profiling or moorings
 - Profiling – Open bio-wiper when power applied, keep it open, and sample and transmit data continuously
 - Moored – Open bio-wiper when power applied, sample and transmit data, close bio-wiper; repeat
- Set up ECO for moored mode in WET Labs ECOView software or a terminal program
 - !!!!! (access sensor command set)
 - \$set 1 (note space between command and number)
 - \$pkt 1 (note space between command and number)
 - \$sto (store settings in memory)



Auxiliary Sensors:

WET Labs Example (ASV Setting Examples)

ECO Chlorophyll Fluorometer

ASV Value	Scale Factor	Range	Resolution
4	26	0-125 ug Chl/l	0.03 ug Chl/l
2	13	0-60 ug Chl/l	0.015 ug Chl/l
1	6	0-30 ug Chl/l	0.007 ug Chl/l

Send following commands to set ASV setting:

!!!!!!

\$asv 1, 2, or 4



Auxiliary Sensors:

WET Labs ECO-FL Example

- Plug ECO into voltage channel 0 (can be any channel) on *16plus V2*; connect CTD to computer
- Run *SeatermV2*; send commands to *16plus V2*
 - **Biowiper=y** (provide enough time for bio-wiper to close after sending a status command)
 - **MM** (moored mode)
 - **Volt0=y** (enable voltage channel 0)
 - **SetVoltType0=ECOFL** (sensor type on voltage channel 0)
 - **SetVoltSN0=12345** (serial number of sensor on voltage channel 0)
 - (continued on next slide)



Auxiliary Sensors:

WET Labs ECO-FL Example

- More setup in SeatermV2
 - **DelayBeforeSampling=4** (provide enough time after applying power for ECO-FL bio-wiper to open before taking a sample)
 - **Note: DelayBeforeSampling=4** is sufficient if ECO-FL is set up to take a single measurement for each sample (\$pkt 1); increase it if taking more measurements for each sample.
 - **DelayAfterSampling=4** (provide enough time for ECO-FL bio-wiper to close after taking a sample, before turning off power)
 - Send **DS** (verify setup)



Auxiliary Sensors:

WET Labs ECO-FL Example

When done with the setup, the status (DS) response should look like this (items not shown in bold may vary):

SBE 16plus V 2.5 SERIAL NO. 4000 24 Jan 2011 14:02:13
vbatt = 10.1, vlith = 8.9, ioper = 61.9 ma, ipump = 20.8 ma, iext01 = 76.2 ma,
status = not logging
samples = 0, free = 3463060
sample interval = 60 seconds, number of measurements per sample = 1
pump = run pump during sample, **delay before sampling = 4.0 seconds, delay after sampling = 4.0 seconds**
transmit real-time = yes
battery cutoff = 7.5 volts
pressure sensor = strain gauge, range = 1000.0
SBE 38=no, SBE50=no, WETLABS=no, OPTODE=no, SBE63=no, Gas Tension Device=no
Ext Volt 0 = yes, Ext Volt 1 = no
Ext Volt 2 = no, Ext Volt 3 = no
Ext Volt 4 = no, Ext Volt5 = no
echo characters = yes
output format = raw HEX
serial sync mode disabled



-
- Fluorometer, WET Labs ECO-AFL/FL
- Serial number
- Calibration date
- Dark output
- Scale factor
- Import Export OK Cancel

Configuration for the SBE 16plus V2 Seacat CTD

Configuration file opened: None

Pressure sensor type: Strain Gauge Data...

External voltage channels: 1

Serial RS-232C sensor: None

Sample interval seconds: 10

☐ NMEA position data added

Channel	Sensor
1. Count	Temperature
2. Frequency	Conductivity
3. Count	Pressure, Strain Gauge
4. A/D voltage 0	Fluorometer, WET Labs ECO-AFL/FL

New Open... Save Save As... Select... Modify...

Report... Help... Exit Cancel



Auxiliary Sensors:

WET Labs ECO-FL Example (Calibration Sheet Example)

ECO Rhodamine Fluorometer Characterization Sheet

Date: 9/21/2010

S/N: FLRHRT-2040

Rhodamine concentration expressed in ppb can be derived using the equation:

$$\text{Rhodamine (ppb)} = \text{Scale Factor} * (\text{Output} - \text{Dark Counts})$$

Dark Counts

Scale Factor (SF)

Maximum Output

Resolution

Ambient temperature during characterization

	↓ Analog Range 1	↓ Analog Range 2	↓ Analog Range 4 (default)	Digital
	0.076	0.045	0.030 V	
	12	23	47 ppb/V	0.0141 ppb/count
	4.92	4.92	4.92 V	16380 counts
	0.8	0.8	0.8 mV	1.0 counts

21.5 °C



Auxiliary Sensors:

WET Labs Example (Calibration Sheet Example)

FLNTU Characterization Sheet

Date: July 30, 2012

S/N: FLNTUS-2771

Chlorophyll Scale Factor

Chlorophyll concentration expressed in $\mu\text{g/l}$ can be derived using the equation:

$$\text{CHL } (\mu\text{g/l}) = \text{Scale Factor} \times (\text{Output} - \text{Dark Counts})$$

Dark Counts

Scale Factor (SF)

Maximum Output

Resolution

Ambient temperature during calibration

Analog		Digital	
0.072	V	43	counts
10	$\mu\text{g/l/V}$	0.0118	$\mu\text{g/l/count}$
4.98	V	4130	counts
0.9	mV		
22.3	$^{\circ}\text{C}$		

Nephelometric Turbidity Unit (NTU) Scale Factor

Turbidity units expressed in NTU can be derived using the equation:

$$\text{NTU} = \text{Scale Factor} \times (\text{Output} - \text{Dark Counts})$$

Dark Counts

NTU Solution Value

Scale Factor (SF)

Maximum Output

Resolution

Ambient temperature during calibration

Analog		Digital	
0.000	V	50	counts
3.77	V	3100	counts
5	NTU/V	0.0061	NTU/count
4.98	V	4130	counts
1.0	mV	1.0	counts

22.3 $^{\circ}\text{C}$

Auxiliary Sensors:

WET Labs ECO-FL Example

- Mount ECO sensors with:
 - Clear path in front of optics face
 - Allow as much free space in front of sensor face as possible
 - Ensure cables are tied to CTD/frame so no cables/ties are able to float in front of sensor face
 - Detector pointed away from CTD body





**Downward
Facing**

**Nothing
In the
Path**

Auxiliary Sensors:

WET Labs ECO-FL Example (Testing ECO Functionality)

- To test ECO functionality:
 - Begin with ECO pointed into open space
 - Place a fluorescent stick/hand 6-8" (15-20 cm) away, in front of sensor face
 - Slowly move stick/hand toward sensor
 - Voltage should increase as stick/hand gets closer to sensor face
 - Slowly move stick/hand away from sensor face
 - Voltage should decrease as distance increases





Preparing for Deployment

- What about Anti-foulant paints?
- Install fresh batteries
- Check outputs from temperature and conductivity and other sensors
- Set internal clock
- Set ID for instruments using inductive modems or RS-485
- Check all cabling, and lubricate and reset underwater connections


Anti-Foul Paint

- Do **NOT** paint instruments with marine anti-fouling bottom paint, as paint will contaminate calibration bath
 - If instrument is painted, all paint must be removed from instrument prior to its return to SBE for re-calibration
 - 3M Tape or the more expensive 3M-Copper tape is an effective anti-foulant that can be used and removed for easy cleaning






Changing Batteries in SBE 16*plus* V2



**Unthread cap by
rotating
counter-clockwise**


**Remove Phillips-
head screws and
washers**



**Install new batteries,
with + terminals
against flat battery
contacts and -
terminals against
spring contacts.**




Changing Batteries in SBE 37




2 screws securing
connector
end cap (screws
shown partially
removed)

Cable mounting
guide



Twist end cap
counter clockwise,
twisting cap screw
out of machined slot;
end cap releases
from housing





Check Connectors and Cables


- Check all the cabling
- Remove the cables from their bulkhead connectors
 - Inspect the bulkhead connectors and mating pieces
 - Clean and lubricate the bulkhead connectors
 - Burp all air out of the connectors when they are resealed



Example: When connectors between a CTD and a sensor become a problem: Moored Oxygen SBE 43

CLUES


- Erratic Data
- Intermittent (good, bad, then good)
- Trending correct
- Clog?
- Fouling?
- Cables?
- Electrical?



POORLY SEATED CONNECTION CAUSED CORROSION ON CONNECTOR



When Underwater Connectors Go Bad



**These were the
connectors on recovery
from the previous page
DO plot showing
Intermittent data.**

**Look for signs of corrosion
before plugging in in sensor.
Be sure connectors are burped
and seated.
Align the pins and do not use
too much lubricant.**



Re-Install Cables and Dummy Plugs

- Clean and re-lubricate connector boots, dummy plugs, and connectors
 - Clean with Kimwipes or other lint free cloth or wipe
 - SBE recommends Dow Corning® DC4 for lubrication
- Never use petroleum-based products





Preparing for Deployment

- Check memory, clear if necessary
 - (not all SBE 37s have internal memory)
 - Provides back up to real-time system
 - old data will NOT be overwritten
- Set Start Logging Date and Time
- Set sampling interval
 - be sure to check your battery endurance!



Sample QUICKSTART Checklist for SBE 37

SBE37 RS232 SN _____

Operator _____ Date _____ Checked by _____

Communications tab, Configure, Com Port _____, Baud 9600

DC (display coefficients) _____ *check to make sure they are in there and correct*

DS (display status) _____ *look at what you want to change*

Set Date/Time _____ (Local or UTC)

vMain _____

Sample Interval _____

Data format _____

Output Salinity (is it enabled?) _____ Mooring Depth Entered _____

Transmit realtime _____

Minimum Conductivity Frequency _____



Preparing for Deployment

- SBE 16*plus* series:
 - Check that you are getting outputs from all enabled sensors
- SBE 37 series:
 - Check that you are getting outputs from all sensors
- ALWAYS keep an archive copy of RAW, non-corrected data before initializing logging
 - This allows a return to original data for correction or reprocessing later on

Verify Functionality



- Log data on instrument, then upload and review
- or
- View data real-time using SeatermV2
 - Establish communications with instrument
- Verify you have most recent calibration coefficients
 - Check for both electronic and hard copies



Pre-Deployment Sensor Check

- Use the **TS** command to check nominal functionality of all sensors
- Also use to check conductivity **zero frequency** against calibration sheet
 - Should be within a few Hz of the Zero Conductivity value
 - Be sure to do this on a dry conductivity cell (no water or droplets)

Record Some Data

Log and check some data

A clean tub full of water is a good way to do this, but it can also be done in air

Verify recorded values seem reasonable

Compare to another instrument you know is good





Pump Mode Settings on Moored Instruments

- If moored in an area with large thermal gradients, pump for a longer period of time to eliminate cell thermal mass effects on conductivity measurement
- Time required for DO measurement equilibration is dependent on sensor's membrane thickness and on water temperature
 - See User's Manual for your instrument about pump option settings for DO



Example:


SBE 16*plus* and 16*plus* V2

Pump Modes

- No pump
 - No mystery here
- Pump for 0.5 seconds before sample
 - T & C only, ventilates the cell, saves power
- Pump on for entire sample period plus for some period prior to the sample
 - For auxiliary sensors with long time constants
 - Dissolved oxygen
 - Fluorometer




Stabilization of Moored Dissolved Oxygen (DO) Sensors



For a **0.5-mil** Membrane



Stabilization Time Versus Temperature of Moored DO Sensors



For a **1.0-mil** Membrane



Pump Functionality and Problems

- Could be pump itself
 - Hook pump up directly to a 12 VDC power supply, and verify pump impeller is spinning
 - Swap pump out if a spare is available
 - Inspect pump
- Could be cable
 - Install a spare cable if possible
 - Wiggle cable to check for intermittent connection




Pump Testing

- Test pump (standard pump circuitry)
 - With instrument connect to your compute, run Seaterm V2, use the PUMP ON command to see if the pump turns on
 - Verify pump impeller is spinning
 - Listen for pump to turn on
 - Look for disturbance at exhaust of pump if in the water
 - Put your finger at the intake or exhaust to feel if there is water movement


What if Pump Is Not Running?

- If pump is not running, remove pump head and inspect impeller and thrust washers to determine if a clogged impeller is problem
- Pump impeller can become stopped by sand, sediment, and salt crystals



Pump Impeller

- Periodically inspect impeller thrust washers and pump impeller housing
- Replace thrust washers and impeller retaining O-ring annually or as required
 - Kits available from SBE






Configure Sensors and CTD Hardware for Clean Data Collection

- Ensure that sensors sample same water
 - Plumbing
 - Place T, C sensors together and duct
- CTD deployment orientations
 - (vertical vs. horizontal)
- Ensure that sensors sample undisturbed water
 - No flow blockage/distortion on frame
 - No foreign thermal mass or wakes




Plumbing for Vertical Deployment



SBE 37



**Y-Fitting with bleed hole
Detail for SBE 16*plus***




**Hole allows
air out of plumbing at
Highest point in
plumbing.
Keep tube above
full of water!!!**



Horizontal Deployment Applications

vertical



**Pump
(vertically
above DO)**

DO sensor

**Vinyl
tubing**

**Conductivity
sensor**

**Temperature
sensor**

Make a Neat Underwater Package

- Tie or tape all loose cabling to frame of package
 - Loose cables can move as package rises or drops
 - Results in wire fatigue
- Make sure no cables are in path of inlet to temperature sensors
- Instrument with aluminum housing: check zinc anodes occasionally
 - Grounding problems can cause zinc anodes to disappear





Removing Air from Plumbing

- On deployment or in test bath, try to expel air from plumbing
 - Moorings deeper than 10 m will expel air
 - For shallow moorings < 10 m, fill plumbing with DI water prior to deployment
- Observe bubbles coming out of bleed-hole or pump exhaust
 - Move instrument under water to “shake” air out
 - Pre-fill with water at deployment if no chance of freezing




Deploying in Very Cold Places

- Glass conductivity cell is subject to breakage due to water freezing in cell
- Remove all water from conductivity cell
 - Repeated ice formation (film or droplets) on electrodes can degrade calibration at 0.001 - 0.020 PSU level
- Make a solution of 1% triton in sterile seawater
 - Use 0.5 micron filtered seawater or boiled seawater
- **Never use anti-freezes like glycol or alcohol**
- SBE 43 Oxygen Sensor – prevent freezing by keeping indoors or in area above freezing




Frozen SBE 43 Oxygen Sensor

Electrolyte will freeze ~ -4 deg C



**Split Open Membrane
Caused by Freezing**



Bloated membrane – Impact, freezing



Log Data Now or Later?

- Use the **StartNow** command to begin logging data immediately
- To begin logging later:
 1. Use the **Startmddy=** command to enter a date to start logging, and then use the **Starthhmmss=** command to enter a start time on that date
 - Or -
 - Use the **StartDateTime=** command to enter a date and time to start logging
 2. Use the **StartLater** command to begin logging on the date and time entered above



Inductive Modem IDs

- Valid range for ID numbers is 00 – 99
- There must be only one instrument on the loop when setting IDs
- IM receiver is very sensitive; instruments not on the loop, but near the loop, will receive the ID change



Getting Data to the Surface and the Shore

- You are responsible for the communications link between the surface buoy and the shore
 - Satellite
 - Cell phone
 - Radio modem
- You are responsible for a buoy computer that requests data from the moored instruments



Requesting Data from Moored Instruments

- **PwrOn** causes the buoy modem to send a wake-up tone down the inductive link
- **GData** tells the moored instruments to prepare a data scan for transmission
- **Dataii** requests the instrument with the ID **ii** to transmit the scan
- **PwrOff** causes all instruments on the mooring to go to sleep



Inductive Telemetry Troubleshooting

- Inductive communication is one way at a time (half duplex)
- Instruments with the same ID will compete for the link
- If request for data occurs during data acquisition, the request will be ignored