User's Manual



Heavy Duty Dissolved Oxygen Meter Model 407510



Introduction

Congratulations on your purchase of Extech's Heavy Duty Dissolved Oxygen / Temperature Meter which simultaneously displays Dissolved Oxygen, Oxygen in air, and Temperature. Units of measure are mg/l for Dissolved Oxygen, % for Oxygen in air, and °C°F for temperature. Oxygen is measured with a remote sensor that also contains a thermistor for measuring temperature. Advanced features include RS 232 PC serial interface, data hold, auto shut off, and Min/Max/Avg recording.

Specifications

General Specifications

eneral Specifications	,		
Circuit	Custom one-chip LSI microprocessor circuit		
Display	Dual function 0.5" (13 mm) 1999 count LCD w/ contrast adjust		
Measurements	Dissolved O ₂ : mg/l (milligrams per liter); Oxygen in air: %;		
	Temperature: °C/°F		
Data hold	Data hold key freezes displayed reading		
Sensor Structure	Remote Polarographic Dissolved Oxygen Sensor		
	Temperature sensor: Precision thermistor		
Data recording	Min/Max/Avg readings stored for later recall		
Auto power off	Meter turns off after 10 minutes		
Sample rate	0.4 Sec (approx.)		
Data Output	RS 232 PC serial interface		
Operating conditions	Temperature: 32 to 122 °F (0 to 50 °C); Humidity: < 80% RH		
Battery power	9V alkaline battery		
Power Consumption	Approx. 6.6 mA DC		
Weight	0.74 lbs. / 335 g (including batteries & probe)		
Dimensions	Main instrument: 7.1 x 2.8 x1.3" (180 x 72 x 32mm)		
	Probe: 4.9" x 0.8" length/diameter (125 x 20mm)		
Accessories	Carrying case, 9V battery, and 5 membranes		
Optional access.	Membranes, data acquisition software & RS232 interface cable		

Electrical Specifications

Measurement	Range	Resolution	Accuracy
Dissolved Oxygen	0.0 - 19.9 mg/L	0.1mg/L	<u>+</u> 0.4 mg/L
Oxygen in air	0 - 100% O ₂	0.1 % O ₂	<u>+</u> 0.7% O ₂
Temperature	32 to 122 °F	0.1°F/C	±1.5 °F
(probe only)	0 to 50 °C		<u>+</u> 0.8 °C
Compensation	Temperature (automatic)	32 to 12	2 °F (0 to 50°C)
adjustments	Salt	0 to 39%	
	Altitude	0 to 3	3900 meters



Meter Description

1	LCD Display	0.0
2	POWER ON/OFF key	13
3	Data HOLD key	12
4	°C/°F selection key	
5	LCD Contrast Adjust	
6	RECORD key	2 2000-
7	RECALL key	3 TUUU 4
8	Factor adjust key	2
9	Probe top	The set of the set
10	Sensor body	8
11	Sensor plug	16
12	Sensor jack	19
13	RS-232 output jack	17 Diversed Depper
14	Battery cover	18
15	Altitude compensation key	
16	DO/O ₂ key	167 10
17	Zero key	
18	O ₂ calibration key	14 -9
19	% Salt key	- Q

Calibration

For first time use or after long periods (several days) of non-use, calibrate the instrument using the following steps. The procedure should be performed in an open, well-ventilated area.

- 1. Ensure that the sensor is DISCONNECTED from the meter.
- 2. Turn ON the meter.
- 3. Slide the O_2/DO selector to the O_2 position.
- 4. Press the zero key to null the meter (the display should indicate "OO").
- 5. Connect the DO sensor to the top of the meter.
- 6. Allow the meter to stand for at least five minutes until the display stabilizes.
- 7. Press the O₂ Cal key and the display will indicate approx. 20.9 (typical O₂ in air).

Measurement Preparation

Before taking measurements, perform the calibration described above if necessary. In addition, perform the % SALT and ALTITUDE compensation adjustments as described below:

% SALT Compensation

Slide the O_2/DO switch to the DO position. If the measured liquid is pure water or is known **not** to have a salt content, set the % Salt factor to 0%.

- 1. Press the % Salt key. The display will indicate **0%** on the middle portion of the LCD display and **S** on the bottom portion of the LCD.
- 2. Pressing the Factor Adj. key once will add 1% to the salt factor.
- 3. Press the Factor Adj. key until the correct factor is displayed.
- 4. Press the % Salt key to store the factor.

ALTITUDE Compensation

The meter has a default calibration for sea level operation (0 meters). Any significant deviation from sea level requires a compensation adjustment. Perform the following steps to do so:

- 1. Press the ALTITUDE key and the display will indicate a "0" in the middle of the LCD and an "H" on the lower portion of the LCD.
- 2. Press the Factor Adj. key once to add 100 meters, twice to add 200 meters, and so on. Maximum compensation is 3900 meters.
- 3. Once the desired compensation is displayed, press the ALTITUDE key again to store the value.

Taking Measurements

- 1. Immerse the probe in the solution under test. For best automatic temperature compensation, immerse the probe to a depth of at least 4" (10 cm).
- 2. Wait until the display stabilizes.
- The velocity of the liquid coming into contact with the probe must be at least 0.6 to 1 ft/min (0.2 to 0.3 m/s). If the solution is standing, stir the solution with the probe or use an agitator.
- 4. Rinse the probe with clean water after each use.

Oxygen in Air (O2) Measurements

Follow the same steps above for DO measurements except for the variations described below:

- 1. Slide the O_2/DO switch to the O_2 position.
- 2. The display will indicate the oxygen air value in %.

Temperature Measurements

The lower display will indicate the temperature of the measured solution. Press the $^{\circ}C'^{\circ}F$ key to change the temperature units.

Advanced Features

Data Hold

Press the Data Hold key to freeze the displayed value. The LCD will display **DH** for Data Hold mode along with the held reading. Press the Hold key again to release the data hold function.

MIN/MAX/AVG Data Recording

When selected, the Data Recording function records the Min, Max, and Average readings. To start a data recording session:

- Press the RECORD key once. The REC indicator will appear on the display and the meter will begin to record the lowest (min), highest (max), and average (avg) readings.
- 2. To recall the data, press the RECALL key once. The MAX indicator will appear along with the highest reading recorded since the RECORD key was pressed.
- 3. Press the RECALL key again to view the MIN value.
- 4. Press the RECALL key again to view the AVG reading.
- 5. To exit the Record mode, press the RECORD key again. The display indicators REC, MIN, MAX, and AVG will disappear.

Auto Power OFF

The meter includes an Auto shut off feature that preserves battery life. The meter will automatically turn off if no function button is pressed in any 10 minute period. To disable this feature press the RECORD key to engage the record function.


LCD Contrast Adjust

It may be necessary to adjust the display contrast due to a change in viewing angle or voltage drift. Use the LCD Contrast adjustment located on the right side of the meter to set the preferred contrast.

Membrane & Electrolyte Replacement

The tip of the probe holds a thin Teflon® membrane and an electrolyte container. If the meter becomes difficult to calibrate or if the readings become erratic, check the probe for loss of electrolyte or a dirty/damaged membrane. The membrane is very delicate and can easily be damaged if it comes in contact with a solid object. Replace the electrolyte and/or the membrane as follows:

- 1. Unscrew the probe top.
- 2. Remove the O-ring and the old membrane. Refer to the diagram below.
- 3. Pour out the old electrolyte from the container.
- 4. Fill the container with new electrolyte.
- 5. Install the new membrane and the O-ring.
- 6. Reassemble the probe.
- 7. Lightly tap the probe to ensure that any air bubbles are forced out.



CPU Reset

Certain improper keystroke sequences can cause the meter to "hang" and become inoperable. The following procedure will reset the meter.

- 1. Slide the O_2/DO switch to the O_2 position.
- 2. Turn the meter OFF and disconnect the DO probe.
- 3. Press and HOLD the O₂ key and then press the POWER key.
- 4. Release the O_2 key and then press the ZERO key.
- 5. Connect the DO probe.
- 6. Wait several minutes for the reading to stabilize and then press the O2 CAL key.

RS-232 PC Interface

The meter includes a RS-232 serial data port. This interface was designed to operate with the Extech Data Acquisition Software/Hardware kit Part No. 407000. This kit enables the user to capture, store and display readings using a PC. For more information contact Extech or refer to the 407000 User Manual for details.

Battery Replacement

The low battery indication LBT appears on the LCD when the battery runs low. To replace the battery:

- Remove the meter's rubber protective cover to access the rear battery compartment.
- 2. Remove the battery compartment cover using a small coin or screwdriver and remove the 9V battery.
- 3. Replace the 9V battery and reinstall the cover and holster.

Calibration and Repair Services

Extech offers complete repair and calibration services for all of the products we sell. For periodic calibration, NIST certification or repair of any Extech product, call customer service for details on services available. Extech recommends that calibration be performed on an annual basis to insure calibration integrity.

Warranty

EXTECH INSTRUMENTS CORPORATION warrants this instrument to be free of defects in parts and workmanship for 3 years from date of shipment (a six month limited warranty applies on sensors and cables). If it should become necessary to return the instrument for service during or beyond the warranty period, contact the Customer Service Department at (781) 890-7440 for authorization. A Return Authorization (RA) number must be issued before any product is returned to Extech. The sender is responsible for shipping charges, freight, insurance and proper packaging to prevent damage in transit. This warranty does not apply to defects resulting from action of the user such as misuse, improper wiring, operation outside of specification, improper maintenance or repair, or unauthorized modification. Extech specific purpose and will not be liable for any direct, indirect, incidental or consequential damages. Extech's total liability is limited to repair or replacement of the product.

is expressed or implied.

Copyright © 2000 Extech Instruments Corporation. All rights reserved including the right of reproduction in whole or in part in any form.

6