


■ MULTIMETER

# Digital Multimeter Model C.A 5230



ENGLISH

User manual



**Warning !** Please refer to the User's Manual before using the instrument.

In this User's Manual, the instructions preceded by the above symbol, should they not be carried out as shown, can result in a physical accident or damage the instrument and the installations.



This device is protected by a double insulation or by a reinforced insulation. No linking is required from the protection earth terminal to ensure the electrical security.

Thank you for purchasing a **C.A 5230 RMS Multimeter**. To get the best service from this instrument :

- **read** this user manual carefully,
- **respect** the safety precautions detailed.



## **SAFETY PRECAUTIONS**




- Respect the value and the type of fuses or there is risk of deterioration of the instrument and invalidation of the warranty.
  - Fuse 0.5A HBC (500V min - 10kA - 6.3 x 32mm)
  - Fuse 12A HBC (600V min - 300kA - 10.3 x 38mm)
- Never use on voltage to earth circuits above 600V, with a voltage surge category of over III, that is to say, fixed industrial and domestic installations (ref. IEC 664-1).
- To be used indoors in environments with a maximum pollution degree of 2 (ref. IEC 664-1), a temperature between 0 and 50°C and relative humidity below 70%.
- Use accessories which conform to safety standards (IEC 1010-2-031), with a minimum voltage of 600V and a voltage surge of category III.
- Never open the multimeter case before disconnecting from any electrical source.
- Never connect up to a circuit to be measured if the multimeter case is not closed correctly.
- Before any measurements are taken, ensure the leads and switch are in the correct positions.
- Never measure resistances on a circuit with the power switched on.




## 2 - DESCRIPTION

### ① LIQUID CRYSTAL DISPLAY

- 4000 measurement counts - height of digits 0.5" (12mm)  
Rate: 2 measurements / second
- Bargraph with 42 segments / Rate: 20 measurements / second  
**Note:** *the bargraph is not operational on frequency and capacitance measurements*
- Automatic display of all the symbols for commands, ranges and functions
- Use battery indication : 
- Low battery indication :
  - the 4 on the left flashes
  - bargraph totally lit plus arrow

### ② CONTROL BUTTONS

  $\dots / \sim$  and  $\Omega / \bullet$

To change from AC ( $\sim$ ) to DC ( $\dots$ ) and reverse, on ammeter function.  
To change from continuity test ( $\bullet$ ) to resistance measurement  $\Omega$  and inverse, on ohmmeter function.

**Note:** *Automatic selection of AC and  $\bullet$  when switched on.*

#### HOLD and ZERO

To freeze the display on the last measurement (HOLD).  
On capacitancemeter function  $\text{H}$ , zero reset by press without releasing.  
Permanent operation: possibility of suppressing auto off, by pressing this button without releasing before operating the switch from the OFF position. The return to the OFF position cancels permanent operation.

#### MIN - MAX

To successively display the min or max values. The instrument then changes to manual range selection. HOLD is also displayed. Min acquisition time 500 ms.

**Note:** *The user can keep the min/max values in memory if you press the HOLD button, PRIOR to disconnecting the test leads.*

#### RANGE

Range selection: to change from automatic mode to manual mode, by prolonged press on this button.

**Note:**

- *automatic mode is selected when the instrument is switched on.*
- *this button also selects the sensitivity for the Hz frequency meter function*



To switch on and off the display backlighting.

**Note:** *Auto off after 1 minute.*

### ③ FUNCTION SELECTOR SWITCH

- OFF** Off position
- V~** AC voltages up to 600V in rms value
- V---** DC voltages up to 600V
- Hz** Frequencies of voltages up to 400kHz
- ))) Ω** Continuity sound test for a resistance  $R \leq 40\Omega$ , and measurements of resistances up to  $40M\Omega$   
**Note:** *The continuity test ●))) is selected automatically when the instrument is switched on.*
- |** Diode test. Measurement of the voltage of the junction in forward direction
- ⊖|** Capacitances up to  $40\mu F$
- mA** Current ranges up to  $400mA_{AC/DC}$  (via the + terminal)
- A**  $10A_{AC/DC}$  current ranges (via the 10A terminal)

### ④ TERMINALS

∅ 4mm safety terminals

- **COM:** common, black
- **+:** red
- **10A:** red lead for the  $10A_{AC/DC}$  ranges

## 3 - DC AND AC VOLTAGE


- Connect the leads to the multimeter and connect it in parallel to the circuit to be tested.
- Place the selector switch on the voltmeter function  $V_{AC/DC}$
- Automatic selection of the range: read the value measured.
- Freeze the value by pressing the HOLD button.  
If necessary, press the following buttons:
- RANGE to select the ranges manually
- MIN-MAX to read the min or max values
- ☀ to light the display

$V_{AC/DC}$	400mV <sup>(1)</sup>	4V	40V	400V	600V <sup>(2)</sup>
Digital resolution	0.1mV	1mV	10mV	100mV	1V
Bargraph resolution	10mV	100mV	1V	10V	100V
Impedance	100MΩ	10MΩ	9.1MΩ		
Accuracy on DC	$\pm 0.25\%$ of Reading $\pm 1ct$				
Accuracy on AC	$\pm 1.5\% R$ $\pm 5cts$	$\pm 1\%$ of Reading $\pm 3cts$			
Permitted overload	600Vrms and 1000V peak				

(1) Accessible by the RANGE button. Min measurement : 20mV

(2) Crest factor  $FC \leq 3$

## 4 - FREQUENCY

- Connect the leads to the multimeter and connect in parallel to the circuit to be tested.
- Place the selector switch on the Hz voltage frequency function.
- Automatic range selection: read the measured value  
**Note:** *The bargraph is inactive on frequency measurement*
- If necessary, press the following buttons:
  - MIN/MAX to read the min or max values
  -  to light the display

Hz	100Hz	1kHz	10kHz	100kHz (2)	400kHz
Resolution	0.01Hz	0.1Hz	1Hz	10Hz	100Hz
Accuracy	± 0.1% of Reading				
	± 10cts	± 4cts		± 8cts	± 20cts
Permitted overload	500V rms and 900V peak				
Operating range (1)	4V to 600V				

(1) The RANGE button for this function selects the triggering threshold :



- 10mV for 100Hz, 1kHz and 10kHz ranges
- 400mV for 100kHz and 400kHz ranges

(2) **Note:** If the frequency applied is 99.99kHz, the decimal point oscillates between 9.999kHz and 99.99kHz.


## 5 - CONTINUITY AND RESISTANCE



### Never test a resistance on a live circuit

- Connect the leads to the multimeter and to the terminals of the circuit or the component to be tested.
- Place the selector switch on the ohmmeter function  Press the  button to change from the continuity sound test to the measurement of resistances and reverse.
- Automatic range selection: read the measured value
- Freeze the value, by pressing the HOLD button.

If necessary, press the following buttons:

- RANGE to select the range manually
- MIN/MAX to read the min or max values
-  to light the display

## 5-1 Resistances

$\Omega$	400 $\Omega$	4k $\Omega$	40k $\Omega$	400k $\Omega$	4M $\Omega$	40M $\Omega$
Digital resolution	0.1 $\Omega$	1 $\Omega$	10 $\Omega$	100 $\Omega$	1k $\Omega$	10k $\Omega$
Bargraph resolution	10 $\Omega$	100 $\Omega$	1k $\Omega$	10k $\Omega$	100k $\Omega$	1M $\Omega$
Accuracy	$\pm 1\% R$ $\pm 4$ cts	$\pm 0.5\%$ of Reading $\pm 3$ cts			$\pm 1\% R$ $\pm 4$ cts	$\pm 1.5\% R$ $\pm 4$ cts
Voltage on	$\leq 0.4 V_{DC}$					
Protection	500Vrms and 750V peak					

## 5-2 Continuity sound test (•)))

On the 400 $\Omega$  range, emission of a continuous beep for a resistance  $R \leq 40\Omega$ . Response time: 100ms

## 6 - DIODE TEST



### Never test a diode on a live circuit

- Connect the leads to the multimeter and to the terminals of the component to be tested.
- Place the selector switch on the  $\rightarrow|$  function:
  - in forward direction the display gives the value of the junction in volts (resolution 1mV)
  - accuracy:  $\pm 1\%$  of Reading  $\pm 2$ cts
  - open circuit voltage: 3.2V typical
  - short circuit current: 0.6mA
  - in reverse direction the display indicates the open circuit voltage, around 4V.
- Freeze the value, by pressing the HOLD button.
- With this function, it is possible to test, besides classic diodes, LED's or any other semiconductor in which the junction corresponds to a direct voltage less than 3V.

## 7 - CAPACITANCE



Never make a capacitance test on a live circuit  
Always respect the polarity of electrolytic condensers.  
This type of condenser may be sensitive to temperature, so avoid touching it during measurement.

- ◆ Connect the leads to the multimeter and to the terminals of the condenser.
- ◆ Place the selector switch on the capacitance meter function
- ◆ Automatic range selection: read the measured value  
Note: The bargraph is not operational on capacitance Measurement
- ◆ Freeze the value, if necessary, by pressing the HOLD button

If necessary, press the following buttons:

- ◆ ZERO to set zero on the 4nF and 40nF ranges only
- ◆ RANGE to select the ranges manually
- ◆ MIN/MAX to read the min or max values
- ◆ to light the display

	4nF	40nF	400nF	4μF	40μF <sup>(1)</sup>
Resolution	1pF	10pF	100pF	1nF	10nF
Accuracy	±2% R ±150cts	±2% of reading ± 8cts			
Protection	500V mns 750 peak				

(1) For a capacitance  $C > 20\mu\text{F}$   
the accuracy is ±5% of the reading ± 8cts



Always de-energize the circuit to be tested before connecting the multimeter to the circuit

- ◆ Warning: connect the leads to the multimeter and connect in series to the circuit
  - the red lead to the + terminal up to 400mA
  - the red lead to the 10A terminal, from 400mA to 10A
- ◆ Place the selector on the A or mA ammeter function  
Press the AC/DC button (... / ~) to select AC or DC
- ◆ Energize the circuit
- ◆ Automatic range selection: read the measured value
- ◆ If necessary, press the following buttons
  - RANGE to manually select the ranges
  - MIN/MAX to read the min or max values
  - to light the display



AAC/DC	40mA	400mA	10A (1)
Voltage drop (2)	450mV	650mV	400mV
Digital resolution	10 $\mu$ A	100 $\mu$ A	10mA
Bargraph resolution	1mA	10mA	1A
Accuracy on DC	$\pm 0.8\%$ of Reading $\pm 2$ cts		$\pm 1.2\%$ R $\pm 4$ cts
Accuracy (3) on AC	$\pm 1.2\%$ of Reading $\pm 4$ cts		$\pm 1.5\%$ R $\pm 5$ cts
Protection (4)	Fuse 0.5A HBC		Fuse 12A HBC

(1) Crest factor  $FC \leq 3$

(2) Voltage drop at the terminals for 40mA, 400mA, 10A

(3) Use on frequency: 40Hz to 1000Hz

(4) Permitted overloads: 12A for 30 seconds for the 10A range

## 9 - GENERAL SPECIFICATIONS

### 9-1 Dimensions and Weight

■ 2.5 x 7 x 1.7 " (64 x 177 x 42mm)

■ 12.3 ounces (350g)

### 9-2 Power Supply

■ One battery 9V

■ Battery life: 300h with battery type 6 F 22

500 h with alkaline battery type 6 LF22

■ Low battery indication: 

■ Auto off after 30 minutes

**Note:** Switch on again via the OFF position.

### 9.3 Buzzer

■ Continuous beep for the continuity test

■ Intermittent beep each time the switch or buttons are pressed, and for the overload indication.

### 9-4 Climatic conditions

■ Temperature: use: 0°C to +50°C / storage : -20°C to +60°C

■ Relative humidity: use:  $\leq 70\%$  RH

storage:  $\leq 90\%$  RH (up to 45°C)

■ Altitude: use <2000m

### 9-5 Conformity with International Standards

#### 9-5-1 Electrical Safety (IEC 1010-1)

■ Double insulation:  ■ Installation category: III

■ Degree of pollution: 2 ■ Assigned voltage: 600VRMS

**Note:** This multimeter, of overvoltage category III satisfies the severe requirements of reliability and availability corresponding to industrial and domestic permanent installations (IEC 664-1).

## 9-5-2 Electromagnetic Compatibility: Conforms to CE

- Emission (EN 50081-1)
- Immunity (EN 50082-1)

## 9-5-3 Mechanical protection

- Degree of watertightness (IEC 529): protection index IP 40

# 10 - TO ORDER

---

Use the designations and references below.

**C.A 5230** ..... **Cat. #2116.76**

Sold with shockproof case, a pair of leads with probes attached, a 9V battery and this user's manual

### Accessories

■ AC current probe model MN 251 (200AAC) ..... **Cat. #2115.77**

■ AC current probe model MD 303 (500AAC) ..... **Cat. #1201.21**

■ AC current probe model SR 652 (1000AAC) ..... **Cat. #2113.46**

■ AC/DC MicroProbe model K110

(from 100 $\mu$ AAC/DC to 300mAAC / 450mADC) ..... **Cat. #2111.73**

■ AC/DC current probe model MR410

(400AAC / 600ADC) ..... **Cat. #1200.70**

■ Amp**FLEX** model 1000-24-1-1 (1000AAC) ..... **Cat. #2112.39**

■ Replacement leads ..... **Cat. #2118.66**

■ Soft carrying case ..... **Cat. #2118.65**

■ Replacement shockproof case ..... **Cat. #2980.15**

■ Fuse set of 10, 0.5A ..... **Cat. #2970.28**

■ Fuse set of 10, 12A ..... **Cat. #2970.21**

# 11 - WARRANTY

---

Our guarantee is applicable for **three years** after the date on which the equipment is made available (copy available on request).

# 12 - MAINTENANCE

---



**For maintenance, use only specified spare parts.**

**The manufacturer will not be held responsible for any accident occurring following a repair done other than by its factory or approved repairers.**

## 12-1 Replacing the battery and the fuses



**The multimeter must be disconnected from any electrical source.**

■ Place the selector switch on the "OFF" position.

■ Unscrew the tool release screws and remove the lower half of the case.

- Replace the dead battery by a 9V battery (6F22 or 6LF22)
- Replace the defective fuses respecting their value and their type:
  - Fuse 0.5A HBC (500V - 10kA - min 6.3 x 32mm)
  - Fuse 12A HBC (600V min - 300kA - 10.3 x 38mm)

## 12-2 Storage

If the multimeter is not to be used for a period of 60 days or more, remove the battery and store separately.

## 12-3 Cleaning



**The multimeter must be disconnected from any electrical source.**

To clean the case, use a cloth slightly moistened with soapy water. Rinse with a damp cloth. Then, dry rapidly with a cloth or in a hot air stream.

## 12-4 Repair and calibration

To guarantee that your instrument complies with the factory specifications, we recommend that the Model C.A 5230 be submitted to our factory service center at one-year intervals for recalibration, or as required by other standards.

For instrument repair and/or calibration, please call our factory, toll-free, at **(800) 945-AEMC** (800-945-2362):

CHAUVINARNOUX, Inc.  
d.b.a. AEMC® Instruments  
15 Faraday Drive  
Dover, NH 03820 USA  
Tel : (800) 954-2362  
(603) 749-6434  
Fax : (603) 742-2346

(Or contact your authorized distributor)

Costs for repair, standard calibration, and calibration traceable to N.I.S.T. are available upon request. Overseas customers must receive written authorization before returning any instrument.

## 12-5 Technical and Sales Assistance

If you are experiencing any technical problems, or require any assistance with the proper use or application of this instrument, please call our technical hotline:

CHAUVINARNOUX, Inc.  
d.b.a. AEMC® Instruments  
200 Foxborough Blvd.  
Foxborough, MA 02111 USA  
Tel : (800) 343-1391  
(508) 698-2115  
Fax : (508) 698-2118

[www.aemc.com](http://www.aemc.com)