


# Animal / Shipping Weighing Scale




# USER'S MANUAL

#### **Power supply**

The indicator head contains six metal hydride re-chargeable batteries. The low battery indicator is displayed when the battery power is insufficient to power the scale.

### **Recharging the batteries**

Insert the AC re-charger adapter into the socket on the indicator head to recharge the batteries.



During the charging, the LCD will be showed 'RED' color. After the indicator is charged

Ready, the LED will be showed 'GREEN 'color.

#### Caution

Always connect the AC adaptor to the indicator head before connecting to the mains power supply. Disconnect from the mains power supply before supply before disconnecting the adaptor from the indicator head.

### **AC** adaptor

The scale uses rechargeable battery pack or 12V 500mA AC adapter.


# **ON/OFF** switch (the left of the display)

Press the red key to on/off the scale



#### The Automatic Turn-off time can be set or disabled (off)

Seconds delay until turn off



The procedure for calibration


- 1. Press ZERO and UNITS first, then press ON/OFF switch, the display "CALu", then release ZERO key.
- 2. Press Unit key to select weight unit: kg or lb
- 3. Press ZERO key and display shows AD value
- 4. Press ZERO key, waiting for the display "CALIBRATION" WEIGHT"
- 5. Load the calibration weight .(Note: Please see table2—calibration weight)
- 6. Press ZERO key to start calibrating.7. The display shows "SAVE" and then shows AD value.
- 8. The calibration is finished, Press ZERO key, shut off the scale.

120 180 240


#### **Function table**

Press [TARE] and [UNITS] first, then press [ON/OFF] switch, the display will show "SET".

Table 2



# **Key functions**



#### 1. ZERO:

This key is "Zero" feature if load is below 4% of full capacity or a negative value

#### 2. UNITS:

- A. Select weigh units: KG/LB/OZ
- B. The next time of powering-on will be showed the last using weighing units.

#### 3. TARE:

- A. When there's load on the scale, press this key to return to zero.
- B. Put a container on the scale, press this key to tare the Weight, and the tarred value is stored.

#### 4. **HOLD**:

- A. Press this key to store weight value.
- B. To release Hold feature, Press the HOLD key again. To release Hold feature and tare the weight, Press the TARE key.

# The meaning of function setting

1 · AOFF: Time for auto off (120s / 180s / 240s /360s / off)

2 · Unit : Weight units (kg/lb/oz)

3 · CAP : Capacity 4 · OvL : Over load

 $5 \cdot \overline{\text{divS}}$ : Division

6 · CAL: Calibration weight

7 · trAn : RS232 Transfer

8 · t.b.r.: RS232 Transfer band rate

9 · Grav.: Gravity

 $10 \cdot \text{trd}$ . : Transfer mode

STATE	DESCRIPTION	Time for shut off	NOTE
Low	Low battery indication	30 seconds	
ErrE	EEPROM ERROR	30 seconds	
EEEEE	Overload	30 seconds	
ErrH	Zero value higher	30 seconds	
ErrL	Zero value lower	30 seconds	
. 0000	Zero tracking	According as time of shut off	
Minus weight	Display of weighing is	According as	
value	minus value	time of shut off	
Same weight value	Display of weighing is Same weight value	According as time of shut off	Inclusion zero tracking and minus weight

|--|

If an empty container is used the weight can be ignored by zeroing the display. To zero the display, press the **TARE** key. Then when material is placed in container only the weight of the material will be shown.

#### **SPECIFICATION**

Capacity 150 kg x 50 g / 300KG X 100G

Display Easy to read 1.2" LCD display with 5 active digits

Operating temperature  $5c \sim 35c$ Weight 23.5 KG

Display head 950mm x 500mm x 45mm

Power supply: 12V 500mA AC adapter / Rechargeable batteries

SUS 304 stainless steel platform

### **RS232** transmit function

- 1. When the function trAn set ON, The RS232 is actived
- 2. Baud rate is selected 4800 or 9600 when the function t.b.r. set 4800 or 9600  $\circ$
- 3. RS232 Transmission Agreement:

Mode: Simplex Asynchronous Serial

Baud rate: 4800 or 9600

Data Bit: 8

Parity Bit: NONE

Stop Bit: 1

Data Format: ASCII

4. Transmission Information Format: 16 Byte , blank=20H

5. Transmission Information Format show:

STX: Start of Transmission=02H

Status: Status bit

Example: \*=(2AH)=Stable weight,

~=(7EH)=Unstable Weight

+/-: +=(2BH)=Positive Weight, -=(2Dh)=Negat Weight

DDDDDDD: Value of Weight, 7 ASCII Code

UUUUU: 4 ASCII Code Weight Units:KG/LB/OZ

ETX: Stop of Transmission =03H

### Safe description

- The scale uses a liquid crystal display. If the LCD breaks and the liquid leaks from the LCD, don't touch it. The liquid is toxic if ingested.
- The platform is designed for easy clean-up.
- The scale isn't an explosion proof model. Don't use the scale in an atmosphere containing flammable gases or explosive fumes. A fire or an explosion can result.
- Do not operate the scale if there is smoke or a burnt smell coming from the scale. Remove the AC adaptor immediately. After making sure that there is no danger, consult your dealer. Never try to repair the scale by yourself.
- If the scale becomes dirty, wipe it with a soft cloth. For stubborn stains, apply a little neutral detergent and then wipe the scale with a dry cloth. Don't use thinner, benzene, or chemical agents, all of which can cause deformation, discoloration, or deterioration of the scale.
- The scale is a sensitive weighing instrument, avoid physical shocks. If you drop something on the scale, step on the platform, or drop it, the scale may be damaged and lose accuracy.
- Don't push the indicator or keys with sharp objects. They may break or puncture the switch membrane panel.

### To keep the scale working efficiently

- Place the scale on a flat stable surface that will support the scale and the load.
- The operating temperature range is from 5 to 35.
- Don't disassemble or modify the scale, you will void the warranty. Modified scales will not be legal for trade.

# **@WEIGH PTY LTD**

P.O.Box 109

**Elsternwick** 

3185

Melbourne

Victoria

**Australia** 

TEL 1300 SCALES (722537)

www.weigh.com.au