

User Manual



Biomass moisture meter

humimeter BM1

Version 2.2_en © Schaller GmbH 2014

Measuring procedure

- 1. Place the scale on an even and sturdy work surface. Place the humimeter BM1 in the centre of the scale. **Zero the scale to show 0.00kg.**
- 2. Fill the supplied 13 litre bucket with samples taken from varying locations in sample storage.
- 3. Check that the measuring chamber is completely empty. It is important that no material is left in the measuring chamber when you turn on the device.
- 4. Switch on the humimeter BM1 by pressing the power button (⊕) for 3 sec.
- 5. As the next step, please do the self calibration. The word "Reinitialize?" will show up on your display. Accept by pressing the v button.
- 6. The self calibration is finished when the display shows the measuring window.
- 7. Fill the measuring device with the sample evenly distributed to ensure reproducible results.







8. Remove material till the next lower weight range is reached. If only a little missing (e.g. 0,10kg) to the next higher level, it should be filled up to that stage. The actual weight is shown on the scale.



- 9. Smooth the material by hand.
- 10. Select the right calibration curve for your material under test using the buttons ▲ or ▼. The weight of the material in the measuring chamber must be the same as the calibration curve. The display shows the water content.
- 11. If the measure value is blinking, the valid measuring range is exceeded (limits see list on page 5). In this case the accuracy will be decreasing. If you are measuring wood chips, select the next higher weight class and refill wood chips to reach the higher filling weight.
- 12. To save the results in the save menu press the (button). The storage was successful when the number in front of the symbol increased. To reach the store menu please press () until the papears.
- 13. To name the saved results press the *button*.
- 14. Empty the humimeter BM1 and ensure that no material rests are accumulated in the measuring chamber.









Measuring process of wooden pellets:


Measure wooden pellets with the calibration curve "5,00kg pellets". For this measurement the bucket not has to be full of pellets, you must fill in 5,00 kilograms of wooden pellets every time.

Measuring process of dry wood-shavings:


Is the 13 litre bucket not big enough for 1,00 kilogram of shavings, the measuring device has to be filled separately (e.g. $2 \times 0,50$ kg). During the filling process the measuring material has to be slightly and constantly compressed in the measuring chamber in order to provide enough place for 1,00kg of shavings. After finishing the filling process, all of the measuring material has to be 5cm below the back case edge.

List of calibration curves

Pressing the \blacktriangle or \intercal key in the measuring window for at least 3 seconds and a list with all available sorts will appear. Select your sort by pressing \blacktriangle or \intercal and confirm it with the \bigstar key. The measurement will continue automatically.



Design of the device



Calibration curves

Name of calibration curve	Material under test	Filling quantity	Measuring range
2.0k Woodchips	Standard woodchips	2.00 kg	5 - 30 %
2.4k Woodchips	Standard woodchips	2.40 kg	10 - 35 %
2.8k Woodchips	Standard woodchips	2.80 kg	10 - 40 %
3,5k Woodchips	Standard woodchips	3.50 kg	20 - 50 %
4.5k Woodchips	Standard woodchips	4.50 kg	35 - 60 %
2.8k Coarse WC	Coarse woodchips	2.80 kg	10 - 50 %
3.5k Coarse WC	Coarse woodchips	3.50 kg	20 - 50 %
2.8k Industr. WC	Industrial woodchips	2.80 kg	10 - 50 %
3.5k Industr. WC	Industrial woodchips	3.50 kg	20 - 50 %
2.4k P100 chips	Very coarse woodchips	2.40 kg	10 - 30 %
2.8k P100 chips	Very coarse woodchips	2.80 kg	25 - 45 %
3.5k P100 chips	Very coarse woodchips	3.50 kg	35 - 55 %
2.4k Barks	Barks	2.40 kg	10 - 35 %
2.8k Barks	Barks	2.80 kg	25 - 60 %
5.0k Pellets	Pellets made of wood	5.00 kg	5 - 15 %
1.0k Shavings	Shavings	1.00 kg	5 - 20 %
1.3k Sawdust	Sawdust	1.30 kg	10 - 30 %
2.0k Sawdust	Sawdust	2.00 kg	15 - 60 %
1.0k Miscanthus	Miscanthus chopped	1.00 kg	10 - 25 %
1.5k Corn cob	Corn cob (without corn)	1.50 kg	5 - 45 %
reference	To test the humimeter BM1. Not for measuring!		

Selection of the right calibration curve:

Below you can find advices for selecting the right calibration curve. If you are not sure about the right calibration curve, we recommend to carry out a comparison measurement by kiln drying (EN 14774) once.

- Woodchips: standard chips of wood (forest wood chips) according to EU-norm EN 14961 class P16, P31,5 and P45.
- Coarse WC: for coarse chips of wood P31,5 & P45 but with fewer fines. If the weight of the filled 13 litre bucket is under 2,6 kg, the standard wood chips calibration curves (2,4k resp. 2,0k) have to be used!
- Industr. WC: for industrial chips of wood without barks and fines (similar P63) and fresh wood chips (which are not older than two weeks after cutting down the tree). If the weight of the filled 13 litre bucket is under 2,6 kg, the standard wood chips calibration curves (2,4k resp. 2,0k) have to be used!
- P100 chips: very coarse chips of wood according to class P100. Information: P100 chips are bigger than G100 chips of wood! To avoid filling differences in cause of these coarse chips make more measurements with one sample and note the average!

<u>Information:</u> There is the possibility to add further existing calibration curves (e.g. shredder, logging debris wood chips) to your humimeter by Schaller GmbH.

Definition of wood chips classes

The stated numbers refer to the particle size that goes through round gaps of the corresponding diameters (e.g. P16 - 16 mm).

- **P16** minimum 75% of the bulk is between 3,15 and 16 mm
- **P31,5** minimum 75% of the bulk is between 8 and 31,5 mm
- **P45** minimum 75% of the bulk is between 8 and 45 mm
- **P63** minimum 75% of the bulk is between 8 and 63 mm
- **P100** minimum 75% of the bulk is between 8 and 100 mm

Changing batteries

Your new device is provided with batteries.

Please find enclosed the manual for fitting and changing of batteries:

- 1.) Press with your finger onto the arrow of the battery cap und pull it back.
- 2.) Remove the empty batteries.
- 3.) Put four new batteries in the device. Make sure that the positions of the battery poles are correct.
- 4.) Press down the batteries and close the cap.

If the battery symbol appears in the measuring window resp. if a critical charge of battery is shown in the status, the batteries have to be changed IMMEDIATELY. If you do not use your humimeter device for a longer period, remove the batteries. For eventual resulting damages we cannot provide any warranty.








Determination of the material reference moisture

The principle is a comparison measurement with the dehydration method according to EN 14774. Take the measured sample and weigh it. Dry it out in an oven and weigh it again.

$$\%F = \frac{Mn - Mt}{Mn} \times 100$$

 M_n : Mass with average moisture content M_t : Mass of the dried sample

%F: Calculated moisture content



Overview main menu

Edit Logs	Options
Manual Logs Clear Logs	Date / Time Log Time Language
Options	Unlock
Status	℃ / °F Password Reset

Activation of the "super user" function

2 times \circ - Options - Unlock

Enter the 4-digit password by using the **L** button (standard is the 4-digit serial number) and confirm by pressing the **H** button.

Changing the Userlevel

Changing from advanced user to single user:

Make sure that you have activated the "super user" functions according to the instructions above. Afterwards change to the menu and choose "Options".

In the submenu please select "o Userlevel" (2 times + - Options – o Userlevel)

Confirm by pressing the **H** button. Now the single user is activated.

Changing from single user to advanced user:

Keep both the buttons \blacktriangle and \blacksquare pressed directly after switching on the device. Your humimeter automatically starts the main menu. Activate the the "super user" functions according to the instructions above.

Navigate to "*Options* – o *Userlevel*" and confirm by pressing the **↓** button.

Notes

Exemption from liability

For miss-readings and wrong measurements and of this resulting damage we refuse any liability. This is a device for quick determination of moisture. The moisture depends on multiple conditions and multiple materials. Therefore we recommend a plausibility check of the measuring results. Each device includes a serial number and the guarantee stamp. If those are broken, no claims for guarantee can be made. In case of a faulty device, please contact Schaller GmbH (<u>www.humimeter.com</u>) or our dealer.

Technical data	
Resolution of the display	0.5% water content 0.5℃ temperature
Measuring range	5 up to 60% depending on the material
Operation temperature	0℃ up to +40℃
Storage temperature	-20 ℃ to +60 ℃
Temperature compensation	Automatically
Power supply	4 pieces 1.5 Volt AA <u>Alkaline</u> batteries (900 measurements)
Auto Switch OFF	After app. 6 minutes
Current consumption	60mA (with light)
Display	128x64 matrix display, lighted
Dimensions	490 x 290 x 300 mm
Weight	App. 5.3 kg (including batteries)
Degree of protection	IP 40
Scope of supply	BM1, Measuring bucket 13 Litre 4 x 1.5Volt AA Alkaline Batteries
	$C_{aa} = 10 km (art ma 110EC)$

Necessary accessory

Scale 10 kg (art. no. 11656)

! IMPORTANT ! please read

Most common reasons for miss readings

• Product temperature out of application range

Material **below 0°C** resp. **above +40°C** (32 to 104 °F) may cause faulty measurements. The storage of cold material in a warm storage area usually creates condensed water which may lead to major measuring errors.

• Not adjusted material under test

Let your humimeter BM1 adjust to the surrounding temperature of the material for approx. half an hour.

A very high temperature difference has a negative effect on the stability of the measurement results.

• Wrong calibration curve

Before you measure your sample, double check the correct selection of the calibration curve.

• Wrong filling quantity

Fill in exactly the right weight $(\pm 0.01 \text{kg})$ of wood chips in the measuring chamber.

- Wet or mouldy material
- Frozen measuring material

Device maintenance instructions

To provide a long life of your device please does not expose it to strong mechanical loads or heat e.g. dropping it or direct sunlight exposure. Clean your device using a dry cloth. The measuring chamber needs to be cleaned with a dry and soft brush.

Any kind of wet cleaning damages the device. The instrument is not rainproof. Keep it in dry areas. When the device is not used for a longer period (6 months) or when the batteries are empty, they should be removed to prevent a leakage of the battery acid.