



BreezeMAX[®]

2.3/2.5/3.3/3.5 GHz TDD 1.7 GA Release Note

March 2011

© Alvarion Ltd. All rights reserved.

The material contained herein is proprietary, privileged, and confidential. No disclosure thereof shall be made to third parties without the express written permission of Alvarion. Alvarion reserves the right to alter the specifications in this publication without prior notice.

General

This document details the main hardware elements and software features of the BreezeMAX 2300 (2.3GHz), BreezeMAX 2500 (2.5GHz), BreezeMAX 3300 (3.3GHz) and the BreezeMAX 3500 (3.5GHz) of release version 1.7.

The Product Released

This release is the GA release for 1.7 releases (software version 4.7).

The product introduced in the 1.7 release is complementary to the 1.5 release with additional features, as described below in this document.

The product released here is based on the BreezeMAX systems of release 1.0, 1.1 and 1.5, working in 2.3GHz, 2.5GHz, and 3.3GHz, 3.4GHz and 3.5GHz bands with TDD duplexing and is intended for worldwide use. The software in release 1.7 (software version 4.7) can be operated on the already released hardware equipment of release 1.5. However, in addition to the existing AU-IDU, this release introduces a new AU-IDU that supports enhanced computational capabilities for future firmware upgrades.

Changes from 4.5 GA Version

The software package for the 4.7 software version consist of NPU/Micro SW Version 4.7.0.151, AU SW version 4.7.0.151 and SU SW version 4.7.0.151; this software package brings the following features:

Hardware

- New ODU working in 2340-2400Mhz
- New all-outdoor GPS product by Alvarion, which can be used with Release 1.7 or higher only.

Software

New functionality:

- QinQ feature. The system supports the 802.1 QinQ standard, which defines the way to have 2 VLAN tags (double-tagged frames).
- Adding 4 new 2.3GHz ODU IDs in the NPU frequency band files as follows:
 - ODU ID 10 2.3WCS
 - ODU ID 11 2.3ROW band A
 - ODU ID 12 2.3WCS
 - ODU ID 40 2.3ROW bandB

These new IDs are replacing the unique ODU ID 12 available for the 2.3GHz frequency range in previous releases.

Note: Prior to performing software upgrade, customers operating in 2.3 GHz frequency band have to disable all ODUs, then, upgrade system software and define the right ODU types before enabling the ODUs. If the software upgrade steps mentioned before are not completed correctly, an ODU mismatch message will be displayed after software upgrade completion, and ODU state will be down.

Removed functionalities:

- Removed Managed VoIP services.

Documentation

There are two major independent manuals, the Base Station System Manual and the CPEs Product Manual. Each manual covers all relevant topics associated with the respective equipment, including:

- Product / system description
- System installation
- Commissioning
- Operation and administration.

The documentation includes the following:

- BreezeMAX Modular Base Station TDD System Manual.
- BreezeMAX CPEs TDD Product Manual.
- BreezeMAX TDD Troubleshooting Guide
- BreezeMAX TDD Traps and Alarms
- BreezeMAX Base Station Installation & Maintenance Manual. This manual contains an appendix for the “H” mounting bracket installation guidelines.
- BreezeMAX PRO CPE Installation Manual
- AlvariCRAFT User Manual
- BreezeMAX Service Manager
- WiMAX Modem Application Operator Manual
- Smart Card Writer/Reader Application User Manual
- Quick Installation Guidelines
 - GPS Quick Installation Guide
 - Preparing the IDU-ODU GPS Cable
 - Si CPE Quick Installation Guide
 - CPE Quick Installation Guide
 - New SAU Quick Installation Guide
 - SAU Extension Cable Quick Installation Guide
 - “H” Mounting Bracket Quick Installation Guide for Monopole
 - “H” Mounting Bracket Quick Installation Guide for Mast
 - “H” Mounting Bracket Quick Installation Guide for Tower

Known Problems and Limitations

1. After a GPS receiver replacement, the NPU must be reset.
2. RF and IF cables must not be disconnected or connected during ODU operation (when power to the ODU is enabled).

3. The management port is for local management only. The management port may only be used when the network is different from the data port (i.e. another router interface). This is to prevent using the same physical router MAC address for both data and management ports.
4. In a system with a great number of connections, in case of heavy traffic, real-time QoS malfunctions while service type is being changed.
5. In scenarios of very heavy traffic and large point-to-multipoint configuration AU resets may occur.
6. When changing from diversity mode to no diversity and vice versa, the AU channel must be enabled manually after changing to diversity mode.
7. AU reset when transmitting overload broadcast frames of 64 bytes.
8. Software download to BreezeMAX CPEs may fail when uplink traffic is higher than 2.5Mbps.
9. SNMP IfOutDiscards and ifInDiscards counters present inaccurate information.
10. Alvarion's Voice Gateway requires working in transparent VLAN mode, in order to avoid problems that may arise while working with enabled Hybrid VLAN mode on one of the services passing through the VG.
11. There is a 30-second waiting period before the AU admin status to can be changed from enable to disable.
12. Smart-Card application does not support windows Millennium and 98 operating systems.
13. The Ethernet port configuration is removed from the list of fields that are read from the Smart-Card by the CPE, as of version 4.1. This still appears in Smart Card Application for backward compatibility (version 4.0.2).
14. It is mandatory to reset the CPE after changing the CPE password or username.
15. Low System Utilization in uplink causes increased jitter and latency in the uplink.
16. It is not possible to configure CIR = 0 via SNMP.
17. When WiMAX Modem Application is running on a PC, it is mandatory to stop any TFTP Server application that is running on the same PC.
18. It is not recommended to use the 1Gbps speed on the NPU data port.
19. When the system is overloaded, CPEs may not succeed in joining fragmented packets, causing increased packet loss.
20. In rare cases, in scenarios of very heavy traffic and large point-to-multipoint configuration, it may not be possible to change the classification configuration in the service.
21. When an ODU is connected, the AU accepts configuration of frequency although the actual ODU has a different band.
22. Before deleting a service, the operator should first disable the service in order to update the Multicast connection.
23. Before disconnecting an IF or RF cable from the ODU, the channel should be disabled (stop – 48VDC)
24. When working in bi-directional in point-to-multipoint at heavy traffic of short packet, there might be throughput degradation.
25. SAU LEDs do not work properly in cases of heavy traffic.
26. When an AU is inserted to a pre-configuring slot in the shelf, the AU has to be reset in order to accept the pre-configuring parameters.
27. The new AU-ODU RF heads (2.3/2.5) are ready to operate in 10MHz. These AU-ODUs can be identified via the NPU. The new AU-ODUs HC08 revision is 137 while the previous AU-ODU was

134. When an old AU-ODU (pre-beta release 08/06) is replaced with a new AU-ODU and vice versa, the AU IDU must be reset. The Tx power range of the new AU-ODUs is between 30-36 dBm and not 25-36 as on previous AU-ODU. If the output power of a new AU-ODU is configured to 25-29dBm, it will actually transmit 30dBm.

Note: In cases of 2nd or 4th order diversity configuration, it is prohibited to mix different types of AU-ODUs (HC08 revision 137 & 134) on the same AU. This means that in 2nd or 4th order diversity configuration, all the ODUs connected to the AU should be of the same type.

28. Service Manager: When two CPEs have the same name but differ in lower or upper case, the service manager rejects the second username, due to a duplication problem.
29. When using RADIUS service, while the Voice Service Profile (Voice Gateway) is changed in the RADIUS, the VG can lose registration with the network. This requires an SU reset.
30. Illegal IP will be accepted by NPU for all sub-interfaces.
31. When configuring CPE channel through the NPU configuration menu, it does not block setting BW which are not supported on CPE (1.75Mhz, 7Mhz). A trap is generated to indicate on the configuration mismatch and the CPE will not apply the change.
32. It is prohibited to configure the PF and the radius with the same IP address.
33. In IP-CS mode only, if customer downgrades from 4.5 to 4.1, the service database will be corrupted. Clearing the service database can be carried out by switching to Eth CS and then switching back to IP CS.
34. For multi-product environment consisting of both 4Motion and BreezeMAX TDD products, additional IOT tests are required for the NMS solution provided by Alvarion. Please check the NMS release notes to see what 4Motion and BMAX TDD Software versions are supported.