


User's Manual for Mach 3, Jog Pendant

1. Shape of front



**** Both rapid & shift button can work connecting with each button
It doesn't work alone.****

2. Each button's function

Button	Function	Button	Function
	RESET and Release RESET		A axis Move (Rapid+) A Axis Rapid Move (Shift+) A Axis Zero Set
	Work Start		Y axis Move (Rapid+) Y Axis Rapid Move (Shift+) Y Axis Zero Set
	Rapid Move		Z axis Move (Rapid+) Z Axis Rapid Move (Shift+) Z Axis Zero Set
	Move Machine Origin		X axis Move (Rapid+) X Axis Rapid Move (Shift+) X Axis Zero Set
	Return to Program Start Position		X axis Move (Shift+) Feed Rate 100% Set
	Move Work Origin		Y axis Move (Shift+) Feed Rate Increase
	Select Extra Function		Z axis Move (Shift+) No Function
	Pause / (Shift+) JOG Rate Decrease(1)		A axis Move (Shift+) Feed Rate Decrease
	Stop / (Shift+) JOG Rate Increase(1)		Spindle Start/Stop (Shift+) Spindle RPM Decrease
	Set Tool Zero		Flood On/Off (Shift+) Spindle RPM Increase

(1) It is possible to modify jog speed in each axis.

(2) If you push the feed button in each axis alone, it transfers to set Jog Rate

(3) If you press "Rapid" and press Axis button, it moves to Maximum speed.


3. How to use

If it is connected with USB in computer, it perceives by keyboard and no need to do separate set-up or power supply.


Go into action Mach 3 and save attached mach3_1024_pendant.set in mach3 folder. After that run “load screen” as below.



Set up feed button in A axis as follows.



If you click A/U++ button, it will open window named “ SetHotKey”
 you press A+ button in pendant this time.
 Click A/U button → Press A- in pendant → Push OK
 If so, the set-up will be finished.



4. Modify Jog Rate & How to do Manual Jog in each axis.

You can find “JOG Rate“ next to Rest Button in existing picture as below.
 This newly comes out to be checked out when changing Jog Rate in Pendant.



To modify Jog Rate,

If press “” & push “” and can see to go down above Jog Rate.
 It decreases by 5 unit and decrease by 0.1 unit under 5.
 It is same when increasing.


If you touch the  after reducing adequately,
You can see it moves slowly than rapid transferring speed.

Push  &  at the same time and you can find it goes by rapid traverse rate.
By doing adjusting “JOG Rate” like this, each axis can change transferring speed.
On demanding moving rapidly, can do it if you use “rapid button” together.


If “Jog Rate “ is 100.00 it can do rapid traverse without pressing “”

5. Set Up Tool Zero in Z axis.


I explain it on condition that there is a Tool Zero Sensor and when it is equipped
in No.13 Pin



Set “Probe” to Input Signal in the Config→Port & Pins
If you used different pin, Input the right pin instead of 13
Press “Apply “ → Push “OK”



Move to below the window in mach picture.




If the GND line doesn't contact with sensor, it shows the "Digitize" is turned off.




If the GND line contact with sensor, confirm the "Digitize" turns on. It is normal.




Click "Edit Button Scrip" in main mach picture.



And Auto Tool Zero button below will flicker. Click that.



If a new window shows up, Input the code below.
After measuring your Tool Sensor and if it is different,
Modify " Const PROBE_HEIGHT= 5" adequately.



The screenshot shows a window titled "HiddenScript.m1s - Mach3 VB Script Editor". The window has a menu bar with "File", "Edit", "Run", "Debug", and "BreakPoints". Below the menu bar is a toolbar with icons for file operations (folder, download), execution (play, pause, stop), and a red 'X' icon. The main area contains the following VB script:

```
Option Explicit

Const PROBE_HEIGHT = 5 'Tool Sensor Height

Const H_SPEED = 200 'Rapid Down Speed
Const L_SPEED = 20 'Slow Down Speed

dim stat as boolean
Dim ZProbeData As Long

Code "G31 Z-500, F" & H_SPEED 'Rapid Down

While isMoving()
Wend 'Until it touches

SetVar(2002,0)
Code "G91 Z2,F200" '2mm up
While isMoving()
Wend

Code "G31 Z-50, F" & L_SPEED 'Slow Down

While isMoving()
Wend

SetDro(2,PROBE_HEIGHT)
Code "G91 Z" & 10 - PROBE_HEIGHT & "F100" 'Tool Height 10mm set

While isMoving()
Wend
```

The status bar at the bottom shows "Ready" and "Ln 28, Col 49".

If you want to do “the stop point(place)” differently,
The “10” in Code “G91 Z” & 10-PROBE_HEIGHT & “F100” is the place designates
the height and it stops the point that it is changed if modify.

Set-up will be finished after saving.

7. Operational Test.

You put the sensor under Endmill,

Click “Auto Tool Zero “ Button in main mach3 picture or click “T-Zero” in Pendant.

If so, the Z axis senses by going down.

You can check out that the Endmill stops on 10mm in material after sensing.

