

IMPORTANT PRODUCT INFORMATION

GFK-2817K

April 2014

PACSystems* RXi Controller - ICRXICTL000-BH, version 8.15

Product Documentation

PACSystems RXi ICRXICTL000 Distributed IO Controller Quick Start Guide, GFK-2815C or later

PACSystems RXi Distributed IO Controller User Manual, GFK-2816C or later


PACSystems Controllers: Battery and Energy Pack Manual, GFK-2741A or later

For user manuals, product updates and other information go to the Support website, <http://www.ge-ip.com/support> and refer to *Controllers and IO, RXi Controllers*.

Release Overview

PACSystems RXi ICRXICTL000 Controller Release 8.15 adds enhanced Ethernet diagnostic capabilities as described in ***New Features and Enhancements in This Release***, below. There are no hardware changes to the RXi Controller.

Functional Compatibility

Subject	Minimum Version Required
Programmer version requirements	
Enhanced Security Passwords Support	Proficy* Machine Edition 7.50 SIM 7 or 8.00 SIM 1
RXi Controller	Proficy Machine Edition 7.50
Intelligent Display Module (IDM)	ICRXIACCIDM01A-AA OS: 2012.1026.1432 APP: 2012.1026.1343
VersaMax PROFINET Scanner	IC200PNS001/002, Firmware release 1.00
PACSystems RSTi PROFINET Scanner	STXPNS001, Firmware release 20.0
PACSystems RX3i PROFINET Scanner	IC695PNS001, Firmware release 1.00
Third-party PROFINET IO-Devices	PROFINET Version 2.2 Certified IO-Devices
PACSystems RXi Energy Pack	ICRXIACCEPK01A-AA RXi Energy Pack (Base Firmware Version 1.25) <div style="text-align: center;">Caution  RXi Controller firmware versions earlier than Release 7.75 are incompatible with the RXi Energy Pack. Users <i>must</i> update the RXi Controller firmware to Release 7.75 or later before attaching an Energy Pack to the controller.</div>

* Indicates a trademark of General Electric Company and/or its subsidiaries. All other trademarks are the property of their respective owners.

Release History

Catalog No.	Firmware Version	Date	Comments
ICRXICTL000-BH	8.15	Apr. 2014	Adds enhanced Ethernet diagnostics capabilities.
ICRXICTL000-BG	8.11	Apr. 2014	Corrects the issue of some IDM modules failing during upgrade to revision 8.10.
ICRXICTL000-BG	8.10	Mar. 2014	Provides support for an OPC-UA embedded server. Corrects issues with IDM ring LED operation, TCP connection failures, <i>Unable to deliver configuration to module</i> faults, loss of Ethernet communication using Modbus client, and the PROFINET device configuration limits.
ICRXICTL000-BF	7.82	Oct. 2013	Corrects the issue of loss of PROFINET and SRTIP communications.
ICRXICTL000-BE	7.80	Aug. 2013	Introduces features, including support for <i>Enhanced Security passwords</i> , to augment security in the RXi Controller firmware. For details, GFK-2817F.
ICRXICTL000-BD	7.75	May 2013	Adds support for an Energy Pack.
ICRXICTL000-BA	7.50	Feb. 2013	Hardware update for improved manufacturability. No change to performance, features or compatibility.
ICRXICTL000-AC	7.65	Jan. 2013	Adds support for Modbus TCP Server Protocol. Available from Support website.
ICRXICTL000-AB	7.60	Nov. 2012	Provides enhanced function block performance and corrects the problems listed in GFK-2817A. Available from Support website.
ICRXICTL000-AA	7.50	Nov. 2012	Initial release

Upgrades

All previous versions of the RXi controller firmware can be upgraded in the field using the following upgrade kit, which is available for download from <http://www.ge-ip.com/support>.

Firmware version 8.15: 41G1729-FW01-000-A8

Caution



During the field upgrade process, there is a window of time during which the controller's programmable components are updated. These updates take approximately 1 minute and require two resets.

Do not power cycle the RXi Controller during the updates because this could place the controller in an unrecoverable and unusable state.

Note: When the firmware updates are completed, the RXi Controller will enter its operational state.

New Features and Enhancements in This Release

New Features in This Release

New Feature	Description
Enhanced Ethernet diagnostics capabilities.	<p>The controller firmware will now capture stack traces during page faults and a few other fatal errors to non-volatile memory and provide a mechanism to read them using the Ethernet Station Manager and PacsAnalyzer tools (available at www.ge-ip.support). When PacsAnalyzer is used with the controller's embedded Ethernet IP Address and "ETM Analysis" checked, fatal error information appears in the PacsAnalyzer log.</p> <p>Note: Only the most recent stack trace will be saved. It will persist across power cycles and controller memory and flash clears until a future fatal error occurs. Since the fatal error info is retained across power cycles and is not cleared, check the time and date stamp in the output to see when the stack trace occurred.</p>

Problems Resolved in This Release

Problem Resolved	Description
[No issues are resolved by this release]	

Restrictions and Open Issues


Restriction or Issue	Description
Ethernet disconnect during word-for-word change	<p>If the Ethernet connection is broken during a word-for-word change, the programmer may not allow a subsequent word-for-word change after reconnecting because it thinks another programmer is currently attached.</p> <p>If this occurs, you should go offline and then back online.</p>
Simultaneous clears, loads and stores not supported	<p>PACSystems CPUs do not support multiple programmers changing CPU contents at the same time. The programming software may generate an error during the operation. Simultaneous loads from a single Controller are allowed.</p>
Hardware configuration Not Equal after changing target name	<p>If you store to flash a hardware configuration that sets Logic/Config Power up Source to Always Flash or Conditional Flash and then change the name of the target in the programming software, the hardware configuration will go Not Equal and will not Verify as equal.</p>
Controller and IO fault tables may need to be cleared twice to clear faulted state	<p>Both Controller and IO fault tables may need to be cleared to take the CPU out of Stop/Fault mode. If one of the tables contains a recurring fault, the order in which the tables are cleared may be significant. If the CPU is still in Stop/Fault mode after both tables are cleared, try clearing the fault tables again.</p>
Setting force on/off by storing initial value	<p>Once a force on or force off has been stored to the Controller, you cannot directly switch from force on to force off or vice-versa by downloading initial values.</p> <p>To turn off the force, download your logic, and then change the force on or off by another download.</p>
Second programmer can change logic while in Test and Edit mode	<p>While currently active in a Test and Edit session using Machine Edition on one PC, Machine Edition running on another PC is not prevented from storing new logic to the Controller.</p>
Must have logic if powering-up from flash	<p>If the application will configure the CPU to retrieve the contents of flash memory at power-up, be sure to include logic along with hardware configuration when saving to flash memory.</p>

<i>Restriction or Issue</i>	<i>Description</i>
Possible Machine Edition inability to connect	Infrequently, an attempt to connect a programmer to Controller via Ethernet will be unsuccessful. The normal connection retry dialog will not be displayed. To resolve this behavior, reboot the computer that is running the programmer.
Sequence Store failure	When downloading projects with very large hardware configuration or that use large amounts of user memory, a "PLC Sequence Store Failure" error could occur when writing the project to flash. To work around this error, either or both of the following actions may be helpful: <ul style="list-style-type: none"> ▪ Perform an explicit clear of flash before performing the write. ▪ Increase the operation timeout used by Machine Edition before performing the write. This is done by expanding the Additional Configuration in the Inspector window for the target controller, and adjusting the Request Timeout. The timeout may need to be increased to as much as 60000 mSec, depending on the amount of memory used and the condition of the flash memory.
SRTP connections remain open after IP Address changed	The Ethernet Interface does not terminate all open SRTP connections before changing its IP address. Consequently, once the local IP address has changed, the privileged connection may not be available until the TCP keep-alive timeout has expired.
Multiple log events	The Ethernet Interface sometimes generates multiple exception log events and Controller fault table entries when a single error condition occurs. Under repetitive error conditions, the exception log and/or Controller fault table can be completely filled with repetitive error messages.
Spurious Ethernet fault	In rare instances, after power cycle, the Ethernet Interface may log the following fault, Event = 28H, Entry 2 = 000eH. This fault can be safely ignored.
Clear of large hardware configurations may cause log event 08/20	A log event 08/20 may occur when very large hardware configurations are cleared and transfers are active on other Server connections. This log event can be safely ignored.
Controller Response Timeout errors (8/08) in Ethernet exception log under extremely heavy SRTP traffic	Under extremely heavy SRTP traffic conditions, the Ethernet Interface may log an event in the Ethernet exception log (Event 8, Entry 2 = 08H) indicating an overload condition. This error terminates the SRTP connection. If this event appears, either the traffic load should be reduced, or the application should use an alternate communications method to verify that critical data transfers were not lost due to the overload.
Intermittent Ethernet log event 8H/15H after power cycle	When starting after a power cycle, the Ethernet Interface may intermittently log an exception (entry 8H, Entry 2 = 15H, Entry 3 = 0000H, Entry 4 = 00aaH). This exception can be ignored.
Output point faults can unexpectedly indicate fault on the first CPU sweep after a Stop-to-Run transition	Output point faults are not reliable for determining errors on the first logic scan. This is consistent with the operation of Series 90*-70 and PACSystems RX3i/RX7i CPUs.
Running applications with fatal faults from flash	Storing an application that generates a fatal fault (such as a watchdog timeout) to flash when the controller is configured to power-up from flash and go to RUN, could cause an endless loop situation (power-up from flash, go to RUN, watchdog timeout, repeat). This issue is mitigated in the RX3i and RX7i CPUs because they have a RUN/STOP switch that can be used to force the CPU to STOP mode on power-up. It is recommended that you thoroughly test your application before writing it to flash.
Long PNC name or PROFINET LAN name will prohibit connecting to a PNS	If the embedded PNC is configured with a 240 (or more) character Device Name and a 31 (or more) character LAN Name, it will not connect to a VersaMax PNS.

<i>Restriction or Issue</i>	<i>Description</i>
MRP extra Closed then Open faults appear when the second port is connected	After a Media Redundancy Protocol (MRP) configuration is downloaded with just a PNS connected to the PNC, the normal Open Ring fault will appear. If a switch is connected to the second port, but the ring is not closed, a Closed fault and then an Open fault will appear in the fault table.
Delaying more than two minutes before initiating a firmware download causes web page problems when another login is required.	Delaying more than two minutes from the time the login page appears before pressing the Upload File button on the Firmware Update page presents another Login page. Depending on how quickly the login credentials are submitted, you could see one of the following: <ul style="list-style-type: none"> ▪ The upgrade page will appear and the upgrade status can be seen. ▪ The web browser will lose connection with the RXi because it automatically reset after upgrading firmware
Backplane communications faults	A Backplane communications with Controller fault can appear in the RXi fault table. This type of fault can be caused by a communications error with a LAN interface, for example as when the logic application sends COMM_REQs faster than the interface can process them. Note: Although there is no backplane in the RXi, this terminology is used because the RXi shares code and fault text strings with the RX3i and RX7i controllers, which do have backplanes.
SNMP walk of SNMP object results in SNMP lock-up	Performing an snmpwalk of the SNMP object results in a request timeout. Subsequent SNMP requests will also timeout. The unit must be restarted to recover SNMP operation.
RXi returns same SNMP system Object ID (OID) as RX3i PNC	The RXi's device specific SNMP Object Identifier (OID) currently returns the same value as the RX3i PNC.
Modbus Client Open Channel COMM_REQs do not work if triggered on the first scan	If a Modbus Client open channel COMM_REQ is sent during the first logic scan, the channel will not be opened. Open channel COMM_REQs sent after the first logic scan function normally.
MRP inconsistent Ring Open/Closed fault logging at power-up	The RXi logs an MRP RING-CLOSED fault at power-up when MRP is enabled (configured as an MRM) and the ring is closed, but does not log a RING-OPEN fault at power-up when the ring is open.
Memory access failures for IDM when Access Control enabled	With Enhanced Security / Access Control enabled, the IDM may be restricted from accessing the state of the Override Present bit (%S11). This issue occurs when the IDM cannot read the I/O Force state. If this occurs, the IDM locally logs "Insufficient privilege level for requested action," and the Controller Fault Table logs "Memory access rejected due to Access Control List violation." To prevent these issues with Access Control enabled, you should configure Access Control with %S System memory area and at least Read-Only access.
Fault tables are not retained during HW watchdog reset	Fault tables are not retained during the hardware watchdog reset.
Clear All clears PLC_BAT and masks Energy Pack failures	A Clear All operation clears the values of all %S bits. After this operation the PLC_BAT bit value might not reflect the actual status of the Energy Pack. For example, an Energy Pack in a failed state before the Clear All operation will remain in the failed state after the Clear All; However, the PLC_BAT bit will indicate a good state.
Using OEM Passwords with Enhanced Security disabled	Single character OEM passwords are not supported when Enhanced Security is disabled.
Proficy Machine Edition cannot display reference tables with Enhanced Security and OEM Lock enabled	When Enhanced Security is enabled and OEM protection is engaged, only reference areas specified within the Access Control List can be viewed by a programmer or HMI, regardless of privilege level.


<i>Restriction or Issue</i>	<i>Description</i>
Controller Communication Window Timer settings below 10 milliseconds are ignored	Normal sweep allows the configuration of the Controller Communications Window Timer for Limited operation and a time range from 0 to 255 milliseconds (default 10 milliseconds). However, the system ignores settings in the 0 to 9 milliseconds range which results in an effective window time of 10 milliseconds for this configuration range. This means a sweep impact of up to 10 milliseconds may occur for some complex Controller Communication Window operations. If this operation is not desired, you should use a different sweep mode such as Constant Sweep or Constant Window.
Selecting <i>Variable Publish State = Internal</i> causes variable to be published to OPC UA address space	Machine Edition allows users to select a <i>Variables Publish State</i> equal to <i>Internal</i> . In some cases, this will cause the variable to be published to the OPC-UA address space. The manual states that users should select <i>External Read/Write</i> or <i>External Read-Only</i> to publish to the address space. This is the recommended approach.
<i>Constant Sweep Time Exceeded</i> Faults	When using the RXi controller with the sweep mode set to constant sweep, the controller will occasionally log <i>Constant Sweep Time Exceeded</i> faults to the controller fault table caused by TCP/IP traffic. The oversweep time for these faults is typically under one millisecond. When this is caused by network traffic, the controller will not have a <i>Window Completion Failure</i> fault in the controller fault table. A <i>Window Completion Failure</i> fault will always be logged in the controller fault table if the fault is caused by user logic running for longer than the configured constant sweep time value.
OPC-UA Server Restart fails to complete	The OPC-UA server may fail to restart after a large number of restart sequences without power cycle. (A restart sequence will occur with the following operations: Run Mode or Stop Mode Store when published variables change and OPC UA server is running.) When this occurs, the server restart bit will stay on indefinitely. The issue is restricted to OPC-UA server operation only. Power cycling the controller corrects the issue.

Operational Notes

<i>Operational Note</i>	<i>Description</i>
Restore an RXi that was updated to firmware revision 8.10 and has become unresponsive	<p>Remove the IDM from the unresponsive RXi module. Power on the module and wait for the controller to be reachable by Ethernet again. Update the RXi firmware from revision 8.10 to 8.11. Power off the controller, reattach the IDM, power the controller back on, and before powering off, wait for the module (including the IDM) to fully power up, as indicated by the IDM showing connectivity to the RXi module.</p> <hr/> <p style="text-align: center;">Caution</p> <p> Do not power off the unit until the power-up process is complete as described above. The IDM could become permanently unrecoverable if its firmware update (from the RXi) is interrupted.</p> <hr/>

Operational Note	Description
Configuration of IP Address is required <i>before</i> using Ethernet communications	<p>The Embedded Ethernet Interface cannot operate on a network until a valid IP address is configured. Configure the necessary Ethernet addressing information prior to actual network operation, or to recover from inadvertent changes to the Ethernet addressing data at the Ethernet Interface. Use one of the following methods to assign an initial IP address:</p> <ul style="list-style-type: none"> ▪ Use the Set Temporary IP functionality provided by the IDM to assign a temporary IP address. ▪ Use the default IP address of the Ethernet Interface, which is 192.168.0.100. <p>Once a temporary IP address is set up, the Embedded Ethernet interface is accessed over the network (such as by the Machine Edition programming software).</p> <p>Notes:</p> <p>1: The controller's Ethernet IP address cannot be changed from the IDM while it has a configuration stored. The IDM can clear the controller's configuration by performing a Clear All.</p> <p>2: BOOTP and the Machine Edition Logic Developer PLC's SetIP tool are not supported.</p>
Ethernet event log not preserved across power cycle	<p>The Ethernet event log on the RXi is not maintained across a power-cycle. However, Ethernet log events are reported in the Controller fault table.</p>
Station Manager commands	<p>The RXi Controller supports a subset of the documented Station Manager commands, consisting of the Monitor commands, which provide information about the Ethernet interface and network. The Login command is not supported, which prevents access to the Modify commands. Refer to <i>TCP/IP Ethernet Communications for PACSystems Station Manager Manual</i>, GFK-2225, for more details.</p>
AUP Parameter restrictions	<p>The RXi Controller does not support Advanced User Parameters...</p>
Serial port operation	<p>The RS232/RS485 port is not operational in this release of the RXi Controller.</p>


Operational Note	Description
<p>Ring network configuration and parameter considerations for bumpless PROFINET IO Device Operation with Media Redundancy Protocol (MRP)</p>	<p>Use of the Media Redundancy Protocol (MRP) allows a ring network to automatically heal itself in the event of a single break of the ring network. If an application requires the PROFINET IO Devices to operate bumplessly through ring network recovery (no observed loss and subsequent addition of PROFINET IO Devices while the ring network recovers), the following network and application design guidelines for minimum IO Update Rates must be observed:</p> <ol style="list-style-type: none"> 1. If only one RXi is in the ring acting as the Media Redundancy Manager (MRM) and all of the Media Redundancy Clients (MRCs) are RX3i PNSs, you can set minimum IO Update Rates as follows and expect PROFINET IO to operate bumplessly through ring network recovery: <ol style="list-style-type: none"> a. A minimum IO Update Rate of 4ms at 100 Mbps, b. A minimum IO Update Rate of 16 ms at 1 Gbps. Set the MRP Test Packet Interval to 10 ms and the MRP Test Packet Count to 2. 2. If multiple RXis are in the ring (one RXi acting as the MRM and other RXi(s) as MRC(s)) where VersaMax PNSs are the only PROFINET IO Devices, you can set minimum IO Update Rates as follows and expect IO to operate bumplessly through ring network recovery: 16 ms IO Update Rate minimum and must set MRP Test Packet Interval to 10 ms and MRP Test Packet Count to 2. 3. If 3rd party MRCs are in use in the ring, you can set a minimum IO update rate to the <i>larger</i> of the options that follow and expect IO to operate bumplessly through ring network recovery: <ol style="list-style-type: none"> a. Minimum IO Update Rate configurable in Machine Edition that is at least 1/3 the time of the worst-case ring recovery stated by 3rd party manufacturer, regardless of ports utilized. (i.e. if a manufacturer states their worst-case ring recovery is 90 ms, the minimum IO update rate allowed would be $90/3 = 30 \text{ ms} - 32\text{ms.}$) <li style="text-align: center;">or b. 16 ms IO Update Rate minimum and must set MRP Test Packet Count to 2.
<p>Storing updated Media Redundancy Protocol (MRP) configurations to large operating MRP ring networks with fast IO update rates configured can result in PROFINET IO device loss/add faults</p>	<p>When storing Media Redundancy Protocol (MRP) configuration updates to an operating MRP ring network, users may infrequently observe one or more pairs of "Loss of Device" and subsequent "Addition of Device" faults regarding PROFINET IO Device faults on the network. This is expected behavior and is more likely to occur on ring networks with a large number of PROFINET IO Devices acting as Media Redundancy Clients (MRC) with very fast IO Update Rates configured.</p> <p>Because changing MRP configuration settings requires each MRC to break and reconnect its own connections to the ring network, IP packets on the network may be lost as this burst of connection breaks and reconnects occurs on the network. If three consecutive IO data packets from a particular PROFINET IO Device are lost due to network reconfiguration, the device will appear to be lost to the RXi and a Loss of IO Device will be logged. When the network stabilizes, the RXi will be able to reestablish connection with the lost IO Device and an Addition of IO Device fault will be logged.</p>

<i>Operational Note</i>	<i>Description</i>
Data Packets arriving on ports blocked by Media Redundancy Protocol (MRP) still forwarded over mirrored ports	When a network is configured for MRP operation, MRMs can put one of their ring ports into a “Blocking” state. MRP uses this blocked port state to break the continuous ring and allow only MRP management traffic to pass through the blocked port. The blocked port does not send or receive any non-MRP management traffic...
PROFINET IO Device Loss/Add faults for 3rd party IO Devices may occur on hardware configuration store in some large network configurations	When storing hardware configurations with more than 64 PROFINET IO Devices that include multiple 3rd Party PROFINET IO Devices, occasional Loss/Addition of IO Device faults may be logged for some 3rd Party PROFINET IO Devices. The devices should operate normally after being reacquired by the RXi Controller and the Loss/Addition faults can be disregarded.
Cannot clear Controller passwords loaded in flash	<hr/> <p style="text-align: center;">Caution</p> <div style="display: flex; align-items: center;">  <p>Passwords loaded to Flash cannot be cleared using Clear Flash or by downloading new firmware. You <i>must</i> document the password because it is not possible for you to restore a unit to the default, no passwords (NULL) condition.</p> </div> <hr/>
Logic driven non-volatile storage not supported in RXi	Logic driven non-volatile storage is not supported on the RXi. This feature is used to support battery backed memory on some RX3i and RX7i CPUs. The Energy Pack makes this feature unnecessary for the RXi.
LD-PLC operations	Machine Edition LD-PLC does not support a single function that connects to the Controller downloads, and then disconnects from the Controller. There are separate connect and download functions. To perform a download to the Controller, you must first connect to the Controller.
Converting Series 90 applications to PACSystems	PACSystems controllers have enhancements and operational differences compared to Series 90 controllers. When converting an application from Series 90 to PACSystems, modifications may be required to accommodate these differences. For a summary, refer to the <i>Series 90 to PACSystems Application Conversion Guide</i> , GFK-2722
Logic executed in row major instead of column major	Logic execution in the PACSystems RXi Controller is performed in row major order (similar to the Series 90-30). This is different from the Series 90-70 that executes in column major order. This means that some complicated rungs may execute slightly differently on a PACSystems RXi and Series 90-70. For specific examples, see the programming software on-line help.
NaN handled differently than in 90-30	The PACSystems RXi CPU may return slightly different values for Not A Number (NaN) as compared to Series 90-30 CPUs. In these exception cases (e.g., 0.0/0.0), power flow out of the function block is identical to Series 90-30 operation and the computed value is still Not A Number.
PID algorithm improved	The PID algorithm used in PACSystems is improved and therefore the PID functions slightly differently on PACSystems RXi than on the Series 90-30. The differences are that the elapsed time is computed in 100µS units instead of 10mS units. This smoothes the output characteristic, eliminating periodic adjustments that occur when the remainder accumulates to 10mS. Also, previous non-linear behavior when the integral gain is changed from some value to 1 repeat/second was eliminated.

<i>Operational Note</i>	<i>Description</i>
Some service requests different from 90-30 or no longer supported	<ul style="list-style-type: none"> ▪ Service Requests 6, 15, and 23 have slightly different parameters. Refer to the programming software online help. ▪ PACSystems RXi does not support Service Request 26/30 functionality via fault locating references. ▪ Service Request 13 requires a valid value in the input parameter block (Refer to the programming software online help for details). On the Series 90-30 and Series 90-70 the parameter block value was ignored. ▪ Service Requests 48 and 49 are no longer supported (there is no auto-restart) because most faults can be configured to be not fatal.
IL and SFC	IL and SFC languages are not available.
DO I/O instruction	The Series 90-30 Enhanced DO I/O instruction is converted to a standard DO I/O instruction (the ALT parameter is discarded and ignored.)
END instruction	The Series 90-30 END instruction is not supported. Alternate programming techniques should be used.
Non-nested JUMP, LABEL, MCR, & ENDMCR instructions	Non-nested JUMPs, LABELs, MCRs, & ENDMCRs are translated to the corresponding nested JUMPs, LABELs, MCRs, & ENDMCRs when converting from Series 90-30 to PACSystems RXi.
OEM Protection not enforced on power-up from User Flash unless engaged before power cycle.	In firmware versions earlier than 7.80, a non-blank OEM key that was loaded from User Flash at power-up using legacy security would result in an automatic OEM lock. In firmware versions 7.80 and later, the OEM Protection Lock must be explicitly set before power down in order to ensure the OEM lock will be set on power-up regardless of the type of security being used.

Operational Note	Description																																
<p>Slot numbering and CPU reference</p>	<p>The RXi Controller does not operate on a slotted backplane. Therefore, the concept of racks and slots does not apply. However, a few areas of functionality require rack and slot information. The following lists the areas that are affected.</p>																																
<table border="1"> <thead> <tr> <th data-bbox="298 407 461 436"><i>User Logic</i></th> <th data-bbox="461 407 769 436">Item Affected</th> <th data-bbox="769 407 1341 436">How Affected</th> </tr> </thead> <tbody> <tr> <td data-bbox="298 436 461 541"></td> <td data-bbox="461 436 769 541"> Service Request #15 (Read Last-Logged Fault Table Entry) </td> <td data-bbox="769 436 1341 541" rowspan="2"> Location of CPU faults will not be the standard 0.1 location, but will reflect that the CPU is in rack slot 0.0. User logic that decodes fault table entries retrieved by these service requests may need updating. </td> </tr> <tr> <td data-bbox="298 541 461 613"></td> <td data-bbox="461 541 769 613"> Service Request #20 (Read Fault Tables) </td> </tr> <tr> <td data-bbox="298 613 461 768"></td> <td data-bbox="461 613 769 768"> Communications Request (Comm_req) </td> <td data-bbox="769 613 1341 768"> Comm_reqs directed to the CPU will need to be updated with the correct CPU slot reference (rack 0, slot 0). Modbus/TCP client channel Comm_reqs should be directed to TASK: 65536 (0x10000). </td> </tr> <tr> <td data-bbox="298 768 461 890"><i>Fault Tables</i></td> <td data-bbox="461 768 769 890"> Faults logged for the CPU </td> <td data-bbox="769 768 1341 890"> The location of faults logged for the CPU in the fault table will not be the standard 0.1 (rack.slot) location. They will reflect that the CPU's actual slot is 0.0. </td> </tr> <tr> <td data-bbox="298 890 461 1432"><i>External Devices</i></td> <td colspan="2" data-bbox="461 890 1341 932" style="text-align: center;"> Series 90 PLCs </td> </tr> <tr> <td data-bbox="298 932 461 1138"></td> <td colspan="2" data-bbox="461 932 1341 1138"> Remote Series 90 PLCs that use SRTP Channels COMM_REQs expect the CPU to be in slot 1. In order to support communications with Series 90 SRTP clients such as Series 90 PLCs using SRTP Channels, the RXi internally redirects incoming SRTP requests destined for rack 0, slot 1 to rack 0, slot 0. This redirection permits Series 90-30 applications that expect the power supply to be located leftmost and the CPU to be located to the right of the power supply to function. </td> </tr> <tr> <td data-bbox="298 1138 461 1180"></td> <td colspan="2" data-bbox="461 1138 1341 1180" style="text-align: center;"> HMI and External Communication Devices </td> </tr> <tr> <td data-bbox="298 1180 461 1327"></td> <td colspan="2" data-bbox="461 1180 1341 1327"> All external communication devices that interact with the CPU should be checked for compatibility with CPU slot locations other than slot 1. Problems may arise with, but are not limited to, initial connection sequences and fault reporting. Machine Edition View users should select "GE SRTP" as their communications driver – it can communicate with a CPU in any slot. </td> </tr> <tr> <td data-bbox="298 1327 461 1369"></td> <td colspan="2" data-bbox="461 1327 1341 1369" style="text-align: center;"> Host Communications Toolkit (HCT) </td> </tr> <tr> <td data-bbox="298 1369 461 1432"></td> <td colspan="2" data-bbox="461 1369 1341 1432"> Applications that use the Host Communications Toolkit may require updated drivers. </td> </tr> </tbody> </table>	<i>User Logic</i>	Item Affected	How Affected		Service Request #15 (Read Last-Logged Fault Table Entry)	Location of CPU faults will not be the standard 0.1 location, but will reflect that the CPU is in rack slot 0.0. User logic that decodes fault table entries retrieved by these service requests may need updating.		Service Request #20 (Read Fault Tables)		Communications Request (Comm_req)	Comm_reqs directed to the CPU will need to be updated with the correct CPU slot reference (rack 0, slot 0). Modbus/TCP client channel Comm_reqs should be directed to TASK: 65536 (0x10000).	<i>Fault Tables</i>	Faults logged for the CPU	The location of faults logged for the CPU in the fault table will not be the standard 0.1 (rack.slot) location. They will reflect that the CPU's actual slot is 0.0.	<i>External Devices</i>	Series 90 PLCs			Remote Series 90 PLCs that use SRTP Channels COMM_REQs expect the CPU to be in slot 1. In order to support communications with Series 90 SRTP clients such as Series 90 PLCs using SRTP Channels, the RXi internally redirects incoming SRTP requests destined for rack 0, slot 1 to rack 0, slot 0. This redirection permits Series 90-30 applications that expect the power supply to be located leftmost and the CPU to be located to the right of the power supply to function.			HMI and External Communication Devices			All external communication devices that interact with the CPU should be checked for compatibility with CPU slot locations other than slot 1. Problems may arise with, but are not limited to, initial connection sequences and fault reporting. Machine Edition View users should select "GE SRTP" as their communications driver – it can communicate with a CPU in any slot.			Host Communications Toolkit (HCT)			Applications that use the Host Communications Toolkit may require updated drivers.		
<i>User Logic</i>	Item Affected	How Affected																															
	Service Request #15 (Read Last-Logged Fault Table Entry)	Location of CPU faults will not be the standard 0.1 location, but will reflect that the CPU is in rack slot 0.0. User logic that decodes fault table entries retrieved by these service requests may need updating.																															
	Service Request #20 (Read Fault Tables)																																
	Communications Request (Comm_req)	Comm_reqs directed to the CPU will need to be updated with the correct CPU slot reference (rack 0, slot 0). Modbus/TCP client channel Comm_reqs should be directed to TASK: 65536 (0x10000).																															
<i>Fault Tables</i>	Faults logged for the CPU	The location of faults logged for the CPU in the fault table will not be the standard 0.1 (rack.slot) location. They will reflect that the CPU's actual slot is 0.0.																															
<i>External Devices</i>	Series 90 PLCs																																
	Remote Series 90 PLCs that use SRTP Channels COMM_REQs expect the CPU to be in slot 1. In order to support communications with Series 90 SRTP clients such as Series 90 PLCs using SRTP Channels, the RXi internally redirects incoming SRTP requests destined for rack 0, slot 1 to rack 0, slot 0. This redirection permits Series 90-30 applications that expect the power supply to be located leftmost and the CPU to be located to the right of the power supply to function.																																
	HMI and External Communication Devices																																
	All external communication devices that interact with the CPU should be checked for compatibility with CPU slot locations other than slot 1. Problems may arise with, but are not limited to, initial connection sequences and fault reporting. Machine Edition View users should select "GE SRTP" as their communications driver – it can communicate with a CPU in any slot.																																
	Host Communications Toolkit (HCT)																																
	Applications that use the Host Communications Toolkit may require updated drivers.																																
<p>Changing IP address of Ethernet interface while connected</p>	<p>Storing a hardware configuration with a new IP address to the RXi while connected via Ethernet will succeed, then immediately disconnect because the RXi is now using a different IP address than the Programmer. You must enter a new IP address in the Target Properties in the Machine Edition Inspector window before reconnecting.</p>																																
<p>Timer operation in Program Blocks</p>	<p>Care should be taken when timers (ONDTR, TMR, and OFDTR) are used in program blocks that are not called every sweep. If a timer is in a block that is not called for a period of time, it still accumulates time. When the timer is reset, it takes a snapshot of the current time as a starting point. Therefore, if a timer is reset, but the block containing it is not called, the timer still accumulates time. When the block is called, if the timer is enabled it will have accumulated time.</p> <p>Example: A block with a timer is reset and the block is not called for 5 minutes. If the timer is enabled when the block is called, the timer will have accumulated 5 minutes. If this is not the desired operation, be sure that timers are reset when resuming execution of a block that is not called for some time.</p>																																

<i>Operational Note</i>	<i>Description</i>
Timer operation with JUMP/JUMPN instructions	ONDTR, TMR, and OFDTR timers that are skipped because of the use of the JUMP instruction will not catch up and will therefore not accumulate time in the same manner as if they were executed every sweep. You should not program a jump around instances of these timers.
Constant sweep	When using Constant Sweep , set the sweep time to a value that is at least 10 milliseconds greater than the normal sweep time to avoid any over-sweep conditions when monitoring or performing on-line changes with the programmer. Window completion faults may occur if the constant sweep setting is too low.
Large number of COMM_REQs sent to module in one sweep causes faults	A large number of COMM_REQs (typically greater than 8) sent to a given board in the same sweep may cause Module Software faults to be logged in the Controller fault table. The fault group is MOD_OTHR_SOFTWR (16t, 10h) and the error code is COMMREQ_MB_FULL_START (2). When this occurs, the "FT" output of the function block will also be set. To prevent this situation, COMM_REQs issued to a given board should be spread across multiple sweeps so that only a limited number (typically 8 or less) of COMM_REQs are sent to a given board in each sweep. In addition, the FT output parameter should be checked for errors. If the FT output is set (meaning an error has been detected), the COMM_REQ could be re-issued by the application logic.
Proper IP addressing is always essential	<p>The PACSystems Ethernet Interface must be configured with the correct IP Address for proper operation in a TCP/IP Ethernet network. Use of incorrect IP addresses can disrupt network operation for the PACSystems and other nodes on the network. Refer to <i>TCP/IP Ethernet Communications for PACSystems</i>, GFK-2224 for important information on IP addressing. When storing a new HW configuration to the RXi, be sure that the HW configuration contains the proper Ethernet addressing data (IP Address, Subnet Mask, and Gateway IP Address) for the RXi.</p> <p>Note: Machine Edition programming software maintains the target IP address (used to connect the programmer to the target) independent of the contents of the HW Configuration for that target). The target IP address is set in the Target Properties in the Machine Edition Inspector window. Storing a HW Configuration whose Ethernet addressing data contains an IP Address that is different from the RXi target IP address will change the IP address used by the target RXi as soon as the Store operation is completed; this will break the Programmer connection. Before attempting to reconnect the Programmer, you must change the target IP address in the Target Properties in the Machine Edition Inspector window to use the new IP address. To regain communication at the former IP address, use the manual corrective action described above.</p> <p>Storing a HW Configuration containing an incorrect Ethernet addressing data to the PACSystems RXi will result in loss of the Programmer connection and will require manual corrective action as described above.</p>
LAN must be tree, not ring	The hub or switch connections in an Ethernet network must form a tree and not a ring; otherwise duplication of packets and network overload may result. In this situation, the RXi Ethernet interface will continually reset.
Reporting of duplicate IP address	The PACSystems RXi does not log an exception or a fault in the Controller fault table when it detects a duplicate IP address on the Ethernet network. However, the controller does log a fault in the I/O Fault Table if it detects a duplicate IP address on the PROFINET network.

<i>Operational Note</i>	<i>Description</i>
<p>Two 10BaseT / 100BaseTX / 1000BaseT auto-negotiating full-duplex Ethernet ports</p>	<p>The PACSystems RXi CPU with embedded Ethernet provides a direct connection to one 10Base-T /100Base-TX / 1000Base-T CAT5 (twisted pair) Ethernet LAN cable from the Ethernet network port. Use a shielded or unshielded cable.</p> <hr/> <p style="text-align: center;">Caution</p> <p> The hub or switch connections in an Ethernet network must form a tree and not a ring; otherwise duplication of packets and network overload may result.</p> <hr/> <p style="text-align: center;">Caution</p> <p>The IEEE 802.3 standard strongly discourages the manual configuration of duplex mode for a port. In the words of the IEEE standard: “Connecting incompatible DTE/MAU combinations such as full duplex mode DTE to a half-duplex mode MAU, or a full-duplex station (DTE or MAU) to a repeater or other half duplex network, can lead to severe network performance degradation, increased collisions, late collisions, CRC errors, and undetected data corruption.”</p> <hr/>
<p>SRTP connections remain open after IP address changed</p>	<p>The Ethernet interface does not terminate all open SRTP connections before changing its IP address. Once the local IP address has changed, any existing open TCP connections are unable to terminate normally. This can leave SRTP connections open until their underlying TCP connections time out. Refer to <i>TCP/IP Ethernet Communications for PACSystems</i>, GFK-2224, for more details.</p>
<p>Incorrect COMM_REQ status for invalid program name</p>	<p>The program name for PACSystems is always "LDPROG1". When another program name is used in a COMM_REQ accessing %L memory, an Invalid Block Name (05D5) error is generated.</p>
<p>COMM_REQ status words declared in bit memory types must be byte-aligned</p>	<p>To ensure that the application operates as expected, the RXi CPU requires byte-aligned COMM_REQ Status Words in bit memory types.</p>

<i>Operational Note</i>	<i>Description</i>
STOP and RUN mode transition priority	<p>The PACSystems CPU receives requests to change between Stop and Run mode from many different sources. These include (but are not limited to) Proficy Machine Edition, HMIs, the user application, and the RXi Intelligent Display Module. Since there are many potential sources for a mode change request, it is possible to receive a new mode change request while another is already in progress.</p> <p>When this occurs, the CPU evaluates the priority of the new mode change request with the mode change that is in progress. If the new mode change request has an equal or higher priority than the one in progress, the CPU transitions to the new mode instead of the one in progress. If, however, the new mode change request has a lower priority than the one in progress, the new mode request is discarded and the CPU completes the mode change that is in progress.</p> <p>The mode priorities are (listed from highest to lowest priority): STOP HALT, STOP FAULT, STOP, and RUN.</p> <p>Note: The IO ENABLED/DISABLED state is not part of the mode priority evaluation. For example, a CPU is in RUN IO ENABLED mode and a Service Request 13 function block is executed to place the CPU into STOP IO DISABLED mode. Before the transition to STOP IO DISABLED is completed, the RUN/STOP switch is changed from RUN IO ENABLED to RUN IO DISABLED. In this case, the CPU ignores the new request from the RUN/STOP switch to go to RUN IO DISABLED mode because it is already processing a request to go to STOP IO DISABLED mode and STOP mode has a higher priority than RUN mode.</p>
Uploaded Controller Supplemental Files lose date and time	Controller Supplemental Files uploaded from the CPU are time stamped as 8/1/1980 12:08AM regardless of PC or Controller time.
Hot swap of CapPack during firmware update results in RXi Controller fatal indication (i.e., blink code)	Insertion or removal of the Energy Pack CapPack during an Energy Pack firmware update will cause the RXi Controller to become non-responsive. To recover from this condition, you must cycle power to the RXi Controller.
Insertion of CapPack during controller power-up could cause failed battery fault	If the Energy Pack is powered on without a CapPack and a CapPack is inserted during the controller's power-up, the Controller could log failed battery fault. The Controller expects the Energy Pack to report fully charged within a certain amount of time. This time limit may not be met if the CapPack is not present at power up.
Using an undersized power-supply can cause unexpected behavior	Unexpected behavior may occur if an undersized power supply is used with the RXi Controller. This unexpected behavior may include LED flickering, audible chatter noise, etc.
When passwords are set with Enhanced Security, connecting with Proficy Machine Edition or establishing SRTP connections can cause a temporary increase in sweep times.	<p>Due to the complex math involved with Enhanced Security authentication, creating SRTP connections and changing privilege levels will take additional sweep time (several milliseconds) that is not required when passwords are set with legacy security.</p> <p>If consistent sweep time is important to the application, it is recommended to configure the sweep mode for Constant Sweep. Alternately, Constant Window or a Normal Sweep with both Limited Backplane Window and Limited Controller Comm Windows can be configured. These sweep modes will limit the sweep impact of Enhanced Security authentication and result in authentication processing across multiple sweeps.</p>