

KERN ALT

Version 1.0 12/2004 Operating Instructions Electronic analytical balance

Table of contents

1	Technical data				
2	2 Declaration of conformity				
3	Fui	ndamental information (general)	74		
	3.1	Designated use	74		
	3.2	Inappropriate use	74		
	3.3	Guarantee	74		
	3.4	Monitoring the test substances	75		
4	Fui	ndamental safety instructions	75		
	4.1	Observe notices in the operating manual	75		
	4.2	Training of personnel	75		
5	Tra	nsport and storage	75		
	5.1	Acceptance check	75		
	5.2	Packing	75		
6	Un	packing, installation and commissioning	76		
	6.1	Installation Site. Location of Use	76		
	6.2	Unpack	76		
	6.2.	Assembly	77		
	0.2.	Maine europhy	// 70		
	0.3	Connection of norinherel equipment	/0		
	6.4 0.5		78		
_	6.5		78		
7	Use	er menu	79		
	7.1	User principle of the menu control	80		
	7.2	Operating the balance with PS/2 keyboard (see chapter 6.3)	81		
	7.3	Menu selection	82		
	7.3.	1 P1 adjustment	82		
	7.3.	2 P2 GLP (G000 laboratory practice)	90 92		
	7.3.	4 P4 Readout	92 94		
	7.3.	5 P5 RS-232	96		
	7.3.	6 P6 Printouts	96		
	7.3.	7 P7 Weighing units	101		
	7.3.	B P8 operating modes	101		
	7.3.	9 P9 General functions	102		

8	8 Operation		
	8.1 C	Dperating modes (P8 modes)	105
	8.1.1	Simple weighing	107
	8.1.2	Parts counting	109
	8.1.3	Weighing with tolerance range	117
	8.1.4	Filling	119
	8.1.5	Percent determination	120
	8.1.6	Animal weighing (Dynamic weighing)	122
	8.1.7		124
	0.1.0	Formulation	I20
	0.1.9	Statistics	128
9	Data	output	131
	9.1 1	Fecnical data	131
	9.2 F	Pin allocation of the balance exit plug (front view)	131
	9.3 F	Remote commands	132
10) Ma	intenance, upkeep, disposal	133
10.1 Cleaning		133	
	10.2 Maintenance, upkeep		133
	10.3 C	Disposal	133
11	134		

1 Technical data

KERN	ALT 100-4M	ALT 160-5D	ALT 220-4M	ALT 310-4	
Readout (d)	0.1 mg	0.1mg/0.01mg	0.1 mg	0.1 mg	
Weighing range (Max)	100 g 160 g/60 g		220 g	310 g	
Taring range (subtractive)	100 g	160 g/60 g	220 g	310 g	
Reproductability	0.2 mg	0.2mg/0.1mg	0.2 mg	0.2 mg	
Linearity	± 0.2 mg	± 0,2mg/0,1mg	± 0.2 mg	± 0.3 mg	
Minimal piece weight for counting function	0,2 mg	0,2 mg	0,2 mg	0,2 mg	
Adjustment weight	internal	internal	internal	internal	
Verifiable	yes	no	yes	no	
Verification value (e)	1 mg	-	1 mg	-	
Accuracy category	Ι	-	Ι	-	
Reference piece numbers for parts counting	10, 20, 50,100, freely selectable				
Weighing Units	mg, g, ct, lb oz, ozt, dwt t {h}, t {S}, mg, g, ct, t {t}, mom, GN, N, t, freely pro- grammable				
Stabilization time (typically)	4 sec.				
Permissible ambient temperature	+ 15° C +30° C				
Humidity of air:	max. 80 % (not condensing)				
Under floor weighing device	On-hook eyelets, serial				
Weighing plate mm	100 80 10			00	
Housing (W x D x H) mm	205 x 500 x 290				
Weight kg (net)	8,9				

2 Declaration of conformity



KERN & Sohn GmbH

D-72322 Balingen-Frommern Postfach 4052 E-Mail: info@kern-sohn.de Tel: 0049-[0]7433- 9933-0 Fax: 0049-[0]7433-9933-149 Internet: www.kern-sohn.de

Konformitätserklärung

Declaration of conformity for apparatus with CE mark Konformitätserklärung für Geräte mit CE-Zeichen Déclaration de conformité pour appareils portant la marque CE Declaración de conformidad para aparatos con marca CE Dichiarazione di conformitá per apparecchi contrassegnati con la marcatura CE

- **English** We hereby declare that the product to which this declaration refers conforms with the following standards.
- **Deutsch** Wir erklären hiermit, dass das Produkt, auf das sich diese Erklärung bezieht, mit den nachstehenden Normen übereinstimmt.
- **Français** Nous déclarons avec cela responsabilité que le produit, auquel se rapporte la présente déclaration, est conforme aux normes citées ci-après.
- **Español** Manifestamos en la presente que el producto al que se refiere esta declaración est´´a de acuerdo con las normas siguientes
- Italiano Dichiariamo con ciò che il prodotto al quale la presente dichiarazione si riferisce è conforme alle norme di seguito citate.

Electronic Balance: KERN ALT

Mark applied	EU Directive	Standards
	89/336EEC EMC	EN 61000-4-2 :1999
		EN 61000-4-3 :1996
		EN 61000-4-4 : 1999
		EN 61000-4-5 : 1998
		EN 61000-4-6 : 1999
		EN 61000-4-11 : 1997
		EN 55022 :2000

Signature:

Gottl. KERN & Sohn GmbH Management

Gottl. KERN & Sohn GmbH, Ziegelei 1, D-72336 Balingen, Tel. +49-[0]7433/9933-0, Fax +49-[0]7433/9933-149

Date: 18.01.2005



KERN & Sohn GmbH

D-72322 Balingen-Frommern Postfach 4052 E-Mail: info@kern-sohn.de Tel: 0049-[0]7433- 9933-0 Fax: 0049-[0]7433-9933-149 Internet: www.kern-sohn.de

Konformitätserklärung

Declaration of conformity for apparatus with CE mark Konformitätserklärung für Geräte mit CE-Zeichen Déclaration de conformité pour appareils portant la marque CE Declaración de conformidad para aparatos con marca CE Dichiarazione di conformitá per apparecchi contrassegnati con la marcatura CE

English We hereby declare that the product to which this declaration refers conforms with the following standards.

This declaration is only valid with the certificate of conformity by a notified body.

Deutsch Wir erklären hiermit, dass das Produkt, auf das sich diese Erklärung bezieht, mit den nachstehenden Normen übereinstimmt.

Diese Erklärung gilt nur in Verbindung mit der Konformitätsbescheinigung einer benannten Stelle.

Français Nous déclarons avec cela responsabilité que le produit, auquel se rapporte la présente déclaration, est conforme aux normes citées ci-après.

Cette déclaration est valide seulement avec un certificat de conformité d'un organisme notifié.

Español Manifestamos en la presente que el producto al que se refiere esta declaración está de acuerdo con las normas siguientes.

Esta declaración solo será válida acompañada del certificado de conformidad de conformidad de la parte nominal.

Italiano Dichiariamo con ciò che il prodotto al quale la presente dichiarazione si riferisce è conforme alle norme di seguito citate. Questa dichiarazione sarà valida solo se accompagnata dal certificato di conformità

Questa dichiarazione sara valida solo se accompagnata dal certificato di conformita della parte nominale.

Model:	KERN ALT 100-4M
	KERN ALT 220-4M

EU Directive	Standards	EC-type-approval certificate no.	Issued by
90/384/EEC	EN 45501	T6655	NMI

Date: 18.01.2005

Signature:

Gottl. KERN & Sohn GmbH Management

Gottl. KERN & Sohn GmbH, Ziegelei 1, D-72336 Balingen, Tel. +49-07433/9933-0, Fax +49-074433/9933-149

3 Fundamental information (general)

3.1 Designated use

The balance you have acquired serves to determine the weighing value of the material to be weighed. It is intended to be used as a "non-automatic" balance, i.e. the material to be weighed is manually and carefully placed in the centre of the weighing plate. The weighing value can be read off after a stable weighing value has been obtained.

3.2 Inappropriate use

Do not use balance for dynamic add-on weighings, if small amounts of goods to be weighed are removed or added. The "stability compensation" installed in the balance may result in displaying an incorrect measuring value! (Example: Slowly draining fluids from a container on the balance.)

Do not leave a permanent load on the weighing plate. This can damage the measuring system.

Be sure to avoid impact shock and overloading the balance in excess of the prescribed maximum load rating (max.), minus any possible tare weight that is already present. This could cause damage to the balance.

Never operate the balance in hazardous locations. The series design is not explosion-proof.

Structural alterations may not be made to the balance. This can lead to incorrect weighing results, faults concerning safety regulations as well as to destruction of the balance.

The balance may only be used in compliance with the described guidelines. Varying areas of application/planned use must be approved by KERN in writing.

3.3 Guarantee

The guarantee is not valid in the following cases:

- non-observation of our guidelines in the operating instructions
- use outside the described applications
- alteration to or opening of the device
- mechanical damage and damage caused by media, liquids, natural wear and tear
- inappropriate erection or electric installation
- overloading of the measuring equipment

3.4 Monitoring the test substances

The metrology features of the balance and any possible available adjusting weight must be checked at regular intervals within the scope of quality assurance. For this purpose, the answerable user must define a suitable interval as well as the nature and scope of this check. Information is available on KERN's home page (www.kern-sohn.com) with regard to the monitoring of balance test substances and the test weights required for this. Test weights and balances can be adjusted quickly and at a reasonable price in KERN's accredited DKD calibration laboratory (return to national normal).

4 Fundamental safety instructions

4.1 Observe notices in the operating manual

Please read the operating instructions carefully before erecting and commissioning, even if you already have experience with KERN balances.

4.2 Training of personnel

The device may only be operated and looked after by trained members of staff.

5 Transport and storage

5.1 Acceptance check

Please check the packaging immediately upon delivery and the device during unpacking for any visible signs of external damage.

5.2 Packing

Please retain all parts of the original packaging in case it should be necessary to return items at any time.

Only the original packaging should be used for return consignments.

Before despatch, disconnect all attached cables and loose/movable parts.

Apply any intended transport security devices. Secure all parts e.g. weighing plate, mains power supply etc. against slipping and damage.

6 Unpacking, installation and commissioning

6.1 Installation Site, Location of Use

The balance is constructed in such a way that reliable weighing results can be achieved under normal application conditions.

By selecting the correct location for your balance, you will be able to work quickly and precisely.

Therefore please observe the following at the place of installation:

- Place the balance on a firm, level surface;
- Avoid extreme heat as well as temperature fluctuation caused by installing next to a radiator or in the direct sunlight;
- Protect the balance against direct draughts due to open windows and doors;
- Avoid jarring during weighing;
- Protect the balance against high humidity, vapours and dust;
- Do not expose the device to extreme dampness for longer periods of time. Inadmissible bedewing (condensation of air moisture on the device) can occur if a cold device is taken into a significantly warmer environment. In this case, please acclimatise the device for approx. 2 hours at room temperature after it has been disconnected from the mains.
- Avoid static charging of items to be weighed, or weighing container.

Major display deviations (incorrect weighing results) are possible if electromagnetic fields occur as well as due to static charging, currents and instable power supply. It is then necessary to change the location.

6.2 Unpack

Carefully remove the balance from its packaging, remove the plastic wrapping and position the balance in its intended working location.

6.2.1 Assembly

Structure of the balance:



- (1) Base plate
- (2) Screen ring
- (3) Weighing plate

Use the foot screws to level the balance until the air bubble in the bubble level is in the prescribed circle.

6.2.2 Scope of delivery Standard accessories:

- Scales
- Weighing plate
- Network appliance
- Instruction manual
- Wind protection

6.3 Mains supply

Electric power supply is by means of the external mains supply circuit. The printed voltage level must comply with the local voltage.

Only use original KERN mains supply circuits. The use of other makes is subject to approval by Kern.



- 1. Mains supply
- 2. PS/2 keyboard
- 3. RS232 interface

6.4 Connection of peripheral equipment

The balance must be disconnected from the mains before connecting or disconnecting additional equipment (printer, PC) to or from the data interface. Only use KERN accessories and peripheral equipment with your balance. These have been ideally coordinated to your balance.

6.5 Initial Commissioning

A warm-up time of 1 hour stabilises the measured values after switching on. The accuracy of the balance depends on the local acceleration of the fall. Instructions in chapter Adjustment must be observed.

7 User menu

The user menu has nine main menus with the following sub-menus:

P1 Calibration	P2 GLP	P3 Date/Time	P4 Readout	P5 RS-232	P6 Printouts	P7 Units	P8 Modes	P9 Globals
							•	
Int. calibr. Ext. calibr User calibr. Calibr. Test: Weight.corr. Aut. calibr. Print report	User No. Prj. No. Time print Date print UserNo. print Prj. No. print Id print Diff. print	Date format Time format Time Date Disp. time Disp. date	Filter Filter range Disp refresh Stable range Stable speed Autozero Last digit	Boud rate Parity Data bits Stop bits Handshake Auto print Interval Print on stab	Printout No. Pr. 1 start Pr. 1 stop Pr. 2 start Pr. 2 stop Pr. 3 start Pr. 3 stop Pr. 4 start Pr. 4 stop String 1 String 2 String 3	Grams Miligrams Kilograms Pounds Ounces, Ounces troy Carats Dwt Taels. Hk Taels. S Taels. T Mommes Granis Newtons Tical Custom Custom Factor	Parts Count Checkweigh ing Filling Percont Animal Formulation Statistics Density	Beep Language Backlight Contrast Screensaver Temperature Balance Id Software rev. Par. Printout Par. Receive. Factory deff.

Main Menu

132 10/11/01 Setup 13:47:56	1. Menu number (P1 – P9)
P1P Calibration P2 GLP P3 Date/Time P4 Readout P5 RS-232 P6 Printouts P7 Units P8 Modes P9 Globals	 Menu designation Cursor (►) indicates the current menu item

Submenu:

(1)(5) (2) (7) (3) (4)	1. Menu number (P1 – P9)
40/44/04 Solum 42:47:56	2. Parameter number and designation
P1 101 Int. calibr.	3. Parameter value or ****** i.e. this
02 Ext. calibr. ******* function	parameter is available as a function
03 Oser calibr. 1******** function 04 Calibr. test 1*******! function	Functional Description
05 Weight. corr. 0.0	5. Cursor (►) indicates the current menu
07 Print report /1 on	item (e.g. P1).
	Cursor (►) indicates the current
	parameter (e.g. 06).
	7. "Setup"i.e. the user is in Setup Mode.
	8. Use the arrow key to modify the
	parameter value, the active parameter
	blinks.

7.1 User principle of the menu control

In the menu the settings of the balance can be modified and functions can be activated.

This way, the balance can be adjusted to individual weighing requirements. To do so proceed as follows:

- \Rightarrow Use the \square -key to turn on the balance.
- \Rightarrow After actuating the \square -key the display shows the main menus that can be set

2.02.05	Setup	13:47:56
P1) Calibration P2 GLP P3 Date/Time P4 Readout P5 RS-232 P6 Printouts P7 Units	Setup	13:47:36
P8 Modes		
P9 Globals		

- Select your setting using the cursor (►).
 Use the + key to move the cursor (►) down, the key to move it up
- ⇒ The → key confirms your selected setting, the display shows the sub-menu or the active menu item blinks:

31.01.05 Setu	p 13:47:56
P1 ▶01 ▶Int. calibr.	******* function
02 Ext. calibr.	******* function
03 User calibr.	******* function
04 Calibr. test	******* function
05 Weight. corr.	0.0
06 Auto calibr.	0 off
07 Auto cal. time	1 1 hour
08 Print report	1 on

 \Rightarrow Use the arrow keys to move within and enter into the menu:



• Decreasing the value for the selected numeral or number

- \Rightarrow Use the 🖾 -key to confirm or the 🖾 -key to cancel
- \Rightarrow Use the 🚟 -key to return to the menu
- Actuate a save the changes you made.



- \Rightarrow Actuating the **Z** -key will save the selected setting.
- \Rightarrow If you do not want to save the selected setting press \square



⇒ The balance will automatically return to weighing mode



7.2 Operating the balance with PS/2 keyboard (see chapter 6.3)

Using a PS/2 keyboard will help you to enter numbers and texts faster and easier. **Key allocation:**



7.3 Menu selection

7.3.1 P1 Calibration (Adjustment)

As the acceleration value due to gravity is not the same at every location on earth, each balance must be coordinated - in compliance with the underlying physical weighing principle - to the existing acceleration due to gravity at its place of location (only if the balance has not already been adjusted to the location in the factory). This adjustment process must be carried out for the first commissioning, after each change of location as well as in case of fluctuating environment temperature. It is also recommendable to adjust the balance periodically during weighing operation in order to obtain exact measured values.

Using the inbuilt adjusting weight the balance automatically carries out an adjustment after any temperature change of 0.8 °C or any time it was disconnected from the power supply.

Of course it is also possible to check the accuracy of the balance manually any time. You can choose between two options:

- Adjustment is started by pressing the -key three times. After successful adjustment the balance automatically returns to weighing mode.
- 2. Under menu item "P1 01 Calibration with internal weight" (see table below)

Procedure for adjustment:

Observe stable environment conditions. A warming-up time of ca. 1 hour for stabilisation is necessary.

Important!

During the adjustment process no objects should be on the weighing plate.

Operator	Indication			
 ⇒ Call up menu item "P1 Calibration " (see chapter 7.1) ⇒ Press - key 	2.02.05 Setup 13:47:56 P1 Calibration P2 GLP P3 Date/Time P4 Readout P5 R5-232 P6 Printouts P7 Units P8 Modes P9 Globals P9 Globals			
01 Int. calibr Adjustment with internal weight				
⇒ Use the cursor (►) to select "01 Int. calibr. "	31.01.05 Setup 13:47:56 P1 ▶01 ▶Int. calibr. ******** function 02 Ext. calibr. ******** 03 User calibr. ******** 04 Calibr. test ******** 05 Weight. corr. 0.0 06 Auto calibr. 0'off 07 Auto cal. time 1'1 hour 08 Print report 1 on			
Press the -key; the adjustment with internal weight is carried out.	Calibration			

Ŷ	After successful adjustment the balance automatically returns to weighing mode. In case of an adjustment error (e.g. objects on the weighing plate) the display will show an error message, repeat adjustment.	$\overbrace{}{[27.01.05]{}}^{(27.01.05)} \xrightarrow{\text{Weighing}} 13:47:56} \\ \overbrace{}{0.0000g} \\ 0\% \boxed{100\%}$					
02	Ext. Cal - Adjustment with an external weight Locked for verifiable appliances						
03	User cal. – locked for verifiable appliances						
04	Cal. test – not documented						
05	Weight corr. – locked for verifiable appliances						
06	Autom. cal. – locked for verifiable appliances						
07	Auto. Cal.time – locked for verifiable appliances						
08	Print report – printout of the adjustment data						
₽	Use the cursor (►) to select "08 "print report"						
⇔	 Press the -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to save your settings Setup 13:47:56 P11 01 Int. calibr. 02 Ext. calibr. 03 User calibr. 04 Calibr. test 05 Weight.corr. 06 Auto calibr. 						
	0 Print report deactivated1 Print report activated	08▶Print report 1 on					
⇔	Confirm with 🖾 -key						
₽	⇒ When print report is activated you will receive a printout of your adjustment data after each adjustment (Ex.):						
	*** Internal calibration report ***						
	Calibr. : internal						
	Diff : 0.0038 g						
	Signature						

7.3.1.1	Calibration	(adjustment)	only for model	KERN ALT 310
---------	-------------	--------------	----------------	---------------------

Op	perator	indication
① ①	Call up menu item " P1 Calibration " (see chapter 7.1) . Press - key	2.02.05 Setup 13:47:56 P1b Calibration P2 GLP P3 Date/Time P4 Readout P5 RS-232 P6 Printouts P7 Units P8 Modes P9 Globals
01	Int. cal Adjustment with internal weight	
分	Use the cursor (►) to select "01 Int. cal."	31.01.05 Setup 13:47:55 P1▶01▶Int. calibr. ******** function 02 Ext. calibr. ******** 03 User calibr. ******** 04 Calibr. test ******** 05 Weight. corr. 0.0 06 Auto calibr. 0 07 Auto cal. time 1 08 Print report 1
⇔	Press the 🖨 key; the adjustment with internal weight is carried out.	Calibration
⇔	After successful adjustment the balance automatically returns to weighing mode. In case of an adjustment error (e.g. objects on the weighing plate) the display will show an error message, repeat adjustment.	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
02	Ext. Cal - Adjustment with an external weight	
₽	Use the cursor (►) to select " 02 Ext. cal."	31.01.05 Setup 13:47:56 P1 ▶01 Int. calibr. ******** function 02 ▶Ext. calibr. ********* function 03 User calibr. ******** function 04 Calibr. test ******** function 05 Weight.corr. 0.0 0 06 Auto calibr. 0 off 0 07 Auto cal. time 1 1 hour 08 Print report 1 on 1
⇔	Press 🖨 -key Ensure that there are no objects on the weighing plate.	External Calbration Clear the pan [Enter]
	Press E-key: the display shows the measuring	External Calbration Weight measuring
	value of the adjusting weight.	05/01/04 Setup 10:12:45 External Calbration Load weight 50.0 g [Enter]

-		
⇔	Now place the adjusting weight in the center of the weighing plate, press the 🐨 -key. After successful adjustment the system will automatically return to the menu. The 🐨 key can be used to cancel the adjustment. In case of an adjustment error or incorrect adjusting weight an error message is displayed. Repeat adjustment.	05/01/04 Setup 10:12:45 External Calibration Weight measuring 10:12:45
03	User calibr. – user-defined adjusting weight	
₽	Use the cursor (►) to select " 03 User. cal."	Stup 13:47:56 P1 ▶01 Int. calibr. ******** 02 Ext. calibr. ******** 03▶User calibr. ******** function 04 Calibr. test ******** 05 Weight. corr. 0.0 06 Auto calibr. 0 off 07 Auto cal. time 1.1 hour 08 Print report 1 on
₽	Press -key; the display shows the measuring value of the adjusting weight. The first numeral of the displayed value blinks. You can modify it using the arrow keys. After setting your new adjusting weight use the -key to confirm.	User Calibration Key in weight value [g]: 20.0000
⇒	Ensure that there are no objects on the weighing plate. Press 🖼 -key	User Calibration Clear the pan [Enter]
₽	Press the 🖼 key; the display shows the measuring value you selected for the adjusting weight	05/01/04 Setup 10:12:45 User Calibration Weight measuring 05/01/04 Setup 10:12:45 User Calibration Load weight 50.0 g [Enter]

 Now place the adjusting weight in the center of the weighing plate, press the -key. After successful adjustment the system will automatically return to the menu. The -key can be used to cancel the adjustment. In case of an adjustment error or incorrect adjusting weight an error message is displayed. Repeat adjustment. 	05:01:04 Setup 10:12:45 User Calibration Weight measuring User Calibration Weight measuring 31:01:05 Setup 13:47:55 P1 ▶01 Int. calibr. 02 Ext. calibr. 03 > User calibr. 04 14:47:55 03 > User calibr. 04 14:47:45 14:47:45 04 Calibr. test 05 0.0 06 Auto calibr. 08 0.0 08 Print report 1
We recommend: Carry out adjustment as close to the maximum load of Information concerning the test weights is available at:	the balance as possible. http://www.kern-sohn.com
04 Calibration test Here, deviation from the last adjustment is determino values are changed.	ned. This is only a check, i.e.
⇒ Use the cursor (►) to select "04 Cal. test"	31.01.05 Setup 13:47:56 P1▶01 Int. calibr. ******** function 02 Ext. calibr. ******** function 03 User calibr. ******** function 04 Calibr. test ******** function 05 Weight.corr. 0.0 0 06 Auto calibr. 0 loff 0 07 Auto cal. time 1 1 hour 08 Print report 1 on
\Rightarrow Press the \square -key, the calibration test is started	Calibration Calibration check
⇒ The result is displayed	Calibration Check results Cal.: 180.1354 Act.: 180.1438 Diff.: - 0.0084
05 Weight corr. – not documented	

06	Automatic cali	bration			
⇔	Use the cursor	(►) to select "06 Autom. cal."	31.01.05 Setup 13:47:56 P1▶01 Int. calibr. ********* Fut calibr. ******** fun ction		
⇔	Press the 🚡 -k	ey; the current menu item blinks.	02 Ext calibr. 03 User calibr. 04 Calibr.test 05 Weight.corr. 06 ▶Auto calibr. 07 Auto cal.time 08 Print report 0 on		
⇔	Use the 違 - or following setting	- key to choose between the s:			
	0 no	Autom. calibration locked			
	1 Temp.Autor	n. Calibration for a Temperature change of 0.8 °C			
	2 Time Autom. Calibration after a user-defined interval				
	3 both	Autom. Calibration for a Temperature change of 0.8 °C or after the defined interval			
⇒	Confirm with	-key			
07	Auto cal. time	- Automatic calibration after a us	er-defined interval		
⇔	Use the cursor	(►) to select "07 Auto.cal.time"	31.01.05 Setup 13:47:56 P1 ▶ 01 Int. calibr. ******** function		
⇔	Press the 🖨 -k	ey; the current menu item blinks.	S. 02 Ext. calibr. ******** function 03 User calibr. ******** function 04 Calibr. test ******** function 05 Weight.corr. 0.0 06 Auto calibr. 01off		
⇔	Use the arrow keys to enter a value between 1 and 12 hours.				
⇔	Confirm with	-key			

00 Drint report								
In this menu item you can activate the function for printin	g your calibrating data							
⇒ Use the cursor (►) to select "08 "print report"								
 Press the key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to save your settings 	31.01.05 Setup 13:47:56 P1 ▶01 Int. calibr. ********* function 02 Ext. calibr. ********* function 03 User calibr. ********* function 04 Calibr.test ********* function 05 Weight.corr. 0.0 off 06 Auto calibr. 0 off 07 Auto calibr. 1 hour							
 0 Print report deactivated 1 Print report activated 	08 ▶Print report 1 on							
⇒ Confirm with								
When print report is activated you will receive a prin after each adjustment (Ex.):	tout of your adjustment data							
*** Internal calibration report*** Calibr. : internal								
diff : 0,0038 g								
Name								
*** External calibration report ***								
Calibr. : external								
diff : -0,0624 g								
Name	Name							
*** User calibration report***	*** User calibration report***							
Calibr. : User calibration								
diff : -0,0003 g								
Name								

7.3.1.2 Verification

General:

According to the EU guideline 90/384/EEC balances must be verified officially if they are to be used as follows (legally regulated area):

- a) For commercial transactions if the price of goods is determined by weighing
- b) For the production of medicines in pharmacies as well as for analyses in the medical and pharmaceutical laboratory
- c) For official purposes
- d) For the production of finished packages

In case of doubt, please contact your local office of weights and measures.

Verification information

An EU qualification approval is available for those balances marked as appropriate for verification in the technical data. In the event that the balance is applied in an area subject to verification as described above, it must be officially verified and reverified at regular intervals.

Re-verification of a balance is carried out in compliance with the respective legal provisions of the states. The term of verification validity for balances in Germany, for example, is normally 2 years.

The legal provisions of the country of use are to be observed.

After verification the balance is sealed at the marked positions.

Verification of the balance is invalid without the seal.

Position of the seal:



Balances with obligatory verification must be taken out of service if:

- The weighing result of the balance is outside the maximum limits of operating errors. Therefore load balance is regular intervals with known test weight (ca. 1/3 of the max. load) and compare with displayed value.
- The date for subsequent or periodical verification has passed.

7.3.2 P2 GLP (Good laboratory practice)

Quality assurance systems require printouts of weighing results as well as of correct adjustment of the balance stating date and time and balance identification. The easiest way is to have a printer connected.

Definition of a standard log:

Operator	Indication
 ⇒ Call up menu item "P2 GLP" (see chapter 7.1) ⇒ Press -key 	20.02.05 Setup 13:47:56 P1 Calibration P2PGLP P3 Date/Time P4 Readout P5 RS-232 P6 Printouts P7 Units P8 Modes P9 Globals P9 Globals
U1 User	
 ⇒ Use the cursor (►) to select "01 User " ⇒ Press the -key; the current menu item blinks. Use the arrow keys (see chapter 7) to enter user name or number (max. 8 characters). 	31.01.05 Setup 13:47:56 P2 ▶01▶User Nowak 02 Project WX/235 03 Time print 0 04 Date print 1 05 User print 1 06 Pojekt print 0 07 Id print 1 08 Last Cal Print 0
⇒ Confirm with	
02 Project	
 ⇒ Use the cursor (►) to select "02 Project " ⇒ Press the -key; the current menu item blinks. Use the arrow keys (see chapter 7) to enter project name or number (max. 8 characters 	31.01.05 Setup 13:47:56 P2 ▶01 User Nowak 02▶ Project WX/235 03 Time print 0 04 Date print 1 05 User print 1 06 Pojekt print 0 07 Id print 1 08 Last Cal Print 0
⇒ Confirm with	
All other settings (03 – 08) are carried out in the same way.	

All settings that should be printed must be activated with "on".

Example 1: Settings

Print

Print

10.429[0] g

P2	03	Printout time	1	yes	Date	: 18.01.05
P2	04	Printout date	1	yes	Time	: 10:41:05
P2	05	User printout	1	yes	User	: Miller
P2	06	Project printout	1	yes	Proiect:	: AB/007
P2	07	ID printout	1	yes	Balance no.	: WL 041078
P2	08	Last cal. print	1	yes		
					18.01.05	07:48
					Automatic calib	oration
					Deviation.:	0.003[5] g

Example 2: Settings

P2 P2 P2 P2	03 04 05 06	Printout time Printout date User printout Project printout	0 1 1 0	no yes yes no	Date: 22/10/2004 User: Miller Balance no.: 10
P2	07	ID printout	1	yes	13.0521 g
P2	08	Last cal. print	0	no	

7.3.3 P3 Date/time

In this menu item you can call up output and formatting of set date and time.

Operator	indication
 ⇒ Menu item "P3 Date/time" (see chapter 7.1) ⇒ Press → -key 	20.02.05 Setup 13:47:56 P1 Calibration P2 GLP P3 Date/Time P3 Date/Time P4 Readout P5 RS-232 P6 Printouts P7 Units P8 Modes P9 Globals
01 Date format	
⇒ Use the cursor (►) to select "01 Date format"	29.12.04 Setup 13:47:56 P 3 ▶01▶ Date format 0 DA/MO/YR
\Rightarrow Press the 🖨 -key; the current menu item blinks.	02 Time format 1 24 Std. 03 Time ******** Function 04 Date ******* Function 05 Disp. time 1 On
Use the -key to choose between the following settings:	06 Disp. Date ' 1'On
1 Month/Day/Year0 Day/Month/Year	
⇒ Confirm with	
02 Time format	
⇒ Use the cursor (►) to select "02 Time format"	29.12.04 Setup 13:47:56 P3 ▶01 Date format 0 DA/MO/YR
\Rightarrow Press the \square -key; the current menu item blinks.	02▶Time format 1 24 Std. 03 Time ******** Function 04 Date ******* Function 05 Disp. time 1 On
⇒ Use the a -key to choose between the following settings:	06 Disp. Date · 1·On
0 24 hours1 12 hours (PM/AM)	

03	03 Time					
Ŷ	Use the cursor (►) to select "03 Time"	29.12.04 Sctup 13.47.56 P3 ▶01 Date format 0 DA/MO/YR 02 Time format 1 24 Std. 03▶ Time ******** Function 04 Date ******** 05 Disp. time 1 On 06 Disp. Date 1 On				
仓仓	Press 🖆 -key Get to your selection with 😭 - or 🖼 - key	10/11/01 Setup 13:47:56 Hours ▶ 13 Minutes 47 Seconds 56				
⇔	Use the 🖨 -key to confirm your selection (e.g. hours), the current menu item blinks.					
ᡎ	Use the 🖙 -key to increase the value, the 😭 -key to decrease.					
⇔	Use the 🖾 - and 🔚 -keys to select the place to be changed (the respective active place blinks).					
ᡎ	Use the 🖾 -key to confirm your selection (e.g. hours).					
⇔	To change minutes and seconds proceed in the same way.					
⇒	Confirm with 躍 -key					
04	Date					
Ŷ	Use the cursor (►) to select "04 Date"	29.12.04 Sctup 13.47.56 P3 ▶01 Date format 0 DA/MO/YR 02 Time format 1 24 Std. 03 Time ******** Function 04▶Date ******** Function 05 Disp. time 1 On 06 Disp. Date 1 On				
⊳	Press 🚡 -key	APRIL 2004 Setup 13:47:56 APRIL 2004 Year ▶ 2004 Month 11 Day 10				
⇔	All other settings are the same as for entering time (03 Time).					

05/06 Disp. time/date	
⇒ Use the cursor (►) to select e.g. "05 Disp. time"	29.12.04 Setup 13:47:56 P3 b01 Date format 0 DAMO/VP
\Rightarrow . Press the 🚰 -key; the current menu item blinks.	02 Time format 1 24 Std. 03 Time ******** Function 04 Date ******** Function 05▶Disp. time 1 On
Use the -key to choose between the following settings:	06 Disp. Date ' 1'On
0 Display of time/date deactivated1 Display of time/date activated	
⇒ Confirm with □ key	

7.3.4 P4 Readout

Operator	indication		
 ⇒ Call up menu item "P4 Readout" (see chapter 7.1) ⇒ Press -key 	20.02.05Setup13:47:56P1CalibrationP2GLPP3Date/TimeP4ReadoutP5RS-232P6PrintoutsP7UnitsP8ModesP9Globals		
01 Filter			
⇒ Use the curser (►) to select "01 Filter"	29.12.04 Setup 13:47:56		
\Rightarrow Press the 🖨 -key; the current menu item blinks.	03 Autozero 1 On 04 Last digit 1 Always		
⇒ With the and - key you can select between the following adjustments:			
 Very quiet and stable environment: Balance works very fast but is more sensitive to external influences 			
\downarrow \downarrow			
5 Busy environment: Balance works more slowly but is less sensitive to outside influences			
⇒ Confirm with			

02 Disp. refresh				
⇒ Use the cursor (►) to select "02 Disp. refresh"	29.12.04 Setup 13:47:56			
\Rightarrow . Press the 🔚 -key; the current menu item blinks.	P4▶ 01 Filter 5 Slowest. 02▶ Disp refresh 1 0.08 s 03 Autozero 1 O n 04 Last digit 1 Always			
⇒ With the and and select between the following adjustments:				
1 0.1 s				
\downarrow \downarrow				
5 0.5 s				
⇒ Confirm with I -key				
03 Autozero				
⇒ Use the cursor (►) to select "03 Autozero"	29.12.04 Setup 13:47:56			
\Rightarrow Press the \square -key; the current menu item blinks.	02 Disp refresh 1 0.08 s 03 Autozero 1 On 04 Last digit 1 Always			
⇒ With the and and a select between the following adjustments:				
0 Deviations from the Zero display are not automatically tared				
 Deviations from the Zero display are automatically tared. 				
⇒ Confirm with I -key				
04 Last digit				
⇒ Use the cursor (►) to select "04 Last digit"	29.12.04 Setup 13:47:56 P4▶ 01 Filter 5 Slowest			
$\Rightarrow \text{ Press the } Image of the state of $				
⇒ With the and - key you can select between the following adjustments:				
0 4 fractional digits.1 All fractional digits				
⇒ Save with 🖾 -key				

7.3.5 P5 RS-232

In this menu item you can save your settings for the interface.

Operator	indication	
 ⇒ Call up menu item "P5 RS-232" (see chapter 7.1) ⇒ Press -key 	20.02.05Setup13:47:56P1 CalibrationP2 GLPP3 Date/TimeP4 ReadoutP5 RS-232P6 PrintoutsP7 UnitsP8 ModesP9 Globals	
01 – 10 Parameter selection		
\Rightarrow Use the cursor (\blacktriangleright) to select your setting (01 – 10)	29.12.04 Setup 13:47:56 P5 ▶01▶ Roud rate 2 9600	
Press the -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to save your settings	02 Parity 0 none 03 Data bits 2 8 bits 04 Stop bits 1 1 bit 05 Handshake 0 none 06 Auto print 0 none 07 Inetrval 25,* 0.1 s 08 Print of stab 1 enabled	
⇒ Confirm with I -key		

7.3.6 P6 Printouts

In this menu item you can select between 5 different types of data output:

Operator	indication
 ⇒ Call up menu item "P6 Printouts" (see chapter 7.1) ⇒ Press -key 	20.02.05 Setup 13:47:56 P1 Calibration P2 GLP P3 Date/Time P4 Readout P5 RS-232 P6P Printouts P7 Units P8 Modes P9 Globals P9 Globals
01 Printout No.	
 ⇒ Use the cursor (►) to select your setting "01 Printout No." ⇒ Press the - key; the current menu item blinks. ⇒ With the - and - key you can select between the following adjustments: 0 standard 1 printout 1 ↓ ↓ 4 printout 4 	29.12.04 Setup 13:47:56 P6 ▶01▶ Printout No. 0 Standard 02 Pr. 1 start 0 03 Pr. 1 stop 0 04 Pr. 2 start 0 05 Pr. 2 stop 0 06 Pr. 3 stop 0 07 Pr. 3 stop 0 08 Pr. 4 start 0 09 Pr. 4 stop 0 10 String 1 1 11 String 2 1 88 String 79 89 89 String 80 1
\Rightarrow Use the 🖀 -key to confirm your selection	

7.3.6.1 Standard-data output (0 standard)

Data output is carried out by actuating the **a**-key. Definition of the log header is executed in menu item **P2 GLP**^{*}. Example

Date:	22/10/2004	Date:	22/10/2004
Time	13.04.23	Time	13.16.49
User:	Mustermann	User:	Mustermann
Project:	XW/456	Project:	XW/456
	0.008 g	Balance:	10
	-	?	62.685 g *

*: ? = instable measuring value

7.3.6.2 User-defined data output (1 printout 1 \leftrightarrow 4 printout 4)

Here you can define 4 different kinds of data output (printout 1 - 4).

 \Rightarrow The content of the data output is defined as follows.

First line	printout 1 start	1, i.e.	text begins at line	1 (string	1)
------------	------------------	---------	---------------------	-----------	----

Last line **printout 1 stop - 20**, i.e. text ends at line 20 (string 20)

⇒ Text input per line is carried out via the arrow keys (see chapter 7.1) in the respective strings.

string 1	Start of text input
string 20	End of text input

During text input lines may overlap, e.g.:

1
40
20
40

Text input:

- Max. 640 characters
- 80 lines
- 8 characters per line
- \Rightarrow After each line confirm your text input using the \square -key.
- After complete text input press the [™]/_■ -key; this is followed by an inquiry whether you want to save your setting.
- \Rightarrow Use the **a** -key to confirm (see chapter 7.1).

Apart from flow text (characters, numbers and numerals) the following variables are stored in the menu:

General variables			
%%	Printout of 1 character "%"(i.e. in order to print out 1 character % two %% have to be entered)		
%N	Net weight		
%d	Current date		
%t	Current time		
%i	Balance ID-no.		
%R	Program no.		
%P	Project no.		
%U	User no.		
%F	Current function (operating mode)		
%C	Date and time of last adjustment		
%K	Type of last adjustment		
%I	Deviation from last adjustment		

Print related variables				
N.	Printout of 1 character " / "(i.e. in order to print out 1 character / two // have to be entered)			
lc	CRLF (carriage return line feed) Beginning of line next line			
١r	CR (carriage return) beginning of line			
\ <i>n</i>	LF (line feed) next line			
\t	Tabulator			
ls	Next "string"			
\0	End of data input			

Variables in the various operating modes				
Variable	Description	Mode of operation		
%W	Reference quantity	Parts counting		
%V	Measuring value in number parts or in % (percent determination)			
%Н	Lower limit	Weighing with tolerance range		
%L	Upper limit			
%Z	Rated value	Dosing		
%В	Reference mass	Percent determination		
%A	Sensibility	Dynamic weighing (Animal		
%b	Median Value	weighing)		
%I	Method	Density determination		
%р	Liquid			
%с	Temperature			
%a	Density liquid			
%v	Sinker			

Variable for statistics			
%n	Number weighings		
%х	Median Value		
%S	Sum of all measuring values		
%m	Min value		
%М	Max value		
%D	Difference min and max value		
%s	Standard Deviation		
%r	Variance		

Variables are entered either directly via arrow keys or more comfortably in menu item **P6 "10 Pr. Edit"**.

Examples for text input:

Example 1: Max mass can not exceed 11.250 g!

Parameter No.	Text							
	1	2	3	4	5	6	7	8
20 string 10	М	а	X		m	а	S	S
21 string 11		С	а	n		n	0	t
22 string 12		е	X	С	е	е	d	
23 string 13	1	1		2	5	0		g
24 string 14		!						
25 string 15								

Example 2:	Kern & Sohn	GmbH
------------	-------------	------

Datum: Zeit:

Gewicht:

*****Unterschrift:.....

*** Wägen mit Toleranzbereich***

Paramatar Nr.		Text							
	Parameter Mr.		2	3	4	5	6	7	8
26	string 16	Κ	е	r	n		&		S
27	string 17	0	h	n		G	m	b	Η
28	string 18	١	С	D	а	t	u	m	:
29	string 19	%	d	١	С	Ζ	е	i	t
30	string 20	:	%	t	1	r	1	n	G
31	string 21	е	¥	i	С	h	t	۰.	%
32	string 22	Ν	١	С	١	С	*	*	*
33	string 23	*	*	U	n	t	е	r	S
34	string 24	С	h	r	i	f	t	:	
35	string 25								
36	string 26			١	С	*	*	%	F
37	string 27	*	*	*	*				

7.3.7 P7 Weighing units

In this menu item you can activate various different weighing units (see chapter 1 "Technical data").

Switch into activated units by pressing the 🐷 - key several times.

Operator		indication
 ⇒ Call up menu item "P7 Units" ⇒ Press → -key 	(see chapter 7.1)	20.02.05Setup13:47:56P1CalibrationP2GLPP3Date/TimeP4ReadoutP5RS-232P6PrintoutsP7/UnitsP8ModesP9Globals
01 – 16 Parameter selection		
 ⇒ Use the cursor (►) to select y ⇒ Press the -key; the current Use the arrow keys (see chap settings 0 Weighing unit deactivated 1 Weighing unit activated 	our setting (01 – 16) menu item blinks. ter 7.1) to save your	10/11/01 Setup 13:47:56 P7 ▶01▶ Grams 1 disabled 02 Miligrams 0 enabled 03 Carats 1 disabled 04 Pounds 0 enabled 05 Ounces 0 enabled 06 Ounces troy 1 disabled 09 Taels Hk. 0 enabled 10 Taels S. 0 enabled 11 Momms 0 enabled 12 Grains 0 enabled 13 Newtons 0 enabled 14 Tical 0 enabled 15 Custom factor 1.0
⇒ Use the a -key to confirm you	ur selection	
⇒ Save (see chapter 7.1)		

7.3.8 P8 operating modes

See chapter 8.1

7.3.9 P9 General functions

Operator		indication		
 ⇒ Call up menu item "P9 Globals" (see chapter 7.1) ⇒ Press → -key 		20.02.05Setup13:47:56P1 CalibrationP2 GLPP3 Date/TimeP4 ReadoutP5 RS-232P6 PrintoutsP7 UnitsP8 ModesP9PGlobals		
01 – 13 Parameter selec	ction			
 ⇒ Use the	29.12.04Setup13:47:56P9 01 ID setting 02 ID autoprint 03 Beep 04 Language 05 Backlight********Function 1 On 1 Screensaver 09 Balance ID 10 Software rev 11 Par. printout 12 Par. receive 13 Passwd. Prot.13:47:56 ******* 1 On 1 On 0 Off ******** MXA0.40 ******** Function			
01 ID setting	Entering a user code			
02 ID Autoprint	User code can also be printed	I		
03 Веер	Tone on/off			
04 Language	User guidance selectable in G	German, English and Spanish		
05 Backlight	Back lighting of the display on	/off		
06 Contrast	Contrast of the display			
07 Screensaver	Back lighting automatically sw measuring value is reached (0	vitches off as soon as a stable Condition: Backlight on)		
08 Temperature	Temperature display			
09 Balance ID	Balance identification no.			
10 Software rev	Software issue			
11 Par. Printout	Balance parameters are printe	ed out		
12 Par receive	not proved by documents			
13 Password protection	Password protection			
\Rightarrow Press the 🖾 -key; the	⇒ Press the arrent menu item blinks.			
Activate / deactivate p	parameter with 窟 - and 🐷 -key	/		
⇒ Confirm your selection	n with 躍 -key			

8 Operation Operating elements

• Display:



• Overview of display:



Balance zero-display:

If the balance does not show exactly zero although the pan scale is unloaded, press the \mathbb{Z} -key and the balance will be reset to zero. (Display [$\rightarrow 0 \leftarrow$]).

Stability display:

If the display shows the stability display [\square] the balance is in a stable status. When status is instable the [\square] –display disappears.

Graphic display:



- 1. Weight display
- 2. Balance zero-display
- 3. Stability display
- 4. Capacity display
- 5. Mode of operation
- 6. Current date
- 7. Current time

• Overview of the keypad:

Key	Function
	Turn on/off
÷	Menu point to the left
F	Access to user menu
\rightarrow	Menu point to the right
	Option key into operating modes
	Decreasing the value for the selected numeral or number
	Parameter selection (cursor control downwards)
	Switching between weighing units
	Parameter selection (cursor control upwards)
	Increasing the value for the selected numeral or number
	Printout of the weighed value on an external appliance (printer or PC)
L L	Confirm/save settings
	• Tare
	Quit menu
	Set weight display at zero

8.1 Operating modes (P8 modes)

In this menu item you can activate/deactivate the following operating modes:

P8 01: Parts Counting P8 02: Check weighing P8 03: Filling P8 04: Percent weighing P8 05: Animal weighing P8 06: Density P8 07: Formulation P8 08: Statistics Some operating modes can be combined (e.g

Notice: Some operating modes can be combined (e.g. statistics/parts counting, statistics/percent determination). Further details are described in the respective chapters.

Activate/deactivate operating modes:

 \Rightarrow In the main menu, call up menu item P8 "Operating mode" (see chapter 7.1)

 \Rightarrow Press \square -key, the overview of the operating modes appears:

20.02.05	Mode	13:47:56
P8 ▶01▶	Parts Count	1 disabled
02	Checkweighing	0 enabled
03	Filling	1 disabled
04	Percont	1 disabled
05	Animal	0 enabled
06	Density	1 disabled
07 08	Formulation Statistics	0 enabled

- ⇒ Use the arrow keys (see chapter 7.1) to activate (1) or deactivate (0) the desired operating modes.
- \Rightarrow Confirm your setting with the **b** -key.
- \Rightarrow Save (see chapter 7.1)

All activated operating modes are now stored in a submenu (M0 – M8) and can be called up directly via the \bigcirc -key:



Moving in the operating mode:

- \Rightarrow Press the \bigcirc -key
- ⇒ Use the cursor (►) to select your operating mode



- \Rightarrow Press the \square -key; the parameter selection appears
- ⇒ Use the cursor (►) to select parameter
- \Rightarrow Press the \square -key; the current menu item blinks
- ⇒ Use the arrow keys (see chapter 7.1) to save your settings. All settings possible are described in the chapters of the respective operating mode
- \Rightarrow Confirm your setting with the **b** -key
- Press again, the graphic display of the respective operating mode appears. You are now in the operating mode.



Return to weighing mode:

- ⇒ Press 🔏 -key
- ⇒ Cursor (►) to M0 Basic weighing



29.12.04

 \Rightarrow Press the \square or the \square -key

8.1.1 Simple weighing

Operation:	Display:
\Rightarrow Use the \square -key to turn on the balance.	
or	
⇒ Use the → Lee to call up menu item "M0 Basic weighing" (chapter 8.1)	
As soon as the weight display shows "0.000" your balance is ready for weighing	0,0000
Put on items to be weighed; after stability time the measuring value is displayed.	19.6879 g
Pressing the a key you can switch to another weighing unit, e.g. ct (see Chapter 7.4.6 "P7 Weighing units")	98.4380 ct
⇒ To turn off the balance press the a-key	

8.1.1.1 Tare

The dead weight of any type of weighing container can be tared out by pressing a button, so that subsequent weighing procedures show the net weight of the items to be weighed.

	Operation:	Display:
₽	Use the 🖾-key to turn on the balance.	
₽	As soon as the weight display shows " 0.0000" your balance is ready for weighing	0.0000 g
₽	Place items to be weighed on balance, the weighed value is displayed.	19.6879 g
₽	Press the Here to start the taring process. The weight of the container is now saved internally.	0.0000 g
₽	Place the item to be weighed into the tare container. Now read the weight of the items to be weighed on the display.	53.2587 g

The taring process can be repeated any number of times, e.g. for several components for a mixture (add-on weighing).

The limit is reached when the whole weighing range is exhausted.

After removing the tare container the overall weight is displayed in the negative.

8.1.1.2 Under floor weighing

Using under floor weighing allows weighing of objects that because of their size of shape cannot be placed on the pan scale.

Proceed as follows:

- Turn off balance.
- Open the closing lid at the bottom of the balance.
- **Carefully and completely** hook in the hook for under floor weighing.
- Place balance over an opening.
- Suspend the item to be weighed from the hook and carry out weighing.



Fig. 1: Setting up balance for under floor weighing



- Ensure that all suspended objects are stable enough to hold the desired items to be weighed securely (danger of breaking).
- Never suspend loads that exceed the stated maximum load (Max) (danger of breaking)

Always ensure that underneath the load there are no living beings or objects that might be damaged.



8.1.2 Parts counting

Before the balance can count parts, it must know the average part weight (i.e. reference). This is either entered manually or determined by weighing. Proceed by putting on a certain number of the parts to be counted. The balance determines the total weight and divides it by the number of parts (the so-called reference quantity). Counting is then carried out on the basis of the calculated average piece weight. As a rule:

The higher the reference quantity the higher the counting accuracy.

Display overview for parts counting operation:



- 1. Number of all parts on the weighing plate
- 2. Weighing-in aid coarse/fine (only displayed for active dispensing)
- 3. Operating mode (status bar)
- 4. Reference weight
- 5. Weight of all parts on the weighing plate
- 6. Tolerance marker (only displayed for active tolerance weighing)



7. Display for parts counting operation

Operator	Indication
⇒ Call up operating mode "M1 Parts counting" (see chapter 8.1)	10/11/01 Modo 13/47/56 M0 Basic weighing M1 Parts counting M2 Checkweighing M3 Filling
⇒ Press -key	M4 Percent M5 Animal weighing M6 Density M7 Statistics
⇒ Use the cursor (►) to select your setting (01 – 07)	Parts counting setup M1▶01 Unit weight ▶ 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting ON 05 Filling ON 06 Statistics OFF 07 Run OFF
01 Unit weight – manual input of reference weight	
Press the -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to enter the reference weight for a unit. Confirm with -key	

₽	Press 🖫 -key; the display changes into parts counting operation	10/11/01 Parts couling 19:47:56 90% 110% APW=5.000 WGH=100.000 C 0% 0 0 pcs 0%
飰	The balance is now in parts counting mode counting all units on the weighing plate	
01	Unit weight – determination of reference weight by we	eighing
Ŷ	Press the 躇 -key; display changes to parts counting operation	Parts counting setup M1▶01 Unit weight ▶ 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting OFF 05 Filling OFF 06 Statistics OFF 07 Run OFF
		10/11/01 Parts continue 15/272/31 90% 10% APW=5.000 WGH=100.000 Image: Continue 0% 0% 0 pcs 0%
\hat{T}	Press the a-key; select reference quantity (factory- defined are quantities of 10, 20, 50,100, or freely selectable), use the key to confirm	Donesicontine 10 M1 № 01 № 01 Sample size 20 02 Sample size 20 03 Sample size 50 04 Sample size 100 05 Sample 0 PCS
⇒	Place as many parts on the weighing plate as required by the set reference quantity, confirm by pressing the -key If you are using a weighing container first tare your balance pressing the -key.	Image: State of the second control of the second
⇔	Press -key The (A) symbol in the display indicates that the automatic reference optimization is turned on. Every time more pieces are added the balance carries out optimization automatically. It is not necessary to press another key to start the optimization process. For each reference optimization the average piece weight (reference) is newly calculated. Since additional parts increase the basis for the calculation the reference becomes more exact.	10/11/01 Parts countine 13/12/50 APW=5.000 WGH=85.000 0 17 pcs 0%
⇒	Actuate the 🖨 -key. The reference quantity is saved under " 01 Unit weight ".	Parts couting setup M1 ► 01 Unit weight ► 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting 05 Filling 08 Statistics 07 Run
₽	Press the 🖾 -key; the balance is now in parts counting mode counting all units on the weighing plate.	10/11/01 Parts counting 13:47:56 APW=5.000 WGH=85.000 0 17 pcs 0%

02	Recall sample – call up a reference weight from the da	atabase	
⇔	Use the cursor (►) to select " 02 Recall sample "	Parts counting setup M1 h 01 Unit weight ▶ 5.0000 g 02 Recall sample 03 Store sample 03 Store sample ON 04 Checkweighting ON 05 Filling ON 06 Statistics OFF 07 Run OFF M1 h 01 Unit weight 5.0000 g 02 Recall sample >	
		04 Checkweighting ON 06 Filling ON 06 Statistics OFF 07 Run	
⇔	Press the 🖾 -key; the sub-menu " 02 Recall sample " will be displayed.	Parts counting setup M1 ▶ 02 ▶ 01▶, BBBB 01 1.5000 g 02 BBBB 02 0.4520 g 03 CCCC 03 1.0032 g	
⇔	Use the arrow keys to select the desired reference weight	49 AAAA 49 0.0015 g 50 AAAA 50 2.0300 g	
⇔	Use the 🖾 -key to confirm; the selected reference weight appears under " 01 Unit weight ".	Parts counting setup M1 ► 01 Unit weight 1.0032 g 02 Recall sample ► 03 Store sample ► 04 Checkweightling ON 05 Filling ON 06 Statistics OFF 07 Run OFF	
₽	Press the 🐷 -key; the balance is now in parts counting mode counting all units on the weighing plate.	0111/01 Parts counting 13:47:56 APW=5.000 WGH=85.000 0 17 pcs 0%	
03	Store sample – Saving a reference weight in the datab	oase	
Th da	e reference weight stored in menu item " 01 Unit weight " o tabase as follows (max. 200 Parameter):	can be saved in the	
₽	Use the cursor (►) to select " 03 Store sample "	Etres countine statuo M1 № 01 Unit weight ► 5.0000 g 03 Store sample 04 Checkweighting ON 05 Filling ON 06 Statistics OFF 07 Run	
		E2nts.countine sctup M1 ≥ 01 Unit weight 5.0000 g 03 Recall sample 03 Store sample ► 04 Checkweighting ON 05 Filling ON 06 Statistics OFF 07 Run	
₽	Press the 🖨 -key; the sub-menu " 03 Store sample " will be displayed.	Darts counting setup M1 ► 02 ► 01►, BBBB 01 1.5000 g 02 BBBB 02 0.4520 g 03 CCCC 03 1.0032 g 03 CCC 03 1.0032 g 1 49 AAAA 49 0.0015 g 50 AAAA 50 2.0300 g	
Ŷ	Use the arrow keys (泽 or 🐨) to select parameter no.	Parts counting setup M1 ► 03 ► 01 BBBB 01 1.5000 g 02 BBBB 02 0.4520 g 03<	

 Press the -key; use the arrow keys to enter parameter name (max. 10 characters) 	Parts counting setup M1 ▶ 03 ▶ 01 BBBB 01 1.5000 g 03 ⊨ 88B 80 1.0032 g 03 ⊨ 88B 80 1.0032 g 04 ⊨ 5000 4 1.0000 g 04 ⊨ 5000 1.0000 g 04 ⊨ 5000 1.0000 g 04 ⊨ 5000 1.0000 g 10000 1.0000 1.0000 10000 1.0000 1.0000 10000 1.0000 1.0000 10000 1.0000 1.0000 100000 1.00000 1.0000
\Rightarrow Use the 🖾 -key to confirm, the blinking stops	Ports counting stup I 1,5000 g 01 BBBB 02 0.4520 g 03 BBBB 03 1.0032 g 04 ⁺ DDDD 04 1.0000 g 1 1 1.0000 </td
⇒ Press the	Darts counting setup M1 ► 01 Unit weight 5.0000 g 02 Recall sample ► 03 Store sample ► 04 Checkweightting ON 05 Statistics OFF 07 Run OFF
04 Checkweighing	
The combination parts counting / checkweighing allows you to reference weight is within your set tolerance	o check whether your
 ⇒ Use the cursor (►) to select the "04 Checkweighing " ⇒ Press -key 	Parts counting setup M1 ▶ 01 Unit weight 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting on 05 Filling OFF 06 Statistics OFF 07 Run OFF
\Rightarrow Press the \blacksquare -key; the current menu item blinks.	Parts counting setup Checkweighing
Activate operating mode "Checkweighing" via the arrow keys	M1 •04 • 01 Checkweighing • TAK 02 Low limit 0 03 High limit 0
⇒ Set tolerance limits	
⇒ Confirm with I -key	

05 Filling			
The combination of parts counting /filling allows your to set a target quantity.			
 ⇒ Use the cursor (►) to select the "05 Filling" ⇒ Press -key 	Parts counting soup M1 ▶ 01 Unit weight 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting on 05 Filling on 06 Statistics OFF 07 Run OFF		
 ⇒ Press the → -key; the current menu item blinks. ⇒ Activate operating mode "Filling" via arrow keys ⇒ Enter value for the target quantity 	Parts counting setup ► Filling M1 ► 05 ► 01 Filling ► OFF 02 Target weight 0 PCS		
⇔ Confirm with			
⇒ Press the	Parts counting setup M1▶01 Unit weight 5.0000 g 02 Recall sample 03 Store sample 03 Store sample 04 Checkweighting 04 Checkweighting on 05 Filling on 06 Statistics OFF 07 Run OFF		
06 Statistics			
When combining parts counting /statistics the displayed value -key.	e is accepted by pressing the		
 ⇒ Use the cursor (►) to select "06 Statistics" ⇒ Press -key 	Data counting actuo M1 01 Unit weight 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting ON 05 Filling ON 06 Statistics > OFF 07 Run > OFF		
\Rightarrow Press the \blacksquare -key; the current menu item blinks	Ports counting source Statistics M1 > 06 > 01 Statistics > OFF 02 Results 03 Clear		
⇒ Use the cursor (►) to select "03 Clear"	Ports countine setur ≽Statistics M1 > 06 > 01 Statistics OFF 05 Clear >		
Press the → -key; data will be deleted	Parts counting setur Statistics Clear statistics ?		
➡ Confirm with I -key	Darts counting source Statistics M1 > 06 > 01 Statistics OFF 02 Results 03 Clear ►		
 ⇒ Use the cursor (►) to select 01 Statistics ⇒ Press -key 	Parts counting setur ≽Statistics M1 ▶ 06 ▶ 01 Statistics ➤ OFF 02 Results 03 Clear		
Activate operating mode "Statistics" with the arrow keys; press the → -key to confirm	Parts counting setur >Statistics M1 > 06 > 01 Statistics > ON 0 Clear		

⇒ Press the a -key; return to menu	Date counting setup M1+01 Unit weight 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting 05 Filling 0N 06 Statistics 07 Run
Press the B -key; the balance is now in parts counting mode	10/11/01 Parts couting 13:47:56 90% 110% N=0 WGH=100.000 € 0% 0 0 pcs 0% 100% 100%
 After each measuring (stable measuring value) press the -key; the displayed value will be saved and added to the saved number of values (N). 	10/11/01 Parts couting 13:47:56 90% N=10 APW=5.000 WGH=100.000 € 0% 0 0 pcs 0%
 ⇒ Calling up the statistic results after e.g. 10 measurements (N=10) Use the	Ebits countine state M1 + 01 Unit weight ► 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting 08 Filling 08 Statistics 07 Run
⇒ Use the cursor (►) to select "06 Statistics"	Exts contine setup M1 ► 01 Unit weight 5.0000 g 02 Recall sample 03 Store sample 04 Checkweighting 05 Filling 08 Statistics 07 Run
⇒ Confirm with	Interconnections setue ► tatistics M1 ► 06 ► 01 Statistics ► ON 02 Results 03 Clear
⇒ Use the cursor (►) to select "02 Results"	Rdrts.counting sctup >statistics M1 ▶ 06 ▶ 01 Statistics ON 0 Clear
Use the -key to confirm; the display will show your statistical results.	Parts counting setup ≪italistics N=10 SUM=40 MIN=4 MAX=5 D=1 SDV=2 RDV=52.7

⇒ By actuating the → -key you can print your statistical results on a connected printer (see example).

N : 10 Image: Number of weighing proc. SUM: 40 pcs Image: Total of all weight values X : 4 pcs Average Value MIN : 4 pcs Smallest value MAX: 5 pcs Largest value D : 1 pcs MAX – MIN SDV : 2 pcs Standard Deviation RDV : 52,7 % Variance		
⇒ Press ^{ME} / ₄₄ -key Statistics ON 02 Results → 03 Clear		
\Rightarrow Use the 躇 -key to return to the sub-menu	Parts counting setup M1 ▶ 01 Unit weight 5.0000 g 02 Recail sample 03 Store sample 04 Checkweighting ON 05 Filling ON 06 Statistics ▶ ON 07 Run 07 Run	
06 Run		
Parameter selection " M1 07 RUN " (confirm with 🖾 -key) will take you directly into parts counting mode.		

8.1.2.1 Printout data output Standard data output:

Key	Indication	GLP Parameters	Data output
PRINT SET	I20.1.05 Parts counting 13.47:56 APW=5.000 WGH=100.000 0 O 17 pcs 170%	P2 03 time printout0: nP2 04 date printout0: nP2 05 user printout.0: nP2 06 project printout 0: nP2 07 printout Id0: nP2 08 cal printout.0: n	0 0 0 0 0 0 0
	Parts counting 13/2/15C APW=5.000 WGH=100.000 O 177 pcs 0% 100%	P2 03 time printout 1: ye P2 04 date printout 1: ye P2 05 user printout. 1: ye P2 06 project printout 1: ye P2 07 printout Id 1: ye P2 08 cal printout. 1: ye	s Date: 16/01/2004 s Time 13:12:30 s User: Mustermann s Project: Checking. s Weight: 1111111 Last adjustment:
			17 pcs

User-defined data output

Key	Indication	Variable selection	Data output
PRINT SET ¢J	СССС 1.25	%d; %t; %i; %R; %P; %U; %V; %V; %N; %W; %S; %m; %M; %D; %S; %r; %C; %K; %I;	17/01/2004 08:16:09 11111111 MBA 0.01 Checking. Mustermann. quantity 15 pcs 15.048 g 5.30000 g 13 15 pcs 15 pcs 15 pcs 15 pcs 15 pcs 15 pcs 15 pcs 2 pcs 0 pcs 0.00 % 16/01/2004 13:02 External adjustment: 0.01 g

8.1.3 Checkweighing (Weighing with tolerance range)

Overview of display:



- 1. Current weight display
- 2. Weighing-in aid coarse/fine
- 3. Mode of operation
- 4. Rated value
- 5. Upper limit (Hi), lower limit (Lo)
- 6. Tolerance marker



Operator		indication	
⇔	Call up operating mode " M2 Checkweighing " (see chapter 8.1)	10/11/01 Mode 13/47/50 M0 Basic weighing M1 Parts counting M2 + Checkweighing M3 Filling III G III	
⇒	Press 🖾 -key	M4 Percent M5 Animal weighing M6 Density M7 Statistics	
01	01 - 02 low/high limit – Enter limiting values		
₽	Use the cursor (►) to select "01 Lower limit or 02 upper limit"	Implementation Setup M2 P 01 Low limits > 0.0000 g 02 Filiph limits 0.0000 g 03 Statistics OFF 04 Run OFF	
\uparrow	Press the 🖨 -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to enter limiting values and confirm with the 🛱 -key. Remark: At first set parameter 02 high limit.		
⇔	Use the cursor (►) to select 04 Run and confirm with the 🖀 -key	Checkweighing setup M2 + 01 Low limits 0.0000 g 02 High limits 0.0000 g 03 Statistics OFF 04 Run	

₽	The balance is now in "Weighing with tolerance range" mode	$\begin{tabular}{ c c c c c c } \hline 10'11'01 & Checkweighing & 13:47:56 \\ \hline & Dif=-60.0000 & Hi=70.0000 & C \\ \hline & & 0.00000 & g \\ \hline & 0.0000 & g \\ \hline & 0.00000 & g \\ \hline & 0.0000 & g \\ \hline \hline & 0.0000 & g \\ \hline \hline & 0.0000 & g \\ \hline & 0.0000 & g \\ \hline \hline & 0.0000 & g \\ \hline \hline & 0.0000 & g \\ \hline & 0.0000 & g \\ \hline \hline \hline & 0.0000 & g \\ \hline \hline \hline & 0.0000 & g \\ \hline \hline \hline \hline & 0.0000 & g \\ \hline \hline \hline \hline & 0.0000 & $
⇔	Put on goods to be weighed, tolerance control is started	10/11/01 Checkweighing 13:47:56 Dif=- 4.9972 Hi=70.0000 Dis Lo=50.0000 Dis 555.0028 g 0%
03	Statistics- Combination checkweighing/statistics	
03 ⇒	Statistics- Combination checkweighing/statistics Use the cursor (►) to select "03 Statistics",	Checkweighing setup M2 ► 01 Low limits ► 0.0000 g 02 High limits 0.0000 g 03 Statistics OFF 04 Run

8.1.4 Filling Display overview for filling operation:



- 1. Residual filling quantity
- 2. Weighing-in aid coarse/fine
- 3. Mode of operation
- 4. Target weight
- 5. Present weight of sample

Op	perator	indication
Ŷ	Call up operating mode "M3 Filling " (see chapter 8.1)	MO Basic weighing M1 Parts counting M2 Checkweighing M3 Filling
⇔	Press 🚡 -key	M4 Percent M5 Animal weighing M6 Density M7 Statistics
\hat{T}	Use the cursor (►) to select 01 Target weight	Filling setup M3 № 01 Target weight 02 Statistics 03 Run
₽	Press the 🖨 -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to enter the target value.	
₽	Confirm with 🖾 -key	
₽	Use the cursor (►) to select 03 Run and confirm with the 🐨 -key; the balance is now in Filling mode	10/11/01 Filling 13/17/56 90% 110% Tr=100.0000 10% 90% 100.00000 g 0%100%
02	Statistics combination Filling/statistics	
₽	Use the cursor (►) to select "02 Statistics"	Filling setup M3 ≥ 01 Target weight 02 Statistics 03 Run
₽	All further steps are the same as for the combination parts count/statistics (chapter 8.1.2)	$\begin{bmatrix} 10/11/01 & \text{Filling} & 13:47:56 \\ 100\% & \text{Tr=100.0000} \\ 100\% & 1000.0000 \\ 0\% & 1000.0000 \\ 0\% & 100\% \end{bmatrix}$

8.1.5 Percent determination

Percent determination allows weight display in percent, in relation to a reference weight

Display overview for percent determination operation:



- 1. % deviation to reference weight
- 2. Weighing-in aid coarse/fine (only displayed for active dispensing)
- 3. Mode of operation
- 4. Present weight of sample
- 5. Reference weight
- 6. Tolerance marker (only displayed for active tolerance weighing)
- 7. Percent determination mode

Operator	indication
 ⇒ Call up operating mode "M4 Percent" (see chapter 8.1) ⇒ Press → -key 	10/11/01 Mode 13/17/56 M0 Basic weighing M1 M1 Parts counting M2 M2 Checkweighing M3 M3 Filling M4+ Percent M5 Animal weighing M6 M6 Density M7 Statistics M3 M3
01 Reference – Numeric entry of the reference weight	
⇒ Use the cursor (►) to select "01 Reference"	Percentsetup M4 + 01 Reference ▶ 0.0000 g 02 Decimal places 1 PLACE 03 Checkweighing OFF 04 Filling OFF 05 Statistics ON 06 Run ON
 ⇒ Press the → -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to enter reference weight and confirm with the → -key. 	
Press the I -key; the balance is now in percent determination mode.	10/11/01 Percent 13/47:56 REF = 100.000 WGH=0.000 % 0% 0% 100%
⇒ Now place items to test onto the weighing plate, the percentage in relation to the reference part is displayed.	

01 Re	01 Reference – determination of reference weight by weighing		
⇔ Pe	ercent determination mode	Percent solup M4 ▶ 01 Reference 0.0000 g 02 Decimal places 0 FF 03 Checkweighing 0 FF 04 ▶ 101 Reference 0 FF 05 Statistics 0 N 06 Run ▶ 10/41/01 ≥ creat 00 % 0 %	
⇔ Pre firs	ess 🖙-key. Put on reference weight; if necessary, tare st	10/11/01 Percent 158/2456 Tare a container if Place a reference mass necessary [Enter] 0.000 g 0%	
⇔ Pre	ess \mathbb{F} -key, the weight is stored as reference (100%).	[24.01.05 Percent 13:47:56] REF = 100.000 WGH=0.000 1000,0 % 0%100%	
⇔ No pe	ow place items to test onto the weighing plate, the crcentage in relation to the reference part is displayed.		
02 De	ecimal places		
⇔ Us	se the cursor (▶) to select " 02 Decimal places" ,	Dercontector 0.0000 g M4 ▶ 01 Reference 0.0000 g 02 Decimal places ▶ 1 PLACE 03 Checkweighing OFF 04 Filling OFF 05 Statistics ON 06 Run ON	
⇔ Pre Us dig	ess the 🖾 -key; the current menu item blinks. se the arrow keys (see chapter 7.1) to enter decimal gits; confirm with the 🐨 -key		
⇔ Pre de	ess the 運 -key; the balance is now in percent termination mode.	10/11/01 Percent 13:47:56 REF =100.000 WGH=0.000 % 0%	
03 CH 04 Fi 05 St 06 Ru	heckweighing Iling tatistics un		
⇔ Us	se the cursor (►) to select parameter "03 - 06"		
⇔ All pa	further steps are the same as for the combination of the combination o		

8.1.6 Animal weighing (Dynamic weighing)

For unsteady items to be weighed (e.g. animals) or strong vibrations you can activate the dynamic weighing function with automatic or manual start. During a certain period of time the balance determines weight values and calculates an average.

In **automatic start** measuring starts automatically as soon as the weight changes.

In **manual start** you trigger measuring by actuating the -key.

Operator	indication		
⇒ Call up opera (see chapter	iting mode " M5 Animal weighing" 8.1)	10/11/01 Mode 13/27/56 M0 Basic weighing 13/27/56 M1 Parts counting 13/27/56 M2 Checkweighing 13/27/56 M3 Filling 13/27/56	
⇒ Press 🔚 -ke	y	M5 Animal weighing M6 Density M7 Statistics	
01 Filter – filter Vibrations are fil	for adjustment to the environmental cond tered out by increasing the number of measu	ditions ring cycles.	
\Rightarrow Use the curse	or (►) to select " 01 Filter"	MSP01 Filter ► FAST 02 Threshold 10 DIV 03 Autostart ON 04 Statistics OFF 05 Run	
⇒ Press the arrow keys (s the filter and	Press the -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to enter the sensitivity of the filter and confirm with the -key.		
slowest slow normal fast fastest	(insensitive, very busy setup location) ↓ (sensitive very guiet setup location)		

02 Threshold (Condition: 03 – Auto start activated)	
⇒ Use the cursor (►) to select "02 Threshold"	Animal weighing setup M5▶01 Filter FAST 02 Threshold 10 DIV 03 Autostart ON 04 Statistics OFF 05 Run 0FF
Press the → -key; the current menu item blinks. Use the arrow keys (see chapter 7.1) to set the number of measurements used for averaging. Confirm by pressing the → -key	
10 DIV	
1000 DIV	
03 Weighing with automatic start After selecting your parameters and with 03 Auto start activated, carry out weighing as follows:	Animal weighing_setup M5▶01 Filter FAST 02 Threshold ▶ 10 DIV 03 Autostart ON 04 Statistics OFF 05 Run 05 Run
⇒ Use the cursor (►) to select "05 Run".Confirm by pressing the a -key	Animal weiching_setup MSP 01 Filter FAST 02 Threshold 10 DIV 03 Autostart ON 04 Statistics OFF 05 Run
⇒ If you are using a weighing container use the [™] / _™ -key for taring	10/11/01 Animal weighing 13/47/56 Tare if necessary. Place an object 0.00000 g 0%100%
⇒ Put goods to be weighed on weighing plate	
⇒ Dynamic weighing is started automatically.	10/11/01 Animal weighing 13:47:56 Result estimating g 0% 100%
⇒ When weighing is complete the weight is shown in the display	10/11/01 Animal weighing 1584755 Result estimating finished. Pleace next object. 555.2540 g
⇒ To start a new weighing cycle relieve the balance	
Press the → -key; return to menu	

03 Weighing with manual start After selecting your parameters and with 03 Auto start deactivated, carry out weighing as follows:	Image: Image and the setup M5▶01 Filter FAST 12 Threshold ▶ 10 DIV 03 Autostart OFF 04 Statistics OFF 05 Run 05 Run
Solution ⇒ Use the cursor (►) to select "05 Run".Confirm by pressing the a -key	Animi Swalobian setup M5 ► 01 Filter FAST 02 Threshold 10 DIV 03 Autostart ON 04 Statistics OFF 05 Run ►
⇒ If you are using a weighing container use the	10/11/01 Animal weighing 13:47:50 Tare if necessary Pleace an object (Units]. 0.00000 g 0%
⇒ Put goods to be weighed on weighing plate	
⇒ Dynamic weighing is started by actuating the	10/11/01 Animal weighing 13:47:56 Result estimating g 0% 100%
When weighing is complete the weight is shown in the display	e 10/11/01 Animal weighing 13:47:56 Result estimating finished. to continue [Units]. 15.3256 g 0%
➡ To start a new weighing cycle relieve the balance and press the	
⇒ Press the -key; return to menu	

8.1.7 Density determination

Density determination of solids and liquids see user manual "Density set".

8.1.8 Formulation

The formulation function allows to add on various components of a mixture. To check, the overall weight of all components can be called up.

Overview of display:



- 1. Present weight of sample
- 2. Weighing-in aid coarse/fine
- 3. Mode of operation
- 4. Sum memory
- 5. Target value of a component (defined in parameter 04 Formula)
- 6. Data of a component (defined in parameter 04 Formula)
- 7. Number of added components

Operator	indication			
 ⇒ Call up operating mode "M7 Formulation" (see chapter 8.1) ⇒ Press → -key 	10/11/01 Mode 13:47:56 M0 Basic weighing . M1 Parts counting . M2 Checkweighing . M3 Filling . M4 Percent . M5 Animal weighing . M6 Density . M7 Formulation			
01 – 07 Parameter selection				
⇒ Use the cursor (►) to select parameter "01 - 07"	Formulation setup M7 ▶ 01 Hints ▶ OFF 02 Auto. print OFF 03 Number of item 1 04 Formula 1 05 Formula printout 06 06 Statistics OFF 07 Run 0FF			

⇒ Press the a -k			
01 Hints	on	Data of the individual components of a formula are shown in the display	$\begin{tabular}{ c c c c c c c c c c c c c c c c c c c$
	off	Setting for generating a mixture by means of weighing	IC=0 SUM=0.0000 0.00000 g 0% 100%
02 Autoprint	on off	Autom. data output No automatic data output	
03 Number of iter	ns	Number of components (1 to 20)	
04 Formula		The formula is entered in the sub-menu (designation max 10 characters and quantity)	Formulation setup Formula M7 ▶04 ▶ 01 BBBB 01 1.5000 g 02 IBBB 02 0.4520 g 03 ► CCCC 03 1.0032 g 1 19 AAAA 49 0.0015 g 20 IAAAA 50 2.0300 g
05 Printout 06 Statistics 07 Run		Printout of formula Combination with statistics Call up of formulation mode	
⇒ Use the arrow keys to activate/deactivate parameters, confirm your selection pressing the → -key			
⇒ Use the cursor (►) to select "05 Run".Confirm by pressing the 3 -key. The balance is now in formulation mode.		$\begin{tabular}{ c c c c c c c c c c c c c c c c c c c$	
⇒ Now you can begin adding on the various components of a mixture:			
⇒ Press the → -key; return to menu			
Generating a mixture according to a defined formula			
If you are using a weighing container use the a -key for taring		$\begin{tabular}{ c c c c c c c c c c c c c c c c c c c$	

⇔	Add on component 1, see target value (WGH) on the display	$\begin{bmatrix} 20.01.05 & \text{Formulation} & 13:47.56 \\ 00\% & \text{Item} & \text{WGH=10.000} \\ 10\% & \text{SUM=0.0001} \\ 0\% & \text{Item} & \text{SUM=0.0001} \\ 0\% & \text{Item} & \text{Item} \\ 0\% & \text{Item} & \text{Item} & \text{Item} \\ 100\% & \text{Item} & \text{Item} & \text{Item} \\ 100\% & \text{Item} & \text{Item} & \text{Item} & \text{Item} \\ 100\% & \text{Item} & \text{Item} & \text{Item} & \text{Item} \\ 100\% & \text{Item} & \text{Item} & \text{Item} & \text{Item} \\ 100\% & \text{Item} & I$
⇔	As soon as the measuring value is stable press the key; component 1 is saved; the display shows the target value component 2 (WGH), the sum of the saved components (SUM), as well as the number if the components already added (IC)	20.01.05 Formulation 13:47:56 90% 110% Item WGH=20.000 90% SUM=10.001 SUM=10.001 0% 0% 90% 00% 100%
⇔	Add on component 2, see target value (WGH) on the display	
⇔	Repeat these two steps until you have added on all components.	
Ŷ	Press Hey	24.01.05 Formulation 13:47:56 Formula finished To continue (Units) 1099.024 g
Û	Confirm completion of the mixture with the -key	
⇔	Press the 🖨 -key; return to menu	
Ge	enerating a mixture by adding on	
⇔	Parameter selection:01 Hintsoff02 Printouton – Formula printout04 FormulaPress 🖾 -key	IC=0 SUM=0.0000 g 0%100%
⇒	If you are using a weighing container use the -key for taring	
⇔	Add on component 1	IC=0 SUM=0.0000 0% 100%
\hat{T}	As soon as the measuring value is stable actuate the -key; component 1 is saved, the display shows the sum of the saved components (SUM), as well as the number if the components already added (IC) The weight display returns to zero.	IC=1 SUM=10.002 0%100% 1100%

① ①	Add on component 2; as soon as the measuring value is stable actuate the 🐨 -key Repeat this step until you have added all components.	IC=5 SUM=120.021 0% 100%
介 介	Confirm adding of the last component with the -key Confirm completion of the mixture with the -key	24.01.05 Formulation 13:47:56 Form u la fin is hed To continue (Units) To continue (Units) 120.021 g 0%
⇔	Press the 🖆 -key; return to menu	

Example for a data output (standard printout)

Key	Indication	GLP Parameters		Data output
PRINT SET	Endedor Receptur Endedor Receptur Um fortusetten (Units) 30.0002 g	P2 03printout of time P2 04printout of date P2 05user's printout P2 06printout of design P2 07printout Id P2 08printout of calibration	0:no 0:no 0:no 0:no 0:no 0:no	1 10.000 g 2 10.000 g 3 10.002 g
	Endedor Receiver Endedor Receiver automotivestica (units) 30.002 g esc	P2 03printout of time P2 04printout of date P2 05 user's printout P2 06printout of design P2 07printout Id P2 08printout of calibration	1:yes 1:yes 1:yes 1:yes 1:yes	Date: 16/01/2004 Time 13:12:30 User: Mustermann Project: xxxxx Balance: :1111111 Last adjustment:

8.1.9 Statistics

The Statistical function is possible for display values in g, pieces or %. By actuating the 🖼 -key the currently displayed value is saved for the statistics. **Overview of display:**



- 1. Present weight of sample
- 2. Number of all weight proc.
- 3. Total of all weight values
- 4. Average value
- 5. Smallest value
- 6. Largest value
- 7. Difference Max-Min

$$\sqrt{n\sum_{x}x^2-\left(\sum_{x}x\right)^2}$$

- 8. Standard deviation SDV: $\bigvee n(n-1)$
- 9. Variance RDV: (SDV / average) * 100%)
- 10. Weighing unit
- 11. Mode of operation

Operator	indication		
 ⇒ Call up operatir 8.1) 	Call up operating mode " M8 Statistics " (see chapter 8.1)		
⇔ .Press 🚡 -key	,	M4 Percent M5 Animal weighing M6 Density M7 F Statistics	
01 – 08 Paramete	r selection		
⇒ Use the cursor	⇒ Use the cursor (►) to select parameter "01 - 08"		
\Rightarrow Press the 🖨 -k	ey; the current menu item blinks.		
01 Clear 02 Sum 03 Mean 04 Min 05 Max 06 Difference 07 Stand. Devi. 08 Factor varianc 09 Run	Delete data Sum of all Weighings Rated value Minimum Maximum Difference min/max Standard Deviation e Variance Enter statistics mode		

ALT-BA-defsi-0410

₽	Use the arrow keys to activate/deactivate parameters, confirm your selection pressing the 🐷 key		
Ŷ	Press the 🖾 -key; the balance is now in statistics mode.	10/11/01 N=0 MIN=0.0000 SDV=0.0000 0%	Statistics 13:47:56 SUM=0.0000 X=0.0000 MAX=0.0000 D=0.0000 RDV=0.0000 0.0000 g
⇔	Use the 🖙 -key to print your statistic values on a connected printer	Prinout: N : SUM : X : Min : MAX : D : SDV : RDV :	5 169,6880 g 33,9376 g 0,0000 g 100,0012 g 100,0012 g 42,2166 g 124,4%
Pr	ess the 🖨 -key; return to menu		

Example for a data output during a measuring sequence:

Key	Indication	GLP Parameters	Data output
PRINT SET	27.1.05 Statistik 13:47:56 N=3 SUM=150.0304 X=50.0101 MIN=50.0099 MAX=50.0104 D=0.0005 SDV=0.0003 RDV=0.1 50.0099 g 0% 110% 100% 100%	P2 03 time printout0: noP2 04 date printout0: noP2 05 user printout.0: noP2 06 project printout.0: noP2 07 printout Id0: noP2 08 Cal printout.0: no	3 50.0099 g
PRINT SET ¢J	Image: 27.4.05 Statistik 13:47:56 N=3 SUM=150.0304 X=50.0101 MIN=50.0099 MAX=50.0104 D=0.0005 SDV=0.0003 RDV=0.1 50.0099 g 0% 100% 100%	P2 03 time printout1: yesP2 04 date printout1: yesP2 05 user printout.1: yesP2 06 project printout1: yesP2 07 printout Id1: yesP2 08 Cal printout.1: yes	Date: 16/01/2004 Time 13:12:30 User: Mustermann Project: xxxxx Weight: : 1111111 Last adjustment:
	27.1.05 Statistik 13:47:56 N=3 SUM=150.0304 X=50.0101 MIN=50.0099 MAX=50.0104 D=0.0005 SDV=0.0003 RDV=0.1 50.0099 g 0% 100% 100%		N : 3 SUM : 150.0304 g X X : 50.0101 g Min : 50.0099 g MAX : : 50.0104 g D : 0.0005 g SDV : 0.0003 g RDV : 0.01 %

9 Data output

9.1 Tecnical data

- 8 Data bits
- Baud rate selectable at 2400, 4800, 9600 and 19200 Baud
- Miniature plug necessary (9 pol D-Sub)
- For operation with interface faultless operation is ensured only with the respective KERN- interface cable (max. 2m)

9.2 Pin allocation of the balance exit plug (front view)



Pin 2: Pin 3:	Rxd Txd
Pin 4:	
Pin 5. Pin 6:	GND Tara
Pin 7:	RTS
Pin 8:	CTS
Pin 9:	Print

9.3 Remote commands

Commands	function
R CR LF	Reset to factory setting – reset
PC CR LF	Command to call up the values of the balance
S CR LF	Measuring value stable
SI CR LF	Measuring value instable
SU CR LF	Last stable measuring value
SUI CR LF	Current measuring value
Z CR LF	Zeroing stable value
ZI CR LF	Zeroing instable value
T CR LF	Taring stable value
TI CR LF	Taring instable value
C0 CR LF	Cancel continuous data output
C1 CR LF	Start continuous data output
CU0 CR LF	Cancel continuous data output (operating mode)
CU1 CR LF	Start continuous data output (operating mode)
NB CR LF	Serial no. of balance
FS CR LF	Weighing range max.
RV CR LF	Software issue
PD CR LF	Date display
PD CR LF	Time display
PMCR LF	Mode of operation
PS CR LF	Balance parameters are printed out
B CR LF	Keytone
ER CR LF	Call up error message
DS CR LF	Display check
CS CR LF	Delete display check
DH CR LF	Display check header
CH CR LF	Delete display check header
DF CR LF	Display check bar graph (footer)
CF CR LF	Delete display check bar graph (footer)
CL CR LF	Start internal adjustment from outside
KL CR LF	Lock keyboard
KU CR LF	Unlock keyboard
E0 CR LF	Keytone off
E1 CR LF	Keytone on
O0 CR LF	Balance off
O1 CR LF	Balance on
A0 CR LF	Auto zero off
A1 CR LF	Auto zero on
TC0 CR LF	Automatic adjustment off
TC1 CR LF	Automatic adjustment on

10 Maintenance, upkeep, disposal

10.1 Cleaning

Please disconnect the device from the operating voltage before cleaning.

Only use a cloth dampened with mild suds and not aggressive cleaning agents (solvents or similar). Please ensure that fluids are not able to get into the device and rub off using a clean, soft cloth.

Loose sample residue/powder can be removed carefully using a brush or hand vacuum cleaner.

Remove any spilt material to be weighed immediately.

10.2 Maintenance, upkeep

The device may only be opened by trained service engineers authorised by KERN. Disconnect from the mains supply before opening.

10.3 Disposal

The operating company shall dispose of the packaging and the device in compliance with the valid national or regional law of the operating location.

11 Troubleshooting

The balance should be switched off for a short time following an interruption in the programme sequence and disconnected from the mains supply. It is then necessary to repeat the weighing process from the beginning.

Help: <i>Malfunction</i>	Possible cause
Weight display is not illuminated.	• The balance is not switched on.
	• The mains supply connection has been interrupted (mains cable not plugged in/faulty).
	• Power supply interrupted.
	Batteries are inserted incorrectly or empty
	• There are no batteries inserted.
The weight display changes continually	Draught/air movement
	Table/floor vibrations
	 Weighing plate has contact with other objects. Electromagnetic fields / static charging (choose different location/switch off interfering device if possible)
The weighing result is obviously wrong	• The display of the balance is not at zero
	Adjustment is no longer correct.
	 Great fluctuations in temperature. Electromagnetic fields / static charging (choose

different location/switch off interfering device if possible)

Switch the balance off if other error messages should appear and then switch on again. If error message persists, inform manufacturer.