Operating instruction

Instruction number LMI-29-02/06/08/ENG

Analytical balances **AS/X series**





MANUFACTURER OF ELECTRONIC WEIGHING INSTRUMENTS

RADWAG 26 – 600 Radom, Bracka 28 Street, POLAND phone +48 48 38 48 800, phone/fax. +48 48 385 00 10 Sales Department +48 48 366 80 06

www.radwag.com

JUNE 2008

Contents


1.	UNWRAPING THE BALANCE	5
	1.1. The balance AS/X	5
2.	START THE BALANCE UP	6
	2.1. Conditions of proper usage	6
	2.2. Set level up	6
	2.3. Warming up	6
3.	APPROPRATION	7
4.	DESCRIPTION OF THE BALANCE - display	8
	4.1. Keyboard	9
	4.2. Connections	
5.	USER MENU	10
	5.1. Move in user menu	13
	5.1.1. The balance keyboard	
	5.1.2. Return to weighing function	
	5.1.3. PS computer keyboard	
	5.1.4. By means of virtual keyboard through RS 232	
	5.2. User menu	
6.		
	6.1. Log-in function	18
7.		
	7.1. Automatic balance calibration	
	7.2. Calibration test	
	7.3. Manual calibration	
	7.3.1. Internal calibration	
	7.3.2. External calibration	
	7.3.4. Calibration report printout	
8.		
9.		
10		
	10.1. Setting filter	
	10.2. Value release	
	10.4. Set une display refreshing time	
	10.5. Last digit	
	10.6. Negative	
11	5	
12		
	1 1 1 1 0 0 0 0 0 0	

13. ACC	ESS TO MASS UNITS	33
14. SET	FING ACCESSIBILITY OF THE WORK MODES	34
15. OTH	ER PARAMETERS	34
	IG WORK MODES	
16.1.	Countign pieces of the same mass	36
16.1.1.	Counting pieces after writing piece mass	
16.1.2.	Counting through determine singular element mass from the	
	rd batch	
16.1.3.	Select piece from date base	
16.2.	Checkweighing	
16.3.	Filling	
16.4.	Percents	
16.5.	Weighing animals	
16.6.	Density of solids and liquids	
16.6.1.	Density of liquids	
16.6.2.	Density of solids	
16.7. 16.8.	Formulation Statistics	
	OS OF PRINTOUTS	
17.1.	Standard printout	
17.2.	Non-standard printout	
17.2.1.	Texts	
17.2.2. 17.2.3.	Composing texts by Edition function	
	Select non-standard printouts	
	PERATION WITH PRINTER OR COMPUTER	
18.1.	Connections	
19. COO	PERATION WITH LABEL PRINTERS CITIZEN CLP-521	65
20. WEI	GHING LOADS UNDER THE BALANCE	70
21. CON	NECTING ADDITIONAL KEYS	71
22. LIST	OF COMMUNICATIONS COMPUTER - BALANCE	71
23. TEC	HNICAL PARAMETERS	74
24. COM	MANDS ABOUT FRRORS	74

1. UNWRAPING THE BALANCE

1.1. The balance AS/X

Cut safety tape off. Take balance off the box. Take all necessary to correct performance of balance elements off the box. After replace balance in place of use put scale and rest of elements on.



- open side doors of weighing chamber.
- inside the chamber place lower shield of weighing chamber (1),
- inside the chamber place antibreeze shield (2),
- put centring ring on the shield (3),
- put the balance pan inside the ring (4),
- close side doors of weighing chamber,
- turn on balance supply,
- pin of power adaptor should be connected to socket in the back of balance casing.

. Draw 1. The components installation for the WAS X balance with d=0,1mg

The balance is supplied through power pack 230 V AC / 11 V AC. Power pack socket is at the rear of the balance.

2. START THE BALANCE UP

2.1. Conditions of proper usage

- Set the balance on stable table, far from vibrations
- The balance should be replaced far from draughts and air breeze.
- The balance should be in stable temperature and humidity room
- The balance should be replaced far from sources of
- Temperature in the room $+18^{\circ} \text{C} \div +30^{\circ} \text{C}$ (AS /X)
- If the static electricity has influence on the balance indications it base should be earthed. Earthing screw is in the rear part of the balance base.
- The balance should be replaced in leveled position

2.2. Set level up

2.3.

The balance should be leveled. The correct leveling is shown on the level indication installed at rear of the balance.





Warming up

Before measurements user should wait untill the balance reaches temperature stabilization. It is warming up time.

For analytical balances warming-up time is about 1 hour.

This periods refers to the balances which ware in surrounding temperature (work) before start weighing.


If the analytical balances are kept in lower temperature before weighing the warming-up time is about 8 hours and for precision balances it is about 2 hours.

During warm-up stabilization the indications can change.

3. APPROPRATION

The balances are used to do precise measurements in laboratories. It is possible to do the zero function in all measure range.

The balance weights in following units:



Draw 2. Measure units

Apart from weighing in various measure units the balance also:

- counts pieces
- weights
- dosages
- determines deviations of the standard mass
- weights animals
- determines liquids and solids density
- formulation
- creates statistics

Measure units and particular functions can be inaccessible for user. It is possible to adapt the balance to individual needs and access functions and units which are necessary at this moment.

It is possible to define accessible or noo-accessible in user menu and it is described in further part of the manual.


4. DESCRIPTION OF THE BALANCE - display



Draw 3. Display balance

- 1. load mass and quantity of pieces
- 2. measure unit
- 3. the result is stable
- 4. line of max range of the balance
- 5. work mode
- 6. date
- 7. time
- 8. precise ZERO


4.1. Keyboard



Each key is dual-function key. Particular function can be done through. User also can move in the balance menu.

Φ	Switches the display off. ON/OFF key.
F	Function key. F key.
Mode	Selects the work mode. MODE key.
Units	Changes measure units. UNITS key.
4	Sends information to external instrument (PRINT) or confirms parameter value or function (ENTER). PRINT/ENTER Key.
Esc +0/T+	Sets indication to zero. Esc/TARA Key.
Cal	Calibration
Setup	Menu of balances
	Navigation bar

4.2. Connections



Draw 4. Sockets of the WPX balance

P1 Calibration

- 1. power adapter socket
- 2. PS keyboard connector
- 3. RS 232 port
- 4. additional display socket

5. USER MENU

There are 9 groups in user menu. Each group is named by P letter. Name and contents of each group is presented below.

P1 Calibration			
01	Int. calibr	* * * * * * * * function	
02	Ext. calibr	* * * * * * * * function	
03	User calibr	* * * * * * * * function	
04	Calibr test	* * * * * * * * function	
05	Weight corr.	0.0	
06	Auto calibr	3 both	
07	Auto cal time	3 3 hours	
80	Print report	1 on	
P2 GLF)		
01	User	Nowak Jan	
02	Project	AR – 65/04	
03	Time print	0 off	
04	Date prin	0 off	
05	User print	0 off	
06	Project print	0 off	
07	ld print	0 off	
80	Last cal print	0 off	
P3 Date	/Time		
01	Date format	0 DA/MO/YR	
02	Time format	0 24 hours	
03	Time	* * * * * * * Function	
04	Date	* * * * * * * Function	
05	Disp. time	1 on	
06	Disp. date	j 1 on	

P4	Readout			
	01	Filter	!	normal
	02 03	Value relase	•	fast + rel
	03	Disp. Refresh Autozero	•	0.1 s on
		Last digit	!	always
	06	Negative		disabled
			·	<u> </u>
P5	RS - 01	Baud rate	. 1	1 4900
	02	Parity	•	4800 none
	03	Data bits		8 bits
	04	Stop bits		1 bit
	05	Handsake		none
	06	Auto print		none
	07	Interval	j 1	* 0.1 s
	80	Min. mass	j 4	10 d
	09	Print on stab		enabled
	10	Printer type	:	Epson /Standard
	11	Cut paper	0	no
P6	Prin	tout		
	01	Printout No.	•	standard
	02	Pr. 1 start] 1	
	03	1	1	•
	04	Pr. 2 start	1]]
	 10	Pr. Edit	 *****	। function
	11	String 1	į	
	 89	String 80	 	
	units		•	•
Ε/	01	• Grams	1 1	enabled
	02	Miligrams		l enabled
	03	Carats	•	enabled
	04	Pounds	•	disabled
	05	Ounces	j o	disabled
	06	Ounces troy	0	disabled
	07	Dwt	•	disabled
	80	Taele Hk.	•	disabled
	09	Taele S.		disabled
	10	Taele T.		disabled
	11 12	Momms Grains	•	disabled disabled
	13	Newtons		disabled disabled
	14	Ticaal	•	disabled disabled
	15	Custom	•	disabled disabled
	16	Custom factor	į ĭ	
			•	•

P8 Work modes

01	Parts count		1	enabled
02	Checkweighing		1	enabled
03	Filling	ĺ	1	enabled
04	Percent	į	1	enabled
05	Animal	į	1	enabled
06	Density	į	1	enabled
07	Formulation	İ	1	j enabled
80	Statistics	į	1	enabled

P9 Globals


01	ID setting	* * * * * * *	function
02	ID autoprint	0	off
03	Веер	1	enabled
04	Language	1	english
05	Backlight	1	on
06	Contrast	* * * * * * * *	function
07	Screensaver	0	enabled
80	Temperature	* * * * * * * *	function
09	Balance Id	114493	
10	Software rev.	MBa.a 23	
11	Par. printout	* * * * * * * *	function
12	Par. Receive	* * * * * * *	function
13	Passwd prot.	*****	function

Parameters in user menu are:

- functional for particular activity eg. the balance calibration
- selectable selects one of few values from the balance memory
- noted changes sets in the balance memory eg. Date, time, user number, texts

Menu - graphic version

Press the **SETUP** key to display main menu of the balance (display I). Select the submenu whose contents is displayed after pressing the **RIGHT ARROW** key (display II).



Draw 5. Menu

- 1 main menu number
- 2 indication of the function selection
- 3 function name
- 4 currently used function
- 5 submenu number
- 6 submenu name
- 7 attribute of the menu
- 8 value of the attribute

5.1. Move in user menu

User moves in the menu by

- the balance keyboard
- PS keyboard,
- Communicates from computer to the balance

5.1.1. The balance keyboard

enter main menu

move down in the menu

move up in the menu

selects submenu which is activated. Submenu contents is presented on the display


move one level up to main menu

Resignation parameter changing

5.1.2. Return to weighing function



Introduced changes are recorded after return to weighing mode and confirm changes. Press the ESC key many times. If following question appears on the display press: ENTER – confirm or ESC – cancel



Draw 6. Return to weighing

5.1.3. PS computer keyboard

Each key on the balance keyboard has its equvivalent on the PS keyboard:


- for functions

	Description	keyboard
Switch on/off the balance display		Ф
Move to the balance menu Setup		Setup
Selects work mode		Mode
Selects measure unit		Units
F5	PRINT	1 ®
F6	TARE	Esc +0/T+

- for direction keys

t	Move up	A
-	Move to level up	•
	Sets selected parameter	•
1	Move down	•

- for ENTER / PRINT keys and ESC




5.1.4. By means of virtual keyboard through RS 232

Most of the functions are done by the balance desk or PS keyboard. They are aslo done by sending orders computer – balance.

This commands enables to move in the balance manu and control the balance work. The list of the commands is at the end of the manual.

5.2. User menu

The menu is presented in p. 5. Press the F key in weighing level. Main menu is presented on the display. Select the submenu which is modificated.




Draw 7. Main menu – submenu selection

If the menu is modificated press the **RIGHT ARROW** key. Selected menu appears on the display. Select what will be changed in this submenu (activate). Select through keys presented on the Draw above. Press the **RIGHT ARROW** key.

Reaction of the balance:

- Activity of the balance (eg. the balance calibration) is done for submenu described as Function
- Attribute activation for submenu which is indicated (digit flashing means the value can be changed and some signs can be written)



Draw 8. Tthe balance submenu

6. WEIGHING

Following conditions must be fulfilled to get reliable results:

- Stable temperature
- Stable ground
- Proper parameters for external conditions
- Before measurements or for essential changes of the external conditions (if the temperature changes more than 1°C/h) calibrate the balance in accordance with p. 7.1.
- Before measurements load the pan and check if the balance show "precise zero" displayed →0 ← in down left corner of the display (only if the parameter P4 06 Autozero has the value 1: yes) and check if the measurement is stable ► is displayed in right up corner of the display. If the balance does not show zero press the key



- If the conditions are unfavourable (no stable result) lines appear on the display. After settled time the balance returns to weighing mode without set up to zero. In this case wait untill the conditions stabilize and press **Esc** again
- By the **Units** key select measure unit. Put the load on the pan and after stabilization read out the result. If measure unit user wants to use is not displayed during pressing the **Units** key check if it has access attribute.
- The indication can be set to zero many times. Sum of loads noted in the balance memory cannot be higher than max capacity.
- Betwenn following measurements do not unpluged the balance.
 The balance should be switched off by the **ON/OFF** key. After pressing the key again the balance is ready to work without warm stabilization.

6.1. Log-in function

The operator has own access code to internal menu. The password system is defined by administrator. Password can contain max 6 digits.


The balance program enables to declare:

- One administrator who is authorised to use all sets and programme functions, change the passwords – own and user
- One user who is authorised to sets and the balance functions determined by administrator

Setting password and access authorization

- After set the password and access parameters (parameter P9 13 Password protection) write the password for administrator
- If the admistrator password is different from "0" the program wants administrator password during enter for the parameter P9 13 Password protection.
- Every enter this parameter the software demands administrator password, after writting correct password it is possible to set the parameter P9 13 Password protection
- Dependly on setting the password is shown as digits or stars (start value each digit = 0)

According to p. 5.1.1 of the manual enter the menu P9 Globals



Draw 9. Password – activation the function

15.03.04	Setup		13:49:18
	Administrator	▶ 0	
	User	0	
	Start	Νo	
	Mode	Νo	
	Setup	Νo	
	Cal+GLP only	Νo	
	Asterisk	Νo	

Draw 9-1. Menu password protection

Administrator

line to write administrator who has access to all set up

User

line to write user password. User who has access to setting with NO attribute (are not protected by password)

- Start up

If it is settled on YES during start the balance up user must write access password (administrator or user)

- Functions

If it is settled on NO (not protected by password) user can use implemented functions in the balance.

- Set up

If it is set up on NO (not protected by password) user can change setting in the balance

- Only Kal+GLP

If it is set up on YES user can perform the calibration and calibration report


- Stars

If it is settled on YES during start the balance up password is hidden under starts

Administrator password

Write the password for administrator (max 6 digits) and user. Each admistrator has access to all functions in the balance. User has access to balance possibilities in accordance with above description. Please, remember the password. If you set YES for "Start up" function the password must be writen after switch the balance on. If the password is not correct using the balance is not possible.

To write the password in use keys described on the drawing 2. or PS/2 keyboard (it can be connected to the balance port). Set up the attributes for other options dependly on authorizations for user.



Draw 10. The keys – introducing the values in the menu

7. BALANCE CALIBRATION

To ensure high precision of weighing corrective factor in relation to standard mass must be noted in the balance memory periodicaly – it is the balance calibration.

Calibration should be performed when:

- The weighing is started,
- Long breaks are between following measure series
- Temperature inside the balance changes more than: 0,8°C

Kind of calibration:

- Internal automatic calibration
 - * started if temperature changes, started if the time changes
- Manual internal calibration
 - * started by the balance keyboard
- Calibration made with external weight
 - * with declared mass which cannot be modificated
 * with any mass which should be given before the calibration
 - process

In verified balances only automatic internal calibration and manual internal calibration is accessible.




Perform the calibration when there is no load on the pan!

7.1. Automatic balance calibration

It is performed when:

- Period of time passes from last calibration
- temperature changes for settled value by manufacturer
 - * for balances is 0,8°C,


Following information appears on the display:



Draw 11. automatic calibration – display

Time delay in starting the calibration up enables user to yese load off the pan untill the measurements are performed. If the T/O key is pressed the calibration process is stopped.

Set up automatic calibartion



Draw 12. Set up automatic balance calibration

- 1 main menu number
- 2 function selection factor
- 3 function name
- 4 name of actual activity
- 5 selects factor to autocalibration (time / temp.)
- 6 declaring autocalibration time
- 7 value of factors for autocalibration
- 8 value of time for autocalibration

if the values for factor and autocalibration time also descriptions for tchem changes (on the drawing field No 9. and No 10.)

01 Internal calibration

Start internal calibration process, the process is automaticaly without operator interference, if there is load on the pan the display shows order to remove the load

02 External calibration

calibration performed by external mass, its value is recorded in factory menu, function inadmissible in verified balances

03 User calibration

calibration performed with any mass which must be introduced before the calibration, function inadmissible in verified balances

04 Calibration test

comparison internal calibration mass with its value recorded in the balance memory

05 Weight code

correct value of internal calibration mass, function inadmissible in verified balances

06 Automatic calibration

determine factor which decides about start automatic internal calibration

- 0 non non of the factors causes start of the calibration
- 1 time calibration in relation to time determined in p. 07
- 2 temperature calibration in relation to changes of surroundign temperature
- 3 both calibration in relation to changes of time and temperature

07 Automatic calibration time

Determination of time automatic calibration starts up


Return to weighing



The changes are recorded when the balance returns to weighing mode with the recording the changes. Press the ESC many times. Following question appears on the display. Select one of the options: ENTER – record / ESC – cancell (see. Draw 9. Return to weighing p. 5.1.2. Return to weighing)

7.2. Calibration test

Internal calibration mass is compared to its value in the balance memory. This preocess is automatic. Its result is shown on the display.



Draw 13. The calibration test

Cal. – value of internal calibration mass

Act. – result of weighing internal calibration mass

Dif – difference between two values

Return to weighing



Changes are recorded only after return to weighing mode and confirmation the changes. Press the ESC key many times. Following question appears on the display. Select one of the options: ENTER – confirmation / ESC – cancel. (see. drawing. 9. Return to weighing. p.. 5.1.2. Return to weighing)

7.3. Manual calibration

7.3.1. Internal calibration

- 1. Enter submenu P1 Calibration.
- 2. Select the function 01 Internal calibration.
- Press the RIGHT ARROW key.
- 4. The balance performs the calibration automatically. During this calibration do not load the pan.
- 5. After this process the balance records results of the calibartion in the memory and returns to weighing mode.
- Pressing the ESC key stops the calibration process
- If during the calibration load is on the pan display show order about error. The calibration process is stopped.
 After take load off the calibration process is finished.
 If the function DRH is active user cannot stop the internal calibration process.

7.3.2. External calibration

The external calibration should be performed with external mass class:

- E₂ – for balances AS/X

List of weights for separate balances is included in technical specification in the final part of the manual.

- Move to submenu P1 Calibration.
- 2. Select the function 02 external calibration
- 3. Press the **RIGHT ARROW** key.
- 4. Order to yese the load off the pan appears on the display (no load on the pan). After yesing load off the pan press the ENTER key.
- 5. The balance determines mass of empty pan

- 6. Put load and press the ENTER
- After the calibration the balance returns to submenu P1 -Calibration
- 8. Return to weighing as in the point 5.1.2.




If the function DRH is active user cannot perform the external calibration process. Function DRH is active in verified balances.

7.3.3. Calibration performed by user

Calibration performed by user with aby external weight class:

- E₂ for balances AS/X
- Enter menu group P1 Calibration. Select the parameter 03 user calibration
- Press the RIGHT ARROW key. The balance displays order to note calibration mass. The first digit flashes and it can be changed.



Draw 14. User calibration – declaring value of weight

- Record new external mass by functional keys (in accordance with p. 5.1.1 of the manual)
- Confirm the mass. The balance starts calibration and shows orders on the display.
- The balance determines mass of empty pan and shows order to put this mass
- After put the weight on the pan confirm by the Enter.
- After this procedure balance returns to menu to group P1 Calibration.
- In accordance with previous point start weighing mode.



It is recomended to select external calibration mass as its mass would be about 3/4 of max balance capacity.



If the DRH function is active user cannot perform the external calibration process.

7.3.4. Calibration report printout

After calibration user can reveice the calibration report. The report can be printed on connected printer and sent to computer or recorded in file.


P1 08 Report printout: 1: yes – report is printed
P1 08 Report printout: 0: no – report is not printed

If the parameter has the value 1 the report is genrated and sent automaticaly.

15.0	3.04		Setup	
P1 ▶	02	Ext. calibr.		function
	03	User calibr	********	function
	04	Calibr. test		function
	05	Weight corr.	0.0	
	06	Auto calibr.	j 3j	both
	07	Auto cal. time	j 3j	3 hours
	08 ▶	Print report	j 1j	on

Draw 15. Submenu calibration

A content of report depends on setting in submenu GLP. All options with YES attribute are printed.



Draw 16. Submenu GLP - setting

Apart from information settled in menu group the report contains: calibration mass remembered by balance after last calibration (description Old:), calibration mass determined during actual calibration (description: Calibration) and deviation of the calibration (description Deviation:) – difference between these two masses.

*** Internal calibration report ***

Date : 16/04/2004

Time : 15:24:39

Balance Id : 114493

Calibr : 891.9[3] g

Old : 891.9[4] g

Difference : - 0.0[1] g

User Id: Nowak

Project Id : AKY-54

Name

Draw 17. Example of balance calibration report

8. SETTING PRINTOUTS FOR GLP PROCEDURES

P2 GLP is group of the parameters which declares factors on the calibration printout. For fields:

- user (max 8 alphanumerical signs)
- design (max 8 alphanumerical signs)


introduce names by the balance keyboard or the PS/2 keyboard. For the rest select:

- 1 no (do not print during report)
- 0 yes (print during report)

Main view of the GLP submenu is presented on drawing 19, page 24. If you use the PS/2 keyboard see what dipendences are between the balance keyboard and PS/2 keyboard (p. 5.1.2)

9. SETTING TIME AND DATE

The balance has real time clock whose parameters can be modificated. Enter the menu group P3 Date/Time as it is show below:



Draw 18. Submenu Date / Time

01 Date form

There are two possibilities:

- 1 format date Month/Dav/Year
- 0 format date Dav/Month/Year

After selection proper value confirm by the ENTER key.

02 Time form


There are two possibilities:

time form 12 h 1 time form 24 h 0

After selection press the ENTER to confirm. 12 h form is distinguished by the letters PM or AM on the printouts.


03 Time

Enter setting the parameter 03 Time by the RIGHT ARROW key in accordance with below scheme.



Draw 19. Submenu / Time - setting time

Replace the marker next to the value which will be changed (Hour, Minute, Second). Confirm with the RIGHT ARROW key. Change the numerical values with Mode and Units keys.



select / hours / minutes / seconds

Draw 20. Submenu Date / Time - setting time - steering keys


Confirm settled value (last change digit stops flashing)

Repeat above activities for following values. After setting new values for time press the ENTER key. The balance returns to submenu P3 Date/Time and displayed time changes.

After setting time return to weighing mode in accordance to p. 5.1.1 of the manual.

04 Date

Set the parameter 04 Date with the **RIGHT ARROW** key. In accordance with previous description (03 Time) set actual date. After setting date return to weighing mode as it is presented in p. 5.1.2 of the manual.



Draw 21. Submenu Date / Time - setting date

05 Display time

for the value 1 - YES on top graph time is displayed, for the value 0 - NO, time is not displayed.

05 Display date


For the value 1 - YES date is displayed on top graph, for the value 0 - NO, date is not displayed.

Return to weighing

(see Draw. 9. - 5.1.2. - Return to weighing)

10. SETTING THE PARAMETERS

User can adjust the balance to existing conditions (filter) and own needs (autozero, displaying last digit) by means of parameters in group <P4 Readout>.



10.1. Setting filter

Dependly on conditions set the filter. If the conditions are conductive set the filter as very fast (value of the parameter 01 Filter 1) and if the conditions are bad (vibrations, draught) set the filter as slowly or very slowly (value of the parameter 01 Filtr at 4 or 5). Efficience of filter is different for range of weighing. The filter works slowler during getting to weighed mass. It works faster when mass is the settled filer range (parameter filter range accessed only from service menu – user does not have acess).

10.2. Value release

Select and set way for stability result of weighing: fast, fast +reliable or reliable.

10.3. Set the display refreshing time

This parameter determines period of time which the display refreshes in. Information on the display is compared to information which is sent by the balance processor about load on the pan.

For higher values of the refreshing parameter indirect not stable mass indications are not presented on the display during puttin on and yesing off the load. For low values all changes in mass during weighing are visible – it enables to dosage liquids and solids. The refreshing time is settled in seconds.

10.4. Set autozero working

To ensure precise indications programmable function "AUTOZERO" is in the balance. This function controls automatically and corrects zero indication of the balance.

If the function is active following results in declared periods of time are compared eg. each 1s. If these results differs at less value than declared range AUTOZERA eg. 1 interval the balance sets to zero automatically and \rightarrow **0** \leftarrow appears on the display.

If the AUTOZERO function is active each measurement starts at precise zero every time. In special cases this function disturbes in the measurements eg. when the load is put on the pan very slowly (pouring substance). In this case correcting system of zero indication can correct also indication of real load mass. AUTOZERA is switched on anr off in the parameter P4 03 in accordance with p. 5.1.1 of the manual. 15.5. Displaying last digit

b. Displaying last digit

10.5. Last digit

To ensure komfort of work with the balance user determines (dependly on needs) if last digit should be displayed and when. One of the following values can be selected:


- 0 never
- 1 always
- 2 when stab

10.6. Negative

This function is designed for changes of displaying.

11. FUNCTIONS IN USING RS 232 PORT

User can set the parameters necessary for correct comunication balance with computer or printer.



Parameter No and name	Parameter No and name
01 Baud rate: 0 : 2400; 1 : 4800; 2 : 9600; 3 : 19200	O7 Interval Interval it is defined how often balance sends indications through RS 232 port. It is counted on base on form for the parameter x 0.1 s = time yestu-interval). Value from 1 to 9999 can be written.
02 Parity: 0 : no; 1 : see; 2 : dont see	08 Min. mass
03 Date bits : 1 : 7 bits; 2 : 8 bits	09 Print on stab 0 : no; 1 : yes
04 Stop bits 1 : 1 bit; 2 : 2 bits	10 Printer type: Epson /Standard (Kafka)
05 Handsake: 0 : no; 1 : RTS/CTS; 2 : XON/XOFF	11 Cut paper: Disabled / enabled (function for printer EPSON TM-U220B or A only)
06 Auto print 0 : none; 1 : constance; 2 : with breakes; 3 : for stable.	

After setting correct values return to weighing mode as it is described in p. 5.1.2 of the manual. For value 1 : computer parameter 09 Printout to, for printouts the last digit of indication is omited.

12. PRINTOUTS

This function is used to make not standard printouts and select type of printout. Precise description for printouts is described in p.17.

13. ACCESS TO MASS UNITS

In this group of parameters user declares mass units which are accessible for operator directly under the key **Units.**


All units which value of the parameters is set up at 1: yes are accessible from the level of switching between units.

For units described as 09 Taele Hk., 10 Taele S., 11 Taele T . there are following dependences:

 If all of them have attribute 1: yes the balance show only first of them 09 Taele Hk

If the measurement is done in units 11 Taele T set the attribute 0 : no for two previous

Enter group of the parameters P7 Units according to p. 5.2.7.




Draw 24. Measure units - setting

After set proper values of the parameters return to weighing mode in accordance to p 5.1.2 of the manual.

14. SETTING ACCESSIBILITY OF THE WORK MODES

In this group of parameters user declares work modes which are accessible for operator after pressing **Mode** key.



All work modes values of the parameters are 1: yes are accessible from the level of switching between work modes. The changes of the parameters can be done according to p. 5.1.1 of the manual.

15. OTHER PARAMETERS

User can set parameters have influence on work with balance in group of the paraemeters P9 Others eg. beep signals etc. Enter submenu group P9 Others the same as in pakt. 14.

01 ID Setting

it includes 6 digits 6 codes which can be used during printouts for product specification, operator, batch etc.

02 Aut. Printout ID

for the option YES all digit codes are printed, for option NO the codes are not printed.

03 Signal

beep signal for pressing keys

04 Language

selection of languages

05 Backlight

switch on/off the backlight

06 Contrast

changes contrast – after entering this function a window appears, by means of keys on the balance contrast on the display can be changed

07 Screen server

if the screen server is switched on displayed values disappear after settled time and if displayed value of the measurement does not change.

08 Temperature

it is information about temperature which is registered by temperature sensor in the balance. Return to the menu – press the ESC key

09 The balance number


it is only information about factory number of the balance

10 The number of the program

it is information about program number of the balance

11 Printout of the parameters

if the function is active the balance parameters in user menu are printed. User gives numbers of the parameters which should be printed.



Draw 26. Submenu Others - printing setting

After confirmation parameters are printed through RS 232 port, actualy sent settled user parameters in the balance

12 The parameter reception

If the functions are activated all parameters of the balance are received through RS 232. After reception the balance informs user how many parameters are accepted, how many are changed, how many were declared incorrectly and how many were not accepted by the software. Printing and reception of the parameters is very easy and fast procedure of introducing new setting.

After printing actual parameters to file in the computer user changes the parameters very fastly and without any problems. User sends new corrected setting to the balance software. After these changes the balance accepts new set up. User must know all parameters and computer operation very well.

13 Password protection

this submenu contains options about accee password for administrator and user (see 6.1.)

16. USING WORK MODES


16.1. Countign pieces of the same mass

It can be done after write singular piece mass:

- Write singular piece mass
- Determine singular piece mass on base of standard quantity
- Element selection from date base


16.1.1. Counting pieces after writing piece mass

Start function of counting pieces (drawing No 33).



ass and press the **FNTFR** or select 07 Start and pres

Set standard mass and press the **ENTER** or select 07 Start and press the **RIGHT ARROW**. Functions to count details are activated.



Draw 28. Counting pieces - display view

APW – singular piece mass [g] WGH – all pieces mass on the pan pcs – mark for counting pieces


Return to weighing

- Press the **MODE** and display shows list of all functions

- Select **MO Weighing**, Press the **RIGHT ARROW**, display show stage of weighing


16.1.2. Counting through determine singular element mass from the standard batch

Start the procedure of counting pieces in accordance with p. 16.1.1, it does not matter which mass in the field 01. Select **07 Start** and press the key **RIGHT ARROW**. In the counting pieces function press the key **Units**. Dialog window appears on the display. Select the batch quantity (fiels 01 – 04) or write it in 05 – Standard.



Draw 29. Countimg pieces with using standard batch

Then press the **RIGHT ARROW** key and follow orders presented on the display.



Draw 30. display with AKD function

- 1- single piece mass
- 2 all elements mass
- 3 AKD (automatic correction of preciseness) function


Display shows quantity of pieces which are on the pan (10 pieces). If less than counted actualy quantity is added mass of singular piece is corrected. In this case APW = 5.2282 to 5.1837. From this moment following pieces are counted in relation to singular mass.

This way mass of singular piece can be determined on base of batch standard.

The are four conditions of AKD (Automatic Correction of Preciseness) in the balance software

- quantity of pieces (after adding) must be higher than it was previously
- 2. quantity of pieces (after adding) must be less than twice quantity which was on the display before adding
- 3. actual quantity must be in tolerance ± 0.3 of the total value,
- 4. the result must be stable.

If user decides that batch quantity is enough singular piece mass must be introduced into the balanc memory after pressing the key **RIGHT ARROW**.




Draw 31. Automatic Correction of Preciseness - record in date base

Select the field and write names of weighed elements. Press the **Enter** (record name) and **Enter** (record value). Next to name singular piece mass should be introduced. It can be remembered using 02 Recall sample

16.1.3. Select piece from date base

Active function of counting pieces as it is shown on below scheme.




Select piece form date base. Start counting pieces.

16.2. Checkweighing


The sample is weighed precisely when the limits of weighing are settled. The process is shown (side graphs) and controled.

The function activation:



Draw 33. Checkweighing - the function activation

Display



Draw 34. Checkweighing - display view

- 1 result
- 2 bargrafy
- 3 function name
- 4 difference between masyw of weighed load and middle of tolerance field

(HI/LO)

- 5 value of low (LO) and (HI) high limit
- 6 graphs which presents weighign range



Rememeber to set the parameter


02 High limit firstly. The balance program checks if the values are correct and if they are in measure range.

If settled values of the parameters are incorrect the balance shows command about error and returns to setting parameters without changes.


16.3. Filling

During dosage (pouring) load mass is filled up till the settled mass is reached. Before the procedure set the standard mass which is upper stage of the dosage.

Activation of the function



Display




- 1 mass which should be added
- 2 graphs
- 3 function name
- 4 TR reference value mass which is declared (see drawing. 39. M3 01 Reference mass)
- 5 WGH mass on the pan

16.4. Percents


This function compares load mass to standard mass which value should be given. The result of this operation is displayed in percentages. Following functions: dosage, weighing, statistics can cooperate with deviation function.

Activation of the function



Draw 37. Percents – activation of the fucntion

Display




- 1 percentage value, proportion of the mass on the pan and standard mass
- 2 function name
- 3 REF masa odnosienia (see drawing 40 M4 01)
- 4 WGH mass on the pan

Cooperation of the deviations with other functions

During activation of the function set option YES for parameters M4 03, 04, 05. Select field START and start work.

- after setting function Dosage YES give up and down stage as % values
- after setting function Dosage YES give the mass value in %
- after selecting Statistics select field Cancel and cancel previous statistics and change the attribute NO into attribute YES. Confirm this option and press the key Enter.




Draw 39. Percents – cooperation with ther functions

- 1 percentage value relation of the load on the pan to reference mass
- 2 stable measurement sign
- 3 function name
- 4 REF reference mass
- 5 WGH mass on the pan
- 6 graph which presents weighign range where the weighing range is
- 7 statistics (N=0 no measurements)
- 8 active function dosage (load mass between 90 110%)

After measurements eg. 10 (quantity of measurements N=10) user can see results of statistics of made measurements.


- Enter work mode
- Select the parameter 05 Statistics
- Pressing the F key and enter the parameter 05 Statistics
- Select the parameter 02 Results
- Enter function of showing statistics results
- After pressing the ENTER statistics result can be printed
- Return to statistics submenu and higher levels key ESC



Draw 40. Percents - cooperation with other functions - Statistics

16.5. Weighing animals

Function activation




Draw 41. Weighign animals - view of the display

External setting

- FILTR (Decides how fast final stable result is received, the faster filter the shorter time of measurement)
- STAGE (Value in actual scale intervals is value the result must be below The result of weighing must be smaller than value of actual scale intervals in order to do following automatic measurement)
- AUTO START (Automatic start up following measurements)
- STATISTICS (Statistics counting for particular subjects)
- START (Start measurements up)

16.6. Density of solids and liquids

In additional equipment of analytical balances there are Specific Gravity Measurement Kit.



Draw 42. Specific Gravity Measurement Kit

Components of the kit:

1	Beaker stand	7	String
2	Pan stand	8	Float hook
3	Float	9	Top pan
4	Beaker	10	String
5	Thermometer	11	Bottom pan
	clamp		
6	Termometer	12	Attachments

16.6.1. Density of liquids

Basic component during measure solids of liquids is glass float. It has precise determined capacity which is stamped on the float hook. Write password to balance memory before the measurements.

During the measurement of liquid density mass of glass float in the air is compared to its mass in the liquid.

The result is presented on the display automaticaly after its counting by the balance program. The result can be sent through RS 232 to printer or computer after pressing PRINT key.

16.6.2. Density of solids

Density of solids can be determined in one of 3 different liquids:

- WATER (destiled water),
- ALCOHOL (spirit 100% +/- 0.1% at 20 °C),
- OTHER (other liquid with known density)

Measurement of density of solids is based on comparison sample mass in air (weighed on top pan) to the same sample mass in the liquid (on bottom pan).

The programme counts density of sample and displays it on the display. The result can be sent through RS 232 to printer or computer after setting the key PRINT.



Precise description of measurements performance and setting is the manual of Specific Gravity Measurement Kit.


16.7. Formulation

This function is used to make mixtures under recipes. This function is recomended to use in drug-stores. The program is equiped with calculate memory. The balance remembers singular component mass and sum of weighed components.

Following information are presented on the display in this work mode:

- 1. load mass on the pan
- 2. actual weighed component name (max 10 signs)
- 3. mass which should be measured for actual weighed component "WGH"
- 4. quantity of components which is weighed in the mixture "IC"
- 5. components mass already weighed "SUM"

The function activation



Draw 43. Recipes - internal setting

parameter 01 Hints

after set the parameter at YES the balance displays names and singular components mass recorded in the parameter 04 Recipe on the graphic display

parameter 02 Automatic printout

after set the parameter at YES the balance sends value on printer or computer through RS port after confirmation mas sof each component

parameter 03 Quantity of components

user determines quantity of components the mixture should include (max 20 signs)

parameter 04 Recipe

after set this parameter following submenu is displayed. In this submenu user can wirte names (not more than 10 signs) and set (standard mass) of each component in the mixture

parameter 05 Recipe printout

This function prints composition of the mixture on connected printer. There are names and setting of particular component and total contents of the mixture.

parameter 06 Statistics

parameter 06 01 Statistics

switch on (YES) or switch off (NO) statistic couting


Attention:

Statistics counting refers only to total mass of prepared mixtures (singular components mass are not counted).

parameter 07 Start


enter work modes Recipes

Information on the graphic display for recipes



Draw 44. Recipes - functions

- 1 mass which is actualy on the pan.
- 2 stable measurement sing
- 3 function name
- 4 settled mass of the weighed component in the parameter 04 Recipe
- 5 Sum of weighed components of the mixture which are in calculate memory of the balance
- 6 quantity of weighed components in the recipe
- 7 name of weighed component
- 8 sige graphs. Information how much left to gain settled component is presented on these graphs.




Draw 45. graphs - automatical scale

Procedure of preparing mixtures – according to recorded components and their mass in the balance memory

Write names and components mass in the parameter 04 Recipe. Remember about the dependences:

- there cannot be more than 10 signs
- confirm each name by the ENTER key and write mass which will be in the mixture



Draw 46. Declared recipes

- total mass of the mixture together with the container cannot be bigger than max capacity of the balance
- there cannot be more than 20 components in the mixture
- Write quantity of components in the parameter 03 Quantity of components
- Quantity of components cannot be higher than 20 pcs
- The program records mixture contents in order they were introduced in the parameter 04 Recipes. If user writes 10 components in the parameter 04 Recipes and set 8 for quantity of components the program finishes preparation of the mixture after weighing 8 components.
- The balance programe creates mixture in order of recorded components in the parameter 04 Recipes and starts from the component 1 and finishes at settled component in the parameter 03 Quantity of components

- If the documentation is printed set the parameter 02 Automatic printout at 1 : YES. After confirmation of each component (key UNITS) their mass are printed on connected printer or computer.
- Set the parameter 01 Prompts at 1 : YES
- Enter function Recipes by pressing the ENTER key
- Tare container mass to the balance memory
- Weight first component (mass in the WGH)
- Press the UNITS key. Mass of component 1 is recorded in the balance memory. The information on the display changes: component 2, mass WGH, IC=1, SUM=. . . .
- Information on the display is settle do zero.
- Repeat it for all components
- After weighing last component and write its mass to the balance memory (the UNITS key) total mass of mixture and prompts to following steps are displayed.

Procedure of making mixtures without recording components and their mass date in the balance memory

If documentation of preparong mixture is printed set the parameter 02 Printout at 1: YES.

If mass of each component is confirmed each mass with their names is printed on connected printer or computer.

- Set the parameter 01 Prompts at the value 0 : NO
- Enter function Recipes by pressing ENTER
- Tare container mass to the balance memory
- Pour component 1 to the container in relation to information about mixture
- Press the UNITS key. Mass of component 1 is recoded in the balance memory. The information on the display changes: IC=1, SUM=. . . The indication is set to zero. Press the key Units
- · Repeat it for all components of the mixture
- After write last component press the →9/T← Procedure of making mixtures is finished. Sum of mixture is kept on the display.

Statistics counting

Statictics counting relate only to making mixtures (particular mass components are not included in the counting).


If user performs statictic counting in this work mode:

- 1. enter the parameter 06 Statistics
- 2. cancell previous results of statistic counting

- 3. set the parameter 06 01 Statistics at YES
- 4. enter work mode for preparing mixtures
- 5. perform measurement series
- 6. enter the parameter 06 Statistics again
- 7. enter the parameter 06 02 Results
- 8. to print results press the key PRINT

16.8. Statistics

Activation



Results of previous statistics should removed after function activation. It is realized through option **M8 01 Cancel.**

All statistic date are actualized after write following measurement to the balance memory. Following measurment is writen to series after load is put on the pan, stabilization of the result (measure unit is displayed) and after pressing **ENTER.**

User decides what statistic date are presented on the graphic display during measurements by setting their activity in the submenu of work mode (values which are set for YES are active). Independly on setting (YES/ NO), during final result the printout contains full statistics.


N: 5 (quantity of weights) SUM: 161.121 q (all components total mass)

X : 32.224 g (average mass of weighed components)

MIN: 20.486 g (min mass) MAX: 35.578 g (max mass)

D: 15.092 g (difference between Max- Min)

SDV: 6.581 g (standard deviation) RDV: 20.4 % (variation factor)




Draw 48. Statistics - display for series of measurement

- 1. mass on the pan
- 2. measurement number in measurement series
- 3. sum of all weighed components in measurement series
- 4. average mass of weighed components in the series
- 5. mass of the lightest component in measurement series
- 6. mas sof the heaviest component in measurement series
- 7. difference between the lightest and the heaviest component in measurement series
- 8. value of counted standard deviation
- 9. value of variation factor
- 10. measure unit [g]
- 11. work mode

17. KINDS OF PRINTOUTS

17.1. Standard printout

The are 2 types of printouts. First of them is standard printout. It includes result of weighing and all variables which have attibute YES in GLP submenu. In User and Project fields names should be written.



Draw 49. Declaration of variables to printout - submenu GLP

Example of standard printout

Draw 50 Example of standard printout (all option settled on YES – printed)

Date : 13/09/2004 User Id : Nowak

Project Id: tabletka Balance Id: 117436

13.838 g

Draw 51 Example of standard printout

Question mark before load mass means that the result is not stable.

17.2. Non-standard printout

Procedure of creating non-standard printouts:

- user can create own 4 printouts,
- give the number of the text which starts the printout eg. Printout 1
 Start 1 and text number which finishes the printout eg. Printout 1
 Stop 40. In this case texts from 1 to 40 are printed.
- And then write text in the lines 1 ÷ 40.
 It is recomended to use PC keyboard what is simplier and faster way.
- Non-standard printouts can overlap each other:

Printout 1 Start – 1


Printout 1 Stop – 40

Printout 2 Start - 20

Printout 2 Stop - 40

Non-standard printout can be created by Edition of the printout.

During manual writting give all special signs as CRLF, tabulator etc. If function Printout Edition is used all these values can be selected in form of ready elements. They are transmitted from one side **Line of selection** to the other window **Printout**



Draw 52. Menu pritnouts - the function activation

Non-standard printout can include:

- Variable dependly on work mode and other user necessities (mass, date, Project No)
- Stable texts in user menu
- Non-standard printout can include not more than 640 signs recorded as 80 texts 8 signs each (from the parameter Text 1 to Text 80). User can design 4 non-standard printouts

17.2.1. Texts

Variables in all modes and with the same values

%%	Printout of "%" singular sign
%N	Actual net mass in basic unit
%d	Actual date
%t	Actual time
%i	The balance number
%R	The program number
%P	The Project number
%U	The user number
%F	Actual function name – work mode
%C	Date and time of last calibration
%K	Kind of last calibration
%I	Deviation of last calibration
%1	Code 1

%2	Code 2
%3	Code 3
%4	Code 4
%5	Code 5
%6	Code 6

Variables dependent on used work mode

Variable	Description	Mod where the variable is active			
%W	1 piece mass	COUNTING PIECES			
%H	Top stage	WEIGHING			
%L	Down Stage	WEIGHING			
%Z	Standard mass	DOSAGE			
%B	Reference mass	DEVIATIONS			
%A	Filter	WEIGHING ANIMALS			
%b	Stage	WEIGHING ANIMALS			

%i	Liquid	
%р	Procedure	
%с	Temperature	MEASUREMENT OF DENSITY
%a	Density of liquid	
%v	Float capacity	

Statistic variables in all modes apart from basic weighing

%n	The measurement number
%x	Average value
%S	Sum
%m	Min value
%M	Max value
%D	Difference between max and min value
%s	Standard deviation
%r	Variation factor

Variable in all modes which value depends on the mode

%V – Mass in actual unit. Value connected to work mode eg. counting pieces for mode Counting pieces or deviation from standard mass in % for mode Deviation

Special signs used to create special printouts

//	Singular sign "\"
/c	CRLF
\r	CR
\n	LF
\t	Tabulator
\s	skip to next "string"
\0	End of the printout

Each text (Text $1 \div 89$ Text 80) can include max 8 signs (letters, digits, special signs, spaces). To write long sentence create it using 8 sings texts. User can use special signs to include variables dependly on own necessities.

Example 1:

Max mass cannot be higher than 11.250 g!

If user write this sentence uses 640 signs grouped in adjacent lines of the text. Set up following texts and write 8 signs in each of them untill the sentence finishes.

Parameter number		Text							
	1	2	3	4	5	6	7	8	
19 Text 10	М	а	S	а		m	а	k	
20 Text 11	s	у	m	а		n	а		
21 Text 12	n	i	е		m	0	Ż	е	
22 Text 13	р	r	Z	е	k	r	а	С	
23 Text 14	Z	а	Ć		1	1		2	
24 Text 15	5	5	0		g	!			

Example 2:

Zakład Mechaniki Precyzyjnej "RADWAG"

Date:

Time:

Load mass:

*****Signature:.....

<actual work mode>

Set following texts and write 8 signs in each of them untill it is finished.

Parameter number	Text							
	1	2	3	4	5	6	7	8
25 Text 16	Z	а	k	ł	а	d		М
26 Text 17	е	С	h	а	n	i	k	i
27 Text 18		Р	r	е	С	у	Z	у
28 Text 19	j	n	е	j		,,	R	Α
29 Text 20	D	W	Α	G	"	\	С	D
30 Text 21	а	t	а	:	%	d	\	С
31 Text 22	G	0	d	Z	i	n	а	:
32 Text 23	%	t	\	r	١	n	М	а
33 Text 24	S	а		ł	а	d	u	n
34 Text 25	k	u	:	%	N	\	С	/
35 Text 26	С	*	*	*	*	*	Р	0
36 Text 27	d	р	i	S	:			
37 Text 28								/
38 Text 29	С	*	*	*	%	F	*	*
39 Text 30	*							

On the balance desk

A	Move up through digits, letters and sings o 1
•	Move down through digits, letters and sings o 1
•	Determine sign to change and move right (if the key is pressed flashing sign is moved in right direction. If no sign is written this keys makes space in the text)
•	Determine sign to change and move lef (after this key is pressed flashing sign is cancelled)
(a)	Confirm the text


On PS/2 keyboard

Press F2 to enter main menu. Press F3 to set parameters indications next to group P6 Printouts and press F2 to enter menu group and then select parameter. Press F2 to activate the procedure of writing the text. By means of keyboard write the text (max 8 signs) and confirm by Enter. Repeat this procedure for the rest of the texts.


Description of the computer keyboard is in the p. 5.1.3

17.2.2. Composing texts by Edition function

The function activation




Draw 53. Not standard printouts – printout edition



Draw 53-1. Not standard printouts - printout edition - select

After activation of the function select printout number (1-4) and beginning of writting the texts in (range from text 1 to text 80). Then select the option Edition to edite (create) printout or cancell all (remove all printouts).



Draw 54. Edition of printouts - selection of the elements

To select following fields use keys **ARROWS TOP/UP**. To print field press the **RIGHT ARROW** key. After the edition press ENTER/PRINT. Display shows question if printout should be done – press ENTER/PRINT again.

17.2.3. Select non-standard printouts


if STANDARD printout is selected – there will be only result and variables declared in the GLP (see p. 17.1 Standard printout - drawing 52. Declaration of the variables to printout – submenu GLP).

If non-standard printout is printed select kind of the printout (1-4) and give the beginning and end of the printout.

18. COOPERATION WITH PRINTER OR COMPUTER

To send the information on the display with the unit of measure to the computer or printer, press the < **PRINT** > key. 9600 bit/s is the default setting for the speed of transmission. If the peripheral unit has a different speed of transmission, you may change the speed of transmission in the balance menu. (see p. 15 of the manual)

18.1. Connections



Draw 55. Connections balance - computer

The balance connection DB 9/F – The computer connection DB 9/F (with control of sending date)

<u>Balance</u>	<u>Computer</u>
2 (RxD)	3 (TxD)
3 (TxD)	2 (RxD)
4 (DTR)	6 DSR
5 (GND)	5 (GND)
6 (DSR)	6 (DTR)
7 (RTS)	8 (CTS)
8 (CTS)	7 (RTS)

19. COOPERATION WITH LABEL PRINTERS CITIZEN CLP-521

You should follow the steps below to assure the proper operation with the label printer. Use the program "ETISOFT" to designer your own label

- label size
- a kind and number of data to place on the label

Notice:

In order to print properly interial (inside balance) variable, you should predict a proper number of characters for each variable. (charts 2, 3, and 4).


After giving it an original name, save the label on a computer hard drive. (alphanumeric characters). Download the label to the CITIZEN CLP-521 printer

- LPT cable (centronics)
- Set RS232 baud rate in the printer to 9600 bits per second

Design a special printout in the balance that will produce printing the downloaded label. (all the information the printer expects to print it). Set corresponding parameters of printout (example):

- Printout number
- The begin and the end of a printout (start and stop)

• A label example named "Etykieta01"



3 labels after each measurement are to be printed out

Printout designing procedure:


 Inscribe printout data in corresponding texts – P6 parameters' group Printout; parameters: String 01 ÷ String 80.

Use variables from chart 1 (printout control variables) and variables including different data from the balance.

Table 1


\02L \c	Start of the label
r labelname∖c	Label name
X/c	Start of variables' edition
\02U01 N/\\\c	Variable 1 NN-variable symbol
\02U02 <i>N</i> /\0000c	Variable 2 NN-variable symbol
\02U03 <i>N</i> /\/\c	Variable 3 NN-variable symbol
\02Unn /\/\\c	Variable nn NN-variable symbol
\02fnnn \c	Paper feeding nnn [mm] – depending on the label size
E/c	End of variables' edition
\02Ennnn \c	Print nnn labels
\02G \c	End of the label

An example of an internal printout definition



Then set the rest of the parameters

Printout number – 1 Prn. 1 start – 1 Prn. 1 stop – 10



 After setting all the corresponding parameters, return to weighing mode (save the parameters).

Now you can connect the balance with the printer (a cable diagram in the users' manual). Check the setting of transmition parameters both in the balance and in the printer. They should be the same. Place a load on the weight pan and after stabilizing press PRINT. The designed printout will be sent to the printer and three identical labels will be printed out.

The printout appearance:

09:14:56

Mass:

145.34[5] g

27/10/1005

Signature:

Table 2

Variables present in all operation modes

Variable	Number of characters	Description
%%	1	Single charakter printout "%"
%N	16 or 18 *	Present net mass in basic unit
%d	10	Present date
%t	8 (for 24h version)	Present time
%i	8	Balance number
%R	8	Program number
%P	8	Project number
%U	8	Operator number
%F	X **	Name of present operation mode
%C	25	Date and time of the last calibration
%K	X **	Type of the last calibration
%I	16 or 18 *	Deviation in the last calibration
%1	6	Code 1
%2	6	Code 2
%3	6	Code 3
%4	6	Code 4
%5	6	Code 5
%6	6	Code 6
%V	16 or 18 *	Mass (present unit) or a value connected with present operation mode eg. Number of pcs for pcs counting or deviation of standard weight in % for deviation mode

Variables that can be used In one operation mode

Variable	Numer of characters	Description	The mode In which the variable is active	
%W	16 or 18 *	1 pcs mass	Pcs counting	
%H	16 or 18 *	Upper threshold	Deceme	
%L	16 or 18 *	Lower threshold	Dosage	
%Z	16 or 18 *	Expected mass	Dosage	
%B	16 or 18 *	Related mass	Deviations	
%A	14	Filter	Animala waighing	
%b	14	threshold	- Animals weighing	
%i	14	Liquid		
%p	14	Procedure		
%с	14	Temperature	Mass density measurement	
%a	16	Liquid mass density		
%v	16	Plunger volume		

Table 4

Table 3

Statistical variables that are present in every operation mode except Basic weighing.


Variable	No of characters	Description
%n	7	Measurment number
%x	16	Avarage value
%S	16	Sum
%m	16	Minimal value
%M	16	Maximal value
%D	16	The difference between minima and maximal value
%s	16	Standard deviation
%r	16	Variance factor

^{*} Depends on the printout parameter PC/printer (additional digit marker)

^{**}depends on the name length

20. WEIGHING LOADS UNDER THE BALANCE

In standard version balances have possible to weight loads under the balance. To use this function:



Draw 56. Weighign under analytical balance

Remove the cover in the base of the balance. There is a hook visible which can be used to suspend a sample.

Note:

- The suspension eye is directly connected to the weighing mechanism. Take great care not to move or rotate the eye, as this will damage the weighing mechanism.
- Accessories such as an under the balance rack and a suspension hook are available.
- 3. The mass of all suspended accesories should be set to zero by pressing **TARE** before commencing any weighing.

21. CONNECTING ADDITIONAL KEYS

It is possible to connect external tare and print buttons by special luster through port RS232.

Printer or computer can be connected to the cluster.

Connected elements are not standard accessries of the balance.

- 1. balance
- 2. cable which connects balance with cluster
- 3. cluster
- 4. button TARA
- 5. button PRINT

22. LIST OF COMMUNICATIONS COMPUTER - BALANCE

Function RESET INTERFACE

Command R CR LF (zero actual orders, restore factory setting)

Function SEND ALL COMMANDS FROM THE BALANCE

Command PC CR LF (all recorded information in commands in the balance

programme are sent from the balance)

Function SEND THE RESULT IN BASIC UNIT

Command S CR LF (result is sent from the balance in basic interval after

stability)

Function SEND RESULT IN BASIC UNIT IMMEDIATELY

Command SI CR LF

Function SEND THE RESULT IN ACTUAL INTERVAL

Command SU CR LF (result in actaul unit is sent from the balance after

stability)

Function SEND RESULT IN ACTUAL INTERVAL IMMEDIATELY

Command SUI CR LF

Function ZERO THE BALANCE

Command Z CR LF (set the balance to zero after it reaches stability)

Function ZERO IMMEDIATELY

Command ZI CR LF

Function TARE WHEN STABLE

Command T CR LF

Function TARE THE BALANCE IMMEDIATELY

Command TI CR LF

Function SWITCH CONSTANCE TRANSMISSION OFF IN BASIC INTERVAL

Command C0 CR LF

Function SWITCH CONSTANCE TRANSMISSION IN BASIC INTERVAL

Command C1 CR LF

Function SWITCH CONSTANCE TRANSMISSION OFF IN ACTUAL

INTERVAL

Command CU0 CR LF

Function SWITCH CONSTANCE TRANSMISSION ON IN ACTUAL

INTERVAL

Command CU1 CR LF

Function NUMBER OF THE BALANCE

Command NB CR LF

Function RANGE OF WEIGHIGN

Command FS CR LF

Function PROGRAM VERSION

Command RV CR LF

Function WRITE OR CHANGE DATE IN THE BALANCE

Command PD CR LF (the balance sends settled date or the date is changed)

Function WRITE NEW OR CHANGE TIME IN THE BALANCE

Command PD CR LF (the balance sends settled time or this time is changed)

Function WRITE ACTUAL WORK MODE

Command PM CR LF

Function SEND SETUP

Command PS CR LF (all balance setup is sent – printout of the parameters)

Function SOUND SIGNAL - "BEEP"

Command B CR LF (sound beep is switched on)

Function SEND LAST ERROR CODE

Command ER CR LF (last order of the error is sent)

Function DISPLAY STRING

Command DS CR LF (signs are show on the display)

Function CANCELL STRING

Command CS CR LF (cancells string and restores previous state of the display)

Function DISPLAY HEADLINE

Command DH CR LF (sinus are displayed in top headline of the display)

Function CANCELL HEADLINE

Command CH CR LF (cancells information in the top healine)

Function CANCELL HEADLINE

Command DF CR LF (displays signs in the bottom headline)

Function CANCELL HEADLINE

Function PERFORM INTERNAL CALIBRATION

Command CL CR LF

Function BLOCK THE KEYBOARD

Command KL CR LF

Function UNBLOCK THE KEYBOARD

Command KU CR LF

Function SWITCH "ECHO" OFF FOR THE KEYBOARD

Command E0 CR LF (keys codes are switched off)

Function SWITCH "ECHO" ON FOR THE KEYBOARD

Command E1 CR LF

Function SWITCH THE BALANCE OFF Command O0 CR LF (the same as ON/OFF)

•

Function SWITCH THE BALANCE ON Command O1 CR LF (the same as ON/OFF)

Function SWITCH AUTOZERO OFF

Command A0 CR LF

Function SWITCH AUTOZERO ON

Command A1 CR LF

If command which is not listed or with error and with CRLF at the end the command is returned in E S CR LF form. Spaces in the forms should be omited,

23. TECHNICAL PARAMETERS

AS/X balances

	AS 60/X	AS 100/X	AS 160/X	AX 220/X
Max capacity	60g	100g	160g	220g
Accuracy	0,1mg			
Tare range	- 60g	- 100g	- 160g	- 220g
Linearity	±0,3mg			
Pan	Ø 85			
Stabilization time	4s			
Repeatability	0,2mg			
Dryft of sensitivity temperature	2ppm/°C in temp. 15 °C - 35 °C			
Temperature	+ 18 °C - + 33 °C			
Power supply	230V , 50 Hz, 8VA / 11V AC			

24. COMMANDS ABOUT ERRORS

Order	Error number	Error description
"control sum error"	1.1	Errors duting date transmission
"A/D Error"	1.2	Converter error
"Exceed range"	2.1	Exceed max measure range of the balance
" Exceed range "	2.2	Exceed max measure range of the balance
"A/D Null"	2.3	No divisions from converter
"A/D Full"	2.4	Exceed max value converter intervals
"Tara/Zero above the range"	2.5	Exceed admissible tare or zero value
"Tara above the range "	2.6	Exceed admissible tare value for the balances
"Zero above the range"	2.7	Exceed zero range for the balances
"Result > 4% Max"	2.8	To high start mass (start the balance up with load on the pan)
"Result > 1% Max"	2.9	Difference between determined calibration mass and calibration mass recorded in the balance memory higher than (difference >1%)
"Piece < 1 Div"	2.10	Singular mass value in counting pieces function less than actual scale interval

Piece < 10 Div"	2.11	Mass on the pan during determining mas sof singular piece in the function of counting pieces less than 10 actual scale intervals	
"Ref < 1000 Div"	2.12	Value of reference mass in the function deviations is less than 1000 actual scaleń intervals	
"above the range"	3.1	The parameter value above the range	
"Faulty value"	3.2	Inadmissible value of the paraemter	
"Blocked - DRH"	3.3	The parameter cannot be changed (Function DRH active in the factory menu)	
"Writting error " 4.1			
" Party error"	4.2		
" Frame error"	4.3	Errors during date transmission to sprinter of	
"stopped transmission CTS"	4.4	computer	
" stopped transmission XOFF"	4.5		
"incorrect date"	5.1	Faulty date	
"Exceed time"	6.1	Exceed admissible time during for an operation (eg. zero)	

Instruction number LMI-29-02/06/08/ENG

MANUFACTURER OF ELECTRONIC WEIGHING INSTRUMENTS



RADWAG 26 – 600 Radom Bracka 28 Street POLAND

Central tel. +48 48 38 48 800, tel./fax. + 48 48 385 00 10 Sales Department + 48 48 366 80 06 www.radwag.com

