


Simple Step

**INTEGRATED STEP MOTOR,
DRIVER, AND CONTROLLER**



USER MANUAL

TABLE OF CONTENTS


SECTION 1: INTRODUCTION TO SIMPLE STEP	3
PLEASE READ BEFORE USING SIMPLE STEP	4
DISCLAIMER.....	4
ELECTRICAL SPECIFICATIONS.....	5
COMMUNICATIONS SPECIFICATIONS.....	5
DIMENSIONS	6
OPERATING SPECIFICATIONS	6
FEATURES	7
DEVELOPER'S KIT LIST	7
SECTION 2: CONNECTORS	8
SECTION 3: GETTING STARTED	9
SETUP FOR HYPER TERMINAL	10
SETUP FOR WINDOWS APPLICATION.....	10
SECTION 4: USING THE DIGITAL I/O	11
INPUT CONNECTIONS	11
OUTPUT CONNECTIONS	13
CONNECTING AN LED TO AN I/O.....	14
CONNECTING MULTIPLE DRIVERS	15
CHANGING ADDRESSES	15
SECTION 5: SOLDERING ACCESSORY PIECES.....	16
PUSH BUTTON.....	16
OPTO SENSOR	17
SECTION 6: SIMPLE STEP COMMANDS SET (HIGHLIGHTS)	18
PROGRAMMING SYNTAX	18
ROTATE MOTOR IN THE POSITIVE AND NEGATIVE DIRECTION	19
CHANGING THE VELOCITY.....	20
CHANGING THE ACCELERATION FACTOR	20
LOOPS	20
SETTING THE CURRENT	21
THE SKIP COMMAND.....	21
STORING PROGRAMS.....	21
ADJUSTING THE STEP RESOLUTION	21
THE HALT COMMAND.....	22
RUNNING MULTIPLE MOTORS	22
EXAMPLES	23
SECTION 7: SOFTWARE DOWNLOADS	24

1. Introduction To Simple Step

The Simple Step is designed to allow for rapid implementation of stepper motors in products requiring automation.

With a fully intelligent controller attached to the back, the Simple Step accepts high level commands from an RS232/RS485 link. The controller only adds 0.5" to the length of the motor which otherwise is a standard Lin Engineering Size 17 High Torque Step Motor.

The Simple Step unit is supplied with a developer's kit, enabling users to easily implement their own programs. An RS485 to RS232 converter card is also given, along with a DB-9 connector cable and accessory pieces. The converter card provides the connection between your Simple Step Unit and your PC. Commands can be issued from any serial terminal program (such as HyperTerminal) or from the Simple Step Windows Application, which can be downloaded from Lin Engineering's website. Accessory pieces such as a red push button switch, an Opto Sensor, and a 4-pin connector for the converter card, are included. Also, additional wiring for I/O's are provided. The commands to the Simple Step are intuitive and simple. For example the command A10000 will move the



stepper motor to Absolute Position 10000 (steps). (This communications protocol is compatible with devices that use the Cavro DT or OEM protocol).

The Simple Step is also capable of stand alone operation with no connection to a PC. It can be set to execute a preset string of commands upon power up. Commands include nested loops, execution halt pending a switch closure, and much more. It is also possible to daisy chain up to 16 different Simple Step units.

This user manual is a complete guide to setting up the Simple Step unit. It also contains information on various types of inputs and outputs your Simple Step unit can be used with. In addition, a highlighted list of commands for programming the Simple Step has been provided.

SIMPLE STEP INSTALLATION NOTES

Thank you for purchasing the Simple Step Integrated Motor & Controller. The Simple Step is warranted to be free of manufacturing defects for 1 year from the date of purchase.

PLEASE READ FIRST BEFORE USING SIMPLE STEP

Before you start, ensure that there is a suitable DC power supply. A current limited lab supply is recommended for first time users to guard against the possibility of miswire. In addition, in order to prevent any harm to the controller board, **do not disconnect the unit while power is still being supplied**. Do not exceed 40VDC under any circumstances.

DISCLAIMER

Lin Engineering reserves the right to make changes without further notice to this product to improve reliability, function, or design. Lin Engineering does not assume any liability arising out of the application or use of any product or circuit described herein; neither does it convey any license under its patent rights of others.

The Simple Step Integrated Motor & Controller and Lin Engineering logo are trademarks of Lin Engineering.

ELECTRICAL SPECIFICATIONS

Power Supply Requirements

Voltage +12 VDC to +40 VDC

Motor Specifications

NEMA Size 17

Motor Rated Current

4118S 0.9 Amps RMS

4118M 1.4 Amps RMS

4118L 1.1 Amps RMS

Holding Torque 4118S 38.4 oz-in

4118M 72.0 oz-in

4118L 84.8 oz-in

Steps per Revolution (1.8° Motor)

400, 800, 1600, 3200, 6400, 12800

Digital I/O Specifications

Number of I/O 2

Number of Inputs 2

Input Voltage +0 VDC to +24 VDC

Input Current 700 mA

Pull-up Resistors 10k Ω

Protection Static Protection to the microprocessor

COMMUNICATION SPECIFICATIONS

Interface Type RS485 to RS232 converter card

Baud Rate 9600 bps

Bits per character 8 Data

Parity None

Stop Bit 1

Flow Control None

DIMENSIONS

A. Motor Front Shaft Extension Length

Standard length is 0.94". Customized length is available.

B. Motor Shaft Diameter

Standard shaft diameter is 0.1968". Customized diameter length is also available.


C. Overall Body Length

Motor body length is available in various lengths

Model 4118S (2.69")

Model 4118M (2.92")

Model 4118L (3.24")



OPERATING SPECIFICATIONS

Maximum Step Frequency

10k pps

Operating Temperature Range

0 to 50 °C

Storage Temperature Range

-20 to 70 °C

FEATURES

- Single 4 wire bus linking up to 16 stepper motors
- 1.50 Amp Chopper (PWM) Driver
- Operates from 12V to 40V
- Stand alone operation with no connection to a PC
- Execution Halt pending switch push button
- Pre-wired for Opto Switch inputs
- 1/2, 1/4, 1/8, 1/32, 1/64 step resolution
- Homes to an Opto or Switch closure with a single command
- Fully programmable ramps and speeds
- Two digital I/O and two fixed input channels
- Switch selectable address
- Software selectable "Move" and "Hold" currents
- Hold Current automatically selected upon move completion
- Simple DB9 connection

DEVELOPER'S KIT LIST

- Simple Step Integrated Motor and Controller
- RS485 to RS232 converter card
- A DB-9 female connector cable, a switch push button, Opto Sensor, a 4 Pin connector for the converter card, and extra wiring for I/O
- User Manual

2. Connectors

A DB-9 female connector cable receives power and provides the control connections for the Simple Step module. On the opposite end of the DB-9 female connector cable, there is a 4 pin connector provided for the converter card in order for the driver to communicate with the PC. This allows the user to solder and program the switch push button and the Opto Sensor, enabling several options. The two I/O wires are colored blue and black. This will allow for options such as solenoids, relays, opto isolators, LED's and many other input and output connections. See Figure 2.1 for details.

Pin #	Color	Function	Input*
1	Red	+V (Main power In)	
2	Black	I/O	1
3	Brown	RS485B	
4	Black/White	RS485A	
5	Orange	Switch Closure to GND (IN)	4
6	Green	GND (-V of main pwr in)	
7	White	Opto Sensor Phototransistor (IN)	3
8	Blue	I/O	2
9	Yellow	Opto Sensor LED (Power Out)	

Table 2.1




Figure 2.1: DB-9 Female Cable Connector (Rear View)

*Inputs are labeled 1, 2, 3 and 4 for programming the 'Halt' and 'Skip' Commands. See page 21 and 22 for more information.

3. Getting Started

1. Connect the DB-9 Female Cable to the back of the Simple Step unit.
2. On the opposite end of the DB-9 cable, there is a 4 pin female connector. Connect this female mating connector to the header of the converter card (RS485 to RS232 converter card).
3. Then connect two wires from the converter card to a power supply. Plus and minus signs should already be allocated on the converter card.
4. Connect one end of a serial cable to the converter card, and the other end to a serial port on a PC (This cable is not provided in the kit.)
5. Turn on your Power Supply (See Figure 3.1 below).

WARNING: DO NOT DISCONNECT THE UNIT WHILE POWER IS STILL BEING SUPPLIED.




Figure 3.1

SETUP FOR HYPERTERMINAL

Please follow these steps in order to properly set up hyperterminal:

1. Open a terminal from your PC by following these steps:

Start Menu → Programs → Accessories →
Communications → HyperTerminal

2. Assign a name for your terminal
3. Make sure your COMM connection corresponds to the same COMM connection as your PC serial port (i.e. COMM 1, COMM 2, etc.)
4. Set your Port Settings to default (i.e. 9600 baud, 8 data, no parity, 1 stop bit, no flow control) To get to your Port Settings, perform the following steps:

File → Properties → Settings

5. Turn on local echo by going to:

File → Properties → Settings → ASCII Setup:

Click on the box for “Echo Typed Characters Locally” and click on the box for “Send Line ends with line feeds”. These options will be useful when typing commands in HyperTerminal.

6. Click OK
7. Now you can type your commands
8. Example: /1A10000R
 - This will run driver 1 to the Absolute position 10000
 - Visit www.linengineering.com for a full list of commands

SETUP FOR WINDOWS APPLICATION

1. Go to www.linengineering.com → Click on the Integrated Motors Icon → Windows Application
2. Install Simple Step onto your PC
3. Open the application
4. Click on Settings, on the bottom right corner and type the correct COM port. Be sure this corresponds with the correct serial port on your PC
5. Begin writing your commands (see the Quick Reference Guide for the Windows Application at www.linengineering.com)

4. Using the Digital I/O

The Simple Step contains two fixed inputs and two digital bidirectional I/O's. It is possible to receive input from external devices such as sensors, switches, or PLC outputs. Outputs such as relays, solenoids, LED's and PLC inputs may be controlled from the Simple Step Unit.

All Input and I/O lines feature internal 20k Ω pull-up resistors. The I/O lines in addition feature a switch closure to ground, which can be used to drive loads connected externally of up to 2.4 mA at 24V, or as low as 0.5 mA at 5V. The I/O lines should not be actively driven high, because of the internal switch closure to ground. (Use a pull-up resistor of 300 Ω or greater and an open collector style pull-down on these particular lines).

INPUT CONNECTIONS

Connecting a Switch Push Button

A Red Capped Switch Push Button is provided in your kit. After completing the 'Getting Started' section, you are now ready to program an input. Please refer to the 'Soldering Accessory Pieces' on page 16 in order to use your switch push button. Figure 4.1 shows a circuit schematic of how the switch push button is configured.




Figure 4.1

Using HyperTerminal, here is how to program your Simple Step Unit to move 1000 steps in the positive direction each time you press the button. Assuming the motor address is set to 1 (see the 'Changing Addresses' section on page 15), type in the following code:

```
/1gH14P1000G0R
```

Connecting a TTL Interface

This enables the user to have one Simple Step unit's output to be another Simple Step unit's input. Below, Figure 4.2 shows the input driver on the left, and the output driver on the right.




Figure 4.2

Be aware of the possibility of a ground shift between the output driver and the input driver. The wiring between the two drivers should be a short 6 inch distance. If your wiring is too long, it is possible that the ground voltage on the input side may be as high as 2 VDC, thus not enabling this connection to work properly. To connect motors further apart, use an opto isolator, as shown in the following section. It is also recommended to connect multiple motors as shown on page 15.

Connecting an Opto Isolator

Connection of two motors is possible using an opto isolator. Be sure to use a transistor opto that has a current, $I_c > 1\text{mA}$ at $I_F = 20\text{mA}$.




Figure 4.3

OUTPUT CONNECTIONS

Connecting an Opto Sensor

An Opto Sensor is provided in your developer's kit. After completing the 'Getting Started' Section, you can now program the Opto in HyperTerminal. Please refer to page 17 for Soldering the Opto.




Figure 4.4

Here is how to program your Simple Step Unit to wait for a switch closure on pin 2, home the stepper to the opto, move to position 1000, then move to position 0:

```
/1H11ZA1000A0R
```

Driving a Relay

It is necessary to place a 1N4001 diode across the relay as shown in order to protect against inductive spikes.




Figure 4.5

Example: To activate the relay, then wait for 500 milliseconds, and then deactivate the relay, type in the following commands:

```
/1gJ3M500J0G5R
```

Driving a small DC Motor

A simple connection shown in Figure 4.6 will allow a 5V to 24V DC motor to run with your Simple Step Unit.




Figure 4.6

Example: To turn on a driver, or an I/O pin, use the 'J' function, as shown in the previous example. For ease of purpose, call J3 to turn on both drivers, and use J0 to turn off both drivers.

/1J3M1000J0R

CONNECTING AN LED TO AN I/O

Since the Inputs and Outputs are tied down together to make a bidirectional I/O line, there is about 0.002 Amps running through the line when it should be off. When connecting an LED, there is a slight chance that the light may appear dim when it is should appear to be completely off. If this happens, an easy solution is to add a 20V Zener Diode between the LED and the circuit board.




Figure 4.7

CONNECTING MULTIPLE DRIVERS

- Ensure that each unit has its own unique address if you choose to have different motions per unit. If you choose to run the same motion on multiple units, then the same address for each unit may be used.
- Figure 4.8 shows a basic schematic of the connections between two motors and the converter card




Figure 4.8

CHANGING ADDRESSES

- Locate the channel selector on the bottom of the Simple Step
- Using a small flat screwdriver, turn dial to the desired channel
- See Figure 4.9 below




Figure 4.9

5. Soldering Accessory Pieces

PUSH BUTTON

The push button needs to be soldered to wire 5 (Orange) and wire 6 (Green). There is no difference in polarity for the push button, therefore, wire 5 and 6 can be interchanged with the push button terminals.




Figure 5.1

Now you can program your switch push button. See 'Examples' in Section 6.

Note: When programming a specific input, note that:

- Input 1 corresponds to Pin 2
- Input 2 corresponds to Pin 8
- Input 3 corresponds to Pin 7
- Input 4 corresponds to Pin 5

See the commands list on how to program switches and halt statements.

OPTO SENOSR

The opto sensor uses wire 6 (Green), wire 7 (White), and wire 9 (Yellow). Four wires are already connected to the opto sensor, colored Red, Black, White, and Green. On the opto sensor, wires Green and Black are both Ground, which need to be soldered together, then soldered to wire 6 (Green) on your DB-9 cable. Then the red wire on the opto sensor needs to be soldered to wire 9 (Yellow) on your DB-9 cable. And the white wire on the sensor needs to be soldered to wire 7 (White) on your DB-9 cable.

Opto Sensor	Cable
Green →	Green
Black →	Green
Red →	Yellow
White →	White

Table 5.1




Figure 5.2

Now you can program your Opto Sensor. See 'Examples' in Section 6.

Note: When programming a specific input, note that:

Input 1 corresponds to Pin 2

Input 2 corresponds to Pin 8

Input 3 corresponds to Pin 7

Input 4 corresponds to Pin 5

6. Simple Step Command Set

Commands to the Simple Step driver and controller are single alpha characters normally followed by a numeric value. The alpha character represents “what to do” and the numeric value represents “how much to do it”.

Values for desired velocities, accelerations, positions, stepping resolutions, and currents can all be set. You can also query the program what position it is currently at and what velocity it currently possesses. Creating loops within the strings are easily possible, and storing these strings for later execution can also be done. These strings are stored on the EEPROM, enabling the Simple Step to power up into a mode of your choice, enabling the Unit to run as a stand alone module.

For a complete list of commands, please visit www.linengineering.com and look for Products → Integrated Motors → Simple Step.

PROGRAMMING SYNTAX

When typing in commands, always follow this format:

Start Character	Simple Step address	Commands	End of string
/	1-9*	Command string	<CR>

*Addresses for 10-16 use a different numbering system, described on page 22.

The forward slash tells the computer that you are going to give it a command. The address number lets the computer know which Simple Step unit you want to program. The command string is your actual command, described in detail in the following sections. After typing in your command, you must type in the letter ‘R’, which stands for ‘Run’. This will tell the computer to run the command. Lastly, by pressing Enter, it tells the computer that you are finished with your string. In the following descriptions and example, we will assume that the motor address you wish to program will be motor address one.

ROTATE MOTOR IN THE POSITIVE AND NEGATIVE DIRECTION

When the motor is standing upright, with the shaft pointing towards the ceiling, the motor will rotate clockwise when stepping in the positive direction. Rotating counterclockwise is stepping in the negative direction.

Command (Case Sensitive)	Operand	Description
Z	0-max*	Initialize the Motor. Motor will turn towards 0 until the home opto sensor is interrupted. If already interrupted it will back out of the opto and come back in until re-interrupted. Current motor position is set to zero.
z	0-max*	Sets current position to be position specified without moving motor
A	0-max*	Move Motor to Absolute position
P	0-max*	Move Motor relative number of steps in positive direction. A value of zero will cause an endless forwards move at speed V. By doing so, it enters into Velocity Mode. Any other finite number will set the mode to be in Position Mode.
D	0-max*	Move Motor relative number of steps in negative direction (Note: Motor will not run in the negative direction if the position is at 0. You can use the 'z' command to set the 0 position to be further away in the negative direction. Then use this command.) A value of zero will cause an endless backwards move at speed V. This will enter Velocity Mode. Any other finite number will set the mode to be in Position Mode.
		* 10^9 (32 Bit)

Example: To run a motor in the positive direction 1000 steps, then in the negative direction 1000 steps, you'd type in: /1P1000D1000R

Note: It is not possible to move in the negative direction if the motor is already at position zero, start position. To query the program what position the motor currently possesses, type: "/1?0R". If the response is "0'0", this means that the motor is at home or start position. To move in the negative position while at the home or start position, it is possible to set the home position further away. Let's say you want to move back by 5000 steps, but you are already at the home position. Set the new Home position to be 5000 steps away, then move 5000 steps in the negative direction:

/1z5000D5000R

CHANGING THE VELOCITY

It is possible to set the start speed, the top speed, and the stop speed of the motor. There are two types of modes: Position mode and Velocity Mode. In velocity mode, it is possible to change the velocity on the fly.

Command (Case Sensitive)	Operand	Description
v	50-900	In Position Mode, this sets the Start Speed of the Motor in half steps per second.
V	5-5800	In Position Mode, this sets the Top Speed of the Motor in half steps per second.
V	5-2500	In Velocity Mode, you can change the Top Speed "on the fly". This is allowed when Top Speed < Start Speed (pps).
c	50-900	In Position Mode, this sets the stop speed of the motor in half steps per second.

Velocity mode occurs when you run the Simple Step Unit infinitely, by typing: "/1P0R". The motor will run forever until you interrupt it with the termination command: "/1TR". While the motor is running, you may slow down the velocity on the fly by typing: "/1V1000". Or, when the motor is not running, it is possible to change the start and top speed by typing in: "/1v300V5000R".

CHANGING THE ACCELERATION FACTOR

Command (Case Sensitive)	Operand	Description
L	1-20	In Position Mode, this sets the Acceleration factor (acceleration = $L * 7500 \text{ steps/sec}^2$)

LOOPS

Command (Case Sensitive)	Operand	Description
g		Beginning of a repeat loop
G	0-30000	End of a repeat loop. Loops can be nested up to 4 levels. A value of 0 causes the loop to be infinite.

Example: To run a motor in the positive direction 1000 steps, then in the negative direction 1000 steps, and then repeat this 5 times, type in:

/1gP1000D1000G5R

SETTING THE CURRENT

Command (Case Sensitive)	Operand	Description
m	0-100	Sets "Fast Move" Current on a scale of 0 to 100% of the max current. When $V > v$, $m100 = 100\%$ of 1.25A for the 4118S series.
l	0-100	Sets "Slow Move" Current on a scale of 0 to 100% of the max current. Use this when $V < v$.
h	0-50	Sets the Hold Current on a scale of 0 to 50% of the max current.

THE SKIP COMMAND

Command (Case Sensitive)	Operand	Description
S	01	Skip next instruction if low on input 1 (Pin no. 2)
	11	Skip next instruction if hi on input 1 (Pin no. 2)
	02	Skip next instruction if low on input 2 (Pin no. 8)
	12	Skip next instruction if hi on input 2 (Pin no. 8)
	03	Skip next instruction if low on input 3 (Pin no. 7)
	13	Skip next instruction if hi on input 3 (Pin no. 7)
	04	Skip next instruction if low on input 4 (Pin no. 5)
	14	Skip next instruction if hi on input 4 (Pin no. 5)

STORING PROGRAMS

Command (Case Sensitive)	Operand	Description
s	0-15	Stores a program. Program 0 is executed on power up (Total of 25 commands max per string)
e	0-15	Executes the Stored Programs 0-15

Example: To store the previous example, type: /1s0gP1000D1000G5R
To execute this program, type: /1e0R

ADJUSTING THE STEP RESOLUTION

Command (Case Sensitive)	Operand	Description
j	2, 4, 8, 16, 32, 64, 128, 256	Adjusts the resolution in micro-steps per step. Resolution depends on model.
o	0-250	Allows user to correct any unevenness in microstep size

THE HALT COMMAND

Command (Case Sensitive)	Operand	Description
H		Halt current command string and wait until condition specified.
	Blank	Wait for switch 2 closure
	01	Wait for low on input 1 (Switch 1, Pin 2)
	11	Wait for high on input 1 (Switch 1, Pin 2)
	02	Wait for low on input 2 (Switch 2, Pin 8)
	12	Wait for high on input 2 (Switch 2, Pin 8)
	03	Wait for low on input 3 (Opto 1, Pin 7)
	13	Wait for high on input 3 (Opto 1, Pin 7)
	04	Wait for low on input 4 (Opto 2, Pin 5)
	14	Wait for high on input 4 (Opto 2, Pin 5)
		Halted operation can also be resumed by typing /1R

RUNNING MULTIPLE MOTORS

*To access drivers 10-16, use these commands:

Driver #	Command
A	:
B	;
C	<
D	=
E	>
F	?
0	@

Running two or more motors together:

Motors 1 and 2:	"A"
Motors 3 and 4:	"C"
Motors 5 and 6:	"E"
Motors 7 and 8:	"G"
Motors 9 and 10:	"I"
Motors 11 and 12:	"K"
Motors 13 and 14:	"M"
Motors 15 and 16:	"O"
Motors 1, 2, 3 and 4:	"Q"
Motors 5, 6, 7 and 8:	"U"
Motors 9, 10, 11 and 12:	"Y"
Motors 13, 14, 15 and 16:	"J" (close bracket)

For all motors: " _ " (underscore)

Example: /CA5000R will move motors addressed 3 and 4 to Absolute Position 5000.

EXAMPLES

Open and Close a Valve with One Push Button

/1s0j2gH11P100H11D100G0R

/1s0	Store the following string as program 0 for driver #1
j2	Step resolution set to half stepping
g	Begin loop
H11	Wait for a switch closure (push button) on input 1, pin 2
P100	Move in the positive direction by 100 steps (90 degrees)
H11	Wait for another switch closure (push button) on input 1, pin 2
D100	Move in the negative direction by 100 steps
G0	Loop continuously
R	Run
<CR>	Carriage Return




Figure 6.1

Push Button to Run Motor, Opto Sensor stops the Motor

/1s0gH11P10000H11Z10000G0R

/1s0 Store the following string as program 0 for driver #1
g Begin loop
H11 Wait for a Halt Switch Closure on input 1, (pin 2)
P10000 Move motor in the Positive Direction by 10000 steps
H11 Wait for another Halt Switch Closure (push button)
Z10000 Move back by 10000 steps, or until a sensor is interrupted
G0 Loop continuously
R Run Program




Figure 6.2

7. Software Downloads

Visit www.linengineering.com for the following information:

- Simple Step Windows Application executable
- Simple Step Full Command Set List
- Quick Reference Guide for Hyper Terminal
- Quick Reference Guide for the Windows Application
- Windows Application Examples



Simple Step User Manual
www.linengineering.com

The Simple Step Integrated Motor & Controller and
Lin Engineering logo are trademarks of Lin Engineering