

# Quick Reference User's Manual

We sincerely appreciate your selection of the X-PLAN.

Please start your work by picking out one or more from the following contents that meet your measuring purposes. Both the SET key and the Mouse key are available in order to set your conditions.

If you would like to know about the X-PLAN in more detail, please make detailed reference to the two manuals mentioned below.

Operation Manual

Interfacing Manual





You will find a lot of convenient functions there.



1. Measurement of Area
  - a) Condition setting with SET
  - b) Condition setting with MOUSE
2. Measurement of Segment and Outline lengths
  - a) Condition setting with SET
  - b) Condition setting with MOUSE
3. Measurement of Area and Outline length
  - a) Condition setting with SET
  - b) Condition setting with MOUSE
4. Measurement of Radius and Arc length
  - a) Condition setting with SET
  - b) Condition setting with MOUSE
5. Measurement of Coordinates (based on the origin and X-axis direction)
6. Measurement of Coordinates (based on two known coordinate points)
7. Affine coordinate transformation
8. Measurement of figures with horizontal and vertical scales that differ
9. Accumulating and averaging measured results  
(measuring area of a doughnut shape)
10. Tracing out points to mark
11. Measuring centers of arc and marking them
12. Measuring centroids and marking them
13. Measurement of radial distances
  - a) Condition setting with SET
  - b) Condition setting with MOUSE
14. Volume calculation
15. Revolutionary solid (volume / surface area / center of gravity): plain solid
16. Revolutionary solid (volume / surface area / center of gravity): hollow solid
17. Revolutionary solid (volume / surface area / center of gravity): plural solids
18. Confirming and setting measuring conditions 1
19. Confirming and setting measuring conditions 2

# Keys and operations used in this manual

\* Refer to the operation manual: Explanation of the Apparatus for more details of each key

## How to move the X-PLAN body using the Mouse key

-  Move the body right and left
-  Rotate the arm up
-  Rotate the arm up and down
-  Rotate the arm down




# 1a MEASUREMENT OF AREA (using the SET key to select conditions)

## KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4 (**SET**) when printer is not attached.
- N O** Key explanation printout unnecessary.
- N O** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **N O** Special measurements unnecessary.
- N O** Coordinates unnecessary.
- N O** Segment length unnecessary.
- YES** Area necessary.
- N O** Total length unnecessary.
- N O** Radius unnecessary.
- N O** / **YES** Select meters (m).
- N O** / **YES** Select scale assignment.
- 1** **0** **0** Input RX scale ratio denominator.
- YES**
- YES** RY=RX, so simply press **YES**.
- N O** / **YES** Select 2nd decimal place.
- N O** / **YES** Automatic Numbering unnecessary.

## KEY OPERATION FOR MEASUREMENT

- S / P** Pt. A.
- S / P** Pt. B.
- ARC** Pt. P (at or near the midpoint of the arc).
- S / P** Pt. C.
- CON** Switch to Continuous Mode at pt. D and trace the segment to pt. E.
- CON** Return to Point Mode at pt. E.
- S / P** Pt. F.
- S / P** Pt. G.
- END**



[diagram]

### CONDITIONS

Unit : m  
Scale: 1/100  
Decimal Place : 2nd

### CONDITIONS PRINTOUT

```
COOR      (X.Y) N
LINE SEG (d)  N
AREA      (A)  Y
LINE      (L)  N
RADIUS    (r)  N
          m     Y
SCALE RATIO  Y
RX         100.
RY         100.
          D.P 2
WITHOUT #ing Y
```

### RESULTS PRINTOUT

```
END
A      8.00 m
```















· although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) It is not necessary to press **S / P** at pts. D or E.
- 2) It is not necessary to return to pt. A from pt. G.
- 3) Pt. P does not have to be the exact midpoint of arc BC.
- 4) **SET** may be pressed immediately after switching the power on in order to enter into the condition setting directly.
- 5) \*means that the message appears with the F, but not with the FC.


# 1b MEASUREMENT OF AREA (using the MOUSE key to select conditions)

## KEY OPERATION FOR SETTING CONDITIONS (using the MOUSE key)

- POWER ON** Begin with step 4(  )when printer is not attached.
- N O** Key explanation printout unnecessary.
- N O** Set conditions printout unnecessary.
-  Enter Conditions Setting Mode.
- \* **S / P** Start selecting measuring conditions.
-  **S / P** Special measurement: Select None.
-  **S / P** Basic measurement: Select A(area).
-  **S / P** Units appear. Start unit setting.
-  **S / P** Unit (system): select m(metric system)
-  **S / P** Unit: Select m.
-  **S / P** Scale appears. Start scale setting.
-  **S / P** Select Scale:Ratio.
- 1 0 0** Input RX scale ratio denominator.
- Y E S**
- Y E S** RY=RX, so simply press **Y E S** .
-  **S / P** Decimal point place appears. Start selection.
-  **S / P** Select D.P.2.
-  **S / P** Numbering(#ING) appears. Start selection.
-  **S / P** Select WITHOUT #ING.
-  Setting ends.

## KEY OPERATION FOR MEASUREMENT

- S / P** Pt. A.
- S / P** Pt. B.
- A R C** Pt. P (at or near the midpoint of the arc).
- S / P** Pt. C.
- C O N** Switch to Continuous Mode at pt.D and trace the segment to. pt. E.
- C O N** Return to Point Mode at pt. E.
- S / P** Pt. F.
- S / P** Pt. G.
- E N D**



### CONDITIONS

Unit : m  
Scale: 1/100  
Decimal Place : 2nd

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG (d)  N
AREA      (A)  Y
LINE      (L)  N
RADIUS    (r)  N
          m    Y
SCALE RATIO  Y
RX         100.
RY         100.
          D.P 2
WITHOUT #ing Y
    
```


### RESULTS PRINTOUT

```

END
A      8.00 m
    
```

although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) It is not necessary to press **S / P** at pts. D or E.
- 2) It is not necessary to return to pt. A from pt. G.
- 3) Pt. P does not have to be the exact midpoint of arc BC.
- 4)  may be pressed immediately after switching the power on in order to enter into the condition setting directly.
- 5) \*means that the message appears with the F, but not with the FC.

# 2a

## MEASUREMENT OF SEGMENT LENGTH AND CIRCUMFERENCE

(using the SET key to select conditions)

### KEY OPERATION FOR SETTING CONDITIONS (using the set KEY)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Safety conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **NO** Special measurements unnecessary.
- NO** Coordinates unnecessary.
- YES** Segment length necessary.
- NO** Area unnecessary.
- YES** Total length(circumference)necessary.
- NO** Radius unnecessary.
- NO** / **YES** Select kilometers(km).
- NO** / **YES** Select scale assignment.
- 5000000** Input RX scale ratio denominator.
- YES**
- YES** RY=RX, so simply press **YES**
- NO** / **YES** Select 1st decimal place.
- NO** / **YES** Select Automatic Numbering (assigned during measurement)

### CONDITIONS

Unit : km  
Scale: 1/50000  
Decimal Place : 1st


### CONTITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG (d)  Y
AREA      (A)  N
LINE      (L)  Y
RADIUS    (r)  N
km        Y
SCALE RATIO  Y
RX        50000.
RY        50000.
          D.P 1
#ing IN PLOT  Y
    
```

### KEY OPERATION FOR MEASUREMENT

- S / P** Pt. A.
- S / P** Pt. B.
- S / P** Pt. C.
- CON** Switch to Continuous Mode at pt. C and trace the segment of pt. D.
- CON** Return to Point Mode at pt. D.
- S / P** Pt. D.
- S / P** Pt. E.
- ARC** Pt. P(at or near the midpoint of the arc).
- S / P** Pt. F.
- S / P** Pt. G.
- S / P** Pt. A.
- END**



### RESULTS PRINTOUT

```

# 1.
# 2.
d      0.4km
# 3.
d      0.5km
# 4.
d      1.5km
# 5.
d      0.3km
# 6.
d      1.3km
# 7.
d      0.5km
# 8.
d      0.9km
END
L      5.4km
    
```

although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:















- 1) Automatic Numbering is not necessary, but using it clarifies the printout.
- 2) Pressing **S / P** at pts. C and D distinguishes the segments for separate segment length measurements.
- 3) When **END** is pressed, the circumference measurement will be outputted.
- 4) \*means that the message appears with the F, but not with the FC.

# 2b

## MEASUREMENT OF SEGMENT LENGTH AND CIRCUMFERENCE

(using the MOUSE key to select conditions)

### KEY OPERATION FOR SETTING CONDITIONS (using the MOUSE key)

- POWER ON**      Begin with step 4(  ) when printer is not attached.
- N O**              Key explanation printout unnecessary.
- N O**              Set conditions printout unnecessary.
-       Enter Conditions Setting Mode.
- S / P**              Start selecting measuring conditions.
- \*  **S / P**      Special measurement: Select None.
-  **S / P**      Basic measurement: Select d(segment length),L(total length)
-  **S / P**      Units appear. Start unit setting.
-  **S / P**      Unit(system): select m(metric system).
-  **S / P**      Unit: Select km.
-  **S / P**      Scale appears. Start scale setting.
-  **S / P**      Select Scale:Ratio
- 5 0 0 0 0**      Input RX scale ratio denominator.
- Y E S**
- Y E S**              RY=RX, so simply press **Y E S**
-  **S / P**      Decimal point place appears. Start selection.
-  **S / P**      Select D.P.1.
-  **S / P**      Numbering(#ING)appears. Start selection.
-  **S / P**      Select #ING IN PLOT.
-       Setting ends.

**CONDITIONS**  
 Unit : km  
 Scale: 1/50000  
 Decimal Place : 1st

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG (d)  Y
AREA      (A)  N
LINE      (L)  Y
RADIUS    (r)  N
km        Y
SCALE RATIO  Y
RX        50000.
RY        50000.
          D.P 1
#ing IN PLOT  Y
  
```


### RESULTS PRINTOUT

```

# 1.
# 2.
d      0.4km
# 3.
d      0.5km
# 4.
d      1.5km
# 5.
d      0.3km
# 6.
d      1.3km
# 7.
d      0.5km
# 8.
d      0.9km
END
L      5.4km
  
```

### KEY OPERATION FOR MEASUREMENT

- S / P**              Pt. A.
- S / P**              Pt. B.
- S / P**              Pt. C.
- C O N**              Switch to Continuous Mode at pt. C and trace the segment to pt. D.
- C O N**              Return to Point Mode at pt. D.
- S / P**              Pt. D.
- S / P**              Pt. E.
- A R C**              Pt. P (at or near the midpoint of the arc).
- S / P**              Pt. F.
- S / P**              Pt. G.
- S / P**              Pt. A.



although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) Automatic Numbering is not necessary, but using it clarifies the printout.
- 2) Pressing **S / P** at pts. C and D distinguishes the segments for separate segment length measurements.
- 3) When **E N D** is pressed, the circumference measurement will be outputted.
- 4) \*means that the message appears with the F, but not with the FC.

# 3a

## MEASUREMENT OF AREA AND OUTLINE LENGTH

(using the SET key to select conditions)

### KEY OPERATION FOR SETTING CONDITIONS(with the SET key)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **NO** Special measurements unnecessary.
- NO** Coordinates unnecessary.
- NO** Segment length unnecessary.
- YES** Area necessary.
- YES** Total length (circumference) necessary.
- NO** Radius unnecessary.
- NO** / **YES** Select m/a.
- NO** / **YES** Select scale assignment.
- 1** **5** **0** **0** Input RX scale ratio denominator
- YES**
- YES** RY=RX, so simply press **YES**
- NO** / **YES** Select 2nd decimal place.
- NO** / **YES** Automatic Numbering unnecessary.

### CONDITIONS

Unit : m / a  
 (length in meters, area in ares)  
 Scale: 1/1500  
 Decimal Place : 2nd

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG  (d)  N
AREA      (A)  Y
LINE      (L)  Y
RADIUS    (r)  N
          m/ a  Y
SCALE RATIO  Y
RX         1500.
RY         1500.
          D.P 2
WITHOUT #ing  Y
  
```


### KEY OPERATION FOR MEASUREMENT

- CON** Switch to Continuous Mode.
- S/P** Pt. A(Start).
- Trace segment from pt. A to pt. B.
- CON** Return to Point Mode at pt. B.
- S/P** Pt. A.

### RESULTS PRINTOUT

```

END
A      15.45 a
L      193.29 m
  
```



[diagram]

- although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:















- 1) After beginning from pt. A, the measurement will automatically be completed upon returning to pt. A(a beep will sound) -> Auto-close Function
- 2) The measurement can be performed moving clockwise or counterclockwise.
- 3) Displayed measurements can be changed by pressing **END**. During measuring (before pressing **END**) **NO** can change the displayed kind of measurements to another.
- 4) \*means that the message appears with the F, but not with the FC.

# 3b

## MEASUREMENT OF AREA AND OUTLINE LENGTH


(using the MOUSE key to select conditions)

### KEY OPERATION FOR SETTING CONDITIONS (using the MOUSE key)

- POWER ON**      Begin with step 4(  )when printer is not attached.
- N O**              Key explanation printout unnecessary.
- N O**              Set conditions printout unnecessary.
-       Enter Conditions Setting Mode.
- S / P**            Start selecting measuring conditions
- \*  **S / P**      Special measurement: Select None.
-  **S / P**      Basic measurement: Select A(area), L(total length)
-  **S / P**      Units appear. Start unit setting.
-  **S / P**      Unit(system): select m(metric system)
-  **S / P**      Unit: Select m/a.
-  **S / P**      Scale appears. Start scale setting.
-  **S / P**      Select Scale: Ratio.
- 1** **5** **0** **0**      Input RX scale ratio denominator.
- Y E S**            RY=RX, so simply press **Y E S**
-  **S / P**      Decimal point place appears. Start selection.
-  **S / P**      Select D.P.2.
-  **S / P**      Numbering(#ING) appears. Start selection.
-  **S / P**      Select WITHOUT #ING
-       Setting ends.

### KEY OPERATION FOR MEASUREMENT

- C O N**            Switch to Continuous Mode.
- S / P**            Pt. A(Start).  
Trace segment from pt.A to pt.B.
- C O N**            Return to Point Mode at pt.B.
- S / P**            Pt. A.



[diagram]

### CONDITIONS

Unit : m / a  
(length in meters, area in ares)  
Scale: 1/1500  
Decimal Place : 2nd

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG  (d)  N
AREA      (A)  Y
LINE      (L)  Y
RADIUS    (r)  N
          m/ a  Y
SCALE RATIO  Y
RX         1500.
RY         1500.
          D.P 2
WITHOUT #ing  Y
    
```

### RESULTS PRINTOUT

```

END
A         15.45 a
L         193.29 m
    
```

\* although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) After beginning from pt. A, the measurement will automatically be completed upon returning to pt. A(a beep will sound) -> Auto-close Function
- 2) The measurement can be performed moving clockwise or counterclockwise.
- 3) Displayed measurements can be changed by pressing **E N D**. During measuring (before pressing **E N D**) **N O** can change the displayed kind of measurements to another.
- 4) \*means that the message appears with the F, but not with the FC.



# 4a

## MEASUREMENT OF RADIUS AND ARC LENGTH


(using the SET key to select conditions)

### KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

<b>POWER ON</b>	Begin with step 4( <b>SET</b> ) when printer is not attached.
<b>NO</b>	Key explanation printout unnecessary.
<b>NO</b>	Set conditions printout unnecessary.
<b>SET</b>	Enter Conditions Setting Mode.
* <b>NO</b>	Special measurements unnecessary.
<b>NO</b>	Coordinates unnecessary.
<b>YES</b>	Segment length (arc length) necessary.
<b>NO</b>	Area unnecessary.
<b>NO</b>	Total length unnecessary.
<b>YES</b>	Radius necessary.
<b>NO</b> / <b>YES</b>	Select millimeters(mm).
<b>NO</b> / <b>YES</b>	Select scale assignment.
<b>0</b> * <b>1</b>	Input RX scale ratio denominator.
<b>YES</b>	
<b>YES</b>	RY=RX, so simply press <b>YES</b>
<b>NO</b> / <b>YES</b>	Select 3rd decimal place.
<b>NO</b> / <b>YES</b>	Select automatic numbering (assigned during measurement).

### KEY OPERATION FOR MEASUREMENT

<b>S / P</b>	Pt. A.
<b>ARC</b>	Pt. P <sub>1</sub> .
<b>S / P</b>	Pt. B.
<b>ARC</b>	Pt. P <sub>2</sub> .
<b>S / P</b>	Pt. C.
<b>ARC</b>	Pt. P <sub>3</sub> .
<b>S / P</b>	Pt. D.



[diagram]

### CONDITIONS

Unit : mm  
 Scale: 1/0.1  
 (enlarged 10 times)  
 Decimal Place : 3rd

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG (d)  Y
AREA      (A)  N
LINE      (L)  N
RADIUS    (r)  Y
mm                Y
SCALE RATIO      Y
RX              0.1
RY              0.1
                D.P 3
#ing IN PLOT    Y
    
```

### RESULTS PRINTOUT

```

# 1.
# 2.
d      1.846mm
r      1.177mm
# 3.
d      2.758mm
r      1.295mm
# 4.
d      3.406mm
r      1.583mm
    
```

· although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:















- 1) Pts. P<sub>1</sub>, P<sub>2</sub>, and P<sub>3</sub> do not have to be exact midpoints of the arcs; as long as they are near the middle of the arcs, an accurate measurement can be obtained.
- 2) In the case of enlarged scales (e. g. microscope photographs) decimals can be used as the scale ratio denominator, such as is done here.
- 3) \*means that the message appears with the F, but not with the FC.

# 4b

## MEASUREMENT OF RADIUS AND ARC LENGTH


(using the MOUSE key to select conditions)

### KEY OPERATION FOR SETTING CONDITIONS (using the MOUSE key)

- POWER ON**      Begin with step 4(  ) when printer is not attached.
- N O**              Key explanation printout unnecessary.
- N O**              Set conditions printout unnecessary.
-               Enter Conditions Setting Mode.
- S / P**              Start selecting measuring conditions
- \*  **S / P**              Special measurement: Select None.
-  **S / P**              Basic measurement: Select d(segment length), r(radius).
-  **S / P**              Units appear. Start unit setting.
-  **S / P**              Unit(system): select m(metric system)
-  **S / P**              Unit: Select mm.
-  **S / P**              Scale appears. Start scale setting.
-  **S / P**              Select Scale:Ratio.
- 0** **.** **1**              Input RX scale ratio denominator.
- Y E S**              **Y E S**
- Y E S**              RY=RX, so simply press **Y E S**
-  **S / P**              Decimal point place appears. Start selection.
-  **S / P**              Select D.P.3.
-  **S / P**              Numbering(#ING) appears. Start selection.
-  **S / P**              Select #ING IN PLOT.
-               Setting ends.

### KEY OPERATION FOR MEASUREMENT

- S / P**              Pt. A.
- A R C**              Pt. P<sub>1</sub>
- S / P**              Pt. B.
- A R C**              Pt. P<sub>2</sub>
- S / P**              Pt. C.
- A R C**              Pt. P<sub>3</sub>
- S / P**              Pt. D.



### CONDITIONS

Unit : mm  
 Scale: 1/0.1  
 (enlarged 10 times)  
 Decimal Place : 3rd

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG  (d)   Y
AREA      (A)   N
LINE      (L)   N
RADIUS    (r)   Y
mm                Y
SCALE RATIO Y
RX         0.1
RY         0.1
           D.P 3
#ing IN PLOT Y
  
```

### RESULTS PRINTOUT

```

# 1.
# 2.
d      1.846mm
r      1.177mm
# 3.
d      2.758mm
r      1.295mm
# 4.
d      3.406mm
r      1.583mm
  
```

although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) Pts. P<sub>1</sub>, P<sub>2</sub>, and P<sub>3</sub> do not have to be exact midpoints of the arcs; as long as they are near the middle of the arcs, an accurate measurement can be obtained.
- 2) In the case of enlarged scales (e. g. microscope photographs) decimals can be used as the scale ratio denominator, such as is done here.
- 3) \*means that the message appears with the F, but not with the FC.

# 5

## Coordinates Plotting 1 based on definition of origin and X-axis direction.

### KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- N O** Key explanation printout unnecessary.
- N O** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **N O** Special measurements unnecessary.
- YES** Coordinates necessary.
- N O** Segment length unnecessary.
- N O** Area unnecessary.
- N O** Total length unnecessary.
- N O** Radius unnecessary.
- N O** / **YES** Select mm.
- N O** / **YES** Select scale assignment.
- 1** Input RX scale ratio denominator.
- YES**
- YES** RY=RX, so simply press **YES**
- N O** / **YES** Select Standard coordinates(horizontal X-axis).
- S / P** "Point" the axes origin(pt. 0)
- S / P** "Point" pt. Q.
- YES** Input origin bias XB=0.
- YES** Input origin bias YB=0.
- N O** / **YES** Select zero(0) decimal places.
- N O** / **YES** Select automatic numbering (assigned during measurement)

### CONDITIONS

Unit : mm  
Scale : 1/1 (actual Size)  
Decimal Place : none  
(integer only)


### CONDITIONS PRINTOUT

```

COOR      (X.Y)  Y
LINE SEG (d)    N
AREA      (A)    N
LINE      (L)    N
RADIUS    (r)    N
mm                                     Y
SCALE RATIO  Y
RX          1.
RY          1.
STAND AXIS  Y
XO          0.000mm
YO          0.000mm
XX          34.313mm
YX          0.000mm
XB          0.mm
YB          0.mm
           D.P  0
#ing IN PLOT  Y
    
```

### KEY OPERATION FOR MEASUREMENT

- S / P** Pt. P<sub>1</sub>.
- S / P** Pt. P<sub>2</sub>.
- S / P** Pt. P<sub>3</sub>.



[diagram]

### RESULTS PRINTOUT

```

# 1.
X          10.mm
Y          15.mm
# 2.
X          28.mm
Y          29.mm
# 3.
X          42.mm
Y           8.mm
    
```

- although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) Pt.Q can be any point in the plus direction of the X-axis, but the farther it is from the origin, the more accurate the measurement will be.
- 2) Automatic numbering is used to make the printed results easier to identify.
- 3) When values other than 0 are inputted for the origin bias (XB,YB), the coordinate axes will be shifted in a parallel fashion.
- 4) \*means that the message appears with the F, but not with the FC.

# 6

## Coordinate Plotting 2 based on 2 points of known coordinates.

### KEY OPERATION FOR MEASUREMENT CONDITIONS(using the SET key)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **NO** Special measurements unnecessary.
- YES** Coordinates necessary.
- NO** Segment length unnecessary.
- NO** Area unnecessary.
- NO** Total length unnecessary.
- NO** Radius unnecessary.
- NO** / **YES** Select m.
- NO** / **YES** Provisionally select scale assignment.
- YES** RX values will be calculated automatically.
- YES** RY values will also be calculated automatically (RX=RY)
- NO** / **YES** Select survey coordinates.
- NO** Select coordinate assignment input ...(\*)
- 2 0 0** / **YES** Input x-coordinate for pt.A(X1).
- 1 0 0** / **YES** Input y-coordinate for pt.A(Y1).
- S / P** "Point" pt.A.
- 5 0 0** / **YES** Input x-coordinate for pt.B(X2).
- 2 0 0** / **YES** Input y-coordinate for pt.B(Y2).
- S / P** "Point" pt.B.
- NO** (\*\*)
- NO** / **YES** Select 2nd decimal place.
- NO** / **YES** Select automatic numbering(assigned during measurement)...clarifies printout.

### CONDITIONS

Unit :m  
 Scale :Automatically calculated  
 from given point coordinates  
 Decimal Place:2nd  
 Direction of X-axis:  
 (survey axes)


### CONDITIONS PRINTOUT

```

COOR      (X.Y)  Y
LINE SEG  (d)    N
AREA      (A)    N
LINE      (L)    N
RADIUS    (r)    N
          m      Y
SCALE RATIO  Y
RX         1.
RY         1.
SURV AXIS  Y
X1         200. m
Y1         -100. m
X -27.22552939mm
Y 18.69137795mm
X2         500. m
Y2         200. m
X -0.764405427mm
Y 49.3446918mm
RX 10477.03986
RY 10477.03986
          D.P 2
#ing IN PLOT  Y
  
```

### KEY OPERATION FOR MEASUREMENT

- S / P** Pt.P1.
- S / P** Pt.P2.
- S / P** Pt.P3.



### RESULTS PRINTOUT

```

# 1.
X      306.86 m
Y     -31.90 m
# 2.
X      462.08 m
Y       50.90 m
# 3.
X      258.71 m
Y      240.17 m
  
```

although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- (\*) ...If known point assignment was used in the previous measurement, this No display does not appear.
- (\*\*) ...In the case of 3 known points, operation can continue with (X3,Y3).
- 1) The scale ratio denominator that is automatically calculated from the known point coordinates can be reviewed.Furthermore, it will appear in the printout.
- 2) Determination of scale ratio based on known points can only be performed when horizontal and vertical scales are the same (RX=RY).
- 3) \*means that the message appears with the F,but not with the FC.

## KEY OPERATION FOR SETTING CONDITIONS(using the SET key)


- POWER ON** Begin with step 4(**SET**)when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **NO** Special measurement unnecessary.
- YES** Coordinates necessary
- NO** Segment length unnecessary
- NO** Area unnecessary
- NO** Total length unnecessary
- NO** Radius unnecessary.
- NO** / **YES** Select mm.
- NO** / **YES** Provisionally select scale assignment.\*
- YES** Enter RX scale ratio denominator
- YES** RX=RY, so simply press(**YES**)
- NO** / **YES** Select Survey/Standard coordinates.
- NO** **NO** Select Affine.
- 0** **YES** Input x-coordinate for pt.1.
- 0** **YES** Input y-coordinate for pt.1
- S / P** "Point" pt.1.
- 0** **YES** Input x-coordinate for pt.2.
- 1** **0** **YES** Input y-coordinate for pt.2
- S / P** "Point" pt.2.
- 1** **0** **YES** Input x-coordinate for pt.3.
- 1** **0** **YES** Input y-coordinate for pt.3.
- S / P** "Point" pt.3.
- 1** **0** **YES** Input x-coordinate for pt.4.
- 0** **YES** Input y-coordinate for pt.4.
- S / P** "Point" pt.4.
- NO** ..
- NO** / **YES** Select 0(integer only).
- NO** / **YES** Select automatic numbering (#ING IN PLOT).

**CONDITIONS**  
 Measurement : coordinates  
 Unit : m  
 Scale ; auto-calculation\*\*\*  
 Decimal Place:0  
 Numbering:#ING IN PLOT

### CONDITIONS PRINTOUT      RESULTS PRINT-

```

..... 1. # 1.
STAND AXIS Y X 3. mm
X0 0. mm Y 3. mm
Y1 0. mm # 2.
X -23.59556996mm X 5. mm
Y -21.38574613mm Y 8. mm
X0 0. mm # 3.
Y2 10. mm X 7. mm
X -16.92834041mm Y 2. mm
Y 17.57350216mm
X0 10. mm
Y3 10. mm
X 22.32696317mm
Y 16.33913461mm
X0 10. mm
Y4 0. mm
X 15.66846136mm
Y -22.62638799mm
AF 4
D.P. 0
#ing IN PLOT Y
    
```



[diagram]      \* although some slight discrepancy may occur, results should be very similar to those shown here.

## KEY OPERATION FOR MEASUREMENT

- S / P** Pt.A.
- S / P** Pt.B.
- S / P** Pt.C.

- NOTES:
- (\* , \*\*\*)...As the input coordinates get used to calculate the scale ratios, values to be input here are merely provisional.
  - (\*\*) ...If there are more control points, continue the series of point input.
  - 1) If the CANCEL key gets pressed while an x-coordinate input display appears, the last input coordinates(x and y) gets canceled.
  - 2) For the Affine transformation, at least three points need to be input. Maximum 25 points are acceptable with the X-PLAN.
  - 3) \*means that the message appears with the F, but not with the FC series.

# 8


## MEASUREMENT OF DIAGRAMS WITH DIFFERENT HORIZONTAL AND VERTICAL SCALES

### KEY OPERATION FOR CONDITIONS (using the SET key)

- POWER ON** Begin with step 4( **SET** )when printer is not attached.
- NO** Key explanation print out unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **NO** Special measurement unnecessary.
- NO** Coordinates unnecessary.
- YES** Segment length necessary.
- YES** Area necessary.
- NO** Total length unnecessary.
- NO** Radius unnecessary.
- NO** / **YES** Select meters(m).
- NO** / **YES** Select scale assignment.
- 2 0 0** / **YES** Input horizontal scale ratio denominator(RX).
- 1 0 0** / **YES** Input vertical scale ratio denominator(RY).
- NO** / **YES** Select standard coordinate system.
- S / P** "Point" origin (pt.0).
- S / P** "Point" pt.P(definition of X-axis direction).
- NO** / **YES** Select 1st decimal place.
- NO** / **YES** Select automatic numbering (assigned during measurement)

### KEY OPERATION FOR MEASUREMENT

- S / P** Pt.A.
- S / P** Pt.B.
- S / P** Pt.C.
- S / P** Pt.D.
- S / P** Pt.A



### CONDITIONS

Unit : m  
 Scale : 1/200(horizontal x-axis)  
           1/100(vertical y-axis)  
 Decimal Place : 1st

### CONDITIONS PRINTOUT

```

COOR      (X.Y) N
LINE SEG  (d)  Y
AREA      (A)  Y
LINE      (L)  N
RADIUS    (r)  N
           m    Y
SCALE RATIO  Y
RX         200.
RY         100.
STAND AXIS  Y
XO         0.00 m
YO         0.00 m
XX         5.75 m
YX         0.00 m
           D.P 1
#ing IN PLOT  Y
  
```

### RESULTS PRINTOUT

```

# 1.
# 2.
d         1.7 m
# 3.
d         3.2 m
# 4.
d         2.2 m
# 1.
d         5.4 m
END
A         6.2 m
  
```

· although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) The X- and Y-axes respectively correspond with differing horizontal and vertical scales. When measuring length or plotting coordinates in diagrams where horizontal and vertical scales differ, it is essential that the axes and scale directions be correctly assigned.
- 2) When measuring only area, proper correspondence of axes and scale directions is not necessary, even when vertical and horizontal differ: also, the message requesting definition of X-axis direction will not appear.
- 3) \*means that the message appears with the F, but not with the FC series.

# 9


## ACCUMULATION AND AVERAGING MEASURED RESULTS (measuring area of a doughnut shape)

### KEY OPERATION FOR SETTING CONDITIONS(using the SET key)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- \* **NO** Special measurement unnecessary.
- NO** Coordinates unnecessary.
- NO** Segment length unnecessary.
- YES** Area necessary.
- NO** Total length unnecessary.
- NO** Radius unnecessary.
- NO** / **YES** Select meters(m).
- NO** / **YES** Select scale assignment.
- 100** / **YES** Enter RX scale ratio denominator.
- YES** RX=RY, so simply press **YES**
- NO** / **YES** Select 2nd decimal place.
- NO** / **YES** Automatic numbering unnecessary.

### KEY OPERATION FOR MEASUREMENT

- CON** Switch to Continuous Mode.
- S/P** "Point" pt.A(start) and trace the outer line, returning to pt.A.(Auto-close).
- +Σ** "Accumulate" the area of the larger contour.
- S/P** "Point" pt.B(start) and trace the inner line, returning to pt.B(Auto-close).
- ±** Switch the area measurement of the smaller contour to a negative value.
- +Σ** "Accumulate" the negative area value of the smaller contour.
- NO** **NO** **NO** The average, number of accumulations, and accumulated value will be displayed.



[diagram]

### CONDITIONS

Unit : m  
Scale: 1/100  
Decimal Place : 2nd

### CONDITIONS PRINTOUT

```

COOR      (X.Y)  N
LINE SEG  (d)    N
AREA      (A)    Y
LINE      (L)    N
RADIUS    (r)    N
           m      Y
SCALE RATIO  Y
RX         100.
RY         100.
           D.P  2
WITHOUT #ing  Y
    
```

### RESULTS PRINTOUT

```

END
A          6.36 m
           +Σ
END
A          1.99 m
           +-
A          -1.99 m
           +Σ
ΣA         2.19 m
n           2.
ΣA         4.37 m
    
```

- although some slight discrepancy may occur, results should be very similar to those shown here.


### NOTES:

- 1) (Area of larger contour)+(negative area of smaller contour)=area of the doughnutshaped diagram; therefore, the accumulated value represents the area of the doughnutshaped diagram.
- 2) An area can be measured repeatedly, and the results averaged, to obtain a very accurate measurement; or a variety of areas can be measured, and a total area value obtained, using the Accumulation Function.
- 3) \*means that the message appears with the F, but not with the FC series.

# 10

# Tracing out points to mark


At coordinate displays, which are ready for marking, for example, just after a centroid is measured, pressing the Mark key will initiate a mark leading display as follows.




The above figures mean distances to the marking point(unit:cm)

The following operations should be carried out while holding the cylindrical knob of the (S/P) key lightly. The Marker hole\* will reach the designated position easily and accurately by going through the following procedures.


- At first, move the X-PLAN in the arrow direction (in this case, right) by approximately 12 cm following the up display until 0 will appear in the up display. The result is as follows.




- Then, following the down display, rotate the tracer arm in the arrow direction (in this case, down) by approximately 3 cm until 0 will appear in the down line.



- The designated position is still located slightly left and also slightly down. In the order of the up display(horizontal) and the down one (up & down), move the X-PLAN body finely as shown by the > < indicators, and rotate the arm slightly as shown by the ^ v indicators. So, the direction signs will decrease in number as the mark hole is reaching the designated point.



- At the above display, pressing the fine adjustment rollers\*\* against the paper with your finger, and rotating them finely in the order of horizontal and vertical movements, ...will disappear and | will appear. It means "pinpointed". At that time, the arrows displayed at the extreme left will be replaced by 0.



- Hold the arm in place by slightly pressing it against the paper, and insert a pen in the marker hole\*\*\* to mark the point. If the pinpointed status is lost in the process, repeat Step 4 for readjustment.

## NOTES:

(\* , \*\*\*)The marking pen guides and marking pin are optional with the FC series.

(\*\*) The FC series do not have the fine adjustment rollers. With the FC series, the fine adjustment should be made while pressing the (S/P) key.

For both rough and fine adjustments, adjusting horizontally first and vertically later will accelerate getting the pinpoint. The vertical direction mentioned here means the rotating direction of the tracer arm, not literally perpendicular.




## KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- N O** Key explanation printout unnecessary.
- N O** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- YES** Special measurement necessary.
- N O** / **YES** Select ARC CENTER.
- N O** / **YES** Select mm.
- N O** / **YES** Select scale assignment.
- 1** **YES** Enter RX scale ratio denominator.
- YES** RX=RY, so simply press **YES**
- N O** / **YES** Select Standard coordinates.
- S / P** "Point" the axes origin (pt.0).
- S / P** "Point" pt.P. (X>0,Y=0)
- 0** **YES** Input origin bias XB=0.
- 0** **YES** Input origin bias YB=0.
- 2** **YES** Select 2nd decimal place.
- N O** / **YES** Automatic numbering unnecessary.

## KEY OPERATION FOR MEASUREMENT

- S / P** Pt.A.
- A R C** Pt.B.(to define an arc)
- S / P** Pt.C.(auto-closed)
- M A R K** Follow the Mark leading display to move the X-PLAN and get the pinpoint display. Mark the point while pinpointed.
- M A R K** Press the Mark key again for Ready mode.



### CONDITIONS

Results:  
 center(x,y) of arc and  
 its marking on drawing  
 Unit : mm  
 Scale : 1/1(actual size)

### CONDITIONS PRINTOUT

```

CENTROID (X.Y) Y
mm                Y
SCALE RATIO      Y
RX                1.
RY                1.
STAND AXIS       Y
XO                0.00mm
YO                0.00mm
XX                42.17mm
YX                0.00mm
XB                0.mm
YB                0.mm
D.P. 2
WITHOUT #ing     Y
    
```

### RESULTS PRINTOUT

```

END
XP                19.75mm
YP                16.37mm

MARK
MARK
    
```

although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:


- 1) The measuring functions of arc center, angle and triangular area can only be used independently of one another. They cannot be used in combination with Basic measurement functions, either.

### KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4( **SET** ) when printer is not attached.
- N O** Key explanation printout unnecessary.
- N O** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- YES** Special measurement necessary.
- N O** / **YES** Select CENTROID.
- N O** Coordinates unnecessary
- N O** Segment length unnecessary
- N O** Area unnecessary
- N O** Total length unnecessary
- N O** Radius unnecessary
- N O** / **YES** Select m.
- N O** / **YES** Select scale assignment.
- 1 0** / **0** / **YES** Enter RX scale ratio denominator
- YES** RX=RY, so simply press **YES**
- N O** / **YES** Select Survey coordinates.
- S / P** "Point" the axes origin (pt.0).
- S / P** "Point" pt.P.(X>0,Y=0)
- 0** / **YES** Input origin bias XB=0.
- 0** / **YES** Input origin bias YB=0.
- 0** / **YES** Select 2nd decimal place.
- N O** / **YES** Automatic numbering unnecessary.

### KEY OPERATION FOR MEASUREMENT

- S / P** Pt.A.(start point)
- A R C** Pt.B.(to define an arc)
- S / P** . . . **S / P** Pt.C,D and E.
- A R C** Pt.F.(to define an arc)
- S / P** Pt.G.
- S / P** Pt.A.(auto-closed)
- MARK** Follow the Mark leading display to move the X-PLAN and get the pinpoint display. Mark the point while pinpointed.
- MARK** Press the Mark key again for Ready mode.



[diagram]

### CONDITIONS

Results:  
centroid coordinates and marking the position on a drawing  
Unit : m  
Scale : 1/100

### CONDITIONS PRINTOUT

```

CENTROID (X.Y) Y
COOR (X.Y) N
LINE SEG (d) N
AREA (A) N
LINE (L) N
RADIUS (r) N
m Y
SCALE RATIO Y
RX 100.
RY 100.
SURV AXIS Y
XO 0.00 m
YO 0.00 m
XX 2.37 m
YX 0.00 m
XB 0. m
YB 0. m
D.P. 2
WITHOUT #ing Y
    
```

### RESULTS PRINTOUT

```

END
XG 1.50 m
YP 2.62 m
    
```

MARK  
MARK

\*although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) The centroid measurement can be done at the same time as coordinates, segment length, total length and radius measurements.
- 2) Curved outlines of figures are to be traced in the Continuous mode, while arc outlines can be measured in the Arc mode by pointing two end points and a midpoint to define arc as shown in this example.

# 13a Measurement of radial distances

(using the SET key to select conditions)


\*for F series users only

## KEY OPERATION FOR SETTING CONDITIONS(with the SET key)

- (POWER ON) Begin with step 4(SET) when printer is not attached.
- (NO) Key explanation printout unnecessary.
- (NO) Set conditions printout unnecessary.
- (SET) Enter Conditions Setting Mode.
- (YES) Special measurement necessary.
- (NO)/(YES) Select CON.DIS.
- (NO)/(YES) Select km.
- (NO)/(YES) Select scale assignment.
- (1)(2)(0)(0) Enter RX scale ratio denominator
- (YES) RX=RY, so simply press(YES).
- (NO)/(YES) Select 2nd decimal place.
- (NO)/(YES) Select #ING IN PLOT.

## KEY OPERATION FOR MEASUREMENT

- (S/P) Pt. any point to initiate the radial distance measurement.
- (S/P) Pt.P.\*
- (S/P) Pt.A.
- (S/P) Pt.B.
- (S/P) Pt.C.



Concentric distances from the center P to Point A,B and C get measured.

[diagram]

### CONDITIONS

Measurement:  
radial distances  
Unit : km  
Scale : 1/1200  
Decimal place:2  
Numbering: #ING IN PLOT

### CONDITIONS PRINTOUT

```
CON.DIS (RL)  Y
km            Y
SCALE RATIO  Y
RX           1200.
RY           1200.
              D.P. 2
#ing IN PLOT  Y
```

### RESULTS PRINTOUT

```
# 1.
RL      0.01km
# 2.
RL      0.03km
# 3.
RL      0.02km
```

although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

(\*) Just after all of the measuring conditions for radial distances are set, the 1st pressing of the (S/P) is to initiate the subject mode and the 2nd is to define the center(control)point.

- 1) The(+Σ) key is available only when the CONTINUOUS indicator is off.
- 2) Availability of other keys are as follows.

During continuous measurement: (END) (CE/C)  
Continuous measurement off: (END) (CE/C) (+Σ) (+/-)














# 13b

## Measurement of radial distances

(using the MOUSE key to select conditions)

\*for F series users only

### KEY OPERATION FOR SETTING CONDITIONS (using the MOUSE key)

- POWER ON** Begin with step 4(  ) when printer is not attached.
- (N O)** Key explanation printout unnecessary.
- (N O)** Set conditions printout unnecessary.
-  Enter Conditions Setting Mode.
- (S / P)** Start selecting measuring conditions
-  **(S / P)** Special measurement: Select RL(radial distance).
-  **(S / P)** Units appear. Start unit setting.
-  **(S / P)** Unit(system): select m(metric system)
-  **(S / P)** Unit: Select cm.
-  **(S / P)** Scale appears. Start scale setting.
-  **(S / P)** Select Scale: Ratio.
- (1 0) (0) (YES)** Enter RX scale ratio denominator.
- (YES)** RX=RY, so simply press **(YES)** .
-  **(S / P)** Decimal point place appears. Start selection.
-  **(S / P)** Select D.P.FULL.
-  **(S / P)** Numbering(#ING)appears. Start selection.
-  **(S / P)** Select #ING IN PLOT.
-  Setting ends.

### CONDITIONS

Measurement:  
radial distances  
Unit : cm  
Scale : 1/100  
Decimal place: not specified  
Numbering: #ING IN PLOT

### CONDITIONS PRINTOUT

```

CON.DIS (RL)  Y
cm            Y
SCALE RATIO  Y
RX           100.
RY           100.
              D.P.FULL
#ing IN PLOT  Y
    
```


### RESULTS PRINTOUT

```

# 1.
RL 199.7149294cm
# 2.
RL 98.17151271cm
# 3.
RL 288.4369006cm
    
```

### KEY OPERATION FOR MEASUREMENT

- (S / P)** Pt. any point to initiate the radial distance measurement.
- (S / P)** Pt.P.\*
- (S / P)** Pt.A.
- (S / P)** Pt.B.
- (S / P)** Pt.C.



Concentric distances from the center P to the vertices A,B and C of the triangle get measured.

[diagram]

\* although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:


- (\*) just after all of the measuring conditions for radial distances are set, the 1st pressing of the **(S / P)** is to initiate the subject mode and the 2nd is to define the center(control)point.
- 1) As the tracer point goes 5 mm or more off the control point(P) in the radial distance measurement mode, continuous display of radial distances get initiated. No radial distance display appears within 5 mm, but pressing the **(S / P)** at that time will show the distance from the tracer point to the control point.

### KEY OPERATION FOR SETTING CONDITIONS(using the SET key)

- POWER ON**      Begin with step 4( **SET** )when printer is not attached.
- N O**            Key explanation printout unnecessary.
- N O**            Set conditions printout unnecessary.
- SET**            Enter Conditions Setting Mode.
- YES**            Special measurement necessary.
- N O** / **YES**    Select VOLUME.
- N O** / **YES**    Select m.
- N O** / **YES**    Select scale assignment.
- 1** **0** **0**        Enter RX scale ratio denominator.
- YES**            RX=RY, so simply press **YES** .
- N O** / **YES**    Select D.P.FULL.
- N O** / **YES**    Select #ING IN PLOT.

### KEY OPERATION FOR MEASUREMENT

- S / P**            Pt.A.
- A R C**           Pt.P1. (see "PSEUDO-ARC PROCESS)
- C O N**           Trace the contour line from B to A
- S / P**            Pt.C. Trace around the contour C to Pt.C.
- S / P**            Pt.D. Trace around the contour D to Pt.D.
- YES**            Display to input the contour interval will appear.
- 2** **0** **YES**    Input the interval here.



[diagram]

### CONDITIONS

Measurement: volume  
 Unit : m  
 Scale : 1/100  
 Decimal place: not specified  
 Numbering: #ING IN PLOT

### CONDITIONS PRINTOUT

```
VOLUME (GV) Y
m Y
SCALE RATIO Y
RX 100.
RY 100.
D.P.FULL
#ing IN PLOT Y
```

### RESULTS PRINTOUT

```
GA 2.223209046 m
GA 5.745091221 m
GA 13.51763125 m
H 20. m
END
GV 272.3102274 m
```

### <Pseudo-arc process>

Portions of contour lines that may be regarded as arcs, can be measured by using the ARC key much faster than in Continuous mode. This is referred to as the pseudo-arc process.

In this example, the contour portion AP(shorter) is regarded as an arc, and in order to define that arc, the ARC key is pressed at P1 (a midpoint of the arc).

The more the pseudo-arc process can be applied, the faster curved lines can be plotted.

• although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- 1) The input interval gets cleared under the following conditions.
  - Pressing the **CE/C** key when contour areas are displayed
  - Inputting another contour interval to calculate volumes
- 2) If **YES** is pressed when the volume result is displayed, a display to input a contour interval will appear for re-calculation.
- 3) With the **+Σ** key, the volume result can be saved. The area result of each contour cannot be saved.

# REVOLUTIONARY SOLID : PLAIN SOLID

(VOLUME / SURFACE AREA / CENTER OF GRAVITY)

\*for F series users only

## KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4 (**SET**) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- YES** Special measurement necessary.
- NO** / **YES** Select VOLUME.
- NO** / **YES** Select cm.
- NO** / **YES** Select scale assignment.
- 1** **0** **YES** Enter RX scale ratio denominator.
- YES** RX=RY, so simply press **YES**.
- 0** **YES** Input bias origin XB=0.
- 0** **YES** Input bias origin YB=0.
- NO** / **YES** Select D.P.2.
- NO** / **YES** Select WITHOUT #ING.

**CONDITIONS**  
 Measurement: revolutionary solid  
 Unit: cm  
 Scale: 1/10  
 Decimal place: 2  
 Numbering: WITHOUT #ING

### CONDITIONS PRINTOUT

```

REV.VOL (VA)  Y
cm            Y
SCALE RATIO  Y
RX           10.
RY           10.
XB           0.cm
YB           0.cm
              D.P.2
WITHOUT #ing  Y
    
```


## KEY OPERATION FOR MEASUREMENT

- S / P** Pt.any point to initiate the revolution measurement.\*
- S / P** Pt.the revolution axis origin.
- S / P** Pt.revolution axis(+)point  
->Revolution axis definition completed: ready for measurement.
- S / P** Pt.A.
- S / P** Pt.B.
- S / P** Pt.C.
- ARC** Pt.P1 (see <14>:PSEUDO-ARC PROCESS)
- S / P** Pt.D.
- ARC** Pt.P2
- S / P** Pt.E.
- ARC** Pt.P3
- S / P** Pt.F.
- END** Volume will appear.
- END** Surface area will appear.
- END** Center of gravity will appear.
- MARK** Start marking the center of gravity.
- MARK** The marking ends.

### RESULTS PRINTOUT

```

XO           0.00cm
YO           0.00cm
XX           48.36cm
YX           0.00cm
END
VA           27396.55cm
VF           4626.18cm
XV           24.14cm
YV           0.00cm
    
```



[diagram] - although some slight discrepancy may occur, results should be very similar to those shown here.

**Notes:**

- \* Just after all of the measuring conditions for the revolution measurement are set, the 1st pressing of the **S / P** is to initiate the subject mode and the 2nd is to define the revolution axis origin.
- 1) The defined revolution axis gets cleared under the following conditions.
  - Pressing the **CE / C** key when the measured results are displayed
  - Inputting to alter the bias origins
- 2) The revolutionary solid measurement function is available only when both vertical and horizontal scales are the same (RX=RY).
- 3) The revolution axis cannot intersect the section diagram to measure.
- 4) Measured results by plotted points
  - One point plotted: VA=0, VF=0, (XV, YV) impossible to calculate
  - Two points plotted: VA=0, VF=good, (XV, YV) impossible to calculate
  - Three points or more: all good

### KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4 (**SET**) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- YES** Special measurement necessary.
- NO** / **YES** Select VOLUME.
- NO** / **YES** Select cm.
- NO** / **YES** Select scale assignment.
- 1 0 0** / **YES** Enter RX scale ratio denominator.
- YES** RX=RY, so simply press **YES**.
- 0** / **YES** Input bias origin XB=0.
- 0** / **YES** Input bias origin YB=0.
- NO** / **YES** Select D.P.FULL
- NO** / **YES** Select WITHOUT #ING

### KEY OPERATION FOR MEASUREMENT

- S/P** Pt.any point to initiate the revolution measurement.\*
- S/P** Pt.the revolution axis origin.
- S/P** Pt.revolution axis(+)point.  
->Revolution axis definition completed: ready for measurement.
- S/P** Pt.A.
- ARC** Pt.P1.
- S/P** Pt.B.
- END** The outer figure gets closed.
- +Σ** The result gets saved in memory.
- S/P** Pt.C.
- ARC** Pt.P2.
- S/P** Pt.D.
- ARC** Pt.P3.
- S/P** Pt.C.The inner figure gets closed.
- +/-** The sign gets changed.
- +Σ** The result gets accumulated in memory.
- NO** Accumulated volume will appear.
- NO** Averaged volume will appear.
- NO** Accumulated surface area will appear.
- NO** Averaged surface area will appear.
- NO** Composed center of gravity will appear.
- NO** Number of accumulations will appear.

### CONDITIONS

Measurement:  
revolutionary solid  
Unit: cm  
Scale: 1/100  
Decimal place: not specified  
Numbering: WITHOUT #ING


### CONDITIONS PRINTOUT

```

XO      0.cm
YO      0.cm
XX 506.2619149cm
YX      0.cm
END
VA 114741797.8cm
VF 1333241.261cm
XV 255.1932167cm
YV      0.cm

+Σ
END
VA 2901883.769cm
VF 142959.4808cm
XV 122.1662073cm
YV      0.cm

+-
VA-2901883.769cm
+Σ
ΣA 111839914.1cm
ΣA 55919957.05cm
ΣF 1476200.742cm
ΣF 738100.371cm
ΣX 258.644837cm
ΣY      0.cm
n      2.
    
```



[diagram] although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- (\*) Just after all of the measuring conditions for the revolution measurement are set, the 1st pressing of the **S/P** is to initiate the subject mode and the 2nd is to define the revolution axis origin.
- 1) Composing centers of gravity is possible only when all figures to measure are located on the same side of the revolutionary axis.
- 2) If the revolutionary axis gets changed, only center of gravity data accumulated in **+Σ** get cancelled.
- 3) If the **MARK** key is pressed when the composed center of gravity is displayed, that point can be marked on the drawing.

# REVOLUTIONARY SOLID : PLURAL SOLID

(VOLUME / SURFACE AREA / CENTER OF GRAVITY)

\*for F series users only

## KEY OPERATION FOR SETTING CONDITIONS (using the SET key)

- POWER ON** Begin with step 4 (**SET**) when printer is not attached.
- NO** Key explanation printout unnecessary.
- NO** Set conditions printout unnecessary.
- SET** Enter Conditions Setting Mode.
- YES** Special measurement necessary.
- NO** / **YES** Select VOLUME.
- NO** / **YES** Select cm.
- NO** / **YES** Select scale assignment.
- 5** **0** **YES** Enter RX scale ratio denominator.
- YES** RX=RY, so simply press **YES**.
- 0** **YES** Input bias origin XB=0.
- 0** **YES** Input bias origin YB=0.
- NO** / **YES** Select D.P.2.
- NO** / **YES** Select WITHOUT #ING.

## KEY OPERATION FOR MEASUREMENT

- S / P** Pt. any point to initiate the revolution measurement.\*
- S / P** Pt. the revolution axis origin.
- S / P** Pt. revolution axis(+) point.  
->Revolution axis definition completed: ready for measurement.
- S / P** Pt.A.
- S / P** Pt.B.
- S / P** Pt.C.
- END** The left figure gets closed.
- +Σ** The result gets saved in memory.
- S / P** Pt.D.
- S / P** Pt.E.
- ARC** Pt.P1
- S / P** Pt.F.
- END** The right figure gets closed.
- +Σ** The result gets accumulated in memory.
- NO** Accumulated volume will appear.
- NO** Averaged volume will appear.
- NO** Accumulated surface area will appear.
- NO** Averaged surface area will appear.
- NO** Composed center of gravity will appear.
- NO** Number of accumulations will appear.

### CONDITIONS

Measurement: revolutionary solid  
 Unit: cm  
 Scale: 1/50  
 Decimal place: 2  
 Numbering: WITHOUT #ING


### CONDITIONS PRINTOUT

```

XO      0.00cm
YO      0.00cm
XX      231.35cm
YX      0.00cm
END
VA      2187892.50cm
VF      145057.30cm
XV      82.49cm
YV      0.00cm

                                +Σ
END
VA      1729927.67cm
VF      88444.33cm
XV      186.37cm
YV      0.00cm

                                +Σ
ΣA      3917820.17cm
ΣA      1958910.09cm
ΣF      233501.63cm
ΣF      116750.82cm
ΣX      128.36cm
ΣY      0.00cm
n        2.
    
```



[diagram]

\* although some slight discrepancy may occur, results should be very similar to those shown here.

### NOTES:

- (\*) Just after all of the measuring conditions for the revolution measurement are set, the 1st pressing of the **S / P** is to initiate the subject mode and the 2nd is to define the revolution axis origin.
- 1) Composing centers of gravity is possible only when all figures to measure are located on the same side of the revolutionary axis.
- 2) If the revolutionary axis gets changed, only center of gravity data accumulated in **+Σ** get cancelled.
- 3) If the **MARK** key is pressed when the composed center of gravity is displayed, that point can be marked on the drawing.



# 18

## Confirming and setting measuring conditions 1

In order to confirm/set measuring conditions for the X-PLAN, there are two ways available.

1. Using the SET key
2. Using the MOUSE key

### Confirmation/Set using the SET key(1)

The last settings will appear in the order of the table of contents, every time the (SET) key is pressed. To change the last setting, press the (NO) key to input differently where necessary.

1	Selection for measuring functions
2	Units selection
3	Scale adjustment selection
4	Definition for coordinate axes
5	Origin bias specification
6	Decimal point placement
7	Auto-numbering selection

### Confirmation/Set using the SET key(2)

By pressing the sequence numbers and the (SET) key successively, the numbered display will appear for measuring conditions setting.

- ex. (3) (SET) ... for display to select scale ratios  
 (6) (SET) ... for display to select decimal point placement

### Confirmation/Set using the MOUSE key

By pressing (MOUSE) key, the Mouse mode selection will be available.

- (1) Measuring functions
- (2) Units
- (3) Scale adjustment ←(4) (see Notes <2>)
- (4) Coordinate axis ←(5)
- (5) Bias origin ←(6)
- (6) Decimal place
- (7) Numbering
- (8) Auto-closing
- (9) Auto-power off
- (0) Contents print (available only with nimi-printer attached)


While confirmation with the (MOUSE) key is being made, "M" blinks in the upper right of the display. By moving the tracer arm up and down, displayed messages will scroll in the same direction of the arm movement as mentioned above. To exit the Mouse mode, just press the (MOUSE) key again.

#### NOTES:


- 1) No matter where the tracer arm is located, the (MOUSE) key can be pressed for confirmation / Set.
- 2) The <-0-> statements that are described above and to the right, mean that more displayed messages will scroll left and right as the X-PLAN body moves left and right.


Scale adjustment: Scale ratios / XY for reference distance measurement  
 Coordinate axes : Orientation by using known points / Affine transformation  
 Bias origin : XY values as bias origin

### Setting by using the Mouse key

Confirmation and setting for measuring conditions can be executed in the Mouse mode by pressing  key. By pressing the  $\langle S/P \rangle$  key when each function item is displayed (while "M" mark blinks in the upper right of display), the setting mode gets initiated. The menu structure is configured as follows.

#### < Structure of Mouse menu >



Pressing the  $\langle S/P \rangle$  key, "M" will appear blinking and the displayed items get ready for selection. After selection or cancellation, move the tracer arm up or down to change to the confirmation mode. In order to exit the mouse mode after setting, just press the  key again.

#### NOTES:

(\*) available only with mini-printer attached.

- 1) Selections for the auto-closing and auto-power off functions are available only in Mouse mode.
- 2) If Conditions print out is selected, data(items) codes and their functions get printed.