

ConST 211
数字压力表
DIGITAL PRESSURE GAUGE



让校准更轻松!
Calibration can be easy!

ConST 211 DIGITAL PRESSURE GAUGE

User's Manual



Beijing ConST Instruments Technology Inc.

CONTENTS

1. Introduction.....	1
2. Specification.....	2
3. Warning.....	4
4. Basic structure.....	5
5. Pushbuttons introduction.....	6
6. Screen area.....	7
7. Basic function.....	9
7.1 Power on/off.....	9
7.2 Pressure Measure.....	9
7.3 Zeroing.....	10
7.4 Pressure units.....	12
7.5 Peak detection.....	13
7.6. Backlight.....	14
7.7. Analogue dial.....	14
7.7.1 Percent pressure.....	15
7.7.2 Pressure swing.....	15
7.7.3 Overpressure alarm.....	16
7.7.4 Set alarm limit.....	17
7.8. Temperature measure.....	18
8. Menu Option (calibration/setting).....	18
8.1. Enter the Menu.....	18
8.2. Menu option.....	19

8.3. Enter/cancel the calibration	20
8.4. Cancel the wrong zeroing	20
8.5. Set measure speed	20
8.6. Set RS232 address	20
8.7. Set RS232 baud rate	20
9. Calibration function	21
9.1. Calibration conditions	21
9.2. Calibration process	21
9.3. Cancel calibration	23
10. Replace the battery	23
11. Contact with us	23
Appendix I: Communication protocols	24
1. Instructions format	24
1.1 PC machine's send format	24
1.2 Return format of the ConST211	24
1.3 Error information code instruction	24
1.4 The series port's communication collocation	25
2. Instructions details	26
3. Pressure units shortening	27
4. Pressure units code	27
5. Data automatically transmit format	27

1. Introduction

The ConST211 is designed to offer a truly compact, cost effective digital pressure gauge to cover a wide range of applications. Besides the pressure measure function, it can calibrate the standard pressure gauge, precision pressure gauge, industry pressure gauge, blood-pressure meter and other pressure instruments.

Since the firmware of ConST211 is based on special micro-power consumption technology, one piece of Li-ion battery works up to 10000 hours (1.5 years).

The ConST211 digital pressure gauge has the excellent compatibility of electromagnetism (EMC), so it is applied in any complicated electromagnetism environment. In addition, it is approved European CE standard.

The ConST211 digital pressure gauge has been certified intrinsically safety by PCEC. The symbol of explosion-proof is Exia II CT4. Intrinsically Safety and Non-incendive for Hazardous Locations: Field 0, 1, 2, Class II (Groups A, B and C), Temperature Code T1 ~ T4.

2. Specification

◆ Pressure ranges

Pressure range	Reference Pressure		Isolation Film		Medium		Accuracy in 1 year (%FS)	Compensated Temperature	Burst Pressure
	gauge	absolute	Yes	No	gas	liquid			
(-100~0)kPa (0~40)kPa (0~60)kPa (0~100)kPa (0~160)kPa (0~250)kPa (0~400)kPa (0~600)kPa	●	●	●	●	●	●	0.05 0.1 0.2	0°C to 50°C	3× & <10MPa
(0~1)MPa (0~1.6)MPa (0~2)MPa (0~2.5)MPa (0~4)MPa (0~6)MPa	●	●	●		●	●			
(0~10)MPa (0~16)MPa (0~20)MPa (0~25)MPa (0~30)MPa (0~40)MPa (0~60)MPa	★	●	●		●	●			3× & <100 MPa
(0~100)MPa	★		●		●	●	0.2	0°C to 50°C	1.25×
(0~160)MPa	★		●		●	●			1.50×
(0~250)MPa	★		●		●	●			1.25×

Notes: Above ★ is sealed gauge pressure.


- ◆ **Instrument type:** Basic type; intrinsically safe type;
- ◆ **Pressure units:** kgf/cm² mmH₂O mmHg inH₂O inHg psi kPa MPa Pa mbar bar, total 11 units;
Remark: In order to avoid the readings overflow or too low to read, only some of pressure units are selected;
- ◆ **Overpressure warning:** The screen will flash or glint if pressure over 120%FS;
- ◆ **Measure speed:** User can set it, factory default is 3 times / s;
- ◆ **Working environment:** a. Temperature: -10°C to 50°C; b. Relative humidity: < 95%;
 c. Atmosphere pressure: (86 ~ 106) kPa;
- ◆ **Compensated temperature:** 0°C to 50°C;
- ◆ **Storage temperature:** -20°C ~ 70°C;
- ◆ **Display:** Big FSTN LCD with blue backlight, 5–digit to display;
- ◆ **Working time:** Up to 10000 hours (3 times/s); if battery power is very low, the ConST211 will power off automatically;
- ◆ **Power supply:** One piece 3.6V Primary Lithium Thionyl Chloride High Energy AA–size Bobbin Battery;
 The recommend battery for intrinsical safety type ConST211 is SUNMOON 3.6V SIZE AA/ER14505;
- ◆ **Re–calibration period:** One year (recommend);
- ◆ **RS232 configuration:** Optional;
- ◆ **Size:** φ 112mm × 35mm, total height is 178mm;
- ◆ **Weight:** 0.58kg;
- ◆ **Pressure connector:** M20×1.5 or custom–made;
- ◆ **Additional functions:**
 - ① Temperature measure: ± 1°C resolution;

- ② Peak detection: Detect the maximum pressure value and minimum pressure value;
- ③ Pressure % indication: to display the current pressure percent value by using sector pointer;
- ④ Pressure swing: to indicate the swing degree between 2 contiguous pressure value by using one pointer;
- ⑤ Overpressure alarm: using two pointers to show the low/high alarm limit; the 3th pointer shows the current % indication.

3. Warning


- ⚡ The installation of ConST211 should abide of the related regulations of GB3836.15–2000 《electrical apparatus in explosive gas atmospheres part 15: electrical installations in hazardous areas (except coal mine)》 (eqv IEC 6007914: 1996);
 - ⚡ The ConST211 has the indication of battery level. Please replace the new battery if the gauge power off automatically; **Remark: Please replace the recommended battery in nonhazardous locations;**
 - ⚡ Do not connect the RS232 communication cable with ConST211 in a hazardous atmosphere;
 - ⚡ Don't change the components or structure of gauge. That could destroy the explosion–proof ability directly;
 - ◆ To prevent damage, do not use ConST211 for long time with overpressure. Once the pressure over 120%FS, please release the pressure immediately;
 - ◆ The ConST211 has 11 different pressure units to switch. However, in order to avoid the reading overflow or too low to read, only some of pressure units in selected;
 - ◆ To prevent damage, do not use the imposition of torque between the shell and the pressure quick connect coupling.
- N.B: The mark “⚡” is only for ConST211 intrinsic safety type!**


4. Basic structure





5. Pushbuttons introduction


(1) Operating instruction


 Power ON/OFF

 Analogue dial: Pressing it shortly to select the % indication, swing (fluctuation) and low/high alarm;
Pressing it longer to enter into the menu of adjusting low/high alarm;



 Peak Value: Pressing it shortly to switch the indication among max Peak, min Peak and quit Peak;
Pressing it longer to enter the menu of MENU OPTION;



 Backlight: Pressing it shortly to turn on or turn off the backlight;
Pressing it longer to select the backlight display time (10s, 20s and 30s), and loosen it for selection;


 Pressure units: Pressing it shortly to switch the different pressure units;
Pressing it longer to enter into the temperature display menu;


 Zeroing: Pressing it for zeroing function (The absolute type ConST211 should be press longer).

(2) Data inputting introduction






①  (←),  (→) Move decimal digit left and right;

②  (↑),  (↓) Increase/ decrease the pressure value;


③  (✓) Confirm the inputting data;

④  (ESC) Cancel the input data.

(3)Menu operation introduction



- ①  (Menu)Pressing it longer to enter the MENU OPTION (calibration/setting);
- ②  (↑),  (↓) Move menu upper or down;
- ③  (↙): Enter function;
- ④  (ESC): Show the previous menu.

6. Screen area




Picture 6-1: Screen area

The definition of every area as following:

- ◆ **Battery icon:** The battery icon  is the indication of full battery;
The battery icon  is the indication of low battery (<25%). However, the ConST211 can continue to work until it powers off automatically;
- ◆ **Pressure unit area:** Total 11 units for selection;
In order to avoid the readings overflow or too low to read, only some of the pressure units are selected;
- ◆ **Calibration icon:** The mark or symbol of operating calibration;
- ◆ **Pressure peak:** The mark or symbol of displaying peak value;
- ◆ **Higher limit:** The mark or symbol of high limit pressure;
- ◆ **Lower limit:** The mark or symbol of lower limit pressure;
- ◆ **Temperature unit:** °C;
- ◆ **Data display area:** To display all data or menu;
- ◆ **Analogue dial:** Includes 3 types of indication: pressure % indication, pressure swing, overpressure alarm.
The content of the area is as follows:
 - ① **% indication:** The current pressure percentage;
 - ② **Pressure swing:** The indication of the pressure fluctuation;
 - ③ **Overpressure alarm:** The alarm indication for overpressure (less or more than the limit);
 - ④ **Sector pointer area:** Including 51 segments, bars, or pointers;
 - ⑤ **Scale bar graph:** It has different definitions under different operation conditions;
 - ⑥ **Scale midpoint:** The middle position of the scale bar graph.

7. Basic function

7.1 Power on/off

Press  to turn on or turn off the ConST211. The instrument does a self test and then shows all applicable data. Figure 7-1 shows the first screen.




Figure 7-1: The first screen




Figure 7-2: Pressure measurement interface

7.2 Pressure Measure

Press the buttons to enter the pressure measure menu, the displayed content includes:


- Battery icon
- Pressure measure value
- Pressure units
- Analogue dial indication

Remark: Initially, these register values are set to the factory calibration values. If the pressure is over 120%FS, the whole screen will flashes to alarm. To prevent damager of sensor, please release the pressure immediatly. While the alarm happened, the measure speed of ConST211 automatically changes to 3 times/s for catching up the pressure changing. When the alarm is over, the speed will go back to normal.

Figure 7-2 shows the pressure measure menu.

7.3 Zeroing

(1) The type of gauge pressure:

First of all, please connect the ConST211 with atmosphere via connector coupling. If the current pressure is in the range of $(-1\% \sim 1\%)$ FS, press  button for zeroing step. Figure 7-3-1 shows the zeroing sequence of gauge pressure.




Figure 7-3-1: The zeroing sequence for gauge pressure ConST211

(2) The type of absolute pressure:


- ① Connect the ConST211 with atmosphere, user should know the current atmosphere pressure value (***Pstandard***);
- ② The actual pressure of ConST211 is (***Pmeasure***);
- ③ Pressing  button longer to enter the data inputting state, then, please input the actual pressure (***Pstandard***);
- ④ In the menu of pressure measure, the measured pressure is changed to (***Pstandard***); it is same as the atmosphere pressure value. Now, the zeroing process is finished.

Figure 7-3-2 shows the zeroing sequence for absolute pressure ConST211.





Figure 7-3-2: Zero process of absolute pressure

Remark: A. Please select third item **3CLT** in the menu of MENU OPTION to cancel the zeroing operation.
B. Make sure the instrument is upright while zeroing.

7.4 Pressure units

Press  button to switch different pressure units. The sequence is Pa > kPa > kgf/cm² > inH₂O > mmH₂O > inHg > mmHg > psi > mbar > bar > MPa. The conversion relation of all pressure units is as following table 7-4-1.

Pa	kPa	kgf/cm ²	inH ₂ O	mmH ₂ O	inHg	mmHg	psi	mbar	bar	MPa
1000	1	0.010197	4.01463	102.047	0.2953	7.50061	0.1450377	10	0.01	0.001

Table 7-4-1: Pressure units' conversion relation

Remark: In order to avoid the readings overflow or too low to read, only some of pressure units are selected.

Figure 7-4 shows the methods to switch the different pressure units.







Figure 7-4: Switching method

7.5 Peak detection

(1) Record maximum/minimum peak value

Press  button to record the peak value.

 -----Show the maximum pressure

 -----Show the minimum pressure

<No Icon>----- Automatically record the actual pressure value.

(2) Reset the peak values

Press  to cancel the previous peak value and save the current peak value.

Figure 7-5 shows the display of peak value.






Figure 7-5: Display peak value

7.6. Backlight

Press  button to power on/off the backlight. The selectable time is 10 seconds, 20 seconds and 30 seconds.

The selection method is as below:

(1) Press  button to display the following sequence for selection.






Figure 7-6: The time selection sequence for backlight

(2) Release  the button to select the suitable time and ConST211 will save it automatically.

7.7. Analogue dial

Includes three indications: % indication, pressure swing and overpressure alarm.

Press the key  to switch each other.

The analogue dial includes:

- ① Percent pressure (%) ② Pressure swing ③ Overpressure alarm
- ④ Sector pointer area ⑤ Scale bar graph ⑥ Scale midpoint

7.7.1 Percent pressure

- ◆ % indication: show the current pressure percentage;
- ◆ Sector pointer area: show the pressure range as sector shape;
- ◆ Scale bar graph: 0%~100%, the minimum scale is 2%;
- ◆ Scale midpoint: point to 50%.

Example: As for the ConST211 with (0~100) kPa, if the current pressure value is 50kPa, the % indication is 50%, as figure 7-7-1.




Figure 7-7-1: Pressure % indication

7.7.2 Pressure swing

- ◆ Pressure swing icon: The indication of the pressure fluctuation;
- ◆ Sector pointer area: By using 1 pointer, to show the fluctuation degree of 2 seriate pressure value;
- ◆ Scale bar graph: Range is (-0.25%~0.25%) FS, the min scale is 0.01%FS;
- ◆ Scale midpoint: Point to 0.00%FS position

Example: As for the ConST211 with (0~100) kPa, if current pressure reading is 50.01kPa and previous pressure is 50.11kPa, The fluctuation degree for 2 seriate pressure is -0.1%FS, as following figure 7-7-2.




Figure7-7-2:Pressure swing indication

7.7.3 Overpressure alarm

- ◆ Overpressure alarm icon: The indication of the overpressure;
- ◆ Sector pointer area: By using 2 pointers to show the high/low alarm limit, the 3rd pointer to show the current pressure%;
- ◆ Scale bar graph: (0%~100%) FS, minimum scale is 2%FS;
- ◆ Scale midpoint: Point to 50%.

Example: As for the ConST211 with (0~100) kPa, if the current pressure reading is 50.00kPa (50%FS) and higher limit is 80kPa (80%FS) and lower limit is 40kPa (40%FS), the analogue dial shows as following figure 7-7-3.













Figure 7-7-3: Overpressure Alarm

When the current pressure is beyond the range of lower/higher limit, the whole screen will flash to warn the users adjust pressure. Meanwhile, display updated to 3 times per seconds automatically for catching up the changing. Once the alarm is over, the display goes back to normal speed.

7.7.4 Set alarm limit

The setting process as follows:

- (1) Press  button to display the higher limit  and lower limit  in turn, please move the cursor left or right direction by pressing the   ;
- (2) By pressing buttons  or  to adjust the alarm higher limit  or lower limit .
- (3) After the high limit is adjusted, the menu will automatically enter the lower limit, and then to quit the menu.
The sequence is: High limit > Low limit > Quit.
- (4) The ConST211 automatically check the validity for inputting data. If there is some problem, the setting is not effective. Figure 7-7-4 shows the setting menu.




Figure 7-7-4: The setting menu of high limit and lower limit

7.8. Temperature measure



Press button  longer to enter the menu of temperature measure, press  again to go back to the pressure measure menu. The temperature measure range is $-30^{\circ}\text{C} \sim 90^{\circ}\text{C}$, the minimum resolution is $\pm 0.1^{\circ}\text{C}$.

Figure 7–8 shows the temperature measure menu.




Figure 7–8: Temperature measure menu





Figure 8–1–1: Enter the password menu

8. Menu Option (calibration/setting)

8.1. Enter the Menu

The password to enter the menu is “211” . The operation steps as follows:

- (1) Press  longer to enter into the password menu, as Figure 8–1–1.
- (2) Input password “211” .

N.B: If the password is wrong, the menu will return to the previous menu.

8.2. Menu option

There are 6 options, as Figure 8–2–1.



Figure 8–2–1: Six menu options

Details as below:

- (1) **1.CAL** To enter into the calibration menu;
- (2) **2.C-1** The ConST211 have been calibrated already;
2.C-0 The ConST211 haven't been calibrated yet;
 If implement this step, all pressure calibration will be cancelled. Please be careful to use this operation;
- (3) **3.CLT** To cancel the previous zeroing operation;
- (4) **4.FAL** To set measure speed (or display update);
- (5) **5.ADD** To set the address of RS232;
- (6) **6.BAU** To set the baud rate of RS232;

Attention: As to the ConST211 without serial port, there aren't 5th and 6th items in the menu option.

ConST

8.3. Enter/cancel the calibration

1CAL To enter the calibration;

2C-1 To cancel the calibration.

8.4. Cancel the wrong zeroing

3CLF To cancel the previous zeroing operation.

8.5. Set measure speed

Please select **4FAL** to enter the selectable menu of measure speed, as follows:

1—3 (3 times / 1 sec) 1—2 (2 times / 1 sec) 1—1 (1 times / 1 sec) 2—1 (1 times / 2 sec)

3—1 (1 times / 3 sec) 4—1 (1 times / 4 sec) 5—1 (1 times / 5 sec) 6—1 (1 times / 6 sec)

7—1 (1 times / 7 sec) 8—1 (1 times / 8 sec) 9—1 (1 times / 9 sec) 10—1 (1 times / 10 sec)

The factory default is 3 times / 1 sec.

8.6. Set RS232 address

Select **5Add** to set the RS232 address from the range 1 to 112. The factory default is 1.

8.7. Set RS232 baud rate

Select **6BAU** to set the RS232 baud rate from the options of 2400 and 4800 and 9600. The factory default is 9600.

9. Calibration function

It is recommended the ConST211 is re-calibrated once a year by the skillful professional. Otherwise, the random operation may be effects the inner parameter and weaken the measure performance. The ConST211 should be pre-ssurized to full scale and release all pressure. In order to achieve the best calibration condition, please do the pre-pressurizing three times at least. If the calibration process is irregular, please use the cancellation function.

Notice: the calibration must according to the standard conditions.

9.1. Calibration conditions

- (1) Environment: Temperature: $20^{\circ}\text{C} \pm 2^{\circ}\text{C}$; Relative humidity: (45–75) %; Atmosphere pressure: (86~106) kPa.
- (2) Standard pressure source.

9.2. Calibration process

Select Menu to enter the calibration menu. There are 2 different pressure gauges:

- (1) Single scale gauge: Two-point pressure calibration, the default is higher/lower limit. The sequence is higher limit > lower limit.
- (2) Dual scale gauge: Three-point pressure calibration, the default is lower/high limit and zero.

The sequence is higher lower limit > zero > higher limit.


The calibration point can be modified if it is meet following conditions:

- (1) The first point value is less than 2nd point;
- (2) Or, the 2nd point value is less than 3rd point.

ConST

Example: The ConST211 with (0~100) kPa

(1) Select **ICAL** and press **zero** to display the calibration value of lower limit, as figure 9-2-1. If use needs to modify this calibration value, please input the desired value. Otherwise, please press **zero** to confirm.



(2) To calibrate lower limit point: Press **zero** to confirm till the actual pressure value is stable. As Figure 9-2-2.

(3) Display higher limit point: As Figure 9-2-3, please input the desired data if user needs to modify the calibration value. Otherwise, press **zero** to confirm.

(4) To calibrate higher limit point: Press **zero** to confirm till the actual pressure value is stable. As Figure 9-2-4.

(5) The screen returns to the calibration menu, the 2nd option changes to **2C-1**. That shows the calibration is finished and effective.

Remark: Three-point pressure calibration is mostly same as the two-point. The only difference is icons **LO** **HI**

LO display together while zero is calibrated.

9.3. Cancel calibration

Select **2C-1** and push the button  to cancel the calibration ,then the screen displays **2C-0**.

10. Replace the battery

- ◆ Please replace the spare battery if the ConST211 power off automatically;
- ◆ Replace the approved battery in non-hazardous locations;
- ◆ Approved battery: SUNMOON 3.6V SIZE AA/ER14505;
- ◆ Unscrew the bolt and remove the battery cover, Install the new battery.

Remark: There is a spare battery for the ConST211 of Non-RS232 type.

11.Contact with us

The product specifications and other information contained this manual are subject without notice. ConST group has made a concerted effort to provide complete and current information for the proper use of the equipment. If there are questions, contact Const:

Tel: 0086-10-82782288

Fax: 0086-10-82782266

Website: www.constgroup.com

Email: sales@constgroup.com




Figure 10-1: Spare battery location

Appendix I: Communication protocols

1. Instructions format

1.1 PC machine's send format

A: X: Knnnn: C0: C1: C2: C3: C4+ Eos (End of symbol)

A: 1 byte, the communication address of ConST211

X: 1 byte, only for W (write) or R (read)

K: 1 byte, M (for measure operation), F (for file operation), O (other operation)

n n n n: 2–5 bytes, the item operated by K instruction

C0:C1:C2:C3:C4: Parameter, refer the specified instruction introduction

Eos: 0x0(Hex)

1.2 Return format of the ConST211

A: X: Knnnn: C0: C1: C2: C3: C4+Eos, hereinto:

A: Communication address of the ConST211

X: E or F, E: error information of this frame data; F: feedback information.

Knnnn: It is same as the instructions from upper machine

C0, C1: Feedback data or error information

Eos: 0x0(Hex)

1.3 Error information code instruction

1000: Receive the overflow from buffer zero.

- 1001: User has no right to do this operation
- 1004: The numeric character string has the irregular wrong character
- 1005: The pressure unit is unavailable
- 1007: The set parameter is irregular
- 1016: The current data is not the range of zeroing
- 1017: The digits of set parameter are not enough
- 1018: This instruction is unavailable
- 1019: The length of operation code is overflowed
- 1020: The r/w of instruction is wrong
- 1024: The set pressure unit is irregular
- 1025: The serial port's address is overflowed
- 1026: The baud rate is wrong
- 1029: Some parameter's character is overflowed

1.4 The series port's communication collocation

Communication Address	Baud rate	Data length	Stop bit	Parity bit	Flow control
1 ~ 112	2400 4800 9600	8	2	N/A	N/A

2. Instructions details

Instructions									Function Introduction	Right return value
A	X	Knnnn	C0	C1	C2	C3	C4	Eos		
		OVER	-	-	-	-	-	0x0	Read the software's version number	A: F: OVER; version # +Eos
		OTYPE	-	-	-	-	-	0x0	Read the instrument's model number	A: F: OVOK: model # +Eos
		OCODE	-	-	-	-	-	0x0	Read instrument's serial number	A: F: OCODE: OK+Eos
		OPRDA	-	-	-	-	-	0x0	Read instrument's manufacture date	A: F: OPRDA: OK+Eos
W		OBLAC	0 (close) 1 (open)	-	-	-	-	0x0	Turn on/off backlight	A: F: OBLAC: OK+Eos
W		OBLAT	10/20/30	-	-	-	-	0x0	Set the time of backlight turn off	A: F: OBLAT: OK+Eos
W		OLEDK	0 ~ 100	-	-	-	-	0x0	Set backlighting contrast, 0% ~ 100%	A: F: OLEDC: OK+Eos
W		OKEY	0 (close) 1 (open)	-	-	-	-	0x0	On/off keypad	A: F: OKEY: OK+Eos
R		OBATV	-	-	-	-	-	0x0	Read the battery level 0 (low battery) 1 (left 1/4) 2 (full)	A: F: OBATV: battery icon +Eos
R		ORAN	-	-	-	-	-	0x0	Read instrument's pressure range Pressure type: 0 (gauge) 1 (absolute)	A: F: ORAN: min Pressure: max Pressure: pressure unit: +Eos
R		MRMD	-	-	-	-	-	0x0	Read the actual pressure value	A: F: MRMD: pressure value: unit: +Eos
R		OTEMP	-	-	-	-	-	0x0	Read the environment temperature	A: F: OTEMP: temperature: °C+Eos
W		MZERO	-	-	-	-	-	0x0	zero the excursion value while the zeroing is operating	A: F: MZERO: OK+Eos
W		OZERO	-	-	-	-	-	0x0	Zero the pressure value	A: F: OZERO: OK+Eos
W		OCONT	0 (close) 1 (open)	1	-	-	-	0x0	instrument end the measure data, see format (5)	A: F: OCONT: OK+Eos
W		OUNIT	Unit shortening	-	-	-	-	0x0	Switch the pressure units	A: F: OUNIT: OK+Eos
R		OUIINF	-	-	-	-	-	0x0	Read the code of optional units;	A: F: OUIINF: : unit info code +Eos
R		OPEAK	-	-	-	-	-	0x0	Read pressure peak value	A: F: OPEAK: max Peak value; min peak value: pressure unit +Eos
W		OPKZE	-	-	-	-	-	0x0	Zero pressure peak value to actual measured pressure value	A: F: OPKZE: OK+Eos
R		OADDR	-	-	-	-	-	0x0	Read series port address(1-112)	A: F: OADDR: address +Eos
W		OADDR	Address	-	-	-	-	0x0	Set up the series port address	A: F: OADDR: OK+Eos
W		OBAUD	Baud rate	-	-	-	-	0x0	Set the baud rate (2400,4800,9600)	A: F: OBAUD: OK+Eos
W		OFALT	-	-	-	-	-	0x0	Cancel the pressure parameter to operation, go back to factory default	A: F: OFALT: OK+Eos

Instructions									Function Introduction	Right return value
A	X	Knnnn	C0	C1	C2	C3	C4	Eos		
	W	OCPS	-	-	-	-	-	0x0	Entrance instruction of calibration	A: F: OCPS: OK+Eos
	W	OCF	Z (zero) M(middle) F (full scale point)	Standard pressure of calibration point	-	-	-	0x0	Input the standard pressure value and calibration points, for calibration	A: F: OCF: OK+Eos
	W	OCPOK	1(save) 2(unsaved)	-	-	-	-	0x0	Quit the pressure calibration process	A: F: OCPOK: OK+Eos
	W	ALARM	High limit	lower limit	Pressure unit	-	-	0x0	Set the alarm limit	A: F: ALARM: OK+Eos
	R	ALARM	-	-	-	-	-	0x0	Read alarm limit	A: F: ALARM: High limit+lower limit + pressure unit
	W	MRATE	D0	D1	-	-	-	0x0	Set measure D1 times/ D0 second	A: F: MRATE: OK+Eos
	R	MRATE	-	-	-	-	-	0x0	Read the measured times per second	A: F: MRATE: seconds: times+Eos
	W	ODIAL	0(%) 1(swing) 2(alarm)	-	-	-	-	0x0	Set the work mode on the analog dial	A: F: ODIAL: OK+Eos

3.Pressure units shortening

Shortening	KGf	INH2O	H2O	INHg	HG	PSI	MBAR	BAR	PA	KPA	MPA
Standard	Kgf/cm ²	inH ₂ O	mmH ₂ O	inHg	mmHg	psi	mbar	bar	Pa	kPa	MPa

4.Pressure units code

The data is read by OUIF is algorithm; please check the selected pressure units after it is changed to hex data with 2 bytes. The selectable pressure code is represented by 2 bytes. 1(this unit is available); 0(This unit is unavailable).

Kgf/cm ²	inH ₂ O	mmH ₂ O	inHg	mmHg	psi	mbar	bar	Pa	kPa	MPa
---------------------	--------------------	--------------------	------	------	-----	------	-----	----	-----	-----

MSB-10

LSB-0

5.Data automatically transmit format

Total data length is 16 bytes, plus an end symbol after the data. Example: *P 0.0364 MPA.

THE END THANKS