

## CHIRP - Bug # 101

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	David McDonald	<b>Category:</b>	
<b>Created:</b>	04/04/2012	<b>Assignee:</b>	Dan Smith
<b>Updated:</b>	04/19/2012	<b>Due date:</b>	
<b>Chirp Version:</b>	0.2.2		
<b>Model affected:</b>	(All models)		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Odd split does not import from radio or write to Kenwood TH-F6		
<b>Description</b>			
Odd split does not import from radio or write to Kenwood TH-F6			
when the radio is read, the split frequency shows as a simplex frequency.			
If i change the memory location offset to split, the radio inserts a window and refuses the change.			
while the window is displayed,the frequency offset displays actual receive frequency.			
if i try to edit the offset. we have the same error.			
thanks			

### Associated revisions

#### Revision 1501:3955840c8cdf - 04/05/2012 01:06 pm - Dan Smith

Add support for split tx frequencies to the older kenwoods that store them as separate sub-channels. This is tested on the D7/D700, but speculative on the TH-F6A.

Hopefully fixes #101

#### Revision 1516:1ff81013a525 - 04/06/2012 08:00 pm - Dan Smith

Another tweak to TH-F6A split memory storage

Related to Bug #101

#### Revision 1561:b4b94b904e63 - 04/18/2012 07:14 am - Dan Smith

Fix reading Kenwood TH-F6A odd splits

Hopefully the final nail in the coffin for #101

### History

#### #1 - 04/04/2012 10:26 am - Dan Smith

- Status changed from New to Feedback
- Assignee set to Dan Smith
- Target version set to 0.2.2

Thanks for the debug log.

From it, it looks like 399 is not set as a split tx frequency in the radio, is this expected?

D7->PC: MR 0,399,00155130000,0,0,0,1,0,0,09,09,000,000000000,0,0

The TX frequency should be in the third-to-last spot there, but it's not.

CHIRP is sending what I expect it should based on my understanding of the format for that radio. Can you manually set one of the channels in the radio as split tx and then send me the debug log after doing so (and tell me which memory you set)?

**#2 - 04/04/2012 11:34 am - David McDonald**

- File *dmtfreqs.fx* added

Hi Dan

The Chirp Software does not read the split on import of radio file nor will it to allow you to change it to split.

When you attempt a change, A window pops up stating not allowed.

however, the split amount reverts to the receive frequency then clears when you click the OK on the popup window.

I have enclosed 4 print screens

1. Kenwood Mcp-F6/F7 memory 399 showing split for example.
2. Kenwood Mcp-F6/F7 memory 397 showing split for example.
3. Chirp with imported radio file "not showing split" as discussed.
4. chirp with attempted change.

I have also enclosed the Kenwood .fx file.

you can change the extension to a .txt file to see the structure

thanks again

kc4yvv

i can export a csv if needed for chirp.

**#3 - 04/04/2012 11:39 am - Dan Smith**

I do understand what's going on, but I need help from you to solve it (I do not have an F6A to work with).

I need to see how the radio represents an odd split in order to be able to fix it. In order to do that, I need you to **manually** program in a split tx channel from the radio's front panel, and then try to download it in chirp. The debug log will then contain the information I need to make the correction.

**#4 - 04/04/2012 12:55 pm - David McDonald**

- File *debug.log* added

memory 31

log file

**#5 - 04/04/2012 01:06 pm - Dan Smith**

Your log reports memory 31 as empty:

PC->RADIO: MR 0,031

D7->PC: N

Are you sure that's the right memory?

**#6 - 04/04/2012 01:30 pm - David McDonald**

- File *chirp1.doc* added

- File *chirp2.doc* added

- File *debug.log* added

Hi Dan

I am resending the print screens

according to the manual, there are two ways to program odd splits on page 15.

1. change the offset amount. this is limited to 50khz steps.
2. Write a memory. tune the desired TX frequency. Then press PTT and MR to write the transmit.  
the display also shows a + - symbols

**#7 - 04/04/2012 01:55 pm - David McDonald**

The best that I can Tell, The program does not recognize the field required.

the logs don't show it.

what can I do to Help.

change the .fx file to .txt and open to see differences.

if it would help. I can create a .fx file to convert to .txt with only three memory locations.

with all on the same Frequency.

you have to see the .txt file to see what I am talking about.

one simplex

one standard 600 offset

and one with a 1.02 mhz odd offset.

best regards as always

kc4yvv

**#8 - 04/05/2012 07:22 am - David McDonald**

- File *TEST1.txt* added

- File *TEST1a.csv* added

- File *TEST1a.xls* added

Hi Dan

I created a blank Kenwood file as follows:

memory 0 145.23 simplex

memory 1 145.23 minus 600 default offset  
memory 2 145.23 plus 600 default offset  
memory 3 145.23 +- odd split 2mhz offset

look at the txt file and the xls files  
the txt file has gaps  
the xls or csv file shows no gaps

hope this helps

kc4yvv

**#9 - 04/05/2012 07:32 am - Dan Smith**

- *Status changed from Feedback to Blocked*

The .fx files and the print screens don't help me. The debug.log is the only thing that shows the actual output from the radio over the serial line, which is what I need, and it doesn't seem to match what I'm asking for.

Thanks for the help, but I'll have to wait until I can get my hands on one of these locally so I can get the information I need.

**#10 - 04/05/2012 07:45 am - David McDonald**

- *File THF6\_protocol.pdf added*

maybe this can help

kc4yvv

**#11 - 04/05/2012 01:07 pm - Dan Smith**

- *Status changed from Blocked to Feedback*

It doesn't directly help, but it has clues.

The TH-D7 (which I happen to have locally) behaves very similar. I just fixed support for split tx on it and speculatively for the TH-F6A. Please test tomorrow's build and report back.

**#12 - 04/06/2012 07:41 pm - David McDonald**

- *File debug.log added*

Hi Dan

the New Build does recognize the split upon the import read.

It does not show the tx frequency. when you click on the split, it shows the receive freq and pops a window saying radio refused.

regards and sorry for the reply delay.

keep me posted.

kc4yvv

**#13 - 04/06/2012 08:02 pm - Dan Smith**

Okay, I found another issue in the format it was sending to the radio which is why it was giving you the refused message. That is fixed for tomorrow.

You say that it's not seeing the split frequency on memories stored in the radio, but I need to know what memory number in the radio has a split frequency set so I can examine the debug log. Previously you said memory #31, but the radio reports that channel as being empty. Please clarify.

**#14 - 04/07/2012 07:50 am - David McDonald**

- *File debug.log added*

Hi Dan

I'll check it when the build posts tonight.

I am working with memory 399 for example.

I did not realize it but I had lost my split prior to the import on the last log.

I am correcting the split and then reading the radio and will send a new debug log.

kc4yvv

**#15 - 04/07/2012 08:20 am - David McDonald**

Memory 292 is also a split. It was not click on.

Memory 399 was click on as the log shows but i do not get a visual of the tx frequency.

I entered the tx freq in the split box but is refused.

kc4yvv

**#16 - 04/07/2012 08:46 am - Dan Smith**

Your latest debug log shows you're still using the 0406 build. Please re-try with 0407, which has fixes from our conversation yesterday.

I appreciate your patience with this. It's very difficult to do this speculatively without hands on the radio, as I'm sure you can imagine. We'll get it resolved though, even if I have to borrow one from someone :)

Thanks!

**#17 - 04/07/2012 09:11 am - David McDonald**

- *File debug.log added*

not there yet

set memory 399 to simplex

sent log

thanks

**#18 - 04/07/2012 09:14 am - Dan Smith**

Okay, it might not seem like it, but this time we're really close.

It looks like it properly fetched the tx frequency from the existing channel 399:

```
D7->PC: MR 0,399,00155130000,0,0,0,1,0,0,09,09,000,000000000,0,0
PC->RADIO: MNA 399
D7->PC: MNA 399,DTNPD 01
PC->RADIO: MR 1,399
D7->PC: MR 1,399,00156150000,0
```

The last line being the TX frequency of 156.150, right?

The attempt to set makes it look like you chose a TX frequency (offset field) of 0MHz, but I assume you did not, right? What did you try to set?

**#19 - 04/07/2012 09:59 pm - David McDonald**

- *File debug.log added*

Hi Dan

This morning, when i read the radio on memory 399 I saw split on the read file.

I did not see the tx frequency on the program live.

I then clicked on the split column and got the radio refused popup window.

I then tried to enter the tx freq.

the end result was a simplex memory of 399.

I have corrected the file and I am going to read the radio and then shut down the program and send the debug log.

I will send a 2nd debug log after I fiddle with the split.

keep in mind, per the radio offset limits, if you try to set a offset not a multiple of 50khz it will fault or round the number to the multiple of 50khz.

I think that's why Kenwood has an additional odd split parameter in their software to allow and set any odd frequency within radio step limits.

Here comes the 1st debug log with strictly a read of the radio and shutting down the program.

I can send you a copy if you want if you don't have it.

**#20 - 04/07/2012 10:25 pm - David McDonald**

- *File debug.log added*

2nd debug log.

399 shows split in duplex column. 0.00000 in offset column. click on offset column a the receive freq pops in the box

the same happened on memory 397 and 392.

still does not display TX freq.

except in log.

btw I don't mind helping at all. You going to Dayton this year?

Regards

kc4yvv

**#21 - 04/08/2012 10:00 am - Dan Smith**

- Status changed from Feedback to Blocked

Hmm, so the TX frequency has to be a 50kHz multiple even though the RX frequency can be down to 5.0kHz? That seems strange to me.

Well, I'm not sure what else to try here, given that it **seems** to behave properly with my D7. I'll ping the local user that I know that has one of these and see if I can borrow it for a bit. If so, I should be able to resolve it this week. Thanks for your patience.

Yep, I'll be at Dayton :)

Thanks!

**#22 - 04/08/2012 11:11 am - David McDonald**

I'm sorry I guess I wasn't clear enough. Kenwood has two means of a non standard split. One is to change the offset amount in 50khz steps.

The other is the true ability to enter a odd split of 5khz to 50 mhz amount I think. per page 15 of the user manual regarding splits.

I can send you the pdf if you wish.

Best regards and enjoy Easter.

kc4yvv

**#23 - 04/11/2012 05:39 am - David McDonald**

Hi Dan

Have you had a chance to get your hands on a TH-F6.

You doing any Presentations or seminars.

I understand theirs a D-STAR forum or class at the Drury Inn Friday morning.

best regards

David

**#24 - 04/11/2012 07:02 am - Dan Smith**

I've got an appointment to get my hands on one, but it will be Tuesday before I can get it. It shouldn't take long after that though.

Yes, I'll be at the D-STAR forum, most likely (always have been in the past).

**#25 - 04/11/2012 07:13 am - Dan Smith**

- Target version changed from 0.2.2 to 0.2.3

**#26 - 04/17/2012 09:17 pm - Dan Smith**

Just FYI I acquired the F6A tonight and will take a look at this in the next day or so to get it resolved. Thanks for your patience.

**#27 - 04/18/2012 07:21 am - Dan Smith**

- Status changed from Blocked to Resolved
- Target version changed from 0.2.3 to 0.3.0

I believe this is fixed now. I'll leave this open for you to test in tomorrow's daily build.

Thanks!

**#28 - 04/19/2012 05:51 am - David McDonald**

Hi Dan

Looks like you got it down pat.

I thought you would cipher it out once you got your hands on one.

hope to meet you in the future and if i can help let me know.

I have:

Kenwood TH-F6

Kenwood TS-690SAT

Icom ID-92AD

Icom IC-2820

Icom 706 MK2G

Thanks

David

kc4yvv

**#29 - 04/19/2012 06:30 am - Dan Smith**

- Status changed from Resolved to Closed
- Chirp Version changed from 0.2.1 to 0.2.2

Glad it's fixed, thanks for your patience. Maybe see you at Dayton?

**Files**

debug.log	49.4 kB	04/04/2012	David McDonald
dmfreqs.fx	23.5 kB	04/04/2012	David McDonald
debug.log	50.1 kB	04/04/2012	David McDonald
chirp1.doc	2.5 MB	04/04/2012	David McDonald
chirp2.doc	3.2 MB	04/04/2012	David McDonald
debug.log	48.5 kB	04/04/2012	David McDonald
TEST1.txt	2.1 kB	04/05/2012	David McDonald
TEST1a.csv	2.1 kB	04/05/2012	David McDonald
TEST1a.xls	28 kB	04/05/2012	David McDonald
THF6_protocol.pdf	883.4 kB	04/05/2012	David McDonald



debug.log	56.9 kB	04/06/2012	David McDonald
debug.log	56.9 kB	04/07/2012	David McDonald
debug.log	56.7 kB	04/07/2012	David McDonald
debug.log	56.8 kB	04/07/2012	David McDonald
debug.log	56.2 kB	04/07/2012	David McDonald