

# **Virginia Panel Corporation's CASS User's Manual**

*Installations, Operations,  
and General User Guide*

Official Edition - 2.7  
Updated February 1998  
Updated November 21, 2001  
Updated February 6, 2002  
Updated January 5, 2004  
Updated May 18, 2007

### **OBJECTIVE**

The following is a Consolidated Automated Support System (CASS) Interface System User's Manual. It has been written to educate CASS users of the required set-up, operations and trouble-shooting procedures of the Interface System.

The objective of the User's Manual is to aid the user in the everyday operations of the Interface System(s).

The Contents of this Manual are based on the field and Life-Cycle Test observations.

### **BACKGROUND**

Virginia Panel Corporation (VPC) has long been recognized for the design and manufacture of Modular Interface Systems. Since developing the industry's first hybrid Modular Interface System in 1968, VPC has been dedicated to providing its customers with the most effective, economical and dependable methods of interconnecting test devices.

VPC's introduction of the CASS is the next stepping stone for an interface providing high pin density, small footprint, multiple termination methods and high quality at an economical price.

**TABLE OF CONTENTS**

<b>Section 1 CASS Interface System Parts</b>	<b>1</b>
<hr/>	
<ul style="list-style-type: none"><li>- To be used in the identification of part(s) or part number(s).</li><li>- Replacement reference guide.</li></ul>	
<b>Section 2 Installation/Removal of Modules and Contacts</b>	<b>3</b>
<hr/>	
<ul style="list-style-type: none"><li>- Describes the step-by-step required instructions on the removal and installation of the Modules and Contacts.</li></ul>	
<b>Section 3 Engaging Interface Device With Receiver</b>	<b>5</b>
<hr/>	
<ul style="list-style-type: none"><li>- Discusses the proper operation/engagement of the CASS Receiver and ID</li><li>- Cover all necessary precautions prior to engagement.</li></ul>	
<b>Section 4 General Maintenance</b>	<b>6</b>
<hr/>	
<ul style="list-style-type: none"><li>- Removal and Installation of Micro-Switch.</li></ul>	
<b>Section 5 Contact Assembly Requirements</b>	<b>7</b>
<hr/>	
<ul style="list-style-type: none"><li>- This Section is about the required tools and parts needed to operate the Interface System at an optimum level of performance by following step-by-step wiring instructions.</li></ul>	
<b>Section 6 Trouble-Shooting and Solutions</b>	<b>35</b>
<hr/>	
<ul style="list-style-type: none"><li>- Possible trouble areas and the simple required necessary actions.</li></ul>	
<b>Section 7 Product Cross Reference Tables</b>	<b>37</b>
<hr/>	
<ul style="list-style-type: none"><li>- Provides the user with quick access to tools needed for removal and installation of contacts, crimping and associated equipment.</li></ul>	
<b>Section 8 Diagrams</b>	<b>40</b>
<hr/>	
<ul style="list-style-type: none"><li>- Diagrams of the Receiver, ID and Modules (dimensions and part numbers are specified) to be used in identifying and inspecting parts of the System.</li></ul>	

***CASS Interface System Parts — Section 1******Receiver***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
310 115 101	1899AS265-01	CASS Receiver Interface, accepts 19 Modules

***Interface Device***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
410 113 101	1899AS279-01	CASS ID Frame, accepts 19 Modules

***Receiver Modules***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
510 113 120	1899AS266-02	Power Module (RCVR), 76 Positions, for Discrete Wiring (40, 20 AMP and 36, 10 AMP Hi-Density for 14 AWG)
510 113 121	1899AS269-02	Coaxial Module (RCVR), 64 Positions, for Discrete Wiring or for side PCB Mount
510 113 122	1899AS271-02	Coaxial Module (RCVR), 64 Positions, for Center PCB Mount
510 113 124	1899AS275-02	Signal Module (RCVR) with 210 Contacts for Right Angle PCB Mounting
510 113 125	1899AS273-02	Signal Module (RCVR), 210 Positions, for Discrete Wiring

***ID Modules***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
510 114 106	1899AS286-01	Signal Module (ID), 210 Positions, for Discrete Wiring
510 114 107	1899AS280-01	Power Module (ID), 76 Positions, for Discrete Wiring (40, 20 AMP and 36, 10 AMP Hi-Density for 14 AWG)
510 114 108	1899AS283-01	Coaxial Module (ID), 64 Positions, for Discrete Wiring
510 114 109	1899AS285-01	Coaxial Module (ID), 64 Positions, for Center PCB Mounting

***Blank Modules***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
510 113 106	1899AS288-01	Blank Module for ID and Receiver

***Receiver Contacts***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
610 104 114	1899AS270-01	Mini Coaxial Contact (RCVR), 50 OHM, for RG316
610 104 141	1899AS270-02	Mini Coaxial Contact (RCVR), 50 OHM, for RG178
610 104 142	2038AS397-01	Mini Coaxial Contact (RCVR), 50 OHM, Solder Sleeve for RG316 or RG178
610 110 122	1899AS276-01	Hi-Density Signal Contact (RCVR), for PCB Mounting Row #1
610 110 123	1899AS276-02	Hi-Density Signal Contact (RCVR), for PCB Mounting Row #2
610 110 124	1899AS276-03	Hi-Density Signal Contact (RCVR), for PCB Mounting Row #3
610 110 125	1899AS274-01	Hi-Density Signal Contact (RCVR), for Crimp or Solder, 50 $\mu$ AU
610 110 174	1899AS268-01	Hi-Density Power Contact (RCVR), 10 AMP for 14 AWG
610 116 112	1899AS267-01	Mini Power Contact (RCVR), 20 AMP for 8 AWG

\* Indicates that no CASS P/N has been assigned to this part

***CASS Interface System Parts — Section 1******ID Contacts***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
610 103 115	1899AS284-01	Mini Coaxial Contact (ID), for RG316 - 30 $\mu$ AU
610 103 130	1899AS284-02	Mini Coaxial Contact (ID), for RG178 - 30 $\mu$ AU
610 103 157	1899AS284-03	Mini Coaxial Contact (ID), for RG178 - 50 $\mu$ AU
610 103 159	1899AS284-04	Mini Coaxial Contact (ID), for RG316 - 50 $\mu$ AU
610 103 140	2038AS396-01	Mini Coaxial Contact (ID), Solder Sleeve <sup>®</sup> for RG316 or RG178 - 30 $\mu$ AU
610 103 158	2038AS396-02	Mini Coaxial Contact (ID), Solder Sleeve <sup>®</sup> for RG316 or RG178 - 50 $\mu$ AU
610 110 108	1899AS287-01	Hi-Density Signal Contact (ID), for Crimp or Solder, 50 $\mu$ AU
610 110 172	1899AS282-01	Hi-Density Power Contact (ID), 10 AMP for 14 AWG
610 110 146	1899AS287-02	Hi-Density Signal Contact (ID), for Crimp or Solder
610 110 173	1899AS282-02	Hi-Density Power Contact (ID), 10 AMP for 14 AWG, 50 $\mu$ AU
610 115 124	2038AS418-01	Mini Power Contact (ID), 50 AMP for 8 AWG

***Crimping Tools & Accessories***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
910 101 102	*	MS31 Microcrimp Tool for Hi-Density Power Contact (ID & Receiver)
910 101 103	*	Microcrimp Tool for Hi-Density Signal Contact (ID & Receiver)
910 101 115	*	Hex Crimp Tool for Mini Coax Contact
910 104 107	*	Locating Die for Hi-Density Signal Contact (ID & Receiver)
910 104 116	*	Locating Die for Hi-Density Receiver Power Contact
910 104 118	*	Locating Die for Hi-Density ID Power Contact

***Insertion & Extraction Tools***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
910 110 102	*	Extraction Tool for Signal Contact (ID & Receiver)
910 112 104	*	Extraction Tool for Mini Coax and Power Contacts (ID & Receiver)

***Quality Control Tools & Accessories***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
910 121 119	*	Center Conductor Forming Tool for female Mini Coax Contact
910 121 126	*	Outer Shield Conductor Forming Tool for Male Mini Coax Contact
910 121 131	*	Weight Gage Kit for female Mini Coax Contact
910 121 142	*	Outer Shield Conductor Expanding Tool for Male Mini Coax Contact
910 121 143	2038AS393	Center Conductor Enlargement Tool for Female Mini Coax Contact
910 121 155	*	Weight Gage Kit for male Mini Coax Contact
910 121 156	*	Inspection Gage Kit to verify depth setting for center conductor on female Mini Coax Contact
910 121 157	*	Inspection Gage to verify depth setting of conductor on male Mini Coax Contact

***Soldering Tools & Accessories***

<b>VPC P/N</b>	<b>CASS P/N</b>	<b>Description</b>
910 121 144	*	Solder Kit for Solder Sleeve Mini Coax Contact
910 121 147	*	Super Heater Gun with Reflector for Solder Sleeve Mini Coax Contact
910 121 148	*	Mini Heater Gun with Reflector for Solder Sleeve Mini Coax Contact
910 121 149	*	Holding Fixture Adapter for Solder Sleeve Mini Coax Contact

\* Indicates that no CASS P/N has been assigned to this part

**Installation/Removal — Section 2****Receiver Module Installation/Removal**

Place the Module in the Receiver until the upper and lower module screws touch the mating holes in the inner frame of the Receiver.

Using a 3/16" socket wrench, tighten the top screw while pushing lightly against the face of the module. Tighten the bottom screw. **Torque the screw until it is 3 to 4 inch pounds (clamping load 175 to 200 pounds).**

To remove, loosen the bottom screw completely. Then loosen top screw to remove module assembly.

**Caution - Improper installation/removal could result in the failure of the Jackscrew!**

**ID Module Installation/Removal**

Install the Module in the ID until the upper and lower module screws touch the mating holes in the inner frame of the ID.

Using a 7/64" hex wrench, tighten the top screw while pushing lightly against the face of the module. Tighten the bottom screw. **Torque the screw until it is 3 to 4 inch pounds (clamping load 175 to 200 pounds).**

To remove, loosen the bottom screw completely. Then loosen top screw to remove module assembly.

**Receiver Hi-Density Contact Removal**

Remove the two cap securing screws using a Phillips screwdriver (the Module does not have to be removed from the system). Remove the cap. Place the Signal Contact Extraction Tool (VPC P/N 910 110 102) over the Contact to be removed/replaced until the Tool touches the face of the Module - releasing the locking tab. Press on Tool. The spring action in the Tool will extract the Contact. Replace the Contact (if needed), cap and screws. **CAUTION - rotate tool slightly prior to pushing out contact to ensure that the retaining ring's ears have collapsed.**

When replacing the upper portion of the two piece Module, torque both screws 3 to 4 inch pounds using a Phillips screwdriver. Torque above 4 inch pounds can cause serious damage to Module lower portion.

**In order to maintain contact, float wires should be restrained a minimum of 2 inches from the back face of the Module by using a strain relief plate.**

**ID Hi-Density Contact Removal**

Place the Signal ID Extraction Tool (VPC P/N 910 110 102) over the Contact to be removed/replaced until the Tool touches the face of the Module - releasing the locking tab. Press on Tool. The spring action in the Tool will extract the Contact. On the rear side of the Module, grasp the Contact with your fingers and hold it while removing the Extraction Tool. This will avoid pulling the Contact back into a locked position. **CAUTION - rotate tool slightly prior to pushing out contact to ensure that the retaining ring's ears have collapsed.**

**Installation/Removal — Section 2****Receiver Contact Removal from Mini Coaxial and Power Modules**

For extraction of the Mini Coaxial and Power contacts remove the Module Cap, modules 510 113 120/1899AS266-02, 510 113 121/1899AS269-02 and 510 113 122/1899AS271-02 use three .086-56 UNC socket head cap screws (510 113 120/1899AS266-02 has an additional two screws due to the extra Hi-Density Power contacts' cap). Remove the socket head cap screws and the Cap. Use the Coaxial/Power Receiver Contact Extraction Tool (VPC P/N 910 112 104) and insert firmly over the Contact by applying pressure with the shaft. Apply pressure with the handle area only when the Tool has slipped over the retaining ring and has collapsed the tabs (twisting the lower portion of the tool will ensure that the tabs have collapsed). On the rear side of the Module, grasp the Contact with your fingers and hold it while removing the Tool. This will avoid pulling the Contact back into the locked position.

**ID Contact Removal from Mini Coaxial and Power Modules**

Use of the Coaxial/Power Receiver Contact Extraction Tool (VPC P/N 910 112 104):  
With the Tool held straight and parallel to the contacts, apply pressure to the handle area after the Tool has slipped over the retaining ring and has collapsed the locking tabs (twisting the lower portion of the tool will ensure that the locking tabs have collapsed). Damage can occur to the contacts if the Tool is not held parallel to the contacts.

**CAUTION**

**Never probe a contact without using a mating contact/patchcord as a probe to avoid damaging the contact(s) being tested.**

### General Operating Procedures and Precautions — Section 3

**Mounting an Enclosure on an ID** - The CASS specification requires stainless steel screws be used in certain IDs (P/N 410 113 111, 410 113 117 and 410 113 118), which has been known to cause self-locking helicoils to seize or pull out. It is recommended when using heat treated unplated or stainless steel screws, an anti-seize compound, e.g., molybden disulfide, must be used in order to minimize galling and assure maximum cycle life.



#### CAUTION

- *When engaging the ID with the Receiver, caution must be taken to ensure that the ID is parallel with the Receiver upon engagement and that the ID rollers are engaged at the same time!*
- *All power supplies for the system should be properly disconnected prior to handling. Caution should always be used when engaging, making sure that all foreign objects are removed from the system.*

### Engaging ID with Receiver

Listed below are the required steps to be taken prior to the engagement of the ID and Receiver.


1. The handle of the Receiver has been designed in such a way as to provide maximum leverage by allowing the handle to extend. The user can extend the Receiver's handle by pushing the slotted handle part up until it extends above the Receiver. The handle may now allow itself to be rotated to the lowered position, allowing the ID to be inserted.
2. Prior to engaging an ID with the Receiver for the first time, the user must check to see if all the Modules (ID and Receiver) have been installed properly. This would involve the inspection of the Module ends - ensuring the even height of all Module ends relative to one-another. While checking this, the user should verify the positioning of the modules themselves. **It is crucial for all modules to be installed properly!**  
Improper installation will cause damage to the modules and possibly to the ID and/or Receiver. All ID Modules have to match the Receiver Modules. This means that upon engaging, an ID Module will mate with its respective Receiver Module (Power ID to mate with Power Receiver, etc.).
3. The ID, upon being inspected, is now ready for engagement with the Receiver. The Receiver should be checked one last time for any foreign objects that may hinder the engagement. The top rollers of the ID may then be placed onto the Receiver's built-in "hangers" with the handle in the closed (and handle not extended) position. The ID may be engaged with the Receiver only if properly lined up - meaning that the ID must be placed onto the Receiver in the upright position. Care should be taken to have the top/side notch of the ID align for "mating" with the keying tab on the top of the Receiver.
4. Due to additional equipment being added onto the ID, the user may find that the ID and Receiver will not line up as described above. One reason may be that the additional weight on the ID will cause it to pull away from the Receiver at the top. **The user should apply pressure to the top of the ID to counter the weight that is pulling the top of the ID away from the Receiver (with the Receiver handle in the "open" position).** The user may then carefully engage the system by raising the handle until the handle makes contact with the Receiver. The handle may now be allowed to slide down to its storage position.

**In the event of complications, such as improper alignment of modules or the ID, a trained technician should be notified immediately to avoid any damage to the system. This should also apply to any difficulties that may be experienced during engagement.**


**NOTE:** The ID and Receiver have been cycled 36,000 times with a 25 lb. weight attached to the ID (extended 6 inches from center of ID) without having any of the contacts breaking continuity or having any parts of the system fail or show significant signs of wear. This life cycle test data may change if the weight of the ID is increased.

revised 11/21/01



**General Maintenance — Section 4****Care & Maintenance of Interface Device (ID)**

The CASS Interface System has been designed to be maintenance free, yet care does need to be taken when handling the ID.

**Micro-Switch Removal & Installation**

The CASS Interface System has been designed to be maintenance free. The only maintenance that is needed for the system to continue functioning effortlessly is the Micro-switch. For replacement of the Microswitch the following steps need to be followed.

1. Disengage the ID from the Receiver (remove the ID completely).
2. With the Receiver Handle still in the open position (Handle down), unscrew the two plate retaining screws (using a Phillips screwdriver) that are located immediately above the top right engaging mechanism/slot - this will expose the Microswitch.
3. Remove the necessary Modules so that the Microswitch retaining screws may be accessed.
4. Unscrew the retaining screws (using a Phillips screwdriver) removing each as they are loosened (caution should be used so that the screw(s) don't fall into the system).
5. Carefully remove the Microswitch for continuity testing.

For Microswitch installation, repeat steps 1-5 in reverse order.

Microswitch is P/N 010025.

**Wiring Assembly Requirements — Section 5**

Virginia Panel Corporation has been providing the ATE market with quality parts and accessories for several years. It is VPC's goal to continue to provide high performance and quality parts.

To ensure that the same level of quality is maintained, VPC expects from its Interface System users that all components used in operating, servicing and adjusting meet certain guidelines. These guidelines are available from VPC directly and are supplied with the Interface Systems.


VPC, in its attempt to perfect its product lines, takes field studies seriously. Observations have revealed that some users are not following VPC's procedures and are not using VPC tools for the proper assembly of the VPC Contacts. The user must strictly adhere to/follow the Assembly Instruction Sheets that are available from and provided by VPC.

The following Assembly Instructions Sheets are available:

Description	VPC P/N	CASS P/N
<b>Hi-Density</b>		
Hi-Density Signal ID	610 110 108	1899AS287-01
Hi-Density Signal Receiver	610 110 125	1899AS274-01
Hi-Density Power Receiver	610 110 174	1899AS268-01
Hi-Density Power ID	610 110 172	1899AS282-01
Hi-Density Signal ID	610 110 146	1899AS287-02
Hi-Density Power ID	610 110 173	1899AS282-02
<b>Solder Sleeve</b>		
Solder Sleeve Mini Coaxial ID for RG316	610 103 140	2038AS396-01
Solder Sleeve Mini Coaxial ID for RG178	610 103 140	2038AS396-01
Solder Sleeve Mini Coaxial Receiver for RG316	610 104 142	2038AS397-01
Solder Sleeve Mini Coaxial Receiver for RG178	610 104 142	2038AS397-01
Solder Sleeve Mini Coaxial ID for RG316	610 103 158	2038AS396-02
Solder Sleeve Mini Coaxial ID for RG178	610 103 158	2038AS396-02
<b>Mini Coaxial</b>		
Mini Coaxial Receiver Terminal (50 OHM) for RG316	610 104 114	1899AS270-01
Mini Coaxial Receiver Terminal (50 OHM) for RG178	610 104 141	1899AS270-02
Mini Coaxial ID Terminal (50 OHM) for RG316	610 103 115	1899AS284-01
Mini Coaxial ID Terminal (50 OHM) for RG178	610 103 130	1899AS284-02
Mini Coaxial ID Terminal (50 OHM) for RG178	610 103 157	1899AS284-03
Mini Coaxial ID Terminal (50 OHM) for RG316	610 103 159	1899AS284-04

## Wiring Assembly Instructions — Section 5 P/N 610 110 108, 610 110 125, 610 110 146 CASS P/N 1899AS287-01, 1899AS274-01, 1899AS287-02

Set up crimp tool P/N 910 101 103 (**Fig. A**) by loosening the latch locking screw (counter-clockwise, until turning stops). Remove any previously used crimp contact locator. Insert the open end of crimp contact locator P/N 910 104 107 into crimp tool contact locator retainer. Slide the retaining latch toward contact locator until contact locator is securely locked into place. The contact locator may have to be twisted to allow latch to retain contact locator. Tighten latch locking screw.




**Fig. A**

Using the table below, adjust the crimp tool setting by pulling adjusting knob and turning it at the same time (clockwise increases, counter-clockwise decreases setting) until the desired setting is achieved on the microcrimp indicator.

Wire Gauge	Strip Length +.05 -0.0	Crimp Max	Crimp Min.	Pullout force (lbs.)
18*	.25	.043	.041	10
20*	.25	.037	.033	10
22	.19	.033	.029	10
24	.19	.029	.025	8
26	.19	.024	.021	4
2-24	.25	.041	.037	8
2-26	.25	.036	.033	4


*\*Recommended maximum wire gauge is 22 AWG, however, 18 AWG and 20 AWG will work when crimped properly. It is preferred that wire 26 AWG or smaller be soldered.*

Using the table above, determine the strip length according to wire gauge. Strip wire. Fully insert stripped wire into contact P/N 610 110 146/1899AS287-02 or P/N 610 110 108/1899AS287-01 (**Fig. B**) P/N 610 110 125/1899AS274-01 (**Fig. C**). With the crimp tool in the open position, insert the prepared contact and wire through the indenter opening. While keeping the wire fully inserted into the contact, squeeze the handles of the crimp tool until a positive stop is reached. Tool will release and return into fully “open” position. Remove crimped contact and wire.



**Fig. B**

P/N 610 110 108/1899AS287-01/610 110 146/1899AS287-02



**Fig. C**

P/N 610 110 125/1899AS274-01


**NOTE: Always drop female contact (without wire attached) into contact locator, allowing it to orient/seat itself properly - squeeze handles of crimp tool slightly to hold contact in position while inserting wire. Note that tool cannot be opened without completing cycle. Never attempt to disassemble tool. Never tighten or loosen stop nuts on back of tool.** rev 11/06/2003

***Wiring Assembly Instructions — Section 5***

***P/N 610 110 172 & 610 110 173***

***CASS P/N 1899AS282-01 & 1899AS282-02***

Set up crimp tool P/N 910 101 102 (**Fig. A**) by loosening the latch locking screw (counter-clockwise, until turning stops). Remove any previously used crimp contact locator. Insert the open end of crimp contact locator P/N 910 104 118 into crimp tool contact locator retainer. Slide the retaining latch toward contact locator until contact locator is securely locked into place. The contact locator may have to be twisted to allow latch to retain contact locator. Tighten latch locking screw.




**Fig. A**

Using the table below, adjust the crimp tool setting by pulling adjusting knob and turning it at the same time (clockwise increases, counter-clockwise decreases setting) until the desired setting is achieved on the microcrimp indicator.

Wire Gauge	Strip Length +.05 -0.0	Crimp Max.	Crimp Min.	Pullout Force (lb.)
14	.20	.063	.059	10
16	.20	.059	.055	10
18	.20	.055	.051	10
2-20	.20	.055	.050	10
2-22	.20	.046	.042	10
1-22 & 1-24	.20	.041	.037	8

Using the table above, determine the strip length according to wire gauge. Strip wire. Fully insert stripped wire into contact P/N 610 110 172/1899AS282-01 or P/N 610 110 173/1899AS282-02 (**Fig. B**). With the crimp tool in the open position, insert the prepared contact and wire through the indenter opening. While keeping the wire fully inserted into the contact, squeeze the handles of the crimp tool until a positive stop is reached. Tool will release and return into fully “open” position. Remove crimped contact and wire.

**NOTE: Observe precision ratchet action by opening and closing tool fully several times. Note that tool cannot be opened without completing cycle. Never attempt to disassemble tool. Never tighten or loosen stop nuts on back of tool.**




**Fig. B**

***Wiring Assembly Instructions — Section 5***

***P/N 610 110 174***

***CASS P/N 1899AS268-01***

Set up crimp tool P/N 910 101 102 (**Fig. A**) by loosening the latch locking screw (counter-clockwise, until turning stops). Remove any previously used crimp contact locator. Insert the open end of crimp contact locator P/N 910 104 116 into crimp tool contact locator retainer. Slide the retaining latch toward contact locator until contact locator is securely locked into place. The contact locator may have to be twisted to allow latch to retain contact locator. Tighten latch locking screw.




**Fig. A**

Using the table below, adjust the crimp tool setting by pulling adjusting knob and turning it at the same time (clockwise increases, counter-clockwise decreases setting) until the desired setting is achieved on the microcrimp indicator.

Wire Gauge	Strip Length +.05 -0.0	Crimp Max.	Crimp Min.	Pullout Force (lbs.)
14	.20	.063	.059	10
16	.20	.059	.055	10

Using the table above, determine the strip length according to wire gauge. Strip wire. Fully insert stripped wire into contact P/N 610 110 174/1899AS268-01 (**Fig. B**). With the crimp tool in the open position, insert the prepared contact and wire through the indenter opening. While keeping the wire fully inserted into the contact, squeeze the handles of the crimp tool until a positive stop is reached. Tool will release and return into fully “open” position. Remove crimped contact and wire.



**Fig. B**

**NOTE: Always drop female contact (without wire attached) into contact locator, allowing it to orient/seat itself properly - squeeze handles of crimp tool slightly to hold contact in position while inserting wire. Note that tool cannot be opened without completing cycle. Never attempt to disassemble tool. Never tighten or loosen stop nuts on back of tool.**

**Wiring Assembly Instructions — Section 5**

VPC P/N 610 103 140/CASS P/N 2038AS396-01

P/N 610 103 158/CASS P/N 2038AS396-02 - RG316

**PARTS REQUIRED:**

- Solder Kit for Mini Coax includes holding fixture and adapter (P/N 910 121 144)
- Adapter (for those who already own a holding fixture) (P/N 910 121 149)
- Steinel Heat Gun with Reflector (P/N 910 121 160) or Raychem MiniGun Heater with Reflector (P/N 910 121 148)
- Mini Coax Contact (ID) Solder Sleeve (P/N 610 103 140 or 610 103 158)

**INSTRUCTIONS:**

1. Prepare the coaxial cable to the dimensions shown (**Fig. A**).
2. Straighten the center conductor making sure the stranded center conductor is twisted into its original lay.
3. Pre-tin stranded center conductor with Sn63 solder per QQ-S-571. Use RMA flux per MIL-F-14256 (Alpha #611 or equivalent).
4. Make sure the shield braid is trimmed evenly and no loose strands are extending out across the exposed dielectric or cable jacket.
5. Smooth the braid ends flat against the cable dielectric.
6. Slip the contact over the end of the prepared cable, and carefully push the contact onto the cable until it stops. Rotating the contact slightly during cable insertion will help prevent the braid from catching.
7. Inspect for proper insertion (**Fig. B**). The center conductor must be visible through one of the forward inspection windows. The distance from the rear of the contact outer body to the cable jacket insulation should be  $.065 \pm .015$ .
8. Install the adapter onto the holding fixture (**Fig. C**). Insert a contact in the adapter side marked "P" for pin and set up the dimensions as shown in **Figure C**.
9. Insert the contact/cable assembly into the adapter. Clamp the cable in the holding fixture. The cable must remain fully inserted in the contact and the contact must be fully inserted in the adapter (for the adapter to act as a heat sink). The cable must be straight between the contact and the cable clamp.
10. Attach the appropriate reflector to the heating tool (see separate **Heat Gun instruction sheet included with tool for tool operation and safety precautions**).
11. Using the holding fixture, position the contact in the heating tool reflector, with the forward inspection window centered in the reflector. Continue heating until the small solder preform in the forward inspection window has melted and flowed. The large solder preform in the rear inspection window should have melted and flowed by this time; if it has not, direct hot air at the rear inspection window until it does.
12. If contact is **UNDERHEATED**, there will be visible remnants of the original shapes of the solder preforms. An underheated contact must be reheated. If contact is **OVERHEATED**, solder will wick away from the joint areas, leaving no solder fillets. An overheated contact must be removed and a new contact installed.
13. After the contact has cooled for at least 10 seconds, remove the contact and cable from the holding fixture.
14. Inspect the completed termination for correct assembly. The cable shield must extend into the contact at least as far as the front edge of the rear inspection windows. The center conductor must be visible through one of the forward inspection windows.




Figure A




Figure B




Figure C

## Wiring Assembly Instructions — Section 5

VPC P/N 610 103 140/CASS P/N 2038AS396-01

P/N 610 103 158/CASS P/N 2038AS396-02-RG178

### PARTS REQUIRED:

- Solder Kit for Mini Coax includes holding fixture and adapter (P/N 910 121 144)
- Adapter (for those who already own a holding fixture) (P/N 910 121 149)
- Steinel Heat Gun with Reflector (P/N 910 121 160) or Raychem MiniGun Heater with Reflector (P/N 910 121 148)
- Mini Coax Contact (ID) Solder Sleeve (P/N 610 103 140 or 610 103 158)

### INSTRUCTIONS:

1. Strip the coaxial cable to the dimensions shown (**Fig. A**).
2. Straighten the center conductor making sure the stranded center conductor is twisted into its original lay.
3. Pretin stranded center conductor with Sn63 solder per QQ-S-571. Use RMA flux per MIL-F-14256 (Alpha #611 or equivalent).
4. Fold the center conductor back on itself as shown (**Fig. B**).
5. Make sure the shield braid is trimmed evenly and no loose strands are extending out across the exposed dielectric or cable jacket.
6. Smooth the braid ends flat against the cable jacket.
7. Slip the contact over the end of the prepared cable, and carefully push the contact onto the cable until it stops. Rotating the contact slightly during cable insertion will help prevent the braid from catching.
8. Inspect for proper insertion (**Fig. C**). The center conductor must be visible through one of the forward inspection windows. The distance from the rear of the contact outer body to the cable jacket insulation should be  $.015 \pm .015$ .
9. Install the adapter onto the holding fixture (**Fig. D**). Insert a contact in the adapter side marked "P" for Pin and set up the dimensions as shown in **Figure D**.
10. Insert the contact/cable assembly into the adapter. Clamp the cable in the holding fixture. The cable must remain fully inserted in the contact and the contact must be fully inserted in the adapter (for the adapter to act as a heat sink). The cable must be straight between the contact and the cable clamp.
11. Attach the appropriate reflector to the heating tool (**see separate Heat Gun instruction sheet included with tool for tool operation and safety precautions**).
12. Using the holding fixture, position the contact in the heating tool reflector, with the forward inspection window centered in the reflector. Continue heating until the small solder preform in the forward inspection window has melted and flowed. The large solder preform in the rear inspection window should have melted and flowed by this time; if it has not, direct hot air at the rear inspection window until it does.
13. If contact is UNDERHEATED, there will be visible remnants of the original shapes of the solder preforms. An underheated contact must be reheated. If contact is OVERHEATED, solder will wick away from the joint areas, leaving no solder fillets. An overheated contact must be removed and a new contact installed.
14. After the contact has cooled for at least 10 seconds, remove the contact and cable from the holding fixture.
15. Inspect the completed termination for correct assembly. The cable shield must extend into the contact at least as far as the front edge of the rear inspection windows. The center conductor must be visible through one of the forward inspection




Figure A




Figure B




Figure C




Figure D

Wiring Assembly Instructions — Section 5

VPC P/N 610 104 142 - CASS P/N 2038AS397-01 RG316

**PARTS REQUIRED:**

- Solder Kit for Mini Coax includes holding fixture and adapter (P/N 910 121 144)
- Adapter (for those who already own a holding fixture) (P/N 910 121 149)
- Steinel Heat Gun with Reflector (P/N 910 121 160) or Raychem MiniGun Heater with Reflector (P/N 910 121 148)
- Mini Coax Contact (Receiver) Solder Sleeve (P/N 610 104 142)

**INSTRUCTIONS:**

1. Prepare the coaxial cable to the dimensions shown (**Fig. A**).
2. Straighten the center conductor making sure the stranded center conductor is twisted into its original lay.
3. Pre-tin stranded center conductor with Sn63 solder per QQ-S-571. Use RMA flux per MIL-F-14256 (Alpha #611 or equivalent).
4. Make sure the shield braid is trimmed evenly and no loose strands are extending out across the exposed dielectric or cable jacket.
5. Smooth the braid ends flat against the cable dielectric.
6. Slip the contact over the end of the prepared cable, and carefully push the contact onto the cable until it stops. Rotating the contact slightly during cable insertion will help prevent the braid from catching.
7. Inspect for proper insertion (**Fig. B**). The center conductor must be visible through one of the forward inspection windows. The distance from the rear of the contact outer body to the cable jacket insulation should be  $.065 \pm .015$ .
8. Install the adapter onto the holding fixture (**Fig. C**). Insert a contact in the adapter side marked "S" for Socket and set up the dimensions as shown in **Figure C**.
9. Insert the contact/cable assembly into the adapter. Clamp the cable in the holding fixture. The cable must remain fully inserted in the contact and the contact must be fully inserted in the adapter (for the adapter to act as a heat sink). The cable must be straight between the contact and the cable clamp.
10. Attach the appropriate reflector to the heating tool (**See separate instructions sheet included with tool for tool operation and safety precautions**).
11. Using the holding fixture, position the contact in the heating tool reflector, with the forward inspection window centered in the reflector. Continue heating until the small solder preform in the forward inspection window has melted and flowed. The large solder preform in the rear inspection window should have melted and flowed by this time; if it has not, direct hot air at the rear inspection window until it does.
12. If contact is **UNDERHEATED**, there will be visible remnants of the original shapes of the solder preforms. An underheated contact must be reheated. If contact is **OVERHEATED**, solder will wick away from the joint areas, leaving no solder fillets. An overheated contact must be removed and a new contact installed.
13. After the contact has cooled for at least 10 seconds, remove the contact and cable from the holding fixture.
14. Inspect the completed termination for correct assembly. The cable shield must extend into the contact at least as far as the front edge of the rear inspection windows. The center conductor must be visible through one of the forward inspection windows.




Figure A




Figure B




Figure C



## Wiring Assembly Instructions — Section 5

VPC P/N 610 104 142 - CASS P/N 2038AS397-01 RG178

### PARTS REQUIRED:

- Solder Kit for Mini Coax includes holding fixture and adapter (P/N 910 121 144)
- Adapter (for those who already own a holding fixture) (P/N 910 121 149)
- Steinel Heat Gun with Reflector (P/N 910 121 160) or Raychem MiniGun Heater with Reflector (P/N 910 121 148)
- Mini Coax Contact (Receiver) Solder Sleeve (P/N 610 104 142)

### INSTRUCTIONS:

1. Strip the coaxial cable to the dimensions shown (Fig. A).
2. Straighten the center conductor making sure the stranded center conductor is twisted into its original lay.
3. Pre-tin stranded center conductor with Sn63 solder per QQ-S-571. Use RMA flux per MIL-F-14256 (Alpha #611 or equivalent).
4. Fold the center conductor back on itself as shown (Fig. B).
5. Make sure the shield braid is trimmed evenly and no loose strands extend out across the exposed dielectric or cable jacket.
6. Smooth the braid ends flat against the cable jacket.
7. Slip the contact over the end of the prepared cable, and carefully push the contact onto the cable until it stops. Rotating the contact slightly during cable insertion will help prevent the braid from catching.
8. Inspect for proper insertion (Fig. C). The center conductor must be visible through one of the forward inspection windows. The distance from the rear of the contact outer body to the cable jacket insulation should be  $.015 \pm .015$ .
9. Install the adapter onto the holding fixture (Fig. D). Insert a contact in the adapter side marked "S" for socket and set up the dimensions as shown in Figure D.
10. Insert the contact/cable assembly into the adapter. Clamp the cable in the holding fixture. The cable must remain fully inserted in the contact and the contact must be fully inserted in the adapter (for the adapter to act as a heat sink). The cable must be straight between the contact and the cable clamp.
11. Attach the appropriate reflector to the heating tool (See separate Heat Gun instruction sheet included with tool for tool operation and safety precautions).
12. Using the holding fixture, position the contact in the heating tool reflector, with the forward inspection window centered in the reflector. Continue heating until the small solder preform in the forward inspection window has melted and flowed. The large solder preform in the rear inspection window should have melted and flowed by this time; if it has not, direct hot air at the rear inspection window until it does.
13. If contact is UNDERHEATED, there will be visible remnants of the original shapes of the solder preforms. An underheated contact must be reheated. If contact is OVERHEATED, solder will wick away from the joint areas, leaving no solder fillets. An overheated contact must be removed and a new contact installed.
14. After the contact has cooled for at least 10 seconds, remove the contact and cable from the holding fixture.
15. Inspect the completed termination for correct assembly. The cable shield must extend into the contact at least as far as the front edge of the rear inspection windows. The center conductor must be visible through one of the forward inspection windows.




Figure A




Figure B




Figure C




Figure D

**Wiring Assembly Instructions — Section 5****VPC P/N 610 104 114 - CASS P/N 1899AS270-01 RG316****VPC Tools Required**

For the assembly of the Mini-Coaxial Contact VPC P/N 610 104 114/CASS P/N 1899AS270-01 the following parts are required by VPC:

**Tools:**

<b>P/N</b>	<b>Description</b>
910 121 143	Center conductor enlargement tool for female mini coax contact
910 121 119	Center conductor forming tool for mini coax contact
910 101 115	Hex crimp tool kit for mini coax contact
254108	Hex crimp tool die (part of 910 101 115)
254117	Hex crimp tool handle (part of 910 101 115)

**Gages & Weights**

<b>P/N</b>	<b>Description</b>
910 121 156	Inspection gage to verify depth setting of center conductor on female mini coax contact
910 121 131	Weight gage kit for female mini coax contact
432026000	4.0 oz. weight - part of kit P/N 910 121 131 with tip "B" (432046102)
432025000	0.5 oz. weight - part of kit P/N 910 121 131 with tip "A" (432044102)


**CAUTION**

**Never probe a contact without using a mating contact/patchcord as a probe to avoid damaging the contact(s) being tested.**


***Wiring Assembly Instructions — Section 5***

**VPC P/N 610 104 114 - CASS P/N 1899AS270-01 - RG316**


1. Strip the outer insulation, cut braid and expose the conductor wire as shown (**Fig. A**).




2. Slide the crimp ring onto the wire (**Fig.B**).




3. Turn braid back over outer insulation (**Fig. C**).



4. Solder wire into center conductor and clean (**Fig. D**). Cut a 3/16" long piece of solder and place it into the center conductor. Apply heat, using a soldering iron, on the outside of the contact until the solder melts. Insert wire into contact while heat is still being applied until an acceptable solder joint is obtained. Note: Center conductor and dielectric must touch.



5. Slide shield conductor over center conductor until the center conductor stops in the Teflon® shield (**Fig. E**). Note: Shield Conductor and Teflon® insulator are supplied as an assembly.




**Wiring Assembly Instructions — Section 5**

**VPC P/N 610 104 114 - CASS P/N 1899AS270-01 - RG316**


6. Calibrate gage P/N 910 121 156 (**Fig. F**) by loosening the dial face retaining screw until the dial face allows itself to be turned. Insert the calibration plug (P/N 414 854 104) into base of gage. While keeping constant pressure on the plug, adjust the dial by rotating it such that the pointer points to "0". Re-tighten retaining screw. Adjust locating markers to "80" and "40".

7. Check  $.06 \pm .02$  dimensions (**Fig. G**) with P/N 910 121 156 (**Fig. F**). Push the contact onto the pressure plunger of the gage (**Fig. F**). After attaining positive stop and while holding firm pressure, push plunger on top of dial (to push collar over Teflon), read the dial on the gage. Go to step 8 if the indicator is between the two marker bands ("80" & "40"). Repeat steps 1-6 should the range of dimensions not meet the criterion.

8. Check minimum extraction force of 1/2 ounce with 432025000 Assembly (**Fig. H**). Slide female center conductor over approximately 3/4 of the length of the tip in the weight gage (**Fig. I**).




**Fig. F**




**Fig. G**

The weight gage should remain mated with the center conductor as the center conductor is slowly lifted and suspended in the air. If weight gage remains mated, move to step 9.


If weight gage falls off, the extraction force is too low and the center conductor needs to be closed with the center conductor forming tool (P/N 910 121 119) (**Fig. J**). Recheck 1/2 ounce retention force.



**Fig. H**



**Fig. I**




**Fig. J**

con't page 18  
revised 11/21/01

**Wiring Assembly Instructions — Section 5**

**VPC P/N 610 104 114 - CASS P/N 1899AS270-01 - RG316**

9. Check maximum extraction force of 4 ounces with 432026000. Slide female center conductor over approximately 3/4 of the length of the tip in the weight gage (**Fig. K**). The weight gage should fall off the contact as the contact is slowly lifted and suspended in the air. If weight gage falls off move to step 10. If weight gage remains mated with contact, the extraction force is too high and the center conductor needs to be opened with the center conductor enlarging tool (P/N 910 121 143) (**Fig. L**).




**Fig. L**


Use Caution when using this tool. Insert and remove tool inline with contact to avoid breaking tip of tool or contact!

To enlarge the center conductor, remove it from shield assembly and gently insert the Enlarging Tool into the Center Conductor. Insert Enlarging Tool until Center Conductor stops on shoulder. Be careful not to break or fracture Center Conductor. Recheck 0.5 and 4 ounce retention force - go to step 8.

10. Turn braid back toward the front of the shield conductor (**Fig. M**).



**Fig. M**




**Fig. K**


11. If braid extends beyond shoulder, trim braid back to face of shoulder.

12. Slide crimp ring into position over the braid.


13. Crimp using the Hex Crimp Tool (P/N 910 101 115) (**Fig. N**) - in Hex Position A for the larger end first and in Hex position B for the smaller section of the crimp ring of 1899AS270-01 (**Fig. O**). To ensure proper crimp position, slide shield conductor over pin on locator (**Fig. P**). Wire must not be allowed to pull on center conductor during crimping (for example, long wire hanging down to floor).



**Fig. O**



**Fig. N**



**Fig. P**

con't page 19  
revised 11/21/01

**Wiring Assembly Instructions — Section 5****VPC P/N 610 104 114 - CASS P/N 1899AS270-01 - RG316**

14. Repeat step 7 to verify  $.06 \pm .02$  dimension with P/N 910 121 156.
15. During installation of contact into module listen for retaining clip ears to spring out, then push on front of contact to ensure that it is locked into position.

**Wiring Assembly Instructions — Section 5****VPC P/N 610 104 141 - CASS P/N 1899AS270-02 - RG178****VPC Tools Required**

For the assembly of the Mini-Coaxial Contact VPC P/N 610 104 141/CASS P/N 1899AS270-02 the following parts are required by VPC:

**Tools:**

<b>P/N</b>	<b>Description</b>
910 121 143	Center conductor enlargement tool for female mini coax contact
910 121 119	Center conductor forming tool for mini coax contact
910 101 115	Hex crimp tool kit for mini coax contact
254108	Hex crimp tool die (part of 910 101 115)
254117	Hex crimp tool handle (part of 910 101 115)

**Gages & Weights:**

<b>P/N</b>	<b>Description</b>
910 121 156	Inspection gage to verify depth setting of center conductor on female mini coax contact
910 121 131	Weight gage kit for female mini coax contact
432026000	4.0 oz. weight - part of kit P/N 910 121 131 with tip "B" (432046102)
432025000	0.5 oz. weight - part of kit P/N 910 121 131 with tip "A" (432044102)


**CAUTION**

**Never probe a contact without using a mating contact/patchcord as a probe to avoid damaging the contact(s) being tested.**

**Wiring Assembly Instructions — Section 5**


**VPC P/N 610 104 141 - CASS P/N 1899AS270-02 - RG178**

1. Strip the outer insulation, cut braid and expose the conductor wire as shown (**Fig. A**).



**Fig. A**


2. Slide the crimp ring onto the wire (**Fig.B**).



**Fig. B**


3. Turn braid back over outer insulation (**Fig. C**).

4. Solder wire into center conductor and clean (**Fig. C**). Note: Center conductor and dielectric must touch.




**Fig. C**

5. Slide the spacer tube over dielectric to edge of the braid (**Fig. D**). Heat spacer tube with a heat gun until it has shrunk to hold on to dielectric.



**Fig. D**

6. Slide shield conductor over center conductor until the center conductor stops in the Teflon® shield. To ensure that coaxial cable has been fully inserted into contact, ensure that a gap is between shielding and contact when achieving positive stop (**Fig. E**). Note: Shield Conductor and Teflon® insulator are supplied as an assembly.




**Fig. E**



**Wiring Assembly Instructions — Section 5**


**VPC P/N 610 104 141- CASS P/N 1899AS270-02 - RG178**

7. Calibrate gage P/N 910 121 156 (**Fig. F**) by loosening the dial face retaining screw until the dial face allows itself to be turned. Insert the calibration plug (P/N 414854104) into base of gage. While keeping constant pressure on the plug, adjust the dial by rotating it such that the pointer points to "0". Re-tighten retaining screw. Adjust locating markers to "80" and "40".



**Fig. F**


8. Check  $.06 \pm .02$  dimensions (**Fig. G**). Push the contact onto the pressure plunger of the gage (**Fig. F**). After attaining positive stop and while holding firm pressure, push plunger on top of dial (to push collar over Teflon), read the dial on the gage.



**Fig. G**


Go to step 9 if the indicator is between the two marker bands ("80" & "40"). Repeat steps 1-6 should the range of dimensions not meet the criterion.

9. Check minimum extraction force of 0.5 ounce with 432025000 Assembly (**Fig. H**). Slide female center conductor over approximately 3/4 of the length of the tip in the weight gage (**Fig. I**). The weight gage should remain mated with the center conductor as the center conductor is slowly lifted and suspended in the air. If weight gage remains mated, move to step 10.




**Fig. H**

If weight gage falls off, the extraction force is too low and the center conductor needs to be closed with the center conductor forming tool (P/N 910 121 119) (**Fig. J**). Recheck 0.5 ounce retention force.



**Fig. I**



**Fig. J**

Wiring Assembly Instructions — Section 5

VPC P/N 610 104 141 - CASS P/N 1899AS270-02 - RG178

10. Check maximum extraction force of 4 ounces with tip "B" 432046102 in 432025000 attached to 432026000. Slide female center conductor over approximately 3/4 of the length of the tip in the weight gage (Fig. K). The weight gage should fall off the contact as the contact is slowly lifted and suspended in the air. If weight gage falls off move to step 11. If weight gage remains mated with contact, the extraction force is too high and the center conductor needs to be opened with the center conductor enlarging tool (P/N 910 121 143) (Fig. L).



Fig. L

Use caution when using this tool. Insert and remove tool in-line with contact to avoid breaking tip of tool or contact!




Fig. K

To enlarge the center conductor, remove it from shield assembly and gently insert the Enlarging Tool into the Center Conductor. Insert Enlarging Tool until Center Conductor stops on shoulder. Be careful not to break or fracture Center Conductor. Recheck 0.5 and 4 ounce retention force - go to step 9.

11. Turn braid back toward the front of the shield conductor (Fig. M).




Fig. M

12. If braid extends beyond shoulder, trim braid back to face of shoulder.

13. Slide crimp ring into position over the braid.

14. Crimp using the Hex Crimp Tool (P/N 910 101 115) (Fig. N) - in Hex Position A for the larger end first and in Hex position C for the smaller section of the crimp ring of 1899AS270-02 (Fig. O). To ensure proper crimp position, slide shield conductor over pin on locator (Fig. P). Wire must not be allowed to pull on center conductor during crimping (for example, long wire hanging down to floor).




Fig. N




Fig. O




Fig. P

con't page 24  
revised 11/21/01

**Wiring Assembly Instructions — Section 5****VPC P/N 610 104 141 - CASS P/N 1899AS270-02 - RG178**

15. Repeat step 8 to verify  $.06 \pm .02$  dimension with P/N 910 121 156.
16. During installation of contact into module listen for retaining clip ears to spring out, then push on front of contact to ensure that it is locked into position.

**Wiring Assembly Instructions — Section 5****P/N 610 103 115 - CASS P/N 1899AS284-01 - RG316****P/N 610 103 159 - CASS P/N 1899AS284-04 - RG316****VPC Tools Required**

For the assembly of the Mini-Coaxial Contact(s) VPC P/N 610 103 115/CASS P/N 1899AS284-01 and/or P/N 610 103 159/1899AS284-04 the following parts are required by VPC:

**Tools:**

<b>P/N</b>	<b>Description</b>
910 121 142	Outer shield conductor expanding tool for male mini coax contact
910 121 126	Outer shield conductor forming tool for male mini coax contact
910 101 115	Hex crimp tool kit for mini coax contact
254108	Hex crimp tool die - part of 910 101 115
254117	Hex crimp tool handle - part of 910 101 115

**Gages & Weights:**


<b>P/N</b>	<b>Description</b>
910 121 157	Inspection gage to verify depth setting of center conductor on male mini coax contact
910 121 155	Weight gage kit for male mini coax contact
414853000	20 oz. weight - part of kit P/N 910 121 155
414852000	3 oz. weight - part of kit P/N 910 121 155

**CAUTION**


**Never probe a contact without using a mating contact/patchcord as a probe to avoid damaging the contact(s) being tested.**

***Wiring Assembly Instructions — Section 5***  
***P/N 610 103 115 - CASS P/N 1899AS284-01 - RG316***  
***P/N 610 103 159 - CASS P/N 1899AS284-04 - RG316***


1. Strip the outer insulation, cut braid and expose the conductor wire as shown (**Fig. A**).




2. Slide the crimp ring onto the wire (**Fig.B**).




3. Turn braid back over outer insulation (**Fig. C**).




4. Solder wire into center conductor and clean (**Fig. D**). Cut a 3/16" long piece of solder and place it into the center conductor. Apply heat, using a soldering iron, on the outside of the contact until the solder melts. Insert wire into contact while heat is still being applied until an acceptable solder joint is obtained. Note: Center conductor and dielectric must touch.



5. Slide shield conductor over center conductor until the center conductor stops in the Teflon® shield (**Fig. E**). Note: Shield Conductor and Teflon® insulator are supplied as an assembly.





6. Turn braid back toward the front of the shield conductor (**Fig. F**). If braid extends beyond shoulder, trim back to face of shoulder.



con't page 27  
 revised 01/05/04

**Wiring Assembly Instructions — Section 5**  
**P/N 610 103 115 - CASS P/N 1899AS284-01 - RG316**  
**P/N 610 103 159 - CASS P/N 1899AS284-04 - RG316**




7. Calibrate gage P/N 910 121 157 (**Fig. G**) by loosening the dial face retaining screw until the dial face allows itself to be turned. Insert the calibration plug (P/N 414855103) into base of gage. While keeping constant pressure on the plug, adjust the dial by rotating it such that the pointer points to "0". Re-tighten retaining screw. Adjust locating markers to "90" and "20".



8. Check  $.01 + .01 - .02$  dimension (**Fig. H**) by using P/N 910 121 157 (**Fig. G**). Insert contact into gage until contact stops. If pointer is between the two markers ("90" & "20"), go to step 9. If the pointer is out of the range of the two markers, check dimensions and/or repeat steps 1-7.

9. Slide crimp ring into position over the braid (**Fig. I**).


10. Crimp using the Hex Crimp Tool 910 101 115 (**Fig. J**) - in Hex Position A for the larger end first and in Hex position B for the smaller section of the crimp ring for 1899AS284-01 (**Fig. I**). To ensure proper crimp position, slide shield conductor over pin on locator (**Fig. K**). Wire must not be allowed to pull on the center conductor during crimping (for example, long wire hanging down to floor).




**Wiring Assembly Instructions — Section 5**  
**P/N 610 103 115 - CASS P/N 1899AS284-01 - RG316**  
**P/N 610 103 159 - CASS P/N 1899AS284-04 - RG316**

11. Check minimum extraction force of 3 ounces with P/N 414852000 (**Fig. L**). Slide contact into tip of weight gage. Insert approximately .15" into tip - be careful not to insert chamfer of contact into tip of weight gage. (**Fig M**). The weight gage should remain mated with the contact as the contact is slowly lifted and suspended in the air. If weight gage remains mated move to step 12.

If weight gage falls off, the extraction force is too low and the shield conductor needs to be opened up with the outer shield conductor enlarging tool P/N 910 121 142 (**Fig. N**).



**Fig. L**



**Fig. M**



**Fig. N**


To enlarge the shield conductor, gently insert the enlarging tool into the contact. Be careful not to bend the contact center conductor. Once inserted into the contact, pivot the enlarging tool to increase the shield diameter. Repeat until 3 ounce weight gage can be held by contact.

12. Check maximum extraction force of 20 ounces with P/N 414853000 (**Fig. O**).


Slide contact into tip of weight gage. Insert approximately .15" into tip - be careful not to insert chamfer of contact into tip of weight gage (**Fig. P**).

The weight gage should fall off the contact as the contact is slowly lifted and suspended in the air. If weight gage falls off move to step 13. If weight gage remains mated with contact, the extraction force is too high and the shield conductor needs to be closed with the outer shield conductor forming tool P/N 910 121 126 (**Fig. Q**).


Squeezing the tool handles will reposition the contact legs. This procedure should be done in three different locations (approximately 120° apart) on the same shield to obtain proper sizing. Repeat steps 11 and 12.



**Fig. O**



**Fig. P**



**Fig. Q**

**Wiring Assembly Instructions — Section 5*****P/N 610 103 115 - CASS P/N 1899AS284-01 - RG316******P/N 610 103 159 - CASS P/N 1899AS284-04 - RG316***

13. Use P/N 910 121 157 to check .010 + .01 -.02 dimension (See step 8).
  
14. During installation of contact into module listen for retaining clip ears to spring out, then push on front of contact to ensure that it is locked into position.



**Wiring Assembly Instructions — Section 5*****P/N 610 103 130 - CASS P/N 1899AS284-02 - RG178******P/N 610 103 157 - CASS P/N 1899AS284-03 - RG178*****VPC Tools Required**

For the assembly of the Mini-Coaxial Contact VPC P/N 610 103 130/CASS P/N 1899AS284-02 and VPC P/N 610 103 157/CASS P/N 1899AS284-03 the following parts are required by VPC:

**Tools:**

<b>P/N</b>	<b>Description</b>
910 121 142	Outer shield conductor expanding tool for male mini coax contact
910 121 126	Outer shield conductor forming tool for male mini coax contact
910 101 115	Hex crimp tool kit for mini coax contact
254108	Hex crimp tool die part of 910 101 115
254117	Hex crimp tool handle part of 910 101 115

**Gages & Weights:**


<b>P/N</b>	<b>Description</b>
910 121 157	Inspection gage to verify depth setting of conductor on male mini coax contact
910 121 155	Weight gage kit for male mini coax contact
414853000	20 oz. weight - part of kit P/N 910 121 155
414852000	3 oz. weight - part of kit P/N 910 121 155

**CAUTION**


**Never probe a contact without using a mating contact/patchcord as a probe to avoid damaging the contact(s) being tested.**

**Wiring Assembly Instructions — Section 5**  
**P/N 610 103 130 - CASS P/N 1899AS284-02 - RG178**  
**P/N 610 103 157 - CASS P/N 1899AS284-03 - RG178**

1. Strip the outer insulation, cut braid and expose the conductor wire as shown (**Fig. A**).




2. Slide the crimp ring onto the wire (**Fig.B**).




**Fig. B**

3. Turn braid back over outer insulation (**Fig. C**).


4. Solder wire into center conductor and clean (**Fig. C**). Note: Center conductor and dielectric must touch.



5. Slide the spacer tube over dielectric to edge of the braid (**Fig. D**). Heat spacer tube with a heat gun until it has shrunk to hold on to dielectric.




6. Slide shield conductor over center conductor until the center conductor stops in the Teflon® shield. To ensure that coaxial cable has been fully inserted into contact, ensure that a gap is between shielding and contact when achieving positive stop (**Fig. E**) Note: Shield Conductor and Teflon® insulator are supplied as an assembly.



**Fig. E**

7. Turn braid back toward the front of the shield conductor (**Fig. F**). If braid extends beyond shoulder, trim back to face of shoulder.



**Fig. F**


con't page 32  
 revised 11/21/01

## Wiring Assembly Instructions — Section 5

P/N 610 103 130 - CASS P/N 1899AS284-02 - RG178


P/N 610 103 157 - CASS P/N 1899AS284-03 - RG178

8. Calibrate gage P/N 910 121 157 (**Fig. G**) by loosening the dial face retaining screw until the dial face allows itself to be turned. Insert the calibration plug (P/N 414 855 103) into base of gage. While keeping constant pressure on the plug, adjust the dial by rotating it such that the pointer points to "0". Re-tighten retaining screw. Adjust locating markers to "90" and "20".




**Fig. G**

9. Check  $.01 + .01 - .02$  dimensions (**Fig. H**) by using P/N 910 121 157 (**Fig. I**). Insert contact into gage and push contact into collar until contact stops. If pointer is between the two markers, go to step 10. If the pointer is out of the range of the two markers, check dimensions and/or repeat steps 1-7.




**Fig. H**

10. Slide crimp ring into position over the braid (**Fig. I**).




**Fig. I**

11. Crimp using the Hex Crimp Tool (**Fig. J**) - in Hex Position A for the larger end first, and in Hex Position C for the smaller section of the crimp ring for 1899AS284-02 (**Fig. I**). To ensure proper crimp position, slide shield conductor over pin on locator (**Fig. K**). Wire must not be allowed to pull on the center conductor during crimping ( for example, long wire hanging down to floor).



**Fig. J**



**Fig. K**


**Wiring Assembly Instructions — Section 5**  
**P/N 610 103 130 - CASS P/N 1899AS284-02 - RG178**  
**P/N 610 103 157 - CASS P/N 1899AS284-03 - RG178**

12. Check minimum extraction force of 3 ounces with P/N 414 852 000 (**Fig L**). Slide contact into tip of weight gage. Insert approximately .15" into tip - be careful not to insert chamfer of contact into tip of weight gage. (**Fig. M**). The weight gage should remain mated with the contact as the contact is slowly lifted and suspended in the air. If weight gage remains mated move to step 13.


If weight gage falls off, the extraction force is too low and the shield conductor needs to be opened with the outer shield conductor enlarging tool (P/N 910 121 142) (**Fig. N**).



**Fig. N**



**Fig. L**



**Fig. M**


To enlarge the shield conductor, gently insert the enlarging tool into the contact. Be careful not to bend the contact center conductor. Once inserted into the contact, pivot the enlarging tool to increase the shield diameter. Repeat until 3 ounce weight gage can be held by contact.

13. Check maximum extraction force of 20 ounces with P/N 414853000 (**Fig. O**).


Slide contact into tip of weight gage. Insert approximately .15" into tip - be careful not to insert chamfer of contact into tip of weight gage (**Fig. P**).

The weight gage should fall off the contact as the contact is slowly lifted and suspended in the air. If weight gage falls off move to step 14. If weight gage remains mated with contact, the extraction force is too high and the shield conductor needs to be closed with the outer shield conductor forming tool P/N 910 121 126 (**Fig. Q**).


Squeezing the tool handles will reposition the contact legs. This procedure should be done in three different locations (approximately 120° apart) on the same shield to obtain proper sizing. Repeat steps 12 and 13.



**Fig. Q**



**Fig. O**



**Fig. P**

**Wiring Assembly Instructions — Section 5*****P/N 610 103 130 - CASS P/N 1899AS284-02 - RG178******P/N 610 103 157 - CASS P/N 1899AS284-03 - RG178***

14. Use P/N 910 121 157 to check .010 +.010 -.020 dimension ( See step 9).
  
15. During installation of contact into module listen for retaining clip ears to spring out, then push on front of contact to ensure that it is locked into position.

**Trouble-Shooting and Solutions — Section 6****•ID or Receiver Modules are Installed up-side-down**

- ! The orientation of the Modules is critical! Those Modules that are improperly installed will need to be removed and oriented properly ( See Section 2).
- ! Forceful engagement of the Receiver and the ID may result in serious damage to multiple parts of the system (Modules, Receiver, ID and Contacts)!

**•ID Engagement Bearings/Studs are not lining up with the Engagement Slots of the Receiver**

- ! Check the alignment of the ID Frame. There is a possibility that the ID Frame will have misaligned itself if it is dropped (See enclosed diagrams). Contact Virginia Panel Corporation - user adjustments to System, unless authorized, will void the warranty.
- ! Forceful engagement of the Receiver and the ID may result in serious damage to multiple parts of the system (Modules, Receiver, ID and Contacts)!

**•ID Frame is not lined up while in the process of engagement with the Receiver**

- ! This may indicate that the ID was dropped and is out of alignment or that a Module is not mating with its intended Module. Remove and inspect the ID for alignment (See enclosed diagrams). Contact Virginia Panel Corporation - user adjustments to System, unless authorized, will void the warranty.
- ! Check for foreign objects/tools.
- ! Verify the orientation of the Receiver and ID Modules (See Section 2).
- ! Inspect the mating of Modules - Power ID Module to mate with Power Receiver Module, etc. (See Section 2).
- ! Forceful engagement of the Receiver and the ID may result in serious damage to multiple parts of the system (Modules, Receiver, ID and Contacts)!

**•Excessive force on the Handle is needed to engage system**

- ! This may indicate that the ID was dropped and is out of alignment or that a Module is not mating with its intended Module. Remove and inspect the ID for alignment (See enclosed diagrams). Contact Virginia Panel Corporation - user adjustments to System, unless authorized, will void the warranty.
- ! Check for foreign objects/tools.
- ! A damaged Contact(s) may provide enough resistance to notice. Upon replacing a Contact in the ID, the mating Contact on the other side (Receiver Contact) should also be inspected and replaced if necessary (See Section 2).
- ! Verify the orientation of the Receiver and ID Modules (See Section 2).
- ! Inspect the mating of Modules - Power ID Module to mate with Power Receiver Module, etc. (See Section 2).
- ! Forceful engagement of the Receiver and the ID may result in serious damage to multiple parts of the system ( Modules, Receiver, ID and Contacts)!

**Trouble-Shooting and Solutions — Section 6*****ID will not engage with the Receiver after diagnosing the above problems***

- ! Check the System for foreign objects.
- ! Check the alignment of the ID Frame. There is possibility that the ID Frame could have misaligned itself if it was dropped (See enclosed diagrams). Contact Virginia Panel Corporation - user adjustments to System, unless authorized, will void the warranty.

***No continuity upon engagement***

- ! Upon replacing a Contact in the ID, the mating Contact on the Receiver side (Receiver Contact) should also be inspected and replaced if necessary (See Section 2).
- ! Check Wiring - replace if necessary.

***A "short" in the wiring upon engagement***

- ! A damaged Contact(s) may provide enough resistance to notice. Upon replacing a Contact in the ID, the mating Contact on the Receiver side (Receiver Contact) should also be inspected and replaced if necessary (See Section 2).
- ! Check wiring - replace if necessary.

***Receiver and ID will not disengage***

- ! This may indicate that the Engagement Mechanism within the Receiver is faulty - contact Virginia Panel Corporation immediately - user adjustments to System, unless authorized, will void the warranty.

**VPC may be contacted at the following telephone number and address:**

Virginia Panel Corporation  
1400 New Hope Road  
Waynesboro, VA 22980

Tel: (540) 932 - 3300  
Fax: (540) 932 - 3369

***Product Cross Reference — Section 7***

The purpose of the cross-reference tables are to provide the user with quick identification of necessary parts and/or tools. It matches the tools with their respective parts for more comprehensive replacements, insertions or configurations.

	Receiver Modules					Crimp Tools & Dies					Extraction Tools		Misc. Tools		Q.C. Tools	
Receiver Contacts & Patchcords	510 113 124/1899AS275-02	510 113 125/1899AS273-02	510 113 120/1899AS266-02	510 113 121/1899AS269-02	510 113 122/1899AS271-02	910 101 102	910 101 103	910 101 115	910 104 107	910 104 116	910 110 102	910 112 104	910 121 119	910 121 143/2038AS393	910 121 156	910 121 131
610 104 114 1899AS270-01				•	•			•				•	•	•	•	•
610 104 141 1899AS270-02				•	•			•				•	•	•	•	•
610 110 122 1899AS276-01	•										•					
610 110 123 1899AS276-02	•										•					
610 110 124 1899AS276-03	•										•					
610 110 125 1899AS274-01		•	•				•		•		•					
610 110 174 1899AS268-01		•	•			•				•	•					
610 116 112 1899AS267-01			•									•				



*Product Cross Reference — Section 7*


	ID Modules				Crimp Tools & Dies					Extraction Tools		Misc. Tools		Q.C. Tools	
ID Contacts & Patchcords	510 114 106/1899AS286-01	510 114 107/1899AS280-01	510 114 108/1899AS283-01	510 114 109/1899AS285-01	910 101 102	910 101 103	910 101 115	910 104 107	910 104 118	910 110 102	910 112 104	910 121 126	910 121 142/2038AS394	910 121 155	910 121 157
610 103 115 1899AS284-01			•	•			•				•	•	•	•	•
610 103 130 1899AS284-02			•	•			•				•	•	•	•	•
610 110 108 1899AS287-01	•	•				•		•		•					
610 110 172 1899AS282-01	•	•			•				•	•					
610 115 124 2038AS418-01		•									•				

**Product Cross Reference — Section 7**

	Receiver Modules		ID Modules		Assembly & Extraction Tools			
	510 113 121/1899AS269-02	510 113 122/1899AS271-02	510 114 108/1899AS283-01	510 114 109/1899AS285-01	910 112 104	910 121 144	910 121 149	910 121 160 or 910 121 148
Receiver and ID Solder Sleeve Contacts								
Receiver 610 104 142 2038AS397-01	•	•			•	•	•	•
ID 610 103 140 2038AS396-01			•	•	•	•	•	•




**Diagrams - Section 8**

**- CASS Receiver -**



Diagrams - Section 8



- CASS Interface Device -



P/N 410 113 101/1899AS279-01


**Diagrams - Section 8**

**- CASS Receiver Modules -**




Diagrams - Section 8


- CASS ID Modules -




P/N 510 114 109/1899AS285-01




P/N 510 114 106/1899AS286-01



P/N 510 114 107/1899AS280-01



P/N 510 114 108/1899AS283-01



P/N 510 113 106/1899AS288-01