

Operation Manual Multi-parameter Transmitter M400



Operation Manual Multi-parameter Transmitter M400

Content

1	Introduction	9
2	Safety instructions	10
2.1	Definition of equipment and documentation symbols and designations	10
2.2	Correct disposal of the unit	11
2.3	Ex Classification	12
3	Unit overview	13
3.1	Overview 1/2DIN	13
3.2	Control/Navigation Keys	14
3.2.1	Menu Structure	14
3.2.2	Navigation keys	14
3.2.2.1	Navigating the menu tree	14
3.2.2.2	Escape	15
3.2.2.3	ENTER	15
3.2.2.4	Menu	15
3.2.2.5	Calibration mode	15
3.2.2.6	Info mode	15
3.2.3	Navigation of data entry fields	15
3.2.4	Entry of data values, selection of data entry options	15
3.2.5	Navigation with ↑ in Display	16
3.2.6	"Save changes" dialog	16
3.2.7	Security Passwords	16
3.2.8	Display	16
4	Installation instruction	17
4.1	Unpacking and inspection of equipment	17
4.1.1	Panel cutout dimensional information – 1/2DIN models	17
4.1.2	Installation procedure	18
4.1.3	Assembly – 1/2DIN version	18
4.1.4	1/2DIN version – Dimension drawings	19
4.1.5	1/2DIN version – Pipe mounting	19
4.2	Connection of power supply	20
4.2.1	Housing (wall mount)	20
4.3	Connector PIN definition	21
4.3.1	TB1 and TB2	21
4.3.2	TB3 – Analog resistive 2-e conductivity sensors	21
4.3.3	TB3 – Analog resistive 4-e conductivity sensors	22
4.3.4	TB3 – Analog inductive conductivity sensors	22
4.3.5	TB3 – Analog pH/ORP sensors	23
4.3.6	TB3 – Analog ISFET sensors	23
4.3.7	TB3 – Analog oxygen sensors	24
4.3.8	TB3 – Analog dissolved carbon dioxide sensors	24
4.3.9	TB3 – 4 to 20 mA input signal	25
4.3.10	TB4 – ISM (digital) sensors for pH, conductivity and oxygen	25
4.4	Connection of ISM (digital) sensors	26
4.4.1	Connection of ISM sensors for pH/ORP, pH/pNa, CO ₂ , Cond 4-e and amperometric oxygen measurement	26
4.4.2	TB4 – AK9 cable assignment	26
4.4.3	Connection of ISM sensor for optical oxygen, CO ₂ Hi (InPro 5500i)	27
4.4.4	TB4 – Optical DO sensor cable assignment	27
4.5	Connection of analog sensors	28
4.5.1	Connection of analog sensor for pH/ORP	28
4.5.2	VP cable assignment for pH/ORP sensor	29
4.5.3	TB3 – Typical wiring for analog pH/ORP sensor	30
4.5.3.1	Example 1	30
4.5.3.2	Example 2	31
4.5.3.3	Example 3	32
4.5.3.4	Example 4	33
4.5.4	Connection of analog ISFET sensor	34
4.5.5	TB3 – Typical wiring for analog ISFET sensor	35
4.5.6	Connection of analog sensor for amperometric oxygen measurement	36
4.5.7	TB3 – Typical wiring for analog sensor for amperometric oxygen measurement	37
4.5.8	Connection of analog sensor for dissolved carbon dioxide	38
4.5.9	TB3 – Typical wiring for analog dissolved carbon dioxide sensor	39

5	Placing transmitter in, or out, of service	40
5.1	Placing transmitter in service	40
5.2	Placing transmitter out of service	40
6	Quick Setup	41
7	Sensor Calibration	42
7.1	Enter Calibration Mode	42
7.2	Conductivity calibration for two- or four-electrode sensors	43
7.2.1	One-point sensor calibration	43
7.2.2	Two-point sensor calibration (four electrode sensors only)	44
7.2.3	Process Calibration	45
7.3	Conductivity calibration for inductive sensors	45
7.3.1	Zero-point calibration	46
7.3.2	One-point slope calibration	47
7.3.3	Process calibration	47
7.4	Calibration of amperometric oxygen sensors	48
7.4.1	One-point calibration for amperometric oxygen sensors	48
7.4.1.1	Auto mode	49
7.4.1.2	Manual mode	49
7.4.2	Process calibration for amperometric oxygen sensors	50
7.5	Calibration of optical oxygen sensors	50
7.5.1	One-point calibration for optical oxygen sensors	50
7.5.1.1	Auto mode	51
7.5.1.2	Manual mode	52
7.5.2	Two-Point sensor calibration	52
7.5.2.1	Auto mode	53
7.5.2.2	Manual mode	53
7.5.3	Process calibration	54
7.6	Calibration of a tunable diode laser (TDL) gas sensor	55
7.6.1	One-point calibration for TDL gas sensors	55
7.6.1.1	Auto mode	55
7.6.1.2	Manual mode	56
7.6.2	Process calibration for TDL gas sensors	56
7.7	pH calibration	57
7.7.1	One point calibration	57
7.7.1.1	Auto mode	57
7.7.1.2	Manual Mode	58
7.7.2	Two-point calibration	58
7.7.2.1	Auto Mode	58
7.7.2.2	Manual Mode	59
7.7.3	Process calibration	60
7.7.4	mV calibration (only for analog sensors)	60
7.7.5	ORP calibration (only for ISM sensors)	61
7.8	ISFET calibration	62
7.8.1	One-point calibration	62
7.8.2	Two-point calibration	62
7.8.3	Process calibration	62
7.8.4	mV calibration	63
7.9	Dissolved carbon dioxide calibration	63
7.9.1	One point calibration	63
7.9.1.1	Auto Mode	63
7.9.1.2	Manual Mode	64
7.9.2	Two-point calibration	64
7.9.2.1	Auto Mode	64
7.9.2.2	Manual Mode	65
7.9.3	Process calibration	65
7.10	CO ₂ Hi (InPro 5500 i)	66
7.10.1	One point calibration	66
7.10.2	Process calibration	67
7.11	Sensor temperature calibration (only for analog sensors)	67
7.11.1	One-Point sensor temperature calibration	67
7.11.2	Two-Point sensor temperature calibration	68
7.12	Edit sensor calibration constants (only for analog sensor)	68
7.13	Sensor verification	69

8	Configuration	70
8.1	Enter configuration mode	70
8.2	Measurement	70
8.2.1	Channel Setup	70
8.2.1.1	Analog sensor	71
8.2.1.2	ISM sensor	71
8.2.1.3	Save changes of the channel setup	72
8.2.2	Temperature source (only for analog sensors)	72
8.2.3	Parameter related settings	72
8.2.3.1	Conductivity temperature compensation	73
8.2.3.2	Concentration table	74
8.2.3.3	pH/ORP parameters	75
8.2.3.4	ISFET parameters	76
8.2.3.5	Parameters for oxygen measurement based on amperometric sensors	76
8.2.3.6	Parameters for oxygen measurement based on optical sensors	77
8.2.3.7	Adjusting sampling rate for optical sensors	79
8.2.3.8	LED Mode	79
8.2.3.9	Dissolved carbon dioxide parameters	80
8.2.3.10	CO ₂ Hi (InPro 5500 i) parameters	81
8.2.3.11	TDL Installation	82
8.2.3.12	TDL Commissioning	82
8.2.3.13	Setting the correct process side purging	84
8.2.4	Set averaging	85
8.3	Analog outputs	85
8.4	Set points	86
8.5	Alarm/Clean	88
8.5.1	Alarm	88
8.5.2	Clean	90
8.6	ISM set up (available for pH and oxygen ISM sensors)	91
8.6.1	Sensor monitoring	91
8.6.2	CIP Cycle Limit	93
8.6.3	SIP Cycle Limit	93
8.6.4	Autoclaving Cycle Limit	94
8.6.5	Reset ISM counter/timer	95
8.6.6	DLI Stress Adjustment (only for pH sensor)	95
8.7	Display	96
8.7.1	Measurement	96
8.7.2	Resolution	96
8.7.3	Backlight	97
8.7.4	Name	97
8.7.5	ISM sensor monitoring (available when ISM sensor connected)	97
8.8	Hold analog outputs	98
9	System	99
9.1	Set Language	99
9.2	USB	99
9.3	Passwords	100
9.3.1	Changing passwords	100
9.3.2	Configuring menu access for operator	100
9.4	Set/Clear lockout	101
9.5	Reset	101
9.5.1	Reset system	101
9.5.2	Reset meter calibration	101
9.5.3	Reset analog calibration	102
9.5.4	Reset sensor calibration (for optical sensors only)	102
9.6	Set date & time	102
10	PID setup	103
10.1	Enter PID setup	104
10.2	PID auto/manual	104
10.3	Mode	105
10.3.1	PID mode	105
10.4	Tune parameters	106
10.4.1	PID assignment & tuning	106
10.4.2	Setpoint & deadband	107
10.4.3	Proportional limits	107
10.4.4	Corner points	107
10.5	PID display	107

11	Service	108
11.1	Diagnostics	108
11.1.1	Model/Software revision	108
11.1.2	Digital input	109
11.1.3	Display	109
11.1.4	Keypad	109
11.1.5	Memory	109
11.1.6	Set Relay	110
11.1.7	Read relays	110
11.1.8	Set analog outputs	110
11.1.9	Read analog outputs	110
11.1.10	O ₂ Optical	111
11.1.11	CO ₂ Hi (InPro 5500i)	111
11.1.12	TDL	111
11.2	Calibrate	111
11.2.1	Calibrate meter (only for channel A)	111
11.2.1.1	Temperature	112
11.2.1.2	Current	112
11.2.1.3	Voltage	113
11.2.1.4	Rg diagnostic	113
11.2.1.5	Rr diagnostic	114
11.2.1.6	Calibrate analog output signals	114
11.2.2	Calibrate unlock	115
11.3	Tech Service	115
12	Info	116
12.1	Messages	116
12.2	Calibration data	116
12.3	Model/Software revision	117
12.4	ISM sensor info (available when ISM sensor connected)	117
12.5	ISM sensor diagnostics (available when ISM sensor connected)	117
13	Maintenance	120
13.1	Front panel cleaning	120
14	Troubleshooting	121
14.1	Changing the fuse	121
14.2	Cond (resistive) Error messages/Warning- and Alarm list for Cond sensors	121
14.3	Cond (inductive) Error messages/Warning- and Alarm list	122
14.4	pH Error messages/Warning- and Alarm list	122
14.4.1	pH sensors except dual membrane pH electrodes	122
14.4.2	Dual membrane pH electrodes (pH/pNa)	123
14.4.3	ORP messages	123
14.5	Amperometric O ₂ Error messages/Warning- and Alarm list	124
14.5.1	High level oxygen sensors	124
14.5.2	Low level oxygen sensors	124
14.5.3	Trace oxygen sensors	125
14.6	Optical O ₂ Error messages/Warning- and Alarm list	125
14.7	TDL/Warning- and Alarm list	126
14.8	ISFET Error messages/Warning- and Alarm list	128
14.9	Dissolved carbon dioxide Error messages/Warning- and Alarm list	128
14.10	CO ₂ Hi (InPro 5500i) Error messages and Alarm list	129
14.11	ISM common messages and Alarm list	129
14.12	Warning- and Alarm indication on the display	129
14.12.1	Warning indication	129
14.12.2	Alarm indication	129
15	Accessories and Spare Parts	130
16	Specifications	131
16.1	General specifications	131
16.2	Electrical specifications	135
16.3	Mechanical specifications	135
16.4	Environmental specifications	136
16.5	Ex Classification	136
17	Default table	137

18	Warranty	140
19	Buffer tables	141
19.1	Standard pH buffers	141
19.1.1	Mettler-9	141
19.1.2	Mettler-10	142
19.1.3	NIST Technical Buffers	142
19.1.4	NIST standard buffers (DIN and JIS 19266: 2000-01)	143
19.1.5	Hach buffers	143
19.1.6	Ciba (94) buffers	144
19.1.7	Merck Titrisole, Riedel-de-Haën Fixanale	144
19.1.8	WTW buffers	145
19.1.9	JIS Z 8802 buffers	145
19.2	Dual membrane pH electrode buffers	146
19.2.1	Mettler-pH/pNa buffers (Na+ 3.9M)	146

1 Introduction

Statement of Intended Use – The M400 multi-parameter transmitter is a single- channel online process instrument for measuring various properties of fluids and gases. These include Conductivity, Dissolved Oxygen, Dissolved Carbon Dioxide (CO₂) and pH/ORP. The transmitter handles also ISFET sensors used for pH measurement. The M400 is available in three different levels. The level indicates the amount of measurement parameters which can be covered. The parameters are indicated on the label on the back of the system.

The M400 is a unique mixed mode transmitter who can handle conventional sensors (analog) or ISM sensors (digital).

M400 parameter fit guide

Parameter	Type 1		Type 1 Cond Ind		Type 2		Type 3	
	Analog	ISM	Analog	ISM	Analog	ISM	Analog	ISM
pH/ORP	•	•	–	•	•	•	•	•
pH (ISFET)	•	–	–	–	•	–	•	–
Conductivity 2-e	•	–	–	–	•	–	•	–
Conductivity 4-e	•	•	–	•	•	•	•	•
Conductivity inductive	–	–	•	–	–	–	–	–
Amp. DO ppm/ppb/trace	–	–	–	–	•/–/–	•/–/–	•/•/–	•/•/•
Amp. O ₂ gas ppm/ppb/trace	–	–	–	–	•/–/–	•/–/–	•/•/–	•/•/•
Oxygen optical ppm/ppb	–	–	–	–	–	•/–	–	•/•
Oxygen TDL	–	–	–	–	–	–	–	•
Dissolved Carbon Dioxide	–	–	–	–	–	–	•	•
CO ₂ Hi (High) InPro 5500i	–	–	–	–	–	–	–	•

A large four line backlit Liquid Crystal Display conveys measuring data and setup information. The menu structure allows the operator to modify all operational parameters by using keys on the front panel. A menu-lockout feature, with password protection, is available to prevent the unauthorized use of the meter. The M400 Multi-parameter transmitter can be configured to use its four analog and/or six relay outputs for process control.

The M400 Multi-parameter transmitter is equipped with a USB communication interface. This interface provides real-time data output and complete instrument configuration capabilities for central monitoring via Personal Computer (PC).

This description corresponds to the firmware release, version 1.5 for the transmitter M400 Type 1, M400 Type 2 and M400 Type 3 as well as to the firmware release, version 1.2 for the transmitter M400 Type 1 Cond Ind. Changes are taking place constantly, without prior notification.

2 Safety instructions

This manual includes safety information with the following designations and formats.

2.1 Definition of equipment and documentation symbols and designations



WARNING: POTENTIAL FOR PERSONAL INJURY.



CAUTION: possible instrument damage or malfunction.



NOTE: Important operating information.



On the transmitter or in this manual text indicates: Caution and/or other possible hazard including risk of electric shock (refer to accompanying documents)

The following is a list of general safety instructions and warnings. Failure to adhere to these instructions can result in damage to the equipment and/or personal injury to the operator.

- The M400 Transmitter should be installed and operated only by personnel familiar with the transmitter and who are qualified for such work.
- The M400 Transmitter must only be operated under the specified operating conditions (see section 16 “Specifications”).
- Repair of the M400 Transmitter must be performed by authorized, trained personnel only.
- With the exception of routine maintenance, cleaning procedures or fuse replacement, as described in this manual, the M400 Transmitter must not be tampered with or altered in any manner.
- Mettler-Toledo accepts no responsibility for damage caused by unauthorized modifications to the transmitter.
- Follow all warnings, cautions, and instructions indicated on and supplied with this product.
- Install equipment as specified in this instruction manual. Follow appropriate local and national codes.
- Protective covers must be in place at all times during normal operation.
- If this equipment is used in a manner not specified by the manufacturer, the protection provided by it against hazards may be impaired.

WARNINGS:

Installation of cable connections and servicing of this product require access to shock hazard voltage levels.

Main power and relay contacts wired to separate power source must be disconnected before servicing.

Switch or circuit breaker shall be in close proximity to the equipment and within easy reach of the OPERATOR; it shall be marked as the disconnecting device for the equipment.

Main power must employ a switch or circuit breaker as the disconnecting device for the equipment.

Electrical installation must be in accordance with the National Electrical Code and/or any other applicable national or local codes.

**NOTE: RELAY CONTROL ACTION**

the M400 transmitter relays will always de-energize on loss of power, equivalent to normal state, regardless of relay state setting for powered operation. Configure any control system using these relays with fail-safe logic accordingly.

**NOTE: PROCESS UPSETS**

Because process and safety conditions may depend on consistent operation of this transmitter, provide appropriate means to maintain operation during sensor cleaning, replacement or sensor or instrument calibration.



NOTE: This is a 4-wire-product with an active 4–20 mA analog output.
Please do not supply to Pin1–Pin6 of TB2.

2.2 Correct disposal of the unit


When the transmitter is finally removed from service, observe all local environmental regulations for proper disposal.

2.3 Ex Classification




NOTE: The Ex classification is valid for the transmitters M400 Type 1, M400 Type 2 and M400 Type 3. For the transmitter M400 Type 1 Cond Ind the approvals are in preparation.

Type plate



N315



N315

Special condition(s) X

1. The strength of the device's casing corresponds only to the low degree of mechanical risk and must therefore be additionally protected by suitable measures against mechanical impact effect.
2. Due to the risk of electrostatic charge, the device may only be cleaned with a damp cloth. This instruction is fitted on the device with a separate warning shield stating the following: WARNING – CLEAN PLASTIC PARTS WITH MOIST CLOTH ONLY.
3. In accordance with guideline 94/9/EG separately certified cable and bushes in addition to sealing plugs/caps may be used.
4. Unused openings must be closed with the sealing plugs/caps shown under point 3.




NOTE:

1. The transmitter M400 Type 1, M400 Type 2, M400 Type 3 is a device of device type II category 3G in accordance with RL 94/9/EC (ATEX 95) appendix I, which may be used in accordance with RL 99/32/EG (ATEX 137) in zone 2 and in the gas groups IIA, IIB and IIC, which are explosive because of inflammable materials in the range of temperature classes T1 to T4. During use/installation, the requirements in accordance with EN 60079-14 must be complied with.
2. The permissible ambient temperature range is -10 °C to +50 °C.

3 Unit overview

The M400 models are available in 1/2DIN case size. The M400 models provide an integral IP65 housing for wall- or pipe mount.

3.1 Overview 1/2DIN




- 1: Hard Polycarbonate case
- 2: Five Tactile-Feedback Navigation Keys
- 3: Four-line LCD Display
- 4: Power Supply Terminals
- 5: USB Interface Port
- 6: Relay Output Terminals
- 7: Analog Output/Digital Input Terminals
- 8: Sensor Input Terminals (analog TB, digital TB)
- 9: List of parameters to be measured with this unit


3.2 Control/Navigation Keys

3.2.1 Menu Structure

Below is the structure of the M400 menu tree:



3.2.2 Navigation keys



3.2.2.1 Navigating the menu tree

Enter the desired main Menu branch with the ◀▶ or ▲ keys. Use the ▲ and ▼ keys to navigate through the selected Menu branch.



NOTE: In order to back up one menu page, without escaping to the measurement mode, move the cursor under the UP Arrow character (↑) at the bottom right of the display screen and press [ENTER].

3.2.2.2 Escape

Press the ◀ and ▶ key simultaneously (escape) to return to the Measurement mode.

3.2.2.3 ENTER

Use the ↵ key to confirm action or selections.

3.2.2.4 Menu

Press the ◀ key to access the main Menu.

3.2.2.5 Calibration mode

Press the ▶ key to enter Calibration mode.

3.2.2.6 Info mode

Press the ▼ key to enter Info mode

3.2.3 Navigation of data entry fields

Use the ▶ key to navigate forward or the ◀ key to navigate backwards within the changeable data entry fields of the display.

3.2.4 Entry of data values, selection of data entry options

Use the ▲ key to increase or the ▼ key to decrease a digit. Use the same keys to navigate within a selection of values or options of a data entry field.



NOTE: Some screens require configuring multiple values via the same data field (ex: configuring multiple setpoints). Be sure to use the ▶ or ◀ key to return to the primary field and the ▲ or ▼ key to toggle between all configuration options before entering to the next display screen.

3.2.5 Navigation with ↑ in Display

If a ↑ is displayed on the bottom right hand corner of the display, you can use the ► or the ◀ key to navigate to it. If you click [ENTER] you will navigate backwards through the menu (go back one screen). This can be a very useful option to move back up the menu tree without having to exit into the measuring mode and re-enter the menu.

3.2.6 "Save changes" dialog

Three options are possible for the "Save changes" dialog: Yes & Exit (Save changes and exit to measuring mode), "Yes & ↑" (Save changes and go back one screen) and "No & Exit" (Don't save changes and exit to measuring mode). The "Yes & ↑" option is very useful if you want to continue configuring without having to re-enter the menu.

3.2.7 Security Passwords

The M400 transmitter allows a security lock-out of various menus. If the security lock-out feature of the transmitter has been enabled, a security password must be entered to allow access to the menu. See section 9.3 for more information.

3.2.8 Display



NOTE: In the event of an alarm or other error condition the M400 Transmitter will display a flashing ⚠ in the upper right corner of the display. This symbol will remain until the condition that caused it has been cleared.



NOTE: During calibrations (Channel A), clean, Digital In with Analog Output/Relay/USB in Hold state, a flashing "H" (Hold) will appear in the upper left corner of the display. During calibration on Channel B, a flashing "H" (Hold) will appear in the second line. Change to B and flash. This symbol will remain for 20 sec., after end of calibration. This symbol will remain for 20 seconds until after the calibration or clean is completed. This symbol will also disappear when Digital In is deactivated.



NOTE: Channel A (A is shown on the left side of the display) indicates that a conventional sensor is connected to the transmitter.

Channel B (B is shown on the left side of the display) indicates, that an ISM Sensor is connected to the transmitter.

The M400 is a single input channel transmitter, and only one sensor can be connected at the same time.

4 Installation instruction

4.1 Unpacking and inspection of equipment

Inspect the shipping container. If it is damaged, contact the shipper immediately for instructions. Do not discard the box.

If there is no apparent damage, unpack the container. Be sure all items shown on the packing list are present.


If items are missing, notify Mettler-Toledo immediately

4.1.1 Panel cutout dimensional information – 1/2DIN models

1/2DIN Model transmitters are designed with an integral rear cover for stand-alone wall mount installation.

The unit may also be wall mounted using the integral rear cover. See installation instructions in Section 4.1.2.

Below are cut-out dimensions required by the 1/2DIN models when mounted within a flat panel or on a flat enclosure door. This surface must be flat and smooth. Textured or rough surfaces are not recommended and may limit the effectiveness of the gasket seal provided.



Optional hardware accessories are available that allow for panel- or pipe-mount. Refer to Section 15 for ordering information.

4.1.2 Installation procedure

General:

- Orient the transmitter so that the cable grips face downward.
- Wiring routed through the cable grips shall be suitable for use in wet locations.
- In order provide IP65 enclosure ratings, all cable glands must be in place. Each cable gland must be filled using a cable, or suitable Cable Gland Hole Seal.


For Wall Mount:

- Remove rear cover from front housing.
- Start by unscrewing the four screws located on the face of the transmitter, in each corner. This allows the front cover to swing away from the rear housing.
- Remove the hinge-pin by squeezing the pin from each end. This allows the front housing to be removed from the rear housing.
- Mount rear housing to wall. Secure mounting kit to the M400 according to the supplied instructions. Attach to wall using appropriate mounting hardware for wall surface. Be sure it is level and securely fastened and the installation adheres to any and all clearance dimensions required for transmitter service and maintenance. Orient the transmitter so that the cable grips are facing downward.
- Replace the front housing to the rear housing. Securely tighten the rear-cover screws to ensure that IP65 enclosure environmental rating is maintained. The unit is ready to be wired.

For Pipe Mount:


- Use only manufacturer-supplied components for pipe-mounting the M400 transmitter and install per the supplied instructions. See section 15 for ordering information.

4.1.3 Assembly – 1/2DIN version




- 1: 3 Pg 13.5 cable glands
2: 2 plastic plugs
3: 4 screws

4.1.4 1/2DIN version – Dimension drawings



4.1.5 1/2DIN version – Pipe mounting



4.2 Connection of power supply


All connections to the transmitter are made on the rear panel of all models.




Be sure power to all wires is turned off before proceeding with the installation. High voltage may be present on the input power wires and relay wires.

A two-terminal connector on the rear panel of all M400 models is provided for power connection. All M400 models are designed to operate from a 20–30 VDC or a 100 to 240 VAC power source. Refer to specifications for power requirements and ratings and size power wiring accordingly (AWG 14, wire cross-section $\leq 2.5 \text{ mm}^2$).

The terminal block for power connections is labeled "Power" on the rear panel of the transmitter. One terminal is labeled **-N** for the Neutral wire and the other **+L** for the Line (or Load) wire.

The terminals are suitable for single wires and flexible leads up to 2.5 mm^2 (AWG 14). There is no earth ground terminal on the transmitter. For this reason the internal power wiring within the transmitter is double insulated and the product label designates this using the  symbol.

4.2.1 Housing (wall mount)



- 1: Connection of power supply
- 2: Terminal for sensors

4.3 Connector PIN definition


4.3.1 TB1 and TB2

Power connections are labeled

–**N** for Neutral and **+L** for Line, for 100 to 240 VAC or 20–30 VDC.

TB2 for ½ DIN	
1	AO1+
2	AO1–/AO2–
3	AO2+
4	AO3+
5	AO3–/AO4–
6	AO4+
7	DI1+
8	DI1–/DI2–
9	DI2+

TB1 for ½ DIN	
1	NO1
2	COM1
3	NC1
4	NO2
5	COM2
6	NC2
7	COM5
8	NC5
9	COM6
10	NO6
11	NO3
12	COM3
13	NO4
14	COM4



NO: normally open (contact open if un-actuated).

NC: normally closed (contact closed if un-actuated).

AO: Analog Output

DI: Digital Input



NOTE: This is a 4-wire-product with an active 4–20 mA analog output.
Please do not supply to Pin1–Pin6 of TB2.

4.3.2 TB3 – Analog resistive 2-e conductivity sensors

Pin no.	Sensor wire color*	Function
1	white	Cnd inner 1
2	white/blue	Cnd outer 1
3	blue	Cnd inner 2
4	black	Cnd outer 2/Shield
5	–	not used
6	bare shield	RTD ref/GND
7	red	RTD sense
8	green	RTD
9	–	+5 V

* Transparent not connected.

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.

4.3.3 TB3 – Analog resistive 4-e conductivity sensors

Pin no.	Sensor wire color*	Function
1	white	Cnd inner 1
2	white/blue	Cnd outer 1
3	blue	Cnd inner 2
4	black	Cnd outer 2 / Shield
5	–	not used
6	bare shield	RTD ret/GND
7	red	RTD sense
8	green	RTD
9	–	+5V

* Transparent not connected.

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.

4.3.4 TB3 – Analog inductive conductivity sensors

Pin no.	Sensor wire color InPro 7250 ST / PFA	Sensor wire color InPro 7250 HT	Function
1	Coax inner/transparent	Coax inner/transparent	receive hi
2	red	yellow	receive lo
3	green/yellow	green/yellow	shield/GND
4	brown	violet	send lo
5	blue	black	send hi
6	white	white	RTD ret/GND
7	grey	grey	RTD sense
8	green	green	RTD
9	–	–	not used

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.

4.3.5 TB3 – Analog pH/ORP sensors

pH/ORP sensors use 52 300 1XX series VP cables, or 10 001 XX02 series AS9 cables (ORP only).

Pin no.	Sensor wire color	Function
1	Coax inner/transparent	Glass
2		not used
3*	Coax shield/red	Reference
4*	green/yellow, blue	Solution GND/Shield
5	–	not used
6	white	RTD ret/GND
7	–	RTD sense
8	green	RTD
9	–	+5 V
	grey (no connection)	

Take care that AS9 cable and AK9 cable have the same configuration. So, if you want AS9 cable with InPro 2000 and AK9 cable with InPro 3030 connect to TB3, do it as DPAS sensor.

Pin no. 1: Sensing (electrode).

Pin no. 3: Reference (Install jumper 3 to 4).

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.



NOTE: * Install Jumper 3 to 4 when used without Solution Ground.

4.3.6 TB3 – Analog ISFET sensors

ISFET sensors use 52 300 40X series VP cables

Pin no.	Sensor wire color	Function
1	Coax inner/pink	FET
2	–	not used
3	yellow	Reference
4	green/yellow	GND / Shield
5	–	not used
6	white	RTD ret/GND
7	–	not used
8	grey	RTD
9	brown	+5 V



NOTE: Jumper 3 to 4 has to be installed.

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.

4.3.7 TB3 – Analog oxygen sensors

These sensors use 52 300 1XX series VP cables.

Pin no.	Sensor wire color	Function
1*	–	not used
2	Coax Shield/red	Anode
3*	–	not used
4*	green/yellow	Shield/GND
5	Coax Inner/transparent	Cathode
6	white, grey	Temperature, Guard
7	–	not used
8	green	Temperature
9	–	+5 V

Blue wire not used.

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.



NOTE: * Install jumper (supplied) 1 to 3 to 4 when using InPro 6900 (ppb measurement).

4.3.8 TB3 – Analog dissolved carbon dioxide sensors

Dissolved carbon dioxide sensors use 52 300 1XX series VP cables.

Pin no.	Sensor wire color	Function
1	Coax inner/transparent	Glass
2	–	not used
3	Coax shield/red	Reference
4	green/yellow	GND/Shield
5	–	not used
6	white	RTD ref/GND
7	–	not used
8	green	RTD
9	–	+5 V
	grey (no connection)	



NOTE: Jumper 3 to 4 has to be installed

Terminal 4 and 6 are internally connected, either terminal can be used to connect a wire.

4.3.9 TB3 – 4 to 20 mA input signal

Pin no.	Function
1	⊕ input of 4/20 mA signal
2	not used
3	not used
4	⊖ input of 4/20 mA signal
5	not used
6	not used
7	not used
8	not used
9	not used



NOTE: Jumper 3 to 4 has to be installed. 50 Ohm resistor has to be installed between 1 and 4.

4.3.10 TB4 – ISM (digital) sensors for pH, conductivity and oxygen


The wiring of the digital 9 terminal connectors is:

		Optical Oxygen, InPro 5500 i	InPro 6860i VP-8 Cable	TDL	pH, pH/pNa, amp. Oxygen, Cond 4-e, InPro 5500 i
Pin no.	Function	Sensor wire color	Sensor wire color	Sensor wire color	Sensor wire color
1	24 VDC	brown	grey	–	–
2	GND (24 VDC)	black	blue	–	–
3	1-Wire	–	–	–	transparent (cable core)
4	GND (5 VDC)	green/yellow	green/yellow	–	red (shield)
5	–	–	–	–	–
6	GND (5 VDC)	–	–	brown	–
7	RS485-B	blue	brown	yellow	–
8	RS485-A	white	pink	green	–
9	5 VDC	–	–	–	–

- ISM digital sensors can only be connected on TB4.
- Analog sensors can only be connected on TB3.

4.4 Connection of ISM (digital) sensors

4.4.1 Connection of ISM sensors for pH/ORP, pH/pNa, CO₂, Cond 4-e and amperometric oxygen measurement




NOTE: Connect the sensor and screw the plug head clockwise (hand tight).

4.4.2 TB4 – AK9 cable assignment

A: 1-wire data (transparent)


B: Ground/shield

4.4.3 Connection of ISM sensor for optical oxygen, CO₂ Hi (InPro 5500 i)




NOTE: Connect the Sensor and screw the plug head clockwise (hand tight).

4.4.4 TB4 – Optical DO sensor cable assignment




4.5 Connection of analog sensors

4.5.1 Connection of analog sensor for pH/ORP



NOTE: Cable lengths > 20 m can worsen the response during pH measurement. Be sure to observe the sensor instruction manual.

4.5.2 VP cable assignment for pH/ORP sensor




T1/T2: Temperature probe for 2-wire connection

T3: Additional connection for temperature probe (3-wire connection)

4.5.3 TB3 – Typical wiring for analog pH/ORP sensor

4.5.3.1 Example 1

pH measurement without Solution Ground




NOTE: Jumper terminals 3 and 4.

Wire colors only valid for connection with VP cable; blue and grey not connected.

- 1: Glass
- 2: Not used
- 3: Reference
- 4: Shield / GND
- 5: Not used
- 6: Solution GND / RTD ref
- 7: Not used
- 8: RTD
- 9: Not used

4.5.3.2 Example 2

pH measurement with Solution Ground




NOTE: Wire colors only valid for connection with VP cable, grey not connected.

- 1: Glass
- 2: Not used
- 3: Reference
- 4: Shield/Solution GND
- 5: Not used
- 6: GND/RTD ret
- 7: Not used
- 8: RTD
- 9: Not used

4.5.3.3 Example 3

ORP (redox) measurement (temperature optional)




NOTE: Jumper terminal 3 and 4

- 1: Platinum
- 2: Not used
- 3: Reference
- 4: Shield/GND
- 5: Not used
- 6: RTD ref
- 7: Not used
- 8: RTD
- 9: Not used

4.5.3.4 Example 4


ORP measurement with pH Solution ground electrode (e.g. InPro 3250SG, InPro 4800SG).



NOTE: Jumper terminal 3 and 4

- 1: Platinum
- 2: Not used
- 3: Reference
- 4: Shield/GND
- 5: Not used
- 6: RTD ref
- 7: Not used
- 8: RTD
- 9: Not used


4.5.4 Connection of analog ISFET sensor



NOTE: Be sure to observe the sensor instruction manual.

4.5.5 TB3 – Typical wiring for analog ISFET sensor

Sensor connection to
M400 Type 1, Type 2, Type 3




NOTE: Jumper Terminal 3 and 4 has to be installed.

M400 connector:


- 1: FET
- 2: not used
- 3: Reference
- 4: Shield/GND
- 5: not used
- 6: RTD ref/GND
- 7: not used
- 8: RTD
- 9: +5 VDC

4.5.6 Connection of analog sensor for amperometric oxygen measurement



NOTE: Be sure to observe the sensor instruction manual.

4.5.7 TB3 – Typical wiring for analog sensor for amperometric oxygen measurement



NOTE: Wire colors only valid for connection with VP cable, blue not connected.




NOTE: Install jumper (supplied) 1 to 3 to 4 when using InPro 6900 (ppb measurement).

M400 connector:


- 1: Not used
- 2: Anode
- 3: Not used
- 4: Shield/GND
- 5: Cathode
- 6: NTC ref, Guard
- 7: Not used
- 8: NTC 2
- 9: Not used

4.5.8 Connection of analog sensor for dissolved carbon dioxide



NOTE: Cable lengths > 20 m can worsen the response during dissolved carbon dioxide measurement. Be sure to observe the sensor instruction manual.

4.5.9 TB3 – Typical wiring for analog dissolved carbon dioxide sensor



NOTE: Jumper Terminal 3 and 4 has to be installed.

M400 connector:

- 1: Glass
- 2: not used
- 3: Reference
- 4: Shield/GND
- 5: not used
- 6: RTD ref/GND
- 7: not used
- 8: RTD
- 9: not used

5 Placing transmitter in, or out, of service

5.1 Placing transmitter in service



After connecting the transmitter to power supply circuit, it will be active as soon as the circuit is powered.

5.2 Placing transmitter out of service

First disconnect the unit from the main power source, then disconnect all remaining electrical connections. Remove the unit from the wall/panel. Use the installation instruction in this manual as reference for dis-assembling mounting hardware.

All transmitter settings stored in memory are non volatile.

6 Quick Setup

(PATH: Menu/Quick Setup)

Select Quick Setup and press the [ENTER] key. Enter the security code if necessary (see section 9.3 "Passwords")



NOTE: Please find the complete description of the Quick Setup routine described in the separate booklet "Quick Setup Guide for Transmitter M400" enclosed in the box.



NOTE: Please do not use Quick Setup menu after configuration of the transmitter, because some of the parameters i.e. analog output configuration will may be reseted.



NOTE: Refer to section 3.2 "Control/Navigation Keys" for information on menu navigation.

7 Sensor Calibration


(PATH: Cal)

The calibration key ► allows the user one-touch access to sensor calibration and verification features.



NOTE: During Calibration on Channel A, a flashing “H” (Hold) in the upper left corner of the display indicates a calibration is in process with a Hold condition active. (The hold output function needs to be activated.) See also chapter 3.3 “Display”.

7.1 Enter Calibration Mode



While in Measurement mode press the ► key. If the display prompts you to enter the calibration security code, press the ▲ or ▼ key to set the calibration security mode, then press the [ENTER] key to confirm the calibration security code.

Press the ▲ or ▼ key to select the type of calibration desired.

Select the desired sensor Calibration task. The choices for each sensor type are:

Conductivity	= Conductivity, Resistivity*, Temperature**, Edit**, Verify
Oxygen	= Oxygen, Temperature**, Edit**, Verify
O ₂ opt	= Oxygen***, Verify***
pH	= pH, mV**, Temperature**, Edit pH**, Edit mV**, Verify, ORP***
ISFET	= ISFET**, Temperature**, Edit ISFET**, mV**, Edit mV**, Verify**,
CO ₂	= CO ₂ **, Temperature**, Edit**, Verify**
CO ₂ Hi	= CO ₂ Hi***, Verify***
TDL	= TDL***, Verify***

Press [ENTER].

* not available at M400 Type 1 Cond Ind

** only on channel “A”

*** only available on channel “B”

After every successful calibration, the three options are available:

Adjust: Calibration values will be overtaken und used for the measurement. Additionally, the data will be stored in the calibration history*.

Calibrate: Calibration values will be stored in the calibration history* for documentation, but will not be used for the measurement. The calibration values from the last valid adjustment will be further used for the measurement.

Abort: Calibration values will be discarded.

* only available with ISM sensors

7.2 Conductivity calibration for two- or four-electrode sensors


This feature provides the ability to perform a one-point, two-point or process Conductivity resp. Resistivity "Sensor" calibration for two- or four-electrode sensors. The procedure described below works for both types of calibrations. There is no reason to perform a two-point calibration on a two-electrode conductivity sensor.



NOTE: When performing calibration on a conductivity sensor, results will vary depending on the methods, calibration apparatus and/or quality of reference standards used to perform the calibration.



NOTE: For measuring tasks the temperature compensation for the application as defined at the menu Resistivity will be considered and not the temperature compensation selected thru the calibration procedure (see also chapter 8.2.3.1 "Conductivity temperature compensation"; PATH: Menu/Configure/Measurement/Resistivity).



Enter Conductivity sensor calibration mode as described in section 7.1 "Enter Calibration Mode".

The next screen will ask to select the type of temperature compensation mode desired during the calibration process.



Choices are "Standard", "Lin 25 °C", "Lin 20 °C" or "Nat H₂O" compensation mode.

Standard compensation: includes compensation for non-linear high purity effects as well as conventional neutral salt impurities and conforms to ASTM standards D1125 and D5391.

Lin 25°C compensation: adjusts the reading by a factor expressed as "% per °C" deviation from 25 °C. The factor can be modified.

Lin 20°C compensation: adjusts the reading by a factor expressed as "% per °C" deviation from 20 °C. The factor can be modified.


Nat H₂O compensation: includes compensation to 25 °C according to EN27888 for natural water.

Choose the compensation mode, modify the factor where appropriate and press [ENTER].

7.2.1 One-point sensor calibration

(Display reflects typical Conductivity Sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.2 "Conductivity calibration for two- or four electrode sensors").



Select 1 point calibration and press [ENTER]. With conductivity sensors a one-point calibration is always performed as a slope calibration.

Place the electrode into the reference solution.

```

A 1.25 µS/cm
A 25.00 °C
A Point1 = 1.413 µS/cm
A C = 1.250 µS/cm ▲

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

```

A 1.25 µS/cm
A 25.0 °C
C M=0.09712 A=0.00000
Save Adjust ↑

```

After the calibration the cell multiplier or slope calibration factor "M" i.e. cell constant and the Adder or offset calibration factor "A" are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.2.2 Two-point sensor calibration (four electrode sensors only)

(Display reflects typical Conductivity sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.2 "Conductivity calibration for two- or four electrode sensors").

```

A 1.25 µS/cm
A 25.00 °C
Conductivity Calibration
Type = 2 point ▲

```

Select 2 point calibration and press [ENTER].

Place the electrode into the first reference solution.

CAUTION: Rinse sensors with a high-purity water solution between calibration points to prevent contamination of the reference solutions.

```

A 1.25 µS/cm
A 25.00 °C
A Point2 = 0.055 µS/cm
A C = 0.057 µS/cm ▲

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable and place the electrode into the second reference solution.

Enter the value for Point 2 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

After the calibration of the cell multiplier or slope calibration factor "M" i.e. cell constant and the Adder or offset calibration factor "A" are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.





If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.2.3 Process Calibration

(Display reflects typical Conductivity sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.2 "Conductivity calibration for two- or four electrode sensors").

Select Process Calibration and press [ENTER]. With conductivity sensors a process calibration is always performed as a slope calibration.

Take a sample and press the [ENTER] key again to store the current measuring value.

During the ongoing calibration process, the letter of the channel, which is concerned by the calibration, "A" or "B" is blinking in the display.

After determining the conductivity value of the sample, press the [CAL] key again to proceed with the calibration.

Enter the conductivity value of the sample, then press the [ENTER] key to start the calculation of calibration results.

After the calibration the Multiplier or slope calibration factor "M" and the Adder or offset calibration factor "A" are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.

7.3 Conductivity calibration for inductive sensors

This feature provides the ability to perform a one-point offset, one-point slope or process calibration for the inductive conductivity sensors. This feature is only available at the M400 Type 1 Cond Ind.



NOTE: When performing calibration on a conductivity sensor, results will vary depending on the methods, calibration apparatus and/or quality of reference standards used to perform the calibration.



NOTE: For measuring tasks the temperature compensation for the application as defined at the menu Resistivity will be considered and not the temperature compensation selected through the calibration procedure (see also chapter 8.2.3.1 "Conductivity temperature compensation"; PATH: Menu/Configure/Measurement/Resistivity).

```

A 1.25 µS/cm
A 25.00 °C
Calibrate Sensor
Channel A Conductivity ▲

```

```

A 1.25 µS/cm
A 25.00 °C
Cal Compensation
Standard ▲

```

Enter Conductivity sensor calibration mode as described in section 7.1 "Enter Calibration Mode".

The next screen will ask to select the type of temperature compensation mode desired during the calibration process.

Choices are "Standard", "Lin 25°C", "Lin 20°C" or "Nat H2O" compensation mode.

Standard compensation: includes compensation for non-linear high purity effects as well as conventional neutral salt impurities and conforms to ASTM standards D1125 and D5391.

Lin 25 °C compensation: adjusts the reading by a factor expressed as "% per °C" at a deviation from 25 °C. The factor can be modified.

Lin 20 °C compensation: adjusts the reading by a factor expressed as "% per °C" at a deviation from 20 °C. The factor can be modified.

Nat H₂O compensation: includes compensation to 25 °C according to EN27888 for natural water.

Choose the compensation mode, modify the factor where appropriate and press [ENTER].

7.3.1 Zero-point calibration

(Display reflects typical Conductivity sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.3 "Conductivity calibration for inductive sensors").

```

H 40.5 mS/cm
A 23.9 °C
Conductivity Calibration
Type = Zero Point ↑

```

Select Zero Point and press [ENTER].

```

A 1.035 mS/cm
A 21.9 °C
Point1 = 0.000 mS/cm
C = 1.035 mS/cm ↑

```

Press the [ENTER] key again to go on with the calibration.

The display changes to show the multiplier or slope calibration factor "M" i.e. cell factor and the adder or offset calibration factor "A".

```

1.035 mS/cm
A 21.9 °C
C M=2.17500 A=-966.67
Save Adjust _

```

After a successful calibration, the calibration values are taken over (Adjust) or discarded (Calibrate) or (Abort).

If "Adjust" is chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.3.2 One-point slope calibration

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.3 "Conductivity calibration for inductive sensors").

Select 1 point Slope and press [ENTER].

```

217.4 μS/cm
A 25.0 °C
Conductivity Calibration
Type = 1 Point Slope ↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

```

217.4 μS/cm
A 25.0 °C
A Point1 = 215.0 μS/cm
A C = 217.4 μS/cm ↑

```

The display changes to show the multiplier or slope calibration factor "M" i.e. cell factor and the adder or offset calibration factor "A".

After a successful calibration, the calibration values are taken over (Adjust) or discarded (Calibrate) or (Abort).

If "Adjust" is chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press Enter" on the display. After pressing "Enter" the M400 returns to the measuring mode.

```

20.5 mS/cm
A 25.0 °C
C M=2.17000 A=0.00000
Save Adjust _

```

7.3.3 Process calibration

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.3 "Conductivity calibration for inductive sensors").

Select Process and press [ENTER].

```

H 1.09 mS/cm
A 25.0 °C
Conductivity Calibration
Type = Process ↑

```

Take a sample and press the [ENTER] key again to store the current measuring value. During the ongoing calibration process, "A" is blinking in the display.

After determining the conductivity value of the sample, press the [CAL] key again to proceed with the calibration.

```

B 1.09 mS/cm
B 25.0 °C
Press ENTER to Capture
B C = 1.087 mS/cm ↑


```

Enter the conductivity value of the sample, then press the [ENTER] key to start the calculation of calibration results.

```

1.09 mS/cm
25.0 °C
A Point1 = 1.000 mS/cm
A C = 1.087 mS/cm ↑

```



After a successful calibration, the calibration values are taken over (Adjust) or discarded (Calibrate) or (Abort).

If "Adjust" is chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.


7.4 Calibration of amperometric oxygen sensors

Oxygen calibration for amperometric sensors is performed as either a one-point or process calibration.




NOTE: Before air calibration, for highest accuracy, enter the barometric pressure and relative humidity, as described in section 8.2.3.5 "Parameters for oxygen measurement based on amperometric sensors".

7.4.1 One-point calibration for amperometric oxygen sensors




Enter Oxygen calibration mode as described in section 7.1 "Enter Calibration Mode".


A one-point calibration of oxygen sensors is always either a one point slope (i.e. with air) or a zero (offset) calibration. A one point slope calibration is done in air and a one point offset calibration is done at 0 ppb oxygen. A one-point zero dissolved oxygen calibration is available but not normally recommended since zero oxygen is very hard to achieve. A zero-point calibration is only recommended if high accuracy at low oxygen level (below 5% air) is needed.



Select 1 point followed by either Slope or ZeroPt as the calibration type. Press [ENTER].



Adjust calibration pressure (CalPres) and relative humidity (RelativeHumid), which are applied during calibration. Press [ENTER].



Place the sensor in the calibration gas (e.g. air) resp. solution. Press [ENTER].

Depending on the parameterized Drift control (see chapter 8.2.3.5 "Parameters for oxygen measurement based on amperometric sensors") one of the two following modes is active.

7.4.1.1 Auto mode



NOTE: For a zero point calibration the Auto mode is not available. If Auto mode has been configured (see section 8.2.3.5 "Parameters for oxygen measurement based on amperometric sensors") and an offset calibration will be executed, the transmitter will perform the calibration in Manual mode.

```

B  98.6 %sat
  25.0 °C

B Point1 = 100.5 %sat
B 02 = 98.6 %sat ↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user.

```

B  98.6 %sat
B  25.0 °C

02 S=-68.66nA Z=0.0000nA
Save Adjust ↑

```

As soon as the stabilization criteria have been fulfilled the display changes. The display shows the calibration result for slope "S" and offset value "Z".

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

7.4.1.2 Manual mode

```

B  98.6 %sat
  25.0 °C

B Point1 = 100.5 %sat
B 02 = 98.6 %sat ↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

```

B  98.6 %sat
B  25.0 °C

02 S=-68.66nA Z=0.0000nA
Save Adjust ↑

```

After the calibration the slope "S" and the offset value "Z" are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.



NOTE: With ISM sensors: If a one point calibration is executed, the transmitter sends the polarization voltage, valid for the calibration, to the sensor. If the polarization voltage for the measuring mode and calibration mode is different, the transmitter will wait 120 seconds before starting the calibration. In this case the transmitter will also go after the calibration for 120 seconds to the HOLD Mode, before returning to the measuring mode again. (see also chapter 8.2.3.5 "Parameter for oxygen measurement based on amperometric sensors").

7.4.2 Process calibration for amperometric oxygen sensors

Enter Oxygen calibration mode as described in section 7.1 "Enter Calibration Mode".

A process calibration of oxygen sensors is always either a slope or a offset calibration.

```

B  57.1  %sat
B  25.0  °C

Calibrate Sensor
Channel B Oxygen  ↑

```

Select Process followed by either Slope or ZeroPt as the calibration type. Press [ENTER]

```

B  57.1  %sat
B  25.0  °C

O2 Calibration
Type = Process Slope  ↑

```

Take a sample and press the [ENTER] key again to store the current measuring value. To show the ongoing calibration process, A or B (depending on the channel) is blinking in the display.

After determining the O₂ value of the sample press the ► key again to proceed with the calibration.

```

B  57.1  %air
B  25.0  °C

Press ENTER to Capture
B  O2=57.1  %air  ↑

```

Enter the O₂ value of the sample then press the [ENTER] key to start the calculation of the calibration results.

```

B  57.1  %sat
B  25.0  °C

B Point1 = 56.90 %sat
B O2 = 57.1 %sat  ↑

```

After the calibration the slope "S" and the offset value "Z" are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

```

57.1  %sat
25.0  °C

O2 S=-0.070nA Z=0.0000nA
Save Adjust  ↑

```

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.

7.5 Calibration of optical oxygen sensors

Oxygen calibration for optical sensors can be performed as a two-point, process or, depending on the sensor model connected to the transmitter, also as a one-point calibration.

7.5.1 One-point calibration for optical oxygen sensors

Typically a one point calibration is done in air. Nevertheless other calibration gases and solutions are possible.

The calibration of an optical sensor is always a calibration of the phase of the fluorescence signal towards the internal reference. During a one point calibration the phase in this point is measured and extrapolated over the measuring range.

```

B  99.3  %AIR
B  25.0  °C

Calibrate Sensor
Channel B O2 Opt  ↑

```

Enter O₂ opt calibration mode as described in section 7.1 "Enter Calibration Mode".

```

B  99.3  %AIR
H  25.0  °C

O2 Optical Calibration
Type = 1 Point  ↑

```

Select 1 point as the calibration type. Press [ENTER].

Place the sensor in the calibration gas (e.g. air) resp. solution.

```

B  99.3  %air
B  25.0  °C

CalPres = 759.8 mmHg
RelativeHumid = 100 %  ↑

```

Adjust calibration pressure (CalPres) and relative humidity (RelativeHumid), which are applied during calibration. Press [ENTER].

```

B  99.3  %air
B  25.0  °C

Press ENTER when
Sensor is in Gas 1(Air) ↑

```

Place the sensor in the calibration gas (e.g. air) resp. solution. Press [ENTER].

Depending on the parameterized Drift control (see chapter 8.2.3.6 "Parameters for oxygen measurement based on optical sensors") one of the two following modes is active.

7.5.1.1 Auto mode

```

B  99.3  %AIR
B  25.0  °C

B Point1=100.0 %AIR  ...;
B  O2=99.30 %AIR  ↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter resp. sensor in the units selected by the user.

```

B  99.3  %AIR
B  25.0  °C

O2 P100=0.00 P0=99.00
Save Adjust  ↑

```

As soon as the stabilization criteria have been fulfilled the display changes.

The display shows now the values for the phase of the sensor at 100% air (P100) and at 0% (P0) air.

In case of a successful calibration, the calibration values are stored in the cal history and taken over (Adjust), stored in the cal history and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.5.1.2 Manual mode

```

B  99.3  %AIR
  25.0  °C

B Point1=100.0 %AIR ...↑
B  02=99.30 %AIR

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter resp. sensor in the units selected by the user.

Press [ENTER] to proceed.

```

B  99.3  %AIR
B  25.0  °C

02 P100=0.00 P0=99.00
Save Adjust ↑

```

The display shows now the values for the phase of the sensor at 100% air (P100) and at 0% (P0) air.

In case of a successful calibration, the calibration values are stored in the cal history and taken over (Adjust), stored in the cal history and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.5.2 Two-Point sensor calibration

The calibration of an optical sensor is always a calibration of the phase of the fluorescence signal towards the internal reference. A two-point calibration is a combination of first a calibration in air (100%) where a new phase P100 is measured and then a calibration in nitrogen (0%) where a new phase P0 is measured. This calibration routine gives the most accurate calibration curve over the whole measuring range.

```

B  99.3  %AIR
B  25.0  °C

Calibrate Sensor
Channel B 02 Opt ↑

```

Enter O₂ opt calibration mode as described in section 7.1 "Enter Calibration Mode".

```

B  99.3  PPb02
  25.0  °C

02 Optical Calibration
Type = 2 Point ↑

```

Select 2 point as the calibration type. Press [ENTER].

```

B  99.3  PPb02
B  25.0  °C

CalPres = 759.8 mmHg
RelativeHumid = 100 % ↑

```

Adjust calibration pressure (CalPres) and relative humidity (RelativeHumid), which are applied during calibration. Press [ENTER].

```

B  99.3  PPb02
B  25.0  °C

Press ENTER when
Sensor is in Gas 1(Air)↑

```

Place the sensor in the first calibration gas (e.g. air) resp. solution. Press [ENTER].

Depending on the parameterized Drift control (see chapter 8.2.3.6 "Parameters for oxygen measurement based on optical sensors") one of the two following modes is active.

7.5.2.1 Auto mode

```

B  99.3  PPbO2
  25.0  °C

B Point1=100.0 %AIR ...
B  02=99.30 %AIR  ...↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter resp. sensor in the units selected by the user.

```

B  99.3  PPbO2
B  25.0  °C

Press ENTER when
Gas is changed  ↑

```

As soon as the stabilisation criteria have been fulfilled, the display changes and prompts you to change the gas.

Place the sensor in the second calibration gas and press the [ENTER] key to go on with the calibration.

```

B  0.3  PPbO2
  25.0  °C

B Point2=0.000 %AIR ...
B  02=0.30 %AIR  ...↑

```

Enter the value for Point 2 including a decimal point and units. The value in the second text line is the value being measured by the transmitter resp. sensor.

```

B  0.3  PPbO2
B  25.0  °C

O2 P100=0.00 P0=99.00
Save Adjust  ↑

```

As soon as the stabilization criteria have been fulfilled the display changes. The display shows now the values for the phase of the sensor at 100% air (P100) and at 0% (P0) air.

In case of a successful calibration, the calibration values are stored in the cal history and taken over (Adjust), stored in the cal history and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.5.2.2 Manual mode

```

B  99.3  PPbO2
  25.0  °C

B Point1=100.0 %AIR ...
B  02=99.30 %AIR  ...↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter resp. sensor in the units selected by the user.

Press [ENTER] to proceed.

```

B  99.3  PPbO2
B  25.0  °C

Press ENTER when
Gas is changed  ↑

```

The display changes and prompts you to change the gas.

Place the sensor in the second calibration gas and press the [ENTER] key to go on with the calibration.

```


B  0.3  PPbO2
  25.0  °C

B Point2=0.000 %AIR ...
B  02=0.30 %AIR  ...↑

```

Enter the value for Point 2 including a decimal point and units. The value in the second text line is the value being measured by the transmitter resp. sensor.

Press [ENTER] to proceed.



The display shows now the values for the phase of the sensor at 100% air (P100) and at 0% (P0) air.


In case of a successful calibration, the calibration values are stored in the cal history and taken over (Adjust), stored in the cal history and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.



7.5.3 Process calibration

The calibration of an optical sensor is always a calibration of the phase of the fluorescence signal towards the internal reference. During a process calibration the phase in this point is measured and extrapolated over the measuring range.

Enter O₂ opt calibration mode as described in section 7.1 "Enter Calibration Mode".





Select 1 point as the calibration type. Press [ENTER].



Take a sample and press the [ENTER] key again to store the current measuring value. To show the ongoing calibration process, A or B (depending on the channel) is blinking in the display.

After determining the O₂ value of the sample press the [CAL] key again to proceed with the calibration.

Enter the O₂ value of the sample then press the [ENTER] key to start calibration.



The display shows now the values for the phase of the sensor at 100% air (P100) and at 0% (P0) air.

In case of a successful calibration, the calibration values are taken over and stored in the cal history (Adjust), only stored in the cal history (Calibrate) or aborted.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.

7.6 Calibration of a tunable diode laser (TDL) gas sensor

Oxygen calibration for a TDL sensor is performed as a one-point or process calibration.

7.6.1 One-point calibration for TDL gas sensors

Enter calibration mode as described in section 7.1 "Enter Calibration Mode".

A one-point calibration of gas sensors is always a slope (i.e. with air) calibration. A one point slope calibration is done in air or any other calibration gas with defined gas concentration.

Select 1 point as calibration type.

Press [ENTER].

Adjust calibration pressure (CalPres) and relative humidity (RelativeHumid), which are applied during calibration. Press [ENTER].

Adjust the optical path length for your individual system.

Place the sensor in the calibration gas (e.g. air). Press [ENTER].

Depending on the used drift control (see chapter 8.2.3.5) one of the two following modes is active.

```
B 20.9 %V O2
B 25.0 °C
Calibrate Sensor
Channel B TDL ↑
```

```
B 20.9 %V O2
H 25.0 °C
TDL Calibration
Type = 1 Point ↑
```

```
B 20.9 %V O2
25.0 °C
Pressure = 1013 hPa
Temperature = 23.00 °C ↑
```

```
B 20.9 %V O2
25.0 °C
Press ENTER when
Sensor is in Gas ↑
```

7.6.1.1 Auto mode

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user.

As soon as the stabilization criteria have been fulfilled the display changes. The display shows the calibration result for slope "S".

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

```
B 98.6 %sat
25.0 °C
B Point1 = 100.5 %sat
B 02 = 98.6 %sat ↑
```

```
B 98.6 %sat
B 25.0 °C
02 S=-68.66nA Z=0.0000nA
Save Adjust ↑
```

7.6.1.2 Manual mode

```

B  98.6 %sat
  25.0 °C

B Point1 = 100.5 %sat
B  O2 = 98.6 %sat ↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

```

B  98.6 %sat
B  25.0 °C

O2 S=-68.66nA Z=0.0000nA
Save Adjust ↑

```

After the calibration the slope "S" is displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.6.2 Process calibration for TDL gas sensors

```

B  12.1 %V O2
B  25.0 °C

Calibrate Sensor
Channel B TDL ↑

```

Enter calibration mode as described in section 7.1 "Enter Calibration Mode".

A process calibration of gas sensors is always a slope calibration.

```

B  12.1 %V O2
B  25.0 °C

TDL Calibration
Type = Process ↑

```

Select Process as the calibration type.

Press [ENTER]

```

B  12.1 %V O2
B  25.0 °C

Press ENTER to Capture
B  O2=0.0000 V% O2 ↑

```

Take a sample and press the [ENTER] key again to store the current measuring value. To show the ongoing calibration process, A or B (depending on the channel) is blinking in the display.

After determining the concentration value of the sample press the ► key again to proceed with the calibration.

```

B  12.1 %V O2
B  25.0 °C

B Point1 = 56.90 %sat
B  O2 = 57.1 %air ↑

```

Enter the concentration value of the sample then press the [ENTER] key to start the calculation of the calibration results.

After the calibration the slope "S" is displayed.

```

B  12.1 %V O2
B  25.0 °C

O2 S=-0.07nA Z=0.0000nA
Save Adjust ↑

```

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.

7.7 pH calibration



For pH sensors, the M400 transmitter features one-point, two-point (Auto or Manual mode) or process calibration with 9 preset buffer sets or manual buffer entry. Buffer values refer to 25 °C. To calibrate the instrument with automatic buffer recognition, you need a standard pH buffer solution that matches one of these values. (See section 8.2.3.3 "pH/ORP parameters" for configuring modes and selecting buffer sets.) Please select the correct buffer table before using automatic calibration (see chapter 19 "Buffer tables").



NOTE: For dual membrane pH electrodes (pH/pNa) only buffer Na+ 3.9M (see section 19.2.1 "Mettler-pH/pNa buffers") is available.

7.7.1 One point calibration

Enter pH calibration mode as described in section 7.1 "Enter Calibration Mode".





Select 1 point Calibration. With pH sensors a one point calibration is always performed as a off-set calibration.


Depending on the parameterized Drift control (see chapter 8.2.3.3 "pH parameters") one of the two following modes is active.

7.7.1.1 Auto mode

Place the electrode in the buffer solution and press the [ENTER] key to start the calibration.



The display shows the buffer the transmitter has recognized (Point 1) and the measured value.



As soon as the stabilisation criteria have been fulfilled the display changes. The display shows now the slope calibration factor S and the offset calibration factor Z.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.7.1.2 Manual Mode

```

8.29  pH
A 20.1 °C

A Point1 = 9.21  pH
A  pH = 8.29  pH  ↑

```

Place the electrode in the buffer solution. The display shows the buffer the transmitter has recognized (Point 1) and the measured value. Press [ENTER] to proceed.

```

8.29  pH
A 20.1 °C

pH S=100.0 %  Z=7.954pH
Save Adjust  ↑

```

The display shows now the slope calibration factor S and the offset calibration factor Z.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.7.2 Two-point calibration

```

A 7.26  pH
A 25.0  °C

Calibrate Sensor
Channel A pH  ↑

```

Enter pH calibration mode as described in section 7.1 "Enter Calibration Mode".

```

7.26  pH
A 20.1 °C

pH Calibration
Type = 2 Point  ↑

```

Select 2 Point calibration.

Depending on the parameterized Drift control (see chapter 8.2.3.3 "pH parameters") one of the two following modes is active.

7.7.2.1 Auto Mode

```

8.29  pH
A 20.1 °C

Press ENTER when
Sensor is in Buffer 1  ↑

```

Place the electrode in the first buffer solution and then press the [ENTER] key.

```

A 8.29  pH
A 20.1 °C

A Point1 = 9.21  pH  .. ↑
A  pH = 8.29  pH

```

The display shows the buffer the transmitter has recognized (Point 1) and the measured value.

```


8.29  pH
A 20.1 °C

Press ENTER when
Sensor is in Buffer 2  ↑


```

As soon as the stabilisation criteria have been fulfilled stabilisation criteria have been fulfilled, the display changes and prompts you to place the electrode in the second buffer.

Place the electrode in the second buffer solution and press the [ENTER] key to go on with the calibration.



The display shows the second buffer the transmitter has recognized (Point 2) and the measured value.




As soon as the stabilisation criteria have been fulfilled the display changes to show the slope calibration factor S and the offset calibration factor Z.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).


* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.


7.7.2.2 Manual Mode



Place the electrode in the first buffer solution. The display shows the buffer the transmitter has recognized (Point 1) and the measured value. Press [ENTER] to proceed.



Place the transmitter in the second buffer solution. The display shows the buffer the transmitter has recognized (Point 2) and the measured value. Press [ENTER] to proceed.



The display shows the slope calibration factor S and the offset calibration factor Z.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.7.3 Process calibration

B 9.68 pH
B 20.1 °C
Calibrate Sensor
Channel B pH ↑

Enter pH calibration mode as described in section 7.1 "Enter Calibration Mode".

A 9.68 pH
A 20.1 °C
pH Calibration
Type = Process ↑

Select Process calibration. With pH sensors a process calibration is always performed as a off-set calibration.

B 9.68 pH
B 20.1 °C
Press ENTER to Capture
B pH = 9.68 pH ↑

Take a sample and press the [ENTER] key again to store the current measuring Value. To show the ongoing calibration process, A or B (depending on the channel) is blinking in the display.

B 9.68 pH
B 20.1 °C

After determining the pH value of the sample, press the [CAL] key again to proceed with the calibration.

A 9.68 pH
A 20.1 °C
A Point1 = 9.220 pH
A pH = 9.68 pH ↑

Enter the pH value of the sample then press the [ENTER] key to start the calculation of the calibration results.

9.68 pH
20.1 °C
pH S=100.0 % Z=6.334pH
Save Adjust ↑

After the calibration the slope calibration factor S and the offset calibration factor Z are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

* only available with ISM sensor. The values will be stored in the sensor.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.


7.7.4 mV calibration (only for analog sensors)

A 6.49 pH
A 20.5 °C
Calibrate Sensor
Channel A mV ↑

Enter mV calibration mode as described in section 7.1 "Enter Calibration Mode".

H 6.49 pH
A 20.5 °C
A Point1 = 25.00 mV
A mV = 30.00 mV ↑

The user can now enter Point 1. The offset calibration factor is calculated by using the value of Point1 instead of the measured value (line 4, mV =) and displayed on the next screen.



Z is the newly calculated offset calibration factor. The slope calibration factor S is always 1 and does not enter the calculation.

After a successful calibration, the calibration values are taken over (Adjust) or discarded (Calibrate) or (Abort).

If "Adjust" is chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.


7.7.5 ORP calibration (only for ISM sensors)

In case that an pH sensor with solution ground based on ISM technology is connected to the M400, the transmitter gives the option to make in addition to the pH calibration an ORP calibration.




NOTE: In case of choosing ORP calibration the parameters defined for pH (see chapter 8.2.3.3 "pH/ORP parameters", PATH: Menu/Configure/Measurement/pH) will not be considered.

Enter ORP calibration mode as described in section 7.1 "Enter Calibration Mode".



The user can now enter Point 1. In addition the actual ORP is displayed.


Press [ENTER] to proceed.



The display shows the slope calibration factor S and the offset calibration factor Z.

After a successful calibration, the calibration values are taken over and stored in the cal history (Adjust), only stored in the cal history (Calibrate) or aborted.

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.



7.8 ISFET calibration



NOTE: When measuring with an ISFET sensor, the nominal zero point must be adjusted each time a new sensor is connected (to adjust the operating point). The adjustment for that sensor remains stored in the transmitter. Immerse sensor in a zero point buffer (6.5 ... 7.5). Make a mV calibration and enter for point 1 the value 00.00 mV. (see chapter 7.7.4 "mV calibration"). Afterwards a two-point calibration (see chapter 7.7.2 "Two-point calibration") of the ISFET sensor is recommended to achieve best measuring results.

7.8.1 One-point calibration

Enter ISFET calibration mode as described in section 7.1 "Enter Calibration Mode".

A 7.00 pH
A 20.5 °C
Calibrate Sensor
Channel A ISFET ↑

Select 1 point Calibration. With ISFET sensors a one point calibration is always performed as a offset calibration.

The following calibration steps are the same as described for pH sensors (see chapter 7.6.1 "One point calibration").

H 7.00 pH
A 20.5 °C
ISFET Calibration
Type = 1 Point ↑

7.8.2 Two-point calibration

Enter ISFET calibration mode as described in section 7.1 "Enter Calibration Mode".

A 7.00 pH
A 20.5 °C
Calibrate Sensor
Channel A ISFET ↑

Select 2 point Calibration.

The following calibration steps are the same as described for pH sensors (see chapter 7.6.2 "Two-point calibration").

H 7.00 pH
A 20.5 °C
ISFET Calibration
Type = 2 Point ↑

7.8.3 Process calibration

Enter ISFET calibration mode as described in section 7.1 "Enter Calibration Mode".


A 7.00 pH
A 20.5 °C
Calibrate Sensor
Channel A ISFET ↑

Select Process Calibration. With ISFET sensors a process calibration is always performed as a offset calibration.

The following calibration steps are the same as described for pH sensors (see chapter 7.6.3 "Process calibration").

7.00 pH
A 20.5 °C
ISFET Calibration
Type = Process ↑

7.8.4 mV calibration




Enter mV calibration mode as described in section 7.1 "Enter Calibration Mode".

The following calibration steps are the same as described for pH sensors (see chapter 7.6.4 "mV calibration").


7.9 Dissolved carbon dioxide calibration

For dissolved carbon dioxide (CO₂) sensors, the M400 transmitter features one-point, two-point (Auto or Manual mode) or process calibration. For the one-point or two-point calibration the solution with pH = 7.00 and/or pH = 9.21 of the Mettler – 9 standard buffer can be used (see also chapter 8.2.3.9 "Dissolved carbon dioxide parameters") or the buffer value can be entered manually.

7.9.1 One point calibration




Enter CO₂ calibration mode as described in section 7.1 "Enter Calibration Mode".




Select 1 point Calibration. With CO₂ sensors a one point calibration is always performed as a offset calibration.

Depending on the parameterized Drift control (see chapter 8.2.3.9 "Dissolved carbon dioxide parameters") one of the two following modes is active.


7.9.1.1 Auto Mode



Place the electrode in the buffer solution and press the [ENTER] key to start the calibration.



The display shows the buffer the transmitter has recognized (Point 1) and the measured value.



As soon as the stabilisation criteria have been fulfilled the display changes to show the slope calibration factor S and the offset calibration factor Z.

After a successful calibration, the calibration values are taken over (Adjust) or were aborted (Calibrate or Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.9.1.2 Manual Mode

```

A 122.4 hPa
A 26.1 °C

A Point1 = 7.00 pH
A CO2 = 7.17 pH ↑

```

Place the electrode in the buffer solution. The display shows the buffer the transmitter has recognized (Point 1) and the measured value. Press [ENTER] to proceed.

```

A 122.4 hPa
A 26.1 °C

pH S=100.0 % Z=6.947pH
Save Adjust ↑

```

The display shows now the slope calibration factor S and the offset calibration factor Z.

After a successful calibration, the calibration values are taken over (Adjust) or were aborted (Calibrate or Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.9.2 Two-point calibration

Enter CO₂ calibration mode as described in section 7.1 "Enter Calibration Mode".

```

A 180.4 hPa
A 26.1 °C

Calibrate Sensor
Channel A CO2 ↑

```

Select 2 Point calibration.

```

H 180.4 hPa
A 26.1 °C

CO2 Calibration
Type = 2 point ↑

```

Depending on the parameterized Drift control (see chapter 8.2.3.9 "Dissolved carbon dioxide parameters") one of the two following modes is active.

7.9.2.1 Auto Mode

Place the electrode in the first buffer solution and press the [ENTER] key to start the calibration.

```

H 137.5 hPa
A 26.1 °C

Press ENTER when
Sensor is in Buffer 1 ↑

```

The display shows the buffer the transmitter has recognized (Point 1) and the measured value.

```

154.5 hPa
A 26.1 °C

A Point1 = 7.00 pH
A CO2 = 7.07 pH ↑

```

As soon as the stabilisation criteria have been fulfilled, the display changes and prompts you to place the electrode in the second buffer.

```

122.4 hPa
A 26.1 °C

Press ENTER when
Sensor is in Buffer 2 ↑

```

Place the electrode in the second buffer solution and press the [ENTER] key to go on with the calibration.


```

2.8    hPa
A 26.1  °C

Point2 = 8.21  pH  ...
CO2 = 8.88  pH  ↑

```

The display shows the second buffer the transmitter has recognized (Point 2) and the measured value.

```

2.8    hPa
A 26.1  °C

pH S=74.21 %  Z=6.948pH
Save Adjust  ↑

```

As soon as the stabilisation criteria have been fulfilled, the display changes to show the slope calibration factor S and the offset calibration factor Z.

After a successful calibration, the calibration values are taken over (Adjust) or were aborted (Calibrate or Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.9.2.2 Manual Mode

```

A 122.4 hPa
A 26.1  °C

Point1 = 7.00  pH  ↑
CO2 = 7.17  pH

```

Place the electrode in the first buffer solution. The display shows the buffer the transmitter has recognized (Point 1) and the measured value. Press [ENTER] to proceed.

```

A 3.1    hPa
A 26.1  °C

Point2 = 8.21  pH  ↑
CO2 = 8.77  pH

```

Place the electrode in the second buffer solution. The display shows the buffer the transmitter has recognized (Point 2) and the measured value. Press [ENTER] to proceed.

```

2.8    hPa
A 26.1  °C

pH S=74.21 %  Z=6.948pH
Save Adjust  ↑

```

The display shows the slope calibration factor S and the offset calibration factor Z.

After a successful calibration, the calibration values are taken over (Adjust) or were aborted (Calibrate or Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.9.3 Process calibration

```

17.3    hPa
A 27.3  °C

Calibrate Sensor
Channel A CO2  ↑

```

Enter CO₂ calibration mode as described in section 7.1 "Enter Calibration Mode".

```

7.00    pH
A 20.5  °C

ISFET Calibration
Type = Process  ↑

```

Select Process calibration. With CO₂ sensors a process calibration is always performed as a off-set calibration.

```

A 17.3 hPa
A 27.3 °C
Press ENTER to Capture
A CO2 = 17.3 hPa ↑

```

Take a sample and press the [ENTER] key again to store the current measuring value. To show the ongoing calibration process, A or B (depending on the channel) is blinking in the display. After determining the CO₂ value of the sample, press the ► key again to proceed with the calibration.

```

A 17.3 hPa
A 27.3 °C
A Point1 = 16.90 hPa
A CO2 = 17.3 hPa ↑

```

Enter the CO₂ value of the sample then press the [ENTER] key to start calibration.

```

A 17.3 hPa
A 27.3 °C
pH S=100.0 % Z=7.009pH
Save Adjust ↑

```

The display shows the slope calibration factor S and the offset calibration factor Z.

After a successful calibration, the calibration values are taken over (Adjust) or were aborted (Calibrate or Abort).

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.

7.10 CO₂ Hi (InPro 5500 i)

7.10.1 One point calibration

```

B 189.0 hPa
B 25.0 °C
Calibrate Sensor
Channel B CO2 Hi ↑

```

While in measurement mode press the key [CAL]. Press the ▼ or ▲ key to select the CO₂ Hi (InPro 5500 i) and press the [ENTER] key to call the sub function.

```

B 189.0 hPa
H 25.0 °C
CO2 Hi Calibration
Type = 1 Point ↑

```

Select "1 point" and press [ENTER].

```

B 189.0 hPa
H 25.0 °C
Press ENTER when
Sensor is in Gas (CO2) ↑

```

Place the sensor in the calibration gas (e.g. CO₂ gas 100%) resp. solution. Press [ENTER].

```

B 189.0 hPa
H 25.0 °C
B Point1=1013. hPa
B CO2=189.0 hPa ↑

```

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user.

Depending on the Drift control (see User Manual chapter 8.2.3.10 "CO₂ Hi Parameters"), one of the two following modes is active.

```

B 189.0 hPa
H 25.0 °C
CO2 S= 9.28 mV BL= 253 mV
Save Adjust ↑

```

If Drift is auto, as soon as the signal of stabilization criteria have been fulfilled, transmitter will display the calibration result automatic.

If Drift is Manual, press [ENTER] to proceed as soon as the value is stable, transmitter will display the calibration result after manual press [ENTER]

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.10.2 Process calibration

Start as in chapter One point Calibration described.

Select Process Calibration

```

B 189.0 hPa
H 25.0 °C
CO2 Hi Calibration
Type Process ↑

```

Take a sample and press the [ENTER] key again to store the current measuring value. To show the ongoing calibration process, A or B (depending on the channel) is blinking in the display.

```

B 189.0 hPa
B 25.0 °C
Press ENTER to Capture
B CO2=189.0 hPa ↑

```

After determining the CO₂ value of the sample press the [CAL] key again to proceed with the calibration.

Enter the CO₂ value of the sample then press the [ENTER] key to start the calculation of the calibration results.

```

B 189.0 hPa
H 25.0 °C
B Point1=1013. hPa
B CO2=189.0 hPa ↑

```

After the calibration the slope calibration factor S and the offset calibration factor Z are displayed.

In case of a successful calibration, the calibration values are stored in the cal history* and taken over (Adjust), stored in the cal history* and not taken over (Calibrate) or discarded (Abort).

```

B 189.0 hPa
H 25.0 °C
CO2 S= 9.28 mV BL= 253 mV
Save Adjust ↑

```

If "Adjust" or "Calibrate" are chosen, the message "Calibration successful" is displayed. The M400 returns to the measuring mode.

7.11 Sensor temperature calibration (only for analog sensors)

Enter Sensor calibration mode as described in section 7.1 "Enter Calibration Mode" and select Temperature.

```

A 1.25 μS/cm
A 25.00 °C
Calibrate Sensor
Channel A Temperature ▲

```

7.11.1 One-Point sensor temperature calibration

Select 1 point calibration. Slope or Offset can be selected with the 1 Point calibration. Select Slope to recalculate the Slope factor M (Multiplier) or Offset to recalculate the offset calibration factor A (Adder).

```

A 1.25 μS/cm
A 25.00 °C
Temperature Calibration
Type = 1 point Slope ▲


```

Enter the value for Point 1 and press [ENTER].

```

A 1.25 μS/cm
A 25.00 °C
A Point1 = 25.02 °C
A T = 25.00 °C ▲

```




After a successful calibration, the calibration values are taken over (Adjust) or aborted (Calibrate, Abort).


If "Adjust" has been chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.11.2 Two-Point sensor temperature calibration


Select 2 Point as calibration type.



Enter the value for Point 1 and press [ENTER].



Enter the value for Point 2 and press [ENTER].



After a successful calibration, the calibration values are taken over (Adjust) or aborted (Calibrate, Abort).

If "Adjust" has been chosen, the message "Calibration successful" is displayed. In any case you will get the message "Re-install sensor" and "Press ENTER" on the display. After pressing "ENTER" the M400 returns to the measuring mode.

7.12 Edit sensor calibration constants (only for analog sensor)

Enter Calibration mode as described in section 7.1 "Enter Calibration Mode" and select Edit, Edit pH, Edit ISFET, or Edit mV.




All calibration constants for the selected sensor channel are displayed. Primary measurement constants (p) are displayed on Line 3. Secondary measurement (temperature) constants (s) for the sensor are displayed on Line 4.



The calibration constants can be changed in this menu.

Select Yes to save the new calibration values and the successful calibration is confirmed on the display.





NOTE: Each time a new analog conductivity sensor is connected to the M400 Type 1, 2, 3 transmitter, it is necessary to enter the unique calibration data (cell constant and offset) located on the sensor label.

7.13 Sensor verification

Enter Calibration mode as described in section 7.1. "Enter Calibration Mode" and select Verify.

A 1.25 $\mu\text{S}/\text{cm}$
A 25.00 $^{\circ}\text{C}$
Calibrate Sensor
Channel A Verify ▲


The measured signal of the primary and the secondary measurement in electrical units are shown. The meter calibration factors are used when calculating these values.

Press [ENTER] to exit from this display.

A 1.25 $\mu\text{S}/\text{cm}$
A 25.00 $^{\circ}\text{C}$
Verify Cal:Channel A
Ch A 1.820 MΩ 1.097 KΩ

8 Configuration

(PATH: Menu/Configure)



* Only available in combination with ISM sensors


8.1 Enter configuration mode



While in Measurement mode, press the ◀ key. Press the ▲ or ▼ key to navigate to the Configure – menu and press [ENTER].

8.2 Measurement

(PATH: Menu/Configure/Measurement)




Enter configuration mode as described in Section 8.1 “Enter configuration mode”.

Press the [ENTER] key to select this menu. The following sub menus can now be selected: Channel Setup, Temperature Source, Comp/pH/O₂ and Set Averaging.

8.2.1 Channel Setup


(PATH: Menu/Configure/Measurement/Channel Setup)



Press the [ENTER] key to select the “Channel Setup” menu.

Depending on the connected sensor (analog or ISM) the channel can be chosen.

8.2.1.1 Analog sensor




Select sensor type Analog and press [ENTER].

Available measurement types are (depends on transmitter type):

Measurement parameter	Type
pH/ORP = pH or ORP	1,2,3
ISFET = pH measurement based on ISFET technology	1,2,3
Cond (2) = 2 electrode conductivity	1,2,3
Cond (4) = 4 electrode conductivity	1,2,3
Cond Ind = Inductive conductivity	1 Cond Ind
O ₂ hi = Dissolved oxygen or oxygen in gas (ppm)	2,3
O ₂ lo = Dissolved oxygen or oxygen in gas (ppb)	3
CO ₂ = Accurate CO ₂ measurement	3

The 4 lines of the display can now be configured with sensor channel "A" for each line of the display as well as measurements and unit multipliers. Pressing the [ENTER] key will display the selection for lines a, b, c and d.

8.2.1.2 ISM sensor



Select sensor type ISM and press [ENTER].

If an ISM sensor is connected, the transmitter automatically (Parameter = Auto) recognizes the type of sensor. You can also fix the transmitter to a certain measurement parameter (Parameter = pH/ORP, pH/pNa, Cond(4), O₂ hi, O₂ lo, O₂ trace or O₂ Opt), depending on the type of transmitter you have.


Measurement parameter	Type
pH/ORP = pH and ORP	1, 1 Cond Ind, 2, 3
pH/pNa = pH and ORP (with pH/pNa electrode)	1, 1 Cond Ind, 2, 3
Cond (4) = 4 electrode conductivity	1, 1 Cond Ind, 2, 3
O ₂ hi = Dissolved oxygen or oxygen in gas (ppm)	2, 3
O ₂ lo = Dissolved oxygen or oxygen in gas (ppb)	3
O ₂ Trace = Dissolved oxygen or oxygen in gas (ppb)	3
O ₂ Opt = Dissolved oxygen optical	2, 3
TDL = TDL(ppm O ₂ , ppmCO, ppmH ₂ O)	3
CO ₂ = Dissolved carbon dioxide	3
CO ₂ Hi = Dissolved carbon dioxide Hi(g/L)	3

The 4 lines of the display can now be configured with sensor channel "A" for each line of the display as well as measurements and unit multipliers. Pressing the [ENTER] key will display the selection for lines a, b, c and d.



NOTE: Beside the measurement values pH, O₂, T, etc. also the ISM values DLI, TTM and ACT can be assigned to the different lines and linked to the analog outputs (see chapter 8.3 "Analog outputs") or set points (see chapter 8.4 "Set points")


8.2.1.3 Save changes of the channel setup



After the procedure of the channel setup described in the previous chapter pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.2 Temperature source (only for analog sensors)

(PATH: Menu/Configure/Measurement/Temperature Source)



Enter Measurement as described in chapter 8.2 "Measurement". Select Temperature Source by using the ▲ or ▼ key and press [ENTER].




The following options can be chosen:

- Auto: The transmitter automatically recognizes the temperature source.
- Use NTC22K: Input will be taken from the sensor attached.
- Use Pt1000: Temperature input will be taken from the sensor attached.
- Use Pt100: Input will be taken from the sensor attached.
- Fixed = 25 °C: Allows a specific temperature value to be entered. It must be chosen when customer use pH sensor without temperature source.



NOTE: If temperature source is set to Fixed, the temperature applied during one-point and/or two-point calibration of pH electrodes can be adjusted within the corresponding calibration procedure. After the calibration the fixed temperature defined in this configuration menu is valid again.

Pressing the [ENTER] key will bring up the Save Changes dialog.



Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3 Parameter related settings


(PATH: Menu/Configure/Measurement/pH or ISFET or O₂ or O₂ optical, O₂ opt sampling rate, LED Mode or Resistivity or Concentration Table or CO₂, CO₂ Hi, TDL)

Additional measurement and calibration parameters can be set for each parameter; conductivity, pH, ISFET, O₂, CO₂, CO₂ Hi, and TDL



NOTE: Use pH menu for settings of pH/pNa sensors.

Enter Configuration Mode as described in section 8.1 "Enter Configuration mode" and select the menu Measurement (see section 8.2 "Configuration/Measurement").



Depending on the connected sensor, the menu pH, ISFET, O₂, O₂ optical, O₂ opt sampling rate, LED Mode, Resistivity, Concentration Table CO₂, CO₂ Hi or TDL, can be selected by using the ▲ or ▼ key. Press [ENTER]

For more details, please see the following explanations depending on the selected parameter.

8.2.3.1 Conductivity temperature compensation

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter conductivity has been chosen or a four-electrode conductivity sensor based on ISM technology is connected to the transmitter, the temperature compensation mode can be selected. Temperature compensation should be matched to the characteristics of the application. The transmitter considers this value for the temperature compensation by calculating and displaying the result for the measured conductivity.




NOTE: For calibration purposes the temperature compensation as defined at the menu "Cal/Compensation" for the buffers resp. samples will be considered (see also chapter 7.2 "Conductivity Calibration for two- or four-electrode sensors" resp. chapter 7.3 "Conductivity calibration for inductive sensors").


For doing this adjustment the menu "Resistivity", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings")

The first two measurement lines are displayed on the screen. This chapter described the procedure for the first measurement line. By using the key ► the second line will be chosen. To select the 3rd and 4th line press [ENTER]. The procedure itself works at every measurement line in the same way.

Choices are "Standard", "Lin 25°C" and "Lin 20°C".




Standard compensation includes compensation for non-linear high purity effects as well as conventional neutral salt impurities and conforms to ASTM standards D1125 and D5391.




Lin 25 °C compensation adjusts the reading by a factor expressed as a "% per °C" (deviation from 25 °C). Use only if the solution has a well-characterized linear temperature coefficient.

The factory default setting is 2.0%/°C.



Lin 20 °C compensation adjusts the reading by a factor expressed as a "% per °C" (deviation from 20 °C). Use only if the solution has a well-characterized linear temperature coefficient.

The factory default setting is 2.0%/°C



If compensation mode "Lin 25 °C" or "Lin 20 °C" has been chosen, the factor for the adjustment of the reading can be modified after pressing [ENTER] (If working at measurement line 1 or 2 press [ENTER] twice).

Adjust the factor for temperature compensation.


Pressing [ENTER] will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.2 Concentration table

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter conductivity has been chosen or an four-electrode conductivity sensor based on ISM technology is connected to the transmitter, a concentration table can be defined.

To specify customers-specific solutions, up to 9 concentration values can be edited in a matrix together with up to 9 temperatures. To do so the desired values are edited under the concentration table menu. Furthermore the conductivity values for the according temperature and concentration values are edited.

For doing the settings the menu "Concentration Table", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings").




Define the desired **unit**.

Press [ENTER]

NOTE: Refer to section 8.2.1 "Channel Setup" to choose the unit used in the display.


Enter the amount of desired temperature points (**Temp Point**) and **Concentration Points**.

Press [ENTER]




Enter the values for the different concentrations (**ConcentrationX**).

Press [ENTER]



Enter the value of the 1st temperature (**Temp1**) and the value for the conductivity which belongs to the first concentration at this temperature.

Press [ENTER]



Enter the value for the conductivity which belongs to the second concentration at the first temperature and press [ENTER] etc..

After entering all conductivity values, that belong to the different concentrations at the first temperature point, enter in the same way the value of the 2nd temperature point (**Temp2**) and the conductivity value which belongs at the second temperature to the first concentration. Press [ENTER] and go on in the same way for the next concentration points as described for the first temperature point.

Enter in this way the values at every temperature point. After entering the last value, pressing [ENTER] again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

NOTE: The values for the temperature have to increase from Temp1 to Temp2 to Temp3 etc.. The values for the concentration have to increase from Concentration1 to Concentration2 to Concentration3 etc..




NOTE: The conductivity values at the different temperatures have to increase or decrease from Concentration1 to Concentration2 to Concentration3 etc.. Maxima and/or minima are not permitted. If the conductivity values at Temp1 are increasing with the different concentrations, they have to increase also at the other temperatures. If the conductivity values at Temp1 are decreasing with the different concentrations, they have to decrease also at the other temperatures.

8.2.3.3 pH/ORP parameters

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter pH/ORP has been chosen or an pH sensor based on ISM technology is connected to the transmitter, the parameters drift control, buffer recognition, STC, IP, fixed Calibration temperature and the displayed units for slope and zero point can be set resp. adjusted.

For doing this adjustments resp. settings the menu "pH", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings").




Select the **drift control** for calibration as Auto (drift and time criteria have to be fulfilled) or manual (The user can decide when a signal is stable enough to complete calibration) followed by the relevant buffer table for the automatic buffer recognition. If the drift rate is less than 0.4 mV over a 19 second interval then the reading is stable and the calibration is done using the last reading. If the drift criteria is not met within 300 seconds then the calibration times out and the message "Calibration Not Done" Press ENTER Enter to "Exit" is displayed.

Press [ENTER]


For automatic **buffer recognition** during calibration, select the buffer solution set that will be used: Mettler-9, Mettler-10, NIST Tech, NIST Std = JIS Std, HACH, CIBA, MERCK, WTW, JIS Z 8802 or None. See Section 19 "Buffer tables" for buffer values. If the auto buffer feature will not be used or if the available buffers are different from those above, select None. Press [ENTER].




NOTE: For dual membrane pH electrodes (pH/pNa) only buffer Na+ 3.9M (see section 19.2.1 "Mettler-pH/pNa buffers") is available.




STC is the solution temperature coefficient in units of pH/°C referenced to 25 °C (Default = 0.000 for most applications). For pure waters, a setting of 0.016 pH/°C should be used. For low conductivity power plant samples near 9 pH, a setting of 0.033 pH/°C should be used. These positive coefficients compensate for the negative temperature influence on the pH of these samples. Press [ENTER].



IP is the isothermal point value (Default = 7.000 for most applications). For specific compensation requirements or non standard inner buffer value, this value can be changed. Press [ENTER].



STC RefTemp sets the temperature to which solution temperature compensation is referenced. The displayed value and the output signal is referenced to STC RefTemp. Selecting "No" means solution temperature compensation is not used. The most common reference temperature is 25°C. Press [ENTER].



The units for the slope and the zero point, that will be shown on the display can be chosen. The default setting for the unit of the slope is [%] and can be changed to [pH/mV]. For the zero point the default setting of the unit is [pH] and can be changed to [mV]. Use the ► key to move to the input field and select the unit by using the ▲ or ▼ key.

Pressing [ENTER] again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.4 ISFET parameters


If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter ISFET has been chosen, the parameters drift control, buffer recognition, STC, IP, fixed Calibration temperature and the displayed units for slope and zero point can be set resp. adjusted.

In case, that an ISFET sensor has been parameterized, the menu "ISFET" will be displayed and has to be chosen. (see chapter 8.2.3 "Parameter related settings") In the same way as described for pH parameters (see chapter 8.2.3.3 "pH/ORP parameters") parameters for ISFET sensors can be modified.

8.2.3.5 Parameters for oxygen measurement based on amperometric sensors

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter O₂ hi, O₂ lo or O₂ Trace has been chosen or an oxygen sensor based on ISM technology is connected to the transmitter, the parameters calibration pressure, process pressure, ProCalPres, salinity and relative humidity can be set resp. adjusted. If an ISM sensor is connected, there is furthermore the option to adjust the parameterization voltage.


For doing this adjustments resp. settings the menu "O₂", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings")



Enter the Calibration pressure in line 3. The default value for CalPres is 759.8 and the default unit is mmHg.


Select Edit in line 4 for entering the applied process pressure manually. Select Ain if an analog input signal is used for the applied process pressure. Press [ENTER]

NOTE: The menu Ain can only be selected if the transmitter is configured for an ISM sensor. 4 to 20 mA input signal has to be wired on TB3. Refer to section 4.3.9 "TB3 – 4 to 20 mA input signal" for wiring of the 4 to 20 mA signal.




If Edit has been chosen an input field for entering the value manually is displayed. In case that Ain has been selected the start value (4mA) and the end value (20 mA) of the range for the 4 to 20 mA input signal have to be entered.

Press [ENTER]



For the algorithm of the process calibration the applied pressure (ProcCalPres) has to be defined. The value of the process pressure (ProcPres) or the calibration pressure (CalPres) can be used. Chose the pressure, that applies during the process calibration, resp. should be used for the algorithm.


Select the required Drift Control of the measuring signal during the calibration procedure. Choose Manual if the user will decide when a signal is stable enough to complete the calibration. Select Auto and an automatic stability control of the sensor signal during calibration through the transmitter will be done. Press [ENTER]



In the next step the salinity of the measured solution can be modified.

In addition the relative humidity of the calibration gas can also be entered. The allowed values for relative humidity are in the range 0% to 100%. When no humidity measurement is available, use 50% (default value).

Press [ENTER]



If an ISM sensor has been connected resp. configured there is furthermore the option to adjust the polarization voltage for the sensor. Different value can be entered for the measuring mode (Umeaspol) and for the calibration mode (Ucalpol). For entered values 0 mV to -550 mV the connected sensor will be set to a polarization voltage of -500mV. If the entered value is less then -550mV, the connected sensor will set to a polarization voltage of -674mV.




NOTE: During a process calibration, the polarization voltage Umeaspol, defined for the measuring mode, will be used.



NOTE: If a one point calibration is executed, the transmitter sends the polarization voltage, valid for the calibration, to the sensor. If the polarization voltage for the measuring mode and calibration mode is different, the transmitter will wait 120 seconds before starting the calibration. In this case the transmitter will also go after the calibration for 120 seconds to the HOLD Mode, before returning to the measuring mode again.

Press [ENTER]




The display shows the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.6 Parameters for oxygen measurement based on optical sensors

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter O₂ Opt has been chosen, the parameters calibration pressure, process pressure, ProCalPres, salinity, drift control and relative humidity can be set resp. adjusted.


For doing these adjustments the menu "O₂ optical", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings")

Press [ENTER]



Enter the calibration pressure (line 3). The default value for CalPres is 759.8 and the default unit is mmHg.


Select Edit in line 4 for entering the applied process pressure manually. Select Ain if an analog input signal is used for the applied process pressure. Press [ENTER]



If Edit has been chosen an input field for entering the value manually is displayed. In case that Ain has been selected the start value (4mA) and the end value (20 mA) of the range for the 4 to 20 mA input signal have to be entered.

Press [ENTER]


NOTE: Refer to section 4.3.9 "TB3 – 4 to 20 mA input signal" for wiring of the 4 to 20 mA signal.



For the algorithm of the process calibration the applied pressure (ProcCalPres) has to be defined. The value of the process pressure (ProcPres) or the calibration pressure (CalPres) can be used. Choose the pressure, that applies during the process calibration, resp. should be used for the algorithm.

Select the drift control for calibration as Auto (drift and time criteria have to be fulfilled) or manual (The user can decide when a signal is stable enough to complete calibration). If Auto is selected, the drift is checked by the sensor. If the drift criteria is not met within a defined time (depending on the sensor model) the calibration times out and the message "Calibration Not Done" is displayed. Press ENTER to "Exit" is displayed.


Press [ENTER]



In the next step the salinity of the measured solution can be modified.

In addition the relative humidity of the calibration gas can also be entered. The allowed values for relative humidity are in the range 0% to 100%. When no humidity measurement is available, use 50% (default value).

Press [ENTER]




Select through the parameter **ProcCal** between Scaling and Calibration for process calibration. If Scaling has been chosen, the calibration curve of the sensor will be untouched, but the output signal of the sensor will be scaled. In case of calibration value <1%, the offset of the sensor output signal will be modified during scaling, for value >1% the slope of the sensor output will be adjusted. For further information about scaling refer to the sensor manual.

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.7 Adjusting sampling rate for optical sensors

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter O₂ Opt has been chosen the parameter O₂ opt sampling rate can be adjusted.

For doing this adjustment the menu "O₂ opt sampling rate" has to be chosen. (see chapter 8.2.3 "Parameter related settings")




The time interval from one measuring cycle of the sensor to the other can be adjusted i.e. adapted to the application. A higher value will increase the life time of the OptoCap of the sensor.

Pressing the [ENTER] key will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.8 LED Mode

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter O₂ Opt has been chosen the parameters LED, T off, DI 1 LED control can be set resp. adjusted.

For doing these adjustments the menu "LED Mode" has to be chosen. (see chapter 8.2.3 "Parameter related settings").



The operation mode for the LED of the sensor can be selected. There are the following options.


Off: LED is permanently switched off.

On: LED is permanently switched on.

Auto: The LED is switched on as long as the measured media temperature is smaller then Toff (see next value) or switched off thru the digital input signal (see over next value).

NOTE: If the LED is switched off, no oxygen measurement is performed.


Press [ENTER]



Depending on the measured media temperature the LED of the sensor can be automatically switched off. If the media temperature is higher then Toff, the LED will switched off. The LED will be switched on as soon as the media temperature falls below Toff - 3K. This function give the option to increase the lifetime of the OptoCap by switching off the LED thru SIP or CIP cycles.

NOTE: This function is only active if the operation mode of the LED is set to "Auto".

Press [ENTER]



The operation mode of the sensor LED can also be influenced by the digital input signal DI1 of the transmitter. If the parameter "DI 1 LED control" is set to Yes, the LED is switched off, if DI1 is active. If "DI 1 LED control" is set to No, the signal of DI1 has now influence on the operation mode of the sensor LED.

This function is helpful for remote control of the sensor thru a SPS or DCS.

NOTE: This function is only active if the operation mode of the LED is set to "Auto".

Pressing the [ENTER] key will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.9 Dissolved carbon dioxide parameters

If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter CO₂ has been chosen, the parameters drift control, salinity, HCO₃, TotPres and the displayed units for slope and zero point can be set resp. adjusted.

For doing this adjustment resp. settings the menu "CO₂", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings")

```

A   2.8   hPa
A   26.1   °C

Drift Control = Auto
pH Buffer = Mettler-9  ↑
  
```

Select **Drift Control** for calibration as Auto (drift and time criteria have to be fulfilled) or manual (the user can decide when a signal is stable enough to complete calibration) followed by the relevant buffer table for the automatic buffer recognition. If the drift rate is less than 0.4 mV over a 19 second interval then the reading is stable and the calibration is done using the last reading. If the drift criteria is not met within 300 seconds then the calibration times out and the message "Calibration Not Done Press ENTER to Exit" is displayed.

For automatic **buffer recognition** during calibration, select the buffer Mettler-9. Use for calibration purposes solution with pH = 7.00 and/or pH = 9.21. If the auto buffer feature will not be used or if the available buffers are different from those above, select None. Press [ENTER] to go on.

```

A   2.8   hPa
A   26.1   °C

Salinity = 28.00 g/L
HCO3 = 0.050 Mol/L  ↑
  
```

The **Salinity** describes the total amount of solved salts in the CO₂ electrolyte of the sensor connected to the transmitter. It is a sensor specific parameter. The default value (28.00 g/L) is valid for the InPro 5000. Do not change this parameter if the InPro 5000 will be used.

The parameter **HCO₃** describes the concentration of hydrogen carbonate in the CO₂ electrolyte of the sensor connected to the transmitter. It is also a sensor specific parameter. The default value 0.050 Mol/L is valid for the InPro 5000. Do not change this parameter if the InPro 5000 will be used.

To go on press [ENTER] again.

```


A   2.8   hPa
A   26.1   °C

TotPres = 750.0 mmHg  ↑
  
```

If the unit for the measured dissolved carbon dioxide is %sat, the pressure during the calibration resp. measurement has to be considered. This will be done by setting the parameter TotPres. If another unit than %sat has been selected, the result will not be influenced by this parameter.


Pressing [ENTER] again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.2.3.10 CO₂ Hi (InPro 5500 i) parameters



If during the channel setup (see chapter 8.2.1 "Channel setup") the parameter CO₂ Hi has been chosen, the parameters drift control, CO₂-solub, Temp factor can be set resp. adjusted.

For doing this adjustment resp. settings the menu "CO₂ Hi", that will be displayed, has to be chosen. (see chapter 8.2.3 "Parameter related settings")



There are the following options for CO₂-solub. Default option is "for beer".

"for beer": select this option if beer is measuring.

CO₂-solub is 1.420g/L, Temp Factor is 2485;


"for pure water": select this option if pure water is measuring.

CO₂-solub is 1.471g/L, Temp Factor is 2491;

"for cola": select this option if cola is measuring.

CO₂-solub is 1.345g/L, Temp Factor is 2370;

"for individual": select this option except these application mentioned above.



Entry the CO₂ solubility and Temp factor if these values are known or calculate these two values according to formula:

$$HCO_2 = A \times \exp(B \times (1/T - 1/298.15))$$

$$cCO_2 = HCO_2 \times pCO_2$$

HCO₂: CO₂-solubility in water (g/l*bar)

A: CO₂-solubility at 25 °C (g/l bar)

B: Temp Factor, exponential factor of CO₂-solubility (K)


T: Temperature in K

pCO₂: Partial pressure of CO₂ in calibration gas (in mbar)


cCO₂: CO₂ concentration

8.2.3.11 TDL Installation

(PATH: Quick Setup/TDL/Installation)




While in measurement mode press the key [MENU]. Press the ▲ or ▼ key to select the TDL and then the Installation menu item.



In this mode, the current live value of the % transmission is displayed during 5 minutes until it automatically returns to the Measurement mode. Use this value to rotate the blue sensor head attached with a loose clamp connection on to the probe until the maximum transmission is found. In this position, and secure the blue sensor head into position and tighten the clamp.

8.2.3.12 TDL Commissioning

(PATH: Quick Setup/TDL/Commissioning)




While in measurement mode press the key [MENU]. Press the ▲ or ▼ key to select the TDL and then the Commissioning menu item.

First, select the type of pressure compensation selected:

- External: current external pressure value coming from a pressure transducer of 4.. 20 mA analog output


- Fixed: pressure compensation uses a fixed value to be set manually.

Note: if this pressure compensation mode is selected, a considerable gas concentration measurement error resulting from a non- realistic pressure value can take place.



If External compensation is selected, then the minimum (4 mA) and maximum (20 mA) analog output signals from the pressure transducer must be mapped to the corresponding Analog input of the TDL. Key in the minimum and maximum values of the pressure in the following units:


- hPa – mmHg – mbar
- psi – kPa



In general, METTLER TOLEDO recommends the use of absolute pressure transducers for more accurate signal compensation over a broad pressure range.

If, however, small pressure variations around atmospheric pressure are to be expected, relative pressure sensors will produce better results; but the variations of the underlying barometric pressure will be ignored.

For relative pressure sensors, the minimum and maximum values must be mapped so that the TDL can interpret the analog pressure signal as "absolute", i.e. a fixed barometric pressure of 1013 mbar (for example) has to be added to the mapped values.



If Fixed compensation is selected, the fixed pressure value with which the measurement signal will be calculated has to be keyed in manually. For the fixed pressure, the following units can be used:

- hPa – mmHg – mbar
- psi – kPa

```

B    20.9    %V O2
B    20.9    %Trm
Pressure=1013. mbar  ↑

```

```

B    20.9    %V O2
B    20.9    %Trm
Temperature=External  ↑

```

```

B    20.9    %V O2
B    20.9    %Trm
Ain  4mA = 0.000 °C
Ain  20mA = 250_0 °C  ↑

```

```

B    20.9    %V O2
B    20.9    %Trm
Temperature=Fixed     ↑

```

```

B    20.9    %V O2
B    20.9    %Trm
Temperature=320.0 °C  ↑

```

```

B    20.9    %V O2
B    20.9    %Trm
Pathlength=00200 mm  ↑

```

If External compensation is selected, then the minimum (4 mA) and maximum (20 mA) analog output signals from the temperature transducer must be mapped to the corresponding Analog input of the TDL. Key in the minimum and maximum values of the temperature in °C.

If Fixed compensation is selected, the fixed temperature value with which the measurement signal will be calculated has to be keyed in manually. For the fixed temperature, only °C can be used.

Last, select the initial optical path length corresponding to the probe length installed:


- 290 mm probe: 200 mm
- 390 mm probe: 400 mm
- 590 mm probe: 800 mm

This initial value is valid when instrument purging on the instrument and on the process side is running. Depending on the process conditions and after the optimum of the process purging flow has been found (see next chapter), this value may have to be slightly adapted.

8.2.3.13 Setting the correct process side purging

The flow rate of the purging will affect the effective path length and consequently the measurement value.

Therefore the following procedure should be used. Start with a very high flow rate and gradually decrease it. The measurement value will then start at a low value and increase with decreasing purge flow. At some point it will level out and stay constant for a while and then again start increasing. Choose a purge flow in the middle of the constant region.



Optimizing the purge flow

On the x-axis there is purge flow and on the y-axis there is the instrument concentration reading.

- 1 Concentration reading with high purge flow. The path length is now shorter than the effective path length since the purge tubes is completely filled with purging gas and some of the purging gas is flowing into the measurement path.
- 2 Concentration reading with optimized purge flow. The path length is now equal to the effective path length since the purge tubes are completely filled with purge gas. See the illustration below.
- 3 Concentration reading with no purge flow. The path length is now equal to the nominal path length since the probe is completely filled with process gas.
- 4 The optimized purge flow.




WARNING: Always start purging at maximum flow before starting the process.



WARNING: Purging must always be switched on in order to avoid dust deposition onto the optical surfaces.

8.2.4 Set averaging

Enter Configuration Mode as described in section 8.1 "Enter Configuration mode" and select the menu Measurement (see section 8.2 "Configuration/Measurement").




Selected the menu "Set Averaging" by using the ▲ or ▼ key. Press [ENTER]

The averaging method (noise filter) for each measurement line can now be selected. The options are Special (Default), None, Low, Medium and High:




None = no averaging or filtering
 Low = equivalent to a 3 point moving average
 Medium = equivalent to a 6 point moving average
 High = equivalent to a 10 point moving average
 Special = averaging depending on signal change (normally High averaging but Low averaging for large changes in input signal)



Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.3 Analog outputs


(PATH: Menu/Configure/Analog Outputs)



Enter Configuration mode as described in Section 8.1. "Enter Configuration Mode" and navigate to the menu "Analog Outputs" by using the ▲ or ▼ key.

Press the [ENTER] key to select this menu, which lets you configure the 4 analog outputs.

Once analog outputs have been selected, use the ◀ and ▶ buttons to navigate between configurable parameters. Once a parameter is selected, its setting can be selected per the following table:



When an alarm value is selected (see chapter 8.5.1 "Alarm";
 PATH: Menu/Configure/Alarm/Clean/Setup Alarm),
 the analog output will go to this value if any of these alarm conditions occurs.

Parameter	Selectable Values
Aout:	1, 2, 3 or 4 (default is 1)
Measurement:	a, b, c, d or blank (none) (default is a)
Alarm Value:	3.6 mA, 22.0 mA or Off (default is off)



NOTE: Beside the measurement values pH, O₂, T, etc. also the ISM values DLI, TTM and ACT can be linked to the analog outputs if they have been assigned to the corresponding line in the display (see chapter 8.2.1.2 "ISM sensor")

The Aout type can be Normal, Bi-Linear, Auto-Range or Logarithmic. The range can be 4–20 mA or 0–20 mA. Normal provides linear scaling between the minimum and maximum scaling limits and is the default setting. Bi-Linear will also prompt for a scaling value for the mid-point of the signal and allows two different linear segments between the minimum and maximum scaling limits.

```

A  0.28  μS/cm
A  24.97  °C
Aout1 Type= Normal
Aout1 Range = 4-20  ▲

```

Enter the minimum and maximum value of Aout.

```

0.28  μS/cm
24.97  °C
Aout1 min= 0.000 μS/cm
Aout1 max= 10.00 μS/cm ▲

```

If Auto-Range was selected then Aout max1 can be configured. Aout max1 is the maximum value for the first range on auto-range. The maximum value for the second range on auto-range was set in the previous menu. If Logarithmic Range was selected, it will also prompt for the number of decades as "Aout1 # of Decades =2".

```

A  0.28  μS/cm
A  24.97  °C
Aout1 max1=20.00 MΩ-cm ▲

```

The value for the Hold mode can be configured to hold the last value or can be set to a fixed value.

```

A  0.28  μS/cm
A  24.97  °C
Aout1 hold mode
Last Value  ▲

```

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

```

A  0.28  μS/cm
A  24.97  °C
Save Change Yes & Exit
Press ENTER to Exit  ▲

```

8.4 Set points

(PATH: Menu/Configure/Set Points)

Enter Configuration mode as described in Section 8.1. "Enter Configuration Mode" and navigate to the menu "Set Points" by using the ▲ or ▼ key.

Press the [ENTER] key to select this menu.

```

A  0.28  μS/cm
A  25.00  °C
Configure
Set Points  ▲

```

Up to 6 setpoints can be configured on any of the measurements (a thru d). The possible Set-point types are Off, High, Low, Outside and Between.

An "Outside" setpoint will cause an alarm condition whenever the measurement goes above its high limit or below its low limit. A "Between" setpoint will cause an alarm condition to occur whenever the measurement is between its high and low limits.

Enter the desired value(s) for the setpoint and press [ENTER]




NOTE: Beside the measurement values pH, O₂, T, etc. also the ISM values DLI, TTM and ACT can be linked to the set points if they have been assigned to the corresponding line in the display (see chapter 8.2.1.2 "ISM sensor").



Depending on the defined setpoint type, this screen provides the option to adjust the values for the setpoint(s).


Press [ENTER] to proceed.



Out of Range

Once configured, the selected relay will be activated if a sensor Out of Range condition is detected on the assigned input channel. Select the setpoint and "Yes" or "No". Select the desired relay that will activate when the setpoint alarm condition is reached.

Press [ENTER]



Delay

Enter the delay time in seconds. A time delay requires the setpoint to be exceeded continuously for the specified length of time before activating the relay. If the condition disappears before the delay period is over, the relay will not be activated.

Hysteresis

Enter value for the hysteresis. A hysteresis value requires the measurement to return within the setpoint value by a specified hysteresis before the relay is deactivated.

For a high setpoint, the measurement must decrease more than the indicated hysteresis below the setpoint value before the relay is deactivated. With a low setpoint, the measurement must rise at least this hysteresis above the setpoint value before the relay is deactivated. For example, with a high setpoint of 100 and hysteresis of 10, when this value is exceeded, the measurement must fall below 90 before the relay is deactivated.

Press [ENTER]



Hold

Enter the Relay Hold Status of "Last", "On" or "Off". This is the state the relay will go to during a hold status.

State


Relay contacts are in normal state until the associated setpoint is exceeded, then the relay is activated and the contact states change.

Select "Inverted" to reverse the normal operating state of the relay (i.e. normally open contacts are in a closed state, and normally closed contacts are in an open state, until the setpoint is exceeded). "Inverted" relay operation is functional when power is applied to the M400 transmitter. Relay No 2 always operates inverted. All other relays can be configured.

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.5 Alarm/Clean

(PATH: Menu/Configure/Alarm/Clean)



Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".

This menu allows the configuration of alarm and clean functionality.

8.5.1 Alarm




To select "Setup Alarm", press the ▲ or ▼ key so that "Alarm" is flashing.

Using the ◀ and ▶ buttons, navigate to "Use Relay #". Using the ▲ or ▼ keys, select a relay to be used for the alarm and press [ENTER].

One of the following events may be alarmed:

1. Power failure
2. Software failure
3. Rg diagnostics – pH glass membrane resistance (only for pH and dissolved carbon dioxide sensors; pH/pNa Rg diagnostics detect both pH and pNa membrane glasses)
4. Rr diagnostics – pH reference resistance (only for pH sensors; except pH/pNa)
5. Dry Cond sensor(only for cond 2-e/4-e sensor)
6. Cond cell shorted (only for cond 2-e / 4-e sensors)
7. Channel B disconnected (only for ISM sensors)
8. Shaft error (only for optical sensors)
9. Signal error (only for optical sensors)
10. Hardware error (only for optical sensors)
11. Cond Ind Defect (only for inductive conductivity sensors)
12. Cell deviation (only for ISM cond sensors)
13. Electrolyte low (only for ISM amperometric oxygen sensors)
14. Software error(only for CO₂ Hi (InPro 5500 i) sensor)
15. CO₂ out of range (only for CO₂ Hi (InPro 5500 i) sensor)
16. Temp out of range (only for CO₂ Hi (InPro 5500 i) sensor)
17. CO₂ not reliable (only for CO₂ Hi (InPro 5500 i) sensor)
18. Change membrane (only for CO₂ Hi (InPro 5500 i) sensor)



If any of these criteria are set to Yes and the conditions for an alarm are given, the flashing symbol \triangle will be shown in the display, an alarm message will be recorded (see also chapter Messages; PATH: Info/Messages) and the selected relay will be activated. Furthermore an alarm can be indicated by the current output if this has been parameterized (see chapter 8.3 "Analog outputs"; PATH: Menu/Configure/Analog Outputs)

The conditions for alarms are:

1. There is a power failure or power cycling
2. The software watchdog performs a reset
3. Rg is out of tolerance – for example, broken measuring electrode (only for pH and dissolved carbon dioxide sensors; pH/pNa Rg diagnostics detect both pH and pNa membrane glasses)
4. Rr is out of tolerance – for example, coated or depleted reference electrode (only for pH sensors; except pH/pNa)
5. If the conductivity sensor is on air (for example in an empty pipe) (only for resistive conductivity sensors)
6. If the conductivity sensor has a short cut (only for resistive conductivity sensors)
7. If no sensor is connected on channel B (only for ISM sensors)
8. If the temperature is out of range, stray light is too high (e.g. because a glass fiber is broken) or the shaft has been removed (see also chapter 11.1 "Diagnostics"; PATH: Menu/Service/Diagnostics/O₂ optical) (only for optical sensors)
9. If the signal or the temperature value is out of range (see also chapter 11.1 "Diagnostics"; PATH: Menu/Service/Diagnostics/O₂ optical) (only for optical sensors)
10. If an hardware error has been detected (see also chapter 11.1 "Diagnostics"; PATH: Menu/Service/Diagnostics/O₂ optical). (Only for optical sensors)
11. If the sensors is faulty e. g. through broken wires or a short cut (only for inductive conductivity sensors)
12. Cell constant (multiplier) is out of tolerance, i.e. has changed too much compared to the value thru the factory calibration (only for ISM conductivity sensors)
13. Electrolyte in the membrane body reaches such a low level that the connection between cathode and reference is disturbed, an immediate action must be taken e.g. exchange and filling the electrolyte.
14. Software error(only for CO₂ Hi (InPro 5500 i) sensor)
15. CO₂ out of range (only for CO₂ Hi (InPro 5500 i) sensor)
16. Temp out of range (only for CO₂ Hi (InPro 5500 i) sensor)
17. CO₂ not reliable (only for CO₂ Hi (InPro 5500 i) sensor)
18. Change membrane broken(only for CO₂ Hi (InPro 5500 i) sensor)

For 1 and 2 the alarm indicator will be turned off when the alarm message is cleared. It will reappear if the power is constantly cycling or if the watchdog is repeatedly resetting the system.

Only for pH sensors

For 3 and 4 the alarm indicator will go off if the message is cleared and the sensor has been replaced or repaired so that the Rg and Rr values are within specification. If the Rg or Rr message is cleared and Rg or Rr is still out of tolerance then the alarm will stay on and the message will reappear. The Rg and Rr alarm can be turned off by going into this menu and setting Rg diagnostics and/or Rr diagnostics to No. The message can then be cleared and the alarm indicator will be off even though Rg or Rr is out of tolerance.

Only for CO₂ Hi (InPro 5500 i) sensor – Resetting CO₂ measurement

Depending on the Alarm (eg. CO₂ not reliable) the thermal conductivity chip is shut down for self-protection purposes. After clearing the Alarm the Sensor's measurement needs to be reset by going to the system menu and restarting the CO₂ Hi (InPro 5500 i) measurement.

(PATH: Menu/System/Reset/Reset CO₂-Meas)

A Temp. out of range Alarm will stop the measurement eg. cut of the TC-sensor for safety purposes. As soon as the temperature cools down to operational levels the CO₂ Hi measurement

start again working. This is the case if SIP/CIP is in progress. The Sensor shuts down for self-protection reasons.


This is only visible at the transmitter if the according Alarms are activated.

Each alarm relay can be configured in either a Normal or Inverted state. In addition, a Delay for the activation can be set. For more information, refer to Section 8.4 "Setpoints".

If power failure is turned on, only inverted state is possible and cannot be changed.

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.

Note: There are additional alarms, which will be indicated in the display. See therefore in chapter 17 "Troubleshooting" the different warning- and alarm lists.



```

A 0.28 µS/cm
A 25.00 °C
Relay State = Inverted
R2 Delay = 001 sec ▲

```

8.5.2 Clean

Configure the relay to be used for the cleaning cycle.

The default value is relay 1.

```

A 0.28 µS/cm
A 25.00 °C
Setup Clean
Use Relay # 1 ▲

```

The cleaning interval can be set from 0.000 to 999.9 hours. Setting it to 0 turns the clean cycle off. The cleaning time can be 0 to 9999 seconds and must be smaller than the cleaning interval.

Select the desired Relay state: Normal or Inverted.

```

A 0.28 µS/cm
A 25.00 °C
CleanInterval= 0.000 hrs
Clean Time = 0000 sec ▲

```

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

```

A 0.28 µS/cm
A 25.00 °C
Relay State = Normal ▲


```

8.6 ISM set up (available for pH and oxygen ISM sensors)

(PATH: Menu/Configure/ISM Setup)


Enter Configuration mode as described in Section 8.1. "Enter Configuration Mode" and navigate to the menu "ISM set up" by using the ▲ or ▼ key. Press [ENTER]

8.6.1 Sensor monitoring



Select the menu "Sensor Monitoring" by pressing [ENTER].

The sensor monitoring options can be turned on or off and every alarm can be assigned to a certain output relays. The following options are possible:



Lifetime indicator: The dynamic lifetime indication allows an estimation, when the pH electrode or the inner body of an amperometric oxygen sensors or the OptoCap of an optical oxygen sensor is at the end of his lifetime, based on the actual stress he is exposed to. The sensor permanently takes the averaged stress of the past days into consideration and is able to increase/decrease the lifetime accordingly.

Lifetime Indicator	YES/NO		
Alarm	YES/NO	R#	choose relay

The following parameters affect the lifetime indicator:

Dynamic parameters:	Static parameters:
– Temperature	– Calibration history
– pH or oxygen value	– Zero and Slope
– Glass impedance (only pH)	– Phase 0 and phase 100 (only optical DO)
– Reference impedance (only pH)	– Illumination time (only optical DO)
	– CIP/SIP/Autoclaving cycles

The sensor keeps the information stored in the built in electronics and can be retrieved via a transmitter or the iSense asset management suite.


The alarm will be reset if the Lifetime Indicator is not 0 days anymore (e.g. after connecting a new sensor or changing on the measurement conditions).

For amperometric oxygen sensors, the lifetime indicator is related to the inner-body of the sensor. After exchanging the inner-body, reset the lifetime indicator as described in chapter 8.6.5 "Reset ISM counter/timer".

For optical DO sensors the lifetime indicator is related to the OptoCap. After exchanging the OptoCap, reset the lifetime indicator as described in chapter 8.6.5 "Reset ISM counter / timer"

If the Lifetime Indicator is turned on, in the measuring mode the value will be automatically shown in the display on line 3.

Press [ENTER]




Time to Maintenance (not for optical sensors): This timer estimates when the next cleaning cycle should be performed to keep the best possible measurement performance. The timer is influenced by significant changes on the DLI parameters.

Time to Maintenance	YES/NO
Alarm	R# choose relay

The time to maintenance can be reset to the initial value by the menu "Reset ISM Counter Timer" (see chapter 8.6.5 "Reset ISM counter/timer"). For amperometric oxygen sensors, the time to maintenance indicates a maintenance cycle for the membrane and electrolyte.

Press [ENTER]




Activation of the **Adaptive Cal Timer**: This timer estimates when the next calibration should be performed to keep the best possible measurement performance. The timer is influenced by significant changes on the DLI parameters.

Adaptive Cal Timer	YES/NO
Alarm	R# choose relay

The Adaptive Calibration Timer will be reset to his initial value after a successful calibration. After a successful calibration will also be the alarm reset. If the Adaptive Cal Timer is turned on, the value will be automatically shown in the display on line 4.

Press [ENTER]




The initial value for Time to Maintenance as well as the Adaptive Calibration Timer can be modified according to the application experience and loaded down to the sensor.




NOTE: By connecting a sensor, the values for Time to Maintenance and/or Adaptive Calibration Timer are read out by the sensor.

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, selecting Yes will save changes made.

8.6.2 CIP Cycle Limit



Navigate to the menu "CIP Cycle Limit" by using the ▲ and ▼ keys and press [ENTER].



The CIP cycle limit counts the number of CIP cycles. If the limit (user defined) is reached, an alarm can be indicated and set to a certain output relays. The following options are possible:

CIP Max 000	Temp 055
Alarm YES/NO	R# choose relay

If the Max setting is on 000, the counter functionality is turned off. The alarm will be reset after exchanging the sensor. For oxygen sensors, the counter can be reset (see chapter 8.6.5 "Reset ISM counter/timer").


CIP characteristics: CIP Cycles will be automatically recognized by the sensor. Since CIP cycles will vary in intensity (duration and temperature) for each application the algorithm of the counter recognizes an increase of the measurement temperature above a adjustable limit (parameter **Temp** in °C). If the temperature does not decrease below the defined limit within the next 5 minutes after the temperature was reached, the counter in question will be incremented by one and also locked for the next two hours. In the case the CIP would last longer than two hours the counter would be incremented by one once more.

Pressing the [ENTER] key will bring up the Save Changes dialog. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.




NOTE: In case of an optical oxygen sensor, the value for CIP Max will also be written to the sensor. The transmitter M400 uploads the value CIP Max from an optical oxygen sensor after the connection.

8.6.3 SIP Cycle Limit



Navigate to the menu "SIP Cycle Limit" by using the ▲ and ▼ keys and press [ENTER].



The SIP cycle limit counts the number of SIP cycles. If the limit (user defined) is reached, an alarm can be indicated and set to a certain output relays. The following options are possible:

SIP Max 000	Temp 115
Alarm YES/NO	R# choose relay

If the Max setting is on 000, the counter functionality is turned off. The alarm will be reset after exchanging the sensor. For oxygen sensors, the counter can be reset (see chapter 8.6.5 "Reset ISM counter/timer").

SIP characteristics: SIP Cycles will be automatically recognized by the sensor. Since SIP cycles will vary in intensity (duration and temperature) for each application the algorithm of the counter recognizes an increase of the measurement temperature above a adjustable limit (parameter **Temp** in °C). If the temperature does not decrease below the defined limit within the next 5 minutes after the first temperature was reached, the counter in question will be incremented by one

and also locked for the next two hours. In the case the SIP would last longer than two hours the counter would be incremented by one once more.

Pressing the [ENTER] key will bring up the Save Changes dialog. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.





NOTE: In case of an optical oxygen sensor, the value for SIP Max will also be written to the sensor. The transmitter M400 uploads the value SIP Max from an optical oxygen sensor after plugging in.

8.6.4 Autoclaving Cycle Limit



NOTE: The transmitter recognizes the connected ISM sensor and offers this menu only if an autoclavable sensor is connected.

Navigate to the menu "AutoClave Cycle Limit" by using the ▲ and ▼ keys and press [ENTER].



The Autoclaving Cycle Limit counts the number of autoclaving cycles. If the limit (user defined) is reached, an alarm can be indicated and set to a certain output relays. The following options are possible:

Autoclave Max 000			
Alarm	YES/NO	R#	choose relay

If the Max setting is on 000, the counter functionality is turned off. The alarm will be reset after exchanging the sensor. For oxygen sensors, the counter can also be reset manually (see chapter 8.6.5 "Reset ISM counter/timer").

Autoclave characteristics: Since during the autoclaving cycle the sensor is not connected to the transmitter, you will be asked after every sensor connection, whether the sensor was autoclaved or not. According to your selection, the counter will be incremented or not.

Pressing the [ENTER] key will bring up the Save Changes dialog. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.



NOTE: In case of an optical oxygen sensor, the value for AutoClave Max will be written to the sensor. The transmitter M400 uploads the value AutoClave Max from an optical oxygen sensor after plugging in.

8.6.5 Reset ISM counter/timer

This menu allows resetting counter and timer functions which cannot be reseted automatically. The adaptive calibration timer will be reseted after a successful adjustment or calibration.

```

B  71.5 %sat
B  25.0 °C

ISM Setup
Reset ISM Counter/Timer↑
  
```

Navigate to the menu "Reset ISM Counter/Timer" by using the ▲ and ▼ keys and press [ENTER].

```

B  71.5 %sat
B  25.0 °C

Reset Time to Maint No ↑
  
```

If an pH sensor or amperometric oxygen sensor is connected, the menu for resetting the Time To Maintenance is displayed. Time To Maintenance needs to be reset after the following operations.

pH sensors: manual maintenance cycle on the sensor.

oxygen sensor: manual maintenance cycle on the sensor or exchanging of the inner-body or membrane of the sensor

CO₂ Hi (InPro 5500 i): exchanging of the MembraCap.

[Press ENTER]

```

B  71.5 %sat
B  25.0 °C

Reset CIP No
Reset SIP No ↑
  
```

If an oxygen sensor is connected, the menu for resetting the CIP and SIP counter is displayed. These counters should be reset after the following operations.

optical sensor: exchanging of the OptoCap

amperometric sensor: exchanging of the inner-body of the sensor.

[Press ENTER]

8.6.6 DLI Stress Adjustment (only for pH sensor)

The menu allows adapt the DLI speed by accelerating or by slowing down the calculations according to the application.

There are the following options. Default option is "Medium".

Low: applications with relatively low reliability requirements

Medium: usual DLI speed, usual reliability requirements

High: Applications with high reliability requirements

```

B  7.0 hPa
B  25.0 °C

DLI Stress Adjustment
Process Stress Medium ↑
  
```




Note: Only pH sensor with FW more than 7.00.

8.7 Display

(PATH: Menu/Configure/Display)

Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".

This menu allows for the configuration of the values to be displayed and also the configuration of the display itself.




8.7.1 Measurement


The display has 4 lines. Line 1 on top and Line 4 on the bottom.

Select the values (Measurement a, b, c or d) to be displayed on each line of the display.

The selection of the values for a, b, c, d needs to be done under Configuration/measurement/Channel Setup.



Select the "Error Display" mode. If this is set to "On" when an alarm or warning has occurred, the message "Failure – Press ENTER" will be displayed on Line 4 when an alarm occurs in the normal measurement mode.




Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.



8.7.2 Resolution


This menu allows the setting of the resolution of each displayed value.

The accuracy of the measurement is not effected by this setting.




Possible settings are 1, 0.1, 0.01, 0.001 or Auto.

Pressing the [ENTER] key will bring up the Save Changes dialog.



8.7.3 Backlight




This Menu allows the setting of the back light options of the display.



Possible settings are On, On 50% or Auto Off 50%. If Auto Off 50% is selected then the backlight will go to 50% after 4 minutes with no keypad activity. The backlight will automatically come back on if a key is pressed.


Pressing the [ENTER] key will bring up the Save Changes dialog.

8.7.4 Name



This menu allows for the configuration of an alpha-numeric name which is displayed in the first 9 characters on lines 3 and 4 of the display. The default is nothing (blank).

If a name is entered on line 3 and/or 4 a measurement can be still displayed on the same line.




Use the ◀ and ▶ keys to navigate between digits to be altered. Using the ▲ and ▼ keys to change the character to be displayed. Once all digits of both display channels have been entered, press [ENTER] to bring up the Save Changes dialog.



The resulting display in the measurement mode appears on lines 3 and 4 ahead of the measurements.

8.7.5 ISM sensor monitoring (available when ISM sensor connected)




The sensor monitoring allows you to display the sensor monitoring details on line 3 and 4 in the display. The following options are possible:

Line 3 Off/Time Indicator/Time to Maint/Adapt Cal Timer

Line 4 Off/Time Indicator/Time to Maint/Adapt Cal Timer


8.8 Hold analog outputs

(PATH: Menu/Configure/Hold Outputs)



Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".

The **"Hold outputs"** function applies during the calibration process. If set "Hold outputs" to Yes, during calibration process the analog output, the output relay and USB output will be at hold state. The hold state depends on the setting. For the possible hold settings, see the list below. The following options are possible:



Hold Outputs? Yes/No

The **"DigitalIn"** function applies all the time. As soon as a signal is active on the digital input the transmitter goes to hold mode and the values on the analog output, the output relays and the USB output will be at hold state.

DigitalIn1 / 2 State = Off/Low/High




NOTE: DigitalIn1 is to hold channel A (conventional sensor)
DigitalIn2 is to hold channel B (ISM sensor)

Possible Hold states:

Output relays:	On/Off	(Configuration/Set point)
Analog Output:	Last/Fixed	(Configuration/Analog output)
USB:	Last/Off	(System/USB)
PID relay	Last/Off	(PID setup/Mode)
PID analog	Last/Off	(PID setup/Mode)

9 System


(PATH: Menu/System)




While in measurement mode press the ◀ key. Press the ▼ or ▲ key to navigate to “System” – Menu and press [ENTER].

9.1 Set Language

(PATH: Menu/System/Set Language)



This menu allows the configuration of the display language.




The following selections are possible:
English, French, German, Italian, Spanish, Portuguese, Russian or Japanese (Katakana).

Pressing the [ENTER] key will bring up the Save Changes dialog.

9.2 USB

(PATH: Menu/System/USB)



This menu allows configuration of the USB hold function.


USB hold may be set to either Off or Last Values. An external host device may poll the M400 for data. If the USB hold is set to Off, current values are returned. If the USB hold is set to Last Values, the values present at the time the hold condition was established are returned.




Press [ENTER] to bring up the Save Changes dialog.

9.3 Passwords

(PATH: Menu/System/Passwords)




This menu allows for the configuration of operator and administrator passwords, as well as setting up a list of allowed menus for the operator. The administrator has rights to access all menus. All default passwords for new transmitters are "00000".




The passwords menu is protected: Enter the administrator password to enter the menu.

9.3.1 Changing passwords




See Section 9.3 on how to enter the passwords menu. Select Change Administrator or Change Operator and set the new password.




Press the [ENTER] key and confirm the new password. Press [ENTER] again to bring up the Save Changed dialog.

9.3.2 Configuring menu access for operator



See 9.3 on how to enter the passwords Menu. Select Configure Operator to configure the access list for the operator. It is possible to assign/deny rights to the following menus: Cal Key, Quick Setup, Configuration, System, PID Setup and Service.



Choose either Yes or No to give/deny access to the above menus and press [ENTER] to advance to the next items. Pressing the [ENTER] key after configuring all menus will bring up the Save Changes dialog. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.

9.4 Set/Clear lockout

(PATH: Menu/System/Set/Clear Lockout)

```

A  0.28  μS/cm
A  25.00  °C
System
Set/Clear Lockout  ▲

```

This menu enables/disables the lockout functionality of the transmitter. The user will be asked for a password before being allowed into any menus if the lockout functionality is enabled.

```

A  0.28  μS/cm
A  25.00  °C
Password = 00000
Enable Lockout = Yes  ▲

```

The lockout-menu is protected: Enter the administrator or operator password and select YES to enable or NO to disable the lockout functionality. Pressing the [ENTER] key after the selection will bring up the Save Changes dialog. Selecting No will discard the entered value, selecting Yes will make the entered value the current one.

9.5 Reset

(PATH: Menu/System/Reset)

```

A  0.28  μS/cm
A  25.00  °C
System
Reset  ▲

```

This menu allows access to the following options:

Reset System, Reset Meter Cal, Reset Analog Cal.

9.5.1 Reset system

```

A  0.28  μS/cm
A  25.00  °C
Reset System  ? Yes
Press ENTER to Continue▲

```

This menu allows the reset of the meter to the factory default settings (setpoints off, analog outputs off, etc.). The meter calibration and the analog output calibration are not affected.

```

A  0.28  μS/cm
A  25.00  °C
Reset System
Are you sure? Yes  ▲

```

Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the measurement mode with no changes. Selecting Yes will reset the meter.

9.5.2 Reset meter calibration

```

A  0.28  μS/cm
A  25.00  °C
Reset Meter Cal ? Yes
Press ENTER to Continue▲

```

This menu allows the reset of the meter's calibration factors to the last factory calibration values.

```

A  0.28  μS/cm
A  25.00  °C
Reset Meter Calibration
Are you sure? Yes  ▲

```

Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the measurement mode with no changes. Selecting Yes will reset the meter calibration factors.

9.5.3 Reset analog calibration

```

A  0.28  μS/cm
A  25.00  °C
Reset Analog Cal? Yes
Press ENTER to Continue▲

```

This menu allows reset of the analog output calibration factors to the last factory calibration values.

```

A  0.28  μS/cm
A  25.00  °C
Reset Analog Calibration
Are you sure? Yes  ▲

```

Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the measurement mode with no changes. Selecting Yes will reset the analog output calibration.

9.5.4 Reset sensor calibration (for optical sensors only)

```

B  23.0  PPbO2
B  25.0  °C
Reset SensorCal ? Yes
Press ENTER to Continue↑

```

If an optical oxygen sensor is connected to the transmitter, this menu is available. The menu allows the reset of the calibration data of the sensors to the factory settings.

```

B  23.0  PPbO2
B  25.0  °C
Reset to factory
Are you sure? Yes  ↑

```

Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the Measurement mode with no changes. Selecting Yes will reset the calibration data of the sensor to factory settings.



NOTE: Thru a reset of the calibration data the Adaptive Calibration Timer (see chapter 8.6.1 "Sensor monitoring") will set to 0.



NOTE: To ensure best measuring results, a new calibration of the sensor is recommended after a reset of the calibration data to factory settings. Depending on the application resp. sensor, the calibration should be performed as a one point calibration or two point calibration (see chapter 7.5 "Calibration of optical oxygen sensors")

9.6 Set date & time

```

B  7.00  pH
B  25.0  °C
System
Set Date&Time  ↑

```


Please enter the actual date and time. The following options are possible. This function is automatically activated at every power-up.

Date (YY-MM-DD):

Time (HH:MM:SS):

10 PID setup

(PATH: Menu/PID Setup)



PID control is proportional, integral and derivative control action that can provide smooth regulation of a process. Before configuring the transmitter, the following process characteristics must be identified.

Identify the **control direction** of the process

– **Conductivity:**

Dilution – direct acting where increasing measurement produces increasing control output such as controlling the feed of low conductivity diluting water to rinse tanks, cooling towers or boilers

Concentrating – reverse acting where increasing measurement produces decreasing control output, such as controlling chemical feed to attain a desired concentration

– **Dissolved Oxygen:**

Deaeration – direct acting where increasing DO concentration produces increasing control output such as controlling the feed of a reducing agent to remove oxygen from boiler feedwater

Aeration – reverse acting where increasing DO concentration produces decreasing control output, such as controlling an aerator blower speed to maintain a desired DO concentration in fermentation or wastewater treatment

– **pH/ORP:**

Acid feed only – direct acting where increasing pH produces increasing control output, also for ORP reducing reagent feed

Base feed only – reverse acting where increasing pH produces decreasing control output, also for ORP oxidizing reagent feed

Both acid and base feed – direct and reverse acting

Identify the **control output type** based on the control device to be used:

Pulse frequency – used with pulse input metering pump


Pulse length – used with solenoid valve

Analog – used with current input device such as electric drive unit, analog input metering pump or current-to-pneumatic (I/P) converter for pneumatic control valve


Default control settings provide linear control, which is appropriate for conductivity, dissolved oxygen. Therefore, when configuring PID for these parameters (or simple pH control) ignore settings of deadband and corner points in the tuning parameter section below. The non-linear control settings are used for more difficult pH/ORP control situations.

If desired, identify the non-linearity of the pH/ORP process. Improved control can be obtained if the non-linearity is accommodated with an opposing non-linearity in the controller. A titration curve (graph of pH or ORP vs. reagent volume) made on a process sample provides the best information. There is often a very high process gain or sensitivity near the setpoint and decreasing gain further away from the setpoint. To counteract this, the instrument allows for adjustable non-linear control with settings of a deadband around the setpoint, corner points further out and proportional limits at the ends of control as shown in the figure below.

Determine the appropriate settings for each of these control parameters based on the shape of the pH process titration curve.




10.1 Enter PID setup



While in measurement mode press the ◀ key. Press the ▲ or ▼ key to navigate to the PID Set-up-menu and press [ENTER].

10.2 PID auto/manual

(PATH: MENU/PID Setup/PID A/M)




This menu allows selection of automatic or manual operation. Select Auto or Manual operation. Pressing the [ENTER] key will bring up the Save Changes dialog.

10.3 Mode

(PATH: MENU/PID Setup/Mode)

This menu contains the selection of control modes using relays or analog outputs.

Press [ENTER].



10.3.1 PID mode


This menu assigns a relay or analog output for PID control action as well as details of their operation. Based on the control device being used, select one of the following three paragraphs for use with solenoid valve, pulse input metering pump or analog control.

Pulse Length – If using a solenoid valve, select “Relays” and “PL”, pulse length. Choose the first relay position as #3 (recommended) and/or the second relay position as #4 (recommended) as well as the pulse length (PL) according to the table below. A longer pulse length will reduce wear on the solenoid valve. The % “on” time in the cycle is proportional to the control output.



NOTE: All relays from #1 to #6 can be used for the controlling function.

	1 st Relay Position (#3)	2 nd Relay Position (#4)	Pulse Length (PL)
Conductivity	Controlling concentrating reagent feed	Controlling dilution water	Short (PL) provides more uniform feed. Suggested start point = 30 sec.
pH/ORP	Feeding base	Feeding acid	Reagent addition cycle: short PL provides more uniform addition of reagent. Suggested start point = 10 sec.
Dissolved Oxygen	Reverse control action	Direct acting control action	Feed cycle time: short PL provides more uniform feed. Suggested start point = 30 sec.



Pulse Frequency – If using a pulse input metering pump, select “Relays” and “PF”, pulse frequency. Choose the first relay position as #3 and/or the second relay position as #4 according to the table below. Set the pulse frequency to the maximum frequency allowed for the particular pump being used, typically 60 to 100 pulses/minute. Control action will produce this frequency at 100% output.



NOTE: All relays from #1 to #6 can be used for the controlling function.

CAUTION: Setting the pulse frequency too high may cause the pump to overheat.

	1 st Relay Position = #3	2 nd Relay Position = #4	Pulse Frequency (PF)
Conductivity	Controlling concentrating chemical feed	Controlling dilution water	Max allowed for the pump used (typically 60–100 pulses/minute)
pH/ORP	Feeding base	Feeding acid	Max allowed for the pump used (typically 60–100 pulses/minute)
Dissolved Oxygen	Reverse control action	Direct acting control action	Max allowed for the pump used (typically 60–100 pulses/minute)

```

A 0.28      μS/cm
A 25.00     °C
PIDMode= Analogout #_ #_
Aout_ = 4-20 Aout_ = 4-20▲

```

Analog – If using analog control, change “Relays” to “Analogout” using up/down arrow keys. Choose the first Analogout position as #1 and/or the second Analogout position as #2 according to the table below. Select the analog output current range required by the control device, 4–20 or 0–20 mA. Press [ENTER].

	1 st Analogout Position = #1	2 nd Analogout Position = #2
Conductivity	Controlling concentrating chemical feed	Controlling dilution water
pH/ORP	Feeding base	Feeding acid
Dissolved Oxygen	Reverse control action	Direct acting control action

10.4 Tune parameters

(PATH: MENU/PID Setup/Tune Parameters)

```

A 0.28      μS/cm
A 25.00     °C
PID Setup
Tune Parameters ▲

```

This menu assigns control to a measurement and sets the setpoint, tuning parameters and non-linear functions of the controller through a series of screens.

10.4.1 PID assignment & tuning

```

A 0.28      μS/cm
A 25.00     °C
PID on _    Gain = 1.000
Tr=0.00 m   Td=0.00 m ▲

```

Assign the measurement, a, b, c, or d to be controlled after “PID on_”. Set the Gain (unitless), integral or reset time Tr (minutes) and rate or derivative time Td (minutes) needed for control. Press [ENTER]. Gain, reset and rate are later adjusted by trial and error based on process response. Always begin with Td at zero.

10.4.2 Setpoint & deadband

```

A  0.28      μS/cm
A  25.00      °C
SetPoint = 0.000 _
Dead Band= +/-0.000 _ ▲

```

Enter the desired setpoint value and the deadband around the setpoint, where no proportional control action will take place. Be sure to include the units multiplier μ or m for conductivity. Press [ENTER].

10.4.3 Proportional limits

```

A  0.28      μS/cm
A  25.00      °C
Prop Limit Low  0.000 _
Prop Limit High 0.000 _▲

```

Enter the low and high proportional limits – the range over which control action is required. Be sure to include the units multiplier μ or m for conductivity. Press [ENTER].

10.4.4 Corner points

```

A  0.28      μS/cm
A  25.00      °C
Corner Low 0.000_1.000
CornerHigh 0.000_-1.00▲

```

Enter the low and high corner points in conductivity, pH, dissolved oxygen units and the respective output values from -1 to +1, shown in the figure as -100 to +100%. Press [ENTER].

10.5 PID display

(PATH: Menu/PID Setup/PID Display Setup)

```

A  0.28      μS/cm
A  25.00      °C
PID Setup
PID Display Setup ▲

```

This screen enables display of PID control status in the normal measurement mode.

```

A  0.28      μS/cm
A  25.00      °C
PID Display Yes ▲

```

When PID Display is selected, the status (Man or Auto) and control output (%) will be displayed on the bottom line. If controlling pH, the reagent will also be displayed. In addition, for the display to be enabled, a measurement must be assigned under Tune Parameters and a relay or analog output must be assigned under Mode.

```



A  0.28      μS/cm
A  25.00      °C
B      7.00 pH
Man Ctrl Out 0.0%

```

In manual, the control output may be adjusted with the up and down arrow keys. (The "Info" key function is not available in manual.)

11 Service


(PATH: Menu/Service)



While in measurement mode press the ◀ key. Press the ▲ or ▼ key to navigate to the “Service” menu and press [ENTER]. The available system configuration options are detailed below.


11.1 Diagnostics

(PATH: Menu/Service/Diagnostics)



This menu is a valuable tool for troubleshooting and provides diagnostic functionality for the following items: Model/Software Revision, Digital Input, Display, Keypad, Memory, Set Relays, Read Relays, Set Analog Outputs, Read Analog Outputs.

11.1.1 Model/Software revision



Essential information for every Service call is the model and software revision number. This menu shows the part number, model and the serial number of the transmitter. By using the ▼ key it is possible to navigate forward through this menu and get additional information like the current version of firmware implemented on the transmitter: (Master V_XXXX and Comm V_XXXX); and – if an ISM sensor is connected – the version of the sensor firmware (Sensor FW V_XXX) and sensor hardware (Sensor HW XXXX).



Press [ENTER] to exit from this display.

11.1.2 Digital input

The digital input menu shows the state of the digital inputs. Press [ENTER] to exit from this display.

```

A  0.28      µS/cm
A  25.00      °C
Diagnostics
Digital Input      ▲

```

```

A  0.28      µS/cm
A  25.00      °C
Digital Input 1 = 0
Digital Input 2 = 0      ▲

```

11.1.3 Display

All pixels of the display will be lit for 15 seconds to allow troubleshooting of the display. After 15 seconds the transmitter will return to the normal measuring mode or press [ENTER] to exit sooner.

```

A  0.28      µS/cm
A  25.00      °C
Diagnostics
Display          ▲

```

11.1.4 Keypad

For keypad diagnostics, the display will indicate which key is pressed. Pressing [ENTER] will return the transmitter to the normal measuring mode.

```

A  0.28      µS/cm
A  25.00      °C
Diagnostics
Keypad          ▲

```

```

A  0.28      µS/cm
A  25.00      °C
Key press =(MENU )
Press ENTER to Continue

```

11.1.5 Memory

If Memory is selected then the transmitter will perform a RAM and ROM memory test. Test patterns will be written to and read from all RAM memory locations. The ROM checksum will be recalculated and compared to the value stored in the ROM.

```

A  0.28      µS/cm
A  25.00      °C
Diagnostics
Memory          ▲

```

```

A  0.28      µS/cm
A  25.00      °C
Memory Test Passed
Press ENTER to Continue

```

11.1.6 Set Relay

```

A  0.28  μS/cm
A  25.00  °C
Diagnostics
Set Relays  ▲

```

The Set Relays diagnostic menu allows to open or close each relay manually. To access relays 5 and 6, press [ENTER].

0 = open the relay
1 = close the relay

```

A  0.28  μS/cm
A  25.00  °C
Relay1 = 0 Relay2 = 0
Relay3 = 0 Relay4 = 0  ▲

```

Press [ENTER] to return to Measurement mode.

11.1.7 Read relays

```

A  0.28  μS/cm
A  25.00  °C
Diagnostics
Read Relays  ▲

```

The Read Relays diagnostic menu shows the state of each relay as defined below. To display relays 5 and 6, press [ENTER]. Press [ENTER] again to exit from this display.

0 = Normal
1 = Inverted.

```

A  0.28  μS/cm
A  25.00  °C
Relay1 = 0 Relay2 = 0
Relay3 = 0 Relay4 = 0

```

11.1.8 Set analog outputs

```

A  0.28  μS/cm
A  25.00  °C
Diagnostics
Set Analog Outputs  ▲

```

This menu enables the user to set all analog outputs to any mA value within the 0–22 mA range. Press [ENTER] to exit from this display.

```

A  0.28  μS/cm
A  25.00  °C
Analog out1 = 04.0 mA
Analog out2 = 04.0 mA  ▲

```

11.1.9 Read analog outputs

```

A  0.28  μS/cm
A  25.00  °C
Diagnostics
Read Analog Outputs  ▲

```

This menu shows the mA value of the analog outputs.

```

A  0.28    μS/cm
A  25.00    °C
Analog out1 = 20.5 mA
Analog out2 = 20.5 mA ▲

```

Press [ENTER] to exit from this display.

11.1.10 O₂ Optical

```

B  13.4    %AIR
B  25.3    °C
Diagnostics
O2 Optical  ↑

```

This menu shows the state and conditions regarding the optical O₂ sensor. By using the key ▲ or ▼ it is possible to navigate through this menu and get additional information. Press [ENTER] to exit from this display.

11.1.11 CO₂ Hi (InPro 5500 i)

```

B  0.0    hPa
B  25.0    °C
Diagnostics
CO2 Hi    ↑

```

This menu shows the state and conditions regarding the CO₂ Hi (InPro 5500 i) sensor. By using the key ▲ or ▼ it is possible to navigate through this menu and get additional information. Press [ENTER] to exit from this display.

11.1.12 TDL

```

B  0.0    ppm O2
B  25.0    °C
Diagnostics
O2-TDL    ↑

```

This menu shows the state and conditions regarding the TDL Hi sensor. By using the key ▲ or ▼ it is possible to navigate through this menu and get additional information. Press [ENTER] to exit from this display.

11.2 Calibrate

(PATH: Menu/Service/Calibrate)

```

A  0.28    μS/cm
A  25.00    °C
Service
Calibrate  ▲

```

Enter Service Menu as described in section 11 "Enter Service Menu", select Calibrate, and press [ENTER].

This menu has the options to calibrate the transmitter and the analog outputs and also allows the unlocking of calibration functionality.

11.2.1 Calibrate meter (only for channel A)


```

A  0.28    μS/cm
A  25.00    °C
Calibrate Meter
Channel A Resistance 1 ▲

```

The M400 transmitter is factory calibrated within specifications. It is not normally necessary to perform meter re-calibration unless extreme conditions cause an out of spec operation shown by Calibration Verification. Periodic verification/re-calibration may also be necessary to meet Q.A. requirements. Meter calibration can be selected as current (used for most dissolved oxygen, Voltage, Rg Diagnostic, Rr Diagnostic (used for pH), and temperature (used for all measurements).


11.2.1.1 Temperature




Temperature is performed as a three point calibration. The table above shows the resistance values of these three points.

Navigate to the Calibrate Meter screen and choose Temperature calibration for Channel A.

Press [ENTER] to begin temperature calibration process




The first text line will ask for the Point 1 temperature resistance value (this will correspond to temperature 1 value shown on the calibration module accessory). The second text line will show the measured resistance value. When the value stabilizes, press [ENTER] to perform calibration.




The transmitter screen will then prompt the user to enter the value for Point 2, and T2 will display the measured resistance value. When this value stabilizes, press [ENTER] to calibrate this range.

Repeat these steps for Point 3.




Press [ENTER] to bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display.




The transmitter will return to the measurement mode in approximately 5 seconds.

11.2.1.2 Current




Current calibration is performed as a two point calibration.

Navigate to the Calibrate Meter screen and select Channel A.



Enter the value for Point 1, in milliamps, of the current source connected to the input. The second display line will show the measured current. Press [ENTER] to begin the calibration process.



Enter the value for Point 2, in milliamps, of the current source connected to the input. The second display line shows the measured current.


```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
Save Calibration Yes
Press ENTER to Exit  ▲

```

Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.

11.2.1.3 Voltage

Voltage calibration is performed as a two point calibration.

Navigate to the Calibrate Meter screen and select Channel A and Voltage.

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
Calibrate Meter
Channel A Voltage  ▲

```

Enter the value for Point 1 in, volts, connected to the input. The second display line will show the measured voltage. Press [ENTER] to begin the calibration process.

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
A Point1 = -1.500 V
A      V = -0.000 V  ▲

```

Enter the value for Point 2, in volts, of the source connected to the input. The second display line shows the measured voltage.

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
A Point2 = 1.5000 V
A      V = 0.1231 V  ▲

```

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
Save Calibration Yes
Press ENTER to Exit  ▲

```

Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful Calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.

11.2.1.4 Rg diagnostic

Rg diagnostic is performed as a two point calibration. Navigate to the Calibrate Meter screen and select Channel A and Rg Diagnostic.

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
Calibrate Meter
Channel A Rg Diagnostic▲

```

Enter the value for Point 1 of the calibration according to the resistor connected across the pH glass electrode measuring input. Press [ENTER] to begin the calibration process.

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
A Point1 = 30.000 MΩ
A      Rg = 572.83 Ω  ▲

```

Enter the value for Point 2 of the calibration according to the resistor connected across the pH glass electrode measuring input.

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
A Point2 = 500.00 MΩ
A      Rg = 572.83 Ω  ▲

```

```

A  0.28       $\mu\text{S}/\text{cm}$ 
A  25.00     °C
Save Calibration Yes
Press ENTER to Exit  ▲

```

Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.

11.2.1.5 Rr diagnostic

A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 Calibrate Meter
 Channel A Rr Diagnostic▲

Rr diagnostic is performed as a two point calibration. Navigate to the Calibrate Meter screen and select Channel A and Rr Diagnostic.

A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 A Point1 = 30.000 K Ω
 A Rr = 29.448 K Ω ▲

Enter the value for Point 1 of the calibration according to the resistor connected across the pH reference measuring input. Press [ENTER] to begin the calibration process.

A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 A Point2 = 200.00 K Ω
 A Rr = 29.446 K Ω ▲

Enter the value for Point 2 of the calibration according to the resistor connected across the pH reference measuring input.

A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 Save Calibration Yes
 Press ENTER to Exit ▲

Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.

11.2.1.6 Calibrate analog output signals

A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 Calibrate Analog
 Analog Output 1 ▲

Select the Analog Output you wish to calibrate. Each analog output can be calibrated at 4 and 20 mA.

A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 Aout1 20mA Set 45000
 Press ENTER when Done ▲

Connect an accurate milliamp meter to the analog output terminals and then adjust the five digit number in the display until the milliamp meter reads 4.00 mA and repeat for 20.00 mA.


A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 Aout1 4mA Set 08800
 Press ENTER when Done ▲

As the five digit number is increased the output current increases and as the number is decreased the output current decreases. Thus coarse changes in the output current can be made by changing the thousands or hundreds digits and fine changes can be made by changing the tens or ones digits.


A 0.28 $\mu\text{S}/\text{cm}$
 A 25.00 $^{\circ}\text{C}$
 Save Calibration Yes
 Press ENTER to Exit ▲

Pressing the [ENTER] key after entering both values will bring up a confirmation screen. Selecting No will discard the entered values, selecting Yes will make the entered values the current ones.

11.2.2 Calibrate unlock



Select this Menu to configure the CAL Menu, see Section 7.



Selecting Yes means that meter and analog output calibration menus will be selectable under the CAL Menu. Selecting No means that only the sensor calibration is available under the CAL Menu. Press [ENTER] after the selection to display a confirmation screen.

11.3 Tech Service


(PATH: Menu/Tech Service)




Note: This menu is for Mettler Toledo service personnel use only.

12 Info

(PATH: Info)




* Only available in combination with ISM sensors




Pressing the ▼ key will display the Info menu with the options Messages, Calibration Data and Model/Software Revision.

12.1 Messages

(PATH: Info/Messages)



The most recent message is displayed. The up and down arrow keys allow scrolling through the last four messages that have occurred.



Clear Messages clears all the messages. Messages are added to the message list when the condition that generates the message first occurs. If all messages are cleared and a message condition still exists and started before the clear then it will not appear in the list. For this message to re-occur in the list the condition must go away and then reappear.


Press [ENTER] to exit from this display.

12.2 Calibration data

(PATH: Info/Calibration Data)



Selecting Calibration Data displays the calibration constants for each sensor.



P = calibration constants for the primary measurement
S = calibration constants for the secondary measurement

Press ▼ for ORP calibration data of ISM pH sensors.

Press [ENTER] to exit from this display.

12.3 Model/Software revision

(PATH: Info/Model/Software Revision)

```

A  0.28  μS/cm
A  25.00  °C
INFO
Model/Software Revision▲
  
```

Selecting Model/Software Revision will display the part number, model and the serial number of the transmitter.

By using the ▼ key it is possible to navigate forward through this menu and get additional information like the current version of firmware implemented on the transmitter (Master V_XXXX and Comm V_XXXX) and – if an ISM sensor is connected – the version of the sensor firmware (Sensor FW V_XXX) and sensor hardware (Sensor HW XXXX).

```

A  0.28  μS/cm
A  25.00  °C
PN xxxxxxxx Vx.xx
SN xxxxxxxx
  
```

The displayed information is important for any Service call. Press [ENTER] to exit from this display.

12.4 ISM sensor info (available when ISM sensor connected)

(PATH: Info/ISM Sensor Info)

```

B  7.00  pH
B  25.0  °C
INFO
ISM Sensor Info  ↑
  
```

After plugging in an ISM sensor it is possible by using the key ▲ or ▼ to navigate to the Menu "ISM Sensor Info".

Press [ENTER] to select the menu.

```

B  7.00  pH
B  25.0  °C
ChB Type: InPro3250
ChB Cal Date:08/01/01 ↑
  
```

The following information about the sensor will be shown in this menu. Use up and down arrows to scroll in the menu. Type: Type of sensor (e.g. InPro 3250)

Cal Date: Date of the last adjustment

Serial-No.: Serial number of the connected sensor

Part-No.: Part number of the connected sensor

Press [ENTER] to exit from this display.

12.5 ISM sensor diagnostics (available when ISM sensor connected)

(PATH: Info/ISM Diagnostics)



```

B  7.00  pH
B  25.0  °C
INFO
ISM Diagnostics  ↑
  
```

After plugging in an ISM sensor it is possible by using the key ▲ or ▼ to navigate to the Menu "ISM Diagnostics".

Press [ENTER] to select the menu.

Navigate to one of the menus, described in this section, and press [ENTER] again.



Cal History

The calibration history is stored with a time stamp in the ISM sensor and is displayed on the transmitter. The calibration history offers the following information:

Fact (Factory calibration): This is the original dataset, determined in the factory. This dataset remains stored in the sensor for reference and cannot be overwritten.

Act (Actual adjustment): This is the actual calibration dataset which is used for the measurement. This dataset moves to Cal2 position after the next adjustment.

1. Adj (First adjustment): This is the first adjustment after the factory calibration. This dataset remains stored in the sensor for reference and cannot be overwritten

Cal1 (last calibration/adjustment): This is the last executed calibration/adjustment. This dataset moves to Cal2 and then to Cal3 when a new calibration/adjustment is performed. Afterwards, the dataset is not available anymore.

Cal2 and Cal3 acting in the same way as Cal1.

Definition:

Adjustment: The calibration procedure is completed and the calibration values are taken over and used for the measurement (Act) and stated in Cal1. The current values from Act will move to Cal2.

Calibration: The calibration procedure is completed, but the calibration values will not be overtaken and the measurement continuous with the last valid adjustment dataset (Act). The dataset will be stored under Cal1.

The calibration history is used for the estimation of the lifetime indicator for ISM sensors.



Press [ENTER] to exit from this display.




Note: This function requires the correct setting of date and time during calibration and / or adjustment tasks (see chapter 9.6 "Set date & time").

Sensor monitoring (not available for Cond 4-e sensor)


The sensor monitoring shows the different diagnostics functions available for each ISM sensor. The following information is available:



Lifetime Indicator: Shows an estimation of the remaining lifetime to ensure a reliable measurement. The lifetime is indicated in days (d) and percentage (%). For a description of the Lifetime indicator, please see section 8.6 "ISM Setup". For oxygen sensors, the lifetime indicator is related to the inner-body of the sensor or the OptoCap for optical sensors. If you want to bring the bar indicator on the screen, see chapter 8.7.5 "ISM sensor monitoring" to activate ISM functions.




Adaptive Cal Timer: This timer shows a Adaptive Cal Timer, when the next calibration should be performed to keep the best possible measurement performance. The Adaptive Cal Timer is indicated in days (d) and percentage (%). For a description of the Adaptive Cal Timer, please see section 8.6 "ISM Setup".



Time to Maintenance: This timer shows a Time to Maintenance, when the next cleaning cycle should be performed to keep the best possible measurement performance. The Time to Maintenance is indicated in days (d) and percentage (%). For a description of the Time to Maintenance, please see section 8.6 "ISM Setup". For oxygen sensors, the Time to Maintenance indicates a maintenance cycle for the membrane and electrolyte.

Press [ENTER] to exit from this display.



Max. Temperature

The maximum temperature shows the maximum temperature that this sensor has ever seen, together with a time stamp of this maximum. This value is stored on the sensor and cannot be changed. During autoclaving the Max temperature is not recorded.


Max. Temperature

Tmax XXX°C YY/MM/DD

Press [ENTER] to exit from this display.



Note: This function requires the correct setting of date and time of the transmitter. (see chapter 9.6 "Set date & time")




CIP Cycles

Shows the amount of CIP cycles that the sensor has been exposed to. For a description of the CIP Cycle indicator, please see section 8.6 "ISM Setup"

CIP Cycles xxx of xxx

Press [ENTER] to exit from this display.




SIP Cycles

Shows the amount of SIP cycles that the sensor has been exposed to. For a description of the SIP Cycle indicator, please see section 8.6 "ISM Setup"

SIP Cycles xxx of xxx

Press [ENTER] to exit from this display.



Autoclaving Cycles

Shows the amount of Autoclaving cycles that the sensor has been exposed to. For a description of the AutoClave Cycle indicator, please see section 8.6 "ISM Setup"

Autoclaving Cycles xxx of xxx

Press [ENTER] to exit from this display.

13 Maintenance

13.1 Front panel cleaning

Clean the front panel with a damp soft cloth (water only, no solvents). Gently wipe the surface and dry with a soft cloth.

14 Troubleshooting

If the equipment is used in a manner not specified by Mettler-Toledo Thornton, Inc., the protection provided by the equipment may be impaired.

Review the table below for possible causes of common problems:

Problem	Possible Cause
Display is blank.	<ul style="list-style-type: none"> – No power to M400. – Blown fuse. – LCD display contrast set incorrectly. – Hardware failure.
Incorrect measurement readings.	<ul style="list-style-type: none"> – Sensor improperly installed. – Incorrect units multiplier entered. – Temperature compensation incorrectly set or disabled. – Sensor or transmitter needs calibration. – Sensor or patch cord defective or exceeds recommended maximum length. – Hardware failure.
Measurement readings not stable.	<ul style="list-style-type: none"> – Sensors or cables installed too close to equipment that generates high level of electrical noise. – Recommended cable length exceeded. – Averaging set too low. – Sensor or patch cord defective.
Displayed Δ is flashing.	<ul style="list-style-type: none"> – Setpoint is in alarm condition (setpoint exceeded). – Alarm has been selected (see chapter 8.5.1 "Alarm") and occurred.
Cannot change menu settings.	<ul style="list-style-type: none"> – User locked out for security reasons.

14.1 Changing the fuse



Make sure that the mains cable is unplugged before changing the fuse. This operation should only be carried out by personnel familiar with the transmitter and who are qualified for such work.

If the power consumption of the M400 transmitter is too high or a manipulation leads to a short circuit the fuse will blow. In this case remove the fuse and replace it with one specified in section 15 "Accessories and Spare Parts".

14.2 Cond (resistive) Error messages/ Warning- and Alarm list for Cond sensors

Alarms	Description
Cond Cell open*	Cell running dry (no measurement solution) or wires are broken
Dry Cond sensor*	Cell running dry (no measurement solution)
Cell deviation*	Multiplier out of tolerance** (depends on sensor model).

* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

** For further information refer to the sensor documentation

14.3 Cond (inductive) Error messages/ Warning- and Alarm list

Alarms	Description
Watchdog time-out*	SW/System fault
Send side open*	Wires for sending coil are broken or sensor defect
Send side short circ.*	Short circuit caused by sensor or cable for the sending coil
Receive side open*	Wires for receiving coil are broken or sensor defect

* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

14.4 pH Error messages/Warning- and Alarm list

14.4.1 pH sensors except dual membrane pH electrodes

Warnings	Description
Warning pH slope >102%	Slope too big
Warning pH Slope <90%	Slope too small
Warning pH Zero > 7.5 pH	Zero offset too big
Warning pH Zero <6.5 pH	Zero offset too small
Warning pHGs change <0.3**	Glass electrode resistance changed by more than factor 0.3
Warning pHGs change >3**	Glass electrode resistance changed by more than factor 3
Warning pHRef change <0.3**	Reference electrode resistance changed by more than factor 0.3
Warning pHRef change >3**	Reference electrode resistance changed by more than factor 3

Alarms	Description
Watchdog time-out*	SW/System fault
Error pH Slope >103%	Slope too big
Error pH Slope <80%	Slope too small
Error pH Zero >8.0 pH	Zero offset too big
Error pH Zero <6.0 pH	Zero offset too small
Error pH Ref Res >150 KΩ**	Reference electrode resistance too big (break)
Error pH Ref Res <2000 Ω**	Reference electrode resistance too small (short)
Error pH Gls Res >2000 MΩ**	Glass electrode resistance too big (break)
Error pH Gls Res <5 MΩ**	Glass electrode resistance too small (short)

* ISM sensors only

** According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

14.4.2 Dual membrane pH electrodes (pH/pNa)

Warnings	Description
Warning pH slope >102%	Slope too big
Warning pH Slope <90%	Slope too small
Warning pH Zero > 7.5 pH	Zero offset too big
Warning pH Zero <6.5 pH	Zero offset too small
Warning pHGs change <0.3*	Glass electrode resistance changed by more than factor 0.3
Warning pHGs change >3*	Glass electrode resistance changed by more than factor 3
Warning pNaGs change<0.3*	Glass electrode resistance changed by more than factor 0.3
Warning pNaGs change >3*	Reference electrode resistance changed by more than factor 3

Alarms	Description
Watchdog time-out	SW/System fault
Error pH Slope >103%	Slope too big
Error pH Slope <80%	Slope too small
Error pH Zero >8.0 pH	Zero offset too big
Error pH Zero <6.0 pH	Zero offset too small
Error pNa Gls Res > 2000 MΩ*	Glass electrode resistance too big (break)
Error pNa Gls Res <5 MΩ*	Glass electrode resistance too small (short)
Error pH Gls Res >2000 MΩ*	Glass electrode resistance too big (break)
Error pH Gls Res <5 MΩ*	Glass electrode resistance too small (short)

* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

14.4.3 ORP messages

Warnings*	Description
Warning ORP ZeroPt >30 mV	Zero offset too big
Warning ORP ZeroPt <-30 mV	Zero offset too small

Alarms*	Description
Watchdog time-out	SW/System fault
Error ORP ZeroPt >60 mV	Zero offset too big
Error ORP ZeroPt <-60 mV	Zero offset too small

* ISM sensors only

14.5 Amperometric O₂ Error messages/ Warning- and Alarm list

14.5.1 High level oxygen sensors

Warnings	Description
Warning O ₂ Slope < -90 nA	Slope too big
Warning O ₂ Slope > -35 nA	Slope too small
Warning O ₂ ZeroPt > 0.3 nA	Zero offset too big
Warning O ₂ ZeroPt < -0.3 nA	Zero offset too small

Alarms	Description
Watchdog time-out*	SW/System fault
Error O ₂ Slope < -110 nA	Slope too big
Error O ₂ Slope > -30 nA	Slope too small
Error O ₂ ZeroPt > 0.6 nA	Zero offset too big
Error O ₂ ZeroPt < -0.6 nA	Zero offset too small
Electrolyte Low*	Too low level of electrolyte

* ISM sensors only

14.5.2 Low level oxygen sensors

Warnings	Description
Warning O ₂ Slope < -460 nA	Slope too big
Warning O ₂ Slope > -250 nA	Slope too small
Warning O ₂ ZeroPt > 0.5 nA	Zero offset too big
Warning O ₂ ZeroPt < -0.5 nA	Zero offset too small

Alarms	Description
Watchdog time-out*	SW/System fault
Error Install O ₂ Jumper	In case of using InPro 6900 a jumper has to be installed (see chapter: Connection of Sensor – Dissolved Oxygen)
Error O ₂ Slope < -525 nA	Slope too big
Error O ₂ Slope > -220 nA	Slope too small
Error O ₂ ZeroPt > 1.0 nA	Zero offset too big
Error O ₂ ZeroPt < -1.0 nA	Zero offset too small
Electrolyte Low*	Too low level of electrolyte

* ISM sensors only

14.5.3 Trace oxygen sensors

Warnings	Description
Warning O ₂ Slope < -5000 nA	Slope too big
Warning O ₂ Slope > -3000 nA	Slope too small
Warning O ₂ ZeroPt > 0.5 nA	Zero offset too big
Warning O ₂ ZeroPt < -0.5 nA	Zero offset too small

Alarms	Description
Watchdog time-out	SW/System fault
Error O ₂ Slope < -6000 nA	Slope too big
Error O ₂ Slope > -2000 nA	Slope too small
Error O ₂ ZeroPt > 1.0 nA	Zero offset too big
Error O ₂ ZeroPt < -1.0 nA	Zero offset too small
Electrolyte Low*	Too low level of electrolyte

* ISM sensors only

14.6 Optical O₂ Error messages/Warning- and Alarm list

Alarms	Description
Watchdog time-out	SW/System fault
Chx Signal error**	Signal or value for temperature out of range
Chx Shaft error**	Temperature bad or stray light too high (e.g. because a glass is fiber broken) or shaft has been removed
Chx Hardware error**	Electronic components fail

** According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

If an alarm has occurred, you will find more information about the cause for the alarm in
Menu/Service/Diagnostics/O₂ optical

14.7 TDL/Warning- and Alarm list

Message	Comment	Action	Source	Relay State	Mapping
No sensor on channel 3	The M400 is unable to detect any of the ISM sensor(s) it can identify. If no sensor is found it will display the message NO SENSOR DETECTED	<ul style="list-style-type: none"> – This is the initial message after Power on. – Wait for the GPro™ 500 to fully boot. – Check if the GPro™ 500 is powered and wait until the system is fully started. – Check the RS485 wiring of the GPro™ 500 to the M400 – Check with the MT-TDL software and the Ethernet port if the system is running correctly. – If timeout still occurs after 60 s, send unit back to METTLER TOLEDO. 	M400	Fault	B disconnected
Signal Processing Failed	Fitting of the line profiles failed.	Send unit back to METTLER TOLEDO	TDL	Fault	Software error
Laser Source Error	The laser wavelength has shifted. Readjustment of the laser temperature necessary	Send unit back to METTLER TOLEDO	TDL	Fault	System error
Bad Signal Quality	Transmission lower than 5% threshold	Clean corner cube and process window. Check the gasket between TDL and probe. Rotate TDL on the probe to maximize Transmission. Reduce the dustload in the process.	TDL	Fault	System error
Flashcard Error	Missing or bad calibration and/or database data	Perform a calibration with the calibration tube. If still not successful, send unit back to METTLER TOLEDO for Flashcard exchange.	TDL	Fault	Software error
Pressure Input Error	Pressure reading out of extended range: 0.6 bara < P < 8 bara 4–20 mA input error: 4mA > P > 20 mA	Check external pressure sensor and mapping	TDL	Maintenance request	System error
Temperature Input Error	Pressure reading out of extended range: –20°C < T < 1000°C 4–20 mA input error: 4mA > P > 20 mA	Check external temperature sensor and mapping	TDL	Maintenance request	System error
Configuration Mode	Ethernet port in use: diagnostic or configuration in progress	Disconnect Ethernet cable	TDL	Maintenance request	Software error

The GPro™ 500 error messages can be found in the M400 under the following path:
Menu → Service → Diagnostics → TDL → Messages

Alarms	Description
Signal Processing Failed	too many iterations
Laser Source Error	Exceeds Range
Laser Source Error	No or invalid Peaks on Reference
Bad Signal Quality	too noisy, strange peaks, etc
Bad Signal Quality	ADC saturated
Bad Signal Quality	
Flashcard Error	missing or broken calibration
Flashcard Error	missing or broken config
Flashcard Error	missing or broken hitran database
Simulation Mode Active	simulated value
Pressure Input Error	no 4..20 mA
Pressure Input Invalid	out of range
Pressure Input Error	not reliable
Temperature Input Error	No 4..20 mA
Temperature Input Invalid	out of range
Temperature Input Error	not reliable
Diskspace Low	diskspace low
Flashcard Error	flashcard access error
Laser Control Error	automatic shutdown
Laser Control Error	Reading different to set value
Internal Temp Exceeded	Exceeds Range
Configuration Mode	ethernet diagnostic or configuration in progress
Hardware error	FPGA and Firmware do not match
Hardware error	Internal Voltage out of Range
Laser Source Error	Is Zero or too high

14.8 ISFET Error messages/Warning- and Alarm list

Warnings	Description
Warning pH slope >102%	Slope too big
Warning pH Slope <90%	Slope too small
Warning pH Zero >7.5 pH	Zero offset too big
Warning pH Zero <6.5 pH	Zero offset too small

Alarms	Description
Watchdog time-out*	SW/System fault
Error pH Slope >103%	Slope too big
Error pH Slope <80%	Slope too small
Error pH Zero >8.0 pH	Zero offset too big
Error pH Zero <6.0 pH	Zero offset too small

* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm).

14.9 Dissolved carbon dioxide Error messages/ Warning- and Alarm list

Warnings	Description
Warning pH slope >102%	Slope too big
Warning pH Slope <90%	Slope too small
Warning pH Zero >7.5 pH	Zero offset too big
Warning pH Zero <6.5 pH	Zero offset too small
Warning pHGIs change <0.3*	Glass electrode resistance changed by more than factor 0.3
Warning pHGIs change >3*	Glass electrode resistance changed by more than factor 3

Alarms	Description
Watchdog time-out*	SW/System fault
Error pH Slope >103%	Slope too big
Error pH Slope <80%	Slope too small
Error pH Zero >8.0 pH	Zero offset too big
Error pH Zero <6.0 pH	Zero offset too small
Error pH GIs Res >2000 MΩ*	Glass electrode resistance too big (break)
Error pH GIs Res <5 MΩ*	Glass electrode resistance too small (short)

* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";
PATH: Menu/Configure/Alarm/Clean/Setup Alarm).

14.10 CO₂ Hi (InPro 5500 i) Error messages and Alarm list

Alarms	Description
Chx CO ₂ slope > xx mV	Slope too big
Chx CO ₂ slope < yy mV	Slope too small
CO ₂ out of range	CO ₂ out of range
Temp out of range	Temp out of range
ChB CO ₂ not reliable	CO ₂ not reliable
ChB Change membrane	Change membrane
ChB System error	Sensor System error
ChB Software error	Sensor Software error

14.11 ISM common messages and Alarm list


Alarms	Description
Chx Cal Required	ACT=0 or measured values out of range
Chx CIP Counter Expired	Limit of CIP cycles reached
Chx SIP Counter Expired	Limit of SIP cycles reached
Chx Autocl.Count.Exp	Limit of Autoclaving cycles reached


14.12 Warning- and Alarm indication on the display


14.12.1 Warning indication

If there are conditions, which generate a warning, the message will be recorded and can be selected through the menu Messages (PATH: Info / Messages; see also chapter 12.1 "Messages"). According to the configuration of the transmitter the hint "Failure – Press ENTER" will be shown at line 4 of the display, if a warning or alarm has occurred (see also chapter 8.7 "Display"; PATH: Menu/Configure/Display/Measurement).

14.12.2 Alarm indication

Alarms will be shown in the display by a flashing symbol  and recorded through the menu point Messages (PATH: Info/Messages; see also chapter 12.1 "Messages").

Furthermore the detection of some alarms can be activated or deactivated (see chapter 8.5 "Alarm/Clean"; PATH: Menu/Configure/Alarm/Clean) for an indication on the display. If one of these alarms occurs and the detection has been activated, the flashing symbol  will be shown on the display and the message will be recorded through the menu Messages (see chapter 12.1 "Messages"; PATH: Info / Messages).

Alarms which are caused by a violation of the limitation of a setpoint or the range (see chapter 8.4 "Setpoints"; PATH: Menu/Configure/Setpoint) will also be shown by a flashing symbol  and recorded through the menu Messages (PATH: Info/Messages; see also chapter 12.1 "Messages").

According to the parameterisation of the transmitter the hint "Failure – Press ENTER" will be shown at line 4 of the display, if a warning or alarm has occurred (see also chapter 8.7 "Display"; PATH: Menu/Configure/Display/Measurement).

15 Accessories and Spare Parts

Please contact your local Mettler-Toledo sales office or representative for details for additional accessories and spare parts.

Description	Order no.
Pipe Mount Kit for 1/2DIN models	52 500 212
Panel Mount Kit for 1/2DIN models	52 500 213
Protective Hood for 1/2DIN models	52 500 214
Terminal blocks for M300, M400	52 121 504

16 Specifications

16.1 General specifications

Conductivity/resistive Specifications	
Range 0.01 cm ⁻¹ constant sensor	0.002 to 200 µS/cm (5000 Ω x cm to 500 MΩ x cm)
Range 0.1 cm ⁻¹ constant sensor	0.02 to 2000 µS/cm (500 Ω x cm to 50 MΩ x cm)
Range 10 cm ⁻¹ constant sensor	10 to 40,000 µS/cm (25 Ω x cm to 100 KΩ x cm)
Display range for 2-e sensor	0 to 40,000 mS/cm (25 Ω x cm to 100 MΩ x cm)
Display range for 4-e sensor	0.01 to 650 mS/cm (1.54 Ω x cm to 0.1 MΩ x cm)
Chemical concentration curves	NaCl: 0–26% @ 0 °C to 0–28% @ +100 °C NaOH: 0–12% @ 0 °C to 0–16% @ +40 °C to 0–6% @ +100 °C HCl: 0–18% @ –20 °C to 0–18% @ 0 °C to 0–5% @ +50 °C HNO ₃ : 0–30% @ –20 °C to 0–30% @ 0 °C to 0–8% @ +50 °C H ₂ SO ₄ : 0–26% @ –12 °C to 0–26% @ +5 °C to 0–9% @ +100 °C H ₃ PO ₄ : 0–35% @ +5 °C to +80 °C User defined concentration table (5x5 matrix)
TDS ranges	NaCl, CaCO ₃
Sensor maximum distance	analog: 61 m (200 ft); 15 m (50 ft with 4-E sensors) ISM: 80 m (260 ft)
Cond/Res accuracy**	±0.5% of reading or 0.25 Ω, whichever is greater, Up to 10 MΩ-cm
Cond/Res repeatability**	±0.25% of reading or 0.25 ohm, whichever is greater
Cond/Res resolution	auto/0.001/0.01/0.1/1 (can be selected)
Temperature input*	Pt1000/Pt100/NTC22K
Temperature measuring range	–40 to +200.0 °C (–40 to 392 °F)
Temperature resolution	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy**	±0.25 K (±0.45 °F) within –30 to +150 °C ±0.50 K (±0.90 °F) outside
Temperature repeatability**	±0.13 K (±0.23 °F)

* Not required on ISM sensors

** For analog input signal (ISM input signal causes no additional error).

Conductivity/inductive Specifications	
Conductivity range	0 to 2000 mS/cm
Chemical concentration curves	NaCl: 0–26% @ 0 °C to 0–28% @ +100 °C NaOH-1: 0–13% @ 0 °C to 0–24 @ +100 °C NaOH-2: 15–50% @ 0 °C to 35–50 @ +100 °C HCl-1: 0–18% @ –20 °C to +50 °C HCl-2: 22–39% @ –20 °C to +50 °C HNO3-1: 0–30% @ –20 °C to +50 °C HNO3-1: 35–96% @ –20 °C to +50 °C H2SO4-1: 0–26% @ –12 °C to 0–37% @ +100 °C H2SO4-2: 28–88% @ 0 °C to 39–88% @ +95 °C H2SO4-3: 94–99% @ –12 °C to 89–99% @ +95 °C H3PO4: 0–35% @ +5 °C to +80 °C User defined concentration table (5x5 matrix)
TDS ranges	NaCl, CaCO3
Sensor maximum distance	10 m
Cond / Ind accuracy	±1% of reading ±0.005 mS/cm
Cond / Ind repeatability	±1% of reading ±0.005 mS/cm
Cond / Ind resolution	auto/0.01/0.01/0.1 (can be selected)
Temperature input	Pt1000/Pt100/NTC22K
Temperature measuring range	–40 to + 200.0 °C (–40 to 392 °F)
Temperature resolution	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy	±0.25 K (±0.45 °F) within –30 to +150 °C ±0.50 K (±0.90 °F) outside
Temperature repeatability	±0.13 K (±0.23 °F)
pH incl. ISFET Specifications	
pH range	–2.00 to 16.00 pH
Sensor maximum distance	Analogue: 10 to 20 m (33 to 65 ft) depending on sensor ISM: 80 m (260 ft)
pH resolution	auto/0.01/0.1/1 (can be selected)
pH accuracy**	±0.02 pH
mV range	–1500 to 1500 mV
mV resolution	auto/0.01/0.1/1 mV
mV accuracy	±1 mV
Temperature input*	Pt1000/Pt100/NTC22K
Temperature measuring range	–30 to 130 °C (–22 to 266 °F)
Temperature resolution	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy**	±0.25 K
Temperature repeatability**	±0.13 K (±0.23 °F)

* Not required on ISM sensors

** For analog input signal (ISM input signal causes no additional error).

Available Buffer Sets:	
Standard buffers	
MT-9 buffers, MT-10 buffers, NIST Technical Buffers, NIST Standard Buffers (DIN 19266:2000-01), JIS Z 8802 buffers, Hach buffers, CIBA (94) buffers, Merck Titrisols-Reidel Fixanals, WTW buffers	
Dual membrane electrodes pH buffers (pH/pNa)	
Mettler-pH/pNa buffers (Na+ 3.9M)	
Specifications for Amperometric Oxygen Sensors	
Measuring range current	0 to 900 nA
Sensor maximum distance	Analogue: 20 m (65 ft) ISM: 80 m (260 ft)
Concentration range	0.1 ppb (µg/l) to 50.00ppm (mg/l)
DO accuracy**	Saturation: 0.5% of reading or 0.5% (whichever is greater) Concentration: Oxygen high: 0.5% of reading or 0.050ppm resp. 0.050mg/l (whichever is greater) Oxygen low: 0.5% of reading or 0.001ppm resp. 0.001mg/l (whichever is greater)
O ₂ gas accuracy**	0.5% of reading or 5ppb O ₂ gas (whichever is greater) for ppm resp. ppb O ₂ gas 0.5% of reading or 0.01% (whichever is greater) for Vol% O ₂ gas
Resolution	auto/0.001/0.01/0.1/1, (can be selected)
Polarization voltage	-674 mV (for analog sensors)
Temperature input*	Pt1000/NTC22K
Temperature measuring range	-30 to 150 °C (-22 to 302 °F)
Temperature resolution	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy**	±0.25 K within -10 to +80 °C
Temperature repeatability**	±0.13 K (±0.23 °F)

* Not required on ISM sensors

** For analog input signal (ISM input signal causes no additional error).

Specifications for Optical Oxygen Sensors	
Sensor maximum distance	15 m (50 ft)
DO concentration range	0.1 ppb (µg/l) to 50.00ppm (mg/l)
DO saturation range	0 to 500%air, 0 to 100%O ₂
DO accuracy	± 1 digit
Resolution	auto/0.001/0.01/0.1/1, (can be selected)
Temperature measuring range	-30 to 150 °C (-22 to 302 °F)
Temperature resolution	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy	± 1 digit
Temperature repeatability	± 1 digit

Dissolved Carbon Dioxide Specifications	
CO ₂ measuring ranges	0 ... 5000 mg/l 0 ... 200%sat 0 ... 1500 mmHg 0 ... 2000 mbar 0 ... 2000 hPa
Sensor maximum distance	15 m (49 ft)
CO ₂ accuracy	±5% of reading ±2 mg/l, resp. ±0.2% of reading ±2 hPa
CO ₂ resolution	auto/0.001/0.01/0.1/1, (can be selected)
mV range	–1500 to 1500 mV
mV resolution	auto/0.01/0.1/1 mV
mV accuracy	±1 mV
Total pressure range (TotPres)	0 ... 4000 mbar
Temperature input	Pt1000/NTC22K
Temperature measuring range	–30 to 150 °C (–22 to 302 °F)
Temperature resolution	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy	–40 to + 200.0 °C (–40 to 392 °F)
Temperature repeatability	auto/0.001/0.01/0.1/1 K (°F), (can be selected)
Temperature accuracy	±0.25 K within –10 to +80 °C
Temperature repeatability	±0.13 K (±0.23 °F)
Available Buffer Set:	
MT-9 buffers with solution pH = 7.00 and pH = 9.21 @ 25 °C	

Specifications for CO₂ Hi (InPro 5500i)	
Measuring range	0~10 bar p (CO ₂), 0~145 psi p (CO ₂) 0~15 g/L 0~7 V/V CO ₂
Accuracy	(0~50) °C, ± 1%

16.2 Electrical specifications

Power requirements	100 to 240 V AC or 20 to 30 V DC, 10 VA, AWG 14 < 2.5 mm ²
Frequency	50 to 60 Hz
Analog output signals	Four 0/4 to 20 mA outputs, galvanically isolated up to 60V from input and from earth/ground
Measurement Error through analog outputs	< ±0.05 mA over 1 to 22 mA range, < ±0.1 mA over 0 to 1 mA range
Analog output configuration	Linear, Bi-Linear, Logarithmic, Autoranging
Load	max. 500 Ω
Connection terminals	Detachable screw terminals
Digital communication	USB port, Type B connector
PID process controller	Pulse length, pulse frequency or analog control
Cycle time	Ca. 1 second
Connection terminals	Detachable screw terminals
Digital Input	2 with switching limits 0.00 VDC to 1.00 VDC for low level and 2.30 VDC to 30.00 VDC for high level
Mains power fuse	1.0 A slow blow type FC
Relays	2-SPDT mechanical 250 VAC, 30 VDC, 3 Amps 2-SPST mechanical rated at 250 VAC, 3 Amps 2-Reed 250 VAC or DC, 0.5 A
Alarm Relay delay	0–999 s
Keypad	5 tactile feedback keys
Display	four-line
Running capacity	Ca. 4 days
Max. cable length ISM	80 m



NOTE: This is a 4-wire-product with an active 4–20 mA analog output.
Please do not supply to Pin1–Pin6 of TB2.

16.3 Mechanical specifications

Dimensions (housing – H x W x D)*	144 x 144 x 116 mm
Front bezel – H x W	150 x 150 mm
Max. D – panel mounted	87 mm (excludes plug-in connectors)
Weight	0.95 kg (2 lb)
Material	ABS/polycarbonate
Ingress rating	IP 65 (when back cover is attached)

* H = Height, W = Width, D = Depth

16.4 Environmental specifications




Storage temperature	–40 to 70 °C (–40 to 158 °F)
Ambient temperature operating range	–10 to 50 °C (14 to 122 °F)
Relative humidity	0 to 95% non-condensing
Emissions	According to EN55011 Class A
Hazardous areas	Type 1, Type 2, Type 3: cFMus Class I Division 2, ATEX Zone 2 Type 1 Cond Ind: cFMus Class I Division 2 (in preparation) ATEX Zone 2 (in preparation)
Ratings / Approvals	CE Compliant

16.5 Ex Classification





NOTE: The Ex classification is valid for the transmitters M400 Type 1, M400 Type 2 and M400 Type 3. For the transmitter M400 Type 1 Cond Ind the approvals are in preparation.

Type plate

Mettler-Toledo AG CH - 8902 Urdorf, Switzerland  		P/N: 52121360 
CL1, DIV2, Groups ABCD T4 ENCLOSURE TYPE2	II 3G Ex nA nC IIC T4 SEV 08 ATEX 0140 X Attention - Consider Manual	M400 1 Channel Power: 100-240 VAC, 50/60 Hz, 10VA; 20-30 VDC, 10VA Output: 0/4-20mA Ambient Temperature: -10 to 50°C
Warning - Potential Electrostatic Charging Hazard - Clean Plastic Parts With Moist Cloth Only		

 N315

Mettler-Toledo, Inc. Billerica, MA 01821, USA  		P/N: 30105022 *30105022*
CL 1, DIV2, Groups ABCD T4 ENCLOSURE TYPE2	II 3G Ex nA nC IIC T4 SEV 08 ATEX 0140 X Attention - Consider Manual	M400 1 Channel Power: 100-240 VAC, 50/60Hz, 10VA; 20-30 VDC, 10VA Output: 0/4-20mA Ambient Temperature: -10 to 50°C
Warning - Potential Electrostatic Charging Hazard - Clean Plastic Parts With Moist Cloth Only		

 N315

Rating

Supply current circuit N(–) and L(+) –	100–240 V AC, 50/60 Hz, 10 W 20–30 V DC, 10 W
Relay current circuits (connections, TB1)	up to 250 V AC max. 20 W or up to 30 V DC max. 20 W
analogue outputs (connections, TB2)	$U_{max.} = 15 \text{ V}$, $I_{max.} = 255 \text{ mA}$, $P_{max.} = 2.5 \text{ W}$
analogue sensor pH, O ₂ , LF (connections, TB3, terminal 1–8)	$U_{max.} = 5.3 \text{ V}$, $I_{max.} \leq 5 \text{ mA}$, $P_{max.} \leq 26.5 \text{ mW}$
digital sensor pH, O ₂ (connections, TB4, terminal 3–4)	$U_{max.} \leq 5.3 \text{ V}$, $I_{max.} \leq 18 \text{ mA}$, $P_{max.} \leq 24 \text{ mW}$

17 Default table

Parameter	Sub parameter	Value	Unit
Alarm	Relay	2	
	Power Failure	No	
	Software Failure	No	
	ChB Disconnected	No	
	Rg diagnostics	No	
	Rr diagnostics	No	
	Cond Cell open	No	
	Cond cell shorted	No	
	Shaft error	No	
	Signal error	No	
	Hardware error	No	
	Cond Ind defect	No	
	Dry Cond sensor	No	
	Cell deviation	No	
	Lifetime indicator	No	
	Time To Maintenance	No	
	Adaptive Cal Timer	No	
	CIP cycle counter	No	
	SIP cycle counter	No	
	Autoclave cycle counter	No	
	Hold Mode*	Last	
	Delay	1	Sec
	Hysteresis	0	
	State	Inverted	
Clean	Relay	1	
	Interval	0	Hrs
	Clean Time	0	Sec
	State	Normal	
	Delay	0	
	Hysteresis	0	
Language		English	
Passwords	Administrator	00000	
	Operator	00000	
All Relays (unless otherwise specified)	Delay	10	Sec
	Hysteresis	5	%
	State	Normal	
	Hold mode	Last	
Lockout	Yes/No	No (= off)	
Channel A	Measurement a	pH (M400, Type 1,2,3)	
		Conductivity (M400, Type 1 Cond Ind)	mS/cm
	Measurement b	Temperature	°C
	Measurement c	Auto	
Channel B	Measurement d	Auto	

* For analogue output signal if relay is switched

Parameter	Sub parameter	Value	Unit
Cal constants (analog sensors)	Cond/Res	M = 0.1, A = 0.0	cm ⁻¹ Ω
	Cond/Ind	M = 2.1750, A = 0.0	cm ⁻¹ Ω
	O ₂ high	S = -70.00 A = 0.0	nA nA
	O ₂ low	S = -350.00 A = 0.0	nA nA
	pH incl. ISFET	S = 100.0, Z = 7.0	% pH
	pH – mV	S = 1.0, Z = 0.0	
	CO ₂	S = 100.0 Z = 7.0	% pH
	Temperature	M = 1.0, A = 0.0	Ω
Analog Out	1	Ch A – pH (M400 Type 1, 2, 3)	
		Ch A – Conductivity (M400 Type 1 Cond Ind)	S/cm
	2	Ch A – Temperature	°C
	3	Ch B – pH (M400 Type 1, 2, 3)	
		Ch B – Conductivity (M400 Type 1 Cond Ind)	S/cm
	4	Ch B – Temperature	°C
All analog out	Mode	4 – 20 mA	
	Type	Normal	
	Alarm	Off	
	Hold mode	Last value	
Conductivity <i>Resistivity</i>	Value 4 mA	0.1 10	μS/cm MΩ-cm
	Value 20 mA	10 20	μS/cm MΩ-cm
Dissolved Oxygen (M400, type 2)	Value 4 mA	0	%sat
	Value 20 mA	100	%sat
Dissolved Oxygen (M400, type 3)	Value 4 mA	0.000	ppb
	Value 20 mA	100.0	ppb
pH incl. ISFET	Value 4 mA	2.000	pH
	Value 20 mA	12.00	pH
Dissolved carbon dioxide	Value 4 mA	0	hPa
	Value 20 mA	100	hPa
Temperature	Value 4 mA	0	°C
	Value 20 mA	100	°C
Set point 1	Measurement	a	
	Type	Off	
Conductivity <i>Resistivity</i>	High Value	0 0	S/cm MΩ-cm
	Low Value	0 0	S/cm MΩ-cm
O ₂	High Value	50	% sat
	Low Value	0	% sat
pH (incl. ISFET)	High Value	12	pH
	Low Value	0	pH

Parameter	Sub parameter	Value	Unit
Relay 3	Set Point	1	
Set point 2	Measurement	c	
	Type	Off	
Conductivity <i>Resistivity</i>	High Value	0 <i>0</i>	S/cm <i>MΩ-cm</i>
	Low Value	0 <i>0</i>	S/cm <i>MΩ-cm</i>
O ₂	High Value	50	% sat
	Low Value	0	% sat
pH (incl. ISFET)	High Value	12	pH
	Low Value	0	pH
Relay 4	Set Point	2	
Resolution		Auto	
Set Point3	Measurement	_(none)	
	Type	Off	
	Relay	_(none)	
Set Point4	Measurement	_(none)	
	Type	Off	
	Relay	_(none)	
Conductivity <i>Resistivity</i>	Compensation	Standard	
Amperometric O ₂	Umeaspol	-675	mV
	Ucalpol	-675	mV
	CalPres	759.8	mmHg
	ProcPres	759.8	mmHg
	ProcCalPres	CalPres	
	Salinity	0.0	g/kg
	Humidity	100	%
Optical O ₂	CalPres	759.8	mmHg
	ProcPres	759.8	mmHg
	ProcCalPres	CalPres	
	Salinity	0.0	g/kg
	Humidity	100	%
	Sampling rate	1	sec/ measurement
	LED Mode	Auto	
	Toff	40.00	°C
pH	Drift Control	Auto	
	IP	7.0	pH
	STC	0.000	pH/°C
	FixCalTemp	No	
	pH Buffer	Mettler-9	
	Cal info slope	[%]	
	Cal info offset	[pH]	
CO ₂	Drift Control	Auto	
	pH Buffer	Mettler-9	
	Salinity	28.00	g/L
	HCO ₃	0.050	Mol/L
	TotPres	750.1	mmHg

18 Warranty

METTLER TOLEDO warrants this product to be free from significant deviations in material and workmanship for a period of one year from the date of purchase. If repair is necessary and not the result of abuse or misuse within the warranty period, please return by freight pre-paid and amendment will be made without any charge. METTLER TOLEDO's Customer Service Dept. will determine if the product problem is due to deviations or customer abuse. Out-of-warranty products will be repaired on an exchange basis at cost.

The above warranty is the only warranty made by METTLER TOLEDO and is lieu of all other warranties, expressed or implied, including, without limitation, implied warranties of merchantability and fitness for a particular purpose. METTLER TOLEDO shall not be liable for any loss, claim, expense or damage caused by, contributed to or arising out of the acts or omissions of the Buyer or Third Parties, whether negligent or otherwise. In no event shall METTLER TOLEDO's liability for any cause of action whatsoever exceed the cost of the item giving rise to the claim, whether based in contract, warranty, indemnity, or tort (including negligence).

19 Buffer tables

M400 transmitters have the ability to do automatic pH buffer recognition. The following tables show different standard buffers that are automatically recognized.

19.1 Standard pH buffers

19.1.1 Mettler-9

Temp (°C)	pH of buffer solutions			
0	2.03	4.01	7.12	9.52
5	2.02	4.01	7.09	9.45
10	2.01	4.00	7.06	9.38
15	2.00	4.00	7.04	9.32
20	2.00	4.00	7.02	9.26
25	2.00	4.01	7.00	9.21
30	1.99	4.01	6.99	9.16
35	1.99	4.02	6.98	9.11
40	1.98	4.03	6.97	9.06
45	1.98	4.04	6.97	9.03
50	1.98	4.06	6.97	8.99
55	1.98	4.08	6.98	8.96
60	1.98	4.10	6.98	8.93
65	1.98	4.13	6.99	8.90
70	1.99	4.16	7.00	8.88
75	1.99	4.19	7.02	8.85
80	2.00	4.22	7.04	8.83
85	2.00	4.26	7.06	8.81
90	2.00	4.30	7.09	8.79
95	2.00	4.35	7.12	8.77

19.1.2 Mettler-10

Temp (°C)	pH of buffer solutions				
0	2.03	4.01	7.12	10.65	
5	2.02	4.01	7.09	10.52	
10	2.01	4.00	7.06	10.39	
15	2.00	4.00	7.04	10.26	
20	2.00	4.00	7.02	10.13	
25	2.00	4.01	7.00	10.00	
30	1.99	4.01	6.99	9.87	
35	1.99	4.02	6.98	9.74	
40	1.98	4.03	6.97	9.61	
45	1.98	4.04	6.97	9.48	
50	1.98	4.06	6.97	9.35	
55	1.98	4.08	6.98		
60	1.98	4.10	6.98		
65	1.99	4.13	6.99		
70	1.98	4.16	7.00		
75	1.99	4.19	7.02		
80	2.00	4.22	7.04		
85	2.00	4.26	7.06		
90	2.00	4.30	7.09		
95	2.00	4.35	7.12		

19.1.3 NIST Technical Buffers

Temp (°C)	pH of buffer solutions				
0	1.67	4.00	7.115	10.32	13.42
5	1.67	4.00	7.085	10.25	13.21
10	1.67	4.00	7.06	10.18	13.01
15	1.67	4.00	7.04	10.12	12.82
20	1.675	4.00	7.015	10.07	12.64
25	1.68	4.005	7.00	10.01	12.46
30	1.68	4.015	6.985	9.97	12.30
35	1.69	4.025	6.98	9.93	12.13
40	1.69	4.03	6.975	9.89	11.99
45	1.70	4.045	6.975	9.86	11.84
50	1.705	4.06	6.97	9.83	11.71
55	1.715	4.075	6.97		11.57
60	1.72	4.085	6.97		11.45
65	1.73	4.10	6.98		
70	1.74	4.13	6.99		
75	1.75	4.14	7.01		
80	1.765	4.16	7.03		
85	1.78	4.18	7.05		
90	1.79	4.21	7.08		
95	1.805	4.23	7.11		

19.1.4 NIST standard buffers (DIN and JIS 19266: 2000–01)

Temp (°C)	pH of buffer solutions			
0				
5	1.668	4.004	6.950	9.392
10	1.670	4.001	6.922	9.331
15	1.672	4.001	6.900	9.277
20	1.676	4.003	6.880	9.228
25	1.680	4.008	6.865	9.184
30	1.685	4.015	6.853	9.144
35	1.694	4.028	6.841	9.095
40	1.697	4.036	6.837	9.076
45	1.704	4.049	6.834	9.046
50	1.712	4.064	6.833	9.018
55	1.715	4.075	6.834	8.985
60	1.723	4.091	6.836	8.962
70	1.743	4.126	6.845	8.921
80	1.766	4.164	6.859	8.885
90	1.792	4.205	6.877	8.850
95	1.806	4.227	6.886	8.833



NOTE: The pH(S) values of the individual charges of the secondary reference materials are documented in a certificate of an accredited laboratory. This certificate is supplied with the respective buffer materials. Only these pH(S) values shall be used as standard values for the secondary reference buffer materials. Correspondingly, this standard does not include a table with standard pH values for practical use. The table above only provides examples of pH(PS) values for orientation.

19.1.5 Hach buffers

Buffer values up to 60 °C as specified by Bergmann & Beving Process AB.

Temp (°C)	pH of buffer solutions		
0	4.00	7.14	10.30
5	4.00	7.10	10.23
10	4.00	7.04	10.11
15	4.00	7.04	10.11
20	4.00	7.02	10.05
25	4.01	7.00	10.00
30	4.01	6.99	9.96
35	4.02	6.98	9.92
40	4.03	6.98	9.88
45	4.05	6.98	9.85
50	4.06	6.98	9.82
55	4.07	6.98	9.79
60	4.09	6.99	9.76

19.1.6 Ciba (94) buffers

Temp (°C)	pH of buffer solutions				
0	2.04	4.00	7.10	10.30	
5	2.09	4.02	7.08	10.21	
10	2.07	4.00	7.05	10.14	
15	2.08	4.00	7.02	10.06	
20	2.09	4.01	6.98	9.99	
25	2.08	4.02	6.98	9.95	
30	2.06	4.00	6.96	9.89	
35	2.06	4.01	6.95	9.85	
40	2.07	4.02	6.94	9.81	
45	2.06	4.03	6.93	9.77	
50	2.06	4.04	6.93	9.73	
55	2.05	4.05	6.91	9.68	
60	2.08	4.10	6.93	9.66	
65	2.07*	4.10*	6.92*	9.61*	
70	2.07	4.11	6.92	9.57	
75	2.04*	4.13*	6.92*	9.54*	
80	2.02	4.15	6.93	9.52	
85	2.03*	4.17*	6.95*	9.47*	
90	2.04	4.20	6.97	9.43	
95	2.05*	4.22*	6.99*	9.38*	

* Extrapolated

19.1.7 Merck Titrisole, Riedel-de-Haën Fixanale

Temp (°C)	pH of buffer solutions				
0	2.01	4.05	7.13	9.24	12.58
5	2.01	4.05	7.07	9.16	12.41
10	2.01	4.02	7.05	9.11	12.26
15	2.00	4.01	7.02	9.05	12.10
20	2.00	4.00	7.00	9.00	12.00
25	2.00	4.01	6.98	8.95	11.88
30	2.00	4.01	6.98	8.91	11.72
35	2.00	4.01	6.96	8.88	11.67
40	2.00	4.01	6.95	8.85	11.54
45	2.00	4.01	6.95	8.82	11.44
50	2.00	4.00	6.95	8.79	11.33
55	2.00	4.00	6.95	8.76	11.19
60	2.00	4.00	6.96	8.73	11.04
65	2.00	4.00	6.96	8.72	10.97
70	2.01	4.00	6.96	8.70	10.90
75	2.01	4.00	6.96	8.68	10.80
80	2.01	4.00	6.97	8.66	10.70
85	2.01	4.00	6.98	8.65	10.59
90	2.01	4.00	7.00	8.64	10.48
95	2.01	4.00	7.02	8.64	10.37

19.1.8 WTW buffers

Temp (°C)	pH of buffer solutions			
0	2.03	4.01	7.12	10.65
5	2.02	4.01	7.09	10.52
10	2.01	4.00	7.06	10.39
15	2.00	4.00	7.04	10.26
20	2.00	4.00	7.02	10.13
25	2.00	4.01	7.00	10.00
30	1.99	4.01	6.99	9.87
35	1.99	4.02	6.98	9.74
40	1.98	4.03	6.97	9.61
45	1.98	4.04	6.97	9.48
50	1.98	4.06	6.97	9.35
55	1.98	4.08	6.98	
60	1.98	4.10	6.98	
65	1.99	4.13	6.99	
70		4.16	7.00	
75		4.19	7.02	
80		4.22	7.04	
85		4.26	7.06	
90		4.30	7.09	
95		4.35	7.12	

19.1.9 JIS Z 8802 buffers

Temp (°C)	pH of buffer solutions			
0	1.666	4.003	6.984	9.464
5	1.668	3.999	6.951	9.395
10	1.670	3.998	6.923	9.332
15	1.672	3.999	6.900	9.276
20	1.675	4.002	6.881	9.225
25	1.679	4.008	6.865	9.180
30	1.683	4.015	6.853	9.139
35	1.688	4.024	6.844	9.102
38	1.691	4.030	6.840	9.081
40	1.694	4.035	6.838	9.068
45	1.700	4.047	6.834	9.038
50	1.707	4.060	6.833	9.011
55	1.715	4.075	6.834	8.985
60	1.723	4.091	6.836	8.962
70	1.743	4.126	6.845	8.921
80	1.766	4.164	6.859	8.885
90	1.792	4.205	6.877	8.850
95	1.806	4.227	6.886	8.833

19.2 Dual membrane pH electrode buffers

19.2.1 Mettler-pH/pNa buffers (Na+ 3.9M)

Temp (°C)	pH of buffer solutions			
0	1.98	3.99	7.01	9.51
5	1.98	3.99	7.00	9.43
10	1.99	3.99	7.00	9.36
15	1.99	3.99	6.99	9.30
20	1.99	4.00	7.00	9.25
25	2.00	4.01	7.00	9.21
30	2.00	4.02	7.01	9.18
35	2.01	4.04	7.01	9.15
40	2.01	4.05	7.02	9.12
45	2.02	4.07	7.03	9.11
50	2.02	4.09	7.04	9.10

Sales and Service:**Australia**

Mettler-Toledo Ltd.
220 Turner Street
Port Melbourne
AUS-3207 Melbourne/VIC
Phone +61 1300 659 761
Fax +61 3 9645 3935
e-mail info.mtaus@mt.com

Austria

Mettler-Toledo Ges.m.b.H.
Südrandstraße 17
A-1230 Wien
Phone +43 1 604 19 80
Fax +43 1 604 28 80
e-mail infoprocess.mtat@mt.com

Brazil

Mettler-Toledo Ind. e Com. Ltda.
Avenida Tamboré, 418
Tamboré
BR-06460-000 Barueri/SP
Tel. +55 11 4166 7400
Fax +55 11 4166 7401
e-mail mettler@mettler.com.br
service@mettler.com.br

China

Mettler-Toledo Instruments
(Shanghai) Co. Ltd.
589 Gui Ping Road
Cao He Jing
CN-200233 Shanghai
Phone +86 21 64 85 04 35
Fax +86 21 64 85 33 51
e-mail mtcs@public.sta.net.cn

Croatia

Mettler-Toledo d.o.o.
Mandlova 3
HR-10000 Zagreb
Phone +385 1 292 06 33
Fax +385 1 295 81 40
e-mail mt.zagreb@mt.com

Czech Republic

Mettler-Toledo s.r.o.
Trebohosticka 2283/2
CZ-100 00 Praha 10
Phone +420 2 72 123 150
Fax +420 2 72 123 170
e-mail sales.mtcz@mt.com

Denmark

Mettler-Toledo A/S
Naverland 8
DK-2600 Glostrup
Phone +45 43 27 08 00
Fax +45 43 27 08 28
e-mail info.mtdk@mt.com

France

Mettler-Toledo
Analyse Industrielle S.A.S.
30, Boulevard de Douaumont
F-75017 Paris
Phone +33 1 47 37 06 00
Fax +33 1 47 37 46 26
e-mail mtpro-f@mt.com

Germany

Mettler-Toledo GmbH
Prozeßanalytik
Ockerweg 3
D-35396 Gießen
Phone +49 641 507 333
Fax +49 641 507 397
e-mail prozess@mt.com

Great Britain

Mettler-Toledo LTD
64 Boston Road, Beaumont Leys
GB-Leicester LE4 1AW
Phone +44 116 235 7070
Fax +44 116 236 5500
e-mail enquire.mtuk@mt.com

Hungary

Mettler-Toledo Kereskedelmi KFT
Teve u. 41
HU-1139 Budapest
Phone +36 1 288 40 40
Fax +36 1 288 40 50
e-mail mthu@axelero.hu

India

Mettler-Toledo India Private Limited
Amar Hill, Saki Vihar Road
Powai
IN-400 072 Mumbai
Phone +91 22 2857 0808
Fax +91 22 2857 5071
e-mail sales.mtin@mt.com

Italy

Mettler-Toledo S.p.A.
Via Vialba 42
I-20026 Novate Milanese
Phone +39 02 333 321
Fax +39 02 356 2973
e-mail customercare.italia@mt.com

Japan

Mettler-Toledo K.K.
Process Division
6F Ikenohata Nisshoku Bldg.
2-9-7, Ikenohata
Taito-ku
JP-110-0008 Tokyo
Phone +81 3 5815 5606
Fax +81 3 5815 5626
e-mail helpdesk.ing.jp@mt.com

Malaysia

Mettler-Toledo (M) Sdn Bhd
Bangunan Electroscon Holding, U 1-01
Lot 8 Jalan Astaka U8/84
Seksyen U8, Bukit Jelutong
MY-40150 Shah Alam Selangor
Phone +60 3 78 44 58 88
Fax +60 3 78 45 87 73
e-mail
MT-MY.CustomerSupport@mt.com

Mexico

Mettler-Toledo S.A. de C.V.
Ejército Nacional #340
Col. Chapultepec Morales
Del. Miguel Hidalgo
MX-11570 México D.F.
Phone +52 55 1946 0900
e-mail ventas.lab@mt.com

Poland

Mettler-Toledo (Poland) Sp.z.o.o.
ul. Poleczki 21
PL-02-822 Warszawa
Phone +48 22 545 06 80
Fax +48 22 545 06 88
e-mail polska@mt.com

Russia

Mettler-Toledo Vostok ZAO
Sretenskij Bulvar 6/1
Office 6
RU-101000 Moscow
Phone +7 495 621 56 66
Fax +7 495 621 63 53
e-mail inforus@mt.com

Singapore

Mettler-Toledo (S) Pte. Ltd.
Block 28
Ayer Rajah Crescent #05-01
SG-139959 Singapore
Phone +65 6890 00 11
Fax +65 6890 00 12
+65 6890 00 13
e-mail precision@mt.com

Slovakia

Mettler-Toledo s.r.o.
Hattalova 12/A
SK-831 03 Bratislava
Phone +421 2 4444 12 20-2
Fax +421 2 4444 12 23
e-mail predaj@mt.com

Slovenia

Mettler-Toledo d.o.o.
Pot heroja Trtnika 26
SI-1261 Ljubljana-Dobrunje
Phone +386 1 530 80 50
Fax +386 1 562 17 89
e-mail keith.racman@mt.com

South Korea

Mettler-Toledo (Korea) Ltd.
Yeil Building 1 & 2 F
124-5, YangJe-Dong
SeCho-Ku
KR-137-130 Seoul
Phone +82 2 3498 3500
Fax +82 2 3498 3555
e-mail Sales_MTKR@mt.com

Spain

Mettler-Toledo S.A.E.
C/Miguel Hernández, 69-71
ES-08908 L'Hospitalet de Llobregat
(Barcelona)
Phone +34 902 32 00 23
Fax +34 902 32 00 24
e-mail mtemkt@mt.com

Sweden

Mettler-Toledo AB
Virkesvägen 10
Box 92161
SE-12008 Stockholm
Phone +46 8 702 50 00
Fax +46 8 642 45 62
e-mail sales.mts@mt.com

Switzerland

Mettler-Toledo (Schweiz) GmbH
Im Langacher
Postfach
CH-8606 Greifensee
Phone +41 44 944 45 45
Fax +41 44 944 45 10
e-mail salesola.ch@mt.com

Thailand

Mettler-Toledo (Thailand) Ltd.
272 Soi Soonvijai 4
Rama 9 Rd., Bangkok
Huay Kwang
TH-10320 Bangkok
Phone +66 2 723 03 00
Fax +66 2 719 64 79
e-mail
MT-TH.CustomerSupport@mt.com

USA/Canada

METTLER TOLEDO
Process Analytics
900 Middlesex Turnpike, Bld. 8
Billerica, MA 01821, USA
Phone +1 781 301 8800
Freephone +1 800 352 8763
Fax +1 781 271 0681
e-mail mtprou@mt.com



Management System
certified according to
ISO 9001 / ISO 14001

Subject to technical changes.
© Mettler-Toledo AG, Process Analytics
12/13 Printed in Switzerland. 51 121 378

Mettler-Toledo AG, Process Analytics
Im Hackacker 15, CH-8902 Urdorf, Switzerland
Tel. +41 44 729 62 11, Fax +41 44 729 66 36

www.mt.com/pro