

ControlLogix Enhanced Redundancy System, Revision 20.055_kit5

Redundancy Module Catalog Numbers 1756-RM, 1756-RMXT, 1756-RM2, 1756-RM2XT

Controller Catalog Numbers

1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75

Communication Module Catalog Numbers

1756-CN2/B, 1756-CN2/C, 1756-CN2R/B, 1756-CN2R/C, 1756-CN2RXT/B, 1756-CN2RXT/C, 1756-CN2RK/C, 1756-EN2T, 1756-EN2TR, 1756-EN2TRT, 1756-EN2TRK/C, 1756-EN2TK/D, 1756-EN2F/A, 1756-EN2F/B, 1756-EN2F/C

IMPORTANT	Throughout this publication, the following applies:
	Ethernet Communication Modules
	 References to the 1756-EN2T/B and 1756-EN2TR/B (or earlier) modules also apply to the 1756-EN2TRXT/B (or earlier) modules.
	 References to the 1756-EN2T/C and 1756-EN2TR/C (or earlier) modules also apply to the 1756-EN2TRXT/C (or earlier) modules.
	 References to the 1756-EN2T/D and 1756-EN2TR/D modules also apply to the 1756-EN2TRXT/D modules.
	ControlNet Communication Modules
	 References to the 1756-CN2/B modules also apply to the 1756-CN2R/B, 1756-CN2RXT/B modules.
	 References to the 1756-CN2/C modules also apply to the 1756-CN2R/C, 1756-CN2RXT/C, 1756-CN2RK/C, modules.
	 Catalog numbers 1756-RM, 1756-RM2, and 1756-RM2XT refer to any series modules.



These release notes describe enhancements, corrected anomalies, known anomalies, restrictions, and application notes regarding enhanced redundancy system revision 20.055_kit5 or earlier.

Topic	Page
Product Release Notes	2
About This Enhanced Redundancy Firmware Bundle	2
Compatible Software Versions	6
About the Redundancy Module Configuration Tool	7
Enhancements	8
Corrected Anomalies	11
Known Anomalies	15
Restrictions	18
Application Notes	21
Upgrade the RSLogix 5000 Software Version	30
Replace a Module in the Secondary Chassis that has the Same Catalog Number and Firmware Revision	32
Replace 1756-EN2T, 1756-EN2TR, or 1756-EN2F Modules	33
Replace 1756-CN2 Modules	39
Upgrade the RSLogix 5000 Software Version and Replace 1756-EN2T, 1756-EN2TR or 1756-CN2	44
Upgrade the Firmware by Using Redundancy System Update	46
Update IP Address Set Via Software to Address Set Via Rotary Switches	66
Replace 1756-RM/B (or earlier) Modules with 1756-RM2 Modules	70
Storing a Project to a Nonvolatile Memory Card While Your Process Is Running	71
Access Product Release Notes	74
Additional Resources	75

Product Release NotesProduct release notes for the individual products that are part of this
ControlLogix* Enhanced Redundancy bundle are available online within the
Product Compatibility and Download Center.For example, you can access release note information specific to the 1756-EN2T
ControlLogix EtherNet/IP bridge.For more information on product release notes, see page 74.About This Enhanced
Redundancy Firmware BundleThis enhanced redundancy firmware bundle, which is identified as revision
20.055_kit5, contains series firmware revisions for each of the modules that are
limed in Table 1. Descined Science of Dimension Comparement Lead

20.055_kit5, contains series firmware revisions for each of the modules that are listed in <u>Table 1</u>, <u>Required Series and Firmware Revisions for Components Used</u> in an Enhanced Redundancy System, <u>Revision 20.055_kit5</u> You can download the firmware bundle at the Product Compatibility and Download Center: http://www.rockwellautomation.com/rockwellautomation/support/pcdc.page?.

Information that has been added or changed since the last revision of this publication is indicated by a change bar as shown next to this paragraph. In addition to information specific to the most recent firmware revision, the information from previous minor revisions is retained in these release notes.

We strongly recommend that you review the information provided regarding previous firmware revisions. We recommend that you do so because if you are upgrading your firmware through multiple previous revisions, all of the information specific to all of the revisions is applicable.

IMPORTANTWhen designing, installing, and operating the redundant chassis pair (RCP) for this
enhanced redundancy system revision, you can use only the modules that are specified
in Table 1, Required Series and Firmware Revisions for Components Used in an
Enhanced Redundancy System, Revision 20.055
kit5.Also, keep in mind the series and firmware revision requirements listed apply only to
components used in the redundant chassis pair, not to components used with
the redundancy system outside the redundant chassis pair.

This enhanced redundancy system revision includes the following:

- Support using the 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, 1756-CN2RK/C modules with firmware revision 25.005
- Support using the 1756-EN2F/C modules with firmware revision 10.009

Table 1 - Required Series and Firmware Revi	isions for Components Used in an Enhanced	d Redundancy System, Revision 20.055_kit5

Cat. No.	Module Description	Series	Firmware Revision	
1756-CN2	ControlLogix ControlNet bridge module		20.020	
1756-CN2R	ControlLogix redundant media ControlNet bridge module			
1756-CN2RXT	ControlLogix-XT [™] redundant media ControlNet bridge module			
1756-CN2 ⁽¹⁾	ControlLogix ControlNet bridge module	C	25.005	
1756-CN2R ⁽¹⁾	ControlLogix redundant media ControlNet bridge module			
1756-CN2RXT ⁽¹⁾	ControlLogix-XT redundant media ControlNet bridge module			
1756-CN2RK ⁽¹⁾	ControlLogix redundant ControlNet bridge (conformal coated) module			
1756-EN2T	ControlLogix EtherNet/IP communication module	D	10.007 ⁽²⁾⁽³⁾	
		C (or earlier)	5.008 or 5.028 ⁽⁴⁾⁽⁵⁾	
1756-EN2TR	ControlLogix EtherNet/IP communication module	C	10.007 ⁽³⁾⁽⁶⁾	
		B (or earlier)	5.008 or 5.028 ⁽⁵⁾⁽⁷⁾	
1756-EN2F	ControlLogix EtherNet/IP fiber communication module	C	10.009 ⁽⁸⁾	
		B (or earlier)	5.008 or 5.028 ⁽⁴⁾⁽⁵⁾	
1756-EN2TXT	ControlLogix-XT EtherNet/IP communication module	C (or earlier)	5.008 or 5.028 ⁽⁴⁾⁽⁵⁾	
		D	10.007 ⁽²⁾⁽³⁾	

Cat. No.	Module Description	Series	Firmware Revision	
1756-EN2TRXT	ControlLogix-XT EtherNet/IP redundant communication module	C	10.007 ⁽³⁾⁽⁶⁾	
		В	5.028 ⁽⁵⁾⁽⁷⁾	
1756-EN2TRK	ControlLogix EtherNet/IP conformal coated communication bridge module	C	10.007 ⁽³⁾⁽⁶⁾	
1756-EN2TK	ControlLogix EtherNet/IP conformal coated communication bridge module	D	10.007 ⁽²⁾⁽³⁾	
1756-L61	ControlLogix5561 controller	Any	20.055	
1756-L62	ControlLogix5562 controller			
1756-L63	ControlLogix5563 controller			
1756-L63XT	ControlLogix-XT controller			
1756-L64	ControlLogix5564 controller			
1756-L65	ControlLogix5565 controller			
1756-L71	ControlLogix5571 controller			
1756-L72	ControlLogix5572 controller			
1756-L73	ControlLogix5573 controller			
1756-L73XT	ControlLogix-XT controller			
1756-L74	ControlLogix5574 controller			
1756-L75	ControlLogix5575 controller			
1756-RM2	ControlLogix redundancy module	Any 20.005		
1756-RM2XT	ControlLogix-XT redundancy module			
1756-RM	ControlLogix redundancy module Any 3.		3.003	
1756-RMXT	ControlLogix-XT redundancy module			

Table 1 - Required Series and Firmware Revisions for Components Used in an Enhanced Redundancy System, Revision 20.055_kit5 (Continued)

(1) **IMPORTANT:** The 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, 1756-CN2RK/C modules do not support firmware revisions previous to revision 25.004. Do not attempt to update the firmware to earlier revisions.

(2) IMPORTANT: The 1756-EN2T/D modules do not support firmware revisions previous to revision 10.006. Do not attempt to update the firmware to earlier revisions.

(3) Firmware revision 10.006 or later is digitally signed. For more information on digitally signed firmware, see page 5.

(4) IMPORTANT: The 1756-EN2T/C (or earlier) modules do not support firmware revision 10.006 or later. Do not attempt to update the firmware to revision 10.006 or later.

(5) Firmware revision 5.028 is digitally signed firmware. Firmware revision 5.008 is unsigned firmware. For more information on digitally signed firmware, see page 5.

(6) IMPORTANT: The 1756-EN2TR/C modules do not support firmware revisions previous to revision 10.007. Do not attempt to update the firmware to previous revisions.

(7) **IMPORTANT:** The 1756-EN2TR/B (or earlier) modules do not support firmware revision 10.007. Do not attempt to update the firmware to revision 10.007.

(8) IMPORTANT: The 1756-EN2F/C modules do not support firmware revisions previous to revision 10.009. Do not attempt to update the firmware to a previous version.

1756-EN2T, 1756-EN2TR, and 1756-EN2F Modules Digitally signed Firmware

Digitally signed firmware provides more security over the unsigned firmware. This firmware is different based on the EtherNet/IP communication modules you use.

Cat. No.	Supported Firmware Revisions	Digitally signed Firmware	Included with the Enhanced Redundancy System, Revision 20.055_kit5 Bundle
1756-EN2T/D	10.006 or later	Yes	Yes
1756-EN2T/C (or earlier)	5.008	No	Yes
	5.028	Yes	No
1756-EN2TR/C	10.007	Yes	Yes
1756-EN2TR/B (or earlier)	5.008	No	Yes
	5.028	Yes	No
1756-EN2F/C	10.009	Yes	Yes
1756-EN2F/B (or earlier)	5.008	No	Yes
	5.028	Yes	No

Firmware revision 5.028 is not included in the enhanced redundancy system, revision 20.055_kit5 firmware bundle. If you want to use it you have to download and install this firmware separately.

IMPORTANT	When you install the digitally signed firmware, that is, firmware revision 5.028, into a 1756-EN2T/C (or earlier), 1756-EN2TR/B (or earlier), or 1756-EN2F/B (or earlier) module, the installation makes the module incompatible with some firmware revisions.
	For example, after you upgrade firmware, the module supports use of only digitally signed firmware. Any unsigned firmware updates are rejected by the module.

You can download firmware revision 5.028 and the enhanced redundancy system, revision 20.055_kit5 firmware bundle at the Product Compatibility and Download Center:

http://www.rockwellautomation.com/rockwellautomation/support/pcdc.page

The firmware bundle is identified as V20.055_kit5.

 TIP
 Select the base catalog number in ControlFlash when upgrading extended temperature or conformal coated modules.

 For example, select the 1756-EN2TR when upgrading a 1756-EN2TRXT module.

 Extended temperature and conformal coated modules use the same Redundancy module ControlFlash kit.

Compatible Software Versions

Use these versions of software with this redundancy firmware bundle.

Table 2 - Required Software Versions for Enhanced Redundancy System, Revision 20.055_kit5

Software	Required Software Version, Min	
CompareTool	3.20.02	
ControlFLASH™	12.01.00	
FactoryTalk Services Platform	2.50.00 (CPR 9, SR5)	
FactoryTalk Activation	3.50.00 (CPR 9, SR5)	
FactoryTalk Alarms and Events	2.40.00 (CPR 9, SR4)	
FactoryTalk AssetCentre	4.00.00	
FactoryTalk Batch	11.00.00 ⁽²⁾	
FactoryTalk View Site Edition	6.10.00 (CPR 9, SR4)	
Redundancy Module Configuration Tool	8.02.01	
RSLinx® Enterprise	5.50.04 (CPR 9, SR5)	
RSLinx Classic	2.59.01 (CPR 9, SR5)	
RSLogix™5000 ⁽¹⁾	20.01.00 (CPR 9, SR5)	
	20.03.00 (CPR9, SR5)	
RSNetWorx™ for ControlNet	11.00.00 (CPR 9, SR5)	
RSNetWorx for EtherNet/IP		

 If you choose to use RSLogix 5000 software, version 20.03.00, we strongly recommend that you read <u>Upgrade the RSLogix 5000</u> <u>Software Version on page 30</u> before proceeding.

(2) Use the most recent FactoryTalk Batch Patch Roll-up with this enhanced redundancy firmware revision. For the most recent patch roll-up, see Rockwell Automation Knowledgebase Answer ID 59058, accessible at: <u>http://www.rockwellautomation.com/knowledgebase/</u>.

For system requirements, go to <u>http://www.rockwellautomation.com/rockwellsoftware/design/rslogix5000/sysreq.html.</u>

About the Redundancy Module Configuration Tool

You can use 1756-RM2, 1756-RM2XT, 1756-RM, or 1756-RMXT redundancy modules to commission a redundant system. These modules operate in a plug-and-play manner, that is, they can commission a system without any additional programming. However, there is more functionality available if you use the modules with the Redundancy Module Configuration Tool (RMCT).

This enhanced redundancy system revision requires the RMCT, version 8.02.01 that is packaged with this enhanced redundancy system revision bundle. The About screen for the RMCT displays 8.2.1.0 but it's the correct version.

About Re	edundancy Configuration Tool	×
	Redundancy Configuration Tool	ОК
	Version: 8.2.1.0	
	Copyright (c) 2011 Rockwell Automation Technolo All Rights Reserved	gies, Inc.

You can use the RMCT with the redundancy modules to complete these tasks:

- View error diagnostics
- View partnered modules' qualification and compatibility status
- Set Auto-Synchronization parameters
- View and set Chassis ID parameters (Chassis A, Chassis B)
- Identify noncompliant modules for removal
- Configure redundancy system parameters

IMPORTANTThis publication documents Corrected Anomalies and Known Anomalies associated
with the RMCT. We recommend that you read these anomaly descriptions before using
the RMCT, version 8.02.01.Also, if you need to upgrade your RMCT separately from downloading this enhanced
redundancy system revision or by using RSLinx Classic software, version 2.59.00, see
Upgrade the Redundancy Module Configuration Tool on page 48.

Enhancements

These enhancements are provided with enhanced redundancy system, revision 20.055_kit5.

Table 3 - Enhancements Provided with Enhanced Redundancy System, Revision 20.055_kit5

System Component	Enhancement
1756-CN2/C support	The 1756-CN2, 1756-CN2R, 1756-CN2RXT, and 1756-CN2RK modules are available with firmware revision 25.005 in this enhanced redundancy bundle.
1756-EN2F/C support	The 1756-EN2F/C modules are available with firmware revision 10.009 in the enhanced redundancy bundle.

These enhancements have been made in previous firmware revisions.

Table 4 - Enhancements Provided with Enhanced Redundancy System, Revision 20.055_kit4 (or earlier)

System Components	Enhanced Redundancy System Revision	Enhancement
1756-CN2/C support	20.055_kit4	The 1756-CN2, 1756-CN2R, 1756-CN2RXT, 1756-CN2RK modules are available with firmware revision 25.004 in this enhanced redundancy bundle.
1756-RM2 firmware		Upgraded Firmware Revision The 1756-RM2 and 1756-RM2XT modules use firmware revision 20.005 in this enhanced redundancy bundle.
Redundancy Module Configuration Tool		The RMCT has been revised to version 8.02.01.
ControlLogix EtherNet/IP communication module, 1756-EN2TR/C	20.055_kit3	New Module Series and Firmware Revision The 1756-EN2TR/C module, firmware revision 10.007, is available. IMPORTANT: The 1756-EN2TR/C modules do not support firmware revisions previous to revision 10.007. Do not attempt to flash the firmware to previous revisions.
		Product Resiliency Improvement This release includes enhancements that are intended to improve product resiliency to potentially disruptive activities. These enhancements have been verified not to affect product safety, performance, expected life, configuration, or operation of the product. Rockwell Automation advises customers to follow good Industrial Control System (ICS) security practices that include regular product updates. To help ensure authenticity, obtain product updates and new releases directly from Rockwell Automation.
		With the 1756-EN2TR/C module, firmware revision 10.007, message performance is improved over earlier revisions.
ControlLogix EtherNet/IP communication module, 1756-EN2T/D		Upgraded Firmware Revision The 1756-EN2T/D module uses firmware revision 10.007 in this enhanced redundancy bundle.

System Components	Enhanced Redundancy System Revision	Enhancement
ControlLogix EtherNet/IP communication	20.055_kit2	The 1756-EN2T/D module, firmware revision 10.006, is available. IMPORTANT: The 1756-EN2T/D modules do not support firmware revisions previous to revision 10.006. Do not attempt to update the firmware to previous revisions.
module, 1756-EN2T/D		With the 1756-EN2T/D module, firmware revision 10.006, message performance is improved over earlier revisions.
		Product Resiliency Improvement This release includes enhancements that are intended to improve product resiliency to potentially disruptive activities. These enhancements have been verified not to affect product safety, performance, expected life, configuration, or operation of the product. Rockwell Automation advises customers to follow good Industrial Control System (ICS) security practices that include regular product updates. To help ensure authenticity, obtain product updates and new releases directly from Rockwell Automation.
RSLogix 5000		Option to use RSLogix 5000 software, version 20.03.00
Software		RSLogix 5000 software, version 20.03.00 includes enhancements that are intended to improve product resiliency to potentially disruptive activities. These enhancements have been verified not to affect product safety, performance, expected life, configuration, or operation of the product.
		IMPORTANT : For information on upgrading your RSLogix 5000 software project to version 20.03.00, see Rockwell Automation Knowledgebase Answer ID 565204 - RSLogix 5000 Software, Version 20.03, accessible at: http://www.rockwellautomation.com/knowledgebase . (log on is required.)
		We strongly recommend that you read the Knowledgebase article, and the associated documents that are referenced within it, before upgrading your RSLogix 5000 software version.
Redundancy Module Configuration Tool	20.054_kit1	Reduction in scan time of up to 35% per sync point in comparison to the 1756-RM/B module, due to higher 1756-RM2 module speed of up to 1000 Mbps.
(RMCT), 1756-RM2		Redundant fiber ports for the 1756-RM2 module for crossloading; no single point of failure of a fiber cable.
		The redundancy module firmware now reports back to the RMCT about the version of the RMCT it is compatible with. If there is an incompatibility, the RMCT shows only the Module Info tab that indicates the version that the firmware is compatible with.
		A synchronization process that takes a long time (up to 10 minutes, in the case of a PTP configuration error) to complete can be aborted via the Disqualify button in the RMCT. Without this feature, you must abort qualification by taking a manual action, for example, when you cycle power to the secondary chassis or when you remove the redundancy module under power (RIUP).
		There are new causes added for partner compatibility of communication modules that appear in the RMCT Status tab under Compatibility. For example, the primary and secondary partners are not on the same network (the partners must be communicating on the same network to synchronize), or one or both of the partner's keepers are invalid. Update the keepers to valid and matching keeper values.

Table 4 - Enhancements Provided with Enhanced Redundancy System, Revision 20.055_kit4 (or earlier) (Continued)

System Enhanced Components Redundancy System Revision	Enhancement		
1756-L61 1756-L62	20.054	The 375 ms RPI limit has been increased. You can now configure I/O modules to use up to a 750 ms RPI; the same as in a sim sys	
1756-L63 1756-L63XT 1756-L64 1756-L65 1756-L71 1756-L72 1756-L73 1756-L73XT 1756-L74 1756-L75		Beginning with revision 20.054, HMI blind time due to switchover has been reduced. See page HMI Blind Time on page 29.	
1756-L71		Support added for the 1756-L71 controller for redundancy Logix and Redundancy Module Configuration Tool (RMCT).	
1756-EN2F		Support added for the 1756-EN2F in the Redundancy Module Configuration Tool (RMCT).	
1756-EN2T 1756-EN2TR		Sockets are supported in the 1756-EN2T and 1756-EN2TR modules.	
Security		To enhance system and device-level security in systems that use our products, Rockwell Automation prescribes validated, defense-in-depth measures and design practices to enhance system and device-level security. For the latest information on security solutions and enhancements, visit <u>http://www.rockwellautomation.com/solutions/security.</u>	
Redundancy Module Configuration Tool		The redundancy module firmware now reports back to the RMCT about the version of the RMCT that it is compatible with. If an incompatibility exists, the RMCT shows the Module Info tab that indicates the version that the firmware is compatible with.	
(RMCT), 1756-RM		An ongoing synchronization process that takes a long time (up to 10 minutes, in the case of a PTP configuration error) to complete can be aborted via the Disqualify button in the RMCT. Without this feature, you must abort qualification by taking a manual action, such as when you cycle power to the secondary chassis, or when you remove the redundancy module under power (RIUP).	
		There are new causes added for partner compatibility of communication modules that appear in the RMCT Status tab under Compatibility. For example, the primary and secondary partners are not on the same network (the partners must be communicating on the same network to synchronize), or one or both of the partner's keepers are invalid. Update the keepers to valid and matching keeper values.	

Table 4 - Enhancements Provided with Enhanced Redundancy System, Revision 20.055_kit4 (or earlier) (Continued)

Corrected Anomalies

The following sections describe anomalies that are corrected in enhanced redundancy system revisions.

Corrected Anomalies with Revision 20.055_kit5

These anomalies have been corrected in enhanced redundancy system, revision 20.055_kit5.

Table 5 - Corrected Anomalies in Enhanced Redundancy System, Revision 20.055_kit5

Cat. No./System Component	Enhanced Redundancy System Revision	Description
1756-CN2/C 1756-CN2R/C 1756-CN2RXT/C 1756-CN2RK	20.055_kit5	CORRECTED: When the second power supply of a redundant power supply pair powers up, ControlNet interface modules that reside in the same chassis experience an overvoltage condition. The 5V power rail on the interface module briefly exceeds the maximum voltage setting in the Voltage Monitoring System (VMS).
		CORRECTED: The Redundancy System Update feature takes several minutes to report that a secondary module with an earlier firmware revision is paired with a primary module that has more recent firmware.

Corrected Anomalies with Revision 20.055_kit1 or earlier

These anomalies have been corrected in enhanced redundancy system, revision 20.055_kit1 (or earlier).

Table 6 - Corrected Anomalies in Enhanced Redundancy System, Revision 20.055_kit1 (or earlier)

Cat. No./System Component	Enhanced Redundancy System Revision	Description
1756-L61 1756-L62 1756-L63 1756-L63XT 1756-L64 1756-L65 1756-L71 1756-L72 1756-L73 1756-L73XT 1756-L74 1756-L75	20.055_kit1	CORRECTED: When using PowerFlex [™] 750 drives with firmware that supports Drives ADC (Automatic Drive Configuration) on powerup, the controller can become stuck in the transition to Run mode. When stuck in the transition to Run mode, the application is not executing and the outputs are not being updated. For more information, see Knowledgebase document 493802. Also refer to Product Notice 2012-10-004. Lgx00140810, Lgx0130112

Cat. No./System Component	Enhanced Redundancy System Revision	Description
1756-L61 1756-L62 1756-L63 1756-L63XT 1756-L64 1756-L65 1756-L71 1756-L72 1756-L73 1756-L73XT 1756-L74 1756-L75	20.054	CORRECTED: During online editing, an anomaly can occur when testing edits to an SFC routine. Normally, test edits are applied to a test SFC routine and verified before accepting them in the program's logic. When this anomaly occurs, test edits are implemented in the online routine. Despite trying to cancel the online editing operation, when the cancelation option appears to cancel the program edits, the edits are, instead, accepted. There are no workarounds for this anomaly. Lgx00119071

Table 6 - Corrected Anomalies in Enhanced Redundancy System, Revision 20.055_kit1 (or earlier) (Continued)

Cat. No./System Component	Enhanced Redundancy System Revision	Description
	Redundancy	CORRECTED: An anomaly can occur when you nest simultaneous branches in a sequential function chart (SFC) routine as shown below.
		// Unit is ready to Transition Step1_ready.dn and Step2_ready.dn and Step3_ready.dn and Step4_ready.dn and Step5_ready.dn This is the modified expression to workaround this anomaly.
		<pre>// Unit is ready to Transition Step1_ready.x and Step2_ready.x and Step3_ready.x and Step4_ready.x and Step5_ready.x and Step1_ready.dn and Step2_ready.dn and Step3_ready.dn and Step4_ready.dn and Step5_ready.dn IMPORTANT: The x bit is cleared when the chart transitions out of a step.</pre>
		Adding this check to the condition forces the engine to wait until all of those steps are genuinely active before advancing out of the simultaneous branch. Lgx00118189, Lgx00116506

Table 6 - Corrected Anomalies in Enhanced Redundancy System, Revision 20.055_kit1 (or earlier) (Continued)

Cat. No./System Component	Enhanced Redundancy System Revision	Description	
1756-L61 1756-L62	20.054	CORRECTED : Deleting a small rung, such as a rung with just an XIC and OTE, or a rung with a single instruction, such as NOP could cause a controller to experience a Major nonrecoverable fault.	or RES,
1756-L63 1756-L63XT			00124861
1756-L64 1756-L65 1756-L71		CORRECTED : When an alarm instruction is being modified online while it is executing, it can cause the redundancy system t disqualify. The system recovers automatically at a later time.	
1756-L72			:00117401
1756-L73 1756-L73XT 1756-L74		CORRECTED: In some systems with a single periodic task, forced output drops upon redundancy switchover.	00124234
1756-L75		CORRECTED: In some systems where the first scan bit (S:FS) is being analyzed, the first system scans the first scan bit again o scan after a switchover.	n the first
	_	Lgx	00126870
1756-CN2, 1756-CN2R, 1756-CN2RXT, 1756-EN2T, 1756-EN2TR,		CORRECTED: After a switchover is completed, the primary redundancy module incorrectly reports a Synchronized status in 5000 software, and primary ControlNet and Ethernet/IP communication modules report a No Partner status After a successful switchover, these components in the enhanced redundancy system give these indications:	ı RSLogix
1756-EN2TXT, 1756-EN2TXT, 1756-RM, 1756-RMXT		 Primary communication module is PwNS Secondary communication module is DSNP Synchronization Status tab in the RMCT shows Synchronized 	
		These indications on the communication module and Synchronization Status tab incorrectly indicate that a switchover is com a redundancy state change is pending.	plete but
		Typically, the components give these indications when the switchover is, in fact, complete and no state change is pending:	
		 Primary communication module is PwDS Secondary communication module is CMPT Synchronization Status tab in the RMCT shows Disqualified 	
		To force the completion of the pending state change and re-synchronize the redundant chassis pair, cycle power to the secon chassis.	
	-		:00115764
RPI		CORRECTED: In all prior releases for ControlLogix Redundancy, the RPI to an I/O module could not be set greater than 376 ms been enhanced to allow any RPI acceptable for the module being configured.	s. This has
		Lgx	00105642
RSLinx software		 CORRECTED: The following RSLinx software corrections have been made: Upgrading RSLinx software to version 2.59.00 or later, no longer stops the operation of the RMCT. If the RSLinx software v that you are upgrading to includes an older version of the RMCT than what is already installed, then the already-installed version is not affected. Alternatively, if the upgraded RSLinx version included a newer version of the RMCT, then the new version installs automatically on top of the already-installed RMCT version. 	l RMCT RMCT
		The RMCT can be successfully installed without seeing any error messages after the uninstallation of RSLinx software, ver 2.57.00 or later.	
		 With RSLinx software, version 2.57.00 or later, RSLinx software can be downgraded to an older version without any errors example, if you have the RMCT, version 7.02.07 installed while using RSLinx software, version 2.59.00, then you can unin RSLinx version 2.59.00 and successfully install RSLinx software, version 2.57.00. The RMCT, version 7.02.07, is not overwrit the older version of the RMCT that is included in RSLinx software, version 2.57.00. To downgrade the RMCT version as we manually uninstall and reinstall the desired RMCT version by using ADD/Remove Programs in the Control Panel. 	istall itten with
		Lgx	00086040
1756-RM, 1756-RMXT		CORRECTED: Repeated connection and disconnection, or irregular insertion, of the 1756-RM or 1756-RMXT redundancy mo fiber-optic cable results in various fault codes indicated on the module status display.	
		If the 1756-RM or 1756-RMXT redundancy modules' fiber-optic cable is disconnected and connected repeatedly within shor of time, or the cable is inserted slowly at a slight angle to the connector, the redundancy module faults and indicates error co as E0xx or EAxx.	t periods odes such
		To avoid experiencing these faults, wait 510 seconds between disconnecting and connecting the 1756-RM or 1756-RMXT redundancy modules' fiber-optic cable and verify that the insertion is quick and straight into the connector.	
		Lgx00084595, Lgx00113995, Lgx00113954, Lgx	00116055

Table 6 - Corrected Anomalies in Enhanced Redundancy System, Revision 20.055_kit1 (or earlier) (Continued)

Known Anomalies This table lists the known anomalies applicable to the enhanced redundancy system, revision 20.055_kit5 (or earlier).

Table 7 - Known Anomalies in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier)

Cat. No.	Description	
1756-EN2T, 1756-EN2TR, 1756-EN2TXT	You cannot have kits with firmware revisions 10.006 and 10.007 installed on the same computer. If you have firmware revision 10.006 installed and you attempt to install firmware revision10.007, 10.007 generates an error directing to an incorrect .nvs file. Reinstall the desired firmware revision and ignore the error. We recommend using Firmware revision 10.007 because it has corrected anomalies from firmware revision 10.006.	
	Lgx00155450	
1756-CN2, 1756-CN2R, 1756-CN2RXT, 1756-EN2T, 1756-EN2TR, 1756-EN2TXT, 1756-EN2F, 1756-RM, 1756-RMXT, 1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75	Multiple switchovers can cause connection failure to SoftLogix controllers. When a high number of consumed connections are routed through a ControlNet communication module in the primary chassis to a SoftLogix controller, the primary controller reports a connection failure, that is, error code 16#0203. This anomaly occurs despite the fact that there are no network disruptions or device power cycling. Lgx0011551	
1756-EN2T, 1756-EN2TR, 1756-EN2TXT, 1756-EN2F, 1756-L61, 1756-L62. 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75	Connections can drop temporarily if a 1756-EN2Tx communication module is not configured correctly. If your application includes a connection from a remote controller to a primary controller over an EtherNet/IP network, you must use these configuration settings for the 1756-EN2Tx communication module in the primary chassis when it is added to the remote controller's RSLogix 5000 project: • Rack Connection = None • Time Sync Connection = None If the parameters are configured in any other combination, the connection between the remote controller and primary controller is temporarily dropped during a switchover. The connection is re-established after the switchover is complete.	
	IMPORTANT When you add the 1756-EN2T <i>x</i> communication module to the primary controller's RSLogix 5000 project, you can use any settings for the parameters above with no effect on the connection from remote controller to primary controller.	
	Lgx00111615, Lgx00108809, Lgx00109656	
1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75	Redundant chassis synchronization fails when the controller is near its connection limit. Chassis synchronization can fail if the controller is near its connection limits. To reduce the likelihood of this anomaly, verify that you use controller connections within the limits of the controller and that at least eight controller connections are reserved for the redundant system.	
	• The 1756-L6x controllers support as many as 250 controller connections. If your enhanced redundancy system uses these controllers, limit the number of controllers connections used to 242 or fewer connections.	
	 The 1756-L7x controllers support as many as 500 controller connections. If your enhanced redundancy system uses these controllers, limit the number of controllers connections used to 492 or fewer connections. 	
	Lgx00063311	
	Alarms scanned during the continuous task can be published to the alarm server twice after a switchover. If a switchover occurs and a continuous task that contains alarm instructions is scanned twice as a result, a duplicate `out of scope' alarm entry can be indicated in the alarm summary object. To clear `out of scope' entries, click Refresh alarm list.	
	Alarm status messages can be duplicated in the Alarm History Log in the event of a switchover. To make troubleshooting duplicate alarm states easier, consider programming alarms to indicate when a redundant system switchover occurs.	
	Alarms that are acknowledged just before or during a switchover can be indicated as active and unacknowledged after a switchover. If this occurs, acknowledge the alarm a second time.	
	If an alarm is active, then inactive, and a switchover occurs before change in the alarm state is updated to the FactoryTalk server, the FactoryTalk alarm history log can not indicate the change in alarm state.	

Cat. No.	Description
1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75	Alarm parameters can be lost when a switchover occurs. When a switchover occurs in a redundant system that uses alarms, certain alarm parameters can not be transferred to the new primary controller if the parameters have changed since the last crossload of data. Alarm parameters that can not transfer include the following: • DeliveryER • DeliveryEN • NoSubscriber • NoConnection • CommError • AlarmBuffered • SubscNotified
	Once the alarm data is buffered, the parameters are updated. Lgx00093529
	Alarms can fail to be acknowledged when the attempt to acknowledge them occurs during a switchover. If you attempt to acknowledge an alarm while a switchover occurs, a failure to acknowledge the alarm is indicated. Attempting to acknowledge the alarm a second time is successful.
	Lgx00093826
	A Partial Import Online to a primary controller over a ControlNet network can fail if a system switchover occurs while the PIO is still in process. When the anomaly occurs and the PIO fails, you can see any of these errors:
	 Failed to import file 'c\\xxx.L5x Object already exists
	Failed to import file 'c\\xxx.L5x
	Already in request mode/state
	 CIP error: Problem with a semaphore Internal Object Identifier (IOI) destination unknown
	After the switchover completes, restart the PIO with the redundant chassis pair disqualified or synchronized, and the PIO is complete. Lgx00114044, Lgx00113005, Lgx00111045, Lgx00111230
	Inhibiting equipment phase can cause disqualification. If you inhibit an equipment phase, or a task that includes an equipment phase, in a primary controller, the secondary controller is disqualified. This disqualification results from program sequence mismatches between the primary and secondary controllers. Lgx00062035
	When you import a routine to an empty program in a synchronized enhanced redundancy system, disqualification can occur. Lgx00108673
1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75	If tasks are not properly tuned and you execute a large PIO, the primary controller can experience a watchdog fault during the import because the Watchdog parameter is set too low. The fault causes a switchover. When this anomaly occurs, however, once the secondary controller goes online, it shows incorrect data in its fault log. The incorrect data appears in the Task, Program, and Routine fields. The fault log typically shows the following: • Watchdog Fault (Type 06)
	 Task watchdog expired. Can be caused by an infinite loop, a complex program, or a higher priority task. (Code 01) Task: <unknown></unknown> Program: <unknown></unknown>
	Routine: <unknown> You must execute an upload on the secondary controller to obtain correct Task, Program, and Routine watchdog information in the event of a future watchdog fault.</unknown>
	Lgx00108575
	When a program in the primary controller is inhibited or uninhibited, the secondary can disqualify and re-qualify. When changing the Inhibit Program setting, plan for secondary chassis disqualification according to potential implications that are specific to your application. Or, unschedule the program rather than inhibiting it.
	Lgx00090432

Table 7 - Known Anomalies in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier) (Continued)

Cat. No.	Description
1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75	1756-L7x controllers display No Project message during qualification process. While qualification is in process in a system that uses 1756-L7x controllers, controllers in the secondary chassis display No Project in their Scrolling Status Display status indicator. When qualification is complete, the secondary controllers display the name of the project loaded into the primary controller.
	Lgx00115228
ControlNet network	If connecting a redundant controller over ControlNet by using the Controller Log feature, and a switchover occurs, the controller log entries no longer shows the user's name. After the switchover, the user name indicates 'unknown.'
	Lgx00125445

Table 7 - Known Anomalies in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier) (Continued)

Restrictions

This table lists the restrictions applicable to the enhanced redundancy system, revision 20.055_kit5 (or earlier)

Table 8 - Restrictions in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier)

System Component	Description	
1756-EN2T/D	The 1756-EN2T module, series D, cannot be used for SIL2 applications as part of the safety loop. For more information on configurations for SIL2 applications, refer to Using ControlLogix in SIL 2 Applications Reference Manual, publication <u>1756-RM001</u> .	
1756-EN2T/D, 1756-EN2T/C, 1756-EN2TR	The existing 1756-EN2T/D module specification sheets do not list the modules as being SIL2 certified. Policies currently in place by TÜV require that only the 1756-EN2T/C or the 1756-EN2TR modules be used for SIL2 applications as part of the safety loop.	
1756-CN2, 1756-CN2R, 1756-CN2RXT, 1756-CN2RK	1756-CN2/B and 1756-CN2R/B module firmware is not compatible with 1756-CN2/A and 1756-CN2R/A, hardware. You cannot flash series A or B firmware on series C hardware or vice versa. The 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, 1756-CN2RK/C module firmware is not compatible with series A and B hardware. The 1756-CN2/B and 1756-CN2R/B module firmware is not compatible with the 1756-CN2/A or 1756-CN2R/A hardware. Do not attempt to upgrade an 1756-CN2/A or 1756-CN2R/A, module with 1756-CN2/B or 1756-CN2R/B firmware. Attempting to do so results in ControlFlash software displaying a severe incompatibility warning. Series A modules are not supported in redundancy.	
	The 1756-CN2x communication modules provide a maximum of 128 CIP connections for standard (non redundancy) application use. The 1756-CN2x communication modules provide 131 CIP connections. However, three of the 131 CIP connections are always reserved for redundant control. These three redundant-system CIP connections always appear to be in use, even when no connections are open. Because three of the 131 CIP connections are reserved for redundancy, 128 CIP connections are available for nonredundant use. When using the 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, and 1756-CN2RK/C communication modules, you must set the electronic keying option to Disable Keying or Compatible Match because Add-on profiles are not available for these modules.	
1756-EN2T	Do not use 1756-EN2T communication modules, firmware revision 1.004 or earlier, in redundant chassis. 1756-EN2T communication module firmware revision 1.004 is not redundancy-compliant either in standard or enhanced redundancy systems. You must upgrade 1756-EN2T communication modules to firmware revision 5.008 to use this enhanced redundancy system revision.	
1756-EN2T, 1756-EN2TR, 1756-EN2TXT 1756-EN2F	The 1756-EN2x communication modules provide 259 CIP connections. However, three of the 259 CIP connections are always reserved for redundant control. These three redundant-system CIP connections always appear to be in use, even when no connections are open. Because three of the 259 CIP connections are reserved for redundancy, 256 CIP connections are available for nonredundancy use.	
	 You cannot use a 1756-EWEB communication module in an enhanced redundancy system, revision 20.054. If you are migrating from a ControlLogix standard redundancy system to an enhanced redundancy system, you must replace existing 1756-EWEB communication modules with any of the 1756-EN2Tx communication modules Keep in mind that when you replace a 1756-EWEB communication module with a 1756-EN2Tx communication module, your application loses functionality that is available with only the 1756-EWEB communication module. These are examples of functionality that is no longer available in an Enhanced Redundancy System: Simple Network Time Protocol (SNTP) Client Web pages You must account for this lost functionality in your RSLogix 5000 software project. IMPORTANT: You cannot perform online migration from 1756-EWEB communication modules to 1756-EN2T or 1756-EN2TR communication modules. 	
	Lgx00092779 The 1756-EN2Tx communication modules do not support Immediate Output (IOT) instructions. Because these modules do not support the IOT instruction, they cannot override the RPI in a remote chassis and immediately send new data over the EtherNet/IP network.	
1756-L75/A 1756-CN2R/B 1756-RM/B 1756-EN2T/C 1756-EN2TR/B 1756-EN2F	If a qualification fails due to a ControlNet scheduling issue ((29) Qualification Error - Failed Connection Duplication logged in the 1756-RM event logs), the system continuously attempts the qualification and fail. This continues to occur until the cause is addressed or the Auto-Qualification option is changed to Never. The visual symptom is a repetitive display sequence of QFNG/DISQ on the 1756-RM.	

System Component	Description		
1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74, 1756-L75 1756-EN2T, 1756-EN2TR, 1756-EN2TXT 1756-EN2F	A redundant controller project cannot contain consumed Unicast connections. The project can contain produced Unicast tags consumed by remote consumers.		
1756-EN2T, 1756-EN2TR, 1756-EN2TXT, 1756-EN2F,	There are differences between CIP Sync technology in nonredundant systems and enhanced redundancy systems, revision 20.054.		
1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73, 1756-L73XT, 1756-L74,1756-L75	IMPORTANT Before you use this enhancement in an enhanced redundancy system, see these publications for a full understanding of CIP Sync technology in any system: • ControlLogix System User Manual, publication 1756-UM001 • ControlLogix Controllers, Revision 18 Release Notes, publication 1756-RN018 • Integrated Architecture and CIP Sync Configuration Application Technique, publication 1A-AT003		
	 Consider the following when you use CIP Sync technology in an enhanced redundancy system, revision 20.054: If you enable CIP Sync Time Synchronization in the controllers in a redundant chassis pair, you must also enable Time Synchronization in the EtherNet/IP communication modules in the redundant chassis pair so all devices have a single path to the Grandmaster. If time synchronization is enabled in any controller in the primary chassis of a disqualified Redundant Chassis Pair, and no other devices, that is, EtherNet/IP communication modules, in the primary chassis have time synchronization enabled, the redundant chassis pair attempts to qualify. However, in these application conditions, the attempt to qualify fails. While CIP Sync technology can handle multiple paths between master and slave clocks, it resolves mastership most effectively if you configure the redundant chassis pair has three 1756-EN2T communication modules and all are connected to the same network, enable Time Synchronization in only one of the modules. If the primary controller is the Grandmaster, the enhanced redundancy system automatically manages the CIP Sync clock attributes so that the controller in the primary chassis is always set to be the Grandmaster instead of the secondary controller. This clock management ensures a change to a new Grandmaster when the redundancy system switches over. When a switchover occurs, these events take place: The Grandmaster status transfers from the original primary controller to the new primary controller. This transfer can take longer to complete than if Grandmaster status was transferred between devices in a nonredundant system. The synchronization of the enhanced redundancy system complete than when it occurs on a switchover in an enhanced redundancy system (RSU) feature to upgrade an enhanced redundancy system, revision 16.081 or earlier, that uses Coordinated System Time (CST), the enhanced redundancy system and then use RSU to upgrade		

Table 8 - Restrictions in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier) (Continued)

System Component	Description		
1756-L61, 1756-L62, 1756-L63, 1756-L63XT, 1756-L64, 1756-L65, 1756-L71, 1756-L72, 1756-L73,	You can place a maximum of two controllers in the same chassis in a redundant chassis pair. When two controllers are used in the same chassis, they must be of the same product family. For example, you cannot place a 1756-L6x controller with a 1756-L7x controller in the same chassis.		
1756-L73XT, 1756-L74, 1756-L75	Do not use Match Project to Controller property with redundant controllers.		
	online with, download to, or upload from the new primary cor	the Advanced tab of the Controller Properties dialog box, you cannot go troller after a switchover. This is because the serial number of the new old primary controller and the project cannot be matched to the	
	Firmware Supervisor You cannot use the Firmware Supervisor feature available in RS	SLogix 5000 software.	
	Event Tasks		
	You cannot use event tasks in a ControlLogix enhanced redund to nonevent tasks or delete them from your project.	ancy systems. When you enable redundancy, you must change event tasks	
	SERCOS Motion or Integrated Motion on the EtherNet/IP Netwo	ork	
	You cannot use Motion in ControlLogix enhanced redundancy s the same network as a redundancy system.	systems. A remote controller can contain motion instructions even if it is on	
	successful. This causes the redundancy module error log to fill	attempts to requalify the system while the error prevents it from being with the same error condition. If the system is in this condition, the stop this from happening, change the redundancy module synchronization to Never, until the error condition is corrected.	
1756-L61, 1756-L62, 1756-L63,	Update controller firmware from boot firmware can cause main	or nonrecoverable fault.	
1756-L63XT, 1756-L64	We recommend that you upgrade controller firmware in a non firmware revisions listed to higher firmware revisions, execute chassis.	redundant chassis. When you update these controllers from the boot the update with the controller in a nonredundant chassis or primary	
	Controller	Firmware Revision	
	1756-L61, 1756-L62, 1756-L63, 1756-L63XT	1.007 or earlier (boot firmware)	
	1756-L64	1.010 or earlier (boot firmware)	
	If you attempt the firmware update with the controller in a redundant chassis, a major nonrecoverable fault (MNRF) can occur. If the fault does occur, the controller remains in a faulted state until you attempt the firmware update again with the controller in a nonredundant chassis. The label on the side of the controller indicates the series controller and the boot firmware revision.		
	Allen-Bradley LOGIX 5563 PROCESSOR UNIT CATALOG / SERIES 1756-L638	7	
	Complete these steps to upgrade from the boot firmware revision.		
	1. Install the controller in a nonredundant chassis.		
	2. Update the controller firmware.		
	3. Use the controller as necessary in the redundant chassis pair.		
	After you have updated the controller beyond the boot firmware revision, you can perform any additional controller updates in either nonredundant or redundant chassis.		

Table 8 - Restrictions in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier) (Continued)

System Component	Description				
1756-CN2, 1756-CN2R, 1756-CN2RXT, 1756-EN2T, 1756-EN2TR, 1756-EN2TXT 1756-EN2F	System Event Entry contains a module failure event when an enhanced communication module is inserted. The System Event History displays a `Module Failure' entry when you insert a 1756-CN2x communication module or a 1756-EN2x communication module in the chassis while the redundant chassis pair is synchronized. This is not indicative of any module failure; instead, it indicates that only an enhanced communication module was inserted in the chassis.				
1756-RM 1756-RMXT	Under rare conditions, inserting a redundancy module into a running system can cause the redundancy system to switchover or disqualify, and cause the other modules in that chassis to reset themselves. Inserting the module at an angle causes the anomaly. Make sure the module is inserted straight into the chassis without any side-to-side or top-to-bottom movement.				

Table 8 - Restrictions in Enhanced Redundancy System, Revision 20.055_kit5 (or earlier) (Continued)

Appl	lication	Notes
------	----------	-------

Consider these application notes when configuring, programming, and using your ControlLogix enhanced redundancy system revision 20.055_kit5.

Add-on Profile Availability

Add-on Profiles (AOP) offer the most current device configuration options in RSLogix 5000 software. AOPs are available between software releases.

You can download AOPs from:

https://download.rockwellautomation.com/esd/download.aspx?downloadid=a ddonprofiles

TIP	You may need to click on the `>' symbol next to the `Custom Download Files' to expand the AOP list.
	Note: The version listed in the tables is the version of the AOP, not the version of the supported firmware.

You use the RSLogix 5000 Module Profiles Setup Wizard to install the AOP.

IMPORTANT	AOPs are not available for the 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, and
	1756-CN2RK/C communication modules.

Consider the following:

• If your RSLogix 5000 software version does not allow you to configure a device to exactly match the physical device, you must download and install the device's AOP.

For example, if your enhanced redundancy system includes a 1756-EN2T/D module and the software project requires the module be configured with Electronic Keying = Exact Match, you must install the AOP first.

IMPORTANT	When using the 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, 1756-CN2RK/C
	communication modules, you can use the settings Disable Keying or Compatible Match.

• If you cannot download or install an AOP, we recommend that you use Electronic Keying = Compatible Module or Disable Keying until you can.

Maintaining SIL2 Certified Systems

The existing 1756-EN2T/D module specification sheets do not list the modules as being SIL2 certified. Policies currently in place by TÜV require that only the 1756-EN2T/C or the 1756-EN2TR modules be used for SIL2 applications as part of the safety loop.

For more information on configurations for SIL2 applications, refer to Using ControlLogix in SIL 2 Applications Reference Manual, publication <u>1756-RM001</u>.

Out-of-box Switch (888) Behavior

With the 1756-EN2T/D modules, firmware 10.006 or later, the 1756-EN2TR/C modules, firmware revision 10.007, and the 1756-EN2F/C modules with firmware revision 10.009, when the switches are set to 888 to perform an out-of-box reset and the module is installed in a chassis, remember the following:

- 1 The module does not become active on the backplane.
- 2 Other modules do not recognize the module.
- 3 RSLinx Classic software does not recognize the module.
- 4 If the module is installed in the primary chassis of a qualified redundant chassis pair, a switchover does not occur. This item does not apply to 1756-EN2T/A/B/C, 1756-EN2T/A/B, or 1756-EN2F/A/B modules.

Performance Differences between Redundancy Module Series

You cannot mix 1756-RM2 or 1756-RM2XT redundancy modules with 1756-RM/B (or earlier) modules in a RCP. For example, you cannot use a 1756-RM module in the primary chassis and a 1756-RM2 module in the secondary chassis.

When you use a partnered set of 1756-RM2 modules in enhanced redundancy systems, revisions 20.054_kit1 (and later), the fiber channel between the modules can reach speeds as fast as 1000 Mbps.

You can use a mix of 1756-RM module series or 1756-RMXT module series in enhanced redundancy system, revision 20.054 (or later). You can also mix series of RM redundancy modules within a partnered set. For example, you can use a 1756-RM module in the primary chassis and a 1756-RM/B module in the secondary chassis.

Performance Difference with 1756-L65 Controller

With enhanced redundancy system, revision 20.054, the ControlLogix 1756-L65 controller's performance differs from that of the ControlLogix 1756-L64 controller.

For more information, see the ControlLogix Enhanced Redundancy System User Manual, publication <u>1756-UM535</u>.

TIP Your enhanced redundancy system experiences the best scan performance if it uses 1756-L7x controllers with 1756-RM2 modules in the RCP.

EtherNet/IP Networks and Redundant Systems

Some connections to an enhanced redundancy chassis pair can briefly drop if the connection path between the device and the redundant chassis pair is made exclusively over an EtherNet/IP network.

For more information, see <u>Communication Interruption on EtherNet/IP</u> Networks on page 28.

Produced/Consumed Tags between Primary Controllers and Nonredundant Controllers

If controllers in the redundant chassis pair produce tags over an EtherNet/IP network that controllers in remote chassis consume, the connection from the remote controller to the redundant controller can briefly drop during a switchover if the remote chassis' EtherNet/IP communication modules do not use specific firmware revisions.

Use these firmware revisions for EtherNet/IP communication modules in the remote chassis to maintain connections during a switchover.

1756-EN2F	5.008 (unsigned)
	5.028 (signed)
1756-EN2T	
1756-EN2TR	4.002
1756-EN3TR	
1756-ENBT	6.001
1768-ENBT	4.001
1769-L2x	19.011
1769-L3xE	19.011
1788-ENBT	3.001
	1

Table 9 - Minimum Firmware Revision for Communication Modules

In a redundant chassis pair, you can use only the ControlLogix modules listed in Table 1.

Minimum Value for the Watchdog Time

To set Watchdog time for your 1756-L6x controllers, use this table to determine which equation to use to calculate the time for each task.

lf	Then use this equation
Using ControlNet I/O ms	(2 * maximum_scan_time) + 150
Using Ethernet I/O ms	(2 * maximum_scan_time) + 100

The *maximum_scan_time* is the maximum scan time for the entire task when the secondary controller is synchronized.

To set the 1756-L7 initial task tuning, follow these steps.

IMPORTANT This works only when there is no Continuous task configured in the Logix application.

- 1. Monitor the Max Scan Time for each task while the redundant chassis pair is synchronized.
- 2. Set the Watchdog times for each task to 3 times the Max Scan Time.
- 3. Use the Logix 5000" Task Monitor Tool to configure each Task Period. $^{(1)}$
- Adjust the Task periods of each so that the maximum scan time is less than 80% of the task period rate.

Name	Rate	CPU	Priority	Last Scan	Max Scan	Watchdog	Overlap	Stat
al_Main Task	Main Taek 100,000ua 20		10	32,360ua	32,812us	500,000us	D	Runn
Dynamix_Acitator	250,000us	0.00%	10	0	0	250,000us	0	Inhibi
🐼 Pls	20,000us	3.60%	14	872us	34,086us	500,000us	0	Runn
Simulation	100,000us	8.74%	10	20, 150us	20,540us	500,000us	D	Runn
No 5Q3	50,000us	1.08%	13	498us	33,172us	500,000us	0	Runn
UP_Premix_01	100.000us	0.94%	10	2.590us	3.060us	500.000us	0	Rum
UP_Reactor_01	100,000us	00us 0.68% 10 0,376us 3,682us 500,000us 0	0	Runn				
UP_Reactor_02	100,000ua	0.52%	10	4,130us	4,196ua	500,000us	D	Runn
Show Programs >> [<u>></u>
* Max Desired Scan Ri System Overhead Time	7282 SDIA			Eesel Ma	xScar Br	eset Øverløp (iouri 🗖	Log

(1) See the PlantPAx Automation System Reference Manual, publication <u>PROCES-RM001</u>.

- Adjust the Task periods so that the Logix CPU% utilization is never above 75%.
- While performing these tests, the HMI and any other external systems must be connected to the Logix controller.

IMPORTANT Verify that there are no task overlaps.

Synchronizing after Disqualification

If your secondary chassis becomes disqualified, or you manually disqualify it, take these actions before you try to synchronize the chassis:

- Verify that the synchronization status of the primary module is full compatibility.
- Wait at least 15 seconds after the redundant chassis are disqualified before you try to synchronize them.

Different 1756-RM 2, 1756-RM2XT, 1756-RM, or 1756-RMXT Redundancy Module Firmware Revisions


The firmware bundle available for enhanced redundancy system, revision 20.054_kit1 (or later), includes a new electronic data sheet (EDS) file for the 1756-RM2 modules and 1756-RM2XT modules. Enhanced redundancy system, revision 16.081, firmware bundle include an earlier, different EDS file for 1756-RM modules and 1756-RM2XT modules.

Failure to install the new EDS files available in enhanced redundancy system, revisions 20.054_kit1 (or later), firmware bundles prevents the use of RMCT, version 8.02.01.

If you use the EDS files available with enhanced redundancy system, revision 16.081 in an enhanced redundancy system, firmware revision 20.054, 1756-RM2/B modules and 1756-RM2XT/B modules, appears as series A modules in the Device Type column of an RSWho browse screen.

In this case, use the information in the Online Name column to identify your redundancy modules' series level. The information in the Online Name column is accurate.

We recommend that you use the EDS file for redundancy modules that is included with the enhanced redundancy system, revision 20.054_kit1 firmware bundle. With the new EDS file, the RSWho software Device Type column shows a generic 1756-RM device type, as shown in this graphic.



Module Device Type

Module Indication

Communication Interruption on EtherNet/IP Networks

Brief communication interruption occurs if the connection between RSLinx Enterprise software and the redundant chassis pair uses a path exclusively over an EtherNet/IP network and a switchover occurs. After the switchover is complete, communication resumes automatically.

These connection types can experience the communication delay when a switchover occurs:

- HMI to redundant chassis pair
- FactoryTalk Batch server to redundant chassis pair

IMPORTANT	The Batch Server detects the lost connection and repeatedly attempts to re-establish the connection until successful. However, while the connection is lost, the Batch Server puts the recipes, or entire batch, in the held state.
	After the connection between the Batch Server and the redundant chassis pair is re-established, you can clear the communication failure and restart the recipes. The Batch Server keeps the recipes in the held state until the failure is cleared and recipes restarted.

• FactoryTalk Alarms and Events Service to redundant chassis pair

If any alarms are generated while the connection is lost, that data is buffered. When the connection is re-established, you must acknowledge the connection loss.

If your application requires that the connections described above are maintained during a switchover, we recommend that the connection bridge between the component and a redundant chassis pair with an EtherNet/IP network to ControlNet network path.or exclusive ControlNet connection.

IMPORTANT I/O connections do not experience delays when a switchover occurs.

HMI Blind Time

After a switchover, the time between the communication (updating active data) interruption and the restoration (resumes updates) is often referred to as 'HMI Blind Time.'

Beginning with revision 20.054, HMI blind time due to switchover has been reduced.

HMI blind time is dependent on several system variables. Variables that determine this length of time are as follows.

- Operating system
- Quantity and types of tags on scan in RSLinx Enterprise software
- Client screen update rates
- Number of program and controller scope tags in the redundant controller
- Controller loading that includes the following:
 - Number of tasks and scan rates (assumes no continuous task)
 - Memory usage
 - Null task percentage available
 - Network traffic

Based on testing with Windows Server 2003 software, 'HMI Blind Time' was reduced 40...80%. User results varies based on the variables listed above.

Upgrade the RSLogix 5000 Software Version

This section describes how to upgrade your RSLogix 5000 software and, subsequently, the software project, when the following system conditions exist:

IMPORTANT	Before you upgrade your RSLogix 5000 software version, consider the following:					
	 We strongly recommend that you read Rockwell Automation Knowledgebase Answer ID 565204 - RSLogix 5000 Software, Version 20.03, accessible at: <u>http://www.rockwellautomation.com/knowledgebase/</u>. 					
	A login is required to access the article.					
	• Upgrading the RSLogix 5000 software to version 20.03.00 is optional.					
	• If desired, you can continue to use RSLogix 5000 software version 20.01.00.					
	 You cannot install RSLogix 5000 software, revision 20.01.00 and revision 20.03.00, on the same computer simultaneously. 					
	using enhanced redundancy system, revisions 20.055_kit1, kit2, 20.055_kit3, 20.055_kit4, or 20.055_kit5.					
• Your sys	tem is using RSLogix 5000 software and project, version 20.01.00					
• You wan	at to upgrade RSLogix 5000 software to version 20.03.00.					
	take the project offline, that is, the system is not required to e to run during the software upgrade.					
	ystem must continue to run during the software upgrade, you mus Redundancy System Update option. This option is described on					
	following steps to upgrade the RSLogix 5000 software version and enhanced redundancy system.					
IMPORTANT	There are multiple methods available to upgrade the RSLogix 5000 software version i your enhanced redundancy system. The specific tasks required vary by system configuration and requirements.					
	This section describes one of the methods available					

This section describes one of the methods available.

For more information on upgrading your RSLogix 5000 software version, see Rockwell Automation Knowledgebase Answer ID 565204 referenced above.

1. If your RSLogix 5000 project is online, go offline.




- 2. Update the computer to use RSLogix 5000 software, version 20.03.00.
- 3. Upload the project from the primary controller.

File Edit V		View	Search Logic			Communic		
Ē	i 🎬	8	¥	Ē	R	⊮⊃	CH.	
Offlir	ne		0. F	I RU	IN			1
No Fo	orces	<u>G</u> o Online						
 NoEd	►	<u>U</u> plo	ad					
Redu	Redundancy			Download				
B	Contro	ller Org		_				

RSLogix converts the project to version 20.03.00 during the upload.

- **4.** Save the project.
- 5. Download the new project to the controller.



Replace a Module in the Secondary Chassis that has the Same Catalog Number and Firmware Revision

These steps only apply when the primary chassis is at revision 20.055_kit5. These steps are used when performing a direct communication module replacement, for example, when replacing a communication module in the secondary chassis with a module that has the same:

- Catalog number
- Series
- Firmware (after updating the firmware, if necessary)

When you replace communication modules, make sure that the node address (for ControlNet modules), rotary switches, and Port Configuration (for Ethernet modules) match the existing modules.

- 1. Using the Redundancy Module Configuration Tool (RMCT):
 - a. Set Auto-qualification to Never.
 - **b.** Disqualify the redundant chassis pair (if not already disqualified).
- 2. Remove the module from the secondary chassis and replace it with the new module.
- 3. If applicable, update the module firmware by using ControlFLASH.
- **4.** In the RMCT, from the Auto-Synchronization pull-down menu, choose your preferred method.

-Redundancy Module Optio	nc
-Redundancy Module Optio	lis
Auto-Synchronization:	Never 💌
	Never
	Always
Chassis ID:	Condition

5. Manually synchronize the chassis, if needed.

-R	edundancy Commands	
	Synchronize Secondary	
	V2	

Replace 1756-EN2T, 1756-EN2TR, or 1756-EN2F Modules

This section describes how to replace ControlLogix EtherNet/IP communication modules in a ControlLogix enhanced redundancy system.

You can replace EtherNet/IP communication modules in this enhanced redundancy system as follows:

- Replace 1756-EN2T/C (or earlier) modules with 1756-EN2T/D modules.
- Replace 1756-EN2TR/B (or earlier) modules with 1756-EN2TR/C modules.

٠

Replace 1756-EN2F/B (or earlier) modules with 1756-EN2F/C modules.

If you want to replace the Ethernet communication module with the same catalog number and same firmware revision in the secondary chassis then see <u>Replace a</u> <u>Module in the Secondary Chassis that has the Same Catalog Number and</u> <u>Firmware Revision on page 32</u>.

IMPORTANT	The following section describes the requirements and tasks used to replace 1756-EN2T modules with 1756-EN2T/D modules.
	The same requirements and tasks apply when you replace 1756-EN2TR modules with 1756-EN2TR/C modules and when you replace 1756-EN2F/B (or earlier) modules with 1756-EN2F/C modules with the only differences being between specific catalog numbers and series levels.
	For example, before replacing 1756-EN2T modules, make sure you have installed the correct firmware on all 1756-EN2T/D modules.
	The same task applies when you replace 1756-EN2TR modules. That is, before you replace 1756-EN2TR modules, make sure you have installed the correct firmware on all 1756-EN2TR/C modules.

You can replace the 1756-EN2T modules with 1756-EN2T/D by using the following methods:

- <u>Synchronization and Switchover for the 1756-EN2T Modules</u> Use this method if the following conditions exist:
 - The module being replaced is a 1756-EN2T module in a system revision 20.055_kit1, 20.055_kit2, 20.055_kit3, 20.055_kit4, or 20.055_kit5 and Electronic Keying is not set to Exact match.

For more information on this method, see page 34.

- <u>Upgrade the Firmware by Using Redundancy System Update</u> You must use this method if either of the following conditions exist:
 - You are upgrading for an enhanced redundancy system, revisions 19.052, 19.053, 19.053 Oct. 2011, 19.053_kit1, 20.054 Enh, or 20.054 Enh_kit1 to revision 20.055_kit5.

TIP Electronic Keying = Exact Match, Compatible Module, or Disable Keying.

 The module being replaced is a 1756-EN2T module is in a system revision 20.055_kit1, 20.055_kit2, 20.055_kit3, 20.055_kit4, or 20.055_kit5 with Electronic Keying set to Exact Match. You must install the AOP described in Add-on Profile Availability on page 21 for the 1756-EN2T/D module to use Exact Match.

For more information on this method, see <u>Upgrade the Firmware by Using</u> <u>Redundancy System Update on page 46</u>

IMPORTANT	Consider the following:
	 Before replacing 1756-EN2T/C (or earlier) modules, make sure you have installed the correct firmware on all 1756-EN2T/D modules.
	 When you upgrade 1756-EN2T/C (or earlier) modules to 1756-EN2T/D modules, you must do so in pairs. If not the system cannot synchronize after a switchover.
	 Partnered pairs of 1756-EN2T modules must use the same values for the following parameters for IP address swapping to work in the system: IP Addresses Network Mask Gateway address

Synchronization and Switchover for the 1756-EN2T Modules

You can replace 1756-EN2T modules with 1756-EN2T/D modules without using the redundancy system update (RSU) feature if the module being replaced is a 1756-EN2T module in a system at revision 20.055_kit1, 20.055_kit2, 20.055_kit3, 20.055_kit4, or 20.055_kit5.

Complete these steps to replace 1756-EN2T modules with 1756-EN2T/D modules.

- 1. Make sure the existing module and replacement module use the same IP, Network Mask, and Gateway addresses.
- 2. If the Redundancy Module Configuration Tool (RMCT) is not at version 8.02.01, update to version 8.02.01.
- 3. If you are using a 1756-RM2, upgrade the firmware to 20.005.

See <u>About the Redundancy Module Configuration Tool on page 7</u> for instructions.

4. In the RSLogix 5000 software, go online with the primary controller.


5. For each module, verify that the Electronic Keying is set to Compatible Module or Disable Keying.

Module Definition*	
Revision:	5 🔹 8 🚔
Electronic Keying:	Compatible Module
Rack Connection:	Exact Match Compatible Module
Time Sync Connection:	Disable Keying

6. In the RSLinx Classic software, start the RMCT for the 1756-RM module in the primary chassis.



7. On the Configuration tab, from the Auto-Synchronization pull-down menu, choose Never.



8. Click Apply.

9. On the Synchronization tab, click Disqualify Secondary.

1756-RM2 REDUNDANC	Y MODULE
Module Info Configuration	Synchronization Synchronization St
Redundancy Commands	
Synchronize Seconda	Disqualify Se ondary

- 10. Make a note of the secondary Ethernet module's Port Configuration.
 - IP Address
 - Network Mask
 - Gateway Address
- 11. Disconnect the Ethernet cables from the secondary Ethernet module.
- 12. Turn off power to the secondary chassis.
- 13. Remove the 1756-EN2T module from the secondary chassis.
- 14. Set the 1756-EN2T/D module switches to 888, insert the module in the secondary chassis, and turn on power on to the chassis.
 - **a.** After the reset is complete, turn power off to the secondary chassis, remove the module from the secondary chassis.
 - b. Set the switches to the same settings as on the EN2T that was removed.
 - **c.** Reinsert the module into the secondary chassis, reattach the cable and Turn on power to the secondary chassis.
 - d. Bridging across the backplane (or via the Ethernet module's USB port), configure the secondary Ethernet module's Port Configuration to match the Ethernet module's Port Configuration from <u>step 10 on page 36</u>.
 - e. If you have not already updated the firmware of the 1756-EN2T/D, Update the module to firmware revision 10.007
- **15.** Repeat steps <u>10</u>...<u>14</u> for all Ethernet modules in the secondary chassis.
- **16.** Verify that the Synchronization Status tab indicates the modules are fully compatible.

	1 -	ration Synchronization Sync		Event Log System Op	date System Event History
Slot	% Complete	Module Name	Module Revision	Secondary Readiness	State Compatibility
0	100	1756-L75/B LOGIX5575	20.54	Synchronized	Primary Full
1	100	1756-L75/B LOGIX5575	20.54	Synchronized	Primary Full
2	100	1756-CN2R/C	25.4	Synchronized	Primary Full
3	100	1756-CN2R/C	25.4	Synchronized	Primary Full
4	100	1756-CN2R/B	20.20	Synchronized	Primary Full
5	100	1756-CN2R/B	20.20	Synchronized	Primary Full
6	100	1756-CN2R/C	25.4	Synchronized	Primary Full
7	100	1756-CN2R/C	25.4	Synchronized	Primary Full
8		<empty></empty>			
9	100	1756-EN2T/B	5.8	Synchronized	Primary Full
10		<empty></empty>			- [-]
11		<empty></empty>			- \ - /
12	100	1756-RM2/A REDUNDAN	20.5	Synchronized	Primary Full

17. On the Synchronization tab, synchronize the secondary chassis.

TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
Module Info Configuration Synchronization Syn
Redund ancy Commands
Synchronize Secondary Disqualify Se

Wait for synchronization to complete.

18. Initiate a switchover.

1756-RM2 REDUNDANC	Y MODULE				
Module Info Configuration	Synchronization	Synchronization S	itatus Event Lo	g System Up	odate
Redundancy Commands					
Synchronize Seconda	y Disqua	lify Secondary	(Initiat S	witchover)
			\sim	\sim	-

- 19. Disconnect the Ethernet cables from the secondary Ethernet module.
- 20. Turn off power to the secondary chassis.
- 21. Remove the 1756-EN2T module from the secondary chassis.
- **22.** Set the 1756-EN2T/D module switches to 888 and insert it in the secondary chassis and turn on power to the secondary chassis.
 - **a.** After the reset is complete, turn power off to the secondary chassis, remove the module from the secondary chassis.
 - **b.** Set the switches to the same settings as on the EN2T that was removed.
 - c. Reinsert the module into the secondary chassis, reattach the cable and turn on power to the secondary chassis.
 - **d.** Bridging across the backplane (or via the Ethernet module's USB port), configure the secondary Ethernet module's Port Configuration to match the Ethernet module's Port Configuration from <u>step 10 on page 36</u>.
 - e. If you have not already updated the firmware of the 1756-EN2T/D, Update the module to firmware revision 10.007
- 23. Repeat the steps <u>19</u>... <u>25</u> for all ethernet modules in secondary chassis.

24. On the Configuration tab, from the Auto-Synchronization pull-down menu, choose Always.

- Redundancy Module Op	ptions
Auto-Synchronization:	
Chassis ID:	Always

- **25.** Click Apply, Yes, and OK.
- 26. Verify that the secondary chassis has qualified.

Replace 1756-CN2 Modules

This section describes how to replace ControlLogix ControlNet communication modules in a ControlLogix enhanced redundancy system. You can replace ControlNet communication modules 1756-CN2/B, 1756-CN2R/B, and 1756-CN2RXT/B modules with 1756-CN2/C, 1756-CN2R/C, 1756-CN2RXT/C, or 1756-CN2RK/C, modules.

IMPORTANT	ControlNet Communication Modules
	 References to the 1756-CN2/B modules also apply to the 1756-CN2R/B, 1756-CN2RXT/B modules.
	 References to the 1756-CN2/C modules also apply to the 1756-CN2R/C, 1756-CN2RXT/C, 1756-CN2RK/C, modules.
	 Catalog numbers 1756-RM, 1756-RM2, and 1756-RM2XT refer to any series modules.
	The following construction of a silver and an electronic data and a silver of the second se
IMPORTANT	modules with 1756-CN2/C modules.
IMPORTANT	The following section describes the requirements and tasks used to replace 1756-CN modules with 1756-CN2/C modules. The same requirements and tasks apply when you replace 1756-CN2R modules with 1756-CN2R/C modules with the only differences being between specific catalog numbers and series levels.

If you need to replace the ControlNet module with the same catalog number and same firmware revision in the secondary chassis, see <u>Replace a Module in the</u> <u>Secondary Chassis that has the Same Catalog Number and Firmware Revision on page 32</u>.

You can replace the 1756-CN2/B modules with 1756-CN2/C by using the following methods:

- <u>Synchronization and Switchover for the 1756-CN2/B Modules</u> Use this method if the following two conditions are met:
 - the module being replaced is a 1756-CN2/B module that is in a system at revision 20.055_kit1, 20.055_kit2, 20.055_kit3, 20.055_kit4, or 20.055_kit5.
 - if electronic keying is set to disable or compatible module

For more information on this method, see page 40.

- <u>Upgrade the Firmware by Using Redundancy System Update</u> You **must** use this method if either of the following conditions are met:
 - you are upgrading an enhanced redundancy system, revisions 19.052, 19.053, 19.053 Oct. 2011, 19.053_kit1, 19.053_kit2, 20.054 Enh, or 20.054 Enh_kit1 to 20.055_kit4 or 20.055_kit5.
 - the module being replaced is a 1756-CN2/B module that is in a system at revision 20.055_kit1, 20.055_kit2, 20.055_kit3, 20.055_kit4, 20.055_kit5 and the electronic keying set to exact match.

IMPORTANTWhen you upgrade 1756-CN2/B modules to 1756-CN2/C modules, you must do so in
pairs. If not, the system cannot synchronize after a switchover.Replace 1756-CN2/B with 1756-CN2/C, and 1756-CN2RXT/B with 1756-CN2RXT/C
modules.

For more information on this method, see <u>page 46</u>.

Synchronization and Switchover for the 1756-CN2/B Modules

You can replace 1756-CN2/B modules with 1756-CN2/C modules without using the redundancy system update (RSU) feature if the following conditions exist:

• The module being replaced is a 1756-CN2/B module that is in a system at revision 20.055_kit1, 20.055_kit2, 20.055_kit3, 20.055_kit4, or 20.055_kit5.

Complete these steps to replace 1756-CN2/B modules with 1756-CN2/C modules.

- 1. Add the EDS files for the Revision 25 1756-CN2/C modules, if you have not already done so.
- 2. Make sure the existing module and replacement module use the same ControlNet node address.
- **3.** If the Redundancy Module Configuration Tool (RMCT) is not at version 8.02.01, update to version 8.02.01.
- 4. If you are using a 1756-RM2, upgrade the firmware to 20.005.
- 5. Using RSLogix 5000 software, go online with the primary controller.
- **6.** For each 1756-CN2/B module, verify that Electronic Keying is set to Compatible Module or Disable Keying.

Module Definition*	
Revision:	5 🔹 8 🚔
Electronic Keying:	Compatible Module
Rack Connection:	Exact Match
Time Sync Connection:	Compatible Module Disable Keying

7. In the RSLinx Classic software, start the RMCT for the 1756-RM or 1756-RM2 module in the primary chassis.



- a. Start RSLinx Classic Software.
- b. Select Communications and choose RSWho.
- **c.** Open the branches of your network until you find the 1756-RM or 1756-RM2 module in the primary chassis.
- **d.** Right-click the 1756-RM or 1756-RM2 module, and choose Module Configuration.
- **8.** On the Configuration tab, from the Auto-Synchronization pull-down menu, choose Never.

篇 1	1756-RM2	REDUNDANC	Y MODULE	
Mo	odule Info	Configuration	Synchronization	Synchro
Г	Redundar	ncy Module Opt	ions	
	Auto-Syno	chronization:	Always	•
Chassis ID:		Never Always Conditional		
				[

- 9. Click Apply and then Yes.
- **10.** On the Synchronization tab, click Disqualify Secondary and then click Yes.

1756-RM2 REDUNDANC	Y MODULE	
Module Info Configuration	Synchronization	Synchronization St
- Redundancy Commands		
Synchronize Seconda	Disqua	lify Selondary

- 11. Turn off power to the secondary chassis.
- 12. Remove the 1756-CN2/B modules from the secondary chassis.
- **13.** Make sure that the node addresses of the replacement ControlNet modules match the existing modules.
- 14. Insert each 1756-CN2/C module into the secondary chassis, reconnect the module to the network, and turn on power to the chassis.

- 15. If you have not already updated the firmware of the 1756-CN2/C modules, use the ControlFlash update tool to update the firmware of each 1756-CN2/C module in secondary chassis.
- **16.** Verify that the Synchronization Status tab indicates the modules are fully compatible.

	nilo conilga	ration Synchronization Sync	nronization Status	Event Log System Up	date Sys	stem Event History
Slot	% Complete	Module Name	Module Revision	Secondary Readiness	State	Compatibility
0	100	1756-L75/B LOGIX5575	20.54	Synchronized	Primary /	Full
1	100	1756-L75/B LOGIX5575	20.54	Synchronized	Primary	Full
2	100	1756-CN2R/C	25.4	Synchronized	Priman	Full
3	100	1756-CN2R/C	25.4	Synchronized	Primary	Full
4	100	1756-CN2R/B	20.20	Synchronized	Primary	Full
5	100	1756-CN2R/B	20.20	Synchronized	Primary	Full
6	100	1756-CN2R/C	25.4	Synchronized	Primary	Full
7	100	1756-CN2R/C	25.4	Synchronized	Primary	Full
8		<empty></empty>			- 1	
9	100	1756-EN2T/B	5.8	Synchronized	Primary	Full
10		<empty></empty>			[
11		<empty></empty>			- 1	
12	100	1756-RM2/A REDUNDAN	20.5	Synchronized	Primary	Full

17. On the Synchronization tab, synchronize the secondary chassis.

🖀 1756-RM2 REDUNDANC	
Module Info Configuration	Synchronization Synch
Redundancy Commands	`
Synchronize Secondar	Disqualify Sec

Wait for synchronization to complete.

18. Initiate a switchover.

E 1756-RM2 REDUNDANCY MODULE	
Module Info Configuration Synchronization	n Synchronization Status Event Log System Update
Redundancy Commands	
Synchronize Secondary Disq	ualify Secondary

- **19.** Turn off the power to secondary chassis and then remove the 1756-CN2/B modules from the secondary chassis.
- **20.** Make sure to match the node address of replacing the ControlNet module with existing module.
- **21.** Insert each 1756-CN2/C module into the secondary chassis, reconnect the module to the network, and turn on power to the chassis.
- 22. If you have not already updated the firmware of the 1756-CN2/C, modules, use ControlFLASH to update the firmware of each 1756-CN2/C module in secondary chassis.

23. In the RMCT, from the Auto-Synchronization pull-down menu, choose your preferred method.

- Redundancy Module Options				
Auto-Synchronization:	Never			
	Never			
Chassis ID:	Always Condition			

24. Manually synchronize the chassis, if needed.

-R	edundancy Commands ——	
	Synchronize Secondary	

- 25. Click Apply, Yes, and OK.
- 26. Verify that the secondary chassis has qualified.

Upgrade the RSLogix 5000 Software Version and Replace 1756-EN2T, 1756-EN2TR or 1756-CN2

This section describes how to upgrade your RSLogix 5000 software and, subsequently, the software project, and also replace ControlLogix EtherNet/IP or ControlNet communication modules in your enhanced redundancy system. when the following system conditions exist:

- You are using enhanced redundancy system, revision 20.055_kit5.
- Your system is using RSLogix 5000 software and project, version 20.01.00.
- You want to upgrade RSLogix 5000 software to version 20.03.00.

IMPORTANT	Before you upgrade the RSLogix 5000 software version on your computer, consider the following:
	 We strongly recommend that you read Rockwell Automation Knowledgebase Answer ID 565204 - RSLogix 5000 Software, Version 20.03, accessible at: <u>http://www.rockwellautomation.com/knowledgebase/</u>. A login is required to access the article.
	• Upgrading the RSLogix 5000 software to version 20.03.00 is optional.
	 If desired, you can continue to use RSLogix 5000 software version 20.01.00.
	 You cannot install RSLogix 5000 software, revision 20.01.00 and revision 20.03.00, on the same computer simultaneously.

- You want to perform one of the following module replacements:
 - Replace 1756-EN2T/C (or earlier) modules with 1756-EN2T/D modules
 - Replace 1756-EN2TR/B (or earlier) modules with 1756-EN2TR/C modules
 - Replace 1756-EN2F/B modules with 1756-EN2F/C modules
 - Replace 1756-CN2/B modules with 1756-CN2/C modules

Complete the following steps to upgrade the RSLogix 5000 software version and project in your enhanced redundancy system.

IMPORTANT	There are multiple methods available to upgrade the RSLogix 5000 software version in your enhanced redundancy system. The specific tasks required vary by system configuration and requirements.
	This section describes one of the methods available.
	For more information on upgrading your RSLogix 5000 software version, see Rockwell Automation Knowledgebase Answer ID 565204 referenced above.


1. If your RSLogix 5000 project is online, go offline.



- 2. Update the computer to use RSLogix 5000 software, version 20.03.00.
- 3. Upload the project from the primary controller.



- 4. Convert the project to version 20.03.00 and save it.
- 5. Download the new project to the controllers and resume normal operation.



- 6. Use one of the methods described in <u>Replace 1756-EN2T, 1756-EN2TR</u>, or 1756-EN2F Modules on page 33 to replace the ControlLogix EtherNet/IP communication modules.
- Use one of the methods described in <u>Replace 1756-CN2 Modules on</u> page 39 to replace the ControlLogix ControlNet communication modules.

Upgrade the Firmware by Using Redundancy System Update

You can upgrade an enhanced redundancy system revision to another while your process continues to run. This is known as Redundancy System Update (RSU).

IMPORTANT	Remember the following before using this section:
	 RSU is available when upgrading only from an enhanced redundancy system revision to another. You cannot use this process to upgrade from a standard redundancy system to an enhanced redundancy system.
	 You can upgrade only from firmware revision 19.052 or later, to firmware revision 20.055.
	Therefore, if you are not upgrading from ControlLogix enhanced redundancy system, revision 19.052 or later, ignore this section.
	 The term 1756-RM is synonymous with 1756-RM2 in the text and graphics throughout this section.
	 You must use this process if the following conditions exist: You are upgrading from an enhanced redundancy system, to revision 20.055_kit5. Your RSLogix 5000 software project requires EtherNet/IP modules to use Electronic Keying = Exact Match.
	You must install the AOP described on <u>page 21</u> for the 1756-EN2T/D, 1756-EN2TR/C, or 1756-EN2F/C modules to use Exact Match.

Complete the steps in this table to upgrade your redundancy system from one **enhanced** redundancy system revision to another **enhanced** redundancy revision while your process continues to run.

Task	Page
Before You Begin	47
Upgrade the Workstation Software	48
Upgrade the Redundancy Module Configuration Tool	48
Verify Your RMCT Version	49
Add the EDS Files	50
Prepare the Redundant Chassis for the Firmware Upgrade	50
Update the Primary Chassis 1756-RM2, 1756-RM2XT, 1756-RM, or 1756-RMXT Redundancy Module Firmware	52
Upgrade the Secondary 1756-RM2, 1756-RM2XT, 1756-RM, or 1756-RMXT Redundancy Module Firmware and All Other Modules' Firmware in the Secondary Chassis	53
Prepare the RSLogix 5000 Project for the Upgrade	58
Lock the System and Initiate a Switchover to Upgrade	60
Upgrade the New Secondary Chassis Firmware	62
Synchronize the Redundant Chassis	64

Before You Begin

Consider these points before you begin upgrading your enhanced redundancy system to a new revision:

- During the upgrade procedures, you cannot use RSLogix 5000 software to change the mode of the controller. Instead, use the mode switch on the front of the controller.
- Leave RSNetWorx for ControlNet software closed or offline throughout this procedure. If the software is open or online, you see errors in the RSNetWorx for ControlNet software during the upgrade process.
- Remember the following when completing the tasks described in the rest of this section:
 - Do not make any changes to the RSLogix 5000 project other than those identified in these tasks.
 - Verify that no one is making changes to the project.
 - Do not use a FactoryTalk Batch Server to change equipment phase-states when upgrading your enhanced redundancy system.

Download and Install the Redundancy Firmware Bundle

Download and install the redundancy firmware revision bundle from the Rockwell Automation Support website at: http://www.rockwellautomation.com/support/

Follow these steps.

- 1. From the Get Support Now menu, click the Downloads link.
- 2. Under Additional Resources, click Firmware Updates.
- 3. Click Control Hardware.
- 4. Click the 1756-Lxx Enhanced Redundancy Bundle file.

The Flash Firmware Updates window appears.

- 5. Enter your Serial Number.
- 6. Click Qualify For Update.
- 7. Click Finish when the Qualified For Update window appears.
- **8.** Download the zipped file.
- 9. Install the Redundancy Firmware Bundle.

Upgrade the Workstation Software

Before you download and upgrade software for your redundant system, use one of these methods to fully shut down RSLinx Classic software:

• Right-click the RSLinx Classic icon in the notification area of the screen and choose Shutdown RSLinx Classic.



• With RSLinx Classic software open, from the File menu, choose Exit and Shutdown.



Install the software required for your redundant system configuration. See <u>Compatible Software Versions on page 6</u> for software versions required for use with this enhanced redundancy system revision.

Use the installation instructions or release notes provided with each software version for installation procedures and requirements.

Upgrade the Redundancy Module Configuration Tool

The RMCT, version 8.02.01, is included in the enhanced redundancy system, revision 20.055_kit5 bundle. Once this bundle is installed, you can use the RMCT, version 8.02.01.


Verify Your RMCT Version

Complete these steps to check or verify the version of the RMCT you have installed.

- 1. Launch RSLinx Classic software.
- 2. Click the RSWho icon.




3. Right-click your redundancy module and choose Module Configuration.



The Module Configuration dialog box opens.

4. Right-click the title bar and choose About.



 About Redundancy Configuration Tool

 Redundancy Configuration Tool

 Version:
 8.2.1.0

 Copyright (c) 2011 Rockwell Automation Technologies, Inc. All Rights Reserved

The About dialog box opens and indicates the RMCT version.

TIP

The RMCT launches at the version that is compatible with the 1756-RM or 1756-RMXT redundancy module firmware that is currently installed.

If you upgrade your RMCT version but do not upgrade your 1756-RM or 1756-RMXT redundancy module firmware revision compatible with the new RMCT version, the About dialog box can not reflect the new RMCT version.

Add the EDS Files

If needed, obtain EDS files for modules in your system from the Rockwell Automation website at: http://www.rockwellautomation.com/resources/eds/.

- 1. Once you have downloaded the required EDS file, launch the EDS Hardware Configuration Tool.
- 2. Choose Start > Programs > Rockwell Software > RSLinx Tools > EDS Hardware Installation Tool.

The tool then prompts you to Add or Remove EDS files.

Prepare the Redundant Chassis for the Firmware Upgrade


Complete these steps to prepare both the primary and secondary redundant chassis for redundancy firmware upgrades.

1. Set the mode switch of the primary and secondary controllers to REM.

If the redundant controllers in both chassis of the redundant chassis pair are not in Remote Program (REM) mode, the redundancy firmware upgrade cannot be completed.

2. Open RSLinx Classic software and browse to the redundancy module.

3. Right-click the redundancy module and choose Module Configuration to open the RMCT.



- 4. Click the Configuration tab in the RMCT.
- 5. From the Auto-Synchronization pull-down menu, choose Never.


Module Info	Configuration	Synchronization	Synch	nronization Status	Event Log	System Update	Syste
– Redunda	ncy Module Opt	ions					
	,						
Auto-Syn	chronization:	Always	•	Serial Number:			
		Never Always	h	Name:			
Chassis II):	Conditional	_ľ				
				Description:			

- 6. Click Apply, and then click Yes.
- 7. Click the Synchronization tab.

Module Info Configuration	Synchronization	Synchronization Stat
Redundancy Commands		
Synchronize Secondar	y Disqua	lify Secondary

8. Click Disqualify Secondary, and then click Yes.

The secondary chassis is disqualified as indicated by the RMCT at the bottom-left of the RMCT and on the redundancy module's status display.



9. Click OK and close the RMCT.


Closing the RMCT helps prevent a timeout from occurring when the redundancy module's firmware is upgraded.


Update the Primary Chassis 1756-RM2, 1756-RM2XT, 1756-RM, or 1756-RMXT Redundancy Module Firmware

Wait at least 45 seconds before you begin updating the 1756-RM firmware. During this time, the redundancy module conducts internal operations to prepare for an upgrade.

Complete these steps to upgrade the firmware of the 1756-RM module in the primary chassis.

- 1. Launch ControlFLASH software and click Next.
- 2. Select the redundancy module catalog number and click Next.






3. Browse to the module and select it.

- 4. Click OK.
- 5. Select the firmware revision to upgrade to and click Next.
- 6. Click Finish.

The firmware begins to update. When the update is complete, the Update status dialog box indicates completion.



Upgrade the Secondary 1756-RM2, 1756-RM2XT, 1756-RM, or 1756-RMXT Redundancy Module Firmware and All Other Modules' Firmware in the Secondary Chassis

Power on the secondary chassis. Wait at least 45 seconds before you begin updating the secondary chassis firmware. During this time, the redundancy module conducts internal operations to prepare for an upgrade.

Complete these steps to upgrade the firmware in the secondary chassis.

- 1. Complete the following steps for each module in the secondary chassis, including a new controller, if applicable.
- 2. If you are replacing or upgrading your module hardware, remove the module from the secondary chassis and replace it with the new module.

IMPORTANTWhen replacing communications modules, make sure that the node address
(for ControlNet modules), rotary switches, and Port Configuration (for
Ethernet modules) match the existing modules.

If you are replacing a controller, use this table to determine if your planned primary and secondary controllers can be used together in the redundant chassis.

Table 10 - Controller Compatibility

Primary Controller	Compatible Secondary Controller
1756-L61	1756-L61, 1756-L62, 1756-L63, 1756-L64, 1756-L65
1756-L62	1756-L62, 1756-L63, 1756-L64, 1756-L65
1756-L63	1756-L63, 1756-L64, 1756-L65
1756-L64	1756-L64, 1756-L65
1756-L65 ⁽¹⁾	1756-L65
1756-L71	1756-L71, 1756-L72, 1756-L73, 1756-L74, 1756-L75
1756-L72	1756-L72, 1756-L73, 1756-L74, 1756-L75
1756-L73	1756-L73, 1756-L74, 1756-L75
1756-L74	1756-L74, 1756-L75
1756-L75	1756-L75

(1) In the ControlLogix enhanced redundancy system, revision 19.052, the ControlLogix 1756-L65 controller's performance differs from that of the ControlLogix 1756-L64 controller.

For more information, see the ControlLogix Enhanced Redundancy System User Manual, publication <u>1756-UM535</u>.

IMPORTANT Controller compatibility is the same for the XT controllers as the standard controllers.

3. Consider these important steps in this table.

IMPORTANT	 Continue with <u>step 12 on page 55</u>, if you are upgrading from a system using revision 19.052, 19.053, 19.053 Oct 2011, or 19.053_kit1, and you are either:
	 Updating 1756-EN2T/C (or earlier) modules with 1756-EN2T/C (or earlier) modules and the modules being replaced have rotary switches set to 2254.
	Replacing 1756-EN2T/C (or earlier) modules with EN2T/D modules, and the modules being replaced have rotary switches set to 2254.

4. Launch ControlFLASH software and click Next.

	Enter the catalog number of the target devic 1756-RM/B	e:
Control FLASH	1756-0B16IS7A 1756-0B32/A 1756-0B8/A 1756-0C8/A 1756-0C8/A 1756-0R8/A 1756-0R8/A 1756-0N8/A 1756-0N8/A 1756-FM/A 1756-FM/B 1756-SYNCH 1756-SYNCH 1768-L43 1758-L45	
	<back next=""> Cancel</back>	Help


5. Select the module catalog number and click Next.

6. Browse to the module and select it.



- 7. Click OK.
- 8. Select the firmware revision to upgrade to and click Next.
- 9. Click Finish.

The firmware begins to update. When the update is complete, the Update status dialog box indicates completion.



- 10. Repeat $\underline{\text{steps 2}}$...9 for the next module in the chassis.
- 11. If this is the last module continue to <u>Prepare the RSLogix 5000 Project for</u> the Upgrade on page 58.
- **12.** Make a note of the **primary** Ethernet module's Port Configuration including the following:
 - IP Address
 - Network Mask

Gateway Address

General Port Configuration					
Network Configuration Type —					
 Static 	0	Dynamic			
 Use DHCP to obtain netw Use BOOTP to obtain net 		~			
IP Address:	192	. 168	. 1	. 41	
Network Mask:	255	. 255	. 25	5.0	
Gateway Address:	0	. 0	. 0	. 0	
Primary Name	0	. 0	. 0	. 0	
Secondary Name	0	. 0	. 0	. 0	
Domain Name:					
Host Name:					
🔽 Auto-negotiate port spee	d and du	plex			
Current Port Speed:	100				-
Current Duplex:	Full dupl	ex			-
(Changes to Port Speed and	Duplex r	equire m	odule res	et.)	
Status: Network Interfa	ce not Co	onfigured			_
OK Can	icel	Αŗ	pply	Help)

- 13. Disconnect the Ethernet cables from the secondary Ethernet module.
- 14. If a 1756-EN2T/D module is the replacement module, then set the 1756-EN2T/D module switches to 888 and insert it in the secondary chassis.
- 15. After the reset is complete, remove the module from the secondary chassis.
- **16.** If a 1756-EN2T/C module is being updated, remove the 1756-EN2T/C from the secondary chassis.
- 17. Set the switches to 999 and reinsert the module into the secondary chassis.
- **18.** Bridging across the backplane (or via the Ethernet module's USB port), configure the **secondary** Ethernet module's Port Configuration to match the **primary** Ethernet module's Port Configuration from <u>step 12</u>.


19. Confirm the **secondary** 1756-EN2T/D module is at firmware revision 10.007 or that the EN2T/C (or earlier) module is at firmware version 5.008.

If necessary, complete the following steps to update module firmware.

- a. Launch ControlFLASH software and click Next.
- **b.** Select the Ethernet module catalog number and click Next.


Catalog Number	Enter the catalog number of the target device:	
	1756-EN2T	
Control FLASH	1715-AENTR 1756-CN2/B 1756-CN2/VB 1756-EN2F 1766-EN2TR 1756-EN3TR 1756-EN3TR 1756-HYD02 1756-IA16/A 1756-IA16/A 1756-IA8D/A 1756-IB16/A 1756-IB16/A 1756-IB16/A	
	<back next=""> Cancel</back>	Help

c. Browse to the module and select it.



- d. Click OK.
- e. Select the firmware revision to upgrade to and click Next.
- f. Click Finish.

The firmware begins to update. When the update is complete, the Update status dialog box indicates completion.



Wait for the update to complete.

- **20.** After the update completes, connect the Ethernet cable to the secondary Ethernet module, and wait for communication to resume on the network.
- **21.** Check the Synchronization tab in the RMCT to verify that compatibility is Full for all communication modules in the chassis.

odule	Info Configu	ration Synchronization Synchronization	Status Event Log	System Update Syste	em Event I	History
Slot	% Complete	Module Name	Module Revision	Secondary Readiness	State	Compatibility
0	100	1756-L73/A LOGIX5573	20.55	Synchronized	Primary	Full
1	100	1756-EN2TR/C 217021900	10.7	Synchronized	Primary	Full
2	100	1756-CN2R/C	25.4	Synchronized	Primary	Full
3	100	1756-RM2 REDUNDANCY MODULE	20.4	Synchronized	Primary	Full

22. Repeat <u>steps 2...21</u> for the next module in the chassis.

Once you have either replaced or upgraded the firmware for each module in the secondary chassis, prepare the RSLogix 5000 project for the upgrade.

Prepare the RSLogix 5000 Project for the Upgrade

Complete these steps to prepare the RSLogix 5000 program and controllers for the upgrade.

- 1. Launch RSLogix 5000 software and go online with the primary controller.
- 2. Verify that the watchdog time is set to a value that corresponds with the requirements of the enhanced redundancy system revision and your application.


See <u>Minimum Value for the Watchdog Time</u> on <u>page 25</u> for information about calculating the minimum watchdog time.

- 3. Cancel or assemble any pending test edits.
- 4. Remove all Sequential Function Chart (SFC) forces from the project.
- 5. Verify that no changes need to be made to the following:
 - I/O forces
 - I/O configuration

After this step, changes to I/O cannot be made until after the enhanced redundancy system revision upgrade is complete and both chassis are synchronized.

- **6.** Configure the controllers and communication modules in the redundant chassis pair as necessary.
- 7. Save the project.

8. Go offline.



9. Click Controller Properties.

10. Click Change Controller.

ľ	🕺 Controller Properties - Enhanced_Redundancy					
	File	Redundancy	Nonv	platile Memory	Memory	Security
	General	Major Faults 1	Minor Faults	Date/Time	Advanced	SFC Execution
	Vendor: Allen-Bradley					
	Type:	ype: 1756-L75 ControlLogix5575 Controller				Change Controller
	Revision:	20.11			_	

- 11. Specify the controller revision you are upgrading to.
- **12.** If you installed a new controller while upgrading the primary chassis firmware, specify the new controller catalog number.
- 13. Click OK.
- 14. Access the Module Properties for each communication module in the chassis and specify the module firmware revision you are upgrading to.

New Module General* Connection Type: 1756-EN2T 1756 10/100 Mbps Ethernet Bridge, Twis Vendor: Allen-Bradley Parent: Local Name: ENET_mod Description: Image: Ima	ed-Pair Media Ethernet Address Private Network: 192168.1. IP Address: Host Name: Nodule Definition Slot: 2 Revision: Electronic Keying: Rack Connection: I	Image: Cancel Help
Status: Creating	OK Cancel Help	

TIP

If you are unable to specify the new revision, you need to change the Electronic Keying parameter to Compatible Keying.

- 15. Save the project.
- 16. Download the project to the secondary controller.

The secondary controller is at the higher network address of the two available for the redundant chassis.

Offline	I. RUN
No Forces	<u>G</u> o Online
No Edits	<u>U</u> pload
Redundancy	Download
Controller Redun	Program Mode

17. After the download is complete, go offline.


You are now ready to lock the system and initiate a locked switchover to update the primary chassis. Continue with <u>Lock the System and Initiate a Switchover to</u> <u>Upgrade</u>.

Lock the System and Initiate a Switchover to Upgrade

Once you have downloaded the RSLogix 5000 project you prepared, complete these steps to lock your system and initiate a switchover.

IMPORTANT	Remain offline while completing these steps.
	 Once you have locked the system, do not abort the system lock. Aborting the system lock during this procedure clears the project from the secondary controller.
	• Do not disconnect any communication cables while completing these steps.
	 Completing a locked switchover causes SFC instructions to be reset to their initial state. This can result in SFC instructions executing twice.

1. In RSLinx Classic software, right-click the 1756-RM or 1756-RMXT redundancy module in the primary chassis and choose Module Configuration to open the RMCT.



Module Info Configuration Synchronization S	nchronization Status Event Log System I	Update Bystem Event History	
Lock For Update	Abort System Lock	Initiate Locked Switchover	

2. Click the System Update tab.

- 3. Click Lock For Update, and then click Yes.
- 4. Wait for the system to lock.

The System Update Lock Attempts log indicates when the system lock is complete.




5. Click Initiate Locked Switchover, and then click Yes.



This step results in your secondary chassis assuming control and becoming the primary chassis. When the switchover is complete, the Locked Switchover Attempts log indicates success.

 N 6/2/2009 22:47:21:032 Success Locked switchover completed at : 6/2/2009 22: N-1 — Not attempted — N-2 — Not attempted — 	
	:47:21:035
N-2 — Not attempted —	
14c Horodeniped	
N-3 — Not attempted —	

In addition to the log, the text in chassis status row indicates the switchover state.



Once your locked switchover is complete, upgrade the firmware revisions for modules in the new secondary chassis.


IMPORTANT	Following the locked switchover, secondary controllers no longer contain a user application and their configuration settings are reset to the factory-default settings.
	The new secondary controllers use the default settings and the components in the secondary chassis are upgraded and the system is synchronized.

Upgrade the New Secondary Chassis Firmware

IMPORTANT	Update the Gateway address of the primary chassis ethernet module to 192.168.1.1, if you are upgrading from a system using revision 19.052, 19.053, 19.053 Oct 2011, or
	19.053_kit1, and Electronic Keying is set to Exact Match, Compatible Module or Disable Keying and you are either:
	a. Updating 1756-EN2T/C (or earlier) modules with 1756-EN2T/C (or earlier) modules, and the modules being replaced have rotary switches set to 2254.
	 Replacing 1756-EN2T/C (or earlier) modules with EN2T/D modules, and the modules being replaced have rotary switches set to 2254.

Complete these steps to upgrade the firmware of all of the modules in the new secondary chassis, except for the 1756-RM or 1756-RMXT redundancy module that was already upgraded as described in <u>Update the Primary Chassis</u>. 1756-RM2, 1756-RM2XT, 1756-RM, or 1756-RMXT Redundancy Module. Firmware on page 52.


- 1. If you are replacing and upgrading your module hardware, remove the module from the secondary chassis and replace it with the new module.
 - TIPWhen replacing communications modules, make sure that the node address
(for Control net modules), rotary switches, and Port Configuration (for
Ethernet modules) match the existing modules.
- 2. If it is an Ethernet module:
 - **a.** Make a note of the rotary switch setting on the modules that you are replacing.
 - **b.** Set rotary switches on the replacement module to 888 and insert the module into the chassis.
 - c. After reset completed, remove the module.
 - d. Set the rotary switches to original values that you noted in step a.
 - e. Insert the module.
 - **f.** Go into the module properties and restore the values that you noted in <u>step 12 on page 55</u>.
- 3. Launch ControlFLASH software and click Next.



4. Select the module catalog number and click Next.

- 6. Click OK.
- 7. Select the firmware revision to upgrade to and click Next.
- 8. Click Finish.

The firmware begins to update. When the updated is complete, the Update status dialog box indicates completion.




9. Complete steps <u>1</u>...<u>8</u> for each module in the new secondary chassis, including the new controllers, if applicable.

Once you have either replaced or upgraded the firmware for each of the modules in the new secondary chassis, continue by synchronizing the redundant chassis.

Synchronize the Redundant Chassis

Complete these steps to synchronize the redundant chassis after firmware in both chassis have been upgraded to the same revision.

1. In RSLinx software, right-click the 1756-RM or 1756-RMXT module in the primary chassis and choose Module Configuration to open the RMCT.



- a. Updating 1756-EN2T/C (or earlier) modules with 1756-EN2T/C (or earlier) modules, and the modules being replaced have rotary switches set to 2...254.
- b. Replacing 1756-EN2T/C (or earlier) modules with EN2T/D modules, and the modules being replaced have rotary switches set to 2...254.
- 2. On the Synchronization tab, synchronize the secondary chassis.

1756-RM2 REDUNDANCY MODULE					
Module Info Configuration	Synchronization Synch				
Redundancy Commands	`				
Synchronize Secondar	y Disqualify Sec				

Wait for synchronization to complete.

<u>Steps 3...7</u> are only applicable if the ethernet switches are set between 2...254.

3. Initiate a switchover.

🔚 1756-RM2 REDUNDANC	Y MODULE			
Module Info Configuration	Synchronization	Synchronization Statu	us Event Log	System Update
Redundancy Commands - Synchronize Secondar	y Disqua	lify Secondary	Initiat Switc	hover
				\geq

- 4. In the new secondary, set the rotary switches back to the original configuration.
- 5. Repeat this for all Ethernet modules that need the rotary switches set back to 2...254.
- **6.** From the Auto-Synchronization pull-down menu, choose the frequency that suits your application.

Redundancy Module Options				
Auto-Synchronization:	Never 💌			
	Never			
Chassis ID:	Always Condition			

7. Manually synchronize the chassis, if needed.

-R	edundancy Commands ——	
	Synchronize Secondary	

- 8. Set the redundancy module date and time according to your preference.
- 9. Click OK.
- 10. Close the RMCT.

Your redundant system firmware upgrade is now complete.

Update IP Address Set Via Software to Address Set Via Rotary Switches


This section describes how to change Ethernet IP address settings set by software to IP addresses set by rotary switches when your system must continue to operate during the update.

One reason to change IP address settings to the rotary switch option is if you system is experiencing a Duplicate IP address condition and IP address swapping is disabled.

IMPORTANT	Remember the following before using this section:
	• If you are replacing 1756-EN2T/C (or earlier) modules, firmware revision 5.008 (or later), ignore this section.
	 If you are replacing 1756-EN2T/D modules, ignore this section.
	 You must execute this procedure before the Redundancy System Update procedure.
	• You must physically be present at the location of the redundant chassis to do this upgrade.
	 You can upgrade only from firmware revision 19.052 or later, to firmware revision 20.055.
	Therefore, if you are not upgrading from ControlLogix enhanced redundancy system, revision 19.052 or later, ignore this section.
	• The term 1756-RM is synonymous with 1756-RM2 in the text and graphics throughout this section.

Complete the following steps.

- 1. Open RSLinx Classic software and browse to the redundancy module.
- 2. Right-click the redundancy module in the primary chassis and choose Module Configuration.




- 3. Verify that the chassis are synchronized.
- **4.** On the Configuration, choose Never from the Auto-Synchronization pull-down menu.

Ē	1756-RM2 REDUNDANCY MODULE			
Ν	Aodule Info	Configuration	Synchronization	Synchro
	Redundar	ncy Module Opti	ons	
(Auto-Syn	chronization:	Always	▼ 9
	Chassis H):	Never Always Conditional	

- 5. Click Apply, and then click Yes.
- **6.** Remove the secondary 1756-EN2T module from its chassis and disconnect the Ethernet cables from the module.
- 7. Configure the IP address on the primary 1756-EN2T module.

The following steps use RSLinx Classic software.

a. Right-click the module icon and choose Module Configuration.



b. On the Port Configuration tab, enter the desired IP address, Network Mask (if not entered automatically), and click OK.

This example uses the values in the following screen capture.

 Network Configuration Ty Static 	
• Static	C Dynamic
	in network configuration.
C Use BOOTP to obt	ain netwerk configuration.
P Address:	192 . 168 . 1 . 1
Network Mask:	255 . 255 . 255 . 0
Gateway Address:	0.0.0.0
Primary Name Server:	0.0.0.0
Secondary Name Server:	0.0.0.0
Domain Name:	
Host Name:	
Auto-negotiate port	speed and duplex
Current Port Speed:	100 👻
Current Duplex:	Full duplex
(Changes to Port Speed	d and Duplex require module reset.)
Status: Network Ir	nterface Configured

- 8. Set the rotary switches on the removed secondary module to 888.
- 9. Reinstall the module into the secondary chassis.

IMPORTANT Make sure the module is not physically connected to the network before reinstalling it.

- 10. After the module resets, remove it again.
- 11. Set the rotary switches on the secondary module to the desired IP address.
- 12. Reinstall the module in the chassis and reconnect it to the network.

Any Duplicate IP address errors that existed previously are no longer present.

13. On the Synchronization tab in the RMCT, click Synchronize Secondary to synchronize the chassis.

The Transferment of the Tr		
Module Info Configuration Synchronization Sy		
Redundancy Commands		
Synchronize Scondary Disqualify		
	_	

14. On the same tab, click Initiate Switchover to switch the primary and secondary chassis in the system.

1756-RM2 REDUNDANC	Y MODULE	An Annu and an entry day of	arrent (
Module Info Configuration	Synchronization	Synchronization Status Event Log S	ystem Upda	
- Redundancy Commands				
Synchronize Secondary				
Recent Synchronization Attempts:				


- **15.** Remove the new secondary 1756-EN2T module from its chassis and disconnect the Ethernet cables from the module.
- 16. Set the rotary switches on the removed secondary module to 888.
- 17. Reinstall the module into the secondary chassis.

IMPORTANT Make sure the module is not physically connected to the network before reinstalling it.

- 18. After the module resets, remove it again.
- 19. Set the rotary switches on the secondary module to the desired IP address.
- 20. Reinstall the module in the chassis and reconnect it to the network.

Any Duplicate IP address errors that existed previously are no longer present.

21. In the RMCT, from the Auto-Synchronization pull-down menu, choose your preferred method.



22. Verify that the chassis are synchronized.Manually synchronize the chassis, if needed.



23. Click Apply, and then click Yes.

Replace 1756-RM/B (or earlier) Modules with 1756-RM2 Modules

You can replace your current redundancy modules with 1756-RM2 modules without initiating a switchover.

TIP For the following steps, `redundancy modules' refers to 1756-RM or 1756-RM/B modules.

Before executing these steps, review <u>Table 1</u> and <u>Table 2</u>.

- <u>Required Series and Firmware Revisions for Components Used in an</u> <u>Enhanced Redundancy System, Revision 20.055_kit5 on page 3</u>
- <u>Required Software Versions for Enhanced Redundancy System, Revision</u>
 <u>20.055_kit5 on page 6</u>.
- 1. Install the compatible version of the RMCT software. You must shut down RSLinx Classic software to perform the installation, and then restart RSLinx Classic software after the installation is complete.
- **2.** On the RMCT Configuration tab, from the Auto-Synchronization pull-down menu, choose Never.
- **3.** Disqualify the redundant chassis pair (if not already disqualified) by using the RMCT.
- 4. Unplug the fiber cable on both of the redundancy modules.
- **5.** Close any open RMCT sessions connected to the current redundancy modules that are being replaced.
- **6.** Remove the redundancy module pair (in any order) from the redundant chassis.
- 7. Insert the 1756-RM2 redundancy module pair (in any order) in the redundant chassis into the same slots as the redundancy modules.
- 8. If not already installed, use RSLinx Classic software to upload the EDS file for the 1756-RM2 module.

If needed, obtain the EDS file for the 1756-RM2 module. Right-click the module in RSWho and choose 'Upload EDS file from device'.

- **9.** Update the primary and secondary 1756-RM2 modules to the to the appropriate firmware revision.
- **10.** Reconnect the fiber cable on either CH1 or CH2 of the 1756-RM2 redundancy module.
- **11.** Optional: Connect a second fiber cable on the remaining channel for fiber redundancy.
- 12. Wait for at least 45 seconds after connecting the fiber cables.
- 13. Launch the RMCT again for the newly-installed 1756-RM2 modules.
- 14. On the RMCT Configuration tab, from the Auto Synchronization pull-down menu, choose your original value.
- **15.** Synchronize the system again (if it is not already qualified) by using the RMCT.

Storing a Project to a Nonvolatile Memory Card While Your Process Is Running

Use this procedure to store an updated project and firmware to the nonvolatile memory card of the controller while your process is running.

IMPORTANT	The ControlLogix controllers use these nonvolatile memory cards.
-----------	--


Cat. No.	Nonvolatile Memory Card
1756-L6 <i>x</i>	1784-CF64 or 1784-CF128 CompactFlash cards
1756-L7 <i>x</i>	1784-SD1 or 1784-SD2 Secure Digital cards

This section describes how to store a project to a nonvolatile memory card in a secondary controller without interrupting your process.

IMPORTANT	We recommend that you store the same project on both controllers' nonvolatile memory cards. By doing so, you can be assured that if a controller, primary or secondary, loses the project from its internal memory, you can load the most recent project back onto that controller.
	If you store the same project on both controllers' nonvolatile memory cards, while the process is running, you must save the project on the controllers while they are in the secondary controller state. To do so, you save the project on the secondary controller, conduct a switchover and save the project on the new secondary controller.
	For more information, see the steps below.

Complete these steps to store the project to the nonvolatile memory card on a secondary controller.

1. Verify that the redundant chassis are synchronized.



If the redundant chassis are not synchronized, synchronize them before continuing with the next step.

- 2. In the RMCT, click the Configuration tab.
- 3. From the Auto-Synchronization pull-down menu, choose Never.

TT56-RM2 REDUNDANCY MODULE				
Module Info	Configuration	Synchronization	Synchro	
Redunda	ncy Module Opt	ions		
Auto-Syn	chronization:	Always	•	
Chassis ID:		Never Always Conditional	1	
		,	(

4. Click Apply, and then click Yes.

5. On the Synchronization tab, click Disqualify Secondary.



6. In RSLogix 5000 software, go online with the secondary controller.

Offline	
No Forces	<u>G</u> o Online
No Edits	UploadV
Redundancy	<u>D</u> ownload

7. Use the steps described in the Logix5000 Controllers Nonvolatile Memory Programming Manual, publication <u>1756-PM017</u>, to store the project.

IMPORTANT	Remain offline after you have stored the project to nonvolatile memory.
	You must stay offline through the remainder of this procedure.

8. In the RMCT, from the Auto-Synchronization pull-down menu, choose your preferred method.

Redundancy Module Options			
	Auto-Synchronization:	Never 💌	
		Never	
	Chassis ID:	Always Condition	


9. Depending on your Auto-Synchronization setting, manually synchronize the chassis if needed.

dundancy Commands
Synchronize Secondary

If you do not need to store the project to the nonvolatile memory card in the primary controller, you are done.

10. If you want to store the project to the primary controller's nonvolatile memory card, execute a switchover as described in these steps.

a. In RSLinx Classic software, right-click the 1756-RM module and choose Module Configuration to open the RMCT for the **primary** redundancy module.




b. Click the Synchronization tab.

c. Click Initiate Switchover.

Module Info Configuration	Synchronization Synchronization Status	Event Log System Update	System Event History
- Redundancy Commands			
Synchronize Seconda	any Disqualify Secondary	Initiate Switchover	Become P
			-
-Recent Synchronization A	.ttempts:		

The Redundancy Configuration Tool dialog box opens.

11. Click Yes.




The switchover begins. When the switchover is complete, the previously primary controller is now the secondary controller.

12. Return to <u>step 1 on page 71</u> to store the project on the new secondary controller.

Access Product Release Notes

Product release notes for the products used with this enhanced redundancy firmware bundle are available online within the Product Compatibility and Download Center.

 From the Quick Links list on <u>http://www.ab.com</u>, choose Product Compatibility and Download Center.



2. From the Compatibility Scenarios tab or the Get Downloads tab, search for and choose your product.

Start by selecting products



3. Click the download icon **to** access product release notes.

Additional Resources

These documents contain additional information concerning related products from Rockwell Automation.

Resource	Description
ControlLogix Enhanced Redundancy System User Manual, publication <u>1756-UM535</u>	Provides design, installation, and troubleshooting information specific to the enhanced redundancy system.
FactoryTalk Batch PhaseManager™ User's Guide, publication BATCHX-UM010	Provides instruction for PhaseManager, FactoryTalk Batch, and RSLogix 5000 software to develop a batch automation system by using phase logic for Logix5000 controllers.
PhaseManager User Manual, publication LOGIX-UM001	Provides details about PhaseManager software and includes details about tags associated with the PHASE data type.
ControlFLASH Firmware Upgrade Kit Quick Start, publication <u>1756-0S105</u>	Contains information on how to upgrade module firmware.
ControlLogix Controllers User Manual, publication <u>1756-UM001</u>	Contains information on how to install, configure, program, and operate a ControlLogix system.
Product Certifications website, <u>http://www.ab.com</u>	Provides declarations of conformity, certificates, and other certification details.
Rockwell Automation Technical Support Knowledgebase, available at http://www.rockwellautomation.com/knowledgebase/	Provides details about how to assemble and mount the controller, how to upgrade firmware, and controller technical specifications.

You can view or download publications at

http://www.rockwellautomation.com/literature. To order paper copies of technical documentation, contact your local Allen-Bradley distributor or Rockwell Automation sales representative.

Rockwell Automation Support

Rockwell Automation provides technical information on the Web to assist you in using its products. At <u>http://www.rockwellautomation.com/support</u> you can find technical and application notes, sample code, and links to software service packs. You can also visit our Support Center at <u>https://rockwellautomation.custhelp.com/</u> for software updates, support chats and forums, technical information, FAQs, and to sign up for product notification updates.

In addition, we offer multiple support programs for installation, configuration, and troubleshooting. For more information, contact your local distributor or Rockwell Automation representative, or visit http://www.rockwellautomation.com/services/online-phone.

Installation Assistance

If you experience a problem within the first 24 hours of installation, review the information that is contained in this manual. You can contact Customer Support for initial help in getting your product up and running.

United States or Canada	1.440.646.3434
Outside United States or Canada	Use the <u>Worldwide Locator</u> at <u>http://www.rockwellautomation.com/rockwellautomation/support/overview.page</u> , or contact your local Rockwell Automation representative.

New Product Satisfaction Return

Rockwell Automation tests all of its products to help ensure that they are fully operational when shipped from the manufacturing facility. However, if your product is not functioning and needs to be returned, follow these procedures.

United States	Contact your distributor. You must provide a Customer Support case number (call the phone number above to obtain one) to your distributor to complete the return process.
Outside United States	Please contact your local Rockwell Automation representative for the return procedure.

Documentation Feedback

Your comments will help us serve your documentation needs better. If you have any suggestions on how to improve this document, complete this form, publication <u>RA-DU002</u>, available at <u>http://www.rockwellautomation.com/literature/</u>.

Rockwell Automation maintains current product environmental information on its website at <u>http://www.rockwellautomation.com/rockwellautomation/about-us/sustainability-ethics/product-environmental-compliance.page</u>.

Allen-Bradley, Rockwell Software, Rockwell Automation, ControlLogix, ControlFLASH, PhaseManager, FactoryTalk, RSLogix, RSLinx, PanelView, RSNetWorx, PowerFlex, ControlLogix-XT, and Logix5000 are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

Rockwell Otomasyon Ticaret A.Ş., Kar Plaza İş Merkezi E Blok Kat:6 34752 İçerenköy, İstanbul, Tel: +90 (216) 5698400

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444 Europe/Middle East/Africa: Rockwell Automation NV, Pegasus Park, De Kleetlaan 12a, 1831 Diegem, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640 Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846