MERITOR WABCO

Operations Manual

Aftermarket Programming

Aftermarket programming is a method of servicing most pneumatic ABS ECUs. Instead of swapping one fully programmed ECU for another, programmable ECUs can be stocked at the point of service and programmed using a purchased configuration file. The process can be completed in the following steps.

- 1. Acquire a programmable replacement ECU from Meritor's Commercial Vehicle Aftermarket by calling 888-725-9355.
- 2. Install the replacement ECU into the vehicle.
- 3. Acquire a configuration file from https:// meritorwabco.snapon.com.
- Load the configuration file into the ECU using Meritor WABCO's TOOLBOX[™] Aftermarket Programming application.

NOTE: Aftermarket programming does not change the functionality of the ABS-based safety system as installed in the vehicle.

Before programming the ECU, verify TOOLBOX[™] Software version 11.5 or higher is installed on the service computer.

How to Obtain Additional Maintenance, Service and Product Information

Refer to Maintenance Manual MM-0112, Anti-Lock Braking System (ABS) and Electronic Stability Controls (ESC). To obtain this publication or if you have any questions about the material covered in this user guide, please contact the Meritor OnTrac[™] Customer Call Center at 866-OnTrac1 (668-7221) or visit our website: meritorwabco.com.

Meritor WABCO ABS ECU Aftermarket Programming User Guide

Aftermarket Programming Procedures

Step 1: Acquire a programmable replacement ECU from Meritor's Commercial Vehicle Aftermarket by calling 888-725-9355.

Meritor's Commercial Vehicle Aftermarket will provide the correct aftermarket programmable replacement ECU for the vehicle being serviced. Programmable ECUs are clearly identified with a large orange sticker indicating it must be programmed. Programmable ECUs are also shipped with an instruction sheet explaining how to complete the service operation. Figure 1.



Step 2: Install the replacement ECU into the vehicle.

The programmable ECU should be installed in the vehicle in the same manner and location as the ECU being replaced. Connect all electrical connectors.

NOTE: Aftermarket programmable ECUs are backwards compatible with the ECUs they replace, so there should be no modifications required to either the mounting or electrical connections.

When the replacement ECU is installed, the ABS lamp will be lit due to an active DTC:

SID	SPN	FMI	Description
253	630	2	Calibration Memory – Wheel Parameter Incorrect

NOTE: This DTC will clear after a configuration file has been successfully loaded into the ECU. The ABS lamp will remain on until the vehicle has been driven above 4 mph (6 km/h).

Step 3: Acquire a configuration file from https:// meritorwabco.snapon.com.

Configuration files are available for purchase at https:// meritorwabco.snapon.com. Begin by either creating an account or logging into an account created during a previous purchase from the site. Figure 2.

NOTE: If you purchased TOOLBOX[™] Software, then you already have an account, and that account information should be used to log in.

hane Support	Register Login Contact
tome > Login	
Registered Users	New Users
Returning users can log on using the controls below. New users must register using one of the options in the New Users panel.	You need to create a user account before you can order tools and equipment.
Username	Create a new user account
Pergit Usamama?	
Password	
Factor Passadot?	
Sign In	
denotes required field	

Click the Aftermarket Programming Configuration Files button at the top of the screen. Figure 3.

NOTE: If TOOLBOX[™] Software is not available at the point of service, it can be purchased by clicking the TOOLBOX[™] Software button.

MERITOR W	International States	 S	P Theorem
Categories			4012076a
Figure 3			

Enter the part details for the vehicle being worked on and the part being replaced. Figure 4.

- The VIN must include all 17 characters.
- The part number of the ECU being replaced must be entered.

• The serial number of the ECU being replaced may be entered, but is not required.

Part Details	
VIN, All 17 Characters - Required	
Part Number of ECU Being Replaced - Required	•
Serial Number - Optional	
Calculate Price	
* denotes required field	
	4012077a

The next screen will show the details of the configuration file linked to the part number and VIN combination entered. The price for the configuration file will also be displayed. Verify the VIN, part number and details of the ECU functionality match those of the ECU being replaced. If this information is correct, click the Add to shopping cart button. Figure 5.

PSETI	Aftermarket Programming Configuration File Configuration file provided based on VIN and part nur	mber Pricing
10-0	input below: Parameter set desc	Add to shopping cart
	Part Details VIN 3HSDGAPN6FN609900 Part Number 4008623100	
Anduct and price information are	Serial Number Details ABS Base Configuration: 454M ESC: Enabled ATC: Enabled	
subject to change without notice,	Reset	

Figure 5

After the configuration file has been added to the shopping cart, the shopping cart will be displayed. Clicking Proceed to Checkout will step through the configuration file purchase process. Figure 6.

A *	Aftermarket Programming Configuration File	e 1	\$251.00	\$251.00
5.3	CONFIGFILE 3HSDGAPN0FN611027 (4008662510)			
	ું જે 🖬	otal Amount:	\$3	251.00
	Update	Ouantities	Proceed To	Checkout

The first step in the checkout process is to verify contact information. The information will automatically populate based on login information; all fields can be edited. When the correct contact details are displayed, click Bill to this address. Figure 7.



The select payment method screen appears next. Enter the credit card information for the purchase, or select an alternative payment method. Once the information is entered, click Pay by Credit Card.

NOTE: Purchasing the configuration file by credit card is recommended for immediate download of the configuration file. Users of other payment methods may experience a delay while payment is processed. Figure 8.



The final screen of the purchase process allows the details of the purchase to be reviewed before placing the order. If all of the information is correct, check the box acknowledging the terms and conditions of the purchase and click Place Order. Figure 9.



The order will be processed, and a link to download the configuration file will be displayed. Click the hyperlink to download the configuration file. Figure 10.

NOTE: The link will remain available for seven days. The configuration file download must be completed in that time.



The following message will be displayed regarding the recommended file storage location. Press OK to continue with saving the file. Figure 11.



Figure 11

When the following screen is displayed, press Save to continue with saving the file. Figure 12.



NOTE: Save the configuration file to a location that can be accessed while connected to the vehicle. The Aftermarket Programming application will allow the selection of the file from any location.

Step 4: Load the configuration file into the ECU using Meritor WABCO's TOOLBOX[™] Aftermarket Programming application.

Start by connecting TOOLBOX[™] Software 11.5 or higher to the vehicle using any J1939 RP1210 diagnostic adapter. Turn the ignition on, open TOOLBOX[™] Software, and click the Aftermarket Programming application to start programming the ECU. Figure 13.

NOTE: Wireless diagnostic adapters should not be used for aftermarket programming or any other Meritor WABCO programming operation.

NOTE: It is recommended that aftermarket programming be completed with ignition on only. Do not cycle the key until the programming operation is complete. Verify the battery is fully charged prior to performing the programming operation; the vehicle should not be connected to a battery charger during programming.

NOTE: For complete instructions for using TOOLBOX[™] Software, refer to the TOOLBOX[™] User's Manual, TP-99102.



Figure 13

A message will be displayed indicating that the ECU will be changed as a result of programming. Click Yes to continue with programming the ECU. Figure 14.



The Aftermarket Programming application will then locate the configuration file. Click OK to select the file. Figure 15.



Use the file selection box to locate the configuration file that matches the VIN and part number of the vehicle being serviced. Select the file by clicking on it, and then click Open. Figure 16.



The Aftermarket Programming application will automatically run from this point. The progress of the programming operation will be displayed in the dialogue box. Once ECU programming is successfully completed, a green PASS indicator will appear at the bottom of the Aftermarket Programming application window. Figure 17.

WEF	(I.I.OF	WAB	CU
	Aftermarket Pro	gramming	
Contracting to angular Constant of Contracting to Standardy for Contracting to Paral system Addition of Contracting Contracting one contracting system Contracting one contracting system Contracting Contracting on Contracting Contracti	nale 1976; 15) Indee Clana III Indee Clana III Indee Clana III (State part nation ; Indee Clana III) Indee Clana III (State Part III)		
	PAS	S	

If the programming operation fails for any reason, a red FAIL indicator will appear at the bottom of the Aftermarket Programming application window. Within the text box, an error code will be displayed with instructions. If the programming operation cannot be completed, record the error code and contact the Meritor OnTrac[™] Customer Call Center at 866-668-7221. Figure 18.

MER	LITOR WAE	SC-C
4	Aftermarket Programming	
Connecting is adapted Received a connectant on Received Cardinal Received Cardinal Received Free Americant Provider Received Free Provider Received Free	where $ m _{2}(\theta_{i}) $ are been raded (2.14) and unlest a different fit	
	FAIL	

NOTE: ESC ECUs will require the ESC End of Line procedure to be completed following ECU replacement. Refer to the procedure in Maintenance Manual MM-0112.

SID	SPN	FMI	Warning Light	Programming Error Code	Message Displayed	Description/Action	_
253	630	N	ABS WL	None	None	This DTC is active for all programmable ECUs that have not been programmed with a configuration file. Completion of the programming operation will clear this DTC. If this code is active for a non-programmable ECU, refer to the SPN, SID, FMI Fault Codes section in this manual.	
253	630	N	ABS WL	Æ	Unable to connect to adapter [Adapter Name] (Error: B1). Please exit this window, cycle power and try again. If the problem persists, please contact the Meritor OnTrac TM Customer Call Center at 866-668- 7221.	The diagnostic adapter selection does not match the selection in TOOLBOX TM Software or the diagnostic adapter is not capable of J1939 communications. Return to the TOOLBOX main screen. Select Utilities> Adapter Selection. Select the diagnostic adapter being used from the list of options.	
253	630	5	ABS WL	B2	Unable to start diagnostic session with ECU (Error: B2). Please exit this window, cycle power and try again. If the problem persists, please contact the Mentor OnTrac [™] Customer Call Center at 866-668-7221.	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the attermarket programming application. If the problem persists, repeat with key on only (IGN off). This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.	
253	630	5	ABS WL	B	Unable to read ECU Production Data (Error: B3). Please exit this window, cycle power and try again. If the problem persists, please contact the Mentor OnTrac TM Customer Call Center at 866-668-7221.	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the attermarket programming application. If the problem persists, repeat with key on only (IGN off). This failure will also occur when one or more of the following are not connected: Power, Ground, J1339 CAN High or J1339 CAN Low. Check for continuity.	
253	630	5	ABS WL	B4	Unable to read ECU Component ID (Error: B4). Please exit this window, cycle power and try again. If the problem persists, please contact the Mentor OnTrac [™] Customer Call Center at 866-668-7221.	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the attermarket programming application. If the problem persists, repeat with key on only (IGN off). This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.	
253	630	2	ABS WL	B5	Aftermarket programming configuration file for download not found (Error: B5).	This error will occur if the configuration file is moved or changed during a configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).	
253	630	5	ABS WL	B	Error reading the Aftermarket Programming configuration file (Error: B6).	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the attermarket programming application. If the problem persists, repeat with key on only (IGN off). This failure will also occur when one or more of the following are not connected: Power, Ground, J1339 CAN High or J1339 CAN Low. Check for continuity.	
253	630	5	ABS WL	B7	Selected file for download has been successfully used before. Please restart Aftermarket Programming and select a different file (Error: B7).	This failure will occur when a user tries to use a configuration file that has already been used to successfully configure an ECU. Purchase a new configuration file at https://meritorwabco.snapon.com.	

Aftermarket Programming Failure Codes List

0	SPN	FMI	Warning Light	Programming Error Code	Message Displayed	Description/Action
23	630	N	ABS WL	œ	Module of the Aftermarket Programming file for download is incorrect for this application (Error: B8). Ensure that the Aftermarket Programming file extension was not renamed. Please exit this window and select Aftermarket Programming to try again.	This error will occur if the configuration file is moved or changed during a configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
23	630	N	ABS WL	о Ш	Part number of installed ECU [part number] does not match part number of Aftermarket Programming configuration file (Error: B9). Contact the Meritor OnTrac TM Customer Call Center at 866-568-7221.	This failure will occur when the part number in the configuration file does not match the aftermarket programmable ECU part number. Verify that the aftermarket programmable replacement ECU is correct for the ECU previously installed on the vehicle.
53	630	7	ABS WL	B10	This Aftermarket Programming configuration file does not work for this vehicle (Error: B10). Contact the Meritor $OnTrac$ TM Customer Call Center at 866-668-7221.	This failure will only occur when the VIN for the configuration file does not match the actual VIN of the vehicle being serviced. Verify that the VIN used to purchase the configuration file matches that of the vehicle the aftermarket programmable replacement ECU is being installed in/programmed on.
53	630	7	ABS WL	B11	Invalid ECU part number [part number] for programming (Error: B11).	This failure will occur when attempting to configure an ECU that does not require aftermarket programming. Verify the ECU does not require programming and refer to the SPN, SID, FMI Fault Codes section in this manual.
53	630	7	ABS WL	B12	Unable to read parameters from ECU (Error: B12), Please exit this window, cycle power and try again. If the problem persists, please contact	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					the Meritor OnTrac™ Customer Call Center at 866-668-7221.	This failure will also occur when one or more of the following are not connected: Power Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
23	630	N	ABS WL	B13	Unable to gain security access to ECU (Error: B13). Please exit this window, cycle power and try again. If the problem persists, please contact	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					the Meritor OnTrac™ Customer Call Center at 866-668-7221.	This failure will also occur when one or more of the following are not connected: Power Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
33	630	7	ABS WL	B14	Unable to write VIN to the ECU (Error: B14). Please exit this window, cycle power and try again. If the problem persists, please contact the Meritor	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					OnTrac™ Customer Call Center at 866-668-7221.	This failure will also occur when one or more of the following are not connected: Power Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
53	630	2	ABS WL	B15	Unable to write checksum to ECU: Block [block information] (Error: B15) Please exit this window, cycle power and try again. If the problem persists,	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					please contact the Meritor On Irac Im Customer Call Center at 866-668- 7221.	This failure will also occur when one or more of the following are not connected: Power Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.

_	SPN	FMI	Warning Light	Programming Error Code	Message Displayed	Description/Action
	630	N	ABS WL	B16	Communication Error (Error: B16). Please exit this window, cycle power and try again. If the problem persists, please contact the Merifor OnTrac ^{1M}	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					Customer Call Center at 866-668- 7221.	This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
	630	N	ABS WL	B17	Parameter Incompatibility (Error: B17). Contact the Meritor OnTrac TM Customer Call Center at 866-668- 7221.	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
	630	0	ABS WL	B18	Unable to read memory address before setting parameter (Error: B18). Please exit this window, cycle power and try again. If the problem persists, please	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					contact the Meritor OnTrac™ Customer Call Center at 866-668-7221.	This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
l	630	N	ABS WL	B19	VCP program error: ByteToChange for [parameter information] neither 0 nor 1 (Error: B19). Please exit this window, cycle power and try again. If	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					the problem persists, please contact the Meritor OnTrac TM Customer Call Center at 866-668-7221.	This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
	630	5	ABS WL	B20	Unable to write parameter: [parameter information] (Error: B20). Please exit this window, cycle power and try again. If the problem persists, please contact	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX [™] Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					the Meritor OnTrac™ Customer Call Center at 866-668-7221	This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
	630	0	ABS WL	B21	Error while trying to set parameters (Error: B21). Please exit this window, cycle power and try again. If the problem persists, please contact	This failure may occur if communication with the ECU is interrupted during the configuration session. Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
					the Meritor OnTrac™ Customer Call Center at 866-668-7221.	This failure will also occur when one or more of the following are not connected: Power, Ground, J1939 CAN High or J1939 CAN Low. Check for continuity.
	630	N	ABS WL	A1	Error parsing the Aftermarket Programming configuration file (Error: A1).	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
	630	N	ABS WL	A2	No parameters were found in the Aftermarket Programming configuration file (Error: A2).	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
	630	N	ABS WL	A3	Part number is missing from the Attermarket Programming configuration file (Error: A4). Contact the Meritor OnTrac TM Customer Call Center at 866-668-7221.	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).

SID	SPN	I FMI	Warning Light	Programming Error Code	Message Displayed	Description/Action
253	630	N	ABS WL	A4	VIN not found in the Affermarket Programming configuration file (Error: A4). Contact the Meritor OnTrac™ Customer Call Center at 866-668- 7221.	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
253	630	7	ABS WL	C1	Mismatch found between installed ECU and the configuration file (Error: C1).	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).
253	630	5	ABS WL	C2	[Parameter] Incorrect for installed ECU part number (Error: C2).	Close the TOOLBOX TM Software, reopen it and restart the aftermarket programming application. If the problem persists, repeat with key on only (IGN off).

MERITOR WABCO

Meritor WABCO Vehicle Control Systems 2135 West Maple Road Troy, MI 48084-7121 USA 866-OnTrac1 (668-7221) meritorwabco.com Information contained in this publication was in effect at the time the publication was approved for printing and is subject to change without notice or liability. Meritor WABCO reserves the right to revise the information presented or to discontinue the production of parts described at any time.

Copyright 2015 Meritor, Inc. All Rights Reserved

Printed in USA

OM-1600 Issued 11-15 (16579)