

ΚΟΝΙζΛ ΜΙΝΟΙΤΛ

SSD SUPPORT SOLUTIONS

FAX 9660 - ALL ACTIVE SOLUTIONS October 2006

This document contains information that was exported directly from Konica Minolta's SSD Support knowledge base. Some solutions may contain hyperlink references which originally contained links to graphic or text files. If you wish to view these files, you must access the solutions via SSD CS Expert Support on Konica Minolta's website, www.kmbs.konicaminolta.us.

Legal Notice

This document is designed as a diagnostic tool, primarily for Konica Minolta's support personnel, and authorized service representatives. Konica Minolta recommends that all service be performed by an authorized service representative. Users are responsible for seeking advice of a Konica Minolta authorized service representative regarding the information, opinion, advice or content of this document.

USER AGREES THAT USE OF THIS DOCUMENT IS AT USER'S SOLE RISK AND THAT THIS DOCUMENT IS PROVIDED ON AN AS IS BASIS WITHOUT WARRANTIES OF ANY KIND, EITHER EXPRESSED OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF TITLE OR IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, OTHER THAN THOSE WARRANTIES THAT ARE IMPLIED BY LAW AND INCAPABLE OF EXCLUSION. IN NO EVENT WILL KONICA MINOLTA OR THOSE ACTING ON ITS BEHALF BE LIABLE FOR ANY DAMAGES, INCLUDING, WITHOUT LIMITATION, DIRECT, INDIRECT, INCIDENTAL, SPECIAL, CONSEQUENTIAL OR PUNITIVE DAMAGES ARISING OUT OF YOUR USE OF THIS DOCUMENT.

Copyright 2006, Konica Minolta Business Solutions U.S.A., Inc.

Solution ID TAUS0610825EN00

Description

How to initialize the machine.

Solution

To initialize the machine, perform the following:

- 1. Power the machine OFF.
- 2. Hold the COPY key down while powering the machine ON.
- 3. Press 3.
- 4. ALL DATA CLR is displayed. To clear all data press YES or press NO to select LOCATION DATA CLR or CONFIG DATA CLR and press YES.
- 5. ARE YOU SURE? is displayed.
- 6. Press YES.
- 7. Press STOP three times to return to the standby display.

Solution ID TAUS0610824EN00

Description

How to enable the TCR/MCF.

Solution

To enable the TCR/MCF (transmit confirmation report/message confirmation report), perform the following:

- Power ON the machine while pressing the SELECT FUNCTION key.
- 2. Press YES.
- 3. Press 0 and then 1.
- 4. Press NO to cycle between ON or OFF.
- 5. Press YES to save setting.
- 6. Press STOP four times to return to normal operation.

TAUS0610983EN00 Solution ID

Description

How to program the fax for direct or memory transmission.

Solution

To program the FAX 9660 to transmit directly or from memory, perform the following:

- 1. Press the SELECT FUNCTION key.
- 2. Press the one-touch 09 key.
- 3. Press the YES key.
- 4. Enter 1 and 8 from the keypad.
- 5. Press NO to toggle between MEM and FEED and press YES.
- 6. Press STOP four times.

TAUS0613663EN00 Solution ID

Description

How to program and send to a group.

Solution

The FAX 9660 can be programmed for up to 20 groups, with each location having up to 129 locations. All locations to be called in a group must be programmed as one-touch or auto-dial numbers. To program the group, perform the following:

- 1. Press the [Select Function] key.
- 2. Press one-touch key [8/Location Program]. The display shows LOCATION PROGRAMMING.
- On the numeric keypad, press the [#] key. The display shows GROUP SETTING.
 Using the numeric keypad enter the 2 digit group number you want to program. The range is 01 to 20.
- 5. The display shows the number of your current group and SELECT LOC.(SAO).
- 6. You can now add a location to your group:
- a. To add a one-touch location, press the one-touch key. Press [YES] to add to the group.
- b. To add an auto-dial, enter the 2 digit auto-dial number. Press [YES] to add to the group.

7. After you have completed the selection by pressing [YES], the display shows SELECT LOC. again. Continue to add or delete locations from your group. Each group can contain up to all the one-touch and auto-dial locations of the FAX 9820.

- 8. When finished programming the group press [NO], the display will show LOCATION PROGRAMMING.
- 9. To program another group go back to step 3, to end press [SELECT FUNCTION].

October 2006



5

Solution Usage

Solution Usage 5

To Broadcast using a group, perform the following:

- 1. Load documents.
- 2. Press [SELECT FUNCTION].
- 3. Press one-touch key [2/ Broadcast Feeder] Display shows BROADCAST/MEMORY TX.
- 4. Using the numeric keypad press [#] followed by the 2 digit group number.
- 5. Press [YES] to confirm.
- 6. Press [NO] at SELECT LOCATION(S) to finish selection.

7. IF multiple locations have been selected the machine will display a confirmation screen. Follow the prompts. When all selections are correct press the [START] key. The documents will be scanned and transmission will begin.

Solution ID TAUS0613468EN00

Description

The image of the first page is not printed on the TCR.

Solution

To have the image of the first transmitted page printed on the TCR, perform the following:

- 1. Turn OFF machine.
- 2. Press and hold the Select Function button while turning the machine ON.
- 3. Press Yes.
- 4. Press 0 and then 4.
- 5. Press the No button until ON is shown in the display.
- 6. Press Yes.
- 7. Turn the machine OFF/ON to exit the service mode.

Note: The image will print on the TCR report as long as a memory transmission is performed. See to page 2-60 (Image in MCF) in the FAX 9660 Service Manual for details.

Solution ID TAUS0614032EN00

Description

How to program the paper size for the paper trays.

Solution

- To program the paper trays, perform the following:
- 1. Press the SELECT FUNCTION button.
- 2. Press one-touch key 9.
- 3. Press YES.
- 4. On the key pad, press 1 and then 3.
- 5. Press NO until the proper paper size is displayed, then press YES.
- 6. The second paper tray selection will be displayed. Press NO until the correct paper size is displayed.
- 7. Press STOP until the standby screen is displayed.

Solution ID TAUS0614424EN00

Description

Unable to receive faxes.

Solution

CAUSE: Memory is corrupted.

SOLUTION: Initialize the machine by performing the following:

- 1. Power machine OFF.
- 2. Hold the Copy key down while powering the machine ON.
- 3. Press 3.

4. Press the LEFT ARROW key three times.

5. Press STOP to return to the standby display.

Solution ID TAUS0624521EN00

Description

Add Toner Message does not clear after replacing the toner cartridge.

olution bouge

4

4

Solution Usage

Solution Usage

Solution Usage 4

Solution

CAUSE: Toner packed in reservoir caused lever to move out of position

- SOLUTION: Reposition magnet lever in drum unit. Before replacing the toner cartridge in the future, perform the following:
- 1. Remove the drum/toner assembly and gently shake the assembly to the left and right.
- Tap lightly on the left side of the drum/toner assembly to dislodge toner caked in the drum unit toner reservoir. 2
- 3. This will help the magnet lever from being forced out position within the toner reservoir prior to adding the new toner cartridge.

Solution ID TAUS0610822EN00

Description

How to adjust the buzzer volume.

Solution

To adjust the buzzer volume, perform the following:

- 1. Power the machine OFF.
- 2. Press and hold the Select Function button down while powering the machine ON.
- 3. Press YES.
- 4. Enter 0 then 7.

Note: Do not use the one-touch button 7.

- 5. Press NO to select LOW, MID or HIGH.
- 6. Press YES after making selection.
- 7. Press STOP until the normal standby screen is displayed.

TAUS0614180EN00 Solution ID

Description

The Activity Journal is not automatically printing.

Solution

CAUSE: The activity journal does not print automatically. The Activity Journal must be manually printed.

SOLUTION: To print an Activity Journal, perform the following:

1. Press the Select Function button.

2. Press the Report Print one-touch 6 button.

3. Press the Yes button.

TAUS0614654EN00 Solution ID

Description

Light prints. Image on the drum is solid.

Solution

CAUSE: Poor contact for the transfer roller.

SOLUTION: Clean and reform the copper contacts to the left side of the drum unit. Verify operation.

TAUS0610713EN00 Solution ID

Description

Does the FAX 9660 support the Printer (multifunctional) Kit?

Solution

The FAX 9660 does not support the multifunctional kit.

Solution ID TAUS0611011EN00

Description

CHANGE DRUM SOON message.



2

October 2006

Solution Usage

3

Solution Usage 3

Solution Usage 2

Solution

CAUSE: CHANGE DRUM SOON message is a warning that the image drum cartridge in the fax may be approaching the end of its usable life. CAUTION: Do not reset the drum counter at this time, as this will accelerate drum life deterioration.

The drum has used approximately 90% of its life based on an internal calculation. The drum yield count is based on the following print criteria: Using the ITU-T 4% Test Chart #1:

- 1 page jobs yields approximately 9000 sheets.
- 3 page jobs yields approximately 14,000 sheets.
- Continuous job yields approximately 20,000 sheets.

SOLUTION: This message does not mean that the drum must be replaced immediately, nor does it cause the fax to stop working. The drum can be used as long as print quality is acceptable, however, a replacement image drum and toner cartridge should be on hand. Replace the drum when print quality deteriorates below an acceptable level.

Note: Reset the drum counter only when finished installing a new image drum. Only reset the counter when the CHANGE DRUM SOON message is on the display. After replacing the drum, clear the message by performing the following:

- 1. Wait until the time, date and the answering mode appear on the display.
- 2. Press the SELECT FUNCTION key.
- 3. Press the one-touch 7 key. The display shows DRUM COUNT.
- 4. Press the Yes key to clear the image drum unit counter.
- 5. Press the STOP key to finish and return to normal operation.

Solution ID TAUS0611213EN00

Description

How to enable time and date stamp on received faxes.

Solution

To enable time and date stamp, perform the following:

- 1. Press Select Function button.
- 2. Press Copy twice to display TECH PROGRAMMING.
- 3. Press 2 from the keypad.
- 4. Press Left Arrow (YES) button.
- 5. Press 0 and then 4 from keypad. The display should read TIME AND DATE PRINT.
- 6. Press NO until desired setting is displayed. The options are OFF, ONCE or ALL.
- 7. Press YES to enable the change.
- 8. Press Stop button repeatedly until back to the standby mode.
- Solution ID TAUS0611470EN00

Description

Black vertical lines on transmitted facsimiles and copies.

Solution

CAUSE: The CIS (Contact Image Sensor) is dirty or has failed.

SOLUTION: Clean CIS (Document Scanner Glass) with glass cleaner and soft cotton pad. Replace CIS (p/n 40141401) if the problem persists after cleaning.

Solution ID TAUS0611707EN00

Description

How to print a Phone Directory.

Solution

To print a Phone Directory, perform the following:

- 1. Press the SELECT FUNCTION key.
- 2. Press the one-touch key 6.
- 3. Press NO until Phone Directory is in the display.

4. Press the YES button.

5. The Phone Directory will print out.

TAUS0613064EN00 Solution ID

2

Solution Usage

2

2

Solution Usage

Solution Usage

Description

How to display the print (total), scan or drum counters.

Solution

To display the counters, perform the following:

- 1. Press Select Function button.
- 2. Press One-touch key 7 (Counter Display).
- 3. Press No (right arrow) button repeatedly for one of the desired selections: DRUM COUNT: Do not clear the drum counter until replacement drum has been installed. PRINT COUNT: This is the total counter of receive faxes, internal test pages and copies. SCAN COUNT: This is the total number of copies and transmitted faxes.
- 4. Press Stop to return to standby mode.

Note: The drum counter will only shown when the Technical Function Service Bit (01) to set to ON.

Solution ID TAUS0614622EN00

Description

How to program the first tray for legal paper.

Solution

To program the upper tray for legal paper, perform the following:

- 1. Power the fax OFF.
- 2. Press Select Function while powering the machine ON.
- 3. Function Program will display. Press Yes.
- 4. Press 1 and then 3 on the ten key pad.
- 5. Press No until LGL14 displays.
- 6. Press Yes to save setting.
- 7. Press Stop until fax is in standby.

Solution ID TAUS0614931EN00

Description

User's Manual, FAX 9660.

Solution

FAX 9660 User's Manual

Note: To view the PDF, Acrobat* Reader must be installed. Acrobat Reader can be downloaded for free from the Adobe* Web site at: [[http://www.adobe.com/products/acrobat/readstep2.html] URL http://www.adobe.com/products/acrobat/readstep2.html]

* Trademark ownership information

Solution ID TAUS0618546EN00

Description

Paper jams in the fuser unit.

Solution

CAUSE: Soiled or worn lower fuser roller.

SOLUTION: Clean and/or replace the roller (p/n 53343701). SPECIAL NOTE: Solution provided by Steven Deutsch, KBT Minneapolis.

Solution ID TAUS0600602EN00

Description

How to print out a phonebook in alphabetical order.

Solution

The FAX 9660 does not have the capability to print the phonebook in alphabetical order.

Solution Usage 2

Solution Usage

2

Solution Usage 2

Solution ID TAUS0608042EN00

Description

Product Configurator, FAX 9660.

Solution

FAX 9660 Product Configurator.

Solution ID TAUS0610787EN00

Description

PRINTER ALARM 2 error message.

Solution

CAUSE: PRINTER ALARM 2 indicates an engine control error (optional second tray).

SOLUTION: Power the unit OFF/ON. If a lower tray option is installed make sure the manual feed tray is open. If this does not clear the message, replace the main CB (p/n 550825501).

Solution ID TAUS0610815EN00

Description

Will faxes received into memory be lost if power is turned off to clear a printer alarm error?

Solution

The FAX 9660 will lose all documents in memory when power is turned off since it does not have a battery backup for the memory. Note: Similar fax units that do have memory battery backup are FAX 9820, FAX 9825, FAX 9830, and FAX 9925.

Solution ID TAUS0610820EN00

Description

How to print out an activity report.

Solution

To print an Activity Journal, perform the following:

- Press the Select Function button.
- 2. Press the Report Print (one-touch 6) button.

3. Press the Yes button.

Solution ID TAUS0610840EN00

Description

How to reset the drum counter.

Solution

Reset the drum counter only when you have finished installing a new image drum. You can only reset the counter when the CHANGE DRUM SOON message is on the display. After replacing the drum, clear the message by performing the following:

- 1. Wait until the time, date and the answering mode appear on the display.
- 2. Press the SELECT FUNCTION key.
- 3. Press the one-touch 7 key. The display shows DRUM COUNT.
- 4. Press the Yes key to clear the image drum unit counter.
- 5. Press the STOP key to finish and return to normal operation.

Note: The CHANGE DRUM SOON message is a warning that the image drum cartridge in the fax may be approaching the end of its usable life. CAUTION: Do not reset the drum counter at this time, as this will accelerate drum life deterioration.

The drum has used approximately 90% of its life based on an internal calculation. The drum yield count is based on the following print criterion: Using the ITU-T 4% Test Chart #1:

7

- 1 page jobs yields approximately 9000 sheets.
- 3 page jobs yields approximately 14,000 sheets.

Solution Usage

1

1

1

1

Solution Usage

Solution Usage 1

Solution Usage

Continuous job yields approximately 20,000 sheets.

The CHANGE DRUM SOON message does not mean that the drum must be replaced immediately, nor does it cause the fax to stop working. The drum can be used as long as print quality is acceptable, however, a replacement image drum and toner cartridge should be on hand. Replace the drum when print quality deteriorates below an acceptable level.

Solution ID TAUS0610841EN00

Description

How to print an activity journal.

Solution

To print an Activity Journal, perform the following:

- 1. Press the Select Function button.
- 2. Press the Report Print one-touch 6 button.
- 3. Press the Yes button.

Solution ID TAUS0611486EN00

Description

Can quick dial be disabled?

Solution

Quick dial cannot be disabled.

Solution ID TAUS0612817EN00

Description

How to adjust the line monitor speaker volume.

Solution

To adjust the line monitor speaker volume, perform the following:

1. Power the machine OFF.

2. Press and hold the Select Function button down while powering the machine ON.

3. Press YES.

4. Enter 0 then 6.

Note: Do not use the one-touch button 6.

5. Press NO to select OFF, LOW or high.

6. Press yes after making selection.

7. Press stop until the normal standby screen is displayed.

Solution ID TAUS0613023EN00

Description

Does the FAX 9660 have dual access?

Solution

Yes, the FAX 9660 has dual access. This feature allows you to load and prepare multiple documents for transmission while the FAX 9660 is sending or receiving another fax.

Note: This feature will not work when the fax unit is dialing a number to transmit. Once a connection is made, the originals can be loaded and scanned for transmission.

8

Solution ID TAUS0614119EN00

Description

How many activity journal transmissions can be stored on the activity journal log?

Solution

The activity journal stores a maximum of 30 transmissions (the last 30 transmissions) which can also be printed.

Solution Usage

Solution Usage

Solution Usage

Solution Usage

1

1

1

1

1

Copyright 2006, Konica Minolta Business Solutions U.S.A., Inc.

FAX 9660

TAUS0614859EN00 Solution ID

Description

Can the fax be connected to a T1 digital line.

Solution

The fax unit must connected to an analog phone line to communicate.

Solution ID TAUS0614875EN00

Description

Black band from lead-to-trail on copies and transmitted faxes. Received faxes and internal reported are fine.

Solution

CAUSE: The Contact Image Sensor (CIS) is soiled or defective.

SOLUTION: Clean the CIS and white reference roller. If the problem persists, replace CIS (p/n 40141401).

Solution ID TAUS0615110EN00

Description

How to program a one-touch key.

Solution

To program a one-touch number, perform the following:

- 1. Press the Select Function key.
- 2. Press the one-touch 8 program key. The display shows LOCATION PROGRAMMING ENTER (SRCH, OT, A/D, #).
- 3. Press a one-touch key 1-15 to program. The display briefly shows NO= , ID= .
- Note: To program one touch keys 16-30, lift the one-touch keyboard up and swing to the right.
- 4. After the display clears, enter the main fax number and press the Start key. The display shows NO= for about three seconds.
- 5. Enter the optional alternate fax number if desired.
- 6. Press the Start key to finish programming. The display shows LOCATION PROGRAMMING.
- 7. To continue programming go back to step 3.
- 8. When completed, press the Select Function key.

Solution ID TAUS0618246EN00

Description

Unable to select features after the select function key has been pressed with the one-touch keys.

Solution

CAUSE: The one-touch keypad cover is not actuating the switch on the operator panel board so that one-touch keys 16 through 30 are the only available keys

SOLUTION: Fully close the one touch keypad cover or adjust so that the switch is actuated.

TAUS0607980EN00 Solution ID

Description

Availability of the FAX 9660.

Solution

The FAX 9660 was introduced in Info Source Branch Bulletin #42-00 .

Solution ID TAUS0610583EN00



Solution Usage

0 Solution Usage

Solution Usage 0

Solution Usage

1

1

1

1

Description

How to enable the TCR.

Solution

To enable the TCR, perform the following:

- 1. Power ON the machine while pressing the SELECT FUNCTION button.
- 2. Press YES.
- Press 0 and then 1.
 Press NO to cycle between ON or OFF.
- Press NO to cycle between ON or C
 Press YES to save setting.
- 6. Press STOP three times.
- 0. Tress STOT three times.

Solution ID TAUS0610642EN00

Description

Video training available for the FAX 9660.

Solution

Video training is available for the FAX 9660 and the FAX 9760 using the FAX 9820 Technical Training Video (p/n FVT-9820). See Media Bulletin #64 for more details.

Solution ID TAUS0616099EN00

Description

FAX 9660 will print same fax multiple times

Solution

CAUSE: Memory is corrupted.

SOLUTION: Initialize the machine by performing the following:

- 1. Power machine OFF.
- 2. Hold the copy key down while powering the machine ON.
- 3. Press 3.
- 4. Press the LEFT ARROW key three times.

5. Press STOP to return to the standby display.

Solution ID TAUS0619613EN00

Description

Jamming and/or paper skew from the Second Paper Feed Tray accompanied by a squeaking noise and evidence of wear on the paper tray feed roller.

Solution

CAUSE: Improperly installed paper weight bar (reversed). The placement angle of the weight bar is not correct.

SOLUTION: Reverse the paper weight bar by removing the retaining clamps on the two ends of the weight bar and reinstall the bar in the correct position. Replace the paper tray feed roller (p/n 50409501) and/or the paper separator pad (p/n 53345801) if there is evidence of excessive wear.

Solution ID TAUS0630560EN00

Description

How to enable the Transmit/Message Confirmation Report (MCF,TCR).

Solution

- To enable the TCR, perform the following:
- 1. Press the SELECT FUNCTION key.
- 2. Press one-touch key 9.
- 3. Press YES.
- Press 0 and then 1.
 Press NO to cycle between ON or OFF.
- 6. Press YES to save setting.
- 7. Press STOP three times to return to normal operation.

Solution Usage

0

0

0

Solution Usage

TAUS0630609EN00 Solution ID

Description

How to enable the Service Bit.

Solution

To enable the Service Bit:

- 1. Power off the Fax.
- 2. Hold the COPY key down and Power ON. TECHNICAL PROGRAMMING will be displayed.
- 3. Selection by YES/NO keys or digit (1 to 8).
- 4. Select 2 and press YES key.
- 5. TECHNICAL FUNCTION will display; push 0 then 1 in the [01] press YES key.
- 6. Service Bit will be displayed and *OFF will be displayed; select NO and the OFF will change to ON, then press YES.
 7. Press Auto Reset to return to Technical Programming and then power OFF fax and power back ON.