User's Manual

# **TY710, TY720**

Digital Multimeter ディジタルマルチメータ



Store this manual in a safe place for future reference.

この取扱説明書は,いつでも使用できるよう 大切に保管してください。

Japanese/ English



IM TY720 2nd Edition Sep. 2008(KYOU)

# ■取扱説明書に関する注意

- 本書の内容に関しては万全を期しておりますが、万一ご不審の点や誤りなどお気づきのことがありましたらお手数ですが、当社にご連絡ください。
- 本書の内容は、性能(機能)などの向上により将来予告なしに変更することがあります。
- ・本書の内容の全部または一部を無断で転載、複製することは禁止されています。

Thank you for purchasing our Model TY710, TY720 Digital Multimeter.

This user's manual describes the specifications and handling precaution for this Digital Multimeter.

Before using this Digital Multimeter, thoroughly read this manual to get a clear understanding on proper use.

Always observe the following instructions.

Failure to do so may result in electric shock or other dangers that may lead to serious injury or the loss of life.

Yokogawa is in no way liable for any damage resulting from the user's mishandling of the product.

For safe use of this product, the following safety symbols are used on the product:

# About This Manual

- Every effort has been made to ensure accuracy in the preparation of this manual. However, should any errors or omissions come to the attention of the user, please contact Yokogawa.
- The contents of this manual are subject to change without prior notice because of improvement in performance or function.
- All rights reserved. No part of this manual may be reproduced in any from without Yokogawa's written permission.

#### **Regarding Safe Use of This Product**

For safe use of this product, the following safety symbols are used on the product and manual:



This indicates that the operator must refer to an explanation in the instruction manual in order to avoid the risk of serious injury or the loss of life.



This indicates that the operator must refer to an explanation in the instruction manual in order to avoid the risk of injury or damage to the product.

**Note** This indicates information that is essential for handling the instrument or should be noted in order to familiarize yourself with the instrument's operating procedures and/or functions.



Danger! Handle with Care

This symbol indicates that the operator must refer to an explanation in the instruction manual in order to avoid risk of injury or death of personnel or damage to the instrument.



Double Insulation

This symbol indicates double insulation or reinforced insulation.

Direct Current This symbol indicates DC voltage/current.

Alternating Current

This symbol indicates AC voltage/current.



# DC/AC

This symbol indicates AC and DC.

Fuse

This symbol indicates a fuse.

Ground

This symbol indicates ground (earth).



■ Always observe the following instructions. Failure to do so may result in electrical shock or other dangers that may lead to serious injury or the loss of life.

#### **Testing leads**

- Use the probes supplied by Yokogawa with this instrument.
- Do not use testing leads that have deteriorated or are defective. Check testing leads continuity.
- Disconnect testing leads from the circuit under test before opening the casing to replace the batteries or for any other reason.
- Disconnect testing leads from the circuit under test before attaching/detaching the testing leads to/from the instrument.
- Disconnect testing leads from the instrument before opening the casing to replace the batteries or for any other reason.
- A cap is provided on the tip of a testing lead. Use a testing lead with the cap on for safety (safety standards: EN 61010-031).

#### Casing

• Do not use the instrument if there is any damage to the casing or when the casing is removed.

#### Fuses

• Use fuses of the specified rating when the fuse is replaced.

#### **Operating Environment**

- Do not operate the instrument in an atmosphere where any flammable or explosive gas is present.
- Avoid using the instrument if it has been exposed to rain or moisture or if your hands are wet.

#### Disassembly

· No person, except personnel from Yokogawa, is authorized to disassemble this instrument.

# Contents

| 1. | Overview   |     |
|----|--|-----|
| 2. | Measurement Category   | 64  |
| 3. | Specifications   | 65  |
|    | 3.1 General Specifications                                     | 65  |
|    | 3.2 Accuracy   |     |
| 4. | Operation  | 76  |
|    | 4.1 Precautions Before Measurement                             |     |
|    | 4.2 Components   | 77  |
|    | 4.3 Measuring Instructions                                     | 82  |
|    | 4.3.1 AC Voltage Measurement                                   | 82  |
|    | 4.3.2 DC Voltage Measurement                                   | 82  |
|    | 4.3.3 DC+AC Voltage Measurement                                |     |
|    | 4.3.4 DC, AC Voltage Dual Display                              | 83  |
|    | 4.3.5 Resistance Measurement                                   |     |
|    | 4.3.6 Low Power-Ω  |     |
|    | 4.3.7 Continuity Check   |     |
|    | 4.3.8 Diode Test   |     |
|    | 4.3.9 Temperature Measurement                                  |     |
|    | 4.3.10 Current Measurement                                     |     |
|    | 4.3.11 DC+AC Current Measurement                               | 88  |
|    | 4.3.12 DC, AC Current Dual Display                             | 89  |
|    | 4.3.13 Capacitor Measurement.                                  | 89  |
|    | 4.3.14 Frequency Measurement, Duty cycle ratio                 |     |
|    | 4.3.15 Function to change RMS detection to/from MEAN detection |     |
|    | mode   |     |
|    | 4.3.16 Function to turn the filter on/off                      |     |
|    | 4.3.17 AUTO HOLD Function                                      |     |
|    | 4.3.18 PEAK HOLD Function                                      |     |
|    | 4.3.19 Relative and percentage calculation                     |     |
|    | 4.3.20 Decibel calculation                                     |     |
|    | 4.3.21 MIN/MAX/AVG Function                                    | 95  |
|    | 4.4 Memory Function  |     |
|    | 4.5 AUTO POWER OFF Function                                    |     |
|    | 4.6 Set-up Function  | 100 |
|    | 4.7 Additional functions simply set when POWER ON              | 103 |
|    | 4.8 Averaging Function   | 103 |
|    | 4.9 5000 display mode  | 104 |
|    | 4.10 LCD Check   | 104 |

| 5. | User Calibration Function    |     |
|----|------------------------------|-----|
| 6. | Battery and Fuse Replacement |     |
|    | 6.1 Battery Replacement      |     |
|    | 6.2 Fuse Replacement         | 111 |
| 7. | Calibration and Maintenance  |     |
| 8  | Disposing the Product        |     |

# 1. Overview

#### • Fast and more accurate measurement

The TY710 and TY720 digital multimeters use  $\Delta\Sigma$  modulation for A/D conversion, which enable fast and more accurate measurement.

# • Display

5-digit (LCD) Maximum Reading: 50000 Bar graph indicator

#### Supports a variety of measurement function Measurement function

DC Voltage, AC Voltage, DC Current, AC Current, Resistance, Frequency, Temperature, Capacitor, Duty cycle ratio, Decibel (dBV, dBm), Continuity Check, Diode Test, LowPower- $\Omega^*$ 

#### Other functions

Data Hold (D•H), Auto Hold (A•H), Peak Hold\* (P•H), Range Hold (R•H), Maximum value (MAX), Minimum value (MIN), Average value (AVG), Zero Adjustment (Capacitor, Resistance), Relative values, Save to Memory, LCD backlight.

LowPower- $\Omega$ : Measures resistance under lowmeasurement current. \*: For model TY720 only

# • Switching detection modes

Effective value (root mean square value) detection (RMS) and mean value detection (MEAN) can be switched during AC voltage or AC current measurement (TY720 only).

# Low-pass filter

The low-pass filter can be switched on/off during AC voltage or AC current measurement (TY720 only).

# • Communication: optional communication package is required

• Measurement data can be transferred to a PC using an optional USB communication package.

The data can be read by certain applications to make trend graphs or can be converted into Excel files.

• The data can also be output from an optional printer via an optional RS232 cable.

# • Safety design

Complied standards: CE standards Uses a current-input terminal shutter for preventing wrong input. Uses high-performance UL-standard fuses.

# 2. Measurement Category

# 


#### Measurement Category (CAT.)

The restrictions on the maximum voltage level for which the TY710, TY720 can be used, depend on the measurement categories specified by the safety standards.

Do not apply any input level higher than maximum allowable input.

AC/DC 1000V CAT. III AC/DC 600V CAT. IV

|    | surement<br>tegory | Description  | Remarks                                   |
|----|--------------------|--|---|
| Ι  | CAT. I             | For measurements performed on circuits not directly connected to MAINS.                    |   |
| П  | CAT. II            | For measurements performed on circuits directly connected to the low voltage installation. | Appliances, portable equipment, ect.      |
| Ш  | CAT.III            | For measurements performed in the building installation.                                   | Distribution board, circuit breaker, ect. |
| IV | CAT. IV            | For measurements performed all the source of the low-voltage installation.                 | Overhead wire,<br>cable systems, ect.     |



# Note

Radiation immunity affects the accuracy of the TY710, TY720 under the conditions specified in EN61326-1.

Use of this instrument is limited to domestic, commercial, and light industry applications. If equipment generating strong electromagnetic interference is located nearly, the instrument may malfunction.

# 3.1 General Specifications

# Measurement function:

|                       | DC Voltage, AC Voltage, DC Current, AC Current, Resistance,            |  |  |  |  |  |  |
|-----------------------|--|--|--|--|--|--|--|
|                       | Frequency, Temperature, Capacitor, Duty cycle ratio,                   |  |  |  |  |  |  |
|                       | Decibel (dBV, dBm), Continuity Check, Diode Test, LowPower-Ω*          |  |  |  |  |  |  |
| Other functions:      | Data Hold (D•H), Auto Hold (A•H), Peak Hold* (P•H),                    |  |  |  |  |  |  |
|                       | Range Hold (R•H), Maximum value (MAX), Minimum value (MIN),            |  |  |  |  |  |  |
|                       | Average value (AVG), Zero Adjustment (Capacitor, Resistance),          |  |  |  |  |  |  |
|                       | Relative values, Save to Memory, LCD backlight.                        |  |  |  |  |  |  |
|                       | LowPower- $\Omega$ : Measures resistance under lowmeasurement current. |  |  |  |  |  |  |
|                       | *: For model TY720 only  |  |  |  |  |  |  |
| Measuring method:     | $\Delta\Sigma$ modulation  |  |  |  |  |  |  |
| Display:              | 5-digit (LCD)/7-segment  |  |  |  |  |  |  |
|                       | Maximum Reading: 50000   |  |  |  |  |  |  |
|                       | Polarity Indicator: "-" Appears automatically when the polarity is     |  |  |  |  |  |  |
|                       | negative   |  |  |  |  |  |  |
|                       | Overrange Indicator: " OL "  |  |  |  |  |  |  |
|                       | Low-battery Indicator: "I + - " Appears when the batteries become      |  |  |  |  |  |  |
|                       | low  |  |  |  |  |  |  |
| Measurement cycle:    | 6 times per second   |  |  |  |  |  |  |
|                       | (except frequency measurement: one times per second, Resistance        |  |  |  |  |  |  |
|                       | measurement : four times per second, capacitor measurement (50mF):     |  |  |  |  |  |  |
|                       | max. 0.03 time per second)   |  |  |  |  |  |  |
|                       | Bar graph display 15 times per second                                  |  |  |  |  |  |  |
| Operating temperatur  | re and humidity ranges:  |  |  |  |  |  |  |
|                       | -20 to 55°C, 80%RH or less (no condensation)                           |  |  |  |  |  |  |
|                       | 70%RH or less at 40 to 55°C.   |  |  |  |  |  |  |
| Storage temperature a | and humidity ranges:   |  |  |  |  |  |  |
|                       | -40 to 70°C, 70%RH or less (no condensation)                           |  |  |  |  |  |  |
| Temperature coefficie | ent:   |  |  |  |  |  |  |
|                       | (Accuracy at $23\pm5^{\circ}$ C) × 0.05/°C or less                     |  |  |  |  |  |  |
|                       | At -20 to 18°C and 28 to 55°C  |  |  |  |  |  |  |
|                       | When continuously DCV and DCA measuring, add 1digit / °C               |  |  |  |  |  |  |
|                       | (except for 50mV, 5A, 10A range, add 3digits / °C).                    |  |  |  |  |  |  |

| Power supply:           | AA-size (R6) 1.5V batteries: 4                                       |
|-------------------------|--|
| Battery life:           | Approximately 120 hours  |
|                         | (Operating hours of alkaline batteries when in DC voltage-mode.)     |
|                         | Note: The battery life varies depending on the operating conditions. |
| Insulation resistance : | $1000V DC$ , $100M\Omega$ or more                                    |
| Withstand voltage:      | 6.88kVrms AC for five seconds  |
|                         | (across input terminals and casing)                                  |
| External dimensions:    | Approximately 90(W)×192(H)×49(D)mm                                   |
| Weight:                 | Approximately 560g (including batteries)                             |
| Complied standards:     | Safety standards   |
|                         | EN61010-1, EN61010-031   |
|                         | CAT.III (Max. input voltage: AC/DC1000V)                             |
|                         | CAT.IV (Max. input voltage: AC/DC600V)                               |
|                         | Pollution degree 2, indoor use,                                      |
|                         | 2000m max. above sea level   |
|                         | EMC standards  |
|                         | EN61326-1 Class B  |
|                         | EN55011 Class B Group 1  |
| Effect of radiation im  | munity:  |
|                         | In the radio-frequency electromagnetic field of 3 V/m, accuracy is   |

within five times the rated accuracy.

Standard accessories: Batteries : 4 Testing leads: 1set (Model 98015) Fuse (included): 440mA/1000V (99015), 10A/1000V (99016) Use's manual: 1

Optional accessories: Carrying case 93029 (for the main unit with testing leads and communication cable) 98015 Testing leads (1set) Fuse 440mA/1000V 99015 10A/1000V 99016 Temperature probes 90050, 90051, 90055, 90056 Communication Package for DMM 92015 (Software, USB adapter and cable) Printer Adapter and Cable 97016 97010 Printer AC adapter (for printer, Europe) 94006 Thermal paper for printer (10 rolls) 97080

# 3.2 Accuracy

Test conditions:

Temperature and humidity: 23±5°C at 80%RH or less Accuracy: ±(% of reading + digits)

Note: Each response time is a value to rated accuracy within selected range.

| Range  | Resolution | Accuracy     | Input Resistance | Maximum<br>Input Voltage |  |  |  |  |  |
|--------|------------|--------------|------------------|--------------------------|--|--|--|--|--|
| _      |            | TY710, TY720 | -                | input voltage            |  |  |  |  |  |
| 50mV   | 0.001mV    | 0.05+10      |                  |                          |  |  |  |  |  |
| 500mV  | 0.01mV     | 0.02+2       | Approx. 100MΩ    | 1000V DC                 |  |  |  |  |  |
| 2400mV | 0.1mV      | 0.02+2       |                  |                          |  |  |  |  |  |
| 5V     | 0.0001V    | 0.025+5      |                  | ]                        |  |  |  |  |  |
| 50V    | 0.001V     |              | 10140            | 1000V rms AC             |  |  |  |  |  |
| 500V   | 0.01V      | 0.03+2       | 10MΩ             | 1000 v rms AC            |  |  |  |  |  |
| 1000V  | 0.1V       |              |                  |                          |  |  |  |  |  |

DC Voltage Measurement \_\_\_\_ V

NMRR: 80dB or more 50/60Hz ±0.1%

(70dB or more 50/60Hz  $\pm 0.1\%$  when 50mV Range)

CMRR: 100dB or more 50/60Hz (Rs=1kΩ)

Response time: 0.3 sec max.

#### AC Voltage Measurement [RMS] ~ V TY710

AC Coupling, Rms-value detection, Crest factor\*: <3

| Range   | Resolution |            | Accu            | Input<br>Impe- | Maximum<br>Input |               |          |        |       |        |
|---------|------------|------------|-----------------|----------------|------------------|---------------|----------|--------|-------|--------|
|         |            | 10 to 20Hz | 20Hz to<br>1kHz | 1k to<br>10kHz | 10k to<br>20kHz  | dance         | Voltage  |        |       |        |
| 500mV   | 0.01mV     |            |                 |                |                  | 11MΩ          |          |        |       |        |
| 5V      | 0.0001V    | 1.5+30 *1  | 0.7+3           | 20 *1          | 2+50 *2          | <50pF         | 1000V    |        |       |        |
| 50V     | 0.001V     | 1.5+50 1   | 0.7+2           | 0.74.          | 0.7+.            | 0.7+.         | 50 . 1   | 2+30 2 | 101/0 | rms AC |
| 500V    | 0.01V      |            |                 |                |                  | 10MΩ<br><50pF | 1000V DC |        |       |        |
| 1000V * | 0.1V       | *2         | *2              | 3+30 *2        | -                | <50pr         |          |        |       |        |

\*: Crest factor <1.5 at 1000V range

Accuracy \*1: At 5 to 100% of range, \*2: At 10 to 100% of range

CMRR: 80dB or more DC to 60Hz (Rs=1kΩ)

Response time: 1 sec max.

#### AC Voltage Measurement [RMS] ~ V

#### TY720

AC Coupling, Rms-value detection, Crest factor\*: <3

|        |                 |               |   |                | Maximum         |                 |                  |                    |        |
|--------|-----------------|---------------|---|----------------|-----------------|-----------------|------------------|--------------------|--------|
| Range  | Reso-<br>lution | 10 to<br>20Hz | 20Hz to<br>1kHz                                       | 1k to<br>10kHz | 10k to<br>20kHz | 20k to<br>50kHz | 50k to<br>100kHz | Input<br>Impedance | Input  |
| 50mV   | 0.001mV         | 2+80<br>*2    | $\begin{array}{c ccccccccccccccccccccccccccccccccccc$ |                | 11MΩ            | 1000V           |                  |                    |        |
| 500mV  | 0.01mV          |               |   |                |                 |                 |                  | <50pF              | rmsAC  |
| 5V     | 0.0001V         | 1+30          | 0.4+  | -30            | 1+40            | 2+70            | 5+200            |                    |        |
| 50V    | 0.001V          | *1            | *   | *1             |                 | *2              | *2               |                    | 100077 |
| 500V   | 0.01V           |               |   |                |                 |                 |                  | 10MΩ               | 1000V  |
| 1000V* | 0.1V            | *2            | *2  | 3+30<br>*2     |                 | -               |                  | <50pF              | DC     |

\*: Crest factor <1.5 at 1000V range

Accuracy \*1: At 5 to 100% of range, \*2: At 10 to 100% of range

CMRR: 80dB or more DC to 60Hz (Rs=1kΩ)

Response time: 1 sec max.

#### AC Voltage Measurement [MEAN] ~~V

#### TY720

AC Coupling, MEAN value detection, RMS value calibration (sine wave)

|       |                 |             |              | Maximum        |                    |                  |
|-------|-----------------|-------------|--------------|----------------|--------------------|------------------|
| Range | Reso-<br>lution | 10 to 20 Hz | 20 to 500 Hz | 500Hz to 1 kHz | Input<br>Impedance | Input<br>Voltage |
| 50mV  | 0.001mV         | 4+80<br>*2  | 1.5+30<br>*2 | 5+30<br>*2     | 11MΩ               | 1000V            |
| 500mV | 0.01mV          |             |              |                | <50pF              | rmsAC            |
| 5V    | 0.0001V         | 2+30        | 1+30         | 3+30           |                    |                  |
| 50V   | 0.001V          | *1          | *1           | *1             | 101/0              | 1000V            |
| 500V  | 0.01V           |             | [            |                | 10MΩ<br><50pF      | DC               |
| 1000V | 0.1V            | *2          | *2           | *2             | ~50pr              |                  |

Accuracy \*1: At 5 to 100% of range, \*2: At 10 to 100% of range CMRR: 80dB or more DC to 60Hz (Rs= $1k\Omega$ )

Response time: 1 sec max.

#### DCV+ACV === + ~ TY710

# Maximum Reading 50000, Crest factor\*: <3

|        |            |           |          | ıracy     | Input    | Maximum       |          |
|--------|------------|-----------|----------|-----------|----------|---------------|----------|
| Range  | Resolution | DC, 10 to | DC, 20Hz | DC, 1k to | DC, 10k  | Impe-         | Input    |
|        |            | 20Hz      | to 1kHz  | 10kHz     | to 20kHz | dance         | Voltage  |
| 5V     | 0.0001V    |           |          |           |          | 11MΩ          | 100017   |
| 51     | 0.0001 V   | 1.5+10    | 1+       | 1+10      |          | <50pF         | 1000V    |
| 50V    | 0.001V     | *1        | *        | 1         | *2       | 101/0         | rms AC   |
| 500V   | 0.01V      |           |          |           |          | 10MΩ<br><50pF | 1000V DC |
| 1000V* | 0.1V       | *2        | *2       |           | -        | Sobt          | 10001 DC |

# dcv+acv ===+ $\sim$

TY720

Maximum Reading 50000, Crest factor\*: <3

|        |                 |                   | Accuracy               |                       |                        |                        |                         |                         |                         |
|--------|-----------------|-------------------|------------------------|-----------------------|------------------------|------------------------|-------------------------|-------------------------|-------------------------|
| Range  | Reso-<br>lution | DC, 10<br>to 20Hz | DC,<br>20Hz to<br>1kHz | DC,<br>1k to<br>10kHz | DC,<br>10k to<br>20kHz | DC,<br>20k to<br>50kHz | DC,<br>50k to<br>100kHz | Input<br>Impe-<br>dance | mum<br>Input<br>Voltage |
| 5V     | 0.0001V         | 1.5+10            | 0.5-                   | +10                   | 1+10                   | 2+10                   | 5+20                    | 11MΩ<br><50pF           | 1000V<br>rms AC         |
| 50V    | 0.001V          | *1                | *                      | 1                     | *1                     | *2                     | *2                      | 101/0                   |                         |
| 500V   | 0.01V           |                   |                        |                       |                        |                        |                         | 10MΩ<br><50pF           | 1000V                   |
| 1000V* | 0.1V            | *2                | *2                     |                       |                        | -                      |                         | Sobr                    | DC                      |

\*: Crest factor <1.5 at 1000V range

Accuracy \*1: At 5 to 100% of range, \*2: At 10 to 100% of range

CMRR: 80dB or more DC to 60Hz (Rs=1kΩ) Response time: Approx. 2 sec

#### DC Current Measurement \_\_\_\_A

| Range   | Resolution | Accuracy<br>TY710, TY720 | Voltage Drop          | Maximum Input<br>Current |
|---------|------------|--------------------------|-----------------------|--------------------------|
| 500μΑ   | 0.01µA     |                          | <0.11mV/µA            |                          |
| 5000μΑ  | 0.1µA      | 0.2+5                    | <0.11111 <b>ν</b> /μΑ | 440mA Protected by a     |
| 50mA    | 0.001mA    | 0.2+3                    | <4mV/mA               | 440mA/1000V fuse.        |
| 500mA*3 | 0.01mA     |                          | ~4III V/III/A         |                          |
| 5A      | 0.0001A    | 0.6+10                   | <0.1V/A               | 10A Protected by a       |
| 10A     | 0.001A     | 0.6+5                    | ~0.1 V/A              | 10A/1000V fuse.          |

\*3: Maximum measurement current : 440mA at 500mA range

Response time: 0.3 sec max.

Note : After measuring over 500mA DC (especially 10A DC), "Zero error" occurs for a while. In that case, please wait for a while at zero input until the value stabilizes before measuring again.

# AC Current Measurement [RMS] $\sim$ A TY710

Rms-value detection, Crest factor: <3

| Range   | Resolution | Accu       | uracy        | Voltage Drop | Maximum Input                  |
|---------|------------|------------|--------------|--------------|--------------------------------|
| Kange   | Resolution | 10 to 20Hz | 20Hz to 1kHz | voltage Diop | Current                        |
| 500µA   | 0.01µA     |            |              | <0.11 mV/µA  | 440 A D A A A                  |
| 5000µA  | 0.1µA      |            |              | <0.11 mv/μA  | 440mA Protected<br>by a 440mA/ |
| 50mA    | 0.001mA    | 1.5+20     | 1+20         | <4mV/mA      | 1000V fuse.                    |
| 500mA*3 | 0.01mA     | 1.5+20     |              |              | 1000 1 1000.                   |
| 5A      | 0.0001A    |            |              | <0.1V/A      | 10A Protected by a             |
| 10A     | 0.001A     |            |              | <0.1 V/A     | 10A/1000V fuse.                |

# AC Current Measurement [RMS] ~ A TY720

Rms-value detection, Crest factor: <3

| Danga    | Resolution |            | Accuracy     |            | Voltage  | Maximum Input              |
|----------|------------|------------|--------------|------------|----------|----------------------------|
| Range    | Resolution | 10 to 20Hz | 20Hz to 1kHz | 1k to 5kHz | Drop     | Current                    |
| 500µA    | 0.01µA     |            |              |            | < 0.11   |                            |
| 5000µA   | 0.1µA      | 1+20       | 0.75 + 20    | 1+30       | mV/μA    | 440mA Protected            |
| 50mA     | 0.001mA    | 1+20       | 0.75 +20     |            | <4 mV/mA | by a 440mA/<br>1000V fuse. |
| 500mA *3 | 0.01mA     |            |              |            |          | 1000 1 1050.               |
| 5A       | 0.0001A    | 1.5+20     | 1+20         | 2+30       | <0.1 V/A | 10A Protected by           |
| 10A      | 0.001A     | 1.5+20     | 1+20         | 2750       | ~0.1 V/A | a 10A/1000V fuse.          |

Model TY710/720

Accuracy At 5 to 100% of range, At 10 to 100% of range for 10A Range

\*3: Maximum measurement current : 440mA at 500mA range

Response time: 1 sec max.

# AC Current Measurement [MEAN] $\sim$ A TY720

MEAN value detection, RMS value calibration (sine wave)

|         |            |            | Accuracy     |                  | Voltage  | Maximum Input                  |
|---------|------------|------------|--------------|------------------|----------|--------------------------------|
| Range   | Resolution | 10 to 20Hz | 20 to 500Hz  | 500Hz to<br>1kHz | Drop     | Current                        |
| 500µA   | 0.01µA     |            |              |                  | < 0.11   | 440 A D A A A                  |
| 5000μΑ  | 0.1µA      | 2+20       | $1.5 \pm 20$ | 2+30             | mV/μA    | 440mA Protected<br>by a 440mA/ |
| 50mA    | 0.001mA    | 2+20       | 1.5 +20      | 2+30             | <4 mV/mA | 100077.0                       |
| 500mA*3 | 0.01mA     |            |              |                  |          | 1000 v Tube.                   |
| 5A      | 0.0001A    |            |              |                  |          | 10A Protected                  |
| 10A     | 0.001A     | 3+20       | 2+20         | 4+30             | <0.1 V/A | by a 10A/<br>1000V fuse.       |

Accuracy At 5 to 100% of range, At 10 to 100% of range for 10A Range

\*3: Maximum measurement current : 440mA at 500mA range

Response time: 1 sec max.

#### DCA+ACA === + ~ TY710

Maximum Reading 50000, Crest factor: <3

|         |            | Accı              | ıracy               |              | Maximum Input        |
|---------|------------|-------------------|---------------------|--------------|----------------------|
| Range   | Resolution | DC, 10 to<br>20Hz | DC, 20Hz to<br>1kHz | Voltage Drop | Current              |
|         |            | 2002              | ткпа                |              |                      |
| 500μΑ   | 0.01µA     |                   |                     | <0.11 mV/µA  |                      |
| 5000µA  | 0.1µA      |                   |                     | <0.11 mv/μA  | 440mA Protected by a |
| 50mA    | 0.001mA    | 2+10              | 1.5+10              | <4mV/mA      | 440mA/1000V fuse.    |
| 500mA*3 | 0.01mA     | 2+10              | 1.5+10              |              |                      |
| 5A      | 0.0001A    |                   |                     | <0.1V/A      | 10A Protected by a   |
| 10A     | 0.001A     |                   |                     | <0.1 V/A     | 10A/1000V fuse.      |

Accuracy At 5 to 100% of range, At 10 to 100% of range for 10A Range

\*3: Maximum measurement current : 440mA at 500mA range

Response time: 2 sec max.

#### DCA+ACA ===+ ~ TY720

Maximum Reading 50000, Crest factor: <3

|         |            |                | Accuracy            |                   |              | Maximum Input                                 |
|---------|------------|----------------|---------------------|-------------------|--------------|---|
| Range   | Resolution | DC, 10 to 20Hz | DC, 20Hz<br>to 1kHz | DC, 1k to<br>5kHz | Voltage Drop | Current                                       |
| 500µA   | 0.01µA     | ZOTIL          | to mil              | UNITE             |              |   |
| 5000µA  | 0.1µA      |                |                     |                   | <0.11 mV/µA  | 440mA Protected<br>by a 440mA/<br>1000V fuse. |
| 50mA    | 0.001mA    | 1.5+10         | 1+10                | 1.5+10            | <4 X7/ A     |   |
| 500mA*3 | 0.01mA     | 1              |                     |                   | <4 mV/mA     | 1000 v 1030.                                  |
| 5A      | 0.0001A    | 2+10           | 1.5+10              | 2+10              | <0.1 V/A     | 10A Protected by a                            |
| 10A     | 0.001A     | 2+10           | 1.5+10              | 3+10              | <0.1 V/A     | 10A/1000V fuse.                               |

Accuracy At 5 to 100% of range, At 10 to 100% of range for 10A Range

\*3: Maximum measurement current : 440mA at 500mA range

Response time: Approx. 2 sec

#### Resistance Measurement $\Omega$

| Panga | Resolution | Accu  | ıracy  | Maximum<br>Measuring | Open-loop | Input Protective |
|-------|------------|-------|--------|----------------------|-----------|------------------|
| Range | Resolution | TY710 | TY720  | Current              | Voltage   | Voltage          |
| 500Ω  | 0.01Ω      |       |        | <1mA                 |           |                  |
| 5kΩ   | 0.0001kΩ   | 0.1+2 | 0.05+2 | <0.25mA              |           |                  |
| 50kΩ  | 0.001kΩ    | *1    | *1     | <25µA                | <2.5V     | 1000V rms        |
| 500kΩ | 0.01kΩ     |       |        | <2.5µA               | ~2.3 V    | 1000 V 11115     |
| 5MΩ   | 0.0001MΩ   | 0.5   | 5+2    | <1.5µA               |           |                  |
| 50MΩ  | 0.001MΩ    | 1-    | +2     | <0.13µA              |           |                  |

\*1: Accuracy is specified after zero adjustment (resistance).

Response time: 1 sec max. at  $500\Omega$  to  $500k\Omega$ 

5 sec max. at 5M $\Omega$  to 50M  $\Omega$ 

#### LowPower-Ω LP-Ω

Maximum Reading 5000

| Range  | Resolution | Accuracy   | Maximum<br>Measuring | Open-loop | Input Protective |
|--------|------------|------------|----------------------|-----------|------------------|
| Kalige | Resolution | TY720 only | Current              | Voltage   | Voltage          |
| 5kΩ    | 0.001kΩ    |            | <10µA                |           |                  |
| 50kΩ   | 0.01kΩ     | 0.2+3      | <1.0µA               | <0.7V     | 1000V rms        |
| 500kΩ  | 0.1kΩ      |            | <0.6µA               | <0.7 V    | 1000 v 11115     |
| 5MΩ    | 0.001MΩ    | 1+3        | <0.05µA              |           |                  |

LowPower- $\Omega$ : Measures resistance under lowmeasurement current.

# Continuity Check ....)

Maximum Reading 5000

| Range | Resolution | Range of Operation  | Measuring<br>Current | Open-loop<br>Voltage | Input Protective<br>Voltage |
|-------|------------|---|----------------------|----------------------|-----------------------------|
| 500Ω  | 0.1Ω       | The buzzer turns on for resistances lower than $100\pm50\Omega$ . | Annrov               | <5V                  | 1000V rms                   |

| Range | Resolution | Accuracy | Measuring Current<br>(Vf=0.6V) | Open-loop<br>Voltage | Input Protective<br>Voltage |
|-------|------------|----------|--------------------------------|----------------------|-----------------------------|
| 2.4V  | 0.0001V    | 1+2      | Approx. 0.5mA                  | <5V                  | 1000V rms                   |

#### Temperature Measurement TEMP

| Range          | Resolution | Accuracy | Input Protective<br>Voltage |
|----------------|------------|----------|-----------------------------|
| -200 to 1372°C | 0.1°C      | 1+1.5°C  | 1000V rms                   |

Use optional Temperature Probe: Thermocouple Type K

# 

Maximum Reading 5000

| Range | Resolution | Accuracy | Input Protective Voltage |
|-------|------------|----------|--------------------------|
| 5nF   | 0.001nF    |          |                          |
| 50nF  | 0.01nF     | 1.5      |                          |
| 500nF | 0.1nF      | 1+5      |                          |
| 5µF   | 0.001µF    | 1        | 1000V rms                |
| 50µF  | 0.01µF     |          | 1000 v 11115             |
| 500µF | 0.1µF      | 2+5      |                          |
| 5mF   | 0.001mF    | 3+5      |                          |
| 50mF  | 0.01mF     | 5+5      |                          |

\*1: Accuracy is specified after zero adjustment (capacitor).

#### Frequency Measurement Hz

#### AC Coupling, Maximum Reading 9999

| Range (AUTO)      | Resolution | Accuracy |
|-------------------|------------|----------|
| 2.000 to 9.999Hz  | 0.001Hz    |          |
| 9.00 to 99.99Hz   | 0.01Hz     | 0.02+1   |
| 90.0 to 999.9Hz   | 0.1Hz      | *1       |
| 0.900 to 9.999kHz | 0.001kHz   |          |
| 9.00 to 99.99kHz  | 0.01kHz    | *2       |

Accuracy

\*1: At 10 to 100% of input voltage or current range

\*2: At 40 to 100% of input voltage or current range

#### Duty cycle ratio %

| Range     | Resolution Accuracy |             |
|-----------|---------------------|-------------|
| 10 to 90% | 1%                  | $\pm 1\%*1$ |

Accuracy

\*1: At 10.00Hz to 500.0Hz, square wave

At 40 to 100% of input voltage or current range

#### Peak Hold P•H

Model TY720 only

Maximum Reading 5000

| Range    | Accuracy   | Response Time Maximum |
|----------|------------|-----------------------|
| DCV, DCA | ±100 digit | >250µS                |

# 4. Operation

# 4.1 Precautions Before Measurement

## Examining Items Contained in the Package

After opening the package, be sure to examine the product as instructed below before use. Should the delivered product be the wrong model, lack any item, or show any flaw in its appearance, contact the vendor from which you purchased the product.

# Precautions of Operation and Storage



- Insert the batteries in the instrument by referring to "6.1 Battery Replacement."
- A Blank cover is provided on the upper part of back casing. Don't remove the Blank cover except when the USB adapter or Printer adapter is connected.
- Do not use the instrument near noise-emitting equipment or where there may be a sudden change of temperature. Otherwise, the instrument may give an unstable reading or errors.

#### **Removal of Dirt**

Do not wipe the instrument using any solvent (chemicals) such as benzine or paint thinner, as this may damage or discolor the front panel.

Use a dry cloth to clean the instrument.


#### **Storage Conditions**

- Do not leave the instrument exposed to direct sunlight or in a hot and humid location such as the inside of a vehicle, for any prolonged length of time.
- If the instrument will not be used for a prolonged period, remove the batteries.

# 4.2 Components

#### Panel Description





# 1) Function switch

| OFF             | Turns off the power.         | Ω    | Resistance measurement    |
|-----------------|------------------------------|------|---------------------------|
| $\sim$ v        | AC voltage (V) measurement   |      | Capacitor measurement     |
| $\sim_{\rm mV}$ | AC voltage (mV) measurement  | TEMP | Temperature measurement   |
| V               | DC voltage (V) measurement   | μA   |                           |
| mV              | DC voltage (mV) measurement  | mA   | DC/AC current measurement |
| -K              | Continuity check, Diode Test | А    |                           |

Turns off the power or select the measurement mode (function).

# 2) SELECT key

Pressing this key in each measurement modes (function) described above selects other measurement modes (function).

| $\sim$ V, $\sim$ mV | 1  | HzV            | : Frequency measurement<br>(Voltage value is displayed.) |
|---------------------|--|----------------|--|
|                     | 2  | Hz%            | : Frequency measurement<br>(Duty cycle ratio)            |
|                     | 3  | dBV            | : dBV measurement<br>(Voltage value is displayed.)       |
|                     | 4  | dBm            | : dBm measurement  |
| <del></del> V       | $m_+ \sim$   | (DC+AC) measur | rement, (DC, AC) Dual display                            |
| Ω                   | LP- $\Omega$ (Model TY720 only)  |                |  |
| -)))                |  |                |  |
| $\mu A/mA/A$        | Pressing this key in each measurement modes (function) described above selects other measurement modes (function). |                |  |
|                     | 1  | $\sim$         | : AC voltage measurement                                 |
|                     | 2  | -              | : (DC+AC) measurement                                    |
|                     | 3  | $=$ . $\sim$   | : (DC, AC) Dual display                                  |
|                     | 4  | Hz%            | : Frequency measurement<br>(Duty cycle ratio)            |
|                     |  |                |  |

#### 3) RANGE key

Allows the operator to select the measuring range.

| Fixed ranges | : The display shows the "R•H " symbol.                      |
|--------------|---|
|              | The range increases every time this key is pressed.         |
| AUTO range   | : The display shows the "AUTO" symbol.                      |
|              | To return to the auto-ranging mode, hold down RANGE key for |
|              | more than one second.                                       |

#### 4) HOLD key

Selects between the DATA HOLD, AUTO HOLD and PEAK HOLD functions. To cancel functions, press this key once again.

| DATA HOLD: | Holds the display readings.                                  |
|------------|--|
|            | The display shows the "D•H " symbol.                         |
| AUTO HOLD: | Holds the measured value when the testing leads are handled. |
|            | The display shows the "A•H " symbol.                         |
| PEAK HOLD: | Holds the peak value.  |
|            | The display shows the "P•H " symbol. (Model TY720 only)      |

#### 5) LIGHT key

LIGHT key: Use to turn on the LCD backlight.

Press this key once to turn on the LCD backlight for approximately one minute.

The LCD backlight is lit for approximately one minute.

(To postpone turned on time, press this key once again.)

To cancel the function, hold down this key for more than one second.

#### 6) REL $\Delta$ / % key

The instrument can calculate relative values or differences, and percentage values from the reference measurement values.

1: Relative Calculation

The display shows the " $\varDelta$ " symbol.

The sub-display shows the reference voltage value.

2: Percentage Calculation

The display shows the " $\Delta$ ", "%" symbol. The sub-display shows the reference voltage value.

#### 7) MIN/MAX key

Displays the minimum value (MIN), maximum value (MAX) and average value (AVG) during measurement.

Pressing this key starts recording and at the same time the display shows MIN/MAX/AVG to release AUTO POWER OFF.

# 8) MEMORY key


Data can be stored in internal memory using this key. Used when outputting to printer with the optional adapter and cable.

#### 9) SHIFT key

While this key is pressed, "Shift" appears on the display. Pressing the following keys with the SHIFT key held down enables the following settings.

|        | LIGHT key | Set-up function       |              |
|--------|-----------|-----------------------|--------------|
| SHIFT+ | RANGE key | Change to [RMS] mode  | (TY720 only) |
| SHIFT  | REL key   | Change to [MEAN] mode | (TY720 only) |
|        | HOLD key  | Turn filter on/off    | (TY720 only) |

#### Display (LCD) Description



| Symbol and Unit          | Description  |
|--------------------------|--|
|                          | Appears when in DC-mode measurement  |
| $\sim$                   | Appears when in AC-mode measurement  |
| $=+\sim$                 | Appears when in DC+AC-mode measurement   |
| -                        | Appears when the polarity is negative  |
|                          | Appears when in diode test   |
| -)))                     | Appears when in continuity check   |
| Δ                        | Relative calculation indicator   |
| R•H                      | Fixed ranges indicator   |
| AUTO                     | AUTO range indicator   |
| D-H                      | DATA HOLD indicator  |
| A·H                      | AUTO HOLD indicator  |
| P-H                      | PEAK HOLD indicator  |
| MAX                      | Lit when in MIN/MAX/AVG-mode   |
|                          | Lit when in MIN/MAX/AVG-mode   |
| AVG                      | Lit when in MIN/MAX/AVG-mode   |
| MEM                      | Lit when in Memory function  |
| AUTO OFF                 | Auto power off indicator   |
| RMS                      | Appears in RMS mode  |
| LP-Ω                     | Appears in Low Power- $\Omega$ measurement   |
| Filter                   | Appears while filter is on   |
| Shift                    | Appears while the SHIFT key is held down   |
| nF, μF, mF               | Unit for capacitance measurement   |
| mV, V                    | Unit for voltage measurement   |
| μA, mA, A                | Unit for current measurement   |
| MΩ, kΩ, Ω                | Unit for resistance measurement  |
| °C                       | Unit for temperature measurement   |
| kHz, Hz                  | Unit for frequency measurement   |
| dB, dBm                  | Decibel calculation indicator  |
| % (Main-display)         | Unit for percentage calculation  |
| % (Sub- display)         | Unit for duty cycle ratio calculation  |
| mV, V (Sub- display)     | Unit for voltage measurement $(dB^V, Hz^V)$  |
| s (Sub- display)         | Unit for recording time when in MIN/MAX/AVG-mode   |
| -88888<br>(Sub- display) | Recording time indicator when in MIN/MAX/AVG-mode<br>Number of saved data indicator<br>Reference value indicator when relative calculation<br>Duty cycle ratio indicator<br>Voltage value (dB <sup>V</sup> , Hz <sup>V</sup> ) indicator<br>Reference resistance value (dBm) indicator |
| OL                       | Overrange Indicator  |
| - <b>CE</b>              | Appears when the batteries become low  |
|                          | Bar graph indicator, Range indicator   |

# 4.3 Measuring Instructions



#### To avoid damage to instrument or equipment

- Before starting measurement, make sure that the position of function switch and the input terminals for connecting the testing leads are appropriate for the desired mode of measurement.
- Temporarily remove the testing leads from the device under test before operating the function switch.

#### 4.3.1 AC Voltage Measurement ( $\sim$ V, $\sim$ mV)

- 1) Turn the function switch to the "  $\sim$  V " or "  $\sim$  mV " position.
- 2) Plug the testing leads into the input terminals.
- Connect the testing leads to the circuit under test and then read the value when it stabilizes.



#### 4.3.2 DC Voltage Measurement (---- V, ---- mV)

- 1) Turn the function switch to the "----- V "or "---- mV" position.
- 2) Plug the testing leads into the input terminals.
- Connect the testing leads to the circuit under test and then read the value when it stabilizes.



# Note

 This instrument has a function which automatically corrects the offset of the internal circuit when measuring DCV.

This correction is designed to operate once at the following timing: power on, a function is switched or a range is switched.

When the environment temperature is changing a certain amount, it is recommended to switch a function and make a correction deliberately for better accurate measurement.

• If "mV "range is selected and the testing leads are left open-circuited, the instrument may give a certain reading. This dose not affect your measurement.

# 4.3.3 DC+AC Voltage Measurement ( ---- + $\sim$ )

- 1) Turn the function switch to the "  $\blacksquare$  V " position.
- 2) Press the SELECT key to select DC+AC voltage measurement. (The display shows the "===+~" symbol.)
- 3) Plug the testing leads into the input terminals.
- Connect the testing leads to the circuit under test and then read the value when it stabilizes.

# 4.3.4 DC, AC Voltage Dual Display ( --- • ~ )

- 1) Turn the function switch to the "DCV" position.
- Press the SELECT key twice to change the mode to DC/AC voltage dual display.

DC voltage measurement appears on the main display and AC voltage on the sub-display.

- 3) Plug the testing leads into the input terminals.
- Connect the testing leads to the circuit under test and then read the value when it stabilizes.

# 4.3.5 Resistance Measurement (Ω)



#### To avoid damage to instrument

Turn off the power to the circuit under test before starting measurement in order to prevent any excessive voltage from being applied to the instrument.

- 1) Turn the function switch to the " $\Omega$  " position.
- 2) Plug the testing leads into the input terminals.
- 3) Connect the testing leads to the circuit under test and then read the value when it stabilizes.

# Note

#### Zero adjustment

Zero adjustment is recommended for correct measurement. After executing 1), 2) above, short the two testing leads. Press the REL key for adjust. (The display shows the " $0.0\Omega$ " value.) The value (zero adjustment) stores till turn off.







# 4.3.6 Low Power-Ω (LP-Ω)

This function is for measuring the resistance of parts on a printed board under low measurement current.

In Low Power- $\Omega$  measurement, up to 5,000 counts are displayed and the measurement range is from 5 k $\Omega$  to 5 M $\Omega$ .

- 1) Turn the function switch to the " $\Omega$ " position.
- Press the SELECT key to set LP- $\Omega$ mode. "LP- $\Omega$ " appears on the display.
- 2) Plug the testing leads into the input terminals.
- 3) Connect the testing leads to the resistance and then read the value when it stabilizes.

# 4.3.7 Continuity Check ( ·)))



#### To avoid damage to instrument

Turn off the power to the circuit under test before starting measurement in order to prevent any excessive voltage from being applied to the instrument.

- 1) Turn the function switch to the "  $\cdot$  )) " position.
- 2) Plug the testing leads into the input terminals.
- Connect the testing leads to the circuit under test. If the circuit is continuous (no more than approximately 100Ω), the buzzer sounds.





#### 



#### To avoid damage to instrument

Turn off the power to the circuit under test before starting measurement in order to prevent any excessive voltage from being applied to the instrument.

KI- TEMP

• 0

Red

COM

Testing lea Black

- Turn the function switch to the "→(→ •))" position. Press the SELECT key to select Diode test. (The display shows the →(→ symbol.)
- 2) Plug the testing leads into the input terminals.
- 3) Connect the testing leads to the diode and then read the value when it stabilizes.


#### <Forward-bias Diode Test>

Connect the black testing lead to the cathode and the red testing lead to the anode. Silicon diodes should give a reading of approximately 0.5V and light-emitting diodes a reading between approximately 1.5V and 2.0V.

#### <Reverse-bias Diode Test>

Connect the black testing lead to the anode and the red testing lead to the cathode. Normally, the display shows the "OL" symbol, indicating that the diode under test is normal.

The diode is defective if the display gives a certain voltage level.



## 4.3.9 Temperature Measurement (TEMP)



#### To avoid damage to instrument

Turn off the power to the circuit under test before starting measurement in order to prevent any excessive voltage from being applied to the instrument.

# Note

Optional Temperature probe is required for temperature measurement. Temperature Probe: Thermocouple Type K Model: 90050, 90051, 90055, 90056 Check the measurable range of respective probes.

1) Turn the function switch to the "TEMP" position.

- 2) Plug the measuring probe into the input terminals.
- 3) Contact the measuring probe to the under test and then read the value when it stabilizes.



## 4.3.10 Current Measurement (µA/mA/A)



#### To avoid damage to instrument or equipment

- Before starting measurement, make sure that the position of function switch and the input terminals for connecting the testing leads are appropriate for the desired mode of measurement.
- The maximum input current (limited by fuses) of the "µA" and "mA" ranges is 440 mA. Be sure not to exceed the limit in the 500 mA range.
- 1) Turn the function switch to the " $\mu$ A", "mA" or "A" position. (If the magnitude of the current being measured is not known, select the "A" position. Make sure the current being measured is no more than 440mA before the " $\mu$ A" or "mA" position is selected.)
- 2) Please select between DC and AC. When selecting AC, press the SELECT key.
- 3) Plug the black testing lead into the "COM" input terminal and the red testing lead into the "A"input terminal. If the current is in the order of mA or less, plug the red testing lead into the "μA • mA" input terminal.
- 4) Connect the testing leads to the circuit under test and then read the value when it stabilizes.

# A COM E Testing leads Black Image: Complex structure </tr

# Note

• This instrument has a function which automatically corrects the offset of the internal circuit when measuring DCA.

This correction is designed to operate once at the following timing: power on, a function is switched or a range is switched.

When the environment temperature is changing a certain amount, it is recommended to switch a function and make a correction deliberately for better accurate measurement.

# 4.3.11 DC+AC Current Measurement ( ---- + ~~ )




#### To avoid damage to instrument or equipment

- Before starting measurement, make sure that the position of function switch and the input terminals for connecting the testing leads are appropriate for the desired mode of measurement.
- The maximum input current (limited by fuses) of the "µA" and "mA" ranges is 440 mA. Be sure not to exceed the limit in the 500 mA range.
- 1) Turn the function switch to the " $\mu$ A", "mA" or "A" position. (If the magnitude of the current being measured is not known, select the "A" position. Make sure the current being measured is no more than 440mA before the " $\mu$ A" or "mA" position is selected.)
- Press the SELECT key twice to select the DC +AC measurement. (The display shows the --- + ~ symbol.)

Plug the black testing lead into the "COM" input terminal and the red testing lead into the "A" input terminal.

If the current is in the order of mA or less, plug the red testing lead into the " $\mu$ A • mA" input terminal.

3) Connect the testing leads to the circuit under test and then read the value when it stabilizes.



# 4.3.12 DC, AC Current Dual Display ( ---- • ~ )

- 1) Turn the function switch to the " $\mu$ A," "mA" or "A" position. (If the magnitude of the current being measured is not known, select the "A" position. Make sure the current being measured is no more than 440 mA before the " $\mu$ A" or "mA" position is selected.)
- 2) Press the SELECT key three times to select DC/AC dual display.

DC current measurement appears on the main display and AC current on the sub-display.

3) Plug the black testing lead into the "COM" input terminal and the red testing lead into the "A" input terminal.

If the current is in the order of mA or less, plug the red testing lead into the " $\mu$ A/mA" input terminal.

 Connect the testing leads to the circuit under test and then read the value when it stabilizes.

# 4.3.13 Capacitor Measurement ( ⊢)




#### To avoid damage to instrument

- Turn off the power to the circuit under test before starting measurement in order to prevent any excessive voltage from being applied to the instrument.
- · Before starting measurement, be sure to discharge the capacitor under check.
- 1) Turn the function switch to the "-|- "position."
- 2) Plug the testing leads into the input terminals.
- 3) Open the testing lead and press the REL key in 5nF range to adjust the capacitance to zero. (The display shows "0.000".)
- Connect the testing leads to the circuit under test and then read the value when it stabilizes.

# Note

The value (zero adjustment) remains displayed until power-off.






#### 4.3.14 Frequency Measurement (Hz), Duty cycle ratio (Hz)



#### To avoid damage to instrument

Turn off the power to the circuit under test before starting measurement in order to prevent any excessive voltage from being applied to the instrument.

- 1) Turn the function switch to the voltage(  $\sim$  V,  $\sim$  mV) or the current ( $\mu$  A, mA, A) position.
- 2) Press the SELECT key to select the range of frequency. (The display shows the unit of frequency.)
- Plug the testing leads into the input terminals.
   Plug the red testing lead into the suitable input terminal ("A" or "μA•mA") for current value when current measurement.
- 4) Contact the measuring probe to the under test and then read the value when it stabilizes. The display shows frequency value in main-display and duty cycle ratio value in subdisplay.



#### 4.3.15 Function to change RMS detection to/from MEAN detection mode (TY720 only)

The instrument has a function to change RMS detection to/from MEAN detection modes.

#### <Change to MEAN detection mode>

- 1) Select the appropriate AC measurement mode (ACV, ACmV, ACµA, ACmA, ACA) by using the function switch and the SELECT key.
- 2) Press the SHIFT key to display "Shift" on the display.
- 3) Press the REL key while holding down the SHIFT key to change to MEAN detection mode. "RMS" disappears on the display.

#### <Change to RMS detection mode>

- 1) Select the appropriate AC measurement mode (ACV, ACmV, ACµA, ACmA, ACA) by using the function switch and the SELECT key.
- 2) Press the SHIFT key to display "Shift" on the display.
- 3) Press the RANGE key while holding down the SHIFT key to change to RMS detection mode. "RMS" appears on the display.


#### 4.3.16 Function to turn the filter on/off (TY720 only)

The instrument has a function to turn the filter on/off during AC measurement.

- 1) Select the appropriate AC measurement mode (ACV, ACmV, AC $\mu$ A, ACmA, ACA) by using the function switch and the SELECT key.
- 2) Press the SHIFT key to display "Shift" on the display.
- 3) Press the HOLD key while holding down the SHIFT key to turn the filter on/off. While the filter is on, "Filter" appears on the display.

While the filter is on, the low-pass filter is activated.

(Refer to filter characteristics in the diagram below.)



#### 4.3.17 AUTO HOLD Function

The instrument can automatically retain the measured value when the testing leads are handled as described below.

1) Press the HOLD key to select Auto hold function.

(The display shows the" A•H " symbol.)

- 2) Connect the testing leads to the circuit under test.
- 3) When the reading stabilized, the buzzer sounds.
- 4) Remove the testing leads from the circuit under test.
- 5) The display shows the measured value that is retained.

You can repeat steps 2) to 4)as many times as you like as long as the display shows the "A• H " symbol.

## Note

- In DC/AC voltage measurement, the Auto hold function is only available for ranges greater than the 5V range.
- This function is not available for Temperature, Capacitor and Frequency measurement.
- The Auto hold function can not be applied to unstable signals.

#### 4.3.18 PEAK HOLD Function

This instrument can always detect, update and display the peak value (instantaneous) in DCV and DCA measurement. The peak value of the wave can be seen.

- 1) Turn the function switch to DCV or DCA position.
- 2) Connect the testing leads to the circuit under test.
- 3) Press the HOLD key to select Peak Hold. (The display shows the "P•H " symbol.)
- 4) The display shows the peak value.
- 5) When resetting the peak value in HOLD, press the MIN/MAX key. Then new peak value can be in HOLD.

#### Note

Even though the input signals (DCV, DCA) have negative polarity, the peak value can be measured when the peak is in the positive direction.

Relative values from the reference values can be shown during the peak value measuring.

- Press the RELΔ/% key to relative calculation in PEAK HOLD mode. The display shows the "Δ" symbol and the relative peak value.
- Press the REL∠/% key once again to percentage calculation. The display shows the "%" symbol and the percentage peak value.

#### SEE ALSO

Next section " Relative and percentage calculation"

When resetting the peak value, press the MIN/MAX key. Then new peak value can be in HOLD.

To cancel the percentage calculation, Press the REL $\Delta$ /% key again.

" % " symbol disappears, then retrieves the PEAK HOLD mode.

#### 4.3.19 Relative and percentage calculation

The instrument can calculate relative values or difference, and percentage values from the reference measurement values. (The range will be fixed.)

#### <Relative (REL) calculation>

Subtracts the reference value from the measured value to display the relative value or difference.

- 1) Take a measurement to set the reference value.
- 2) Press the REL $\Delta$ /% key.

(The display shows the " $\Delta$ " symbol and the sub-display shows the reference value.)

3) Take another measurement.

#### <Percentage (%) calculation>

Calculates and display the percentage value according to the following equation: % value =(measured value – reference value)/reference value

- 1) Take a measurement to set the reference value.
- 2) Press the REL $\Delta$ /% key.

(The display shows the " $\Delta$ " symbol and the sub-display shows the reference value.)

3) Take another measurement.

Press the REL $\Delta$ /% key again. (The display shows the" % " symbol.)

#### 4.3.20 Decibel calculation (dBm, dB<sup>V</sup>)

The instrument can perform logarithmic calculations on a AC voltage.

 $\begin{array}{ll} dBm & : 20log & \displaystyle \frac{Measured \ voltage \ value}{\sqrt{Reference \ resistance \ value \times \ 10^{-3}}} \\ (1mW/Reference \ resistance \ (\Omega)=0dBm) \\ dB^{v} & : 20log & \displaystyle \frac{Measured \ voltage \ value}{1(V)} \end{array}$ 

1) Turn the function switch to the  $\sim$  V or  $\sim$  mV position.

2) Press the SELECT key to select dBm  $dB^{V}$ .

(The display shows the "dBm", "dB" symbol.)

- 3) Connect the testing leads to the circuit under test and then read the value when it stabilizes.
- 4) When calculating relative value, press the REL $\Delta$ /% key.

#### Note

The instrument can switch (select) reference resistance value when measuring dBm.

The reference resistance value is switched as follows every time the RANGE key is pressed. (Shown in sub-display.)

Reference resistance value:

 $\begin{array}{c} 4,8,16,32,50,75,93,110,125,135,150\\ 200,250,300,500,600,800,900,1000,1200\\ Default value: 600\Omega\\ \end{array}$  The default settings can be changed. Refer to the Set-up function.

#### 4.3.21 MIN/MAX/AVG Function

The minimum value (MIN), maximum value (MAX) and average value (AVG) during measurement are shown. (The range is fixed.) The average value is shown by dividing the integrated record data by the number of recording times.

Pressing this key starts recording and at the same time the display shows "MIN", "MAX" and "AVG" to release AUTO POWER OFF.

#### <Recording time>

The timer is activated to show the elapsed time from the start and simultaneously the renewed time for MIN/MAX is also recorded.

The elapsed time is displayed as follows:

0 sec. to 99 min. and 59 sec.: steps of 1 sec.

100 min. or more: steps of 1 min.

Press the HOLD key to stop recording. (The display shows the "D•H " symbol.)

#### <To confirm the recording time>

For confirming the recording time, press the MIN/MAX key.

Subsequent pressing of this key repeats to display the present minimum value (MIN), maximum value (MAX) and average value (AVG).

Press the HOLD key once again to restart recording.

To cancel the confirming mode, hold down the MAX / MIN key for one second.

("MAX" "MIN" "AVG" symbol disappears.)

### Note

- No influence is exerted on the recorded data even if the test leads are disconnected while the recording is stopped.
- If overload is recorded, the MIN or MAX display changes to "OL" display, resulting in incorrect average data.
- For widely varying signal measurement, set the appropriate range in which the MAX or MIN does not change to "OL" display.

## 4.4 Memory Function

#### <To save a Data in internal memory>

The instrument can save a data using with the following two types of modes. SAVE-mode: Saves a data for one measurement by manual operation. LOGGING-mode: Automatically saves a data from the start of logging.

Memory capacity

SAVE-mode: 100 data LOGGING-mode: Logging data of one time Model TY710 1,000 data Model TY720 10.000 data

Number of saved data

Number of saved data is 4-digit numbers. When LOGGING-mode, "L" is attached to the top of 4-digit numbers. The instrument allocates the smallest number, between 0000 to 9999, that has not yet been used. Use the  $\blacktriangle$  (RANGE) key or  $\checkmark$  (REL $\angle$ /%) key switches the number of saved data.

#### To save a Data (SAVE-mode)

1) Press the MEMORY key. (The display shows the "MEM "symbol.)

2) Press the SAVE (HOLD) key.

(The display shows the number of saved data.)

3) Press the SAVE (HOLD) key to save the data.

Another press of the SAVE (HOLD) key saves a data for the second time measurement or later.

 To cancel the function, hold down the MEMORY key for one second. ("MEM" symbol disappears.)

## Note

HOLD data can be saved. Hold the display and save it according to the above steps.

The number of saved data

#### To save a Data (LOGGING-mode)

In logging measurement mode, the time needs to be set. Note that changing the batteries resets the time to 00:00. Set the time by referring to the Set-up function.

- 1) Press the MEMORY key. (The display shows the "MEM "symbol.)
- 2) Press the LOG (MIN/MAX) key.

(The display shows the logging interval (period).)

Set the value with the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL $\angle /\%$ ) key.

The default setting is one second. (The default settings can be changed. Refer to the Set-up function.)

The display shows "FULL" when the logging data is already saved.

When saving the new data, perform delete of data.

3) Press the LOG (MIN/MAX) key to start logging. (The "MEM "symbol is flashing.) Every time the MIN/MAX key is pressed, the sub-display changes.

(Sub display : saved number  $\rightarrow$  saved time (min : sec) $\rightarrow$ (hour : min) $\rightarrow$ saved number)

4) To cancel the function, hold down the MEMORY key for one second. When memory capacity becomes full, the function is automatically canceled.

("MEM " symbol disappears.)

## Note

LOGGING-mode operation during HOLD-mode disables HOLD-mode.

#### To load a Data (SAVE-mode)

- 1) Press the MEMORY key. (The display shows the "MEM "symbol.)
- 2) Press the READ (LIGHT) key.
- Press the SAVE (HOLD) key to select the number of saved data. Select the number with the ▲ (RANGE) key or ▼ (REL∠/%) key.
- 4) To cancel the function, hold down the MEMORY key for one second. (" MEM " symbol disappears.)

### To load a Data (LOGGING-mode)

- 1) Press the MEMORY key. (The display shows the "MEM "symbol.)
- 2) Press the READ (LIGHT) key.
- 3) Press the LOG (MIN/MAX) key to select the number of saved data. Select the number with the ▲ (RANGE) key or ▼ (REL△/%) key. Every time the MIN/MAX key is pressed, the sub-display changes. (Sub display : saved number → saved time (min : sec)→(hour : min)→saved number)
- 4) To cancel the function, hold down the MEMORY key for one second.
  - ("MEM " symbol disappears.)

#### <To delete of saving data>

#### Delete method (SAVE-mode)

- · To delete all data
- 1) Press the MEMORY key.
  - (The display shows the "MEM "symbol.)
- 2) Hold down the SAVE (HOLD) key for one second. (The display shows the " CLr ? "symbol.)
- 3) Press the SAVE (HOLD) key. All data is deleted.
- · To overwrite selected data
- 1) Press the MEMORY key.
  - (The display shows the "MEM "symbol.)
- 2) Press the SAVE (HOLD) key.

(The sub-display shows the number of saved data.)

- 3) Use the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL $\angle 1/\%$ ) key to select the number of saved data.
- 4) Press the SAVE (HOLD) key to save (over write) the data.
- 5) To cancel the function, hold down the MEMORY key for one second. ("MEM" symbol disappears.)

### Delete method (LOGGING-mode)

- To delete all data
- 1) Press the MEMORY key.
  - (The display shows the "MEM "symbol.)
- 2) Hold down the LOG (MIN/MAX) key for one second. (The display shows the " CLr ? "symbol.)
- 3) Press the LOG (MIN/MAX) key.
  - All data is deleted.



## 4.5 AUTO POWER OFF Function

#### <To use the AUTO POWER OFF function>

The display shows the "AUTO OFF "indication.

- The instrument automatically turns off twenty minutes after the last key operation. The instrument will beep for approximately 30 seconds to alert the operator before the AUTO POWER OFF function takes effect.
- · Pressing any key or switch while the instrument is beeping postpones the power-off time.
- Turning the function switch once after the power to the instrument is automatically turned off switches the instrument on again.

#### <To cancel the AUTO POWER OFF function>

- 1) Turn the function switch to the OFF.
- 2) With pressing the HOLD key, turn the function switch to the desired position of any measurement mode (function).

The "AUTO OFF" indication turns off when the function is canceled.

## Note

Additional functions simply set when POWER ON can be used.

#### <To enable the AUTO POWER OFF function once again>

- 1) Turn the function switch to the OFF.
- 2) Turn the function switch to the desired position of any measurement mode (function). The AUTO POWER OFF function is enabled again.

The display shows the "AUTO OFF" indication.

## 4.6 Set-up Function

The following settings can be made using the Set-up function:

- · time setting
- · default setting of dBm measurement reference resistance
- · default setting of detection mode during AC measurement
- · default setting of LOGGING interval
- · default setting of number display/time display during LOGGING mode
- sound on/off setting (beep of buzzer)
- · reset to factory preset mode
- 1) Press the SHIFT key shows "Shift" on the display.
- Press the LIGHT key while holding down the SHIFT key changes the mode to Set-up mode (from Set-up to time display).



- 3) Press the LIGHT key changes the setting items accordingly.
- 4) Change values by using the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL) key.
- 5) Press the HOLD key to save/finish each setting.
- "SEt" appears and the display returns to the setting items.
- 6) Hold down the LIGHT key for more than one second to return from Set-up mode to measurement mode.

#### Note


To cancel any setting, hold down the LIGHT key for more than one second, or turn off by using the function key.

#### <Time setting>

Set the time to be displayed during LOGGING mode. Be sure to set the time after changing the batteries.

1) Display "CLOCK" by using the LIGHT key.

The first two digits of the time blink on the sub-display.




- 2) Set the present hour by using the  $\blacktriangle$  (RANGE) key or  $\lor$  (REL) key.
- 3) Press the LIGHT key to make the last two digits blink.
- 4) Set the present minute by using the  $\blacktriangle$  (RANGE) key or  $\lor$  (REL) key.
- 5) Press the HOLD key to save the setting.
  - "SEt" appears and then "CLOCK."

#### <Default setting of dBm measurement reference resistance>

Set a default value of the reference resistance during dBm measurement mode.

1) Display "db-r" by using the LIGHT key.

The reference value appears on the display.



2) Select the reference resistance by using the  $\blacktriangle$  (RANGE) key or  $\lor$  (REL) key.

3) Press the HOLD key to save the setting.

"SEt" appears and then "db-r."

Setting values of reference resistance


4, 8, 16, 32, 50, 75, 93, 110, 125, 135, 150, 200, 250, 300, 500, 600, 800, 900, 1000, 1200Ω(default value is 600Ω)

#### <Default setting of detection method during AC measurement> (TY720 only)

Set a default setting of detection methods during AC measurement.

RMS or MEAN: The default setting is RMS.

1) Display "Ac" by using the LIGHT key.



2) Select the detection method by using the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL) key.

3) Press the HOLD key to save the setting.

4) "SEt" appears and then "Ac."

#### <Default value of LOGGING interval>

Set a default value of the saving interval during LOGGING mode.

1) Display "LG. int" by using the LIGHT key.

The default setting is 1 sec.



2) Select the saving interval by using the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL) key.

3) Press the HOLD key to save the setting. "SEt" appears and then "LG. int."

Settings of saving interval 1, 2, 5, 10, 30, 60, 600, 1800 sec

#### <Default setting of number display/time display during LOGGING mode>

Set the sub-display during LOGGING mode.

(The numbers of saved data or time (minute : second))

Default is the numbers of saved data.

1) Pressing the LIGHT key shows "LG. Unt" on the display.



- 2) Select the desired setting by using the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL) key.
- 3) Press the HOLD key to save the setting.


"SEt" appears and then "LG. Unt."

#### <Sound on/off setting>

Set the sound on/off (beep of buzzer)

Even if the user sets the sound off, it goes off at the following points.


- · checking continuity
- · alarm for over-input
- · alarm for auto power-off
- 1) Pressing the LIGHT key shows "bEEP" on the display. Set on/off on the sub-display. Default is ON.



- 2) Select on/off by using the  $\blacktriangle$  (RANGE) key or  $\blacktriangledown$  (REL) key.
- 3) Press the HOLD key to save the setting. "SEt" appears and then "bEEP."

#### <Reset to factory preset mode>

Reset all the settings to factory preset mode except for time. 1) Pressing the LIGHT key shows "dEF." on the display.



2) Press the HOLD key to reset the settings.

"donE" appears and then "dEF."



#### To avoid damage to instrument

When the measurement function is completed, turn the function switch back to the OFF position to turn off.

## 4.7 Additional functions simply set when POWER ON

With pressing the following keys, turn the function switch to the desired position of any measurement mode (POWER ON-state).

| Keys           | Functions to be set                                    |  |  |
|----------------|--|--|--|
| MIN/MAX        | Averaging Function (calculates the average of 8 times) |  |  |
| RANGE          | 5000 (3.5-digit display)                               |  |  |
| SELECT         | LCD check (Lit only while pressing the SELECT key)     |  |  |
| HOLD           | Cancels the Auto power off function                    |  |  |
| HOLD + REL⊿/%  | Reset all calibration values to those before shipment. |  |  |
| SELECT + RANGE | Calibration function                                   |  |  |

This enables the following functions corresponding to the press keys.

## 4.8 Averaging Function

The measured value may greatly fluctuate, the instrument can calculate the average (8 times / approx. 2 seconds).

This function is available for Voltage, Current and Resistance-mode measurement.

The function (averaging) operates until the power is turned off.

## Note

Additional functions simply set when POWER ON can be used.

## 4.9 5000 display mode

This function switches 3.5-digit display (5000) and 5-digit display (50000).

The function is not available for Capacitor, Temperature, DC+AC, Continuity and Frequencymode measurement.

The function (5000 display) operates until the power is turned off.

## Note

Additional functions simply set when POWER ON can be used.

## 4.10 LCD Check

The instrument can lit all segments and mark for LCD check. (Lit only while pressing the SELECT key.)

## 5. User Calibration Function

It is recommended that the instrument be calibrated periodically. The instrument can be calibrated.



#### To avoid electrical shock

- Only authorized engineers are allowed to calibrate the instrument using dedicated facilities.
- Connect the calibrator to the instrument with the calibrator's testing leads.
- Before carrying out calibration, read the instruction manual of the calibrator.
- Temporarily remove the testing leads from the instrument before switching measurement mode (function).

#### <Conditions of calibration>

Calibrator: With accuracy higher than of this instrument

Ambient Environment:

Temperature: 23±3°C Humidity: 55%RH or less Leave the instrument for 30 minutes under above conditions before carrying out calibration.

After reference valve of Calibrator stabilizes, Press the key to confirm for calibration valve.

#### <Table 1>

Carry out calibration of ranges in accordance with Table 1.

Calibration for 2 points (Input 1 and Input 2) is required other than DC range.

After Input 1, carry out calibration of Input 2 repeating steps 6) and 7).

For AC voltage and AC current ranges (marked with O), calibration is carried out at 50Hz or 60Hz frequency.

1) Turn the function switch from the OFF position to the \_\_\_\_ mV position while pressing the SELECT and RANGE keys at the same time.

The display shows the "CAL" symbol then the "PASS" symbol.

- 2) Press the SELECT key. (The display shows the " " symbol.)
- 3) Press the HOLD key twice. (The display shows the "---" symbol.)
- 4) Press the RANGE key. (The display shows the "mV" symbol.)
- 5) Connect the instrument to the calibrator with the testing leads.
- 6) Set the calibrator to Input 1 value as an input to the instrument.
- 7) Press the HOLD key.
- 8) Be sure to confirm that the function switch and input terminal are set to the desired range. Carry out calibration of other ranges by repeating steps 6) and 7).
- 9) To quit calibration, turn the function switch back to the OFF position.

## Note

The model TY720 needs to be calibrated at mean value detection (MEAN) mode and filter on of AC current.

| Range                  | Input 1 | Input 2 | Unit |
|------------------------|---------|---------|------|
| DC 50mV                | 0.000   | 50.000  | mV   |
| DC 500mV               | 500.00  | -       | mV   |
| DC 2400mV              | 2000.0  | -       | mV   |
| DC 5V                  | 5.0000  | -       | V    |
| DC 50V                 | 50.000  | -       | V    |
| DC 500V                | 500.00  | -       | V    |
| DC 1000V               | 1000.0  | -       | V    |
| O AC 50mV*1 −          | 5.000   | 50.000  | mV   |
| O AC 500mV             | 50.00   | 500.00  | mV   |
| O AC 5V *2 _ 50Hz/60Hz | 0.5000  | 5.0000  | V    |
| O AC 50V               | 5.000   | 50.000  | V    |
| O AC 500V              | 50.00   | 500.00  | V    |
| O AC 1000V _           | 100.0   | 1000.0  | V    |
| 500Ω                   | 0.00    | 500.00  | Ω    |
| 5kΩ                    | 0.0000  | 5.0000  | kΩ   |
| 50kΩ                   | 0.000   | 50.000  | kΩ   |
| 500kΩ                  | 0.00    | 500.00  | kΩ   |
| 5ΜΩ                    | 0.0000  | 5.0000  | MΩ   |
| 50ΜΩ                   | 0.000   | 30.000  | MΩ   |
| Continuity Check ( ))  | 0.0     | 500.0   | Ω    |
| DC 500 µA              | 0.00    | 500.00  | μΑ   |
| DC 5000 µA             | 0.0     | 5000.0  | μA   |
| DC 50mA                | 0.000   | 50.000  | mA   |
| DC 500mA               | 0.00    | 400.00  | mA   |
| DC 5A                  | 0.0000  | 5.0000  | А    |
| DC 10A                 | 0.000   | 10.000  | А    |
| Ο ΑC 500 μΑ –          | 50.00   | 500.00  | μΑ   |
| Ο ΑC 5000 μΑ           | 500.0   | 5000.0  | μA   |
| O AC 50mA              | 5.000   | 50.000  | mA   |
| O AC 500mA - 50Hz/60Hz | 50.00   | 400.00  | mA   |
| O AC 5A                | 0.5000  | 5.0000  | А    |
| O AC 10A               | 1.000   | 10.000  | А    |

Table 1. Input Signal for Calibration

\*1: For model TY720.

\*2: For model TY720. Calibration points added in 5 VAC range (setting, input value).

O [RMS], Filter OFF, Input1 (0.50000), Input2 (5.0000)

O [MEAN], Filter OFF, Input1 (0.50000), Input2 (5.0000)

O [RMS], Filter ON, Input1 (0.5000), Input2 (5.0000)

#### <Table 2>

After completing the calibration for ranges in Table 1, carry out calibration for "Frequency Characteristic".

The calibration for is frequency characteristic required for AC voltage and AC current ranges (marked with O).

Calibration is carried out at the designated frequency in table 2.

- 1) Set the calibrator to Input value as an input to the instrument.
- 2) Press the MEMORY key.
- 3) After 20 seconds, buzzer sounds and the instrument confirm calibration.

(Do not next key operation till buzzer sounds.)

|   | Range                             | Input  | Unit |
|---|-----------------------------------|--------|------|
| 0 | AC 50mV*1                         | 50.000 | mV   |
| 0 | AC 500mV                          | 500.00 | mV   |
| 0 | AC 5V – 5kHz                      | 5.0000 | V    |
| 0 | AC 50V                            | 50.000 | V    |
| 0 | AC 500V                           | 500.00 | V    |
| 0 | AC 1000V 600Hz                    | 1000.0 | V    |
|   |                                   |        |      |
| 0 | AC 500 $\mu$ A $\rightarrow$ 1kHz | 500.00 | μΑ   |
| 0 | AC 5000μA _ TK112                 | 5000.0 | μΑ   |

#### Table 2. Input Signal for Calibration

\*1: For model TY720.

#### • Calibration of Capacitor Range

Before start calibration of the Capacitor range,

turn the function switch back to the OFF position.

- Turn the function switch from the OFF position to the -| ⊢ (Capacitor) position while pressing the SELECT and RANGE keys at the same time. The display shows the "CAL" symbol then the "PASS " symbol.
- Press the SELECT key. (The display shows the " " symbol.)
- 3) Press the HOLD key twice. (The display shows the "---" symbol.)
- 4) Press the RANGE key. (The display shows the " nF " symbol.)
- 5) Connect the instrument to the calibrator with the testing leads.
- 6) Set the calibrator to Input 1 value as an input to the instrument.
- 7) Press the HOLD key to confirm.
- 8) Set the calibrator to Input 2 value as an input to the instrument.
- 9) Press the HOLD key to confirm.
- 10) Carry out calibration of other ranges by repeating steps 6) to 9).
- 11) To quit calibration, turn the function switch back to the OFF position.

| Range | Input 1 | Input 2 | Unit |
|-------|---------|---------|------|
| 5nF   | 0.500   | 5.000   | nF   |
| 50nF  | 5.00    | 50.00   | nF   |
| 500nF | 50.0    | 500.0   | nF   |
| 5μF   | 0.500   | 5.000   | μF   |
| 50µF  | 5.00    | 50.00   | μF   |
| 500µF | 50.0    | 500.0   | μF   |
| 5mF   | 0.500   | 5.000   | mF   |
| 50mF  | 5.00    | 40.00   | mF   |

## 6. Battery and Fuse Replacement

## 6.1 Battery Replacement

If the batteries fall below the normal operating voltage, the "**I** symbol turns on. Follow the steps below to replace the batteries with new ones.

(AA-size (R6) 1.5V batteries)

Set the time by referring to the Set-up function after changing the batteries. If you remove the batteries, the time resets to 00:00 and the time for LOGGING measurement will not be correct.




Be sure to disconnect the instrument from the circuit under test and testing leads before replacing the batteries.



- Turn the function switch to OFF (turn off the power).
- Do not mix batteries of different types or new batteries with used ones.
- Make sure the polarities of the new batteries are exactly as shown on the battery holder.

#### To replace the batteries:

- 1) Remove the screw on the back of the casing.
- 2) Remove the back cover.
- 3) Take the batteries out of the housing.
- 4) Replace the batteries with new ones.
- 5) Close the casing and fasten it with the screw.



## 6.2 Fuse Replacement

If a current greater than the rated value flows when the instrument is in the currentmeasurement range, a protection fuse may blow.

If this happens, replace that fuse. The instrument contains the following types of fuses.



- Turn the function switch to OFF (turn off the power).
- Be sure to disconnect the instrument from the circuit under test and testing leads before replacing the fuses.
- · Do not operate the instrument with the casing left open.
- In order to avoid damage to the instrument or any possible accident, use fuses of the specified rating.


| Fuse rating: | F1 | 99015 (440mA/1000V) |
|--------------|----|---------------------|
|              | F2 | 99016 (10A/1000V)   |

#### To replace the fuse:

- 1) Remove the screw on the back of the casing.
- 2) Remove the back cover.
- 3) Remove the blown fuse from the fuse holder.
- 4) Install a new fuse in the holder.

(Make sure the fuse rating.)

5) Close the casing and fasten it with the screw.



## 7. Calibration and Maintenance

#### **Calibration Cycle**

It is recommended that the instrument be calibrated once every year. (SEE ALSO: User Calibration Function)

#### **Contacts of Services**

Please contact one of the Yokogawa sales offices listed on the back cover of this manual or the sales representative from which you purchased the instrument. Phillips screw.

## 8 Disposing the Product

#### Waste Electrical and Electronic Equipment (WEEE), Directive 2002/96/EC

This Product complies with the WEEE Directive (2002/96/EC) marking requirement. The affixed product label (see below) indicates that you must not discard this electrical/ electronic product in domestic household waste.

#### **Product Category**

With reference to the equipment types in the WEEE directive Annex 1, this product is classified as a "Monitoring and Control instrumentation" product.

To return unwanted products within the EU area, contact your local Yokogawa Europe B. V. office.

Do not dispose in domestic household waste.





## "Measures for Administration of the Pollution Control of Electronic Information Product" of the People's Republic of China

中華人民共和国の「電子情報製品の汚染予防管理方法」による説明です。

中華人民共和国でのみ有効です。

The following are the provisions of "Measures for Administration of the Pollution Control of Electronic Information Product" of the People's Republic of China.

They are applicable only in the People's Republic of China.

|  | 有毒有害物质      |           |           |                    |               |                 |  |
|--|-------------|-----------|-----------|--------------------|---------------|-----------------|--|
| 部件名称   | 铅<br>(Pb)   | 汞<br>(Hg) | 镉<br>(Cd) | 六价铬<br>( Cr (VI) ) | 多溴联苯<br>(PBB) | 多溴二苯醚<br>(PBDE) |  |
| 框架(塑料)   | ×           | ×         | ×         | ×                  | 0             | 0               |  |
| 线路板 ASSY   | ×           | ×         | ×         | ×                  | 0             | 0               |  |
| 导线<br>98015  | ×           | ×         | ×         | ×                  | 0             | 0               |  |
| 电池   | ×           | ×         | ×         | ×                  | 0             | 0               |  |
| 〇:表示该部件的所有均质材料中的有毒有害物质的含量均在 SJ/T11363-2006 标准中所规定的限量以下。  |             |           |           |                    |               |                 |  |
| ×:表示该部件中至少有一种均质材料中的有毒有害物质或元素的含量超过 SJ/T11363-2006 标准所规定的限 |             |           |           |                    |               |                 |  |
| 量要求。   |             |           |           |                    |               |                 |  |
| <选购>   |             |           |           |                    |               |                 |  |
| 90050 - 90056:TC-K(温度探头)                                 |             |           |           |                    |               |                 |  |
|  | x x x x 0 0 |           |           |                    |               |                 |  |

产品中有毒有害物质或元素的名称及含量

环保使用期限:



该标识适用于 2006 年 2 月 28 日颁布的《电子信息产品污染控制管理办法》以及 SJ/T11364 - 2006《电子信息产品污染控制标识要求》中所述,在中华人民共和国销 售的电子信息产品的环保使用期限。

只要您遵守该产品相关的安全及使用注意事项,在自制造日起算的年限内,则不会因 产品中有害物质泄漏或突发变异,而造成对环境的污染或对人体及财产产生恶劣影响。 注)该年数为"环保使用期限",并非产品的质量保证期。零件更换的推荐周期,请 参照使用说明书。

# YOKOGAWA 🔶

横河メータ&インスツルメンツ株式会社 Yokogawa Meters & Instruments Corporation

東日本営業 〒190-8586 東京都立川市栄町6-1-3 立飛ビル2号館 電話:042-534-1456 ファクシミリ:042-534-1438

関 西 営 業 〒530-0001 大阪府大阪市北区梅田2-4-9 ブリーゼタワー18F 電話:06-6341-1517 ファクシミリ:06-6341-1519

#### Yokogawa Meters & Instruments Corporation

International Sales Dept. Tachihi Bld. No.2, 6-1-3, Sakaecho, Tachikawa-shi, Tokyo 190-8586 Japan Phone: 81-42-534-1413, Facsimile: 81-42-534-1426

YOKOGAWA CORPORATION OF AMERICA (U.S.A.) Phone: 1-800-888-6400 Facsimile: 1-770-254-0928

YOKOGAWA EUROPE B. V. (THE NETHERLANDS) Phone: 31-33-464-1611 Facsimile: 31-33-464-1610

YOKOGAWA ENGINEERING ASIA PTE. LTD. (SINGAPORE) Phone: 65-6241-9933 Facsimile: 65-6241-2606

YOKOGAWA AMERICA DO SUL LTDA. (BRAZIL) Phone: 55-11-5681-2400 Facsimile: 55-11-5681-4434

YOKOGAWA MEASURING INSTRUMENTS KOREA CORPORATION (KOREA) Phone: 82-2-551-0660 to -0664 Facsimile: 82-2-551-0665

YOKOGAWA AUSTRALIA PTY. LTD. (AUSTRALIA) Phone: 61-2-8870-1100 Facsimile: 61-2-8870-1111

YOKOGAWA INDIA LTD. (INDIA) Phone: 91-80-4158-6000 Facsimile: 91-80-2852-1441

YOKOGAWA SHANGHAI TRADING CO., LTD. (CHINA) Phone: 86-21-6239-6363 Facsimile: 86-21-6880-4987

YOKOGAWA MIDDLE EAST B.S.C(C) (BAHRAIN) Phone: 973-17-358100 Facsimile: 973-17-336100

YOKOGAWA ELECTRIC CIS LTD. (RUSSIAN FEDERATION) Phone: 7-495-737-7868 Facsimile: 7-495-737-7869

(2008.8)