

Applies To: 2000 Accord - See VEHICLES AFFECTED

April 23, 2002

Safety Recall: 2000 Accord Passenger's Airbag

(Supersedes 02-021, dated April 3, 2002)

BACKGROUND

During the manufacturing process, a component in the inflator of some passenger's airbags was not welded properly. As a result, the affected airbags may not deploy correctly in a collision, increasing the risk of injury to a front seat passenger.

VEHICLES AFFECTED

Japan-Produced Vehicles:

4-door: VIN JHMCF8...YC000203

From VIN JHMCG5...YC000765 thru JHMCG5...YC020966 From VIN JHMCG6...YC001006 thru JHMCG6...YC017116

US-Produced Vehicles:

2-door: From VIN 1HGCG3...YA000213 thru 1HGCG3...YA005775

4-door: From VIN 1HGCG5...YA001962 thru 1HGCG5...YA064562

From VIN 1HGCG6...YA002203 thru 1HGCG6...YA126540

> From VIN 1HGCF8...YA025010 thru 1HGCF8...YA025032

Only a small number of vehicles in the listed VIN ranges are affected by this campaign. Before beginning work, verify that the vehicle is eligible by checking at least one of the following.

- The customer has a notification letter.
- The vehicle is shown on your campaign responsibility report.
- The vehicle is shown as eligible on a VIN Status Inquiry on DCS.

CUSTOMER NOTIFICATION

All owners of affected vehicles will be sent a notification of this campaign. An example of the customer notification is at the end of this service bulletin.

Some affected vehicles may be in your used vehicle inventory. *According to Federal law, these vehicles cannot be sold or leased until they are repaired.* Please check your vehicle inventory for 2000 Accords. If any of these vehicles are within the affected VIN range, find out if they need to be repaired by doing a VIN status inquiry on DCS, then repair the vehicle as described in this service bulletin.

CORRECTIVE ACTION

Replace the passenger's airbag. **Do not** deploy the removed airbag.

PARTS INFORMATION

Passenger's Airbag Assembly:

Lapis (B94L)	– P/N 77850-S84-305ZA, H/C 7122138
Quartz Gray (NH283L)	 P/N 77850-S84-305ZB, H/C 7122187
Taupe (YR164L)	 – P/N 77850-S84-305ZC, H/C 7122195
Classy Gray (NH264L)	 P/N 77850-S84-305ZD, H/C 7122211

WARRANTY CLAIM INFORMATION

Operation Number:	754101
Flat Rate Time:	0.5 hour
Failed Part:	P/N 06780-S82-A10ZA H/C 6218051
Defect Code:	5AU
Contention Code:	L51
Template ID:	Lapis (B94L) – 02-021A Quartz Gray (NH283L) – 02-021B Taupe (YR164L) – 02-021C Classy Gray (NH264L) – 02-021D
Skill Level:	Repair Technician

REPAIR PROCEDURE

- 1. Make sure you have the anti-theft code for the radio, then write down the radio station presets.
- 2. Disconnect the negative cable from the battery, then wait at least 3 minutes.
- 3. Remove the glove box (see page 20-87 of the 1998–02 Accord Service Manual).


© 2002 American Honda Motor Co., Inc. – All Rights Reserved

ATB 23735-23788 (0204)




CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

4. Disconnect the passenger's airbag 2P connector, and remove the harness clamp.



5. Remove the four mounting nuts.



6. Cover the airbag lid with a cloth, then carefully pry with a screwdriver to lift the airbag out of the dashboard.

NOTE: The airbag lid has pawls on its side that attach it to the dashboard.

7. Place the new airbag into the dashboard. Torque the mounting nuts to 9.8 N·m (7.2 lb-ft).

- 8. Install the harness clamp, then connect the 2P connector. Attach the connector to the connector holder.
- 9. Install the glove box. Make sure the glove box light connector is properly connected.
- 10. Connect the negative cable to the battery.
- 11. Confirm the SRS works properly: When you turn the ignition switch to ON (II), the SRS indicator should come on for about 6 seconds and then go off. If the indicator doesn't come on, or stays on, refer to section 23 of the service manual for troubleshooting information.
- 12. Enter the radio anti-theft code and the radio station presets. Set the clock.
- 13. Center-punch a completion mark above the 10th character of the engine compartment VIN.



14. Do not deploy the old airbag; pack it in the box that the new airbag came in.

NOTE: The old airbag is hazardous. Refer to Section 8 of the Honda Service Operations Manual for instructions on proper handling.

15. Ship the undeployed airbag, freight prepaid, to

Warranty Parts Inspection American Honda Motor Co., Inc. 24500 Honda Parkway Marysville, OH 43040 Fed Ex Account 1312-2690-0 April 2002

Safety Recall: 2000 Accord Passenger's Airbag

Dear Accord Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

What is the reason for this notice?

Honda Motor Co., Ltd., has determined that a defect relating to motor vehicle safety exists in the passenger's airbag on certain 2000 model year Accords. During the manufacturing process, a component in the inflator of some passenger's airbags was not welded properly. As a result, the affected airbags may not deploy correctly in a collision, increasing the risk of injury to a front seat passenger.

What should you do?

Call any authorized Honda dealer and make an appointment to have your car repaired. The dealer will replace the passenger's airbag. *This repair will be done free of charge*. Please plan to leave your vehicle at the dealership for half a day to allow the dealer flexibility in scheduling.

Until your car is repaired, make sure your front seat passenger is properly secured by the seat belt, since the passenger's airbag may not provide adequate protection in a collision.

Who to contact if you experience problems.

If you are not satisfied with the service you receive from your Honda dealer, you may write to:

American Honda Motor Co., Inc. Automobile Customer Service Mail Stop 500-2N-7A 1919 Torrance Blvd. Torrance, CA 90501-2746

If you believe that American Honda or the dealer has failed or is unable to remedy the defect in your vehicle, without charge, within a reasonable period of time (60 days from the date you first contact the dealer for a repair appointment), you may submit a complaint to:

Administrator National Highway Traffic Safety Administration 400 Seventh Street, SW Washington, DC 20590

Or call the toll-free Auto Safety Hotline at (888) 327-4236.

What to do if you feel this notice is in error.

Our records show that you are the current owner or lessee of a 2000 Accord involved in this recall. If this is not the case, or the name/address information is incorrect, please fill out and return the included, postage-paid *Information Change Card*. This will help us to update our records.

If you have questions.

If you have questions about this notice, or need assistance with contacting a Honda dealer, please call Automobile Customer Service at (800) 999-1009.

We apologize for any inconvenience this campaign may cause you.

Sincerely,

American Honda Motor Co., Inc. Honda Automobile Division