



97-1, *Publication Date: JANUARY 2, 1997*

<ul style="list-style-type: none"><li>• Service Manual - Powertrain Control/Emissions Diagnosis (PC/ED) On-Board Diagnosis II (OBD II) - Cover Page Replacement To Include 1997 Vehicles With FD1060 Or FD1460 Engine</li><li>• Service Manual - Powertrain Control/Emissions Diagnosis (PC/ED) On-Board Diagnosis II (OBD II) - Cover Page Replacement To Include 1997 Windstar</li></ul>	<b>Article No. 97-1-15</b>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------

**LIGHT TRUCK:**

1997 WINDSTAR

**MEDIUM/HEAVY TRUCK:**

1997 CARGO SERIES, F & B SERIES, L SERIES

This TSB article is being republished in its entirety to include reference to FD1060 and FD1460 engines.

**ISSUE:**

The 1996 Powertrain Control/Emissions Diagnosis (PC/ED) On-Board Diagnostics II (OBD II) Service Manual is required to service driveability concerns for the 1997 Windstar. The 1996 PC/ED OBD I Service Manual is required to service 1997 vehicles with an FD1060 or FD1460 diesel engine.

**ACTION:**

Refer to the 1996 PC/ED OBD II Service Manual for servicing driveability concerns on the 1997 Windstar, and refer to the 1996 PC/ED OBD I Service Manual for servicing driveability concerns on the 1997 FD1060 and FD1460 diesel F & B/Cargo/L-Series vehicles. Replace the existing 1997 PC/ED OBD II Service Manual cover page with the new cover page that includes a reference note to the 1997 Windstar and FD1060 and FD1460 diesel engines.

**OTHER APPLICABLE ARTICLES:** NONE

**SUPERSEDES:** 96-22-14

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 190000, 290000, 390000, 490000, 590000, 690000, 790000

---



97-1, Publication Date: JANUARY 2, 1997

- Heater - Lack Of Heat In Passenger Compartment - Vehicles Equipped With FD1060 Engine
- Cooling System - Engine Does Not Reach Operating Temperature - Vehicles Equipped With FD1060 Engine

Article No.  
97-1-17

#### MEDIUM/HEAVY TRUCK:

1992-97 CARGO SERIES, F & B SERIES, L SERIES  
1996-97 LOUISVILLE

#### ISSUE:

There may be a lack of interior cab heat and/or the engine may not reach normal operating temperatures. This may be caused by the thermostat and deaeration system currently used in FD1060 engines allowing coolant to bypass the thermostat and not reach normal operating temperatures.




Figure 1 - Article 97-1-17

#### ACTION:

Replace the thermostat and deaeration system. The new thermostat will allow for zero bypass of the coolant which should allow the engine to warm up to operating temperature quicker. Refer to the following Service Procedure for details.

#### SERVICE PROCEDURE

Refer to the following sections of the appropriate model/year Service Manual for specific component removal and installation procedures that may be necessary to gain access to the engine thermostat.

- Engine Cooling System - 03A-03
  - Air Cleaner Ducting - 03A-12
  - Turbocharge Ducting - 03A-48
  - Generator - 14-02
  - Accessory Drive Belts - 03A-05
1. Disconnect the battery ground cable.
  2. Drain the engine coolant into an appropriate container.
  3. Remove and/or reposition as necessary the air cleaner, turbocharger ducting, generator, accessory drive belts and other components to gain access to the thermostat housing.
  4. Disconnect the upper radiator hose from the thermostat housing.
  5. Remove and retain the three (3) thermostat housing attaching bolts.
  6. Remove and discard the thermostat housing, thermostat and gasket.
  7. Remove and retain the lifting eye.
  8. Clean the lifting eye and engine block of any sealing material or other debris.

Refer to Figure 2.




Figure 2 - Article 97-1-17

**NOTE:**

FOR THE NEW ZERO LEAK THERMOSTAT TO BE INSTALLED INTO THE ENGINE A NEW THERMOSTAT HOUSING AND TWO (2) NEW RING SEALS WILL ALSO BE NEEDED.

**NOTE:**

INSTEAD OF THE SINGLE THERMOSTAT GASKET, THE ZERO LEAK THERMOSTAT USES TWO (2) SEALS TO PROVIDE A SEAL FOR THE COOLING SYSTEM. A THERMOSTAT GASKET IS THEREFORE NOT NEEDED. ALSO IT IS NOT NECESSARY TO USE AN RTV OR OTHER SEALER ON THE NEW SEAL RINGS.

9. Install the existing engine lifting eye, the new thick Seal Ring (F7HZ-8255-BA), Zero Leak Thermostat (F7HZ-8575-AA), thin Seal Ring (F7HZ-8255-AA) and Thermostat Housing (F7HZ-8592-AA) onto the engine as shown in Figure 2 using the three (3) existing attaching bolts. Torque the bolts to 42-57 N-m (31-42 lb-ft).

Refer to Figure 3.




Figure 3 - Article 97-1-17

**NOTE:**

FIGURE 3 PROVIDES A VIEW OF THE DEAERATION SYSTEM AND THE ENGINE COOLANT TEMPERATURE SENDER AS IT APPEARS ON 1996-97 VEHICLES AFTER THE INSTALLATION OF THE NEW DEAERATION CHECK VALVE/JIGGLE PIN. ON 1992-95 VEHICLES, THE INSTALLATION OF THE ENGINE COOLANT TEMPERATURE SENDER VARIED. THE CHANGE WAS OUTLINED IN TSB «95-20-12». FOR THESE VEHICLES, THE COOLANT TEMPERATURE SENDER INSTALLATION SHOULD BE MODIFIED AS STATED IN TSB 95-20-12. THIS WILL PROVIDE A MORE ACCURATE COOLANT TEMPERATURE GAUGE READING.

10. Remove the existing deaeration hose from the hose fitting.

11. Remove the existing deaeration hose barb fitting and bushing from the coolant stand pipe assembly and discard. The new deaeration check valve/jiggle pin will replace both of these components.
12. Install the new deaeration Check Valve/Jiggle Pin (3926761-CF) into the coolant stand pipe. Be sure the threaded portion of the new check valve/jiggle pin is first coated with a sealer or wrapped in a teflon tape prior to installation to reduce the possibility of coolant leaks.
13. Install the deaeration hose onto the new check valve/jiggle pin and tighten the hose clamp to 1-1.5 N-m (9-13 lb-in).
14. Reinstall and/or reposition any components removed to gain access to the thermostat housing.
15. Reinstall the negative battery cable.
16. Refill the cooling system following the procedure provided in the appropriate model/year Service Manual.

PART NUMBER	PART NAME
F7HZ-8575-AA	Thermostat
F7HZ-8255-AA	Ring Seal - Thin
F7HZ-8255-BA	Ring Seal - Thick
F7HZ-8592-AA	Thermostat Housing
3926761-CF	Check Valve

**OTHER APPLICABLE ARTICLES:**

**95-20-12**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
97Q117A	Replace Thermostat And Deaeration System	1.1 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
8575	11

**OASIS CODES:** 208100, 208999, 402000, 499000

---



97-1, *Publication Date: JANUARY 2, 1997*

<ul style="list-style-type: none"><li>• Engine - FD1060 Or FD1460 - High Vibration At Low Engine RPM</li><li>• Vibration - High - At Low Engine RPM - Vehicles With FD1060 Or FD1460 Engine</li></ul>	<b>Article No.</b> <b>97-1-18</b>
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------

**MEDIUM/HEAVY TRUCK:**

1992-97 CARGO SERIES, F & B SERIES, L SERIES

**ISSUE:**

High engine noise/vibration/harshness (NVH) at low engine rpm may occur on some vehicles. This may be caused by a reduction in cushioning of the rear engine mounts.

**ACTION:**

Replace the rear engine mount with a revised rear engine mount. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

**NOTE:**

1992-93 VEHICLES WITH AN FD ENGINE WERE ORIGINALLY EQUIPPED WITH SOLID FRONT AND REAR ENGINE MOUNTS/ISOLATORS. TO RESOLVE NOISE/VIBRATION/HARSHNESS (NVH) CONCERNS, TSB ARTICLE [«95-23-15»](#) SHOULD BE USED TO UPDATE THESE VEHICLES TO THE VOIDED STYLE MOUNTS/ISOLATORS. THE REAR ENGINE MOUNTS/ISOLATORS PROVIDED IN THIS TSB ARTICLE SHOULD ONLY BE USED ON 1992-93 VEHICLES IF TSB ARTICLE 95-23-15 HAS ALREADY BEEN PERFORMED AND THE VOIDED REAR MOUNTS/ISOLATORS HAVE SINCE COLLAPSED OR HAVE OTHERWISE FAILED. 1994-97 VEHICLES WERE ORIGINALLY EQUIPPED WITH THE VOIDED MOUNTS AND THIS TSB ARTICLE SHOULD BE FOLLOWED WHEN REPLACING THE REAR MOUNTS/ISOLATORS.

**NOTE:**

NVH CONCERNS MAY BE CAUSED AND/OR AMPLIFIED IF THE ENGINE IDLE SPEED IS SET BELOW SPECIFICATIONS. THE ENGINE IDLE SPEED SHOULD BE CHECKED AND IF NECESSARY ADJUSTED TO THE SPECIFICATION PROVIDED ON THE ENGINE DATA PLATE. THE POWERTRAIN CONTROL/EMISSIONS DIAGNOSIS (PC/ED) MANUAL, SECTION 19A, PROVIDES THE IDLE SETTING PROCEDURE.

Refer to Figures 1, 2 and 3 for the following procedure.

**REAR ENGINE MOUNT/SOLATOR INSTALLATION  
FD1460 ENGINE SHOWN**




Figure 1 - Article 97-1-18






Figure 2 - Article 97-1-18



**FD1460 ENGINE SHOWN - VEHICLES BUILT BEFORE 10/15/96**



**FD1460 ENGINE SHOWN - VEHICLES BUILT AFTER 10/15/96**



**Figure 3 - Article 97-1-18**

1. Remove the bolts, nuts and washers that retain both the right and left side rear engine mount/isolator caps.
2. Carefully raise the rear of the engine using suitable service jack and a wood block placed under the transmission. The engine should only be raised enough to unload the rear engine mounts/isolators and to allow their removal.
3. Remove and discard the existing rear mounts/isolators.

**NOTE:**

THE REVISED ISOLATORS HAVE A SELF ALIGNING FEATURE BUILT INTO THEM. IT IS A RUBBER WEDGE THAT FITS ONTO THE CORRESPONDING FLAT OF THE NEW SUPPORT PIN. THIS FEATURE AIDS THE ASSEMBLY PROCESS AND IT IS UTILIZED ON VEHICLES BUILT AFTER 10/15/96. ON VEHICLES ALREADY IN SERVICE EQUIPPED WITH THE ORIGINAL FULLY ROUND PIN, THE ALIGNING FEATURE OF THE NEW ISOLATOR MUST BE REMOVED. THIS CAN BE DONE BY CUTTING THE RUBBER WEDGE OUT USING A KNIFE. NEW SUPPORT PINS ARE NOT NEEDED.

**NOTE:**

PROPER POSITIONING OF THE NEW REAR MOUNTS/ISOLATORS IS VERY IMPORTANT. ON FD1060 ENGINES, THE NEW ISOLATORS MUST BE INSTALLED WITH THE LARGE VOID ON TOP. ON FD1460 ENGINES, THE ISOLATORS MUST BE INSTALLED WITH THE LARGE VOID ON THE BOTTOM.

4. Be sure the new isolators are oriented correctly, then install the new isolators onto the pins.

**NOTE:**

TO PREVENT THE POSSIBLE ROTATION OF THE NEW ISOLATOR, NEW CAPS ARE NEEDED. THE NEW CAP HAS A SETSCREW BUILT IN THAT LOCKS THE ISOLATOR IN PLACE.

5. Slowly lower the engine onto the revised isolators and remove the service jack and wood block.
6. Install a new cap onto each revised isolators.
7. Install the existing isolator/cap retaining bolts, washers and new Nuts (34989-S2). Torque the bolts to 102-142 N-m (75-105 lb-ft).

PART NUMBER	PART NAME
F7HZ-6038-AA	Rear Engine Mount Isolator (2 Req'd.)
F7HZ-6A065-AA	Rear Engine Mount Cap (2 Req'd.)
34989-S2	Nut - 1/2"-13 Hex Lock P/T (4 Req'd.)

**OTHER APPLICABLE ARTICLES:**

**95-23-15**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970118A	Replace Rear Engine Mounts - Cargo With FD1060 Engine	3.4 Hrs.
970118B	Replace Rear Engine Mounts - Cargo With FD1460 Engine	2.8 Hrs.
970118C	Replace Rear Engine Mounts - F &B And L-Series With FD1060 Engine	2.9 Hrs.
970118D	Replace Rear Engine Mounts - F &B And L-Series With FD1460 Engine	2.2 Hrs.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
6070	56

**OASIS CODES:** 497000, 499000, 703000

---



97-1, *Publication Date: JANUARY 2, 1997*

<b>Noise - Air Leak From Behind Instrument Panel - Vehicles Built Through 10/21/96</b>	<b>Article No. 97-1-19</b>
----------------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

An air leak may be heard from one or more of the following accessory air valve assemblies:

- Differential Axle Lock
- Fifth Wheel
- Engine Air
- Air Suspension Dump
- Wheel Lock

These air valves are located on the right side of the instrument panel.

**ACTION:**

Replace the leaking valve with a new valve. The new valve has been revised to reduce the possibility of an air leak. Refer to the following Service Procedure for replacement details.

**SERVICE PROCEDURE**

There are five (5) types of air valves currently available that operate various accessories. The number of valves in a vehicle will depend on the options in the vehicle.

If an air leak is noted that is originating from behind the instrument panel, locate the source of the leak. If one of the air valve assemblies is leaking, replace the valve using the following procedure.

1. Disconnect the negative battery cable.
2. Remove the eight (8) Torx head screws that retain the RH instrument panel to the dash.
3. Carefully pull the instrument panel away from the dash.
4. Locate/identify the leaking air valve.
5. Release any air pressure left in the system.
6. Remove the two (2) air lines from the valve by pushing in on the tube, depressing the collet and then pulling the tube out of the fitting. If a fitting has been exposed to particularly harsh conditions or has been in service for a long period of time, it may be necessary to grip the collet with a pair of pliers and rotate the collet slightly to help free the components. Additional information regarding Push-To-Connect fittings can be found on Page 06-08-3 of the appropriate year Louisville/Aeromax

Service Manual.

7. Squeeze the valve tangs that retain the valve to the instrument panel and remove the valve from the panel.
8. Install a new valve into the instrument panel in place of the original.

**NOTE:**

BEFORE CONNECTING THE TUBES INTO THE NEW VALVE, CHECK THE END OF THE TUBE AND BE SURE IT IS CUT SQUARE AND THAT THE TUBE END IS NOT DISTORTED OR DAMAGED. THE MAXIMUM ALLOWABLE ANGLE IS 15 DEGREES. IF THE ANGLE OF THE CUT EXCEEDS THIS SPECIFICATION, RE-CUT THE TUBE. USE A SHARP BLADED CUTTING TOOL THAT WILL NOT COLLAPSE THE TUBE OR LEAVE BURRS ON THE TUBE END THAT COULD DAMAGE THE O-RING.

9. Make sure the air tubes are installed in the same position on the new valve as they were on the original. Insert each tube into the fitting until it is fully seated. A small resistance will be felt as the tube passes the collet teeth and the O-ring. Pull back on the tube to be sure the collet is properly retained on the tube.
10. Reposition the instrument panel into the dash.
11. Reinstall the eight (8) Torx head screws and torque to 2.5-3.5 N-m (22-30 lb-in).
12. Reconnect the negative battery cable.

PART NUMBER	PART NAME
F7HZ-4484-AA	Differential Axle Lock
F7HZ-4484-BA	Fifth Wheel
F7HZ-4484-CA	Engine Air
F7HZ-4484-DA	Air Suspension
F7HZ-4484-EA	Wheel Lock

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970119A	Replace One (1) Or Two (2) Valves	0.6 Hr.
970119B	Replace Three (3) Valves	0.7 Hr.
970119C	Replace Four (4) Or Five (5) Valves	0.8 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
4484	77

**OASIS CODES:** 205000, 301000, 304000, 702000

---



97-2, *Publication Date: JANUARY 20, 1997*

<b>Doors - Battery Access Doors May Come Loose - New Part Availability - Vehicles Built Through 9/96</b>	<b>Article No. 97-2-17</b>
----------------------------------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

The fasteners for the battery access doors on vehicles equipped with lower body side panels may become loose. This may be caused by the current fasteners not retaining torque. Also, the battery access doors were not serviced/available individually and parts are now available.

**ACTION:**

Replace the existing door fasteners with new fasteners. The new fasteners should retain their torque and reduce the possibility of the door coming loose. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

Refer to Figure 1.




Figure 1 - Article 97-2-17

1. Loosen the four (4) existing battery access door screws and remove the door from the body panel.
2. Remove the existing screws from the door and discard.
3. Remove the four (4) corresponding J-nuts from the lower body panel and discard.
4. Install four (4) new J-nuts (N623332-S100) onto the lower body panel at the location of the holes.
5. Place the battery access door into position on the lower body panel and secure it with four (4) new Screws (W701810-S300) and torque the screws to 10-13 N-m (85-115 lb-in).
6. Repeat this procedure for the opposite battery access door.

**NOTE:**

THE BATTERY ACCESS PANELS ARE NOW AVAILABLE INDIVIDUALLY. IF ONE BECOMES LOST OR DAMAGED, IT CAN NOW BE REPLACED. REFER TO THE PARTS BLOCK AT THE END OF THIS TSB ARTICLE FOR CORRECT PART NUMBERS.

PART NUMBER	PART NAME
N623332-S100	J-Nut
W701810-S300	Screw
F7HZ-90291C22-AA	Access Door - RH
F7HZ-90291C23-AA	Access Door - LH

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
970217AT	Replace Battery Access Cover Hardware - Both Sides	0.5 Hr.
970217A	Replace Battery Access Cover Hardware - One Side	0.3 Hr.

**DEALER CODING**

<b>BASIC PART NO.</b>	<b>CONDITION CODE</b>
7020125	33

**OASIS CODES:** 108000, 111000

---





97-3, *Publication Date: FEBRUARY 3, 1997*

<ul style="list-style-type: none"> <li>• <b>No Start - Starter Will Not Turn Engine Over - Vehicles With FD1060 Engine</b></li> <li>• <b>Starter - Engine Will Not Turn Over - Vehicles With FD1060 Engine</b></li> </ul>	<p><b>Article No.</b> <b>97-3-15</b></p>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------

**MEDIUM/HEAVY TRUCK:**

1992-97 CARGO SERIES, F & B SERIES, L SERIES

**ISSUE:**

The engine may not crank on some vehicles. This may be due to the starter motor not being robust enough for certain applications that are subject to frequent and/or repeated starts and/or vehicles which are operated in extremely cold weather.

**ACTION:**

If the starter motor requires service, replace the motor with a revised, more robust starter motor. The new motor has been developed to have improved life in these severe operating conditions. Refer to the following text for details.

**NOTE:**

FOR 1992-95 VEHICLES BUILT BEFORE 8/22/94, THE STARTER MOTOR WIRING MODIFICATION PROCEDURE OUTLINED IN TSB 94-26-13 MUST BE COMPLETED BEFORE THE REVISED MOTOR IS INSTALLED.

**NOTE:**

COMPLETE DIAGNOSING AND TESTING PROCEDURES FOR THE STARTING SYSTEM AND ITS COMPONENTS AND WIRING CAN BE FOUND IN SECTION 03-06 OF THE APPROPRIATE MODEL/YEAR SERVICE MANUAL.

Starter motor removal and installation procedures can be found in Section 03-06 of the appropriate model/year Service Manual.

**NOTE:**

TO EASE THE INSTALLATION OF THE NEW STARTER MOTOR, ON VEHICLES EQUIPPED WITH A MANUAL TRANSMISSION, INSERT THE UPPER STARTER MOTOR ATTACHING BOLT THROUGH THE STARTER FLANGE BEFORE INSTALLING THE STARTER ONTO THE ENGINE. THEN DURING INSTALLATION THE UPPER BOLT WILL HAVE TO BE THREADED INTO PLACE BEFORE THE STARTER MOTOR CAN BE FULLY SEATED ONTO THE BELLHOUSING.

**NOTE:**

WHEN INSTALLED ON THE ENGINE, THE SOLENOID OF THE NEW STARTER MOTOR IS POSITIONED BELOW THE NEW STARTER. ON SOME VEHICLES IT MAY BE NECESSARY TO ADJUST THE ROUTING AND/OR CLIPPING OF THE STARTER MOTOR WIRING HARNESS TO PROVIDE SUFFICIENT LENGTH FOR INSTALLATION AND ENSURE THE WIRING IS NOT STRESSED DURING ENGINE OPERATION.

PART NUMBER	PART NAME
F7HZ-11002-EA	Starter (Manual Transmission And Automatic Transmission EXCEPT AT-545)
F7HZ-11002-FA	Starter (Vehicles With AT-545 Automatic Transmission)

**OTHER APPLICABLE ARTICLES:**

## 94-26-13

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

### LABOR ALLOWANCE

OPERATION	DESCRIPTION	TIME
970315A	Replace Starter Motor - F &B Series Alligator Hood	1.1 Hr.
970315B	Replace Starter Motor - L/F &B Series Tilt Hood	1.0 Hr.
970315C	Replace Starter Motor - Cargo	0.9 Hr.

### DEALER CODING

BASIC PART NO.	CONDITION CODE
11002	30

**OASIS CODES:** 499000, 601300, 603300

---



97-4, *Publication Date: FEBRUARY 17, 1997*

<b>FEAD Belt - High Wear And/Or Comes Off Of The Drive Pulley - Vehicles Built From 4/1/92 Through 6/1/96 With FD1060 Engine</b>	<b>Article No. 97-4-11</b>
----------------------------------------------------------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1992-97 CARGO SERIES, F & B SERIES, L SERIES

This TSB article is being republished in its entirety to revise the part number of the Idler Pulley Support Plate.

**ISSUE:**

The Front End Accessory Drive (FEAD) belt may have high wear and/or may come off of the drive pulleys on some vehicles. This may be caused by the belt tensioner support plate and/or the idler pulley support plate not being flat. This can cause the tensioner and idler pulleys to be out of alignment which results in accelerated FEAD belt wear and/or belt roll off.

**ACTION:**

Replace the belt tensioner support plate and if equipped, the idler pulley support plate. The revised plate(s) should allow both pulleys to be in proper alignment which should reduce the possibility of belt wear and/or belt roll off. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Rotate the automatic belt tensioner using a 3/8" breaker bar or ratchet in the square of the belt tensioner arm to release drive belt tension.
2. With the tension released, remove the drive belt from the tensioner.
3. Inspect the original drive belt for wear. If it is still serviceable, it may be reused. If wear is noted, replace the belt with a new Belt (F3HZ-8620-F, F/B/L-Series and F3HZ-8620-K, Cargo Series).

**NOTE:**

THE PARTS CATALOGUE INCORRECTLY CALLS OUT AN F3HZ-8620-M FOR SOME APPLICATIONS. USE ONLY THE BELT LISTED IN THIS TSB ARTICLE.


**NOTE:**

IF THE DRIVE BELT NEEDS TO BE REPLACED AND THE VEHICLE IS EQUIPPED WITH HYDRAULIC BRAKES, THEN THE HYDRAULIC BRAKE PUMP DRIVE BELT WILL HAVE TO BE REMOVED BEFORE THE SERPENTINE DRIVE BELT CAN BE REMOVED FROM THE ENGINE. FOR REMOVAL PROCEDURE, REFER TO THE APPROPRIATE MODEL/YEAR SERVICE MANUAL, SECTION 03A-05.

**NOTE:**


ON EARLY BUILT FD1060 ENGINES, THE TENSIONER AND IDLER SUPPORT PLATES WERE ATTACHED TO THE ENGINE WITH COUNTERSUNK BOLTS (REFER TO FIGURE 2). THE NEW IDLER AND SUPPORT PLATE ASSEMBLY NOW USES HEX HEAD FLANGE BOLTS. THEREFORE, IF AN ENGINE IS EQUIPPED WITH THE COUNTERSUNK BOLTS, THEN THOSE BOLTS MUST BE REPLACED WITH NEW HEX HEAD FLANGE BOLTS (3900631-CF).

**IDLER PULLEY WITHOUT A/C COMPRESSOR  
(SHOWN WITH ORIGINAL COUNTERSUNK ATTACHING BOLT)**



**Figure 2 - Article 97-4-11**

4. Remove the automatic belt tensioner from the support plate and then remove the support plate from the engine. Discard the support plate. Refer to Figure 1.



**Figure 1 - Article 97-4-11**

**NOTE:**


IF THE AUTOMATIC BELT TENSIONER IS EQUIPPED WITH A PLASTIC PULLEY, THEN REFER TO [«TSB 96-8-23»](#) FOR INFORMATION REGARDING AN IMPROVED AUTOMATIC TENSIONER.

5. Install the new automatic Belt Tensioner Support Plate (F3HZ-6B209-AAA) onto the engine with the two (2) attaching bolts. Torque the bolts to 20-32 N-m (15-24 lb-ft).
6. Install the automatic belt tensioner onto the support plate with one (1) bolt and torque to 41-52 N-m (30-38 lb-ft).
7. If the vehicle is equipped with air conditioning, proceed to Step 9. If the vehicle is not equipped with air conditioning, proceed to Step 8.
8. Remove the idler pulley and support plate assembly from the engine and discard. Install the new Idler Pulley Support Plate (F3HZ-8678-AAA) onto the engine with two (2) bolts and torque to 24 N-m (18 lb-ft). Refer to Figure 2.

**NOTE:**

AN IDLER PULLEY IS USED IN PLACE OF THE AIR CONDITIONING COMPRESSOR ON VEHICLES NOT EQUIPPED WITH AIR CONDITIONING. THE IDLER PULLEY AND SUPPORT PLATE ARE ONLY AVAILABLE TOGETHER AS AN ASSEMBLY.

9. Install the new belt or verify the original belt is wrapped properly around the crankshaft, fan, generator and A/C compressor or idler pulley (Figure 3). The belt must be completely seated in the groove of each pulley.



Item	Ford Base Part Number	Description	Item	Ford Base Part Number	Description
1	10270	Generator Support Strap	8	8501	Water Pump
2	8A357	Water Inlet Support Bracket	9	6312	Crankshaft Pulley
3	8A616	Fan Clutch	10	6010	Generator Mounting Bracket
4	8620	Hydro-Max Pump Drive Belt	11	6010	Water Inlet Connection
5	2N211	Hydro-Max Pump (Hydraulic Brakes Only)	12	6B209	Automatic Drive Belt Tensioner
6	3D673	Hydro-Max Auxiliary Drive Pulley	13	19D629	Air Conditioning Compressor
7	8620	Serpentine Drive Belt	14	10300	Generator

**Figure 3 - Article 97-4-11**

10. Position the drive belt on the inside of the automatic belt tensioner.
11. With one hand, rotate the tensioner to release the tension. With the other hand, guide the drive belt onto the water pump pulley. Carefully release the tensioner to tighten the drive belt.
12. Check again to verify the drive belt is properly positioned in all the drive pulley's grooves.

**NOTE:**

IF SO EQUIPPED, REINSTALL THE HYDRAULIC PUMP DRIVE BELT BY REFERRING TO THE APPROPRIATE MODEL/YEAR SERVICE MANUAL, SECTION 03A-03.

13. Start the engine and check the belt and belt tensioner for proper operation.

PART NUMBER	PART NAME
F3HZ-6B209-AAA	Belt Tensioner Support Plate
F3HZ-8678-AAA	Idler Pulley Support Plate
3900631-CF	Bolt (Hex Head Flange)
F3HZ-8620-F	Belt
F3HZ-8620-K	Belt

**OTHER APPLICABLE ARTICLES:**

**96-8-23**

**SUPERSEDES:** 96-25-29

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970411A	Replace Belt Tensioner Support Plate Only	0.4 Hr.
970411B	Replace Belt Tensioner Support Plate And Idler Pulley Support Plate	0.5 Hr.
970411C	Additional Time If Vehicle Is Equipped With Hydraulic Brakes	0.2 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
8680	36

**OASIS CODES:** 497000, 499000

---



97-4, *Publication Date: FEBRUARY 17, 1997*

<b>Cooling System - Engine Cooling Fan Cracks At Center Hub</b>	<b>Article No. 97-4-12</b>
-----------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1991-97 L SERIES  
1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

The center hub of the 28.5" fan may crack around the mounting bolts due to the use of thin material at the center hub point.

**ACTION:**

Replace the fan with a revised fan. The revised fan has a thicker steel mounting disc than the previous design. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Remove the old fan.
2. Refer to the following Application Chart and procure the correct revised fan and install.
3. Torque the retaining bolts to 42-57 N-m (31-42 lb-ft).

**NOTE:**

IF USING A RUBBER-MOUNTED FAN ON DETROIT DIESEL CORPORATION (DDC) ENGINES, THE SPECIAL BOLTS NEED TO BE FIRST TORQUED TO 20 N-m (15 LB-FT) FOLLOWING A STAR PATTERN. THEN REPEAT THE STAR PATTERN AND TORQUE TO 34 N-m (25 LB-FT).

<b>APPLICATION CHART</b>	
<b>Old Engineering Number</b>	<b>New Service Number</b>
F1HT-8600-LA	F7HZ-8600-HA
F1HT-8600-NA	F7HZ-8600-EA
F1HT-8600-MA	F7HZ-8600-FA
F1HT-8600-KA	F7HZ-8600-JA
F4HT-8600-BA	F7HZ-8600-HA
F5HT-8600-AA	F7HZ-8600-GA

<b>PART NUMBER</b>	<b>PART NAME</b>
F7HZ-8600-EA	Fan
F7HZ-8600-FA	Fan
F7HZ-8600-GA	Fan
F7HZ-8600-HA	Fan
F7HZ-8600-JA	Fan

**OTHER APPLICABLE ARTICLES: NONE**



**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970412A	Replace Fan	0.7 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
8600	01

**OASIS CODES:** 402000, 499000

---



97-5, *Publication Date: MARCH 3, 1997*

**Engine - Diesel - FD1060 And FD1460 - White Smoke From Exhaust - Service Tip**

**Article No.  
97-5-17**

**MEDIUM/HEAVY TRUCK:**

1992-97 CARGO SERIES, F & B SERIES, L SERIES  
1997 AEROMAX, LOUISVILLE

**ISSUE:**

White smoke from the exhaust system of a diesel engine during initial warm-up in cold ambient temperatures is normal, in most cases. It is caused by the incomplete combustion of the air/fuel mixture resulting from low engine operating temperatures and cold ambients. However, once the engine temperature warms, the amount of white smoke present in the exhaust should diminish.

**ACTION:**

To help identify whether the white smoke is a normal condition caused by a cold engine and cold ambients, refer to the following Diagnostic Procedure for details.

**DIAGNOSTIC PROCEDURE**

1. When the engine is cold, start the engine, allow it to run at its normal idle speed and monitor the temperature of the engine oil pan. A hand held infrared temperature meter or a Digital Volt-Ohm Meter (DVOM) with a temperature probe may be used. The engine oil/oil pan provides an accessible reading point for engine temperature and also correlates to the engine coolant temperature.

**NOTE:**

ON CERTAIN VEHICLES, A NOISE SHIELD HAS BEEN MOUNTED ONTO THE EXTERIOR OF THE OIL PAN. IT IS IMPORTANT, THEREFORE, TO BE SURE THE TEMPERATURE READINGS ARE TAKEN DIRECTLY FROM THE OIL PAN, OTHERWISE THE TEMPERATURE READINGS WILL NOT BE ACCURATE.

**NOTE:**

IN EXTREME COLD AMBIENTS, IT MAY BE NECESSARY TO OPERATE THE ENGINE AT SPEEDS HIGHER THAN IDLE OR WITH THE ENGINE UNDER LOAD SO THAT IT IS ABLE TO OBTAIN THE TEMPERATURES LISTED IN STEP 2.

2. Once the engine oil/oil pan reaches approximately 57-66°C (135-150°F), white smoke should no longer be emitted from the exhaust. The 57-66°C (135-150°F) engine oil/oil pan temperature correlates to the engine coolant temperature gauge reading at about the beginning of the normal range.
3. If the engine exhaust system emits white smoke during the initial warm-up of the engine, but the white smoke is gone by the time the engine oil/oil pan temperature reaches 57-66°C (135-150°F) and no other engine driveability concerns exist, the engine is operating properly and no further action should be taken. If the engine exhaust system emits white smoke during the initial warm-up of the engine and/or:
  - a. The white smoke continues even after the engine oil/oil pan temperature reaches 57-66°C (135-150°F),

- b. The engine oil/oil pan temperature does not reach the 57-66°C (135-150°F),
- c. Other driveability concerns exist, then further diagnosis should be performed on the engine, fuel and/or cooling systems to determine the root cause of the concern.

Factors that can affect engine operation and white smoke are in the list that follows this paragraph. Complete operation and diagnosis information on each system can be found in the appropriate model/year Powertrain/Drivetrain Service Manual and the Powertrain Control/Emissions Diagnosis (PC/ED) Service Manual.

- Cooling system size/volume - auxiliary heaters/cooling system hose routing/use of shutoff valves, etc.
- Ambient temperature
- Fuel quality
- Engine starting aids - what type/how used
- Time allowed for engine warm-up at idle before beginning normal operation
- Engine base idle speed
- Cooling system specification - fan clutch type, viscous or on-off/winter fronts
- Cooling system operation - thermostats, fan clutch
- Engine operation - base timing, fuel injection pump, injectors, base engine, etc.

**NOTE:**

TWO (2) TSB ARTICLES HAVE BEEN ISSUED THAT SPECIFICALLY RELATE TO THE ENGINE COOLING SYSTEM AND THE ENGINE'S ABILITY TO ACHIEVE NORMAL OPERATING TEMPERATURES. THESE TSB ARTICLES SHOULD BE REVIEWED AND, IF APPLICABLE, PERFORMED ON VEHICLES THAT HAVE CONCERNS WITH WHITE SMOKE AND/OR ENGINE/CAB HEATING CONCERNS. THE TWO (2) TSB ARTICLES ARE: 1) FD1460 ENGINE - «96-19-11», ENGINE THERMOSTAT SHIM KIT, AND 2) FD1060 ENGINE - «97-1-17», ZERO LEAK THERMOSTAT AND DEAERATION CHECK VALVE.

**OTHER APPLICABLE ARTICLES:**

**96-19-11**

**97-1-17**

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 403000, 499000

---



97-5, *Publication Date: MARCH 3, 1997*

<b>Front End Accessory Drive Belt (FEAD) - FEAD Belt May Wear And/Or Come Off - Vehicles Equipped With FD1460 Engine Built Through 12/96</b>	<b>Article No. 97-5-18</b>
----------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1997 AEROMAX, LOUISVILLE

**ISSUE:**

The Front End Accessory Drive (FEAD) belt may wear and/or come off on some vehicles equipped with an FD1460 engine, Delco generator, and air conditioning. This may be caused by the generator and air conditioning support bracket allowing the generator drive pulley to be misaligned with the other pulleys in the FEAD system.

**ACTION:**

Replace the generator and air conditioning bracket with a revised bracket. The revised bracket should keep the pulleys in alignment to reduce the possibility of FEAD belt wear and/or roll off. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

Refer to Page 12-03A-54 of the 1997 Louisville/AeroMax Service Manual for a sketch of the bracket. The bracket is Item #10.

1. Disconnect the negative battery cable.
2. Remove or reposition any components as necessary to gain access to the bracket.

**NOTE:**

REMOVAL AND INSTALLATION PROCEDURES FOR THE AIR CONDITIONING COMPRESSOR CAN BE FOUND IN SECTION 12-03A, AND FOR THE GENERATOR, SECTION 14-02B, OF THE 1997 LOUISVILLE/AEROMAX SERVICE MANUAL.

3. Remove the bracket from the engine. Discard the bracket, but retain the four (4) attaching bolts.
4. Position the revised Bracket (F7HZ-19D626-AA) onto the engine and torque the attaching bolts to 22-33 N-m (16-24 lb-ft).
5. Reinstall all components that were previously removed.
6. Reconnect the negative battery cable.

PART NUMBER	PART NAME
F7HZ-19D626-AA	Bracket

**OTHER APPLICABLE ARTICLES: NONE**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970518A	Replace Generator Bracket	1.5 Hrs.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
19D626	59

**OASIS CODES:** 203100, 208200, 499000

---



97-6, *Publication Date: MARCH 17, 1997*

<ul style="list-style-type: none"><li>• <b>Hard Starting - Possible Plugged Catalytic Converter/Muffler (CCM) - Vehicles Built After 11/29/93 Equipped With 1994 Emission Level FD1060 Or FD1460 Diesel Engine</b></li><li>• <b>Lack Of Power - Possible Plugged Catalytic Converter/Muffler (CCM) - Vehicles Built After 11/29/93 With 1994 Emission Level FD1060 Or FD1460 Diesel Engine</b></li><li>• <b>Catalytic Converter/Muffler (CCM) - Diagnostic Procedures And Service Parts List - Vehicles Built After 11/29/93 Equipped With 1994 Emission Level FD1060 Or FD1460 Diesel Engine</b></li><li>• <b>Catalytic Converter/Muffler (CCM) - Possible Plugged CCM Due To Internal Engine, Turbocharger Or Fuel Injector Failure - Vehicles Built After 11/29/93 With 1994 Emission Level FD1060 Or FD1460 Diesel Engine</b></li></ul>	<p><b>Article No. 97-6-30</b></p>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------

**MEDIUM/HEAVY TRUCK:**

1994-97 CARGO SERIES, F & B SERIES, L SERIES  
1996-97 AEROMAX, LOUISVILLE

This TSB article is being republished in its entirety to include the latest level parts and to include vehicles built through the 1997 model year.

**ISSUE:**

To comply with 1994 Federal Emission requirements for Diesel Engines, a Catalytic Converter/Muffler (CCM) has been released for FD1060 and FD1460 midrange diesel engines.

**ACTION:**

This TSB article provides information on the CCM application, design, serviceability and testing procedures.


**NOTE:**

PERFORM TSB'S [«96-19-11»](#) AND [«97-1-17»](#) WHEN PROCEEDING WITH THIS TSB ARTICLE.

**CCM APPLICATION**



- Only 1994 emission level engines are equipped with a CCM. The word "catalyst" followed by a five (5) digit number will appear on the engine data plate if the engine is required to be equipped with a CCM. (The engine data plate is attached to the side of the front gear housing in front of the fuel injection pump. Refer to Figure 1.) Certain 1994 engines/vehicles built for export may not be equipped with a CCM. A vehicle's model year and/or build date are not absolute indicators of CCM usage. To verify usage, consult the engine data plate.

ENGINE  
DATA PLATE  
LOCATION





### 1994 EMISSION LEVEL ENGINE DATA PLATE

THE 1994 EMISSION LEVEL ENGINE DATA PLATE HAS A SPECIFIC SECTION THAT INDICATES CATALYST USAGE. A FIVE-DIGIT NUMBER WILL APPEAR IN THIS SECTION IF THE ENGINE IS EQUIPPED WITH A CATALYTIC CONVERTER/MUFFLER (CCM).

 <b>MANUFACTURED BY: CUMMINS ENGINE CO. FOR: FORD MOTOR COMPANY</b> 	Engine Cert. I.D. Certificat d'Identite	C.I.D./ L. Pouce Cube/L	Model Modele	CPL	Family Familie Catalyst No. Catalyseur No.	FEL NOx	EPA	CARB	
	<b>WARNING:</b> Excess fuel may result and warranty is voided if fuel rate rpm or altitudes exceed published maximum values for this model and application. <b>AVERTISSEMENT:</b> Danger de blessures et d'annulation de la garantie si de bit de combustible trop ou defaut de passer les valeurs maximums autorisees pour ce modele et son utilisation. Made in U.S.A.					Engine No. Moteur No.	PM		
	Timing - T.D.C. Calage - P.M.H.	Valve lash cold Jeux Soup. à Froid		Int. Adm	Exh. Ech.	Ford P/N			
	Firing Order Order d'Allumage	Idle Speed (rpm) Vitesse Relevis		E.C.S.	Fuel rate at adv. HP Debit combust. a puis. indiquee		mm <sup>3</sup> / stroke		
Date of Mfg. Date de Fabrication	3926851			Advertised HP Puis. Indiquee (ch)	at a	rpm			

### 1991 EMISSION LEVEL ENGINE DATA PLATE

THE 1991 EMISSION LEVEL ENGINE DATA PLATE DOES NOT HAVE A CATALYST USAGE SECTION.

 <b>MANUFACTURED BY: CUMMINS ENGINE CO. FOR: FORD MOTOR COMPANY</b> 	Engine Cert. I.D. Certificat d'Identite	C.I.D./ L. Pouce Cube/L	Model Modele	CPL	Family Familie	FEL NOx	EPA	CARB	
	<b>WARNING:</b> Excess fuel may result and warranty is voided if fuel rate rpm or altitudes exceed published maximum values for this model and application. <b>AVERTISSEMENT:</b> Danger de blessures et d'annulation de la garantie si de bit de combustible trop ou defaut de passer les valeurs maximums autorisees pour ce modele et son utilisation. Made in U.S.A.					Engine No. Moteur No.	PM		
	Timing - T.D.C. Calage - P.M.H.	Valve lash cold Jeux Soup. à Froid		Int. Adm	Exh. Ech.	Ford P/N			
	Firing Order Order d'Allumage	Idle Speed (rpm) Vitesse Relevis		E.C.S.	Fuel rate at adv. HP Debit combust. a puis. indiquee		mm <sup>3</sup> / stroke		
Date of Mfg. Date de Fabrication	3921620			Advertised HP Puis. Indiquee (ch)	at a	rpm			

## CCM COMPONENT DESIGN AND SERVICEABILITY

- The CCM looks very similar to a conventional muffler, however the CCM contains an oxidation catalyst. Refer to Figure 2.




Figure 2 - Article 97-6-30

- The CCM is not repairable. It must be replaced with the correct CCM.
- Low sulfur diesel fuel must be used. High sulfur diesel fuel can reduce the efficiency of the CCM.

### **WARNING:**

**EXPOSURE TO SULFATES HAS BEEN SHOWN TO RESULT IN RESPIRATORY DISCOMFORT. THE USE OF HIGH SULFUR DIESEL FUEL (ABOVE 0.5% SULFUR BY WEIGHT MAXIMUM) WILL RESULT IN SULFATE FORMATION IN THE EXHAUST GAS, UNDER HIGH LOAD CONTINUOUS USE.**

- **Blending waste lubricating oil in the fuel is not permitted.** The blended oil will accumulate on the catalyst and plug the CCM.
- Internal engine, turbocharger and fuel injector failures may allow debris, excessive engine oil and/or fuel to accumulate on the catalyst and plug the CCM.
- The original equipment (OE) horizontal mounting straps are not reusable. The production straps can be removed and new service straps installed. Depending on the part number, a service CCM may come with mounting straps. Refer to Figure 3 for applications. Mounting straps will have to be ordered separately for those CCM's that do not already come equipped with mounting straps.



## NEW PARTS FOR CCM SYSTEM

USAGE				
ENGINE	EXHAUST	MODELS	PART NUMBERS	DESCRIPTION
FD1080	SHM	F-COWL/BUS	F7HZ-5F250-YA *	MUFFLER/CATALYST
FD1060/FD1480	SHM	LCF/F	F7HZ-5F250-AB *	MUFFLER/CATALYST
FD1080	SHM	F-LO PROFILE	F4HZ-5F250-G *	MUFFLER/CATALYST
FD1060/FD1480	SVM	LCF	F7HZ-5F250-ZA o **SEE NOTE	MUFFLER/CATALYST
FD1060/FD1480	SVO	F	F7HZ-5F250-AC *	MUFFLER/CATALYST
FD1060/FD1450	SVO	LCF	F7HZ-5F250-AD *	MUFFLER/CATALYST
FD1080	SVM	L/A 8601	F7HZ-5F250-Ae *	MUFFLER/CATALYST
FD1480	SVM	L/A 8501/8513	F7HZ-5F250-AE *	MUFFLER/CATALYST
FD1060/FD1480	SHM	L/A 8501	F7HZ-5F250-AJ *	MUFFLER/CATALYST
FD1480	SHM	L/A 8613	F7HZ-5F250-AQ *	MUFFLER/CATALYST
FD1060/FD1480	SVO UF	L/A 8501	F7HZ-5F250-AH *	MUFFLER/CATALYST
FD1480	SVO UF	L/A 8513	F7HZ-5F250-AF *	MUFFLER/CATALYST
FD1060/FD1450	SVO OF	L/A 8501	F7HZ-5F250-9B *	MUFFLER/CATALYST
FD1480	SVO OF	L/A 8513	F7HZ-5F250-AK *	MUFFLER/CATALYST
FD1060	STM Bev	F	F6HZ-5F250-GA *	MUFFLER/CATALYST
FD1060	STM Bev	L 8501	F6HZ-5F250-GA *	MUFFLER/CATALYST
FD1480	STM Bev	L-Series	F6HZ-5F250-HA *	MUFFLER/CATALYST
FD1480	STM Bev	L 8501/8513	F6HZ-5F250-HA *	MUFFLER/CATALYST
FD1480	STM Dump	L 8513	F6HZ-5F250-EA *	MUFFLER/CATALYST
FD1480	STM VO Dump	L 8513	F6HZ-5F250-FA *	MUFFLER/CATALYST

- SHM - Single Horizontal CCM with Horizontal Outlet  
 SVO - Single Horizontal CCM with Vertical Outlet Pipe  
 SVM - Single Vertical CCM  
 STM - Single Transverse CCM with Horizontal Outlet  
 STM VO - Single Transverse CCM with Vertical Outlet  
 SVO UF - Single Horizontal CCM with Vertical Outlet Pipe Routed Under Frame  
 SVO OF - Single Horizontal CCM with Vertical Outlet Pipe Routed Over Frame  
 STM Bev - Single Transverse CCM for Beverage Application  
 STM Dump - Single Transverse CCM for Dump Application  
 STM VO Dump - Single Transverse CCM with Vertical Outlet for Dump Application

- \* Straps included on service CCM
  - o Straps not included on service CCM
  - o Straps not required on service CCM

\*\*NOTE - The following items are required for FD1060 SVM LCF with revised 300 CPS1 CCMs

			DESCRIPTION	PART NUMBER
LCF without Aero	SVM	FD1060	6" Diameter CCM Outlet Pipe for 5" CCM	D8HZ-5255-A
L with Aero	SVM	FD1060	6" Diameter CCM Outlet Pipe for 5" CCM	E8HZ-5255-A
LCF	SVM	FD1060	5" Diameter Outlet Clamp for 5" CCM	E1HZ-5A231-H

### CCM STRAPS

SVO			(11 INCH DIA. CCM)
FCF	L/A 8501/8513	F4HZ-5D223-E	
SHM	F/CF/B/L/F-COWL	F4HZ-5D223-E	
SHM	L/A 8501/8513	F4HZ-5D223-E	
SVO	L-SERIES (STRAIGHT FRAME)	E7HZ-5A215-A	
SVO	L-SERIES (VARIABLE FRAME)	E7HZ-5A215-B	

### (10 INCH DIA. CCM)

SHM	F-LO PROFILE	F4HZ-5D223-D
-----	--------------	--------------

### WATER DRAIN SYSTEM

SVM	LCF	F6HZ-5Q203-A	WATER DRAIN TUBE ASSY.
SVM	L/A 8501/8513	F6HZ-5Q203-AB	WATER DRAIN TUBE ASSY.
SVM	ALL MODELS	375909-S101	ELBOW

### VEHICLE LABELS

ALL MODELS		F4HZ-9A095-C (English)	LABEL -
All Exhaust		F4HZ-9A095-B (French)	NO FUEL/OIL BLENDING

USAGE				
ENGINE	EXHAUST	MODELS	PART NUMBERS	DESCRIPTION
FD1060/FD1450	ALL	ALL	CCM INLET PIPE CLAMP F4HZ-5A231-A	"TORCA" CLAMP (FOR USE WITH SLOTTED INLET PIPE)


NOTE: The "TORCA" clamp bolt must be located between the "TORCA" slots on the end of the inlet pipe. A new "TORCA" clamp is included on each new service CCM. If servicing a CCM inlet pipe, a new "TORCA" clamp should be used.

NOTE: All CCM inlet pipes are 409 stainless or better with "TORCA" slots at the CCM end.

**Figure 3 - Article 97-6-30**

- If the catalyst inlet pipe is modified (e.g., for installation of an exhaust brake), any new inlet pipes must be made of stainless steel, grade 409 or higher, to prevent interior pipe rust from plugging the catalyst.
- Vertical CCM's have a water drain system to prevent water from contacting the catalyst. The water drain system, consisting of an internal water trap, a drain port, a 90 degree elbow and a water drain tube, drains water away from the catalyst and directs it to the ground. The drain tube should be checked periodically to make sure it is not restricted.
- Horizontal CCM's with vertical outlet pipes have two (2) 1/4" diameter water drain holes on the bottom of the CCM body. The drain holes should be checked periodically to make sure they are not restricted.
- A special "Torca" clamp is used to seal and connect the inlet exhaust pipe to the CCM. This special clamp is required to properly close the "Torca" slots on the CCM inlet. When installed on the CCM, inlet the clamp bolt should not be positioned over one (1) of the four (4) "Torca" slots. Instead, the clamp bolt needs to be positioned between the slots in order to seal the connection properly. Refer to Figure 4. Each new service CCM will come equipped with a new "Torca" clamp. These clamps are also available individually.



## TORCA CLAMP AND TORCA SLOTS




### TORCA CLAMP POSITIONING

THE TORCA CLAMP SHOULD BE INSTALLED SO THAT THE CLAMP BOLT IS POSITIONED BETWEEN THE TORCA SLOTS AND THE CLAMP IS FLUSH WITH THE FRONT EDGE OF THE INLET PIPE OF THE CCM.

THIS



NOT THIS



## **CCM DIAGNOSTIC PROCEDURES**

- A CCM back pressure test should be performed when symptoms indicate excessive exhaust system back pressure may be causing engine driveability concerns, such as low power, hard starting, black smoke or low turbocharger boost pressure.
- A CCM back pressure test should also be performed following an internal engine, turbocharger, or fuel injector failure and repair. These types of failures may allow engine debris and/or excessive amounts of engine oil or fuel to accumulate on the catalyst and plug the CCM. The results of this will be excessive exhaust system back pressure and engine driveability concerns.
- Other components in the exhaust system may affect the back pressure test. The integrity of the entire system should be checked before the test is performed.
- The engine data plate should be checked to determine the engine's rated rpm and make sure the vehicle is equipped with a CCM before the test procedure is performed. Refer to Figure 1.

## **DIAGNOSTIC PROCEDURE - CCM BACK PRESSURE TEST PROCEDURE**

### **CAUTION:**

**MAKE SURE VEHICLE PARKING BRAKE IS SET, WHEELS BLOCKED, TRANSMISSION IN NEUTRAL AND THE AREA AROUND THE VEHICLE AND THE ENGINE IS CLEAR BEFORE PERFORMING THIS TEST.**

1. Locate the back pressure test port (1/8" NPT fitting).
  - a. The test port for the single horizontal CCM and the single vertical CCM is located in the inlet end cap of the CCM.
  - b. The test port for the single horizontal CCM with vertical outlet pipe is located in the exhaust pipe just downstream of the engine turbocharger.
2. Install a pressure gauge (Manometer) with a range of 0-60 In. H<sub>2</sub>O or 0-10 In. Hg. or 0-20 kPa onto the test port. The Rotunda Diesel Engine Pressure Test Kit (Gauge Bar) 014-00761 has an appropriate gauge.
3. Determine the engine's rated rpm. This rated rpm specification is located on the engine data plate.
4. Install a tachometer if vehicle is not so equipped.
5. Operate the engine until it reaches normal operating temperature.
6. Accelerate the engine to its high idle/no load wide open throttle (WOT) limit (maximum engine speed). The FD engines under these conditions will reach speeds from 10 to 17 percent above their rated rpm.
  - a. If the engine is unable to reach its high idle/no load WOT limit (maximum speed) (rated rpm plus 10%) it will be necessary to first diagnose and repair this concern before the back pressure test can be performed. Failure to reach rated rpm plus 10% could be caused by a misadjusted throttle linkage, incorrect engine timing, fuel system restrictions or base engine concerns.
  - b. A CCM that is severely plugged could also prevent the engine from reaching its high idle/no load

WOT limit (maximum speed) (rated rpm plus 10%). In this case record the engine rpm and the CCM back pressure at the maximum obtainable engine speed in the comment section of the Repair Order and then replace the CCM.

7. With the engine operating 10 percent above its rated rpm (e.g., rated rpm 2500, engine must operate at 2750 rpm or above), record the engine rpm and exhaust system back pressure. These results must be entered into the comments section of the Warranty Repair Order.
8. The MAXIMUM back pressure limit for both the FD1060 and FD1460 engines is 41 In. H<sub>2</sub>O or 3 In. Hg. or 10.2 kPa. If this is exceeded, replace the CCM. Refer to Figure 3 for applications. If the back pressure is below this specification, then the CCM is not plugged.

### **DEALER WARRANTY CLAIM PROCEDURE**

In the comment section of the Warranty Repair Order, record the engine rpm and exhaust system back pressure results that were obtained during the test (e.g., Engine Maximum rpm: \_\_\_\_\_, "CCM Back Pressure: \_\_\_\_ inches of Hg/H<sub>2</sub>O or kPa"). A copy of the Warranty Repair Order with this information MUST be returned with the CCM. The repair order should be placed into an envelope and attached directly to the CCM.

All CCM assemblies are mandatory return parts. An FCS-700 tag will be issued for each warranty replacement. The failed CCM must be returned to the Warranty Parts Return Center (WPRC), 7655 Haggerty Road, Canton, Michigan 48187. Return the CCM, freight prepaid. Claims for freight reimbursement can be submitted by following the warranty freight reimbursement procedures outlined in the Warranty and Policy Manual, Section 6.3. The failed CCM should be returned in the service CCM packaging. Remove the CCM mounting straps, if necessary to package.

**NOTE:**

IF MOUNTING STRAPS WERE THE CAUSE OF THE CCM FAILURE, THE STRAPS MUST NOT BE REMOVED; BOTH THE CCM AND STRAPS MUST BE RETURNED AS AN ASSEMBLY.

**NOTE:**

WARRANTY PAYMENT MAY BE DENIED IF THE CCM IS REPLACED FOR EXCESSIVE BACK PRESSURE AND THE ENGINE MAXIMUM RPM AND EXHAUST SYSTEM BACK PRESSURE TEST RESULTS ARE NOT WRITTEN ON THE WARRANTY REPAIR ORDER. A COPY OF THE WARRANTY REPAIR ORDER WITH THIS INFORMATION MUST BE RETURNED WITH THE CCM. THE REPAIR ORDER SHOULD BE PLACED INTO AN ENVELOPE AND ATTACHED DIRECTLY TO THE CCM.

PART NUMBER	PART NAME
F4HZ-5F250-G	Muffler/Catalyst
F6HZ-5F250-EA	Muffler/Catalyst
F6HZ-5F250-FA	Muffler/Catalyst
F6HZ-5F250-GA	Muffler/Catalyst
F6HZ-5F250-HA	Muffler/Catalyst
F7HZ-5F250-AB	Muffler/Catalyst
F7HZ-5F250-AC	Muffler/Catalyst
F7HZ-5F250-AD	Muffler/Catalyst
F7HZ-5F250-AE	Muffler/Catalyst
F7HZ-5F250-AF	Muffler/Catalyst
F7HZ-5F250-AG	Muffler/Catalyst
F7HZ-5F250-AH	Muffler/Catalyst
F7HZ-5F250-AJ	Muffler/Catalyst
F7HZ-5F250-AK	Muffler/Catalyst
F7HZ-5F250-BB	Muffler/Catalyst
F7HZ-5F250-YA	Muffler/Catalyst
F7HZ-5F250-ZA	Muffler/Catalyst
D8HZ-5255-A	Outlet Pipe
E5HZ-5255-A	Outlet Pipe
E1HZ-5A231-H	Outlet Clamp
E7HZ-5A215-A	Catalytic Converter/Muffler (CCM) Strap
E7HZ-5A215-B	Catalytic Converter/Muffler (CCM) Strap
F4HZ-5D223-D	Catalytic Converter/Muffler (CCM) Strap
F4HZ-5D223-E	Catalytic Converter/Muffler (CCM) Strap

PART NUMBER	PART NAME
F5HZ-5G203-A	Water Drain Tube
F6HZ-5G203-AB	Water Drain Tube
375906-S101	Water Drain Elbow
F4HZ-9A095-C	Label (English)
F4HZ-9A095-B	Label (French)
F4HZ-5A231-A	Inlet Clamp - "Torca"

**OTHER APPLICABLE ARTICLES:**

**96-19-11**

**97-1-17**

**SUPERSEDES:** 95-5-28

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage And Emissions Warranty Coverage (For Return Details, Refer To Warranty Claim Procedure In This TSB Article)

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970630A	Perform Exhaust Back Pressure Test	0.6 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
5F250	08

**OASIS CODES:** 403000, 602300, 614000, 614500, 614600

---



97-7, *Publication Date: MARCH 31, 1997*

<b>Sun Visor - Optional Roof-Mounted Sun Visor Vibrates At Highway Speeds</b>	<b>Article No. 97-7-15</b>
-------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

The optional roof-mounted sun visor may vibrate excessively at highway speeds. This may be caused by the attaching bolts not properly securing the sun visor to the roof.

**ACTION:**

Replace the current fasteners and add two (2) additional fasteners. The new fasteners and the additional two (2) fasteners should improve the mounting of the sun visor and reduce the possibility of vibration. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Remove the six (6) existing sun visor-to-roof attaching screws and discard.
2. Remove the sun visor and place it on a workbench.
3. To determine the location of the two (2) new sun visor attaching bolts, first measure the length of the sun visor to determine its centerpoint and mark. Refer to Figure 1.







Figure 1 - Article 97-7-15

4. Outboard from the centerpoint, measure 63.5mm (2.5") to each side and mark. Refer to Figure 1.
5. Measure from the rear edge of the visor forward 38mm (1.5") and mark. Refer to Figure 1.
6. Then mark the intersection of the two (2) measurements and drill an 8mm hole through the sun visor. Refer to Figure 1.
7. Place the sun visor in position on the roof, making sure that all six (6) attaching bolt holes are aligned. Using the sun visor as a template, mark the location in the roof that corresponds to the two (2) new holes in the sun visor.
8. Remove the sun visor and drill a 13mm hole at each of the two (2) marks on the roof.

Refer to Figure 2 for the following Steps.



FRONT OF  
VEHICLE

Item	Description	Part Number	Notes
1	Sun Visor		
2	New Screw and Washer Assembly	N606691-S101	2 required
3	New Screw and Washer Assembly	N606689-S55	6 required
4	Existing Isolator Pads	F6HZ-9053740-AA	Replace as needed
5	Cab Roof		
6	New Rivet Nut	N808712-S309	2 required
7	New Clear Silicone Rubber Sealer	D6AZ-19562-AA	
8	New Isolator Pads	E5HZ-9042598-A	2 required
9	Stainless Steel Flatwashers (bolt size - 5/16" or 3/8" - outside diameter 1" - thickness 1/8")		Obtain locally - 8 required (3 for each new screw location)

**Figure 2 - Article 97-7-15**

9. Install a new Rivet Nut (N808712-S309) in the two (2) new holes and apply a small amount of Clear Silicone Rubber Sealer (D6AZ-19562-AA or equivalent meeting Ford specification ESB-M4G92-A) onto the roof around the new rivet nut.
10. Remove the protective paper from the new self-adhesive Isolator Pad (E5HZ-9042598-A) and attach the pad to the new Spacer (obtain locally).
11. Check the condition of the original sun visor-to-roof isolator pads. If the new pads are needed, replace them with new Isolator Pads (F6HZ-9053740-AA).
12. Carefully position the sun visor onto the roof and align the attaching bolt holes.
13. Flatwashers will be needed as spacers between the sun visor and the roof at the two (2) new attaching screw locations. Obtain locally, six (6) stainless steel 5/16" or 3/8"x1/8" washers and place three (3) washers between the roof/isolator pad and new sun visor at each of the two (2) new attaching locations.
14. Install six (6) new Screw and Washer Assemblies (N606689-S55) through the original six (6) hole positions.
15. Install the two (2) new Screw and Washer Assemblies (N606691-S101) through the two (2) new sun visor holes with the new spacer/pad assemblies into the new rivet nuts.
16. Make sure the sun visor is properly aligned and torque all the fasteners to 22-32 N-m (16-24 lb-ft).

PART NUMBER	PART NAME
(Obtain Locally)	Washer - 5/16" Or 3/8"x1/8" - Stainless Steel
E5HZ-9042598-A	Isolator Pad
F6HZ-9053740-AA	Isolator Pad
N606691-S101	Screw And Washer Assembly
N808712-S309	Rivet Nut
N606689-S55	Screw And Washer Assembly
D6AZ-19562-AA	Clear Silicone Rubber Sealer

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970715A	Replace Current Fasteners And Install Repair Kit	0.8 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
7004104	57

**OASIS CODES:** 108000, 111000, 701000, 703000

---



97-7, *Publication Date: MARCH 31, 1997*

<ul style="list-style-type: none"><li>• <b>Fuel Injection Pump - Bosch - Service Information For FD1060/1460 Diesel Engines</b></li><li>• <b>Engine - FD1060 - Bosch Fuel Injection Pump Service - Service Tip</b></li><li>• <b>Engine - FD1460 - Bosch Fuel Injection Pump Service - Service Tip</b></li></ul>	<b>Article No. 97-7-16</b>
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1992-97 C SERIES, F & B SERIES, L SERIES

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

There have been several requests from the field to clarify the Bosch warranty policy and procedures for components used on FD1060 and FD1460 engines.

**ACTION:**

Refer to the following text for service information regarding Bosch policies and procedure on warrantable repairs.

The Bosch warranty coverage on fuel injection components used on FD1060 and FD1460 engines is 2 years from a vehicle's warranty start date or 160,900 km (100,000 miles), whichever comes first.

For vehicles that have exceeded the time and mileage limits of the Bosch warranty, certain components may still be covered under the Ford warranty. Specific information regarding the Ford warranty can be found in the Ford Warranty and Policy Manual.

If a Bosch component is suspect of failure it should be removed from the engine and brought to a Bosch Diesel Service Dealer (DSD) for diagnosis, repair and or replacement. **It is very important that the DSD be advised if the failed component is still covered within the Bosch warranty program.** The DSD will then be able to submit for payment the necessary repairs through the Bosch warranty system. In order for the DSD to file a warranty claim, certain information regarding the vehicle and the failed Bosch component is required. This information should be provided to the DSD when the component is brought in for service. The required information is:

- Customer complaint/engine driveability concern
- Engine make and model
- Engine serial number
- Vehicle make and model
- Vehicle delivery date or warranty start date
- Failed component part number
- Failed component/vehicle miles or hours of operation
- Failure date/vehicle repair date

Bosch provides a form entitled "Request for Warranty Repair" that highlights the required information. It is available from the local DSD and is a useful tool to ensure all the required information is provided.

In some cases, the Bosch warranty may have expired, however, a vehicle may still be covered under the Ford warranty. In these cases, the failed component should still be repaired at a Bosch DSD and a claim for the cost submitted to Ford Motor Company following the procedure listed in the Ford Warranty and Policy Manual. Additional questions regarding Bosch warranty policies and procedure should be directed to your local Bosch DSD.

**NOTE:**

IF THE FUEL INJECTION PUMP IS RETURNED TO A DSD FOR DIAGNOSIS AND/OR REPAIR, IT IS VERY IMPORTANT THAT THE OVERFLOW CHECK VALVE/FUEL PRESSURE VALVE BE RETURNED WITH THE PUMP. THIS WILL ENSURE THAT THE DSD WILL BE ABLE TO MAKE THE PROPER DIAGNOSIS.

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 404000

---



97-7, *Publication Date: MARCH 31, 1997*

<b>Wiring - Wire Harness Ground - Intermittent Or Open</b>	<b>Article No. 97-7-17</b>
------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**


Intermittent or complete loss of the electrical system may be experienced on some vehicles. This may be due to the improper seating of the single terminal ground system connectors which are used to connect the -14290- wire harness to the -14289- or -14305- wire assemblies.

**ACTION:**

Gain access to the ground system connectors and fully seat the connections. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Raise the hood to gain access to the left inner fender splash panel.
2. Loosen the fender splash panel forward retaining nut. **DO NOT REMOVE THE NUT.**
3. While supporting the fender splash panel, remove the remaining five (5) nuts and then carefully remove the fender splash panel.
4. Locate the ground system single terminal connectors (Figure 1) that connect the -14290- wire assembly to the -14289- or -14305- wire assemblies.



**Figure 1 - Article 97-7-17**

5. The two (2) ground circuits are tagged green and blue for identification. In addition, if the vehicle is equipped with a sleeper, there will be a third ground system connector in this location that will need to be checked.
6. With channel lock pliers, carefully seat each connector completely. Seating the connectors by hand will not supply sufficient force to completely seat the connectors.
7. Reinstall the inner fender splash panel and the retaining screws.

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970717A	Repair Wiring Connections	0.4 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
14290	93

**OASIS CODES:** 203000, 203200

---



## Bulletin Contents

TSB Article 97-8-3 has been superseded by Article 98-2-1.

---



97-9, *Publication Date: APRIL 28, 1997*

<b>Accessory Drive Belts - Excessive Wear And/Or Roll-off - Vehicles Equipped With Detroit Diesel Engine</b>	<b>Article No. 97-9-22</b>
--------------------------------------------------------------------------------------------------------------	--------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-98 AEROMAX, LOUISVILLE

**ISSUE:**

The generator drive belts may wear excessively and/or roll off the Front End Accessory Drive (FEAD) pulleys on some vehicles. This may be caused by the belts oscillating excessively at certain engine rpms.

**ACTION:**

Replace the current belts with revised belts. The revised belts are banded and are less susceptible to oscillations. This should reduce the belt wear and roll-off concern. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Remove the two (2) single V-belts from the generator and engine pulleys. Refer to the appropriate year Louisville/AeroMax Service Manual, Page 03C-05-1 for removal procedures.
2. Check the conditions of the drive pulleys. Make sure they are free of nicks, debris, etc.
3. Install the new banded belt over the generator pulleys and engine pulleys. Be sure the belts are properly seated in the pulleys.
4. Tighten the generator adjusting bolt so that the belt tension on the new banded belt is within 183-203 N-m (135-150 lb-ft).

PART NUMBER	PART NAME
F7HZ-8620-VA	Banded V-Belt

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
970922A	Replace Generator Belts	0.4 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
8620	36

**OASIS CODES:** 203000, 203100, 205000, 499000





97-10, *Publication Date: MAY 12, 1997*

<ul style="list-style-type: none"><li>• <b>Air Brakes - Oil Leak At Air Brake Compressor - Vehicles Built Through 4/1/97 Equipped With FD1460 Engine And Air Brakes</b></li><li>• <b>Leak - Oil Leak At Air Brake Compressor - Vehicles Built Through 4/1/97 Equipped With FD1460 Engine And Air Brakes</b></li></ul>	<b>Article No. 97-10-11</b>
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1993-97 CARGO SERIES, F SERIES, L SERIES

**ISSUE:**

The engine may leak oil at the air brake compressor on some vehicles. This may be caused by insufficient rear support of the air brake compressor.

**ACTION:**

Replace the rear air brake compressor support bracket with a new bracket. The new bracket will provide additional support to reduce the possibility of oil leakage. Refer to the following Service Procedure for details.


**SERVICE PROCEDURE**

**NOTE:**

THIS PROCEDURE DETAILS THE REMOVAL AND INSTALLATION OF THE AIR BRAKE REAR SUPPORT BRACKET ONLY. IF ENGINE OIL IS LEAKING FROM THE AIR BRAKE COMPRESSOR TO FRONT COVER ATTACHMENT POINT, IT MAY BE NECESSARY TO RESOLVE THE ENGINE OIL LEAK BEFORE REPLACING THE BRACKET AS OUTLINED IN THIS TSB ARTICLE. REFER TO THE APPROPRIATE MODEL/YEAR SERVICE MANUAL FOR COMPLETE AIR COMPRESSOR AND GASKET REMOVAL AND INSTALLATION PROCEDURES.

Refer to Figure 1.

**FD1460  
EXISTING INSTALLATION  
BRAKE AIR COMPRESSOR REAR SUPPORT BRACKET**



Item	Description	
1	Engine Bracket	(retain)
2	Engine Bracket Washers	(retain)
3	Engine Bracket Bolts	(retain)
4	Air Compressor Rear Support Bracket Bolts	(discard)
5	Air Compressor Rear Support Bracket	(discard)


---

**Figure 1 - Article 97-10-11**

1. Remove and discard the existing air compressor support bracket and the four (4) bracket retaining bolts.

Refer to Figure 2.

**FD1460  
REVISED INSTALLATION  
BRAKE AIR COMPRESSOR REAR SUPPORT BRACKET**



Item	Description
1	Original Engine Bracket
2	Original Engine Bracket Washers
3	Original Engine Bracket Bolts
4	Revised Air Compressor Rear Support Bracket Bolts
5	Revised Air Compressor Rear Support Bracket

**Figure 2 - Article 97-10-11**

2. Coat the four (4) new Bolts (N807470-S36) with Loctite 242 or equivalent.
3. Position the new Support Bracket (F7HZ-2902-BA) onto the air compressor and engine bracket.
4. Install the four (4) new bolts, torquing the bolts to 41-62 N-m (30-46 lb-ft).

PART NUMBER	PART NAME
F7HZ-2902-BA	Support Bracket
N807470-S36	Bolts (4 Req'd.)

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971011A	Install New Support Bracket - Vehicles Equipped With Power Steering	0.9 Hr.
971011B	Install New Support Bracket - Vehicles Not Equipped With Power Steering	0.6 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
2902	33

**OASIS CODES:** 301000, 302000, 401000, 497000, 499000

---





97-10, *Publication Date: MAY 12, 1997*

<ul style="list-style-type: none"><li>• <b>Loss Of Power - Premium Electronic Diesel Engines - Intermittent Or No Signal From Vehicle Speed Sensor (VSS) - Vehicles Built Through 1/14/97</b></li><li>• <b>Malfunction Indicator Lamp (MIL) Illuminated - Fault Codes: 31 And 36 For CAT Engine, 241 And 242 For Cummins Engine, And 54 And 84 For DDC Engine - Vehicles Built Through 1/14/97</b></li><li>• <b>Cruise Control - Erratic Or Inoperative - Vehicles With Premium Electronic Diesel Engine - Vehicles Built Through 1/14/97</b></li><li>• <b>Lamp - Malfunction Indicator Lamp (MIL) Illuminated With Fault Codes: 31 And 36 For CAT Engine, 241 And 242 For Cummins Engine, And 54 And 84 For DDC Engine - Vehicles Built Through 1/14/97</b></li><li>• <b>Speedometer - Erratic Or Inoperative - Vehicles With Premium Electronic Diesel Engine - Vehicles Built Through 1/14/97</b></li><li>• <b>Engine - Premium Electronic Diesel - Intermittent Or No Signal From Vehicle Speed Sensor (VSS) - Vehicles Built Through 1/14/97</b></li></ul>	<b>Article No. 97-10-12</b>
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

#### **MEDIUM/HEAVY TRUCK:**

1997 AEROMAX, LOUISVILLE

#### **ISSUE:**

A loss of power, and inoperative or erratic speedometer and cruise control may occur on some vehicles. The Malfunction Indicator Lamp (MIL) may illuminate with Electronic Control Module (ECM) fault codes:

- 31 and 36 for CAT engines
- 241 and 242 for Cummins engines
- 54 and 58 for DDC engines

This may be caused by a complete or intermittent loss of the Vehicle Speed Sensor (VSS) signal to the ECM.

#### **ACTION:**

Verify wire harness and connector integrity by referring to the following Service Procedure, Steps 1-3. Refer to Step 4 if engine loss of power occurs after the instrument cluster has been heat-soaked through normal operation. In addition, refer to the 1997 Louisville/AeroMax Service Manual, Sections 03C and 13 for normal diagnostic and repair of the VSS, cruise control and instrumentation/warning systems.

#### **SERVICE PROCEDURE**

1. VSS Connector Terminal Crimp
  - a. Unplug the VSS connector at the transmission.

#### **NOTE:**

THE WIRE ASSEMBLY CONNECTOR USED AT THE VSS IS A PULL-TO-SEAT TYPE CONNECTOR. TO INSPECT THE WIRE TERMINAL CRIMPS, CAREFULLY PUSH THE TERMINALS AND WIRES TOWARD THE FRONT OF THE CONNECTOR HARD SHELL.

- b. Each terminal will have separate insulation and conductor crimps. If both insulation and conductor have been crimped at the conductor crimp location, this will result in a loss of conductor integrity at the crimp and an intermittent or continuous loss of the vehicle speed input signal to the

speedometer. If loss of conductor integrity is found, go to the following Step 1c.

- c. Replace the connector assembly with Connector Kit F6HZ-14A464-DEA. Refer to TSB «97-10-13» for additional kit information.

2. Electronic Control Module (ECM) Connector Terminal Crimp - -12A581- Wire Assembly (DDC Series 60 Engines)

- a. Unplug the -12A581- wire assembly to the ECM connector.

**NOTE:**

THE WIRE ASSEMBLY CONNECTOR USED AT THE ECM IS A PULL-TO-SEAT CONNECTOR. TO INSPECT THE VEHICLE SPEED INPUT CIRCUIT (CK-614 GREEN) LOCATED AT PIN E2, CAREFULLY PUSH THE TERMINAL AND WIRE TOWARD THE FRONT OF THE CONNECTOR HARD SHELL.

- b. The terminal will have separate insulation and conductor crimps. If both insulation and conductor have been crimped at the conductor crimp, this will result in a loss of conductor integrity at the crimp and an intermittent or continuous loss of the vehicle speed input signal to the ECM. If loss of conductor integrity is found, go to Step 2c.
- c. Replace the damaged terminal with a terminal and wire pigtail assembly from the VSS Connector Kit (F6HZ-14A464-DEA). Refer to TSB «97-10-13» for additional kit information.

3. Speedometer Head - 16-Way Connector Terminals - -14401- Wire Assembly

- a. If Steps 1a-2c indicate no problem and an intermittent or no signal condition is present, carefully inspect the speedometer head to -14401- wire assembly connector.

**CAUTION:**

**DO NOT ATTEMPT TO PROBE THE SPEEDOMETER HEAD-TO-WIRE ASSEMBLY CONNECTOR FROM THE FRONT.**

- b. Inspect the connector for deformed terminals by looking into the front of the connector.
- c. If the connector hard shell or any terminals show signs of damage, replace the connector with the connector assembly found in Connector Kit (F7HZ-14A464-AB).

4. Speedometer Head - Loss Of Digital Output Signal To ECM - Erratic Or Inoperative Speedometer

- a. Check the vehicle production date. If the production date is earlier than 1/14/97, remove the speedometer assembly.
- b. Check the speedometer head for a tag showing alert number 10695533. Electronic cluster gauges will have the alert sticker placed on the metal housing of the tachometer. Individual case gauges will have the alert sticker on the plastic housing of the gauge.

If no alert sticker is found, and the engineering number is one of the following:

- F7HT-17255-AB
- F7HT-17255-BB
- F7HT-17C290-AB
- F7HT-17C290-BB

- F7HT-17C290-CB
- F7HT-17C290-DB

replace the speedometer assembly.

Refer to the following Speedometer Assembly Description Chart for part number.

<b>SPEEDOMETER ASSEMBLY DESCRIPTION</b>		
<b>Gauge Type</b>	<b>Description</b>	<b>Part Number</b>
RPO Case	5" Speedometer - Miles	F7HZ-17255-AB
RPO Case	5" Speedometer - Kilometers	F7HZ-17255-BB
Electronic Cluster	Speedometer/Tachometer - Miles	F7HZ-17255-AA
Electronic Cluster	Speedometer/Tachometer - Kilometers	F7HZ-17255-BA
Electronic Cluster	Speedometer/Tachometer - Miles with Hour	F7HZ-17255-CA
Electronic Cluster	Speedometer/Tachometer - Kilometers with Hour	F7HZ-17255-DA

- Set the speedometer and, if applicable, tachometer calibration as per the procedure outline in the 1997 Louisville/AeroMax Service Manual, Section 13.
- If needed, the speedometer repair can be verified by performing the following Speedometer Heat Test.

### **SPEEDOMETER ASSEMBLY HEAT SENSITIVITY/HEAT SOAK TEST**

**NOTE:**

TESTS MUST BE PERFORMED WITH THE SPEEDOMETER ASSEMBLY COMPLETELY INSTALLED. PERFORMING THE HEAT SOAK/BREAKDOWN TEST WITH THE ASSEMBLY REMOVED WILL BE INEFFECTIVE.

- Clear any active/inactive codes from the ECM. Start the engine, turn on instrument panel lights, set fan to high speed, heat to full "hot" position and vent ducts to floor position.
- With windows closed, bring the engine and cab to full operating temperature.
- After allowing the speedometer head and instrument panel assembly to fully heat soak, speedometer operation and vehicle speed signal output to the ECM can be verified by road testing or dynamometer testing. The test may also be performed by operating the transmission in high gear at engine idle with the transmission coupling shaft removed.
- With instrument panel lights on and the heater on high as per Step 1 of this test, the engine should not derate, speedometer become inoperative/erratic, or the check engine light come on during the test.
- Verify that the ECM has not logged a loss of vehicle speed signal fault code to complete the test.

PART NUMBER	PART NAME
F7HZ-14A464-AB	Connector Kit
F6HZ-14A464-DEA	Connector Kit
F7HZ-17255-AB	Speedometer Assembly
F7HZ-17255-BB	Speedometer Assembly
F7HZ-17255-AA	Speedometer Assembly
F7HZ-17255-BA	Speedometer Assembly
F7HZ-17255-CA	Speedometer Assembly
F7HZ-17255-DA	Speedometer Assembly

**OTHER APPLICABLE ARTICLES:**

**97-10-13**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971012A	Install Vehicle Speed Sensor (VSS) Or Electronic Control Module (ECM) Connector Kit	0.5 Hr.
971012B	Replace Speedometer 16-Way Connector	0.5 Hr.
971012C	Replace Speedometer Assembly - Cluster Assembly Type	0.7 Hr.
971012D	Replace Speedometer Assembly - Individual Gauge Type	0.9 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
17255	42

**OASIS CODES:** 204000, 204200, 205000, 609000, 610000, 612000, 614000, 698298

---



97-10, *Publication Date: MAY 12, 1997*

<b>Wiring - Electrical Connector Kit Availability</b>	<b>Article No. 97-10-13</b>
-------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

This TSB article is being republished in its entirety to include the latest level parts for repairing the Speedometer and Tachometer.

**ISSUE:**

Kits for repairing wire harness connectors are now available for service. These kits will save the cost of replacing an entire wiring harness when only the connector needs replacing.

**ACTION:**

If connector repairs are required and you desire to purchase a kit(s), refer to the Connector Repair Kits Chart in this TSB article to order the proper repair kit.

The connector repair kits provide service to in-line and component connectors, fuse panel and power distribution box terminals, and bulkhead connectors.

**IN-LINE AND COMPONENT CONNECTORS**

Each kit contains a connector, pigtail assemblies (terminals and butt splice crimped to a 203mm (8") wire) and applicable spacer and grommet. The kit contains material to completely replace an entire connector, independent of usage.

**FUSE PANEL, POWER DISTRIBUTION BOX AND BULKHEAD TERMINALS**

Each kit contains pigtail assemblies in various wire gauges to provide terminal replacement for one of the following components:

- Fuses
- Relays
- Circuit Breakers
- Customer Access Studs
- Bulkhead Connectors (cab and engine compartment)

**BULKHEAD CONNECTOR**

Each cab and engine compartment bulkhead connector is offered individually.

### CONNECTOR REPAIR KITS

Usage	Service Part Number	Instruction Sheet (I.S.) Number
Rear axle shift control switch	F6HZ-14A464-BAA	6880A
Rectangular headlamp	F6HZ-14A464-BB	6881
Gauges: transmission temperature, engine oil temperature, rear axle temperature, water temperature, voltmeter, fuel	F6HZ-14A464-BC	6882
Ignition switch	F6HZ-14A464-BD	6883
Blower motor switch	F6HZ-14A464-BE	6884
Courtesy lamp switch	F6HZ-14A464-BF	6885
Engine temperature (ether start) switch and warning indicator switches: transmission oil, engine oil, water	F6HZ-14A464-BG	6886
Stoplamp low pressure switch, 2-speed axle selector motor	F6HZ-14A464-BJA	6888
Turn/emergency signal switch (UT)	F6HZ-14A464-BKA	6889

### CONNECTOR REPAIR KITS (Cont'd.)

Usage	Service Part Number	Instruction Sheet (I.S.) Number
Windshield wiper control module (Signal-Stat), multi-function switch (UT), audio amplifier output	F6HZ-14A464-BLA	6890
Aerodynamic headlamps	F6HZ-14A464-BMA	6891
Ether valve solenoid, heated seat	F6HZ-14A464-BN	6892
Windshield washer pump motor	F6HZ-14A464-BR	6893
23-pin in-line connector (14289/12A581 wire assembly)	F6HZ-14A464-BSA	6894
Switches: low air pressure, park brake, cruise dropout, low oil pressure	F6HZ-14A464-BTA	6895
Engine fan control module (Cummins M11, N14, 3306, and 1460)	F6HZ-14A464-BUA	6896
Stoplamp switch, air dryer	F6HZ-14A464-BVA	6897
Multi-function turn/emergency signal switch (UT)	F6HZ-14A464-BYA	6898
Fuel sender, fog/road lamps	F6HZ-14A464-BZA	6899
Push button start switch	F6HZ-14A464-CAA	6875
9-pin trailer connector	F6HZ-14A464-CBA	6876
31-pin in-line connector (15525 wire assembly)	F6HZ-14A464-CCA	6877
31-pin in-line connector (15525 wire assembly)	F6HZ-14A464-CDA	6878
Tail lamp, A/C compressor (CAT 3306/FD1460)	F6HZ-14A464-CEA	6879
Idle validation switch (Cummins/DDC engines)	F6HZ-14A464-CFA	6936
Start interlock switch	F6HZ-14A464-CGA	6937
Exhaust brake clutch switch	F6HZ-14A464-CHA	6938
Air intake solenoid, temperature senders: engine oil, transmission oil, water, rear axle	F6HZ-14A464-CJA	6939
Wiper control module (Signal-Stat/Ford)	F6HZ-14A464-CKA	6940
76-way (white) bulkhead connector (cab)	F6HZ-14A464-CLA	7100
76-way (black) bulkhead connector (cab)	F6HZ-14A464-CMA	7101

**CONNECTOR REPAIR KITS (Cont'd.)**

<b>Usage</b>	<b>Service Part Number</b>	<b>Instruction Sheet (I.S.) Number</b>
76-way (white) bulkhead connector (engine)	F6HZ-14A464-CNA	7102A
76-way (black) bulkhead connector (engine)	F6HZ-14A464-CRA	7103
ABS control module	F6HZ-14A464-CTA	7105A
ABS wheel speed sensor	F6HZ-14A464-CUA	7106
ABS regulating air valve	F6HZ-14A464-CVA	7107
Accelerator position sensor (CAT engine)	F6HZ-14A464-CYA	7108
1-pin in-line connector (10K699/14290/14305/14A318 wire assemblies)	F6HZ-14A464-CZA	7109
1-pin in-line connector (10K699/14289/14305/14A318 wire assemblies)	F6HZ-14A464-DAA	7110
Headlamp switch	F6HZ-14A464-DBA	7111
Temperature sensor: air intake heater, fan control coolant	F6HZ-14A464-DCA	7112
Accelerator position sensor (Cummins-electronic, DDC, and mechanical engines with electronic transmission)	F6HZ-14A464-DDA	7113
Hood-mounted turn signal lamps, speed sensor (manual transmission), engine speed sensor, turbine speed sensor, output speed sensor	F6HZ-14A464-DEA	7114
Speedometer sensor (non-electronic automatic transmission), tachometer sensor	F6HZ-14A464-DFA	7115
Neutral sensing switch (non-electronic automatic transmission)	F6HZ-14A464-DGA	7116
Clockspring assembly	F6HZ-14A464-DHA	7117
Gauge illumination: fuel, voltmeter, brake application pressure, air pressure, oil pressure, rear axle temperature, water temperature, engine oil temperature, transmission oil temperature	F6HZ-14A464-DJA	7118
Message center	F6HZ-14A464-DKA	7119
Dimmer/dome switch, multi-function switch (Signal-Stat)	F6HZ-14A464-DLA	7120

**CONNECTOR REPAIR KITS (Cont'd.)**

Usage	Service Part Number	Instruction Sheet (I.S.) Number
Switches: engine brake min/max (CAT/DDC), jake brake min/max, clearance lamp/blink, engine shutdown override DDC60, pressure governor system enable, engine idle (Cummins), exhaust brake control, heated mirror, 2-speed axle, trailer hook-up, fan override, engine brake on/off (CAT/DDC), road/fog lamp	F6HZ-14A464-DMA	7121
CB hot post	F6HZ-14A464-DNA	7122
Blower motor resistor	F6HZ-14A464-DRA	7123
Allison HD-4000 Series transmission	F6HZ-14A464-DS	7124
1-pin in-line connector (12A581/14289 wire assemblies)	F6HZ-14A464-DT	7125
1-pin in-line connector (12A581/14289 wire assemblies)	F6HZ-14A464-DU	7126
Customer access - Allison electronic automatic transmission	F6HZ-14A464-DV	7127
Engine customer access (Cummins M11/N14 and CAT 3176/3406)	F6HZ-14A464-DY	7128
Circuit breaker terminals	F6HZ-14A464-DZ	7129
Fuse terminals	F6HZ-14A464-EA	7130
Relay terminals	F6HZ-14A464-EB	7131
Bulkhead connector terminals (cab)	F6HZ-14A464-EC	7132
Bulkhead connector terminals (engine compartment)	F6HZ-14A464-ED	7133
Customer access - fuse panel (eyelets)	F6HZ-14A464-EE	7134
Back-up lamp switch (manual transmission)	F6HZ-14A464-FB	6753B
Low coolant level sensor (mechanical/DDC), idle validation switch	F6HZ-14A464-FC	6754A
Gauges: fuel, voltmeter, water temperature, rear axle temperature, engine oil temperature, transmission temperature	F6HZ-14A464-FD	6755A
Fuel shut-off solenoid (FD1460), Cummins electronic control module	F6HZ-14A464-FM	6763A
Heater blower motor	F6HZ-14A464-LB	6773A
Daytime running lamp module	F7HZ-14A464-BA	7170
Air valve switch	F7HZ-14A464-AA	7171
Speedometer	F7HZ-14A464-AB	7210
Tachometer	F7HZ-14A464-AC	7211



PART NUMBER	PART NAME
F6HZ-14A464-BAA	Connector Repair Kit
F6HZ-14A464-BB	Connector Repair Kit
F6HZ-14A464-BC	Connector Repair Kit
F6HZ-14A464-BD	Connector Repair Kit
F6HZ-14A464-BE	Connector Repair Kit
F6HZ-14A464-BF	Connector Repair Kit
F6HZ-14A464-BG	Connector Repair Kit
F6HZ-14A464-BJA	Connector Repair Kit
F6HZ-14A464-BKA	Connector Repair Kit
F6HZ-14A464-BLA	Connector Repair Kit
F6HZ-14A464-BMA	Connector Repair Kit
F6HZ-14A464-BN	Connector Repair Kit
F6HZ-14A464-BR	Connector Repair Kit
F6HZ-14A464-BSA	Connector Repair Kit
F6HZ-14A464-BTA	Connector Repair Kit
F6HZ-14A464-BUA	Connector Repair Kit
F6HZ-14A464-BVA	Connector Repair Kit
F6HZ-14A464-BYA	Connector Repair Kit
F6HZ-14A464-BZA	Connector Repair Kit
F6HZ-14A464-CAA	Connector Repair Kit
F6HZ-14A464-CBA	Connector Repair Kit
F6HZ-14A464-CCA	Connector Repair Kit
F6HZ-14A464-CDA	Connector Repair Kit
F6HZ-14A464-CEA	Connector Repair Kit
F6HZ-14A464-CFA	Connector Repair Kit
F6HZ-14A464-CGA	Connector Repair Kit
F6HZ-14A464-CHA	Connector Repair Kit
F6HZ-14A464-CJA	Connector Repair Kit
F6HZ-14A464-CKA	Connector Repair Kit
F6HZ-14A464-CLA	Connector Repair Kit
F6HZ-14A464-CMA	Connector Repair Kit
F6HZ-14A464-CNA	Connector Repair Kit
F6HZ-14A464-CRA	Connector Repair Kit
F6HZ-14A464-CTA	Connector Repair Kit
F6HZ-14A464-CUA	Connector Repair Kit
F6HZ-14A464-CVA	Connector Repair Kit
F6HZ-14A464-CYA	Connector Repair Kit
F6HZ-14A464-CZA	Connector Repair Kit
F6HZ-14A464-DAA	Connector Repair Kit
F6HZ-14A464-DBA	Connector Repair Kit
F6HZ-14A464-DCA	Connector Repair Kit
F6HZ-14A464-DDA	Connector Repair Kit
F6HZ-14A464-DEA	Connector Repair Kit
F6HZ-14A464-DFA	Connector Repair Kit
F6HZ-14A464-DGA	Connector Repair Kit
F6HZ-14A464-DHA	Connector Repair Kit
F6HZ-14A464-DJA	Connector Repair Kit
F6HZ-14A464-DKA	Connector Repair Kit
F6HZ-14A464-DLA	Connector Repair Kit
F6HZ-14A464-DMA	Connector Repair Kit
F6HZ-14A464-DNA	Connector Repair Kit
F6HZ-14A464-DRA	Connector Repair Kit
F6HZ-14A464-DS	Connector Repair Kit
F6HZ-14A464-DT	Connector Repair Kit

PART NUMBER	PART NAME
F6HZ-14A464-DU	Connector Repair Kit
F6HZ-14A464-DV	Connector Repair Kit
F6HZ-14A464-DY	Connector Repair Kit
F6HZ-14A464-DZ	Connector Repair Kit
F6HZ-14A464-EA	Connector Repair Kit
F6HZ-14A464-EB	Connector Repair Kit
F6HZ-14A464-EC	Connector Repair Kit
F6HZ-14A464-ED	Connector Repair Kit
F6HZ-14A464-EE	Connector Repair Kit
F6HZ-14A464-FB	Connector Repair Kit
F6HZ-14A464-FC	Connector Repair Kit
F6HZ-14A464-FD	Connector Repair Kit
F6HZ-14A464-FM	Connector Repair Kit
F6HZ-14A464-LB	Connector Repair Kit
F7HZ-14A464-BA	Connector Repair Kit
F7HZ-14A464-AA	Connector Repair Kit
F7HZ-14A464-AB	Connector Repair Kit
F7HZ-14A464-AC	Connector Repair Kit

**OTHER APPLICABLE ARTICLES:** NONE

**SUPERSEDES:** 96-23-23

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 203000, 203200

---



97-11, *Publication Date: MAY 27, 1997*

**BRAKES - 4-Way Flashers Do Not Function While Service Brake Is Applied - Vehicles With Signal-Stat Turn Signal System**

**Article No.  
97-11-23**

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

An additional module is needed to allow the 4-way flashers to function with the service brakes applied, depending on the vocation of the truck. The standard Signal-Stat multi-function switch does not allow the 4-way flashers to function with the service brakes applied.

**ACTION:**

Install a new Brake Override Module. The new module in series with the Signal-Stat multi-function switch will allow the 4-way flashers to function with the service brake applied. Refer to the following Service Procedure for details.

**NOTE:**

THIS INFORMATION IS ONLY APPLICABLE TO THE SIGNAL-STAT (TRACTOR PACKAGE) TURN SIGNAL SYSTEM.

**SERVICE PROCEDURE**

This is an information only TSB article. This is a Domestic Special Order (DSO) option that the customer may now need, due to a change in the vocation of the truck. Start with Step 1 for electronic engines. For mechanical engines, start with Step 2.

1. If equipped with an electronic engine, remove the Deutsch engine diagnostic plug bracket mounted below the instrument panel on the left side of the steering column. Install a new Module Mounting Bracket (F7HZ-14A206-BB) and relocate the Deutsch engine diagnostic plug to the new mounting bracket.
2. On mechanical engines, install a Module Mounting Bracket (F7HZ-14A206-BB) below the instrument panel on the left side of the steering column.
3. Disconnect Connector C254 from the Signal-Stat multi-function switch and install a Brake Override Module (F7HZ-13A318-BA) in series. Mount the Brake Override Module to the new mounting bracket. Refer to the Louisville/AeroMax Electrical and Vacuum Troubleshooting Manual (EVTM), Page 90-2.
4. Plug the Ground Wire (F7HZ-14N000-AA) into the module ground terminal and the eyelet into a suitable ground location. A ground possibility would be the fuse panel terminal post "C".

PART NUMBER	PART NAME
F7HZ-14A206-BB	Module Mounting Bracket
F7HZ-13A318-BA	Brake Override Module
F7HZ-14N000-AA	Ground Wire

**OTHER APPLICABLE ARTICLES: NONE**

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 201000, 201200, 301000

---



97-11, *Publication Date: MAY 27, 1997*

<ul style="list-style-type: none"> <li>• <b>Air Brakes - Oil Leak At Air Brake Compressor - Vehicles Built Through 4/1/97 Equipped With FD1060 Or FD1460 Engine And Air Brakes</b></li> <li>• <b>Leak - Oil Leak At Air Brake Compressor - Vehicles Built Through 4/1/97 Equipped With FD1060 Or FD1460 Engine And Air Brakes</b></li> </ul>	<p><b>Article No.</b> <b>97-11-24</b></p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------

**MEDIUM/HEAVY TRUCK:**

1993-97 CARGO SERIES, F SERIES, L SERIES

**ISSUE:**

The engine may leak oil between the air brake compressor and engine gear housing mating point on some vehicles. This may be caused by the gasket not sealing properly between these two points.

**ACTION:**

Replace the original gasket with a revised Gasket. The revised gasket has been redesigned to provide an improved sealing surface to reduce the possibility of oil leakage. Refer to the following text for details.

The removal and installation procedures for the air brake compressor and the revised gasket can be found in the appropriate model/year Service Manual, Section 06-08A.

**NOTE:**

FOR THE REVISED GASKET TO PERFORM PROPERLY, IT IS VERY IMPORTANT THAT THE AIR BRAKE COMPRESSOR BE MOUNTED SECURELY TO THE FRONT GEAR HOUSING. MAKE SURE THE TWO (2) STUDS AND NUTS THAT SECURE THE AIR BRAKE COMPRESSOR TO THE FRONT GEAR HOUSING ARE SOUND, COATED WITH LOCTITE AND TORQUED TO THE FOLLOWING SPECIFICATIONS: AIR COMPRESSOR MOUNTING STUDS 60-95 N-m (44-70 LB-FT) AND AIR COMPRESSOR ATTACHING NUTS 60-95 N-m (44-70 LB-FT). THE AIR BRAKE COMPRESSOR REAR SUPPORT BRACKET MUST ALSO BE MOUNTED PROPERLY AND ITS FASTENERS COATED WITH LOCTITE AND TORQUED PROPERLY. ADDITIONAL INFORMATION REGARDING THE AIR BRAKE COMPRESSOR CAN BE FOUND IN THE FOLLOWING TSBs, [«94-9-18»](#), [«95-15-17»](#), AND TSB [«97-10-11»](#).

PART NUMBER	PART NAME
F7HZ-3K506-AA	Gasket

**OTHER APPLICABLE ARTICLES:**

**94-9-18**

**95-15-17**

**97-10-11**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971124A	Replace Air Brake Compressor Mounting Gasket	Refer To SLTS Manual

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
2902	33

**OASIS CODES:** 301000, 302000, 401000, 497000, 499000

---



97-12, *Publication Date: JUNE 9, 1997*

<b>Turn Signal - Turn Signals May Cancel/Shut Off When Steering Column Is Jarred - Vehicles Equipped With Manual Cancel Turn Signal Switch Built 11/95 Through 5/97</b>	<b>Article No. 97-12-14</b>
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**


The turn signal switch may self-cancel when the steering column and/or vehicle is jarred. This may be caused by insufficient detent within the switch for the turn signal switch lever.

**ACTION:**

Replace the turn signal switch with a revised Turn Signal Switch (F7HZ-13B302-DA) which has an improved detent. Refer to Section 17-01 of the appropriate year Louisville/AeroMax Service Manual for removal and installation procedures.

**NOTE:**

THE NEW TURN SIGNAL SWITCH HAS A LONGER WIRING HARNESS WHICH NOW CONNECTS DIRECTLY TO THE WIPER MOTOR (REFER TO FIGURE 1). WITH THE NEW SWITCH, THE JUMPER HARNESS THAT WAS USED TO CONNECT THE PREVIOUS SWITCH TO THE WIPER MOTOR IS NO LONGER NEEDED AND SHOULD BE REMOVED AND DISCARDED.



Item	Description
1	New Signal Stat Turn Signal/Multi-function Switch
2	Steering Column
3	Clutch Pedal
4	New Switch Wiring Harness (this harness is part of the Signal Stat Switch and it connects directly into the Windshield Wiper Module)
5	Windshield Wiper Module



**Figure 1 - Article 97-12-14**

PART NUMBER	PART NAME
F7HZ-13B302-DA	Turn Signal Switch

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971214A	Replace Turn Signal Switch	0.3 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
13341	12

**OASIS CODES:** 201000, 201200, 203000

---



97-12, *Publication Date: JUNE 9, 1997*

<ul style="list-style-type: none"><li>• <b>NOISE - "Rattling" Noise In Clutch Linkage - Vehicles With Standard Transmission And 113 Inch Or 122 Inch Bumper-To-Back Of Cab Length</b></li><li>• <b>CLUTCH - "Rattling" Noise In Clutch Linkage - Vehicles With Standard Transmission And 113 Inch Or 122 Inch Bumper-To-Back Of Cab Length</b></li></ul>	<b>Article No. 97-12-15</b>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1997-98 AEROMAX, LOUISVILLE

**ISSUE:**

A "rattling" noise may be heard coming from the clutch linkage on some vehicles. This noise is most prevalent when the vehicle is being driven under load at highway speeds. This may be caused by vibrations generated by the engine, transmission, and driveline that are transmitted through the hard mechanical clutch linkage into the cab.


**ACTION:**

Replace the original clutch rod end with the new elastomeric rod end. The new rod end has an internal rubber isolator which may reduce the amount of vibrations that can be transmitted through the clutch rod. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

Refer to Figures 1 and 2 for Step 1 of the Service Procedure.


**ORIGINAL CLUTCH PEDAL LINKAGE INSTALLATION**



Item	Description
1	Clutch Pedal Shaft and Lever
2	Clutch Pedal
3	Clutch Rod Assembly
4	Clutch Rod Ball Stud (will be replaced)
5	Clutch Release Lever

**Figure 1 - Article 97-12-15**

**ORIGINAL CLUTCH ROD ASSEMBLY INSTALLATION**



**VIEW IN DIRECTION OF ARROW A (PREVIOUS ILLUSTRATION)  
TOP VIEW**

**BEFORE DISASSEMBLY, NOTE THE POSITION OF THE CLUTCH ROD ASSEMBLY, EITHER INBOARD OR OUTBOARD OF THE CLUTCH RELEASE LEVER. THIS POSITION MUST BE MAINTAINED WHEN THE CLUTCH ROD IS REINSTALLED.**

Item	Description
1	Clutch Rod Ball Stud
2	Clutch Rod Assembly
3	Ball Stud Attaching Nut
4	Clutch Release Lever
5	Transmission

---

**Figure 2 - Article 97-12-15**

**NOTE:**

TO ENSURE PROPER OPERATION, IT IS VERY IMPORTANT THAT THE STANDARD PARTS PROVIDED IN THIS TSB BE USED TO INSTALL THE NEW ELASTOMERIC ROD.

1. Remove the clutch rod assembly from the vehicle.
  - a. Remove the nut (at the top of the rod) retaining the clutch rod to the clutch pedal shaft and lever. Discard the nut.

**NOTE:**

BEFORE REMOVING THE CLUTCH ROD ASSEMBLY FROM THE CLUTCH ROD LEVER AT THE TRANSMISSION, BE SURE TO NOTICE ITS ORIENTATION. THE CLUTCH ROD WILL EITHER BE INBOARD (BETWEEN THE CLUTCH LEVER AND THE TRANSMISSION) OR OUTBOARD OF THE CLUTCH LEVER (OPPOSITE THE TRANSMISSION, BETWEEN THE CLUTCH LEVER AND THE FRAME).

- b. Remove the nut (at the bottom of the rod) retaining the clutch rod to the clutch release lever. Discard the nut.
    - c. Remove the clutch rod assembly from the vehicle.
2. Secure the clutch rod in a vise so that the lower ball stud (the ball stud that attaches to the clutch release lever) is accessible.


Refer to Figure 3 for Steps 3 and 4 of the Service Procedure.

**ORIGINAL BALL STUD AND NEW ELASTOMERIC ROD END**

CUT THE BALL STUD SHANK HERE – USE CARE TO PREVENT DAMAGE TO THE CLUTCH ROD THREADS

MEASURE AND NOTE THIS DIMENSION

INSTALL THE NEW ELASTOMERIC ROD END SO THAT THIS DIMENSION IS MAINTAINED



Item	Description
1	Clutch Rod
2	Original Ball Stud
3	Clutch Release Lever
4	New Elastomeric Rod End
5	New Attaching Bolt
6	New Washer
7	New Locknuts

**Figure 3 - Article 97-12-15**

3. Measure the distance from the center of the ball stud to the collar of the clutch rod as shown in Figure 3. Note this measurement.
4. In addition, mark the clutch rod to note the orientation of the ball stud in relation to the clutch rod.

**NOTE:**

THE ORIGINAL BALL STUD WAS CRIMPED ONTO THE CLUTCH ROD. IN ORDER TO INSTALL THE NEW ELASTOMERIC ROD END, THE ORIGINAL BALL STUD MUST BE REMOVED. THIS MUST BE DONE CAREFULLY TO PREVENT DAMAGE TO THE CLUTCH ROD THREADS.

5. Using a die grinder with a metal cutting bit, carefully cut the original ball stud shank lengthwise making sure not to cut the threads of the clutch rod. Several cuts can be made to ease removal.
6. With the cuts made, the ball stud can now be rotated off the clutch rod threads.
7. Inspect the threads on the rod for damage. If necessary, a die, 3/8-24 UNF, may be used to clean up the threads.

Refer to Figure 3 for Step 8 of the Service Procedure.

8. Assemble the new Elastomeric Rod End (F7HZ-7B537-CC) onto the clutch rod.
  - a. Thread the new Stop Nut (355571-S8) onto the clutch rod.

**NOTE:**

IT IS VERY IMPORTANT THAT THE NEW ELASTOMERIC ROD END BE INSTALLED IN THE SAME POSITION AND ORIENTATION AS THE ORIGINAL BALL STUD.

- b. Thread the new rod end onto the clutch rod until the same dimension is obtained as was measured in Step 3.
  - c. Make sure the orientation of the rod is the same as the original.
  - d. Tighten the stop nut against the new rod end.
9. Install the clutch rod onto the vehicle.
  - a. Place the clutch rod either inboard or outboard of the clutch release lever, as was noted in Step 1.
  - b. Install the new Bolt (58638-S100) through the new Washer (391817-S421M), the new rod end, and then through the clutch release lever. Install the new Nut (382802-S36) onto the bolt. Torque the nut to 42-57 N-m (31-42 lb-ft). Do not exceed this torque value.
  - c. Attach the upper end of the clutch rod onto the clutch pedal shaft and lever. Install a new Nut (391494-S2) and torque the nut to 42-57 N-m (31-42 lb-ft).
10. Cycle the clutch pedal several times to be sure the linkage operates correctly.

**NOTE:**

THIS PROCEDURE SHOULD NOT AFFECT THE CLUTCH PEDAL ADJUSTMENT. HOWEVER, IF CLUTCH PEDAL ADJUSTMENT IS NEEDED, REFER TO SECTION 08-02 OF THE APPROPRIATE YEAR LOUISVILLE/AEROMAX SERVICE MANUAL FOR THE ADJUSTMENT PROCEDURE.



PART NUMBER	PART NAME
F7HZ-7B537-CC	Clutch Rod Elastomeric End
58638-S100	Bolt (3/8"-16x2.0)
382802-S36	Nut (3/8"-16 Lock)
391817-S421M	Washer (3/8")
355571-S8	Nut (3/8"-24 Jam)
391494-S2	Nut (3/8"-24 P/T)

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971215A	Replace Clutch Rod End	0.7 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
7521	33

**OASIS CODES:** 497000, 506000, 597997, 702000

---



97-13, *Publication Date: JUNE 23, 1997*

<b>Heater - Lack Of Heat In Cab - Vehicles With FD1060 Engine Built Through 12/5/96</b>	<b>Article No. 97-13-24</b>
-----------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1997 LOUISVILLE

**ISSUE:**

There may be insufficient cab heat on some vehicles. This may be caused by the hot water supply being incorrectly routed from the radiator.

**ACTION:**



Relocate the hot water supply to the engine block to provide sufficient cab heat. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

**NOTE:**

COMPONENTS WHICH ARE THREADED WITH AN NPT SHOULD NOT BE REUSED. ONLY COMPONENTS WITH NEW PIPE THREADS AND SEALANT SHOULD BE USED IN THE MODIFICATION DESCRIBED IN THIS TSB ARTICLE.

1. Drain engine coolant to a level just below the top of the water jacket.
2. Remove the heater core supply hose (lower hose) from the heater core and current valve location on the upper radiator pipe.
3. Remove heater control valve and all attached elbows and fittings from the upper radiator pipe and install a new Plug (obtain locally) into the boss where the valve was located.
4. Remove all components and plugs from the two (2) water jacket penetrations near the top, forward portion of the engine immediately before the thermostat housing.
5. Assemble the Heater Water Inlet Tube Assembly (F2HZ-18696-C), T-fitting (obtain locally), Pipe Connector 5/8x1/2" (obtain locally), Heater Water Control Valve Assembly (FOHZ-18495-A), Elbow - 45 Degree (obtain locally), and Pipe Connector 3/4x1/2" (obtain locally) into the water jacket penetration nearest engine centerline. Refer to Figure 1.



**Figure 1 - Article 97-13-24**

6. Connect upper hose connector coming out of the shutoff valve and Heater Core Inlet (standard bulk hose or silicone hose) with existing sleeve protector cut to 584mm (23"), and secure hose at both ends with Hose Clamps (E9HS-8287-CA). Secure air compressor coolant hose to the other hose connector hose clamp in the T-fitting with an existing hose clamp (Figure 1).
7. Into the other open water jacket penetration, nearest lift hook, install a 1/4x1/2" Bushing (obtain locally), then the Water Outlet Adapter (F6HZ-8K554-A) and the quiescent vent line.
8. All fitting orientations shall be such that no hoses contact any other engine component.
9. Refill engine coolant to correct level and check for leaks.

PART NUMBER	PART NAME
E9HS-8287-CA	Hose Clamp
F2HZ-18696-C	Heater Water Inlet Tube Assembly
(Obtain Locally)	Tee (1/2x1/2" External x 1/2" Pipe)
(Obtain Locally)	Connector (5/8x1/2")
F6HZ-8K554-A	Adapter - Water Outlet Connector
(Obtain Locally)	Pipe Reducer Bushing
FOHZ-18495-A	Heater Water Control Valve Assembly
(Obtain Locally)	Elbow
(Obtain Locally)	Plug
(Obtain Locally)	Connector (3/4x1/2")
(Obtain Locally)	Heater Hose
(Obtain Locally)	Heater Hose Sleeve Protector

**OTHER APPLICABLE ARTICLES: NONE**

**WARRANTY STATUS: Eligible Under Basic Warranty Coverage**

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971324A	Relocate Hot Water Supply As Outlined	0.7 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
18696	43

**OASIS CODES: 208000, 208100, 208999**



97-14, *Publication Date: JULY 7, 1997*

<b>Horns - Air Horn Lanyard Is Loose And/Or Pulls Free - Vehicles Equipped With Air Horns</b>	<b>Article No. 97-14-24</b>
-----------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-98 AEROMAX, LOUISVILLE

**ISSUE:**

The air horn lanyard may become loose and/or unattached from the air horn valve. This may be due to the air horn valve fastener not being able to properly fasten the lanyard to the valve.

**ACTION:**

Replace the air horn and lanyard assembly. The new valve and lanyard have been revised to reduce the possibility of the lanyard pulling away from the valve. Refer to Section 13-01 of the appropriate Louisville/AeroMax Service Manual for removal and installation procedures.

PART NUMBER	PART NAME
F8HZ-13910-AA	Air Horn Valve And Lanyard Assembly

**OTHER APPLICABLE ARTICLES: NONE**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971424A	Replace Air Horn Valve And Lanyard	2.1 Hrs.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
13910	01

**OASIS CODES:** 203000, 205000

---



97-15, *Publication Date: JULY 21, 1997*

<b>Window - Window May be Difficult To Roll Up Or Down</b>	<b>Article No. 97-15-29</b>
------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1975-96 L SERIES

**ISSUE:**

The windows may be hard to roll up and/or down. This may be caused by corrosion buildup within the window regulator mechanism.

**ACTION:**

Replace the window regulator with a revised regulator which has added a corrosion coating on the regulator to reduce the possibility of corrosion. Refer to the appropriate L-Series Service Manual, Section 01-11, for removal and installation procedures.

PART NUMBER	PART NAME
F5HZ-8023200-AA	Regulator - Right
F5HZ-8023201-AA	Regulator - Left

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971529AT	Replace Window Regulator - Both Sides	1.3 Hrs.
971529A	Replace Window Regulator - One Side	0.8 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
8023200	41

**OASIS CODES:** 102000, 110000

---



97-15, *Publication Date: JULY 21, 1997*

Not enough memory.

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

1996-98 CARGO SERIES, F & B SERIES, L SERIES

**ISSUE:**

A brake "squealing" noise and/or vibration may be heard or felt on some vehicles traveling at low speeds with a light load. This may be caused by the brake lining material.

**ACTION:**

Replace the brake linings. The new linings have been revised with a different material to reduce the possibility of noise and/or vibration at low speeds with a light load. Refer to the appropriate model/year Service Manual for removal and installation procedures.

**NOTE:**

THE BRAKE LININGS LISTED IN THIS ARTICLE ONLY APPLY TO VEHICLES EQUIPPED WITH Q-PLUS BRAKES.

PART NUMBER	PART NAME
F8HZ-2018-AA	Brake Shoes - 15x4 (9K Axle)
F8HZ-2018-BA	Brake Shoes - 15x4 (10-13K Axle)
F8HZ-2018-CA	Brake Shoes - 16.5x5 (12-13K Axle)
F8HZ-2018-DA	Brake Shoes - 16.5x5 (14.6K Narrow Axle)
F8HZ-2018-EA	Brake Shoes - 16.5x6 (14.6K Wide Axle)
F8HZ-2018-FA	Brake Shoes - 16.5x6 (16-18K Axle)
F8HZ-2218-AA	Brake Shoes - 16.5x7 (21K Axle)
F8HZ-2218-BA	Brake Shoes - 16.5x7 (17.5-19K Single/34K, 40K Tandem Axle)
F8HZ-2007-AA	Lining Kit - 15x4 (9K Axle)
F8HZ-2007-BA	Lining Kit - 15x4 (10-13K Axle)
F8HZ-2007-CA	Lining Kit - 16.5x5 (12-13K Axle)
F8HZ-2007-DA	Lining Kit - 16.5x5 (14.6K Narrow Axle)
F8HZ-2007-EA	Lining Kit - 16.5x6 (14.6K Wide Axle)
F8HZ-2007-FA	Lining Kit - 16.5x6 (16-18K Axle)
F8HZ-2007-HA	Lining Kit - 16.5x7 (21K Axle)
F8HZ-2007-JA	Lining Kit - 16.5x7 (17.5-19K Single/34K, 40K Tandem Axle)

**OTHER APPLICABLE ARTICLES: NONE**

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971530A	Replace Brake Linings	Refer To SLTS Manual

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
2007	69

**OASIS CODES:** 301000, 702000, 702100, 702200, 703000

---





97-16, *Publication Date: AUGUST 4, 1997*

<b>Exhaust - Muffler Inlet Pipe Cracked - Vehicles Equipped With Detroit Diesel Engine With Vertical Exhaust - Built Through 5/5/97</b>	<b>Article No. 97-16-13</b>
-----------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-98 AEROMAX, LOUISVILLE

**ISSUE:**

The exhaust pipe may crack on some vehicles at the muffler inlet. The original exhaust pipe is not robust enough and results in cracking around the pipe flange where it mates with the turbocharger outlet.

**ACTION:**

Replace the muffler inlet pipe with a revised pipe to reduce the potential for cracking. Refer to Section 09-00 of the appropriate Louisville/AeroMax Service Manual for removal and installation procedures.

PART NUMBER	PART NAME
F8HZ-5218-AA	Muffler Inlet Pipe

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
971613A	Replace Muffler Inlet Pipe	0.7 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
5246	01

**OASIS CODES:** 403000

---



97-18, *Publication Date: SEPTEMBER 2, 1997*

<b>Brakes - Air Brake Governor Operational Specifications - Service Tip</b>	<b>Article No. 97-18-14</b>
-----------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1998 AEROMAX, F & B SERIES, LOUISVILLE

**ISSUE:**

The specification for the air brake governor cut-in and cut-out on vehicles equipped with air brakes has been changed starting with vehicles built after 3/1/97. This is due to a change in Federal Regulations concerning air brake systems.

**ACTION:**

Refer to the following text for the new specifications.

Additional information regarding air brake supply systems and the air brake governor can be found in Section 06 of the appropriate Service Manual.

For vehicles built after 3/1/97, the air brake governor specifications are:

- Cut-in pressure - 765 ±76 kPa (111 ±11 PSI)
- Cut-out pressure - 896 ±34 kPa (130 ±5 PSI)

For vehicles built before 3/1/97, the air brake governor specifications are:

- Cut-in pressure - When pressure drops below cut-out pressure by 83-179 kPa (12-26 PSI)
- Cut-out pressure - 827 ±34 kPa (120 ±5 PSI)

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 301000, 302000, 390000

---

## Bulletin Contents

TSB Article 97-18-15 has been superseded by Article 97-19-23.

---

## Bulletin Contents

TSB Article 97-18-16 has been superseded by Article 97-19-24.

---



97-18, *Publication Date: SEPTEMBER 2, 1997*

<b>Engine - Electronically Controlled Engine - Service Caution</b>	<b>Article No. 97-18-17</b>
--------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1995-98 AEROMAX, L SERIES, LOUISVILLE

**ISSUE:**

A service caution is necessary when reprogramming electronic diesel engine management systems (Powertrain Control Module/Electronic Control Unit).

**ACTION:**

Some electronically controlled diesel engines can be modified to increase engine output by altering the original engine management system. Such modification may result in damage to the drivetrain and chassis components designed to accommodate original engine output levels. These modifications may void the vehicle warranty for affected components as stated in the vehicle's warranty guide.

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 614000, 614500, 614600

---

## Bulletin Contents

TSB Article 97-19-10 has been superseded by Article 98-10-4.

---



97-19, *Publication Date: SEPTEMBER 15, 1997*

**Steering - Wandering Or Darting After Contacting Uneven Pavement - Vehicles With 18,000-20,000 Lb Front Axle, Dual Steering Gears, And Additional Pusher Or Tag Rear Axles**

**Article No.  
97-19-21**

**MEDIUM/HEAVY TRUCK:**

1996-98 LOUISVILLE

**ISSUE:**

The vehicle may wander or dart after contacting uneven pavement. This may be caused by the addition of aftermarket pusher axles or tag rear axles and their affect on the front end geometry.

**ACTION:**

Install new steering and suspension components. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

**NOTE:**

THE SERVICE PROCEDURE IN THIS TSB ARTICLE PROVIDES ONLY A GENERAL GUIDELINE FOR DIAGNOSING AND REPAIRING A POTENTIAL STEERING WANDER OR DARTING CONCERN ON CERTAIN LOUISVILLE VEHICLES. COMPLETE DIAGNOSTIC AND SERVICE (INCLUDING PART REMOVAL AND INSTALLATION PROCEDURES AND FASTENER TORQUE SPECIFICATIONS) INFORMATION FOR THE PARTS PROVIDED IN THE ARTICLE CAN BE FOUND IN THE APPROPRIATE YEAR LOUISVILLE/AEROMAX SERVICE MANUAL, SECTIONS 04 AND 11.

**CAUTION:**

**ON SOME VEHICLES IT WILL BE NECESSARY TO DRILL NEW MOUNTING HOLES FOR THE UPPER SHOCK BRACKET INTO EACH FRAME RAIL. CARE SHOULD BE TAKEN WHEN PERFORMING THE DRILLING OPERATION TO PREVENT DAMAGE TO THE FRAME AND SURROUNDING COMPONENTS. REFER TO THE FORD BODY BUILDERS LAYOUT BOOK FOR ADDITIONAL INFORMATION REGARDING FRAME RAIL MODIFICATIONS.**

1. Verify the concern.


**NOTE:**

INSPECT THE VEHICLE TO DETERMINE IF A MODIFICATION HAS BEEN MADE TO THE FRONT SUSPENSION OF THE VEHICLE. SOME VEHICLES COMPLETED AS DUMP TRUCKS HAVE ADDITIONAL PUSHER OR TAG REAR AXLES, AND TO LEVEL OUT THE FRAME, SPACERS OR ADDITIONAL SPRING LEAVES MAY HAVE BEEN ADDED TO THE FRONT SPRINGS. THE MAXIMUM ALLOWABLE SPRING PACK THICKNESS IS 134.1mm (5.28") WITH THE CASTER WEDGE INCLUDED (NEW SPRINGS HAVE A CASTER WEDGE INCLUDED IN THE SPRING PACK). IF THE SPRING PACK IS THICKER, THE EXTRA LEAVES MUST BE REMOVED.

2. Balance the front tires.
3. Check and correct, if necessary, front wheel runout if it exceeds 2.28mm (0.090").
4. Refer to the following chart:







Item	Description
1	New U-Bolts
2	Existing Spring Pack
3	New Lower Shock Bracket (if needed)
4	New Shock Absorber (if needed)
5	Washer
6	Nut
7	Front Axle
8	Spacer

Figure 1 - Article 97-19-21






Figure 2 - Article 97-19-21

Item	Description
1	Pitman Arm (Right Side)
2	Pitman Arm (Left Side)




**RH SIDE**  
**18,000-LB AND 20,000-LB**  
**FRONT AXLES ONLY**

**LH SIDE**



**Figure 3 - Article 97-19-21**

# HOLE PATTERN - UPPER SHOCK BRACKET



REFERENCE: BRAKE JOUNCE HOSE  
BULKHEAD FITTING

3 HOLES REQUIRED -

13.87mm (0.546") DIA.  
13.36mm (0.526")

**Figure 4 - Article 97-19-21**

5. Replace the two (2) existing pitman arms with revised Pitman Arms (F8HZ-3590-CA - Right Side, and F8HZ-3590-DA - Left Side) (Figure 3).
6. Check the front end caster and toe-in, and if necessary adjust to specifications listed in the appropriate Louisville/AeroMax Service Manual, Section 04-00.

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

**DEALER CODING**

**OASIS CODES:** 303000, 304000

---



97-19, *Publication Date: SEPTEMBER 15, 1997*

**Tachometer - Inoperative And/Or Erratic - Vehicles Equipped With CAT 3306, Cummins 1060, Or Cummins 1460 Mechanical Engine**

**Article No.  
97-19-22**

**MEDIUM/HEAVY TRUCK:**

1996-98 AEROMAX, LOUISVILLE

**ISSUE:**

The tachometer may become inoperative and/or erratic on some vehicles equipped with a mechanical engine. This may be due to a defective and/or improperly adjusted tachometer sensor.

**ACTION:**

Install a new tachometer sensor that has a plastic spacer used to set initial gap. The correct gap should reduce the possibility of an inoperative and/or erratic tachometer. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Check the tachometer sensor output voltage signal at the wire harness connector on the tachometer gauge. Output voltage must be measured with the connector attached to the gauge and the engine at an idle.
  - a. For individual case gauges, measure voltage between Pins 4 and 7.
  - b. For electronic cluster gauges, measure voltage between Pins 1 and 10.
2. If the voltage is less than 1.5 volts, replace the tachometer sensor.

**NOTE:**

THE ELECTRICAL CONNECTOR ON THE NEW TACHOMETER SENSOR WILL NOT CONNECT TO THE EXISTING TACHOMETER SENSOR CONNECTOR OF THE 14289 WIRE HARNESS. IN ORDER TO CONNECT THE NEW SENSOR TO THE WIRE HARNESS, IT WILL BE NECESSARY TO REMOVE BOTH THE SENSOR AND WIRE HARNESS CONNECTORS AND SPLICE THE SENSORS DIRECTLY TO THE HARNESS WIRES, OR USE A QUALITY WATERPROOF TWO PIN AFTERMARKET CONNECTOR TO CONNECT THE SENSOR TO THE HARNESS. REFER TO THE SPLICING PROCEDURES FOUND IN «[TSB 96-16-3](#)» TO ENSURE A QUALITY ELECTRICAL CONNECTION. DUE TO THE TYPE OF SIGNAL GENERATED BY THE TACHOMETER SENSOR, EITHER ONE OF THE SENSOR WIRES MAY BE CONNECTED TO EITHER ONE OF THE HARNESS WIRES FOR THE SENSOR AND GAUGE TO FUNCTION PROPERLY.

3. Adjust the new sensor by rotating the sensor clockwise until it contacts the flywheel. Tighten the jam nut to 27-34 N-m (20-25 lb-ft). Operating the engine will remove the plastic spacer.
4. If the sensor is removed and reinstalled after the initial adjustment procedure, it can be adjusted by rotating the sensor clockwise until it contacts the flywheel and then backing off 1/4 to 1/2 turn. The correct sensor gap should be 1.25mm (0.050").



**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

**DEALER CODING**

**OASIS CODES:** 204000, 204100, 204200

---



97-19, *Publication Date: SEPTEMBER 15, 1997*

<ul style="list-style-type: none"><li>• <b>Electrical - Fan Clutch May Be Inadvertently Activated When Operating Some Electrical Accessories - Vehicles With CAT 3306, Cummins M11, Cummins N14, FD1060 Or FD1460 Engine - Vehicles With Air Operated On/Off Engine Cooling Fan Clutches</b></li><li>• <b>Engine - CAT 3306 - Fan Clutch May Be Inadvertently Activated When Operating Some Electrical Accessories - Vehicles With Air Operated On/Off Engine Cooling Fan Clutches</b></li><li>• <b>Engine - Cummins M11 Or N14 - Fan Clutch May Be Inadvertently Activated When Operating Some Electrical Accessories - Vehicles With Air Operated On/Off Engine Cooling Fan Clutches</b></li><li>• <b>Engine - FD1060 Or FD1460 - Fan Clutch May Be Inadvertently Activated When Operating Some Electrical Accessories - Vehicles With Air Operated On/Off Engine Cooling Fan Clutches</b></li></ul>	<p style="text-align: center;"><b>Article No. 97-19-23</b></p>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------

#### **MEDIUM/HEAVY TRUCK:**

1996-98 AEROMAX, LOUISVILLE

This TSB article is being republished in its entirety to revise the Operation Time.

#### **ISSUE:**

The fan clutch may cycle on when electrical accessories, such as turn signals, headlamps, etc. are activated on some vehicles. This may be due to the engine cooling fan control module ground circuit picking up interference from other electrical accessories and causing the module to falsely cycle the fan clutch.

#### **ACTION:**

Add a dedicated electrical ground wire for the fan control module. Refer to the following Service Procedure for details.

#### **SERVICE PROCEDURE**


##### **NOTE:**

THE INFORMATION IN THIS TSB ARTICLE APPLIES TO VEHICLES EQUIPPED WITH ELECTRIC STARTERS THAT HAVE A GROUND STUD. VEHICLES EQUIPPED WITH AIR STARTERS WILL REQUIRE THAT THE NEW JUMPER GROUND WIRE BE ATTACHED DIRECTLY TO THE BATTERY NEGATIVE TERMINAL SINCE THE AIR STARTER DOES NOT CONTAIN A STUD. Fabricate a new fan control ground circuit jumper wire using the following locally obtained components:

- Approximately 1905mm (75") of 14 gauge wire
- Butt connector, 14 gauge, with heat shrink insulation
- Eye connector, 14 gauge, with heat shrink insulation (determine eye terminal size by measuring the starter motor ground stud diameter and then selecting the appropriate size terminal)

1. Disconnect the negative battery cable.

For Steps 2 and 3, refer to Figure 1.



FAN CONTROL  
MODULE

-14290-  
CONNECTOR


FRONT OF  
VEHICLE

STEERING  
SHAFT

**Figure 1 - Article 97-19-23**

2. Locate the engine fan control module on the cowl panel just above the steering column outlet. It may be necessary to temporarily remove the air cleaner housing to gain access to the module.
3. Disconnect the -14290- harness from the module.
4. Open the -14290- harness and locate the module ground wire #57 BK. The #57 BK wire connects to Pin B of the fan control module.

For Steps 5-7, refer to Figure 2.




Item	Description
1	New Jumper Wire – Module Ground (75" 14 gauge wire)
2	New Butt Connector (14 gauge with heat shrink insulation)
3	Existing Module Ground Wire #57 (cut to accept new jumper wire)
4	New Starter Motor Ground Stud Eyelet Connector (eyelet connector with 14 gauge wire connector and heat shrink insulation)
5	Starter Motor

**Figure 2 - Article 97-19-23**

5. About 127mm (5") from the module connector, cut the #57 wire.
6. Strip the module end of the #57 wire and install and crimp the new butt connector onto the wire. Heat to seal the insulation.
7. On the harness side of the #57 wire, use heat shrink tubing to seal off the end.
8. Reconnect the -14290- connector onto the fan control module.
9. Route the new jumper wire along the cowl, across to the engine and down to the starter. Use plastic wire ties to secure the wire in position. The new jumper wire must be routed and secured to prevent it from interfering or chafing on other components.

For Step 10-12, refer to Figure 3.



**Figure 3 - Article 97-19-23**

10. Remove the starter motor ground stud nut.
11. Install the new jumper harness eyelet onto the starter motor ground stud.
12. Install the ground stud nut. Torque specifications for the ground stud nut based on the stud can be found in the Louisville/AeroMax Service Manual Index.
13. If removed, install the air cleaner housing assembly or any other components that may have been removed to gain access to perform this repair.
14. Reconnect the battery ground cable.

**OTHER APPLICABLE ARTICLES:** NONE

**SUPERSEDES:** 97-18-15

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

**DEALER CODING**

**OASIS CODES:** 402000, 499000

---

## Bulletin Contents

TSB Article 97-19-24 has been superseded by Article 98-25-7.

---



## Bulletin Contents

TSB Article 97-20-1 has been superseded by Article 97-21-4.

---



**Hood - Hood Tilt Cylinder Inoperative - Vehicles Built Through 11/96**

**Article No.  
97-20-20**

**MEDIUM/HEAVY TRUCK:**

1996-97 AEROMAX, LOUISVILLE

**ISSUE:**

The hood tilt cylinder may become inoperative. This may be caused by motion between the hood and radiator support causing the seals and attaching components to fail.

**ACTION:**

Replace the hood tilt cylinder with a cable system. The cable system is not sensitive to motion between the hood and radiator support. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Tilt hood and support the hood from the ground.
2. Remove the tilt cylinder and the two (2) mounting brackets and discard. Also discard the clevis pin. Refer to Figure 1.




Figure 1 - Article 97-20-20

3. Install revised hood bracket onto the hood using the fasteners removed in Step 2. Torque the bolts to

9-13 N-m (80-115 lb-in).

4. Install revised radiator support bracket onto the radiator support using the fasteners removed in Step 2. Torque the bolts to 42-57 N-m (31-42 lb-ft).
5. Using a 5/16" Clevis Pin (76007-S8, or equivalent), install the cable yoke onto the hood bracket and secure with the retaining clip removed in Step 2. Install the cable spring onto the radiator support bracket as shown in Figure 2.




Figure 2 - Article 97-20-20

PART NUMBER	PART NAME
F7HZ-16B816-DA	Hood Bracket
F7HZ-16828-CA	Radiator Support Bracket
F7HZ-16B898-BA	Cable Assembly

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
972020A	Replace Hood Tilt Cylinder With Cable System	0.5 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
16B816	12

**OASIS CODES:** 112000

---



97-20, Publication Date: SEPTEMBER 29, 1997

- Heater - Poor/Slow Heat And/Or Coolant Leak - Vehicles Equipped With DDC Series 60, CAT 3406, Or FD1460 Engine Built Through 6/11/97
- Cooling System - Coolant Leak - Poor/Slow Heat - Vehicles Equipped With DDC Series 60, CAT 3406, Or FD1460 Engine Built Through 6/11/97

Article No.  
97-20-21

#### MEDIUM/HEAVY TRUCK:

1997 AEROMAX, F & B SERIES, LOUISVILLE

#### ISSUE:

Some vehicles may have been built with a 45 degree elbow that is missing some threads. The elbow is located within the heater plumbing and may result in a coolant leak and/or poor/slow heat.

#### ACTION:

Replace the 45 degree elbow in the heater plumbing. Refer to the following Service Procedure for details.

#### SERVICE PROCEDURE

1. Verify the concern.
2. Drain coolant following the procedure outlined in the appropriate Service Manual.
3. Remove the 45 degree elbow fitting from location shown in Figures 1 through 4 and inspect for thread shortage.




Figure 1 - Article 97-20-21





Figure 2 - Article 97-20-21



**FD1460 ENGINE**

**369275-S101**

**TB-5241-A**

Figure 3 - Article 97-20-21




Figure 4 - Article 97-20-21

4. Replace the 45 Degree Elbow (F7HZ-18599-SA) fitting.
5. Refill cooling system. Verify the repair.

PART NUMBER	PART NAME
F7HZ-18599-SA	45 Degree Elbow

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
972021A	Replace Fittings	0.7 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
18599	17

OASIS CODES: 208000, 208100, 208999, 402000



## Bulletin Contents

TSB Article 97-20-22 has been superseded by Article 99-14-13.

---

## Bulletin Contents

TSB Article 97-21-3 has been superseded by Article 99-12-10.

---

## Bulletin Contents

TSB Article 97-21-4 has been superseded by Article 98-9-3.

---



97-21, *Publication Date: OCTOBER 13, 1997*

<b>Cooling System - Fan Clutch Attaching Bolts Loosen - Vehicles Built Through 7/14/97 Equipped With CAT 3126 Engine And Kysor On/Off Fan Clutch</b>	<b>Article No. 97-21-17</b>
----------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1997-98 AEROMAX, LOUISVILLE

**ISSUE:**

The fan clutch attaching bolts may become loose on some vehicles equipped with the Kysor on/off fan clutch. This may be due to the original fan mounting hub not being robust enough.


**ACTION:**

Modify the existing mounting of the fan clutch hub and add two (2) additional attaching bolts. The additional bolts should help prohibit the possibility of the fan hub from becoming loose. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

Refer to Figure 1.

**KYSOR FAN CLUTCH WITH 26" FAN**



Item	Description
1	Nut
2	Fan
3	Kysor Fan Clutch Assembly
4	Fan Clutch Air Line Fitting
5	Fan Clutch Air Line
6	Washer (8mmx17x2.25 Flat Stl)
7	Bolt (M8x1.25x35 Hex Hd)


---

**Figure 1 - Article 97-21-17**

1. Remove the RH side charge air cooler pipe to gain access to the fan and fan clutch.
2. Remove the cooling fan.
3. Remove the serpentine belt.
4. Disconnect the air line from the fan hub/clutch assembly.
5. Remove the four (4) bolts that attach the fan hub/clutch assembly to the engine and discard.
6. Remove the fan hub/clutch assembly from the engine and place it on a work bench so that the mounting flange is accessible.

Refer to Figure 2.

REAR VIEW OF KYSOR ON/OFF FAN CLUTCH



**Figure 2 - Article 97-21-17**

7. Carefully mark the new attaching bolt locations on the mounting flange using the information provided in Figure 2.
8. Drill two (2) 9.7mm (0.38") holes at the locations marked.
9. Reinstall the fan hub/clutch assembly onto the engine using six (6) new Bolts (N601212-S2) and six (6) new Washers (N630068-S2). Be sure to coat the bolts with Ford Threadlock 262 (E2FZ-19554-B) prior to installation.
10. Torque the six (6) bolts to 22-33 N-m (16-24 lb-ft).
11. Install the fan hub/clutch air line.
12. Install the serpentine drive belt.
13. Install the fan assembly and torque the bolts to 42-57 N-m (31-42 lb-ft).
14. Install the air charge cooler tube and torque the clamps to 2-3 N-m (18-27 lb-in).

PART NUMBER	PART NAME
N601212-S2	Bolt
N630068-S2	Washer
E2FZ-19554-B	Threadlock 262

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
972117A	Modify Fan Clutch Mounting Bracket	1.3 Hrs.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
8A627	57

**OASIS CODES:** 402000, 497000

---





97-22, *Publication Date: OCTOBER 27, 1997*

<ul style="list-style-type: none"><li>• <b>Cooling Fan - Electrical Wiring Schematics - Diagnosis Information - Horton And/Or Kysor On/Off Fan Clutch - Vehicles Equipped With Electronic Premium Diesel Engine - Vehicles Built After 10/7/96</b></li><li>• <b>Cooling Fan - Diagnosis Information - Horton And/Or Kysor On/Off Fan Clutch - Vehicles Equipped With Premium Electronic Diesel Engine - Vehicles Built After 10/7/96</b></li></ul>	<b>Article No. 97-22-18</b>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

#### **MEDIUM/HEAVY TRUCK:**

1997-98 AEROMAX, LOUISVILLE

#### **ISSUE:**

This TSB article will provide diagnostic information and wiring schematics for both the Horton and Kysor engine cooling fan clutches.

#### **ACTION:**

If the engine cooling fan is not functioning properly, refer to the following text and illustrations to aid in identifying the root cause of the concern.

#### **DIAGNOSTIC INFORMATION**

##### **NOTE:**

THIS TSB PROVIDES SPECIFIC ENGINE COOLING FAN SERVICE INFORMATION FOR VEHICLES EQUIPPED WITH A PREMIUM ELECTRONIC DIESEL ENGINE BUILT AFTER 10/7/96 ONLY. ADDITIONAL SERVICE INFORMATION ON FAN CLUTCH OPERATION CAN BE FOUND IN OTHER TECHNICAL SERVICE BULLETINS, IN SERVICE MANUALS, AND THE ELECTRICAL AND VACUUM TROUBLESHOOTING MANUAL (EVTM).

#### **ON/OFF FAN CLUTCH TERMINOLOGY**

- Electronic Control Unit (ECU) - an electronic module used to control the operation of the engine
- Fan Override Switch - a toggle switch mounted on the instrument panel which activates the fan if the parking brakes are set
- F/P - fuse panel
- A/C - air conditioning
- Jumper - using a separate wire to link two (2) electrical connectors
- KOER - key on engine running
- Powered Circuit - circuit on which more than 6 volts are present
- R-21 - the fan control relay located on the instrument panel fuse panel
- R-15 - the air conditioning high pressure relay located on the instrument panel fuse panel
- Voltage Drop Test - using a voltmeter to measure voltage differential by connecting the negative voltmeter probe on the negative battery post and the positive probe on the tested components ground

pin. A measurement of more than 0.2 volts on the tested components indicates a poor ground circuit

## **ON/OFF FAN CLUTCH OPERATIONAL THEORY**

- These vehicles use the electronic engine ECU to control the engine cooling fan operation. This TSB does not apply to CAT 3126 electronic engines
- On CAT and Cummins engines, the ECU will turn the engine cooling fan off by applying 12 volts to Circuit 721 which is wired to either Pin 1 or 2 of the fan control relay (R-21). The opposite pin in the relay, either 1 or 2 will contain a ground on Circuit 57
- On Detroit Diesel engines, the ECU will turn the engine cooling fan off by applying a ground to Circuit 721 which is wired to either Pin 1 or 2 of the fan control relay (R-21). The opposite pin in the relay, either Pin 1 or 2 will contain a 12 volt power source from Fuse 12 on Circuit 517
- On all engines, with no signal from the ECU, the fan control relay (R-21) should default to the fan on position (i.e., the engine cooling fan should run all the time)
- Circuit 721 can be found on the ECU connectors at the following locations:
  - CAT engines - Pin 28 of Connector C110
  - Cummins engines - Pin C of Connector C171
  - Detroit Diesel engines - Pin Y3 of Connector C135

### **NOTE:**

ON DDC ENGINES, THE C135 CONNECTOR IS IN THE ENGINE HARNESS ABOUT 61cm (24") FORWARD OF THE ENGINE ECU.

- Before the ECU will turn the engine cooling fan off, it is programmed to check for a signal loop on the A/C high pressure switch input to the ECU. This signal is a loop between two (2) pins at the ECU that, if broken or open, will cause the engine cooling fan to run continuously. This signal loop runs from:
  - CAT engines - Pin 29 of Connector C110 to Pin 38 of Connector C110
  - Cummins engines - Pin 10 of Connector C170 to Pin T of Connector C171
  - Detroit Diesel engines - ground of Pin H1 of Connector C135
- Relay R-15 is wired into this signal loop. R-15 will be normally closed allowing the signal loop to return to the ECU. The ECU will then control the engine cooling fan based on engine requirements
- If the A/C high pressure relay (R-15) is opened or removed from the panel, the ECU will assume high pressure and will turn the engine cooling fan on
- The A/C high pressure relay (R-15) is controlled by two systems:
  - The A/C high pressure switch (if equipped)
  - The fan clutch override switch (if equipped)
- The coil in the A/C high pressure relay (R-15) is powered by Circuit 517 at Relay Pin 1 or 2. The opposite pin contains ground Circuit 90 which splits and runs to both the A/C high pressure switch and fan clutch override switch. Each of these switches supply ground necessary to power the A/C


high pressure relay (R-15) causing the relay to open and the engine fan to come on

- If the A/C high pressure switch senses excessive pressure in the A/C system, the following will occur:
  - The A/C high pressure switch closes grounding Circuit 90
  - Relay R-15 will open causing an open in the signal loop to the ECU
  - The ECU will turn the engine cooling fan on until relay R-15 closes and the signal loop is restored or 3 minutes have elapsed whichever occurs last
- If the driver switches the fan override switch to the on position the following will occur:
  - The fan override switch grounds Circuit 90. The parking brake must be applied for the override switch to function
  - Relay R-15 will open causing a loss of the signal loop to the ECU
  - The ECU turns the engine cooling fan on
- During the vehicle build process, the engine ECU is programmed to accept/identify the options of the vehicle such as A/C or the fan override switch. If the ECU programming has been changed or is incorrect, the operation of these systems and/or the engine cooling fan clutch can be affected

## **DIAGNOSIS**

All diagnosis begins with Figure 1 and ends with Figure 12. Start with Figure 1 and follow the diagnostic path for the specific fan clutch concern. It is very important that each Step or Test in the diagnostics be followed and/or performed in order to be sure that the root cause of the concern is identified.


**FAN CLUTCH OPERATION DIAGNOSTICS**



TB-8278-A

Figure 1 - Article 97-22-18


**CHART A - FAN WILL NOT ENGAGE - HORTON FAN CLUTCH**



TB-5276-A

Figure 2 - Article 97-22-18

**CHART B - FAN WILL NOT ENGAGE - BENDIX AND KYSOR FAN CLUTCHES**



TB-6277-A

Figure 3 - Article 97-22-18

**CHART C - FAN WILL NOT ENGAGE - ALL FAN CLUTCHES**

**NOTE: ECM = ELECTRONIC CONTROL MODULE.**





Figure 4 - Article 97-22-18

**CHART D – FAN STAYS ENGAGED – HORTON FAN CLUTCH**




TS-6279-A

Figure 5 - Article 97-22-18




**CHART E - FAN STAYS ENGAGED - BENDIX AND KYSOR FAN CLUTCHES**



TB-5280-A

Figure 6 - Article 97-22-18


**CHART F - FAN STAYS ON - ALL FAN CLUTCHES**



TB-5221-A

Figure 7 - Article 97-22-18

**CHART G – ELECTRONIC CONTROL MODULE (ECM) CHECK**



TB-5282-A

Figure 8 - Article 97-22-18



**CHART I - A/C HIGH PRESSURE RELAY WIRING**





Figure 10 - Article 97-22-18

**CHART J - FAN WILL NOT ENGAGE WITH OVERRIDE SWITCH ON**



TB-5285-A

Figure 11 - Article 97-22-18




Figure 12 - Article 97-22-18

## WIRING SCHEMATICS

- CAT and Cummins electronic engines with Kysor fan clutch - Figure 13




Figure 13 - Article 97-22-18

- CAT and Cummins electronic engines with Horton fan clutch - Figure 14







Figure 14 - Article 97-22-18

- Detroit Diesel electronic engines with Kysor fan clutch - Figure 15



- Detroit Diesel electronic engines with Horton fan clutch - Figure 16




Figure 16 - Article 97-22-18

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: INFORMATION ONLY

OASIS CODES: 208000, 402000, 499000



97-23, *Publication Date: NOVEMBER 10, 1997*

<b>Hood - Inner Hood Reinforcement Bond Separation - 101, 113, And 122 Inch Bumper-To-Back-Of-Cab Vehicles - Vehicles Built From 10/7/96 Through 3/13/97</b>	<b>Article No. 97-23-16</b>
--------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1997 AEROMAX, LOUISVILLE

**ISSUE:**

The hood may separate at the inner hood reinforcement bond on some vehicles. This may be caused by the bonding design between the hood center rear reinforcement and the hood side reinforcement.


**ACTION:**

Repair the hood by securing the hood center rear reinforcement to the hood side reinforcements. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**


1. Open and inspect the inside of the hood at the hood center rear reinforcement to the hood side reinforcement bond locations (Figures 2 and 3 for 113" and 122" Bumper-to-Back-of-Cab (BBC) vehicles, and Figures 4 and 5 for 101" BBC vehicles). Inspect both right and left side bonds.

SEAM (LOCATION OF POSSIBLE HOOD REINFORCEMENT SEPARATION)




VIEW OF LEFT INSIDE OF HOOD  
VIEW A

CROSS-SECTION VIEW OF HOOD  
CENTER REAR REINFORCEMENT  
AND HOOD OUTER SHELL



**Figure 2 - Article 97-23-16**


SEAM (LOCATION OF POSSIBLE HOOD REINFORCEMENT SEPARATION)



NEW RIVET LOCATIONS

VIEW OF RIGHT INSIDE OF HOOD  
VIEW B

CROSS-SECTION VIEW OF HOOD  
CENTER REAR REINFORCEMENT  
AND HOOD OUTER SHELL




NEW RIVET  
LOCATIONS

FRONT OF  
VEHICLE

TOP








**VIEW OF LEFT INSIDE OF HOOD  
101 BBC ONLY  
VIEW A**

**CROSS-SECTION VIEW OF HOOD  
CENTER REAR REINFORCEMENT  
AND HOOD OUTER SHELL**



**Figure 4 - Article 97-23-16**




Figure 5 - Article 97-23-16

- If evidence of a separation concern between the hood center rear reinforcement and the hood side reinforcements is present, proceed to Step 2. If no evidence is present, the following repair is not needed.

**NOTE:**

SIX (6) NEW RIVETS WILL BE USED TO SECURE THE HOOD CENTER REAR REINFORCEMENT TO THE HOOD SIDE REINFORCEMENTS. THE INSTALLATION OF THE NEW RIVETS CAN BE DONE WITHOUT REMOVING THE HOOD FROM THE VEHICLE.

2. Using the information provided in Figures 1-5, determine and mark the location for all six (6) new rivet holes on the hood center rear reinforcement. Six (6) rivets will be used, three (3) on the left and three (3) on the right side.




Figure 1 - Article 97-23-16

**CAUTION:**

**ONLY DRILL THROUGH THE HOOD CENTER REAR AND HOOD SIDE REINFORCEMENTS. BE CAREFUL NOT TO DRILL INTO OR THROUGH THE OUTER SHELL OF THE HOOD.**

3. Make sure the hood center rear reinforcement is fully seated against the hood side reinforcements and drill six (6) new 6.75mm (17/64") holes through the reinforcements at the locations marked (Figures 2 through 5).
4. Make sure the hood center rear reinforcement is still fully seated against the hood side reinforcements, then using a suitable rivet tool, install one (1) W525174-S rivet into each side hole. Complete this procedure for all six (6) new rivet holes.

PART NUMBER	PART NAME
W525174-S	Rivet

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
972316A	Repair Hood Bond	0.5 Hr.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
16000	01

**OASIS CODES:** 108000, 111000

---



<ul style="list-style-type: none"> <li>• Cooling Fan - Electrical Wiring Schematics - Horton, Kysor And/Or Bendix On/Off Fan Clutch - Vehicles Equipped With Premium Diesel Engines Only Built Before 10/7/96</li> <li>• Cooling Fan - Diagnosis Information - Horton, Kysor And/Or Bendix On/Off Fan Clutch - Vehicles Equipped With Premium Diesel Engines Only Built Before 10/7/96</li> </ul>	<p>Article No. 97-24-30</p>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------


**MEDIUM/HEAVY TRUCK:**  
1996-98 AEROMAX, LOUISVILLE


**ISSUE:**

This TSB article will provide diagnostic information and wiring schematics for the Horton, Kysor, and Bendix engine cooling fan clutches.

**ACTION:**

If the engine cooling fan is not functioning properly, refer to the following text and illustrations (Figures 1-4) to aid in identifying the root cause of the concern.





TB-8511-A

Figure 2 - Article 97-24-30








Figure 4 - Article 97-24-30

**DIAGNOSTIC INFORMATION**

**NOTE:**

THIS TSB PROVIDES SPECIFIC ENGINE COOLING FAN SERVICE INFORMATION FOR VEHICLES EQUIPPED A WITH PREMIUM DIESEL ENGINE BUILT BEFORE 10/7/96. THIS TSB DOES NOT APPLY TO CAT 3126 ELECTRONIC ENGINES. ADDITIONAL SERVICE INFORMATION ON FAN CLUTCH OPERATION CAN BE FOUND IN OTHER TECHNICAL SERVICE BULLETINS, IN SERVICE MANUALS, AND THE ELECTRICAL AND VACUUM TROUBLESHOOTING MANUAL (EVTM).

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 208000, 402000, 499000



97-24, *Publication Date: NOVEMBER 24, 1997*

<b>Exhaust System - Flex Pipe Which Attaches To The Turbocharger Outlet Pipe May Crack - Vehicles Equipped With Detroit Diesel Engine Built Through 12/97</b>	<b>Article No. 97-24-31</b>
---------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------

**MEDIUM/HEAVY TRUCK:**

1996-98 AEROMAX, LOUISVILLE

**ISSUE:**

The exhaust flex pipe that comes from the turbocharger outlet may crack on some vehicles equipped with a Detroit Diesel engine. This may be caused by the existing pipe being too rigid to compensate for normal vibrations and movements of the exhaust system.


**ACTION:**

Modify the exhaust system and install a longer flex pipe. The longer flex pipe should reduce the possibility of cracking. Refer to the following Service Procedure for details.

**SERVICE PROCEDURE**

1. Remove and discard the existing exhaust system flex pipe and clamps.
2. Cut a total of 76mm (3") from the existing turbocharger outlet pipe and/or muffler inlet pipe extension at the flex pipe connection. Refer to Figure 1.

**LOUISVILLE/AEROMAX WITH DDC ENGINE AND HORIZONTAL MUFFLER SHOWN ORIGINAL INSTALLATION**



**A TOTAL OF 76mm (3") OF PIPE MUST BE REMOVED FROM THE TURBOCHARGER OUTLET PIPE AND/OR MUFFLER INLET PIPE EXTENSION TO ACCOMODATE THE NEW LONGER FLEX PIPE**

**Figure 1 - Article 97-24-31**

**NOTE:**

THE MOUNTING AND ALIGNMENT OF THE EXHAUST SYSTEM IS CRITICAL TO THE DURABILITY OF THE FLEX PIPE. THE ENTIRE EXHAUST SYSTEM SHOULD BE CHECKED AND REPAIRED IF NECESSARY PRIOR TO INSTALLING THE NEW FLEX PIPE.

- 3. Install the new Flex Pipe (DOHZ-5B286-B) and new wide band Clamps (F2HZ-5A231-C).
- 4. Torque the clamps to 61-81 N-m (45-60 lb-ft).

PART NUMBER	PART NAME
DOHZ-5B286-B	Flex Pipe
F2HZ-5A231-C	Clamps (2 Req'd.)

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

**LABOR ALLOWANCE**

OPERATION	DESCRIPTION	TIME
972431A	Repair Exhaust - Horizontal Muffler	1.4 Hrs.
972431B	Repair Exhaust - Vertical Muffler	1.3 Hrs.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
5B286	01

**OASIS CODES:** 403000, 497000

---