

1(4) SB1204

October 26, 2012

TOPIC: OVER TENSIONING OF INLET MANIFOLD FASTENERS

LEADING TO GASKET FAILURE

APPLICABLE TO: ALL SANDVIK CAT C7 ACERT EXPLOSION PROTECTED

**DIESEL ENGINE SYSTEMS** 

SANDVIK LS171, LS191 LOADERS

The Owner of machinery has a liability to inform and when necessary to train according to the content of this Bulletin all the personnel (like operators, maintenance personnel) whom this Bulletin concerns.

Supplementary safety information including new hazard(s) identified how to avoid the hazard(s) and the potential consequences of not avoiding the hazard:

| <u></u> |  |  |  |
|---------|--|--|--|
|         | Over tensioning of the Inlet Manifold fasteners can lead to crush of the gasket at the corner and may jeopardise the flameproof integrity of the inlet system. |  |  |



2(4) SB1204

October 26, 2012

#### **Background information:**

The Engineering Department responsible for Load & Haul Products continues to undertake work to improve documentation used for component assessments, Code D Overhauls Explosion Protected Diesel Engine Systems. During the course of this exercise, the inlet manifold of the CAT C7 Engine was machined to minimum tolerances and pressure tested with test backing plates fitted and gaskets and fasteners as nominated on the Diesel Engine System Drawing Registered with NSW Department of Trade and Investment.

A problem was discovered when tensioning the corner fasteners to the maximum tolerance. Due to the lack of stiffness in the Inlet Manifold, the gasket is crushed locally at the corners. The same lack of stiffness prevents proper sealing of the fixed joint at the end of the manifold. This would not normally be noticed when neoprene rubber is used for Pressure Testing, due to the added flexibility and sealing properties of the neoprene test gasket.

Further testing resolved the issue by using an additional support plate to spread the load of the fasteners.

All C7 engines already have a Fuel Filter Bracket on one end which adequately performs this function. The testing also showed that as little as 1.5mm of gasket width adjacent to the bolt hole is sufficient to contain the full pressure of 1000kPa of the pressure test.

Figure 1 shows an extreme example of crushing as witnessed during the testing after a number of tests.

Figure 2 shows a damaged gasket. Note the outer edges are damaged and the inner edges are intact.





Figure 1

Figure 2

#### Notes:

- 1. Pressure determination testing to AS3584.2:2008 on the intake system found the maximum pressure to be 68.1kPa. Hydrostatic pressure testing of the Inlet System is therefore determined to be the greater of 1.5x68.1kPa (102.2kPa) or 350kPa. The test pressure nominated as 1000kPa for the Inlet System was due to market area requirements for South Africa.
- 2. Turbo boost pressure at torque stall is approx 150kPa. ie Approx 2.2 times Pressure Determination test value.

There have been no cases of Inlet Manifold cracking or Gasket Failure reported to Sandvik from the field.

#### © 2012 SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD

431 Masonite Road Heatherbrae NSW 2324, AUSTRALIA www.sandvik.com

ABN: 62 003 771 382

Issued Bulletins are available on the Sandvik website at: www.miningandconstruction.sandvik.com/au



SB1204

October 26, 2012

## Actions to be taken immediately:



Review all Attached documents and follow the recommendations.

#### **RECOMMENDATIONS**

- Inspect the Inlet Manifold and gasket edges at the corners (Radiator end).
- The inspection must include;
  - A visual inspection for extrusion of the gasket from between the faces of the Inlet Manifold (BD00009952) and Cylinder Head.
  - A visual inspection for cracking of the Inlet Manifold at the corners nearest the radiator. (NB. Possible where severe extrusion of the Gasket has occurred).
  - A soapy water test around the radiator end of Inlet Manifold conducted at torque stall. (Note: The vehicle must be in a non-explosive gas environment at the time of this test.)
- Based on this inspection, the following options may be implemented;
  - If the manifold is not cracked and the gasket appears not to have been extruded from the joint;
    - Fit the additional support bracket (1 x BU00000853) and Fasteners (4 x BU00000993) (see attachments) and replace the Fasteners (4 x BU00000993) at the Fuel Filter Bracket end without the removal of the inlet manifold. A full description to remove and install the Inlet Manifold is provided in the attachments. A portion of this procedure may be used for the fitting of the support bracket and fasteners.
    - Once complete, perform soapy water test (refer Inspection Step 3) around the Inlet Manifold to Cylinder Head (Fixed Joint 3) with the engine at Torque Stall to detect leaks. If leaks occur, proceed to option 2.

OR

- 2. If the manifold is cracked and/or the gasket appears to have extruded from the
  - Following the Service Manual information provided, remove the Inlet Manifold and Inlet System components.
  - Perform a dimensional check and pressure test (Code D) inspection of the Inlet Manifold using critical details noted on pages 1 & 4 of drawings A2U900-830879, Rev B [1] or BD00020101, Rev B [2]. **Note:** At Dimension 3.3, the minimum allowable dimension is 1.5mm.
  - Reinstall the Inlet system including the additional support bracket, fasteners and new gaskets shown in "Inlet Manifold Kit – BU00001018".
  - All work should be supervised by a responsible person and in accordance with Code D requirements.
  - Once complete, perform soapy water test (refer Inspection Step 3)

© 2012 SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD

431 Masonite Road Heatherbrae NSW 2324, AUSTRALIA www.sandvik.com

ABN: 62 003 771 382

Issued Bulletins are available on the Sandvik website at: www.miningandconstruction.sandvik.com/au



4(4) SB1204

October 26, 2012

#### **IMPORTANT NOTES:**

Disregard the intake system fastener torque settings on the relevant Registration drawings [1], [2]. Instead use the fastener torques nominated in the "Service Manual – Inlet Manifold Installation Procedure for CAT C7 Engine" and "Flametrap Housing Group - A2U900-240102".

It is Sandvik's intention to apply for supplementary changes to DES Registrations to the respective statutory authorities.

Ensure a copy of this bulletin and attachments is stored with the Plant Safety Documentation for the machine.

#### Reference documents:

- [1] Registration Drawing, CAT C7 ACERT, A2U900-830879 Rev B (Australia)
- [2] Registration Drawing, CAT C7 ACERT, BD00020101 Rev B (South Africa)

#### List of attachments:

| Drawing No.   | Title   | Model         |  |
|---------------|---|---------------|--|
|               | Service Manual, CAT C7 Engine, Inlet Manifold | LS171 & LS191 |  |
|               | Installation Procedure for CAT C7.            |               |  |
| BU00001018    | Inlet Manifold Kit, Flametrap Housing Group   | LS171 & LS191 |  |
| Rev A         |   |               |  |
| A2U900—240102 | Flametrap Housing Group, Engine Cradle Group  | LS171 & LS191 |  |
| Rev E         |   |               |  |

Note: The latest revisions of the above drawings are issued at the time of writing.

#### Request for Feedback:

For mines, hirers or maintenance contractors that have implemented all of the above recommendations, Sandvik is interested to hear from you. Please contact your Sandvik representative to discuss any difficulties or to simply provide feedback on the condition of the Inlet Manifold and Gasket as you found it.

Approved by: Product Line Manager – Terry Marler

Appendixes: N/A

© 2012 SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD

431 Masonite Road Heatherbrae NSW 2324, AUSTRALIA www.sandvik.com ABN: 62 003 771 382

Issued Bulletins are available on the Sandvik website at: www.miningandconstruction.sandvik.com/au

# SERVICE MANUAL CAT C7 ENGINE

Inlet Manifold Installation Procedure for CAT C7 Engine

SANDVIK

## **Inlet Manifold Installation Procedure for Cat C7 Engine**

NOTICE

Read ENTIRE document before commencing job.

The inlet manifold is an integral part of the Explosion Protected C7 Diesel Engine System (DES). Ensuring the correct installation of the inlet manifold will ensure the flameproof integrity of the DES should an ignition of combustible gases occur in the inlet tract between the inlet valve and the Flametrap.

Ensure the LHD is parked with wheels chocked in a suitable service area. This should be in a surface workshop with adequate light, shelter and ventilation. Apply the appropriate site isolation tags and / or locks so the LHD cannot be operated.

### **WARNING**



PERSONAL INJURY HAZARD! Ensure all required personal protective equipment (PPE) including gloves and eyewear is worn.


BURNS HAZARD - HOT FLUIDS AND ENGINE COMPONENTS!

Wait until the engine has cooled before commencing disassembly.


The procedure for inlet manifold replacement is as follows:

# 1.1. Preparation

1. Raise the engine covers (1) on the side of the machine to access the engine.




- 2. Clean the area of coal, oil dust before removing any components.
- 3. Isolate the fuel supply (2).




# 1.2. Disassembly


1. Remove primary fuel filter assembly and fuel filter lines (shown in magenta).




2. Remove fuel line and the adaptor fitting from the HUEI pump to cylinder head (shown in magenta).




3. Remove the sensors located in the top of the inlet manifold (shown in magenta).




4. Remove the Can-Bus sensors located on the cover support rail, being careful as to not damage them (shown in magenta).




5. Remove the secondary fuel filter from the cover support rail and then remove the rail (shown in magenta).




6. Remove the flametrap housing from the strangler valve and the inlet manifold adaptor plate (shown in magenta). This can be done as a complete assembly or in two stages. Please note that new gaskets will be needed for assembling these items back together.



7. Remove the adaptor plate from the inlet manifold (shown in magenta).




8. Remove the inlet manifold from the cylinder head (shown in magenta).



## 1.3. Inspection and Cleaning

- 1. Remove all traces of the old gasket from the contact faces carefully so as not to mark or score the metal surfaces.
- 2. Perform Code D component compliance check on the inlet manifold (see separate dwg. BD00009952, sheet 2/2).
- 3. Once the inlet manifold has passed, proceed with the assembly of all components (Ref 1.4).



See bill of materials (BOM) on following page.


Bill of materials (BOM)

Extracted from drawing A2U900-240102


|     | 12/25 |                             |                                     |                      |     |           |
|-----|-------|-----------------------------|-------------------------------------|----------------------|-----|-----------|
| 4   | 32    | BU00000993/A (FASTENER KIT) |                                     | Grade 12.9 (UNBRAKO) | 8   | 0.2       |
| E   | 31    | BU00000853/A                | Bracket                             | AS3678-250           | 1   | 0.4       |
|     |       | BD00020705/A (FASTENER KIT) |                                     | CLASS 10 (ZN PLATE)  | 14  | 9=        |
|     | 29    | BD00020703/A (FASTENER KIT) | Washer, Flat, M8, (Class 10)        | CLASS 10 (ZN PLATE)  | 8   | <u>-</u>  |
|     | 28    |                             | Hex Nut, M10 x 1.50                 | CLASS 12             | 6   | 0.1       |
|     | 27    | BD00020233/A (FASTENER KIT) | SHCS, M10 x 1.5 x 35 LG.            | Grade 12.9 (UNBRAKO) | 8   | 0.3       |
|     | 26    | BD00020232/A (FASTENER KIT) | SHCS, M10 x 1.5 x 45 LG.            | Grade 12.9 (UNBRAKO) | 3   | 0.1       |
|     | 25    | BD00020231/A (FASTENER KIT) | SHCS, M10 x 1.5 x 40 LG.            | Grade 12.9 (UNBRAKO) | 3   | 0.1       |
| E   | 24    | BD00020223/A (FASTENER KIT) | SHCS, MB x 1.25 x 80 LG.            | Grade 12.9 (UNBRAKO) | 8   | 0.3       |
|     | 23    | BD00020155/A                | 1/8" ALLEN KEY BSPP PLUG            | STAINLESS            | 2   | 7 -       |
|     | 22    | BD00018800/B                | CUP SHROUD, M10 HEX                 | S.S. Gr 304          | 6   | 0.2       |
| E   | 21    | BD00009952/E                | INLET MANIFOLD                      |                      | 1   | -         |
| ^   | 20    | BD00001534/C                | FASTENER KIT-FLAMETRAP HSG<br>GROUP |                      | 1   | _         |
| E   | 19    | A2U900-291329/A             | Bracket-Fuel Filter                 | AS3678-250           | 1   | S-        |
|     | 18    | A2U900-291320/A             | Boss-Bracket Support                | AS3679-300           | 2   | 0.4       |
| É   | 17    | A2U900-291286/A             | Bracket-Top Support                 | Steel                | 1   | _         |
|     | 16    | A2U900-291285/A             | Bracket-Bottom Support              | Steel                | 1   | -         |
|     | 15    | A2U900-243026/C             | Gasket - Air Intake                 | See Dwg              | 1   | 0.1       |
|     | 14    | A2U900-243021/B             | Gasket-Adaptor Plate                | See Drawing          | 1   | 0.1       |
| E   | 13    | A2U900-243020/C             | Gasket-Flametrap Housing            | See Drawing          | 1   | 0.2       |
| É   | 12    | A2U900-243007/D             | Gasket, Flametrap                   | NOVATECH PREMIUM     | 1   | -         |
|     | 11    | A2U900-241080/D             | FLAME TRAP COVER                    |                      | 1   | _         |
|     | 10    | A2U900-241079/E             | Flame Trap Housing                  |                      | 1   | _         |
| E   | 9     | A2U900-241078/H             | Adaptor Plate-Inlet Manifold        | AS3678-250           | 1   | 2.8       |
|     | 8     | A2U900-241033/E             | FLAMETRAP ELEMENT                   | AS SUPPLIED          | 1   | 0.7       |
|     | 7     | 455309034/A (FASTENER KIT)  | Hex Nut, M10 X 1.5                  | GR 8                 | 2   | _         |
|     | 6     | 450081120/A (FASTENER KIT)  | Washer, Spring, 8 mm                | Steel                | 2   | -         |
|     | 5     | 450081022/A (FASTENER KIT)  | Washer, Spring, 10 mm               | Steel                | 2   | _         |
|     | 4     | 450062508/A (FASTENER KIT)  | Washer, Flat, 10 mm                 | Steel                | 4   | -         |
|     | 3     | 450062506/A (FASTENER KIT)  | Washer, Flat, 8 mm                  | Steel                | 2   | _         |
|     | 2     | 445502802/A (FASTENER KIT)  | Bolt Hex Head, M10 x 30mm Long      | GR 8.8               | 2   | 0.1       |
|     | 1     | 445402771/A (FASTENER KIT)  | Bolt Hex Head, M8 x 65mm Long       | GR 8.8               | 2   | 0.1       |
| - 1 | ITEM  | PART No.                    | DESCRIPTION                         | MATERIAL             | QTY | MASS (kg) |

## 1.4. Assembly

1. Please note the installation of the additional support bracket (31) on the HUEI pump end of the inlet manifold (see image). When installing, make sure the fuel filter bracket (19), inlet manifold adaptor plate (9) and the new longer 40mm SHCS for the ends are in place before commencing the bolt torque procedure.



- 2. Bolt torque procedure:
- A. Start the first sequence at 10Nm and work in the numbered pattern (1 to 16) as shown below.
- B. When you have achieved to above mentioned torque, re-tension them to 15nm using the same pattern as shown above. Then proceed to 20Nm using the same pattern, then to 25Nm. Once all bolts are at 25Nm then repeat the tensioning sequence at 25Nm again to be sure that all fasteners have achieved the full 25Nm of torque.
  - 3. Reinstall remaining components in reverse order to removal. Replace any damaged components. Ensure only new gaskets are used.



#### 1.5. Test and Commission

1. Once the engine is completely reassembled, remove all tools, consumables, rags etc from the engine bay. Perform a check of the area and inform all personnel involved in the repair operation to stand clear. Ensure the wheels are chocked, the brakes are applied and there is adequate ventilation. If safe to do so, remove isolation tags and locks, open the fuel isolation valve and start the engine. Allow the engine a few minutes to come up to temperature. Perform a "Torque Stall Test" whilst an assistant sprays a soapy water solution around the fixed joints that have been disturbed for this repair.

NOTICE

WARNING - Be careful not to overheat the torque converter or engine.

Observe closely for bubbles around the joints for signs of leakage. If leakage occurs, check the security of all fasteners to the correct torque. There must be no leaks for the machine to be returned to service. If no leaks occur, the machine may be returned to service. Ensure all repair and commissioning documents are stored in the filing system for the machine.

## 1.6. Disposal of Waste

1. Dispose of any waste materials - metals, recycle, gaskets, waste bins, oils, lubricant containers, waste containers etc in an approved manner.

