

APPENDIX J

Smog Check OBD II Reference (Testability Issues)

Appendix J provides information and test instructions about known OBD II functional test difficulties. Technicians must familiarize themselves with the information contained in this Appendix and follow the specified test instructions when conducting a Smog Check inspection on any vehicle listed.

Please watch for Appendix J updates on the Smog Check website or via ET Blasts. If other problems or solutions arise concerning the testing of OBD II vehicles, BAR will provide updated information advising technicians how to test the affected vehicles.

- **Table 1 - 1a** lists known OBD II testability issues.
- **Table 2** lists CAN equipped vehicles that currently cannot be OBD II tested. The EIS should automatically bypass the OBD II test for CAN equipped vehicles. However, if the EIS prompts for an OBD II test, bypass the test by answering “No” to the OBD II functional test prompt. Unless otherwise instructed by BAR, do not answer “No” to bypass the OBD II functional test for any other OBD II equipped vehicles.

In addition to the vehicles listed in Table 2, all vehicles one model-year old and newer are excepted from the OBD II functional test. With each new calendar year, the exceptions change accordingly. For example: In 2007, all 2006 model-year and newer vehicles are excepted from the OBD II functional test. In 2008, the 2006 model-year vehicles are subject to the OBD II test and the exceptions change to 2007 model-year and newer.

Note: Once the BAR-97 EIS incorporates CAN communication protocol, these vehicles will become testable.

To ensure that any special test processes are appropriately applied, always select vehicle information (make, model, engine size, etc.) from the BAR-97 inspection menus.

TABLE 1 – OBD II Testability Issues

Make	Model Year	Model	Problem	Action
Audi and Volkswagen	1996-2002	All models with non-OEM stereos	If the OEM stereo has been replaced with an aftermarket stereo, these vehicles may not communicate with the analyzer and/or OBD code scanner and may cause severe damage to the analyzer/scanner. For more information, see VW Technical service bulletin 02-03 dated June 10, 2002.	BAR recommends that you check with your analyzer/scan tool manufacturer to determine whether or not your analyzer/scan tool has complete current/voltage override protection. Override protection will protect the test equipment in cases where aftermarket installations cause over current conditions. BAR's June 22, 2002 ET Blast provides a method of checking for high voltage conditions using a test light. An alternative is to send all 96-newer VW/Audis with non-OEM radio installations to a VW/Audi dealership for verification of proper OBD function.
Chrysler	1996	Cirrus, Concorde, LHS, Sebring, Sebring Convertible	All monitors reset to "incomplete" upon <u>every</u> ignition key-off.	Determine if Recall Campaign #678 (9/96) has been performed; if not, refer to dealer. TSB 18-005-01 applies to non-California certified vehicles, and may be performed at no cost, even if warranty is expired.
Dodge	1996	Avenger, Intrepid, Stratus, Neon	All monitors reset to "incomplete" upon <u>every</u> ignition key-off	Determine if Recall Campaign #678 (9/96) has been performed; if not, refer to dealer. TSB 18-005-01 applies to non-California certified vehicles, and may be performed at no cost, even if warranty is expired.
Eagle	1996	Talon, Vision	All monitors reset to "incomplete" upon <u>every</u> ignition key-off.	Determine if Recall Campaign #678 (9/96) has been performed; if not, refer to dealer. TSB 18-005-01 applies to non-California certified vehicles, and may be performed at no cost, even if warranty is expired.
Hyundai	2002	Sonata	Readiness monitors are difficult to complete. Must successfully complete drive cycle TWO times.	Hyundai TSB #02-36-030 applies. Hyundai TSB information at: < http://hmaservice.com/webtech >
Hyundai	2003	Tiburon	Will not communicate with generic OBD II test equipment.	A manufacturer recall is in effect; recall campaign #057 and Hyundai TSB #03-01-003-01. Refer to dealership for recall.
Infiniti	1996	All Models	The catalyst and evaporative monitors are difficult to set to "complete."	Nissan provides recommended drive cycles (drive patterns). See Nissan Technical Service Bulletin #NTB98-018, February 18, 1998.
Mercedes-Benz	1996	C220, E320, C280, S320, SL320	The MIL illuminates whenever a scan tool is connected to the DLC. Trouble codes are not stored. However, if the OBD II connector is used as an RPM source during the Smog Check, the MIL will illuminate.	Do not connect the OBD II connector until the analyzer prompts for the OBD II functional test. Use the conventional contact or non-contact method to obtain an rpm signal.

Table 1 continued on next page...

TABLE 1 – OBD II Testability Issues

Make	Model Year	Model	Problem	Action
Mercedes- Benz	2001-2003	All models	No communication with some Snap-On EIS.	Snap-On produces a revised chip that enables communication. If your Snap-On EIS does not use the revised chip, do not inspect these vehicles; they will NOT communicate. Refer the motorist to another station for inspection.
Mitsubishi	1998-2001	Montero, Montero Sport, Diamante, 3000GT, Mirage, Galant, Expo/Expo LRV, and Eclipse models (except 2.0L non--turbo 420A engine models)	Some monitors are difficult to set to "complete."	Mitsubishi provides recommended drive cycles in its service. See service manual for 1998-2001 drive cycles.
Nissan	1996-1997	All Models	The catalyst and evaporative monitors are difficult to set to "complete."	Nissan provides recommended drive cycles (drive patterns) in its service information to assist technicians to operate monitors. See Nissan Technical Service Bulletin #NTB98-018c, January 3, 2002.
Plymouth	1996	Breeze Neon	All monitors reset to "incomplete" upon <u>every</u> ignition key-off.	A manufacturer recall is in effect. Verify recall has been performed. If not, refer to dealer for the recall.
Saab	1996-1998	900 (B234i with Motronic 4.1)	All monitors are difficult to set to "complete."	Saab Service Instruction No. 248 describes the correct drive cycle for completion of the monitors.
Saab	1996-1998	All Models	The catalyst and evaporative monitors are difficult to set to "complete."	The Smog Check OBD readiness criteria for this vehicle allow two monitors to be incomplete.
Toyota	1997	Tercel, Paseo	The evaporative monitor will never set to "complete."	The Smog Check OBD readiness criteria for these vehicles allow two monitors to be incomplete.
Volkswagen and Audi	1997-2002	All models with non-OEM stereos	If the OEM stereo has been replaced with an aftermarket stereo, these vehicles may not communicate with OBD code scanners and may cause severe damage to code scanning tools. For more information, see VW Technical service bulletin 02-03 dated June 10, 2002.	BAR recommends that you check with your analyzer/scan tool manufacturer to determine whether or not your analyzer/scan tool has complete current/voltage override protection. Override protection will protect the test equipment in cases where aftermarket installations cause over current conditions. BAR's June 22, 2002 ET Blast provides a method of checking for over current conditions using a test light. An alternative is to send all 96-newer VW/Audis with non-OEM radio installations to a VW/Audi dealership for verification of proper OBD function.

End Table 1.....1a next page

TABLE 1a
The EIS Ignores Monitor Readiness Status

Make	Model Year	Model	DISP	Action
BMW	1996	750iL, 850Ci, 850Csi 12-cylinder engines.		Complete Inspection as prompted by the EIS.
Dodge	1996	Stealth, Stealth RT	3.0	Complete Inspection as prompted by the EIS.
Mitsubishi	1996-97	3000 GT, 3000 GT Spider, 3000 GT VR-4, Diamante, Eclipse, Galant, Mighty Max, Mirage, Montero, Montero Sport	1.5, 1.8, 2.0, 2.4, 2.5, 3.0, 3.5	Complete Inspection as prompted by the EIS.
Subaru	1996	Impreza, Legacy, SVX	1.8, 2.2, 2.5, 3.3	Complete Inspection as prompted by the EIS.
Volvo	1996-97	960	2.5, 2.9	Complete Inspection as prompted by the EIS.
Volvo	1996-97	850, 850R, 850Turbo	2.3, 2.4	Complete Inspection as prompted by the EIS.
Volvo	1998	C70, S70, V70, S90, V90	2.3, 2.4, 2.9	Complete Inspection as prompted by the EIS.
				End Table 1a

TABLE 2 – Vehicles Currently Not OBD II Testable

The following vehicles use an OBD II protocol, known as Controller Area Network (CAN), that will not currently communicate with the EIS. Once the BAR-97 EIS incorporates CAN communication protocol, these vehicles will become testable and this table will be removed from Appendix J.

Model Year	Make	Model	Issue
2003			
2003	Ford	2.3L A/T Focus, 2.3L M/T Focus, 3.9L Thunderbird	Uses CAN, currently incompatible with EIS.
2003	Lincoln	3.0L A/T LS, 3.9L A/T LS	Uses CAN, currently incompatible with EIS.
2003	Mazda	2.3L Mazda6, 3.0L Mazda6	Uses CAN, currently incompatible with EIS.
2003	Porsche	Cayenne S, Cayenne Turbo	Uses CAN, currently incompatible with EIS.
2003	SAAB	9-3 Sedan (175hp), 9-3 Sedan (210hp)	Uses CAN, currently incompatible with EIS.
2003	Saturn	Ion	Uses CAN, currently incompatible with EIS.
2004			
2004	Buick	Rendezvous	Uses CAN, currently incompatible with EIS.
2004	Cadillac	CTS, SRX, XLR	Uses CAN, currently incompatible with EIS.
2004	Dodge	Durango	Uses CAN, currently incompatible with EIS.
2004	Ford	Explorer, F-150, 2.3L Focus, Taurus, Thunderbird	Uses CAN, currently incompatible with EIS.
2004	Lexus	LS430	Uses CAN, currently incompatible with EIS.
2004	Lincoln	LS	Uses CAN, currently incompatible with EIS.
2004	Mazda	Mazda3, Mazda6, RX8	Uses CAN, currently incompatible with EIS.
2004	Mercury	Sable	Uses CAN, currently incompatible with EIS.
2004	Porsche	Cayenne S, Cayenne Turbo	Uses CAN, currently incompatible with EIS.
2004	Saab	9-3	Uses CAN, currently incompatible with EIS.
2004	Saturn	Ion	Uses CAN, currently incompatible with EIS.
2004	Toyota	Prius	Uses CAN, currently incompatible with EIS.
2004	Volvo	2.4L S40, 2.5L S40	Uses CAN, currently incompatible with EIS.
2005			
2005	Audi	A4, A6	Uses CAN, currently incompatible with EIS.
2005	Aston Martin	DB9	Uses CAN, currently incompatible with EIS.
2005	Buick	LaCrosse, Rainier, Rendezvous	Uses CAN, currently incompatible with EIS.

Model Year	Make	Model	Issue
2005	Cadillac	CTS, SRX, STS, XLR	Uses CAN, currently incompatible with EIS.
2005	Chevrolet	Cobalt, Corvette, Equinox, Malibu, SSR, Trailblazer EXT	Uses CAN, currently incompatible with EIS.
2005	Chrysler	300C	Uses CAN, currently incompatible with EIS.
2005	Dodge	Dakota, Durango, Magnum	Uses CAN, currently incompatible with EIS.
2005	Ford	Crown Victoria, E-150, E-250, E-350, Escape, Excursion, Expedition, Explorer, F-150, F-250, F-350, Five Hundred, Focus, Freestyle, Mustang, Taurus, Thunderbird	Uses CAN, currently incompatible with EIS.
2005	GMC	Envoy ESV, Envoy XL	Uses CAN, currently incompatible with EIS.
2005	Isuzu	Ascender	Uses CAN, currently incompatible with EIS.
2005	Jeep	Grand Cherokee	Uses CAN, currently incompatible with EIS.
2005	Land Rover	LR3	Uses CAN, currently incompatible with EIS.
2005	Lexus	LS400, LS430, GX470	Uses CAN, currently incompatible with EIS.
2005	Lincoln	LS, Navigator, Town Car	Uses CAN, currently incompatible with EIS.
2005	Mazda	Mazda3, Mazda6, RX8, MPV, Tribute	Uses CAN, currently incompatible with EIS.
2005	Mercedes	SLK350	Uses CAN, currently incompatible with EIS.
2005	Mercury	Grand Marquis, Mariner, Montego, Sable	Uses CAN, currently incompatible with EIS.
2005	Pontiac	G6, Grand Prix, GTO	Uses CAN, currently incompatible with EIS.
2005	Porsche	Cayenne S, Cayenne Turbo	Uses CAN, currently incompatible with EIS.
2005	Saab	9-3, 9-7X	Uses CAN, currently incompatible with EIS.
2005	Saturn	Ion	Uses CAN, currently incompatible with EIS.
2005	Toyota	Avalon, Tacoma, 4Runner, Tundra, Sequoia	Uses CAN, currently incompatible with EIS.
2005	Volvo	S40, V50, S60, V70, S80, XC90	Uses CAN, currently incompatible with EIS.
2006			
2006	Aston Martin	V8 Vantage	Uses CAN, currently incompatible with EIS.
2006	Ford	Five Hundred, Crown Victoria, E250, E360, Escape, E Series Econoline, Expedition, Explorer, F150, F350, Focus, Freestar, Freestyle, Fusion, Mustang, Taurus	Uses CAN, currently incompatible with EIS.
2006	Lincoln	LS, Mark LT, Navigator, Town Car	Uses CAN, currently incompatible with EIS.
2006	Mercury	Grand Marquis, Mariner, Milan, Montego, Monterey Wagon, Mountaineer, Sable, Zephyr	Uses CAN, currently incompatible with EIS.
2006	Buick	LaCrosse, Lucerne, Rainier, Rendezvous, Terraza Mini Van	Uses CAN, currently incompatible with EIS.

Model Year	Make	Model	Issue
2006	Cadillac	CTS, DTS, SRX, STS, XLR	Uses CAN, currently incompatible with EIS.
2006	Chevrolet	Cobalt, Corvette, Equinox, Express, HHR, Impala, Malibu, Monte Carlo, SSR, TrailBlazer, Uplander Mini Van	Uses CAN, currently incompatible with EIS.
2006	GMC	Envoy, Savana Mini Van, Sierra	Uses CAN, currently incompatible with EIS.
2006	Pontiac	G6, Grand Prix, GTO, Montana Mini Van, Solstice, Torrent	Uses CAN, currently incompatible with EIS.
2006	Saab	9-3, 9-7X	Uses CAN, currently incompatible with EIS.
2006	Saturn	Ion, Relay Mini Van	Uses CAN, currently incompatible with EIS.
2006	Honda	Civic, Civic Hybrid, Civic Si, Civic GX (CNG)	Uses CAN, currently incompatible with EIS.
2006	Mazda	Mazda 3, Mazda 5 Mini Van, Mazda 6, Mazdaspeed 6, MPV Mini Van, MX-5, RX-8, Tribute	Uses CAN, currently incompatible with EIS.
2006	Mitsubishi	Eclipse, Galant, Raider	Uses CAN, currently incompatible with EIS.
2006	Lexus	GS430, GX470, IS250, IS350, LS430, LX470, SC430	Uses CAN, currently incompatible with EIS.
2006	Toyota	Land Cruiser, RAV4, Scion, Sequoia, Solara, Tacoma, Tundra, Yaris	Uses CAN, currently incompatible with EIS.
2006	Volvo	C70, S40, S60, S80, V50, V70, XC70, XC90	Uses CAN, currently incompatible with EIS.
2006	Volkswagen	Jetta, GTI, Passat Sedan	Uses CAN, currently incompatible with EIS.
2007			
2007	BMW	X5	Uses CAN, currently incompatible with EIS.
2007	Porsche	911 Turbo	Uses CAN, currently incompatible with EIS.
2007	Saab	B9 Tribeca	Uses CAN, currently incompatible with EIS.
2007	Lexus	ES350, LS460, RX350	Uses CAN, currently incompatible with EIS.
2007	Mini	Cooper	Uses CAN, currently incompatible with EIS.
2007	Toyota	Camry, FJ Cruiser, Solara, Yaris	Uses CAN, currently incompatible with EIS.
2007	Volvo	C70, S40, S60, S80, V50, V70, XC70, XC90	Uses CAN, currently incompatible with EIS.
2007	Volkswagen	Passat, Passat Wagon	Uses CAN, currently incompatible with EIS.
End table 2.			