

# HONDA Service Bulletin



March 23, 2004 Applies To: 2002-04 Odyssey - ALL

2003 Pilot - ALL

2004 Pilot - From VIN 2HKYF1...4H500001 thru 2HKYF1...4H541020

# Clunk From the Rear Brakes

### **SYMPTOM**

The rear brake calipers clunk when you first apply the brakes after changing the direction of the vehicle.

#### **PROBABLE CAUSE**

The outer shims on the rear brake pads do not allow the pads to slide easily when you press the brake pedal. This causes the outer pad to hit hard during a change of direction, resulting in a clunk.

## **CORRECTIVE ACTION**

Replace the rear brake pad shims.

NOTE: Brake pad replacement and disc resurfacing is not needed to get rid of the clunk.

#### PARTS INFORMATION

Rear Brake Pad Shim Set: P/N 06435-S3V-A01, H/C 7660848

# **REQUIRED MATERIALS**

M-77 Assembly Paste: P/N 08798-9010, H/C 4503793

# WARRANTY CLAIM INFORMATION

**In warranty:** The normal warranty applies.

Operation Number: 411150 Flat Rate Time: 0.7 hour

Failed Part: P/N 06435-S3V-A00

H/C 6406086

**Defect Code:** 03001 Symptom Code: 04213 04-019A Template ID:


Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Parts and Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

#### REPAIR PROCEDURE

1. Remove and discard the rear brake pad shims (three per caliper). For Pilots, refer to the 2003-04 Pilot Service Manual, page 19-18. For Odysseys, refer to the 1999-04 Odyssey Service Manual, page 19-25.

NOTE: Brake pad replacement and disc resurfacing is not needed to get rid of the clunk.

- 2. Apply a thin coat of M-77 assembly paste to the new brake pad shims in these areas:
  - The back of inner shim A and outer shim D.
  - Both sides of inner shim B and outer shim C.



3. Install the new brake pad shims (four per side) on each rear caliper. For Pilots, refer to the 2003-04 Pilot Service Manual, page 19-19. For Odysseys, refer to the 1999-04 Odyssey Service Manual, page 19-26.

© 2004 American Honda Motor Co., Inc. - All Rights Reserved

ATB 26825 (0403)

1 of 1

