



This technical manual was OCR'ed for the Sinclair world by Andy Dansby. andydansby@yahoo.com

All intellicial information contained inside this technical manual is the property of Amstrad.

Thank you Clive for the ZX Spectrum.

## SERVICINGMANUAL

FOR

## ZX SPECTRUM®

LIST OF CONTENTS

	INTRODUCTION
SECTION 1	SYSTEM DESCRIPTION
SECTION 2	DISASSEMBLY/ASSEMBLY
SECTION 3	SETTING UP AND SYSTEM TEST
SECTION 4	FAULT DIAGNOSIS AND REPAIR
SECTION 5	PARTS LISTS

# i\_\_\_\_\_LIST\_OF\_ILLUSTRATIONS\_\_\_\_\_

\_\_\_\_\_i Fig No.

ZX Spectrum Block Diagram	1.1
Expansion RAM RAS/CAS Timing (Read Cycle shown)	1.2
Keyboard Matrix Interconnections	1.3
ZX Spectrum (Issue 2) Circuit Diagram	1.4
ZX Spectrum (Issue 3) Circuit Diagram	1.5
Keyboard Format	4.1
Speaker Load Input Waveforms	4.2
Expansion Memory 1C Locations	4.3
Issue 3 Links vs 1C Manufacturer and Type	4.4
Printed Circuit Board (Issue 2) Component Layout	5.1
Printed Circuit Board (Issue 3) Component Layout	5.2
Printed Circuit Board (Issue 3B) Component Layout	5.3
Prepared by THORN (EMI) DATATECH LTD for SINCLAIR RESEARCH LTD	MARCH 1984

© Sinclair Research Ltd.

•

## - INTRODUCTION

This manual is for use by authorised SINCLAIR dealers, engineers and representatives as a guide to rectifying faults on the SINCLAIR ZX SPECTRUM personal computer.

The manual refers principally to the Issue 2 and Issue 3 Spectrums but provides a background to the Issue 1 version in the section dealing with modification history.

Basic knowledge of ZX SPECTRUM operating procedures is assumed as is knowledge of current workshop practice relating to microcomputers.

NOTE: Essential modifications are required on some Issue 2 Spectrums. Refer to Modification History (Section 4) and implement as necessary. - SAFETY MEASURES.

This instruction manual contains certain

- WARNING - and CAUTION -

notices which MUST be- followed by the user to ensure SAFE operation and to retain the equipment in a SAFE condition.

Any adjustment, maintenance and repair of the opened apparatus under voltage shall be carried cut only by a skilled person who is AWARE OF THE HAZARD INVOLVED.

#### SECTION 1

#### SYSTEM DESCRIPTION

Sub-Section	LIST OF CONTENTS	Page No.
1	Introduction	1.1
2 3	Architecture Z80A CPU	1.1 1.2
4	Memory Organisation Read/Write Operations	1.4 1.4
5	Input/Output TV Picture Generation	1.6 1.6
	Keyboard Scanning	1.8
6	Tape Interface Power Supplies Circuit Diagrams	1.10 1.11
	ZX Spectrum, Issue 2 ZX Spectrum, Issue 3	Fig. 1.4 Fig. 1.5


#### 1. INTRODUCTION

1.1 A block diagram of the complete ZX SPECTRUM micro-computer is given in Figure 1.1. It is valid for all build standards, fitted with either 16k or 48k bytes of dynamic RAM memory. Although functionally identical, detailed circuit changes have been introduced to improve reliability and to assist with manufacture. The printed circuit board layout has also been modified. Details of these changes are highlighted where necessary in the following paragraphs, and in later sections referring to fault diagnosis and repair.

#### 2. ARCHITECTURE


- 2.1 The architecture of the Spectrum shown in Figure 1.1 is typical of many microcomputer systems in that it comprises a single microprocessor board (in this instance a Z80A or u 780 CPU), a read only memory (ROM), an expandable RAM memory and an input/output section handling the keyboard, tape and TV display functions. The latter is recognisable as the logic gate array (ULA) and the three functional blocks shown in the right of the diagram.
- 2.2 The computer is built on a single printed circuit board which also includes a regulated power supply fed from an external 9V power pack. The keyboard matrix is part of the upper case assembly and is connected to the board via two ribbon cables KB1 and KB2. A description of each section follows.


- 3. Z80A CPU
- 3.1 The Z80A is an 8-bit single-IC central processing unit (CPU). It is clocked at 14.0 MHz from an external source controlled by the logic gate array (ULA) and has a standard three bus input/output arrangement. These buses are the Data Bus, Address Bus and Control Bus respectively.
- 3.2 Data Bus. D7-D10 constitutes an 8-bit bi-directional data bus with active high, tri-state input/outputs. It is used for data exchanges with the memory and with the ULA.
- 3.3 Address Bus. A15-A0 constitutes a 16-bit address bus with active high, tri-state outputs. The address bus provides the address for memory (up to 64k bytes) data exchanges and for data exchanges with the ULA. It is also used during the interrupt routine (see below) when scanning the keyboard matrix.
- 3.4 Control Bus. The control bus is a collection of individual signals which generally organise the flow of data on the address and data buses. The block diagram only shows five of these signals although others of minor importance are made available at the expansion port (see Figures 1.4 and 1.5 for details).
- 3.5 Starting with memory reguest fMREQ), this signal is active low indicating when the address bus holds a valid address for a memory read or memory write operation. Input/Output reguest (IORQ) is also active low but indicates when the lower half of the address bus holds a valid I/O address for the ULA during I/O read/write operations.
- 3.6 The read and write signals (RD and WR) are active low, and one or other is active indicating that the CPU wants to read or write data to a memory location or I/O device. All the control signals discussed so far are active low, tri-state outputs.
- 3.7 The control signal described here is the interrupt 3.7 Iast maskable (INT). This input is active low and is generated by the ULA once every 20 ms. Each time it is received the CPU 'calls' the 'maskable interrupt' routine during which the real-time is incremented and the keyboard is scanned.
- 3.8 CPU Clock. Returning to the CPU clock mentioned earlier in this section, the ULA is able to inhibit this input bringing the CPU to a temporary halt. This mechanism gives the ULA absolute priority, allowing it to access the standard 16k RAM without interference from the CPU (see RAM description). Switching transistor TR3 ensures that the clock amplitude is +5V rather than some arbitrary TTL level. This is essential if the CPU is to operate effectively while executing fast machine code programs of the 'space invader' ^'




ZX SPECTRUM BLOCK DIAGRAM FIG 1.1


- 3.9 Dynamic Memory Refresh. The CPU incorporates built-in dynamic RAM refresh circuitry. As part of the instruction OP code fetch cycle, the CPU performs a memory request after first placing the refresh address on the lower eight bits of the address bus. At the end of the cycle the address is incremented so that over 255 fetch cycles, each row of the dynamic RAM is refreshed. This mechanism only applies to the optional 32k expansion RAM in the 48k Spectrum. An alternative refresh method is adapted for the standard 16K RAM.
- 4. MEMORY ORGANISATION
- 4.1 In the standard 16k Spectrum there are 32k bytes of addressable memory equally divided between ROM and RAM.
- 4.2 The lower 16k bytes of memory (addresses 0000 3FFF) are implemented in a single ROM (IC5) which holds the monitor program. This program is a complex Z80 machine code program divided broadly into three parts one each covering the input/output routines, the BASIC interpreter and expression handling. Details of the program content, although outside the scope of this manual, are referred to as necessary.
- 4.3 The upper 16 bytes of memory (addresses 4000 7FFF) are implemented using eight 16k bit dynamic RAMs (IC6-IC13). Approximately half of this space is available to the user for writing BASIC or machine code programs. The remainder is used to hold the system variables including 6k bytes reserved for the memory mapped display area.
- 4.4 In the 48k Spectrum an additional 32k bytes of RAM are provided (addresses 8000 - FFFF) which are implemented using eight 32k bit dynamic RAMs (IC15-IC32). The RAM, providing extra memory space for the user, is normally fitted during manufacture but may be added retrospectively using the RAM expander kit. In addition to the RAMs, the kit includes the address multiplexer and read/write control ICs IC23-IC26. Board space and the necessary discrete components are already provided on the board.
- 4.5 Read/Write Operations
- 4.5.1 The following description should be read in conjunction with the circuit diagrams given in Figures 1.4 and 1.5.
- 4.5.2 Read Only Memory (ICS). The CPU addresses the ROM directly during memory read cycles using the address bus A13-A0. MREQ and RD enable the ROM and the ROM outputs respectively. A third input (CS) derived by the ULA 'ROMCS) selects the ROM, provided the higher order address bits A14 and A15 are both low. These are reserved for accessing the RAM memory which starts with address 4000 (i.e. address A14 set). An external ROM 1C select input, supplied via the expansion port on pin 25A, selectively disables the on-board ROM by pulling the select input high. By virtue of R33 placed on the ULA side of the ROM the ULA ROMCS output is effectively inhibited. Interface 1 uses this









ISSUE 1A







mechanism allowing the CPU to read the extension ROM in the interface for microdrive and RS232 applications.

- 4.5.3 Links H and N, shown directly above IC5, allow a second source ROM to be fitted. The Hitachi (H) and NEC (N) ROMs use different pins for the enable and select inputs (i.e. pins 20 and 27). The links allow the inputs to be reversed accordingly.
- 4.5.4 Standard 16k RAM (IC6-IC13). The eight 16k RAM ICs making up the standard 16k x 8 bit RAM memory are organised as a matrix of 128 rows x 128 columns. Thus, separate 7-bit row and column addresses are reguired to access any one of the locations. These addresses are supplied by the CPU on address bus A13-AO via an address multiplexer IC3/IC4. The low order address bits A6-AO give the row address and are selected at the beginning of the memory access cycle when initially the RAS output from the ULA is high. Later, as the row address is latched, RAS goes low selecting the high order address bits A13-A7 giving the column address.
- 4.5.5 The RAS/CAS outputs from the ULA are generated in seguence in response to MREQ and A14 from\_the CPU. The DRAMWE output, also from the ULA is a decode of the RD/WR waveforms telling the RAM to expect either a read or a write cycle.
- 4.5.6 It is also apparent from the circuit diagram that the ULA can access RAM by generating a set of addresses independent of those generated by The address port for the RAM is therefore dualled by the the CPU. (R17-R23) insertion of small value resistors on the address multiplexer side of the RAM. This ensures that where there is likely to be conflict between the ULA and CPU, the ULA address has priority. Priority is assigned on the basis that the ULA must access the memory mapped display area in the RAM at set intervals in order to build up the video for the TV display. If the ULA is about to access the RAM and it detects either A14 or A15 (i.e. the CPU is also about to access the RAM) the ULA inhibits the CPU clock temporarily halting the CPU memory transaction until its own transaction is completed.
- 4.5.7 Resistors Rl to R8, in series with the data bus lines, perform a similar function to the address portplr£sistors described above. They ensure that the ULA does not 'see' CPU write data while the ULA is accessing the RAM.
- 4.5.8 Refresh for the standard 16k dynamic RAM is accomplished during normal read cycles, i.e. most rows are refreshed each time the ULA accesses the memory mapped display area during picture compilation; the remaining rows are refreshed as a result of other read cycles also known to occur at regular intervals within the refresh period.

- 4.5.9 32k Expansion RAM (IC15-IC32). The eight 32k ICs making up the 32k x 8 bit expansion RAM are in fact 64k ICs with either row or column drop-out rendering one half of the memory non-functional. In order to accommodate the Texas Instruments RAM (Type TMS 4532) or the optional OKI RAM (Type MSM3732) a set of links are provided, visible on the circuit diagram above the address multiplexer IC25/IC26. These links not only cater for the different manufacturer (Issue 3 Spectrums only) but also allow, in both instances, one of two 1C versions to be selected depending on which half of the RAM (top, bottom, left or right) is functional. The links are respectively TI and OKI (manufacturer Issue 3 Spectrums only), -3/-4 (TI version) and -H/-L (OKI version Issue 3 Spectrums only).
  - NOTE: It is essential when replacing ICs in this area that all RAMs carry the same manufacturers part number and that the links are selected accordingly.
- 4.5.10 The expansion RAM is organised as a matrix of 128 rows x 256 columns (TI RAMs) or 256 rows x 128 (OKI RAMs). Thus, separate 7/8 bit row and column addresses are required to access any one of these locations. These addresses are supplied by the CPU on address bus A14-AO via an address multiplexer IC25/IC26. For example, when accessing the TI RAM the low order address bits A6 to AO give the row address; AR is held low on the -3 version selecting the top half of the memory and high on the -4 version selecting the bottom half. The column address is given by the high order address bits A14-A7.
- 4.5.11 Row/column address selection and RAS/CAS timing for the RAM is decoded in IC23/IC24 from inputs supplied by the CPU, i.e. address line A15 selecting addresses 8000 upwards, and MREQ heralding a memory read or write cycle. A theoretical timing diagram illustrating the RAS/CAS waveforms is given in Figure 1.2.
- 5. INPUT/OUTPUT
- 5.1 The input/output section of the Spectrum is centered round the ULA (IC1). The functions performed within the device include TV video compilation, keyboard scanning and tape input/output. It also derives and controls the CPU clock (<j>CPU) using an external 14 MHz crystal XI, and drives the loudspeaker when a 'BEEP' instruction is being executed. Each of these sections and the supporting circuits are described below.
- 5.2 TV Picture Generation
- 5.2.1 The video compilation section of the ULA operates in conjunction with the memory mapped picture display area in the standard 16k RAM, the colour (chrominance) modulator (IC14) and the UHF modulator. This combination produces a high resolution, 24 line x 32 character, eight colour TV display.





FIG 1.2 EXPANSION RAM RAS/CAS TIMING (READ CYCLE SHOWN)

- 5.2.2 Using the 14 MHz clock the ULA derives line and field timing compatible with the external TV receiver. Video is derived by accessing the memory mapped display area in the RAM in a set seguence at set times throughout the picture frame. The addresses are necessarily independent of the CPU and appear on the ULA address lines A6 through AO as two separate bytes timed by the RAS/CAS row/column address select lines.
- 5.2.3 The net result is three separate video waveforms outputs from the ULA on pins 15, 16 and 17. These carry the luminance signal Y, incorporating the line and field sync, and two unmodulated colour-difference signals U and Y making the Spectrum compatible with both colour and monochrome receivers.
- 5.2.4 From the ULA the colour difference signals are applied to the colour modulator IC14 via two level shifting networks. These match the ULA output levels with those reguired at the B-Y and R-Y inputs to the modulator. In the Issue 2 Spectrum the level shifting network is passive, incorporating two potentiometers VR1, VR2. These are reguired to set-up the chroma bias level on IC14 pin 3 such that the voltage difference measured between pin 3 and the colour difference signals on pins 2 and 3 respectively is nominally 0V d.c. In the Issue 3 Spectrum two active networks incorporating IRS and TR9 eliminate the potentiometers, greatly improving colour stability.
- 5.2.5 The level shifted colour difference signals, input to IC14, are then encoded, by guadrature modulating two 4.43 MHz chroma sub-carriers. The sub-carriers are generated with the assistance of an external crystal X2 and a CR lead/lag network introducing a 90° phase shift between pins 1 and 18. (A further difference between the Issue 2 and 3 Spectrums lies in the bias oscillator. The early issues incorporate a trimmer TC2 allowing the chroma sub-carrier freguency to be adjusted; on the later issues the freguency is fixed). The resultant modulated colour difference signals are finally mixed producing a composite chroma sub-carrier at IC14 pin 13.
- 5.2.6 At this point the chroma signal is a.c. coupled to the base of TR2 and added to the inverted luminence signal on TR1 collector. The resultant composite video is then buffered and applied to an encapsulated UHF modulator operating on European standard channel 36.
- 5.3 Keyboard Scanning
- 5.3.1 Every 20 ms (i.e. once per maskable interrupt), the CPU systematically scans the keyboard recording which 'keys '(if any) have been pressed. The scanning method is described below with the aid of Figure 1.3. As the figure clearly illustrates the keyboard consists of an 8 x 5 matrix, the inter-section of each row and column bridged by a normally open switch contact. The row 'outputs' and column 'inputs' are shown connected by separate ribbon cables KB1 and KB2, one to the ULA and the other to the high order address lines A15-A8. Pull-up resistors R64 through R68 ensure that when the address bus is in the high Z state, or none of the key-switches is closed, row outputs KBO to KB4 remain high.



1.9

- 5.3.2 When the keyboard scanning routines are entered the CPU performs successive I/O read cycles setting the IOREQ and RD lines to the IJLA, low. At the same time, the I/O port addresses placed on the upper half of the address bus are modified with each cycle such that each of the address lines A15 through A8 is set low in turn, the other lines remaininghigh.
- 5.3.3 The seguence starts with I/O port address FE driving address line A8 low. The keyboard matrix also sees this potential on column 6 applied via D6 and the ribbon cable KB2. Thus, when any of the switches on the inter-section with column 6 is pressed, the corresponding row output supplying the ULA via the second ribbon cable (KB1), is pulled low. The row signal(s) is subsequently inverted by the ULA and placed on one of the five low order data bus lines. For example, if the CAPS SHIFT key is pressed row one output drives data bus DO high and so on. The sequence ends with I/O address 7F when column 8 is addressed. In this instance, operation of the SPACE key drives DO high. Clearly, the keyboard scanning routines make the distinction between the CAPS SHIFT and SPACE key by knowing which address line is being driven.
- 5.4 Tape Interface
- 5.4.1 When LOADing or SAVEing programs using a cassette recorder, the ULA transfers information between the MIC and EAR sockets and the data bus, performing A/D and D/A conversions as reguired. Since the LOAD and SAVE functions are mutually exclusive, a single pin on the ULA (i.e. pin 28) is used both for input and output. Separate I/O read/write cycles to port address 254 configure the pin accordingly. During the LOAD operation the CPU executes successive I/O read cycles, reading the EAR input off data bus 6. When performing a SAVE operation, the CPU executes successive I/O write cycles, this time writing data to the MIC output via data bus 3.
- 5.4.2 To ensure that I/O cycles are correctly implemented, the IOREQ line supplying the ULA is gated with address line AO via TR6. Thus, if any memory transactions occur where AO is high (i.e. not port address 254) then the IOREQ input is forced high inhibiting any attempt to perform an I/O cycle.
- 5.4.3 Loudspeaker (BEEP) Operation. It should be noted that while SAVEing, the level of the MIC output is barely sufficient to drive the loudspeaker via D9 and TR7 (D10). However, during the execution of a BEEP instruction the CPU writes instead to port 254 on data bus 4. This effectively boosts the MIC output, driving the loudspeaker so that the BEEP tone can be easily heard. During the execution of such an instruction the cassette recorder is not running so there is no conflict at the MIC/EAR sockets.

## 6. POWER SUPPLIES

- 6.1 The on-board power supply unit receives a 9V unregulated supply from the external Sinclair ZX power pack and derives the following internal supply rails:
  - (a) regulated +5V for the 1C logic circuits, the ULA and the UHF modulator,
  - (b) -5V and +12V for the standard 16k dynamic RAM,
  - (c) +12V for the colour modulator circuits.
- 6.2 The external power pack incorporates a mains transformer, full wave rectifier and capacitive smoothing. A thermal fuse is fitted at the transformer input.
- 6.3 The on-board power supply unit incorporates a 7805 regulator, deriving the +5V power rail, and an inverter stage TR4/TR5. The latter raises the level of the +9V unregulated supply to in excess of +12V. The resultant square wave at the junction of TR4 collector and the inverter coil is subsequently rectified and smoothed by D5/C44 producing the +12V output for the RAM. Additional smoothing, imparted by R62/C45, produces the +12V supply for the TV circuits free from noise generated by the RAM. The square wave at TR4 collector also supplies the Zener/rectifier diode combination D16/D12 generating -5V for the RAM, and is available at the expansion port for use by peripherals. The +12V, +5V and -5V are also made available.

#### SECTION 2

#### DISASSEMBLY/ASSEMBLY

Sub-Section	LIST OF CONTENTS	Page No.
1	Disassembly	2.1
2	Assembly	2.1

- 1. DISASSEMBLY
- 1.1 Unplug all input/output leads and turn the computer upside-down to reveal five self-tapping screws. Remove the screws. Hold the two halves of the case together and return the computer to the keys uppermost position. The top half of the case can now be separated from the bottom half, although it remains connected to it by two flexible keyboard ribbon connectors. Care should be taken not to damage the ribbon connectors. As an aid to reassembly, the lie of the connectors within the case should be noted.
- 1.2 To remove the board from the lower half of the case, remove one selftapping screw (adjacent to IC22 socket) and lift out the board. It may be advantageous to make up two short pluggable extensions for the keyboard connectors in order to improve accessibility to the board.
- 1.3 To change either the keyboard membrane or the rubber keyboard mat it is first necessary to remove the escutcheon plate (template). This is attached to the case by double-sided adhesive tape around the edges. The template is removed by inserting a screwdriver at one end and levering it away from the case. It is not normally possible to remove the template without damage.
- 2. ASSEMBLY
- 2.1 Assembly is carried out using the reverse procedure to that of disassembly. Do not overtighten self-tapping fixing screws.
- 2.2 When replacing a keyboard component, note that the membrane keys into projections on the case. Place the keypad over the membrane and ensure that it is positioned and seated properly. Faulty installation can result in depressed keys being trapped under the template during subsequent key operations. To install the template, place double-sided adhesive tape around all four edges, locate it in position on the case and apply firm pressure around the edges (12 mm tape on sides and bottom, 6 mm at top).

2.3 When aligning the top half of the case with the bottom half ensure that the two keyboard ribbon cables are not trapped between projecting components within the case. In their correct positions there is sufficient room for the cables to take up a comfortably curved position inside the case. If a cable is trapped and bent double, an open circuit will sooner or later result.

#### SECTION 3

#### SETTING UP AND SYSTEM TEST

Sub-Section	LIST OF CONTENTS	Page No.
1	General Alignment Introduction Voltage Check Colour Adjustment Sub-Carrier Oscillator 14MHz Oscillator	3.1 3.1 3.1 3.1 3.2 3.2
2	System Test	3.3

#### 1. GENERAL ALIGNMENT

1.1 Introduction. The Issue 3 Spectrum modification removes the need for adjustment of the colour tuning using potentiometers and trimmers. Therefore, the setting-up procedure for this board is confined to checking that the internally generated power supply voltages and two oscillator frequencies are correct. Adjustment instructions apply strictly to the Issue 2 Spectrum boards only but are generally relevant to the Issue 1 Spectrum as well.

To carry out the setting up procedure it is first necessary to remove the ZX SPECTRUM from the case (Section 2, Assembly/Disassembly). For convenience the keyboard may also be disconnected.

1.2 Voltage Check. Check that the internally generated power voltages are as follows:

Circuit Reference	Nominal Value	Tolerance
IC6 pin 9	+ 5V	± 0.25V
IC6 pin 1	- 5V	- 5.5V to -4V
IC6 pin 8	+12V	± 1.2V
LT side of C52	+12VA	± 1.2V

1.3 Colour Adjustment. Potentiometers VR1 and VR2 are used to effectively null the voltages between pins 4 and 2 (for VR1) and pins 2 and 3 (for VR2) on IC14 (LM1889). To allow for thermal drift, the potentiometers are set for non-zero voltages; furthermore these voltage off-sets are set to satisfactory but non-optimum levels in production, and optimum values may be used to advantage in servicing. The relevant figures are given in the following table - voltages are given relative to pin 3 of LM1889.

Pot.	IC14 Pin No.	Factory Setting (mV)	Optimum (r Voltage	nV) Tolerance	Overall Ranqe (mV)
VR1	4	$130 \pm 20$	+50	-5	+45 to +150
VR2	2	$75 \pm 20$	-50	-50 +5	-45 to -100

1.4 Sub-Carrier Oscillator. The chrominance sub-carrier oscillator frequency should be 4.433619 MHz ± 50 Hz. This frequency may be checked/adjusted by using one of two methods, listed in (a) or (b) below.

Apply power to the power socket using a bench power supply set at 9V. Current consumption will be approximately 500 mA to 700 mA for the 16k Spectrum and 700 mA to 900 mA for the 48k Spectrum.

- (a) Feed the Spectrum modulator output via a co-axial cable into a standard colour TV receiver. Measure the frequency of the locked TV chroma sub-carrier.
- (b) Connect pin 17 of IC14 (LM1889) via a 4.7 pF capacitor and a lead to the frequency meter. It is recommended that this is done using a jiq made up from an 1C test clip. Pin 18 of this clip must be removed to minimise stray capacitance. Connect a 10k ohm resistor between the input terminals of the frequency meter. Measure the frequency and adjust trimmer TC2 if the measured frequency is outside tolerance.
- 1.5 14 MHz Oscillator. This frequency is not readily set by working to a specified frequency and tolerance. On Issue 2 boards trimmer TCI should be adjusted to minimise the effects of beat frequencies which cause waves of distortion to flow across the screen. These are particularly apparent with certain colour combinations, e.g. red INK or green PAPER, and the phenomenon is sometimes referred to as 'dot crawl'. It is stressed that adjustment of this frequency is not straight-forward, as deviations due to temperature change are easily visible; tuning should be adjusted to minimise rather than remove this effect. Proceed as follows:
  - (a) Set up the Spectrum to display green PAPER with red INK.
  - (b) Type-in three or four lines of characters and monitor the screen.
  - (c) Adjust trimmer TCI to minimise the effects of distortion.

#### 2. SYSTEM TEST

- 2.1 The system test for the Spectrum may be undertaken using the ZXTP taped program (see 1.1 Test Equipment in Section 4) loaded conventionally; this requires that the keyboard is connected. The test should be carried out with the Spectrum connected to its own power supply.
- 2.2 The test program exercises all of the Spectrum circuitry with the exception of the SAVE function. To test this function a small, possibly one line program should be typed in, SAVED and then VERIFIED as described in the instruction manual.

## SECTION 4

## FAULT DIAGNOSIS AND REPAIR

Sub-Section	LIST OF CONTENTS	Page No.
1	Introduction Test Equipment Modification History Modifications - Issue 1 Board Modifications - Issue 2 Board 32k Extension Memory - (16k-48k) Hitachi vs NEC ROM	4.2 4.2 4.3 4.4 4.5 4.5 4.5 4.6
2	Fault Diagnosis Techniques Power Supply Unit Initialisation Memory Check Keyboard Structure Fault-Finding Guide	4.6 4.6 4.7 4.7 4.7 4.8 4.10 4.11
3	Repair	4.19
4	16k to 48k Upgrade Integrated Circuits/Link Settings Issue 2 Board Issue 3 Board	4.19 4.19 4.20 4.20

#### 1. INTRODUCTION

#### 1.1 Test Equipment

Section 4 is intended as a guide to fault diagnosis and repair of the ZX SPECTRUM. It is assumed that users have a reasonable knowledge of electronic servicing, theory and standard fault-finding techniques and have access to the test equipment and tools required to carry out the task. The table below contains a list of the minimum recommended test equipment and materials.

## SPECIFICATION/MANUFACTURER EQUIPMENT Oscilloscope with Rise Time: 0.02 us/cm Oscilloscope probe (x1O) Variable power supply unit 0 to 30V d.c. Mono cassette recorder With RECORD and PLAYBACK facilities Mains extension lead 'Safebloc' type Multimeter General purpose Colour Television Open Market **ZX** Printer Sinclair ZXTP test tape Blank tape Open Market 12mm and 6mm wide, Tesafix 959 Double-sided adhesive tape (B.D.F. TESA) or 3M equivalent

Engineers who are already familiar with the Sinclair ZX81 will find some similarities in the ZX SPECTRUM. The Spectrum, however, is a more sophisticated device with colour and sound circuitry.

The ZX SPECTRUM is supplied with either 16k or 48k of on-board RAM. The 16k version is wired so that it can be expanded to 48k by the addition of a number of appropriate plug-in ICs. For details of the memory upgrade, see sub-section 4 of this section.

See Section 5, Figures 5.1 and 5.2 for the layouts of the Issue 2 and Issue 3 boards respectively.

## 1.2 Modification History

Two major modifications have been implemented on the Spectrum boards:

(a) A modified layout of board (i.e. Issue 1, Issue 2 and Issue 3)

Issue 1. This layout allowed for the 16k RAM to be mounted direct on the board, with the 32k extension consisting of a subsidiary board mounting onto special OIL connectors. Approximately 26,000 units were manufactured.

Issue 2. This layout allows for all 48k of RAM to be mounted direct on the board; sockets, ready for a memory update, are fitted on 16k versions. A small number of Issue 2 units were manufactured using disc capacitors for 47 pF and 100 )jF values, but subsequently axials were introduced.

Issue 3. This layout incorporates advanced circuitry for the colour tuning, removing the need for potentiometers and trimmers and the associated adjustment. It also allows for OKI ICs to be used in the 32k extension memory. The heatsink is also redesigned and is relocated at the back of the case.

(b) The Ferranti ULA, type 5C102, plus spider addition replaced by ULA type 5C112.

5C102. This ULA has a timing fault which was cured by connecting a 74LS00 1C mounted on a miniature board and spider. This ULA was fitted to approximately 40,000 units.

5C112. This improved ULA has no spider modification, but has either a diode or resistor or transistor connected to it. The details are:

Diode/resistor mod : 4k7 resistor from +12V to pin 30 on IC2 and diode (IN 4148) from pin 30 of IC2 to pin 33 of IC1.

Transistor mod : TR6 (ZTX313) connected as follows:

Base to IC2, pin 30.

Emitter to IC1, pin 33.

Collector to IC2, pin 11.

6C001 This ULA alters the timing of the colour burst signal, and improves the performance of the Spectrum with certain television sets (e.g. Hitachi, Grundig). It also causes the screen picture to be shifted by one character width to the left.

NOTE: The values of certain components vary depending on which board and which ULA is used as follows:

Board Issue No	2	2	3
ULA Type	5C112	6C001	6C001
Component			
R 4 7	220 a	I k	Ik
R49	8 k2	10 k	10 k
R 5 6	220 n	470 fi	Ik
R 6 3	220 n	470 n	Ik

## 1.3 Modifications - Issue 1 Board

A number of modifications were introduced, and these should be checked for and, if necessary, introduced retrospectively:

- (a) 100 pF capacitor between RAS and ground necessary only when using ULA 5C102.
- (b) 470 pF capacitor between IC2, pin 28 and ground required only when IC2 and RAM ICs are all of NEC manufacture.
- (c) 1 k resistor between RAS and 23V and 1 k resistor between CAS and 12V, only when RAM ICs are of National manufacture. R57 (330n) must be removed, and the 470 pF capacitor is not required.
- (d) 47 k resistor between pin 13 of LMI889 and ground required only if the difference between white and yellow colours is inadequate.
- (e) If disc capacitors are used for C41 and C49 (47 nF) they must be replaced by axial components.
- (f) Capacitor C46 (1 uF electrolytic) should be replaced by a high temperature component.
- (g) This modification is required for efficient operation of certain machine code software and should be implemented on all units. It has been implemented in manufacture for all ULAs 5C112-2 and later.

D14 replaced by C67 (100 pF) R24 changed from 3k3 to Ik R27 changed from 680 n to 470 n R73 (Ik) added between Id/32 and +5V

(h) A significant cause of problems has been found to be failure of the internal power supply transistor TR4. The circuit may be improved by changing the value of R60 from 100 n to 270 fl and connecting a 4.7 uF electrolytic (perferably radial type) with positive end to TR5 emitter (positive end of C34) and negative end to TR5 base (to R58). 1.4 Modifications - Issue 2 Board

A number of modifications have also been introduced for the Issue 2 board. These should be checked and, if necessary, introduced retrospectively.

(a) These components should be changed if colour quality needs upgrading:

R48 changed from 4k7 to 2k2 R49 changed from 18 k to 8k2 R50 changed from 8k2 to 4k7 R72 changed from 47 k (or 18 k) to 10 k C65 changed from 100 yF to 22 yF

- (b) Early Issue 2 boards were manufactured using a considerable number of 47 yF and 100 uF disc capacitors. C41 (47 nF) and C43 (100 nF) should be replaced with axial components to prevent undue risk of short circuits.
- (c) To prevent lifting of the keyboard template, a thin strip (6 mm wide) of double-sided tape was introduced to the top edge of the template. (Previously, only the other 3 edges had tape). This modification should be introduced whenever template lifting is found to be a problem.
- (d) See Items 1.3(g) and (h) above.
- 1.5 Modifications Issue 3B Board

Although functionally similar to the Issue 3 board, the layout differs. The DC converter design has been improved, providing greater power supply reliability. Component changes are as follows (see Fig 1.5 for details):

C77 (IQOnF) added C49 changed from 47nF to 560pF R60 changed from 270fl to 68n TR4 can be either ZTX650 or TIPP31

1.6 32k Extension Memory - (16k to 48k)

Board Issue 1: The extension memory is supplied as a plug-in module which is inserted into sockets near the edge connector. The ICs used are either TI 4532-3 or TI 4532-4, and all ICs in a unit must be of the same type (i.e. all must be -3 or all must be -4).

Board Issue 2: The extra memory is obtained by plugging in 4 logic ICs and 8 memory ICs (see Sub-Section 4). The ICs used are either TI 4532-3 or TI 4532-4, and all ICs must again be of the same type. It should be noted that the RAM select signal is 0V for the -3 1C and +5V for the -4. A link on the board provides the required select level.

Board Issue 3: This allows OKI ICs to be used in place of TI 4532. Again, all ICs must be of the same designation. Appropriate links (2) must be fitted in the grid located on the board between the edgeconnector and the 'mic' jack socket. Again the extra memory is obtained by plugging in 4 logic ICs and eight memory ICs.

## 1.7 Hitachi vs NEC ROM

During manufacture, wiring links are selected and inserted in the board according to whether a Hitachi or NEC ROM is used. These links are marked 'H' and 'N' as appropriate and are located as follows.

Board Issue 1 - between the ROM and the heat sink

Board Issue 2 - beneath the raised portion of the heatsink

Board Issue 3 - adjacent to the loudspeaker

Clearly, if the ROM is changed for one of a different make, then these links must be changed as well.

## 2. FAULT DIAGNOSIS

## 2.1 Techniques

In a closed loop system such as a computer, because of the interdependence of numerous component parts, fault diagnosis is not necessarily straight-forward. In addition, because of the high speed cyclic operation, interpretation of any waveforms on control, data and address lines as being valid depends to a large extent on practical experience of the system. There are however, certain checks with valid waveforms and levels that can be carried out before substituting any integrated circuits. Experience has shown that the best method of initially checking waveforms and levels can be to compare with the same point in a known serviceable board. The following pages provide a basic fault-finding procedure and furnish a list of possible faults along with suggested ways of curing them.

With a densely populated board such as the ZX SPECTRUM, a careful physical examination of the board can sometimes indicate an obvious fault. Burst-out discrete components or an overheated track show up immediately, as do the attentions of an enthusiastic amateur. Bearing in mind the latter, short ^circuits, caused ,by hairline solder splatter can be or several ohms resistance and can cause some very

misleading fault symptoms.

Provided first principles are adhered to and a common-sense approach is adopted, it will be found after a short space of time that fixing a faulty Spectrum is very much a routine operation.

## 2.2 Power Supply Unit

The unstabilised external power supply unit is a source of some problems. The design is such that, at minimum input voltage (215V a.c.) and 1.4A output, the voltage trough should not be less than 7.0V; at maximum input voltage (265V a.c.) and 60QmA output, the voltage peak should be less than 13V.

## 2.3 Initialisation

At switch-on the computer should automatically 'initialise' and produce a clear screen with the statement

## (01982 Sinclair Research Ltd

displayed in the lower left section of the screen. This indicates that most of the system is working. If the Spectrum does not initialise, carry out the following basic checks.

Basic Checks. It is difficult to be specific in a fault-finding guide because of the large variety of fault conditions which can occur, but the following procedure, starting with a table of checks set out in order of priority, will however isolate the major fault area.

FUNCTION	CIRCUIT REF.	WAVEFORM/VOLTAGE
Voltage regulator input	+ve side of C50	+9V d.c. ± 2.0V. At less than +7V the regulator may not operate correctly.
Voltage regulator output	+ve side of C34	+5V d.c. ± 0.25V - no discernable ripple.
On-board power supply outputs: +5V d.c.	IC6 pin 9	+5V d.c. ± 0.25V – no discernable ripple.
-5V d.c. +12V d.c. +12VA(to IC14 only)	IC6 pin 1 IV6 pin 8 LT end of C52	-5V d.c.
Clock pulses	IC1 pin 32 TR3 base and collector IC2 pin 6	14MHz squarewave at +5V amplitude,
Address and data lines (following through to relevant ICs)	RT side of R17-R23 RT side of R1-R8	Waveform of amplitude 3.5V

If these tests prove satisfactory check IC1 pin 14, IC2 pin 11 and IC5 pin 28 for +5V. Also check for ground at IC1 pin 40, IC2 pin 29 and IC5 pin 14. If all is still satisfactory at this point and IC1 is the plug-in type, replace IC1. If replacement of IC1 does not cure the fault, check the address and data lines of IC1, IC2 and IC5 for active data.

It is possible that one of the Z80A or RAM control lines has become faulty therefore, comparing with a known serviceable board if possible, check the waveforms at the following points at origin and destination:

(a)	IC2:	Pin         16         -         INT           Pin         20         -         IDREQ           Pin         19         -         MREQ           Pin         21         -         M           Pin         22         -         WR	Pin 17 - NM1 Pin 24 - WAIT Pin 25 : fflCTEQ Pin /b KtbM
(b)	IC22:	Pin 4 - "RAT Pin 15 - CA3~	Pin 3 - WITE

If no fault has been found and the computer still has not initialised, the fault could lie in the RAM. If the computer is a 48k machine the 32k of expansion RAM can be isolated. An easy way of doing this, assuming that the ICs are not fitted into sockets, is to remove the +5V from IC25. This is probably best done by very carefully cutting the track to IC25 pin 16. If this operation clears the fault condition, the expansion RAM will have to be further isolated. In either instance the point has been reached where it is necessary to start replacing ICs.

Where the fault persists after isolating the 32k expansion RAM it would be necessary to start changing individual ICs in the order of IC13 to IC6 (RAM), IC1 (ULA), IC2 (Z80A). After each change of 1C the unit must be powered up to check for correct initialisation.

A method of fault-finding that can be used on both the 16k and 48k versions is to make up a 'test 1C' device. This may be done by using an 1C test clip, to which is attached a serviceable 1C (of the relevant type e.g. 4116 or 4532), to bridge across each suspect 1C in turn. This method is not guaranteed to work but can often save a lot of time unnecessarily changing suspect ICs.

Memory Check

Where a Spectrum has initialised correctly but a RAM memory fault is suspected, it is possible to find the faulty address and relate it to a faulty 1C by carrying out the following procedure:

Key in the instruction:

PRINT PEEK 23732 + PEEK 23733 \* 256

The value printed should be:

(a) for a 48k unit - 65535

(b) for a 16k unit - 32767

The value printed in each instance is the last valid memory location, and in a serviceable unit would be as set out above. Therefore, if a different value, n, is printed the faulty location will be n + 1. If the value returned is less than 32767 the fault lies in the original 16k of RAM. The following example illustrates the method of relating a faulty location to a faulty 1C.

Example. If a 48k Spectrum is giving a memory of 25.25k key in the following instruction:

PRINT PEEK 23732 + PEEK 23733 \* 256

Assume the answer displayed is 43200, therefore the faulty location is 43201 (stops at last valid location). Key-in:

POKE 43201,85 : PRINT PEEK 43201 (= answer A)

If answer A is 85, key-in:

POKE 43201,170 : PRINT PEEK 43201 (= answer B)

If answer B is anything other than 170 look up in the following table which 1C to change (e.g. if answer B is 234 change IC21). Similarly, if answer A is other than 85 refer to the table to find the faulty 1C.

Data 85 IC6-IC13	Data 170 IC15-IC22	Size of Error	Error Bit	Faulty RAM < 32767	location if: > 32767
84	171	1	0	IC6	IC15
87	168	2	1	IC7	IC16
81	174	4	2	IC8	IC17
93	162	8	3	IC9	IC18
69	186	16	4	IC10	IC19
117	138	32	5	IC11	IC20
21	234	64	6	IC12	IC21
213	42	128	7	IC13	IC22

If there is more than one faulty RAM location the first fault identified will have to be repaired before it is possible to proceed.

## 2.5 Keyboard Structure

The keyboard is connected horizontally in eight blocks of five keys anoth frigging the light webschoft is the state of the set of th

fault is with KB2 circuitry or the 8-way membrane, and that if any block of eight keys fail the fault is with KB1 circuitry or the 5-way membrane. Possible keyboard faults are listed in paragraph 2.6




FIGURE 4.1 KEYBOARD FORMAT

### 2.6 Fault-Finding Guide

As with any complex digital equipment the possible fault permutations are vast, thus the following table is not intended to be an exhaustive list of the faults that might occur on the Spectrum. It is intended as a guide only to possible courses of action to follow when faults show up in particular areas of the circuit. These areas are listed in the table with sub-headings, in no particular order of priority. It is envisaged that the ZXTP test tape has been loaded, or an attempt has been made to load the tape, in order to check for a faulty condition.

AREA	SYMPTOM	ACTION			
TV screen dead, smoke appears on switch-on.	TR4 base-collector shorted.	Remove TR4			
switch on.	Short persists with TR4removed.	<ol> <li>Check TR5 and C44.</li> <li>Visually check track.</li> <li>Check TR4.</li> </ol>			
	TR4 blows again.	<ol> <li>Change TR4 and TR5 (even though TR5 checks out).</li> <li>Check that TR5 circuit components are to latest specification.</li> </ol>			
Not initialising.	No '(C)1982 Sine!air. Research Ltd1 statement.	Follow fault-finding procedure, paragraph 2.2 above. y y y			
No video.	No video.	<ol> <li>Change IC1.</li> <li>Check TR1 and TR2.</li> </ol>			
NOTE: Table 4.1 sets out typical signals found on IC14 pins 1-18 IC14 pins 1-18.	No video after ULA changed.	<ol> <li>Visually check IC1 and socket,</li> <li>Check for shorting between C65 and R53.</li> <li>Carry out fault-finding procedure, para 2.2 above.</li> </ol>			
		<ol> <li>Check voltage drop across R64.</li> <li>Check +5V regulator 0/P and +9V regulator I/P.</li> <li>Check PWR socket not shorted.</li> </ol>			

4. Check power unit.

AREA	SYMPTOM	ACTION
No video, (contd)	No VIDEO INPUT at IC14 pin 12.	<ol> <li>Check waveform at IC14 pin 13. If correct check TR1 and TR2.</li> <li>Check waveforms at IC1 pins 15, 16 and 17: PIN 15 *3V- *2V-</li> </ol>
		+3V
		+3.5V <sup></sup>
		If correct check VR1, VR2 (Issue 1 and Issue 2 boards).
		<ol> <li>Change IC1.</li> <li>If +5V and VIDEO INPUT correct change modulator.</li> </ol>
Corrupt Paper, after ULA change.	-	<ol> <li>Check IC1 socket.</li> <li>Check PWR socket is not intermittent.</li> <li>Check IC1 pin 14 for +5V with no discernible ripple.</li> </ol>
	No 3 MHz at IC2 pin 6.	<ol> <li>Low amplitude - check R25.</li> <li>Check TR3.</li> <li>Check IC1 pin 32 for 3 MHz.</li> <li>Check IC1 pin 39 for 14 MHz.</li> <li>Check crystal XI.</li> <li>Check IC1 pin 13 for +3V.</li> </ol>

AREA	SYMPTOM	ACTION			
Video Incorrect.	Dark Screen.	<ol> <li>Check tuning.</li> <li>Change modulator.</li> </ol>			
	Dim 'Sinclair' Io9°-	<ol> <li>Check +12V"</li> <li>Check C65 for high impedance.</li> <li>Check R52.</li> <li>Check +5V on IC14 pin 3.</li> </ol>			
	Wavy lines across screen.	<ol> <li>Press down on each electrolytic capacitor to see if lines disappear. If so change that capacitor.</li> <li>Check crystal X2.</li> <li>Check/change TR1 and/or TR2.</li> <li>Check/change IC14.</li> </ol>			
	Self resetting.	Check TR6.			
	Random dynamic squares.	Change C54.			
	Paper area too low.	Change IC1.			
	Diagonal lines in the border area.	Change R47.			
	Distorted video.	<ol> <li>Check for +3V at IC1 pin 13.</li> <li>Change C30.</li> </ol>			
Colour tuning faults (Issue 1 and Issue 2 boards)	-	Visually check IC14 circuits.			
	VR1 or VR2 fails to adjust IC14 pin 13 waveform.	<ol> <li>Monitor IC14 pin 2 trimming VR2.</li> <li>Monitor IC14 pin 4 trimming VR1.</li> <li>Change IC14.</li> </ol>			

AREA


Colour tuning VRl or VR2 d.c. Change IC14. shifts IC14 pin 13 faults, (cont'd) waveform. Alternate dark lines Change IC14. on screen. No colour after trimming TC2: 1. Check crystal X2. ICH pin 17 not oscillating 2. Change ICH. 3. Change X2. Check for broken track, ICH pin 17 1. oscillatingbut 2. Change TC2. fails to tune. 3. Change ICH. 1. With 'Sinclair' logo on ICH pin 17 output correct but still screen ICH pin 2 and no colour (boards ICH pin 4 should be as at all Issue Nos). follows: PIN 2 PIN 4 65 n S 2. pins 2 and 4 If ICH correct, change are modulator. Colour faults Pin screen. Change crystal X2. (Issue 1 - Issue 3 boards. If untunable Issue 1 and issue 2 boardsj chage ICH. Blue haze around 'Sinclair1 \*\_mo

Screen too yellow. Chan

Change ICH.

AREA	SYMPTOM	ACTION				
Colour faults (cont'd)	Intermittent colour.	<ol> <li>Change TC2 (Issue 1 and Issue 2 boards).</li> <li>Change IC14.</li> </ol>				
	Red, Blue or Green 'Sinclair' logo.	Change IC1.				
	Washed-out colours.	Check TR2.				
Keyboard faults.	KB1 fault.	<ol> <li>Check for short on 2 or more of the 5 tracks.</li> <li>Change membrane.</li> </ol>				
	KB2fault.	<ol> <li>Check for short on 2 or more of the 8 tracks.</li> <li>Change membrane.</li> </ol>				
	Dead keyboard.	Change IC1.				
	Wrong keyboard response.	Change IC1.				
	Keyboard response too fast.	Change IC1.				
Regulator coil.	Coil excessively noise.	Change coil.				
Speaker. NOTE: Figure 4.2 shows typical waveforms in the speaker circuit	No speaker output.	<ol> <li>Check load input wave- forms.</li> <li>Check TR7.</li> <li>Check D9.</li> <li>Change speaker.</li> </ol>				
Test program.	'Tape Loading Error' output.	Reload program.				
	Paper area edges distort.	Change ICl.				

AREA	SYMPTOM	ACTION			
Test Program. (cont'd)	Paper area corrupts during tests.	1. Change IC1.			
(cont d)	during tests.	2. Carry out fault-finding procedure (paragraph 2.2).			
	Border colours are striped.	Change IC14.			
	Failure messages.	Carry out fault-finding procedure (paragraph 2.2).			
	'Test Passed1 message not flashing				
	Reduced memory size.	1. Perform memory test,			
		2. Change IC1.			
Program Loading.	Keyboard does not allow loading.	See keyboard faults,			
	Program fails to load,	1. Check jack sockets are fully inserted.			
		2. If loading stripes in border are unusually wide, check D13.			
		3. Check/change IC1.			
	'Program appears.	Check/Change IC2.			








FIGURE 4.2 SPEAKER LOAD INPUT WAVEFORMS

Pin No.	Signal
1	(CHROMA LEAD) SINEWAVE BOOmV, 0.2yS, d.c. 9.5V
2	(R - Y INPUT) [130µ5] [65;] dc 5V µ5
3	(CHROMA BIAS) d.c. 4.8V
4	(B - Y INPUT) 500mv de 4.8V
5	0V (GROUND)
12	(VIDEO INPUT) d.c. 12V unreg.
13	(CHROMA SUBCARRIER)
14	(R.F SUPPLY)
15	(SOUND TANK) 'LINKED1 12V d>c-
16	(CHROMA SUPPLY
17	(CHROMA OSCILLATOR OUTPUT) SQUAREWAVE 0.2 us 4V P-P. D.C. 0.8V
18	(CHROMA LAG) SINEWAVE BOOmV P-P 2 uS d.c. 9.5V
6,7,8 9,10, 11	Not Connected
NOTES:	<ul> <li>(1) Rails and signals taken on switch-on, computer displaying 'Sinclair1 y</li> <li>(2) No keys pressed</li> <li>(3) All d.c. levels positive wrt 0)/</li> </ul>

Pin No.

Signal

(3) All d.c. levels positive wrt OV

#### 3. REPAIR

- 3.1 Renewal of components should be carried out using recognised desoldering/heatsinking techniques to prevent damage to the component or to the printed circuit board. Other points to be noted are:
  - (a) When replacing a keyboard matrix, take care that the ribbon connectors are fully inserted into the board connectors, and are not kinked during insertion.
  - (b) Make sure there is a good contact made between the voltage regulator body and the associated heatsink in order to ensure adequate heat conduction. The heatsink hole in certain Issue 3 boards allows excessive play which could cause fouling of the edge connector. Take care in re-assembly that the heatsink is fitted away from the edge connector.
  - (c) When the regulator is being replaced it is recommended that a suitable proprietary thermal grease is applied to the rear surface of the component body.
  - (d) The modulator should be replaced as a complete unit.
  - (e) When replacing plug-in ICs it is advisable to use the correct removal and insertion tools. Avoid contaminating the connection pins by hand!ing.
  - (f) When handling ICs take normal anti-static precautions. It is recommended that only a suitably earthed, low power soldering iron be used.
  - (g) After any component has been renewed the circuit board should be examined carefully, to ensure that there are no solder 'splatters' which may cause short circuits between tracks or connector pins.
- 4. 16k TO 48k UPGRADE
- 4.1 Integrated Circuits/Link Settings

For both the Issue 2 and the Issue 3 boards the memory upgrade is accomplished by plugging four logic ICs and eight memory ICs into existing board sockets. Depending on the types of memory 1C used, appropriate circuit links must be fitted on the board. Figure 4.3 shows the layout of the area of the board containing the empty sockets. The Issue 3 board is shown which also gives positions (top left of diagram) of the links. 4.2 Issue 2 Board

The ICs used on this board are as follows:

1C	TYPE
IC15 - IC22	TI 4532-3 or TI 4532-4 200ns (or 250ns)
IC23	74LS32
IC24	74LSOO
IC25, IC26	74LS157 (NOT National Semiconductors)

NOTES:	(1)	All external RAM ICs must be of the same type
		(i.e. all -3 or -4 variants).
	(2)	LINK 3 on the board (IC26, pin 10) should be fitted

- if IC15-IC22 are type 4532-3.
- (3) LINK 4 should be fitted if IC15-IC22 are type 4532-4.

.3 Issue 3 Board

The ICs used on this board are as follows:

- 1C
   TYPE

   IC15 IC22
   TI 4532-3, TI 4532-4 or OKI MSM3732

   IC23
   74LS32

   IC24
   74LS00

   IC25, IC26
   74LS157 (NOT National Semiconductors)
- NOTES: (1) All extension RAM ICs must be of the same type.
  (2) Two links must be fitted on the board (grid located between edge connector and m/c jack socket) depending on memory manufacturer and type (high or low enable). See Figure 4.4 for link positions vs manufacturer and 1C type.






FIGURE 4.3 EXPANSION MEMORY IC LOCATIONS



# OKI HIGH ENABLE

OKI LOW ENABLE



TI 4532-4

TI 4532-3

FIGURE 4.4 ISSUE 3 LINKS vs 1C MANUFACTURER AND TYPE

						If () If ()I	PRINTED CIRCUIT BOARD (ISSUE 2) FIG 5 1
	55 e1. 55 69,		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	÷	2011 P.44 5049 AEG		PRINTED CI
		ತೆ ಜ≍ತತೆಕೆ	* ****		EL1 1004 SPEARCA		
i izii	i 	ಂದನಂದ					
5212 3222	-======	2222	 	   	   		
51	20282 2020 20282 20292 2020 2020 2020 2020 2020 2020 2020 2020 2020 2020 2020	53 			NIC CON		
1	11 5511 2511 2511 2511 2511	4-444 4444 4444 4444 4444 4444 4444 44	11.	~	11 X2. 11 X2. 11 X2. 12 X 1001		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				NOULATOR		
5223	33993		<u> </u>				

#### SECTION 5

#### PARTS LIST

Sub-Section	LIST OF CONTENTS	Page No.
1	Introduction	5.1
2	Notes to Table 5.2	5.1

- 1. INTRODUCTION
- 1.1 Parts lists for the ZX SPECTRUM are provided in table form; one for the case assembly (Table 5.1) and another for the board assembly (Table 5.2). The latter covers the Issue 2 and 3 Spectrums and is related to the board layout diagrams given in Figure 5.1 and 5.2. Table 5.2 also lists the alternative components which the service engineer will occasionally find on production versions of the Issue 2 board or may introduce retrospectively in order to improve performance. These components are listed in the column headed 'ISSUE 2 MODS' with references to notes against them. These notes are explained below-
- 2. NOTES TO TABLE 5.2
  - (1) The alternative values given for R47, R49, R56 and T63 are used if the ULA fitted is Type 6C001.
  - (2) The alternative values for R48, R50, R72 and C65 are introduced to improve the colour quality.
  - (3) C74 is essential on all Issue 2 boards and should be fitted retrospectively. At the same time R60 must be replaced with the larger value.
  - (4) The introduction of alternative components for R24 and R27 is essential. At the same time C67 replaces D14 and R73 is added.
  - (5) Issue 2 boards fitted with the Type 5C112 ULA have either a transistor (TR6) or diode/resistor modification (see Issue 2 circuit diagram for details).
  - (6) On Issue 3 boards only crystal X2 must have a close tolerance specification (i.e. 10 ppm absolute, 10 ppm 20°C to 60°C, 5 ppm per year.)
  - (7) On Issue 3B boards, the d.c. converter design has improved reliability. R60 is changed from 270n to 68ft and C49 is changed from 47nF to 560pF. Capacitor C77 (100nF) has been added.

2.1 General Capacitor Change. Early Issue 2 units were manufactured using a considerable number of 47 nF and 100 nF disc capacitors. Where these occur the service engineer should take the opportunity to replace C41 and C49 with axial types.

### TABLE 5.1 CASE ASSEMBLY

### DESCRIPTION

### MANUFACTURER

- Assembled board as appropriate (Table 5.2)
- Moulded Upper Case
- Moulded Lower Case
- Keyboard Mat (Rubber)
- Keyboard Membrane N.F.I.
- Keyboard Template
- Rubber Feet
- Self Tap Screws (case fixings), 5 off
- Double-sided adhesive tape -12 mm wide; Tesafix 959 B.D.F. Tesa
- Double sided adhesive tape -6 mm wide; Tesafix 959 B.D.F. Tesa
- Self Tap Screw (board fixing), 1 off

PRINTED CIRCUIT BOARD (1SSUE 3) FIG. 5.2 COMPONENT LAYOUT DSK12756 13506 A

: ] ] ] [ ] [ ] ]	:	1911	11		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
5 62454	(1)	s = = = = = = = = = =	2	5		
	2 632 <b>3</b> 5			19 19 19		
	52223		ŧ	2992		
12225 <b>1</b> 25				2925	-	
82 8 8 8 6 8 8 8 8 6 8 6 8	81181			22	=_=#~,	
28288	355E 35			53 <u>5</u>		
86 I 88845 	52825 92858	<u> </u>	EE.	<u>2</u> 2	31:: 	
46232	63985 22853		<u> </u>	55	E	
32212 22223			92	555	Ŧ	
2222	===533 3	-	=	4		

# TABLE5.2BOARDASSEMBLY

Circuit Reference		2 Iss Mod	sue 2	Notes	Issue	3	Rating/ To!	Manufacture Type			
CAPACITORS											
	otherwis	e stated	all ca	apacito	rs are az	xial	types)				
C1-C8	47 nF				47 nF	2	25V, 10%	Ceramic			
C25	22 yF				22 yF		0V,-10%+80%	Elect.			
C26	47 nF				47 nF	2	5V, 10%	Ceramic			
C27	1 yF				1 yF	5	0V,-10%	Ceramic			
C28	22 yF				22 yF		10V,-10%+80%	Elect.			
C29/C30	47 nF				47 nF	2	5V, 10%	Ceramic			
C31/C32	lOOnF				100nF		25V, 10%	Ceramic			
C33	47 nF				47 nF	2	5V, 10%	Ceramic			
C34	22 yF				22 yF		10V,-10%+80%	Elect.			
C35	10 nF				10 nF	2	5V, 10%	Ceramic			
C36	47 nF				-	2	5V, 10%	Ceramic			
C37/C38	33 pF				33 pF	2	5V, 10%	Ceramic			
C39	10 nF				10 nF	2	5V, 10%	Ceramic			
C40/C42	47 nF				47 nF	25	V, 10%	Ceramic			
C43	lOOnF				lOOnF	2	25V, 10%	Ceramic			
C44/C45	lOOyF				lOOyF		6V,10%+80%	Ceramic			
C46	1 yF				1 yF	5	0V,-10%+80%	Elect.			
C47	22 yF				22 yF		10V,-10%+80%	Elect.			
C48	47 nF				47 nF	2:	5V, 10%	Ceramic			
C49	47 nF			(7)	47/560pF	F 25	5V, 10%	Ceramic			
C50	22 yF				22 yF		0V,-10%+80%	Elect.			
C51	-				-						
C52/C53	150pF				150pF	25	V, 10%	Ceramic			
C54	470pF				-		5V, 10%	Ceramic			
C55-C62	47 nF				47 nF	2	5V, 10%	Ceramic			
C63	47 pF				47 pF	2	5V, 10%	Ceramic			
C64	lOOpF				lOOpF	2	5V, 10%	Ceramic			
C65	100yF	22 yF		(2)	22 yF		20V,10%+80%	Elect.			
C66	47 nF	•		. ,	47 nF		5V, 10%	Ceramic			
C67	-	lOOpF		(4)	lOOpF		5V, 10%	Ceramic			
C68-C71	-	-			100nF		5V, 10%	Ceramic			
C72/C73	-				16 pF		5V, 10%	Ceramic			
C74	-	4.7WF	(	(3)	4.7uF		min 🕺	Elect.			
C75	-	-	,		lOOnF		5V, 10%	Ceramic			
TC1/TC2											
C76	-				47 nF	25	5V, 10%	Ceramic			
C77	-	-		(7)	lOOnF		5V, 10%	Ceramic			
				X . 7		-	7				

# COIL

Circuit Reference	Issue 2	Issue 2 Mod	Notes	Issue 3	Rating/ Tol	Manufacture Type
Coil	SPECTRUM	-	-	SPECTRUM	-	1703

#### CONNECTORS

Reference	Description	Manufacturer/ Part Number
EAR MIC PWR	<ul><li>3.5 mm jack socket</li><li>3.5 mm jack socket</li><li>2.1 mm co-axial socket</li></ul>	
KB1	5-way ribbon connector	Molex 5229-05CPB
KB2	8-way ribbon connector	Molex 5229-08CPB

# CRYSTALS

Circuit Reference	Issue 2	Issue 2 Mod	Notes	Issue 3	Manufacture Type
XI X2	14.000000MHz 4.433619MHz	-	Note (6)	14.000000MHz 4. 433619MHz	

# DIODES

Circuit Reference	Issue 2	Issue 2 Mod	Notes	Issue 3	Manufacture Type
D1-D9	1N4148	-	-	1N4148	Signal
D10	1N4148	-	-	-	Signal
D11-D13	1N4148	-	-	1N4148	Signal
D14	1N4148	-	(4)	-	Signal
D15	BA157	-	-	BA157	Rectifier
D16	5V1	-	-	5V1	Zener

# INTEGRATED CIRCUITS

Circuit Reference	Issue 2	Issue 2 Mod	Notes	Issue 3		Manufacture Type
		11100				- ) P •
ICl(ULA)	5C102	5C112	(1)	6C0001	-	Ferranti
IC2(CPU)	Z80A/U78	0 -		Z80A/M780		
IC3/IC4	74LS157N	-		74LS157N	-	Not National
IC5(ROM)	SPECTRUM	SPECTRUM		SPECTRUM	-	NEC/Hitachi
IC6-IC13	4116	-		4116	-	150 ns
IC14	LM1889	-		LM1889		
IC15-IC22	TI4532	-		TI4532/	48k only	Texas/
				MSM3732	-	OKI
IC23	74LS32N	-		74LS32N	48k only	
IC24	74LSOON	-		74LSOON	48k only	
IC25/IC26	74LS157N	-		74LS157N	48k only	Not National

Circuit Reference	Issue 2	Issue 2 Mod	Notes	Issue 3	Rating Tol	Issue 3B
R1-R8 R9-R16	470R 8K2			470R 8K2		
R17-R23	330R			330R		
R24	3K3	1KO	(4)	1KO		
R25	180R			180R		
R26/R27	680R			470		
R28	10KO			10K		
R29	1KB			10K		
R30	1KO			10K		
R31	220KO			220K		
R32	100R			100R		
R33	680R			680R	1/2 ar 1W	
R34	15R			15R	1/2 or 1W	
R35	10KO 680R			10K		
R36	1KO			680R IK		
R37 R38	3K3			IK		
R38 R39	3K3 3K3					
R39 R40	3K3 1K0					
R40 R41	1KO 1KB					
R41 R42	1KD 1KO			1KO		
R42 R43	3KO			3KO	2%	
R43 R44	5K0 5K1			BK1	2%	
R44 R4B/R46	1KO			1KO	270	
R4D/R40 R47	22OR	1KO	(1)	1KO		
R48	4K7	2K2	(1) (2)	2K2		
R49	8K2	10KO	(1)	10KO		
RBO	8K2	4K7	(1) (2)	4K7		
R61/R52	2K2	1117	(2)	2K2		
R53	390R			390		
R54	100K			100K		
R55	56R			56R		
R56	220R	470R	(1)	1KO		
R57	330R		(-)			
R58	1KO			1KO	2%	
R59	1K8			1K8	2%	
R60	100R	270R	(3), (7)	270R		68R
R61/R62	15R			15R		
R63	220R	470R	(1)	1KO		
R64	15R			15R		
R65-R69	10КО			10KO		
R70/R71	220R			220R		
R72	470Kor18K	10KO	(2)	10KO		
R73	_	1KO	(4)	1KO		
R74/R75	-			10KO		
R76/R77	-			1KO		
R78	-			470R		
VR1/VR2	2K2					

# RESISTORS (1/4W, 5% unless otherwise stated)

# TRANSISTORS

Circuit Issue 2 Reference	Issue 2 Mod	Notes	Issue 3
TR1/TR2 ZTX313	-		ZTX313
TR3 ZTX313	-		ZTX313
TR4 ZTX650/TIPH			ZTX650
TR5 ZTX213	-		ZTX213
TR6 ZTX313	-	(5)	ZTX313
TR7 -	-		ZTX450
TR8/TR9 -	-		BC184

# MISCELLANEOUS

Reference	Description	Manufacturer/ Part Number
REG	5V regulator	7805
MOD	UHF Modulator with E36 vision carrier (UK only)	Astec UM1233
Loudspeaker	40 ohm T.V. Type	
Modulator Screen Insulator		1740
Heatsink	Special (Issue 2 or 3)	
(2)	Screw, ch hd. 4BA x 15/16 in Washer, shk prf, 4BA Nut, hex, 4BA	
OIL SKT	16-way (10-off) for 48k expansion RAM (16k model only)	
OIL SKT	14-way (2-off) for 48k expansion RAM (16k model only)	
OIL SKT	28-way for IC1 (ULA)	

# GENERAL DATA

Earliest version	-	very pale brown keys.
Second version	-	grey keys
Third/Fourth versions	-	grey keys, but heatsink now visible through the edge connector slot
Early Spectrum plus	-	same as fourth type.
Dissembly -	af	Eter removing the screws, tilt back, face up and carefully lift the top taking care not to break any of the keyboard tails.
Heatsink	-	when operating computer with the heatsink removed to obtain access a temporary heatsink must be used made of anything as long as it fits under regulator.
Circuit Diagram	-	idealised version on centre pages shows all modific- ations which should be made. Note that connecting items such as standard capacitors may not be shown.
Edge Connector	-	28 pin double-sided to which no interface may be inserted or removed whilst computer is switched on.
Plugs & Cables	-	use only genuine Sinclair issue or HK plugs, etc.
Power Supply	- V	Where any possibility of fluctuating mains exists a transient suppressor should be fitted.
Links	-	T1/T3 for Texas THS4532-3; T1/T4 for Texas TMS4532-4 1/H for OKI HSH3732H; 1/L for OKI MSM3732-L.

Rank A823 CTV Chassis Philips G8 CTV Chassis Thorn 3000/3500 CTV Chassis Thorn 8000/8004/8500/8600 CTV Chassis Rank T20/20A CTV Chassis The Tunbridge & McCourt T.V. Repair Manuals The Tunbridge Video Repair Manuals

### SERVICE DATA

Modification of earplug: Connect a 330 ohm resistor between signal and earth leads of earplug to allow earplug to be left in place while saving a programme.

Inserting or removing such items as joysticks, especially via a Kempston interface, while the computer is switched on will damage the power resistors and regulator.

Modification to voltage generator circuit: Where not fitted already, insert a 22uf capacitor between the TR4 and D15 as shown in the circuit diagram, this will ensure the correct 12v supply. On early models replace R60 by a 270 ohm resistor and fit C74 if missing. Ensure that the 12v supply is 12v.

Manufacturer's advised modifications: In early versions replace all ceramic capacitors by axial ones and replace C46 by a high-temperature luf type. All resistors to be changed to show the second value show in centre pages circuit diagram herein; same applies to capacitors.

Weak sound: Only if particularly noticeable should the sound section be changed to same as shown herein.

Tape and Sound Circuits: 5Vp-p at ear socket for 2Vp-p at IC1 verifies IC1.

Alignment: Only needed for early models. Place meter on pin 4 of IC4 and adjust VR1 to obtain 130mV; adjust VR2 to obtain -75raV at pin 2 with a 20mV allowable error either way. Use TC2 to set colour subcarrier frequency to 4.433619MHz to 50Hz either way. TCI only helpful to improve screen colour pattern.

Alignment: All models. Run the programme to display the eight colours in sequence from black to white. This is normally given as:-

10 FOR A=0 TO 7 20 FOR B=0 TO 3 30 PAPER A: PRINT" "; 40 NEXT B 50 NEXT A 60 GOTO 10

If this shows incorrect or missing colours then align as stated for early models. See repair data for later models.

#### REPAIR DATA

#### 1) GENERAL REPAIR PROCEDURE AND NOTES ON ALL FAULTS

These computers are reportedly very unreliable with some 50% of new ones alleged to have to be returned for replacement. Many faults are due to loose or badly fitted components so that a good checkover is essential for this reason, to determine if a factory failure first.

Check heatsink first for any reported fault, is it loose? Are there overtightened screws? Look for dry joints, cracks in print or cracked boards, badly fitted components, especially ICs; dirty or tarnished contacts, pins, holders, edge connectors; damaged keyboard tails and fins are certainly not uncommon for whatever reason.

Before investigating any fault check any add-ons and interfaces to the computer for broken solder, etc. caused by user wiggling them about. It is also essential to note if add-on is loose or faulty which will give a guide to any damage so caused. This will also determine if fault in add-on not computer. Knowing what add-ons are used can be a good guide to probable fault: for example, suspect TR4 blown and/or destroyed RAMS if a Kempton is used.

Check if customer has been inserting or removing any add-ons without first switching off and point out how this practice has damaged machine and costing him unnecessary expenditure. If this is admitted then check TR4 first then RAMS and see symptom 3.


#### 2} WONT LOAD FROM RECORDER


Almost invariably this will be caused by the alignment of the recorder head not being good enough. The recorder will play music, etc. and function well but it will still need adjusted to operate the Spectrum properly and it matters not whether it is an old or just newly bought recorder.

Disconnect Spectrum from recorder and with any tape playing use a long thin-bladed screwdriver to adjust the azimuth screw through the hole normally provided for this purpose. The object is to obtain the sharpest possible sounding note, noting that if note is in the least muffled sounding then there is no chance of the Spectrum loading from it.


If no hole is provided this should be done with the recorder cover removed. Although it is reccommended that volume should be set at midpoint it is far better to vary volume setting to that at which maximum treble is obtained. Finally give head a good clean and recheck setting.


If the adjustment does not cure the problem then save a short programme from the computer (or use one previously saved) and if this doesn't load then it is safe to assume that there is a fault, probably in the computer. In this case, check connections to computer and the circuit from the edge connector to the first I.C.






Later types board






Early circuit showing presets Td, TC2, VRl and VR2 to match the early type boards.

Note:- the different pins 16/17 setup from Id in the generalised circuit diagram shown in the middle pages.



In very  $versions_t$  instead of TR6 a somewhat **unreliable**, resistor/diode was used which should be modified as shown in the centre pages.



This very **unreliable** circuit was used in very early versions from pin 32 to base of Id. This circuit **should** be modified to that shown in the centre pages if not already done.

Modifications associated with IC1

#### 3) NO COIL BUZZ FROM INVERTER, -5V ABSENT

From symptom 1 it should be obvious that TR4 (ZIX650) is very prone to damage and this symptom is a sure indication that TR4 must be replaced. However, before replacing the TR4 check the TR5 (ZIX213) (using a transistor tester is O.K.) and the coil since it is not unknown for all three to have gone at the same time and if only the TR4 is replaced it can fail again immediately if the others are faulty.

Whether or not these three are faulty or not, there can be one or more faulty RAMS as well caused possibly by the same forcing in of an interface during switch on. If all else has been fixed, switch on and check if any RAM gets hot; replace any very hot RAMS either in basic set or in extra board as this is a sure sign of being short circuit. If open circuit, the guickest way to check is to bye-pass each RAM in turn using a RAM known to be O.K. When so doing the same RAM must be used as the suspect and it should not be removed after each check for some ten seconds after each switch off or it will fault itself. Use of a 'scope or logic probe is clearly a better alternative if available. Tandy m<tke a good, inexpensive logic probe.

#### 4) DIRECT CHECK FOR A SINGLE FAULTY RAM

Type PRINT PEEK 23732+256 \* PEEK 23733 (CR). If computer RAMS O.K. the reply is either 32767 or 85535, if less than either this means that there is a shortage of available RAMS, thus one or more RAMS may be faulty.

Call the reply N and if POKE N+1,85 (CR) then PRINT PEEK N+1 (CR) is typed the reply should be 85 if RAMS O.K., in that case type POKE N+1,170 (CR) then PRINT PEEK N+1 (CR) when a different number to the 170 you have just poked into that address will be printed. 85 and 170 are the easiest binary numbers (01010101 and 10101010) to cover all combinations in an 8-bit chip.

Where a different reply is given to either POKE locate the incorrect 1C as follows:-

Where 85 is poked in

IC6 faulty gives 84; IC7 87; IC8 81; IC9 93; IC10 69; IC11 117; IC12 21; IC13 213.

Where 170 is poked in IC15 faulty gives 171; IC16 158; IC17 174; IC18 162; IC19 186; IC20 138; IC21 234; IC22 42.

5) NO COIL BUZZ FROM INVERTER, REG7805 OPEN CIRCUIT

Before replacing the 7805 check the heatsink to see if faulty or badly fitted. Remedy any physical defect in print or damage around screws, etc. Also check the TR4/5 and coil.

#### 6) CONTINUAL FAILURE OF POWER SUPPLY TRANSISTORS

Ensure that all modifications have been carried out and that the edge connector is O.K. and not loose or, damaged. Check for proper fitting of all peripherals and verify that owner is not persistently inserting/removing any of the add-ons, etc. while the computer is switched on. Note that many users are apparently incapable of grasping this simple point. Check the plug/sockets and cable, if not suitable then replace with correct ones. Check the mains and possible interference from other items on same circuit.

If satisfied then check if the Ov is correct on earth. Monitor the Ov while running computer as this nay shew up an intermittent voltage fault. A systematic check on all capacitors.resistors to earth should find the culprit for this uncommon cause.

#### 7) KEYBOARD FAULTS

It is recommended that keyboards are better replaced completely since they take a lot of battering and replacement is guite inexpensive. If it is decided that the keyboard is worth repairing then the diagram will show which tail is faulty according to keys in error.

If the entire keyboard is non-functional then check the 5v supply is reaching it O.K. before replacing the ULA I.C. Probably the commonest fault lies with a faulty 10K resistor (R65 to R69) easily identified according to which keyboard co91umn is faulty.

#### 8) VARIOUS FAULTS WHICH APPEAR ONLY WHEN WARM

Check heatsink thoroughly. If heatsink is O.K. then the ULA I.C. ICl will be the cause. If ICl has been replaced before it may be worth adding extra heatsink for it. See also following symptom.

#### 9) INTERMITTENT FAULTS

If such faults show up with a comoaritively new Spectrum then it is most likely that they are due to poor contacts/soldering during the manufacturing process. Check all holders and pins for tarnish and dry joints. Replace faulty holders by cutting them out and replacing completely. Check after this for poor contacts or loose contacts, look for items which have been poorly soldered or even where soldering has been omitted. Finally check the boards for hairline cracks and breaks, especially radiating from heatsink screws.

#### 10) TEXAS SN1889 INSTEAD OF LHA889

A few models appeared with the SN version and these may even have been used as replacements during repairs. Although unlikely to find now, if SN types have been used replace completely by LH type.

#### 11) POWER SUPPLY O.K. - COMPUTER NOT WORKING CORRECTLY

If computer is functioning at all check for single RAM failure then multiple RAM failure as already described. If RAMS are O.K. or fault is more serious and RAMS cannot be checked then check if the 5v supply is reaching all I.C.s in order IC1, 2, 24, 23, 3, 4, 26, 25 and 5. Replace the open circuit component cutting off the 5v supply if this is the case. ,'

Faulty or missing sound usually identifies the ULA I.C. IC1 as being faulty and this is the most likely suspect in any case. Flick the clock crystal with your finger, this will guickly determine if it is faulty or not.

Although I.C.s are best checked out systematically using a logic probe or even a 'scope, it is worth noting that after IC1 the most likely culprits are IC2 and IC5, neither of which are particularly reliable and it may even be worth replacing the three automatically as a fast check.

## 12) PERMANENT I.C. CHECKER FOR LOGIC PROBE USE

If a logic probe is available it is well worth making a table of the results of checking each 1C pin with a good computer switched on with keyboard disconnected. Thus when any computer is being tested all that is needed is to compare the readings with your correct set and the different readings will quickly pinpoint the faults.

#### 13) FLICKERING WHITE BACKGROUND - MAY BE CAUSING EYESTRAIN

If resetting the computer doesn't help, which is not uncommon if a CTV is being used, then the only thing is to set up the computer to display a coloured background with white printing. See spectrum manual for this, but green is the most relaxing background. Save this programme and load it every time Spectrum is not being used for games.

### 14) SPARE PARTS SUPPLIERS

At time of printing the most popular suppliers appear to be:-CPC Electronic Components, 194 North Road, Preston, Lanes. PV Tubes, 104 Abbey Street, Accrington, Lanes. BBS 1EE.

This list may be amended in future printings.

# NOTES