4.2.2 Error code and message

Messages appear on the Smart Panel program window or on the control panel display to indicate machine status or errors. Refer to the tables below to better understand the meanings of each message, then follow the suggested solution provided on the page that you are referred to.

Error Code	Error Message	Troubleshooting
01-000	Door is open or Check Transfer belt	4-31 page
01-004	Paper jam in MP tray	4-32 page
01-005	Paper jam in tray 1	4-33 page
01-006 01-018	Paper jam in tray 2	4-34 page
01-009	Paper jam inside of machine	4-35 page
01-010	Paper jam in exit area	4-36 page
01-015	Paper jam at the top of duplex path	4-37 page
01-016	Paper jam inside of duplex path	-
01-017	Output bin full. Remove printed paper.	4-38 page
02-000	System error: #02-000. Please turn off then on	4-39 page
02-001 02-006	Fuser error: #02-001/006. Please turn off then on	4-40 page
02-002	System error: #02-002. Please turn off then on	4-41 page
02-005	System error: #02-005. Please turn off then on	4-41 page
03-000	Motor error. Error: #03-000. Turn off then on	4-42 page
03-007 03-008 03-009	Motor error. Error: #03-007/008/009. Turn off then on	4-43 page
03-015	Motor error. Error: #03-015. Turn off then on	4-44 page
04-001 04-002 04-008	LSU error: #04-001/002/008. Please turn off then on.	4-45 page
08-000 08-001	Original paper Jam Original paper jam inside of scanner. Remove Jam	4-46 page
08-002 08-006	Original paper jam inside of scanner	4-47 page
08-003 08-010	Original paper Jam Original paper jam inside of scanner. Remove Jam	4-48 page
08-004 08-006	Original paper Jam Original paper jam inside of scanner. Remove Jam	4-49 page
08-008	Scanner door Open Door of scanner is open. Close it	4-50 page
11-003	Scanner locked Scanner locking switch is locked. Release it	4-51 page

Error Code	Error Message	Troubleshooting
12-000 12-001	Paper mismatch Tray1/2 Load [A4] [Plain] Continue ⊙ Cancel X	4-52 page
12-004	Paper mismatch MP. Load [A4] [Plain] Continue ⊙ Cancel X	4-53 page
18-000	Fax memory is almost full.	4-54 page
18-001	Fax memory is full. Print or remove received fax job	4-54 page
18-002	Too many faxes are in the print queue waiting to be printed. Wait, reprioritize, and/or remove unwanted jobs from the print queue.	4-54 page
18-003	Too many faxes are received. Reprioritize, and/or remove unwanted jobs from the print queue.	4-54 page
21-002	Paper Empty in tray1 Paper is empty in tray1. Load paper	4-55 page
21-003	Tray 1 cassette is pulled out. Insert it properly	4-56 page
21-010	Paper is empty in MP tray. Load paper	4-57 page
21-018	Paper Empty in tray2 Paper is empty in tray2. Load paper	4-58 page
21-019	Tray2 cassette is pulled out. Insert it properly	4-59 page
28-001 28-002 28-003	Transfer belt is not installed. Install it. Transfer belt is not compatible for this machine. Check user's guide.	4-60 page

Code	
------------------------	--

01-000

Door is open or Check Transfer belt


Symptom

Front cover or top cover is opened.

• Possible Cause

- 1. Harness is defective, Connector is not connected properly.
- 2. Sensor is defective.

- 1. Ensure the Front and Top Covers are closed properly.
- 2. If the PTB [paper transfer belt] is not installed, install it.
- 3. Check the cover switch harness between Main PBA and HVPS.
- 4. Check the 24V enable signal on Main PBA. If the voltage is high(5V), replace the Main PBA.
- 5. Check the 24V1 on SMPS. If there is no output, replace the SMPS board.



• Code	• Error message
01-004	Paper Jam in MP tray


• Symptom

The paper from the MP tray has not reached to the feed sensor within a predetermined period of time after pick up.

Possible Cause

- 1. Pickup roller rubber is worn out.
- 2. Pickup Clutch does not work.
- 3. Feed Sensor is defective.

- 1. Ensure the Front and Top Covers are closed properly.
- 2. If the PTB [paper transfer belt] is not installed, install it.
- 3. Check the cover switch harness between Main PBA and HVPS.
- 4. Check the 24V enable signal on Main PBA. If the voltage is high(5V), replace the Main PBA.
- 5. Check the 24V1 on SMPS. If there is no output, replace the SMPS board.





• Code	• Error message
01-005	Paper jam in tray 1

The paper from the tray1 has not reached to a feed sensor within a predetermined period of time after pick up.

Possible Cause

- 1. Pickup roller rubber is worn out.
- 2. Pickup Clutch does not work.
- 3. Feed Sensor is defective.

- 1. Take out the cassette and remove the jammed paper.
- 2. Check the separator pad of the cassette. If it become loose or has reached its PM interval, replace it.
- * MEA Holder Pad (JC97-02892A)
- 3. If the pick up roller does not rotate, check the Gear Pick up(JC97-02895A) and solenoid. If it is defective, replace it.
- 4. If the pick up roller rotates but the paper is not feeding, replace the Feed motor (JC31-00112A).
- 5. Check the connectors are plugged in properly on CN4,5,9 on HVPS.
- 6. Check the connectors are plugged in properly on CN1,2 on HVPS and check the flat cable.
- 7. Check that the PM interval for Pick-up Roller has expired. If so, replace it.
- 8. Check the actuator on the Feed Sn. If it does not work correctly, replace the feed-sensor.
- 9. Check for proper positioning of the Knockup-Plate(JC97-02888A)
- 10. Check if the Guide-adjust is adjusted for paper entry properly.

• Code	• Error message
01-006	Paper jam in tray 2
01-018	

The paper from the tray2 has not reached to a feed sensor within a predetermined period of time after pick up.

• Possible Cause

- 1. Pickup roller rubber is worn out.
- 2. Pickup Clutch does not work.
- 3. Feed Sensor is defective.

- 1. Take out the 2nd cassette and remove the jammed paper.
- 2. If the pick up roller does not rotate, check the Gear Pick up(JC97-03228A). If it is defective, replace it.
- 3. If the pick up roller rotates but the paper is not feeding, replace the Clutch-Feed(JC97-03270A).
- 4. Check the connector is plugged in properly on CN9 connector on Main PBA
- 5. Check the sensor and connector in SCF.

•	Code
0	1-009

Paper jam inside of machine

Symptom


Paper jam inside of machine


- 1. At Power On, the paper is jamming at Regi sensor or Feed sensor.
- 2. At printing, the paper is detecting at Regi sensor or Feed sensor continuously.
- 3. At printing, the paper is not detected at exit sensor within a predetermined time.

Possible Cause

- 1. Feed sensor or Regi Sensor is defective.
- 2. Exit sensor is defective.
- 3. Feed Clutch is defective.
- 4. Regi Clutch is defective.

- 1. Check the Spring tension of the Regi. roller and Regi shaft. If the spring is defective, replace it.
- 2. Check and replace the exit sensor.
- 3. Check the connectors are plugged in properly on the flat cable / exit sensor harness / Feed sensor harness.
- 4. Check the OPC motor is working. / OPC lock.
- 5. Check PTB [paper transfer belt] working condition, if PTB-Belt is torn replace it.







• Code 01-010

• Error message

Paper jam in exit area


Symptom

Paper jam in exit area

• Possible Cause

There is paper jammed under the Exit Sensor at Power ON, or the Fuser Actuator Arm, or Exit Sensor is defective.

- 1. If the actuator fuser sensing part is binding or broken, replace the Fuser Actuator [JC66-01404A] and exit sensor if required.
- 2. Check the connectors are plugged in properly on the flat cable / Exit sensor harness.





•	Code
0	1-015

Paper jam at the top of duplex path

Symptom

- 1. At Power On, if the Fuser Exit Sensor and/or Reverse Sensor detects paper.
- 2. At Printing, Fuser Exit sensor and Reverse Sensor is not on within a predetermined time after paper moves into the Reverse path.

Possible Cause

- 1. Check the Fuser Exit Sensor, Reverse Sensor Harness and Connector.
- 2. Check if the UI message is changed in the Fuser Exit Sensor and the Reverse Sensor operation (EDC Mode).
- 3. Check the Reverse Motor and Fuser Exit Motor. (EDC Mode).

• Troubleshooting method

1. Lift the Scan Unit and Open the Reverse Top Cover and the Middle Open Cover. Check for Paper in the Fuser and Reverse Unit.



2. If the paper is jammed, remove the paper in the Fuser.



3. If the paper is not present, check if the Fuser Exit and Reverse actuator's return action as the EDC Mode just checks on/off. If so, check the actuator springs of the Fuser Exit and Reverse return spring tension is sufficient,. and sensor arm works smoothly. (EDC Mode -> Test Routines -> Engine Diagnostic Test -> 102-370 / 102-xxx)





4. If the Actuator Arm in the Fuser and Reverse is Operating properly. Check if Reverse motor and Fuser Exit Motor is turning properly in EDC Mode. (EDC Mode -> Test Routines -> Engine Diagnostic Test -> 100-xxx / 100-xxx)

• Code	 Error message
01-017	Output bin Full

Output bin Full.

Remove printed paper

Symptom

When the tray limit is reached, the out-bin full sensor is on for 600ms.


Possible Cause


- 1. Check the Out-Bin Full Sensor.
- 2. Check if the UI message is changed by the Out-Bin Full Sensor operation.
- 3. Check the Out-Bin Full Sensor Harness and Connector.

• Troubleshooting method


1. Check the BIN_FULL_SENSOR (picture'1' below) by pushing the trigger (picture'2' below) beneath the SCAN_ASSY.

Check if the UI message is changed by the Out-Bin Full Sensor operation





Check if the Harness is defective.Check if the connector is connected properly.







- 3. Replace the Main PBA or the Scan_Joint PBA or the Panel PBA.
- 4. Enter the EDC mode and follow the below sequence after the repair is done.
 (EDC Mode → Test Routines → 101-Clutch → 0190-OutBin Full → Start → Status check → Stop)

• Code 02-000

• Error message

Fuser Error:#02-000 Please turn off then on.

• Symptom

At Warm-up, this error has occurred. The machine does not work until power off/on. If the error code reoccurs, follow the "Troubleshooting method" below.

Possible Cause

Fuser Unit is not installed and AC is not supplied to the Heat Lamp.

• Troubleshooting method

- 1. Turn off the power. And turn on the power.
- 2. If the problem persists, replace the fuser unit.
- 3. If the problem persists after replacing the fuser unit, reconnect the CN35 connector on Main-PBA.
- 4. If the problem persists, replace the Main-PBA.



CN35 →Thermistor

• Code	• Error message
02-001	Fuser Error:#02-001 Please turn off then on.
02-006	Fuser Error:#02-006 Please turn off then on.

At Warm-up, this error has occurred. The machine does not work until power off/on. If the error code reoccurs, follow the "Troubleshooting method" below.

Possible Cause

Fuser Unit is not installed and AC is not supplied to the Heat Lamp.

- 1. Turn off the power. And turn on the power.
- 2. Check the connection of the Fuser AC on FDB 2.
- 3. Check the Fuser control harness ①.
- 4. Check the resistance value of the thermostat. If the value is infinite, replace the thermostat.
- 5. If the problem persists, replace the Fuser unit.
- 6. Replace the SMPS board or FDB (Fuser drive board).



Code

• Error message

02-002

System Error:#02-002 Please turn off then on.

Symptom

The fuser unit is overheated. The machine does not work until power off/on. If the error code reoccurs, follow the "Troubleshooting method" below.

Possible Cause

The machine can not control fuser temperature.

• Troubleshooting method

- 1. Turn off the power. And turn on the power.
- 2. Replace the Fuser unit.
- 3. Replace the FDB.
- 4. Replace the Main-PBA.

Code

• Error message

02-005

System Error:#02-005 Please turn off then on.

• Symptom

The ADC port is short.

• Possible Cause

The machine can not control fuser temperature.

- 1. Turn the power off then on again.
- 2. If the problem persists, replace the Main PBA.

• Code	Error message
03-000	Motor error
	Error: #03-000
	Turn off then on

Motor Signal is abnormal.

Possible Cause

- 1. Harness is defective, Connector is not connected properly.
- 2. Main BLDC Motor is defective.
- 3. Main Board is defective.

- 1. Replace Harness if defective.
- 2. Replace the Main BLDC Motor if defective.
- 3. Replace the Main Board if defective.


• Code	• Error message
03-007	Motor error
03-008	
03-009	Error: #03-007/008/009
	Turn off then on

Motor Signal is abnormal.

Possible Cause

- 1. Harness is defective, Connector is not connected properly.
- 2. Color OPC BLDC Motor is defective.
- 3. Main Board is defective.

- 1. Check the motor connector. Reconnect the harness.
- 2. If the problem persists, replace the BLDC motor.
- 3. If the problem persists after replacing BLDC motor, replace the Main PBA.



• Code 03-015

• Error message

Motor error

Error: #03-015
Turn off then on


Symptom

Fan does not operate.

Possible Cause

Fan is defective.

- 1. Check the CN17 connector (FAN) on Main PBA.
- 2. If the FAN is defective, replace it.
- 3. If the problem persists, replace the Main PBA.



• Code	• Error message
04-001	LSU error: #04-001. Please turn off then on.
04-002	LSU error: #04-002. Please turn off then on.
04-008	LSU error: #04-008. Please turn off then on.

• Symptom

Laser beam detect signal has not occurred or is irregular.

LSU motor does not operate.

• Possible Cause

- 1. Harness is defective, Connector is not connected properly.
- 2. LSU is defective.
- 3. Main Board is defective.

• Troubleshooting method

- 1. Check the LSU connector on Main PBA. Reconnect it. If necessary, replace it.
- 2. If the problem persists, replace the LSU or Main PBA.



CN10/11 → LSU LD, Hsync Connector

CN15 → LSU Motor Connector

• Code	• Error message
08-000	Original paper Jam
08-001	Original paper jam inside of scanner. Remove Jam


• Symptom and Possible Cause

The lead edge of the document failed to actuate the Registration sensor within the predetermined time after initialization of Paper Pick up.


Possible Cause

- 1. Pick up roller is defective.
- 2. Scan sensor or actuator is defective.
- 3. Document paper path is contaminated.

- 1. Check the paper path for a small piece of paper that may have been torn from an original; or foreign materials such as paper clips, extracted staples, etc.
- 2. Check the condition of the Pick-up, Paper Feed Roller and DADF Rubber, it may have reached its PM interval.
- 3. Registration Sensor change
- 4. Registration Sensor drive Board change
- 5. Pick-up Solenoid change







• Code	• Error message
08-002	Original paper jam inside of scanner
08-006	


• Symptom and Possible Cause


The leadedge of the document has not reached to scan sensor after being sensed by the regi sensor.

Possible Cause


- 1. Gate sensor or actuator is defective.
- 2. Document paper path is contaminated.
- 3. WHITE BAR SHEET is not attached properly.
- 4. WHITE BAR is defective.

- 1. Check the paper path for a small piece of paper that may have been torn from an original; or foreign materials such as paper clips, extracted staples, etc.
- 2. Check that the White bar sheet is properly set to the guide.
- 3. Check and clean the Registration Roller, replace as is necessary.
- 4. Check and clean the Exit Roller, replace as is necessary.
- 5. Check and clean the Scan Senor for paper dust, replace as is necessary.
- 6. Check the signals from the Scan Sensor Drive Board, replace as is necessary.
- 7. Check and clean the Exit Solenoid, replace as is necessary.









• Code	• Error message
08-003	Original paper Jam
08-010	Original paper jam inside of scanner. Remove Jam


• Symptom and Possible Cause


At duplex scan, the leadedge of the document has not reached to the duplex sensor after scanning the front side.

Possible Cause


- 1. Duplex sensor or actuator is defective.
- 2. There is the contamination on paper path or a defective assembly.
- 3. The Duplex Gate does not work properly.
- 4. Duplex motor is defective.

- 1. Check and clean the Duplex Solenoid, replace as is necessary.
- 2. Check and clean the Exit Roller, replace as is necessary.
- 3. Check the signals from the DADF Drive Board, replace as is necessary.









• Code	• Error message
08-004	Original paper Jam
08-006	Original paper jam inside of scanner. Remove Jam


Symptom and Possible Cause


The bottom edge of the document failed to pass the scan sensor after the leadedge of the document has reached to the duplex sensor and scan sensor.

Possible Cause

- 1. Scan sensor or actuator is defective.
- 2. There is the contamination on paper path or a defective assembly.

- 1. Check the paper path for a small piece of paper that may have been torn from an original; or foreign materials such as paper clips, extracted staples, etc.
- 2. Check and clean the Registration Roller, replace as is necessary.
- 3. Check and clean the Exit Roller, replace as is necessary.
- 4. Check and clean the Scan Sensor for paper dust, replace as is necessary.
- 5. Check the signals from the Scan Sensor Drive Board, replace as is necessary.
- 6. Check and clean the Exit Solenoid, replace as is necessary.





08-008

Scanner door Open

Door of scanner is open. Close it

• Symptom

DADF door is opened.

• Possible Cause

The cover open sensor is defective.

• Troubleshooting method

Check if the DADF cover is closed.




<door is opened>



<door is closed>

If opened, close the DADF cover until it blocks the PHOTO-INTERRUPTER.



If UI message is not changed, open the COVER-DADF REAR and replace the PHOTO-INTTERRUPTER.

• Code	• Error message
11-003	Scanner locked
	Scanner locking switch is locked. Release it

• Symptom

Scanner locking switch is locked or Home checking is abnormal.


• Possible Cause

Scanner locking switch is locked.

• Troubleshooting method

Check if the scanner locking switch is locked.

If the scanner locking switch is locked, move the switch from $\ \textcircled{1}$ to $\ \textcircled{2}$.



• Code	• Error message
12-000	Paper mismatch Tray1/2
12-001	
	Load [A4] [Plain]
	Continue ⊙ Cancel X

The paper in tray1 and/or tray 2 does not match the size selected.

Possible Cause


- 1. Check that the size selected matches the copy paper in the tray selected.
- 2. Check the harness and connector of the Trya1/2 Size Sensor.
- 3. Tray1/2 Size Sensors and it operation.

• Troubleshooting method

- 1. Pull out Tray1/2 Cassette.
- 2. Load [Letter] paper in Tray1/2 Cassette.
- 3. Install Tray1/2 Cassette.

Check if Feed-Actuator works correctly.

- 1. Check the tension spring is properly loaded on the Actuator_Feed.
- 2. Check that the connector for the photo sensor is plugged in securely.



•	Code
1	2-004

Paper mismatch MP.

Load [A4] [Plain]
Continue ⊙ Cancel X


Symptom

The paper in Manual Tray does not match the size selected.

• Possible Cause

- 1. Check that the size selected matches the copy paper in the Manual Tray.
- 2. Check the harness and connector of the MP Size Sensor.
- 3. MP Size Sensor is defective.

- 1. Open MP Tray.
- 2. Load [Letter] paper in MP Tray.
- 3. If the problem persists, check if the MP_Paper_Detect_Actuator works correctly.
 - a. Check the spring is put in the right place of the actuator
 - b. Check the harness and the connector fit on the photo sensor.
 - c. Check the connection of the Drawer_MP and screw points.



• Code	Error message
18-000	Fax memory is almost full.
18-001	Fax memory is full. Print or remove received fax Job
18-002	Too many faxes are queued to be sent. Wait or remove queued job.
18-003	Too many faxes are received. Print or remove job

Cannot execute the Fax function.

Possible Cause

There is not enough fax memory.

• Troubleshooting method

1. "Fax memory is almost full." message case :

- 1) Check the printing condition of machine. (Toner or Paper of tray)
- 2) Even though the printing condition of machine is normal, if this message is displaying, check the Secure Receive option.

(Fax mode > Menu > Fax Feature > Secure Receive > Off)

3) Even though the option of Secure Receive is off, if this message is displaying, remove the job using the STOP button.

2. "Fax memory is full. Print or remove receive fax job." message case :

- 1) Check the printing condition of machine. (Toner or Paper of tray)
- 2) Even though the printing condition of machine is normal, if this message is displaying, check the Secure Receive option.

(Fax mode > Menu > Fax Feature > Secure Receive > Off)

3) Even though the option of Secure Receive is off, if this message is displaying, remove the job using the STOP button.

3. "Too many faxes are queued to be sent. Wait or remove queued job." message case :

- 1) Check the delayed Fax job. (Reserved delay send job)
- 2) If the number of reserved send jobs is reached Max Job Count, reservation of send job is denied.
- 3) So, remove the delayed job .

(Fax mode > Menu > Fax Feature > Cancel job)

4. "Too many faxes are received. Print or remove job." message case :

- 1) Check the printing condition of machine. (Toner or Paper of tray)
- 2) Even though the printing condition of machine is normal, if this message is displaying, check the Secure Receive option.

(Fax mode > Menu > Fax Feature > Secure Receive > Off)

3) Even though the option of Secure Receive is off, if this message is displaying, remove the job using the STOP button.


• Code	• Error message
21-002	Paper Empty in tray1
	Paper is empty in tray1. Load paper

There is the paper in tray1 but error message is displayed.

• Possible Cause

- 1. Tray1 empty sensor harness is not connected properly. .
- 2. Empty Sensor is defective.

- 1. Check the paper empty sensor connector. Reconnect it.
- 2. Check the paper empty sensor. If it is defective, replace it.
- 3. Check if the actuator is broken.



21-003

Tray 1 cassette is pulled out. Insert it properly

Symptom

Tray1 cassette is inserted in machine but error message is displayed.

• Possible Cause

- 1. The connector of the Tray1 Home Position Sensor is not connected properly.
- 2. Tray1 Home Position Sensor is defective.

• Troubleshooting method

- 1. Reinstall the tray1 cassette.
- 2. Reconnect the / Feed sensor harness.



3. Check the CST Draw connector. Reconnect it.



•	Code
2	1-010

Paper is empty in MP tray. Load paper


Symptom

There is the paper in MP tray but error message is displayed.

• Possible Cause

- 1. MP Paper Empty Sensor harness is not connected properly.
- 2. MP Paper Empty Sensor is defective.

- 1. Check the MP paper empty sensor connector. Reconnect it.
- 2. Check the MP paper empty sensor. If it is defective, replace it.
- 3. Check if the MP Empty actuator is broken.



21-018

Paper Empty in tray2 Paper is empty in tray2. Load paper

• Symptom

There is the paper in tray2 but error message is displayed.

• Possible Cause

- 1. Tray2 empty sensor harness is not connected properly. .
- 2. Empty Sensor is defective.

- 1. Check the paper Tray2 empty sensor connector. Reconnect it.
- 2. Check the paper Tray2 empty sensor. If it is defective, replace it.
- 3. Check if the Tray2 actuator is broken.






• Code	• Error message
21-019	Tray2 cassette is pulled out. Insert it properly

Tray2 cassette is inserted in machine but error message is displayed.

• Possible Cause

- 1. The connector of the Tray2 Home Position Sensor is not connected properly.
- 2. Tray2 Home Position Sensor is defective.

- 1. Reinstall the tray2 cassette.
- 2. Check the Tray2 Open micro sensor connector. Reconnect it.
- 3. Check the Tray2 Open micro sensor. If it is defective, replace it.



• Code	• Error message
28-001	Transfer belt is not installed. Install it.
28-002	Transfer belt is not compatible for this machine. Check user's guide.
28-003	

The red LED is turning on and the machine does not operate.

Possible Cause

The transfer belt unit is installed in the machine but the machine could not read the information from the CRUM. CRUM information is different from machine.

- 1. Check if transfer belt unit is properly installed.
- Check CRUM PBA connector pins.
 Replace the CRUM PBA with normal thing and test it. If the CRUM PBA is defective, replace the transfer belt unit or CRUM PBA.
- 3. Check if the Transfer Belt CRUM Harness is defective and check that the connector is properly plugged into the Engine Board.
- 4. Replace the Main Board with a known good one and test it. If it works replace Main Board.

