


Introduction

Thank you for your purchasing our U-WAVE-R.
The U-WAVE-R in conjunction with a Mitutoyo U-WAVE-T (available separately) allows wireless communication of the measurement data from Digimatic-output interfaced tool to load it to a personal computer for data display. Go through this Quick Manual to properly use the U-WAVE-R and U-WAVE-T.
Also for the proper use, be sure to go through both the “U-WAVE-R User’s Manual” and “U-WAVE-T User’s Manual”. After reading, keep this manual safely in place.

1. System Configuration

The U-WAVE is comprised of the following system components illustrated below.



2. Software Installation

2.1. Installing the U-WAVEPAK

The U-WAVEPAK contained in the supplied CD is software necessary for data communications between the U-WAVE-R and U-WAVE-T. Firstly, install the U-WAVEPAK in a personal computer.

CAUTION

- Log in to Windows by 'Administrator'.
- Do not connect the U-WAVE-R to a personal computer before completing the U-WAVEPAK installation.

Additionally, for details on U-WAVEPAK operation, refer to the “U-WAVEPAK User’s Manual” in the “PDF_Manual” folder in the supplied CD.
“Adobe Reader” of Adobe Systems Inc. needs to be installed to read the User’s Manual.
1) Boot a personal computer and load the supplied CD.
2) Using Windows Explorer or the like, run the “Setup.exe” in the “Setup” folder.
(For Windows Vista, press [Allow] button on “User Account Control”.)
(For Windows 7 / 8 / 8.1, press [Yes] button on “User Account Control”).

- 3) a) Select the language to be used.
b) Press the [OK] button.
- 4) “Welcome to the U-WAVEPAK Setup Wizard” will boot. Then, press the [Next] button.
- 5) Go through the “License Agreement” and select [I accept the agreement] if you agree, and press the [Next] button.
- 6) “Select Destination Location” appears. Then, press the [Next] button.
- 7) “Select Start Menu Folder” appears. Then, press the [Next] button.
- 8) a) Select “Create a desktop icon”.
b) Press the [Next] button.
- 9) “Ready to Install” appears. Then, press the [Install] button.
- 10) “Completion the U-WAVEPAK Setup Wizard” appears. Then, press the [Finish] button.
Now, the U-WAVEPAK installation is complete.

2.2. Driver Installation

Next, connect the U-WAVE-R to the personal computer and install the USB driver.
Procedures differ between Windows XP, Windows Vista(Windows 7 / 8 / 8.1) and Windows 2000. Follow procedures according to the personal computer used.

For Windows XP:

- 1) Connect the U-WAVE-R to the personal computer with a USB cable.
- 2) After a while, the following dialog will be displayed.
- a) Select “No, not this time”.
b) Press the [Next] button.
- 3) a) Select “Install from a list or specific location [Advanced].”
b) Press the [Next] button.
- 4) a) Select “Search for the best driver in these locations.”
b) Select “Include this location in the search.”
c) Press the [Browse] button.




- 5) After selecting C:\Program Files\Mitutoyo\UWAVEPAK\Drivers\CDM_U-WAVE\, press the [OK] button, and on the dialog in step 4), press the [Next] button.
- Press the [OK] button.
- 6) Although a warning about Windows XP logo authentication will appear, press the [Continue Anyway] button.
- 7) “Completing the Found New Hardware Wizard” will be displayed. Then, press the [Finish] button.
- 8) The dialog in step 2) will appear again. Then, repeat procedures 2) through 7).
Now, the driver installation is complete. Upon the completion of the driver installation, the green LED and red one on the U-WAVE-R blink alternately.

For Windows Vista, Windows 7 / 8 / 8.1:

- 1) Connect the U-WAVER-R to a personal computer with a USB cable.
- 2) For Windows Vista, after a while, the following dialog will be displayed.
- Press the [Cancel] button.
- 3) Open [Control panel]-[Hardware and Sound] of Windows.
- 4) Open [Hardware and Sound]-[Device Manager] of Windows.
- 5) Click [Other devices].
Point the cursor to [Mitutoyo U-WAVE].
Right-click in the mouse and select [Update Driver Software].
- If [Mitutoyo U-WAVE] or [USB Serial Port] is not displayed in [Other devices], the device driver has already been installed.
Therefore, close [Device Manager] and end the installation of the device driver.
- 6) Select “Browse my computer for driver software”.
- 7) Press the [Browse] button.
- 8) Select C:\Mitutoyo\UWAVEPAK\Drivers\CDM_U-WAVE\, press the [OK] button, and then press the [Next] button on the dialog in step 7).
- Press the [Install] button.
- 10) Then, press the [Close] button after ending the installation.
- 11) The dialog of 5) is displayed again.
- Click [Other devices].
Point the cursor to [USB Serial Port].
Right-click in the mouse and select [Update Driver Software].


And, re-operate from 6) to 10).
Now, driver installation is complete. Upon the completion of the driver installation, the green LED and red one on the U-WAVE-R blink alternately.

For Windows 2000:

- 1) Connect the U-WAVER-R to a personal computer with a USB cable.
 - 2) After a while, “Welcome to the Found New Hardware Wizard” will appear. Then, press the [Next] button.
 - 3)  a) Select “Search for a suitable driver for my device [recommended].”
b) Press the [Next] button.
 - 4)  a) Select “Specify a location”.
b) Press the [Next] button.
 - 5)  Press the [Browse] button.
 - 6) Select C:\Program Files\Mitutoyo\UWAVEPAK\Drivers\CDM_U-WAVE\, press the [Open] button, and then press the [OK] button on the dialog in step 5).
- 
- 7) “Driver File Search Results” will appear. Then, press the [Next] button.
 - 8) “Completing the Found New Hardware Wizard” will appear. Then, press the [Finish] button.
 - 9) The dialog in step 2) appears again. Then, repeat steps 2) through 8).
Now, driver installation is complete. Upon the completion of the driver installation, the green LED and red one on the U-WAVE-R blink alternately.

3. Setup
3.1. U-WAVE-T Setup


- Use the 0-size screwdriver, a standard accessory of the U-WAVE-T, to mount and remove screws and fasten them with a torque of about 5-8N•cm.
- Battery setting**
- 1) Remove the set screws on the rear of the U-WAVE-T and remove the battery lid.
 - 2) With the plus side of the battery facing toward the lid, insert the battery edge into the “+” battery terminal of the U-WAVE-T and slide the other side of the battery into the battery retaining lug.
 - 3) Ensure that the battery lid packing (circular type) is fitted in place.
 - 4) Replace the battery lid into position and fix it by tightening screws.



Connecting the connecting cable

CAUTION


When connecting a connecting cable to the U-WAVE-T, ensure that the black marked connector of the connecting cable is connected to the U-WAVE-T.



Measuring tool side
(The connector differs in shape and color depending on the measuring tool to be mated.)

U-WAVE-T side

- 1) Remove the connector cover set screws of the U-WAVE-T and take off the connector cover.
- 2) Ensure that a packing is fitted in place in the connector.
- 3) Connect the connecting cable to the U-WAVE-T.
- 4) Holding the edges of the connecting cable down by the fingers and ensuring that there will be no gap between the lid and the main body, fasten them with screws.
- 5) Put the removed connector cover and screws in place for safekeeping.




Now, the U-WAVE-T setup is complete.

3.2. U-WAVE-R Setup


- Next, set up the U-WAVE-R with the UWAVEPAK.
- 1) Connect the U-WAVE-R to a personal computer with a USB cable.
The green LED and red one on the U-WAVE-R blink alternately.
 - 2) Boot the UWAVEPAK with the desktop icon.
 - 3) “Driver for Virtual COM port” will appear. Then, press the [OK] button.




- 4) The U-WAVEPAK menu dialog appears.



- 5) “Confirm processing” will appear. Then, press the [Yes] button.
- 6) After a while, the following dialog will be displayed.





- 7) “Confirm processing” will appear. Then, press the [Yes] button.
- 8) After a while, the following setup dialog will be displayed and the green LED on the U-WAVE-R lights up. Now, the U-WAVE-R setup is complete.




3.3. U-WAVE-T Information Registration


Proceed to register the U-WAVE-T information in the U-WAVE-R.



- 3) “Confirm processing” will appear. Then, press the [Yes] button.




- 4) Press the DATA switch on the U-WAVE-T already set up.
(After blinking in orange color, the U-WAVE-T blinks in green upon connection.)
Please connect the DATA switch pushing long (Push-down time: 5sec <t, Orange blinking 0.3 sec interval) when it is not possible to communicate and red blinks.



- 5) Connect the measuring tool to be used to the U-WAVE-T.

6) Press the DATA switch on the U-WAVE-T with the measuring tool in counting state.



Here, the measurement data is indicated as “DT1 00 00 +0000010.000M”.

Group ID | Measured data
Channel

Whether data transmission has been properly performed to the U-WAVE-R can be confirmed by the LED (buzzer) of the U-WAVE-T. The LED (buzzer) status implies as follows.

Information	LED	Buzz (only with buzzer type)
Wireless transmission completed properly	Green LED blinks	Buzzes shortly twice
·Wireless transmission failed. ·Error occurred.	Red LED blinks.	Buzzes long once.


CAUTION

- Log in to Windows by 'Power Users' or above.
- The green LED blinks on the U-WAVE-T if communication has been made properly with the U-WAVE-R on which the green LED stays on even without having booted the U-WAVEPAK.


Now, information registration is complete, allowing wireless communication to be performed.

4. Measurement Data Input Into Microsoft Excel

Proceed to input the measurement data into Excel from a measuring tool.

1) 

Press the [Exit setup] button.

2) 

Press the [Data I/F start] button.

3) 

"U-WAVEPAK Data I/F" contained in Windows task bar will boot.

4) Boot Microsoft Excel.


5) Measurement data input takes place as shown below at the press of the DATA switch.



6) To exit, click “U-WAVEPAK Data I/F” after saving the measured data.




Click “U-WAVEPAK Data I/F” to display the “Data I/F” dialog.

7) 

a) Press the “Stop data I/F” button.

b) Press the “Exit data I/F” button.

8) 

Press the [Exit] button to exit the U-WAVEPAK.


CAUTION

The U-WAVEPAK automatically transmits the measurement data to the active application software (such as Microsoft Excel or Microsoft Word). Before booting multiple application software simultaneously, be sure to activate Microsoft Excel.

5. Inputting Measurement Data into the Specified Cell of Microsoft Excel

Measurement data input into the specified cell is possible by using the data collection macro appended to the U-WAVEPAK. Here is how to input measurement data into the specified cells from two units of U-WAVE-T using this macro.


1) Firstly, register the two units of U-WAVE-T in the U-WAVE-R referring to section 3.3.




U-WAVE-T Setup

	No.	Channel	Group ID	Device ID
Measuring tool A	1	00	00	0000000001
Measuring tool B	2	01		0000000002

- 2) Press the [Exit setup] button.
- 3) Press the [Exit] button in the U-WAVEPAK menu dialog to exit the U-WAVPAK.
- 4) Boot [Data Collection Macro for U-WAVE] from Windows programs menu.
- 5) Press [Data File] and select [Data Input].




6) “NEWUW.RPX” will open. Press [Data Input] and select [Edit].



The “Measure mode” and “Edit mode” are in the measurement data input screen. The mode selected is identified here.

7) Specify in the “Edit Mode” the cell into which data input is made for each channel of the U-WAVE-T.




The following editing is possible in the “Edit Mode”.

- Comments editing
- Nominal data editing
- Upper/lower tolerance value editing

Here, edit a table which allows measurement data to be input as shown below.

	Measurement item 1	Measurement item 2	Measurement item 3	Measurement item 4	Measurement item 5	Measurement item 6
Work-1						
Work-2						
Work-3						
Work-4						
Work-5						
Work-6						

8) Press [Data Input] and select [Edit Sheet]-[Delete Input Area Size].




9) Delete


a) Enter the column/row number to be deleted.

b) Press the [OK] button.

10) Press [Data Input] and select [Data Collection Configuration].




Items 7 and 8 and Work-7 and -8 will be deleted from measurement items and work labels, respectively.

11) 

a) Select “Grouping Items and Specify Each Group”.

b) Press the [OK] button.


12) Set in the “Item Assign Table” the group IDs and channel, and then press the [OK] button.



Measuring tool A assignment


Measuring tool B assignment

13) Press [Data Input] and select [U-WAVE Port]-[Open Port].




14) “Driver for Virtual COM port” appears. Then, press the [OK] button.

15) Click “U-WAVEPAK Data I/F” to display the “Data I/F” dialog.

16) 

a) Press the [Stop data I/F] button.

b) Press the [Environment] button.


17) 

a) Select “ENTER”.

b) Select “All data”.


c) Select “Collects”

d) Press the [OK] button.

18) 

Press the [Start data I/F] button.

19) The system turns into the “Data collection” state, allowing measurement data to be collected as shown below.



Measuring tool B data


Measuring tool A data

Red cells indicate “Tolerance judgment: NG” and green ones indicate “Tolerance judgment: GO”.

20) To quit, press [Data Input] and select [U-WAVE Port]-[Close Port]. Proceed to press [Data Input] and select [Return to File Menu] from the menu.

21) Select [Save Data File(RPX)] from [Data File].

22) Enter a desired file name (RPX) and press the [Save] button.



23) Quit the data collecting macro by selecting [Exit this program] from [Data File].

For detailed procedures of “Data Collection Macro”, refer to the “U-WAVEPAK User’s Manual” in the “PDF_Manual” folder contained in the supplied CD.

“Adobe Reader” supplied by Adobe Systems Inc. is required to view the manual.

6. Communication over the Virtual COM Port

With the connection of the U-WAVE-R to a personal computer, a virtual COM port appears allowing the U-WAVE-R to be used as an RS-232C interfaced device connected to an ordinary COM port is used.


Here is how to communicate with the PC’s Hyper Terminal over the virtual COM port.

1) Boot the U-WAVEPAK with the desktop icon.

2) 

a) Select “Use the driver for Virtual COM port.”

b) Press the [OK] button.

3) 


a) Select the COM port of the U-WAVE-R.

b) Press the [Add] button.

c) “COMXX,57600,0,8,1,1” appears.

d) Press the [OK] button.

4) Press the [Setup start] button on the U-WAVEPAK menu dialog.

5) 

a) Confirm the COM port No. of the U-WAVE-R.

b) Press the [Exit setup] button.

6) Press the [Exit] button on the U-WAVEPAK menu dialog to exit the U-WAVEPAK.

7) Boot [Hyper Terminal] from Windows programs menu.




a) Enter a desired “Name”.

b) Press the [OK] button.

8) 

a) Select the COM port No. confirmed in step 5).

b) Press the [OK] button.

9) 

a) Set up the port according to the table below.

b) Press the [OK] button

Bits per second	57600
Data bits	8
Party	None
Stop bits	1
Flow control	Hardware

10) The system turns into the Communication state, showing measurement data as in the figure below.

