Date: July 17, 2009 No. B-2048



## **Service Bulletin**

Ariens Company 655 W. Ryan St. Brillion, WI 54110 www.ariens.com

Product Family: 917001 27-Ton Log Splitter

**Subject: Wedge Mounting Hardware Replacement** 

**Dealer Action: Install New Mounting Bolts** 

Model	Serial Number Range	Description
917001	000101 - 000611; 000622; 001004 - 001005; 001027; 001058; 001073; 001090; 001092 - 001096; 001098; 001113 - 001114; 001134; 001153; 001170	27-Ton Log Splitter

The Ariens Company has learned that the splitting wedge mounting bolts on the model 917001 27-Ton Log Splitter may fail under extreme loads. Replacing the two existing .38-16 hex bolts closest to the cylinder with two .50-13 x 2 Grade 8 hex bolts (p/n 05970700), two .563 x 1.38 x .109 flat steel washers (p/n 06442000), and two .50-13 center lock nuts (p/n 06536300) reduces the potential for failure under such loads.

Before putting into service any 917001 27-Ton Log Splitter in the above-listed serial number ranges, replace the two.38-16 hex bolts closest to the cylinder as indicated in the illustration on page two with two .50-13 x 2 Grade 8 hex bolts (p/n 05970700), two .563 x  $1.38 \times .109$  flat steel washers (p/n 06442000), and two .50-13 center lock nuts (p/n 06536300). For units in these serial number ranges already sold to end users, contact the customer and replace the hardware at the customer's earliest convenience.

Only the units in the serial numbers listed above need to have hardware replaced. All other units will have had this change made before shipping from Ariens.

Dealers should file a warranty claim for each log splitter they service, using flat rate code 17900. Dealers will be reimbursed for 0.25 hours of labor at their standard posted shop labor rate.

Refer to the illustration on page 2 for hardware location and installation instructions.

