

**Electronic Total Station** 

R-300 SERIES

R-315(N)/R-325(N)/R-335(N)/R-322(N)/R-323(N)/R326

**Special Functions** 

**PSF Software Ver.365** 

**PENTAX Industrial Instruments CO., Ltd.** 

Document Ver. 1.10

## Copyright

Copyright © 2002 PENTAX Industrial Instruments Co., Ltd.

All Rights Reserved

PENTAX Industrial Instruments Co., Ltd. is a sole proprietor of the PSF software.

The PSF software and publication or parts thereof, may not be reproduced in any form, by any method, for any purpose.

PENTAX Industrial Instruments Co., Ltd. makes no warranty, expressed or implied, including but not limited to any implied warranties or merchantability or fitness for a particular purpose, regarding these materials and makes such materials available.


Document Ver.1.10: July 2004

Before using this product, be sure that you have thoroughly read and understood this instruction manual to ensure proper operation. After reading this manual, be sure to keep in a convenient place for easy reference.

# **Display and Keyboard**

The display and keyboard of the R-300 series are described below.

٠



# **Operation Keys**

Key	Description	
POWER	ON/OFF of power supply	
[ESC]	Returns to previous screen or cancels an operation.	
Illumination	Turns the illumination of the LCD display and telescope reticle on and off.	
[ENT]	Accepts the selected , hilighted, choice or the displayed screen value.	
[Laser]	Displays the laser plummet *1, Electronic vial function, and the LD point screen when you push the laser plummet/electronic vial key.  (Refer to "2-5 LD POINT", "3-2 Laser plummet", and "3-5 Leveling with Electronic vial").  *1:Only the product with the Laser plummet function	
Alphanumeric	At the numerical value screen, the numerical value and the sign '.' displayed are input. The English characters printed right under numeric of each key are input.	
[HELP]	Pressing [ILLU]+[ESC] key causes a help menu to appear in A MODE or B MODE or causes a help message to appear.	

## **Function Keys**

Display	F Key	Description	
Mode A		•	
[MEAS]	F1	Pressing this key one-time measures the distance and measurement type can be	
		selected by Initial Setting 2.	
[MEAS]	F1	Pressing this key twice measures the distance and another measurement type	
		can be selected by Initial Setting 2.	
[TARGET]	F2	Select whether the target is SHEET/PRISM/REFRECTORLESS.)	
[0 SET]	F3	Resets the horizontal angle to 0° 0′ 0″ by pressing twice.	
[DISP]	F4	Toggles the display composition in the order "H.angle/H.dist./V.dist.",	
IMAGE!		"H.angle/V.angle/S.dist.", and "H.angle/V.angle/H.dist./S.dist./V.dist".	
[MODE]	F5	Toggles the screen between MODE A and MODE B.	
Mode B	1		
[S.FUNC]	F1	PSF Special Functions	
[ANG	F2	Brings up the angle setting screen for setting angle-related parameters	
SET]		(ANGLE, %GRADE, H.ANGLE INPUT and R/L REVERSE).	
[HOLD]	F3	Pressing this key twice retains (holds) the horizontal angle shown on the display.	
[CORR]	F4	Brings up the screen for changing the Target constant, Temperature, Pressure setting	
[MODE]	F5	Toggles the screen between MODE A and MODE B.	
Other functions			
[ ]	F1	Moves the cursor to the left.	
[ ]	F2	Moves the cursor to the right.	
[ ]	F1	Goes back five Items on the screen	
[ ]	F2	Goes forward five items on the screen.	
RETICLE	F3	Changing the Reticle illumination when pressing Illumination key	
[ ]	F3	Moves the cursor up	
LCD	F4	Changing the LCD contrast when pressing Illumination key	
[ ]	F4	Moves the cursor down	
ILLU	F5	Changing the LCD illumination when pressing Illumination key	
[CLEAR]	F5	Clears the figure	
[SELECT]	F5	Opens the selection window	

### **Alphanumeric Input**

The point name is inputted by the Alphanumeric keys as following.

Key	Letter under Key	Letter & Figure sequential order to input
[ 0 ]		[@][.][_][-][:][/][0]
[1]	PQRS	[P][Q][R][S][p][q][r][s][1]
[2]	TUV	[T][U][V][t][u][v][2]
[ 3 ]	WXYZ	[W][X][Y][Z][w][x][y][z][3]
[4]	GHI	[G][H][I][g][h][i][4]
[ 5 ]	JKL	[J][K][L][j][k][1][5]
[ 6 ]	MNO	[M][N][O][m][n][o][6]
[7]		[ ][?][!][_][ ][^][ ][&][7]
[8]	ABC	[A][B][C][a][b][c][8]
[ 9 ]	DEF	[D][E][F][d][e][f][9]
[ • ]		[.][,][:][;][#][(][)]
[+/-]		[+][-][*][/][%][=][<][>]

### **Memories in the Instrument**

This instrument incorporates not only 8 measuring programs but also a MEMORY MANAGER program as special functions and so it can receive and record Coordinates data and surveying

data of maximum 7500 points.

# Relations between memories and each Special function

Special Function	Memory	Data to be read	Data to be stored
DATA STORAGE	Yes	Job name	Job name, Station P.*1Measured P.*1
COORDINATES	Yes	Job name, Station P.*2 Backsight P.	Job name, Station P.*2 Backsight P., Measured P.*2
COORD. STAKEOUT	Yes	Job name, Station P.*2 Backsight P., Stakeout P.	Job name, Station P.*2 Backsight P., Stakeout P.
OFFSET SHOTS	Yes	Job name, Station P.*2 Backsight P.	Job name, Station P.*2 Backsight P., Target P.
RESECTION	Yes	Job name, Known P. A,B,C	Job name, Station P.*2 Known P. A,B,C
RDM			
REM			
DISTANCE STAKEOUT			
MEMORY MANAGER	Yes	(Yes)	(Yes)

## **Each data contents**

Station P.*1	Station P. No. Description Instrument H. Target C.		
	Temperature Pressure ppm Correction value		
Station P.*2	P. No. Coordinate Description		
Backsight P.	P. No. Coordinate Description		
Stakeout P.	P. No. Coordinate Description		
Target P.	P. No. Coordinate Description		
Known P.	P. No. Coordinate Description		
Measured P.*1	P. No. Prism H. H. Angle V. Angle S. Distance Description		
Measured P.*2	P. No. Coordinate Description		

# **CONTENTS**

# Copyright

# **Display and Keyboard**

## **Memories in the Instrument**

### Relations between memories and each function

1 INTRODUCTION 1-1 INTRODUCTION 1-2 BEFORE USING THE PSF MANUAL	7 7 7
2 ACCESSING THE SPECIAL FUNCTIONS 2-1 ACCESSING BY SPECIAL KEY 2-2 ACCESSING BY HELP KEY 2-3 ACCESSING BY 007	8 8 9 10
3 COORD. STAKEOUT  General pictures of measurement Detailed Operating procedures  1. JOB NAME  2. STATION SETUP  3. STAKEOUT	11 11 12 12 14
4 DISTANCE STAKEOUT General pictures of measurement Detailed Operating procedures	19
<b>5 RDM</b> General pictures of measurement Detailed Operating procedures	23 23 24
6 COORDINATES General pictures of measurement Detailed Operating procedures 1. JOB NAME 2. STATION SETUP 3. SURVEY	25 25 26
7 OFFSET SHOTS General pictures of measurement Detailed Operating procedures 1. JOB NAME 2. STATION SETUP 3. SURVEY	27 27 27 27 28 30
8 REM General pictures of measurement Detailed Operating procedures	31 31 32 32
	32 34

#### **PSF Software Ver.365**

General pictures of measurement Detailed Operating procedures 1. JOB NAME 2. STATION SETUP 3. SURVEY	
10 DATA STORAGE General pictures of measurement	40
General picture	40 40
1. JOB NAME	40
2. STATION SETUP 3. SURVEY	41
0. 00KV21	41
11 MEMORY MANAGER	
Detailed Operating procedures	
1. COORDINATES SEND 2. COORDINATES RECEIVE	42
3. COORDINATES RECEIVE  3. COORDINATES EDIT	42
4. COORDINATES DELETE	42
5. SURVEY DATA SEND	43
6. SURVEY DATA EDIT 7. SURVEY DATA DELETE	44
1. SONVET DATA DELETE	44 45
12 DataLink DL- 01 Software	45 46
	40
	47

9 RESECTION

# 1 INTRODUCTION

#### 1.1 INTRODUCTION

Thank you for your first looks at PSF by reading this manual. The PSF is a user friendly data collection and calculation program for the PENTAX total station R-300 series.

The PSF is developed based on the PCS-300 Special functions, which is known as versatile on-board software for PENTAX PCS-300 total station series. The optimum combination of PCS-300 and R-300 hardware makes PSF as an easy and useful fieldwork tool. The main menu offers you the following possibilities.

- COORD, STAKEOUT
- DISTANCE STAKEOUT
- RDM
- COORDINATES
- OFFSET SHOTS
- RFM
- RESECTION
- DATA STORAGE
- MEMORY MANAGER

#### 1.2 BEFORE USING THE R-300 PSF software MANUAL

- The PSF manual mainly describes the R-300 special functions, and the basic operations are described in the (basic) R-300 manual. And, therefore, refer to the R-300 basic manual regarding the R-300 general instrument operations.
- Before performing PSF functions, select the Target type, "Reflector Sheet" or "Prism" or "Reflectorless".
- General pictures of measurement:
  - This illustrates the content of the program.
- Detailed Operating procedures:
  - This describes the actual detailed operating procedures. Since detailing the Operating procedures of each program would cause unnecessary complexity, this manual shows detail for "Coordinate Stakeout Measurement" only, as an example.
  - Descriptions of the other programs are simplified. The guide messages, however, of each step of the operation help you to proceed in a proper manner for the other programs. We are confident, therefore, that you will be able to use the other application programs once you're familiar with the operation of "Coordinate Stakeout Measurement" program.
- Press the keys, which are drawn by the index finger.
- For further information, please contact your local Pentax Authorized dealer.

# **2 ACCESSING THE SPECIAL FUNCTIONS**

### 2-1 ACCESSING BY SPECIAL KEY

**Example: COORD. STAKEOUT** 

Press the [S.FUNC] key at mode B. (Mode A must be changed to mode B by pressing the [MODE] key.)	Pentax Special Function  1.DATA STORAGE 2.COORDINARES 3.COORD.STAKEOUT 4.OFFSET SHOTS 5.RESECTION
Move the cursor to <b>3.COORD.STAKEOUT</b> by pressing $[\Delta]$ , $[\nabla]$ or $[\uparrow]$ , $[\downarrow]$ key.	Pentax Special Function  1.DATA STORAGE 2.COORDINARES 3.COORD.STAKEOUT 4.OFFSET SHOTS 5.RESECTION
The COORD.STAKEOUT can be accessed by pressing the [ENT] key.	COORD.STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT

Other Pentax Special Function are:

#### **Pentax Special Function**

- 5. RESECTION
- 6. RDM
- 7. REM
- 8. DIST STAKEOUT
- 9. MEMORYMANAGER

### **2 ACCESSING THE SPECIAL FUNCTIONS**

# 2-2 ACCESSING BY HELP KEY


**Example: COORD. STAKEOUT** 

Press the [ESC] key while pressing the [ILLU] at mode A or B.  The HELP menu is displayed.	HELP  2.401 TARGET CONST 3.402 ATM CORR : AUTO 4. 501 MEAS.MIN DISP: COARSE. 5. 502 SHOT COUNT  SELECT
2	HELP
Move the cursor to <b>28. COORD.STAKEOUT</b> by pressing $[\Delta]$ , $[\nabla]$ or $[\uparrow]$ , $[\downarrow]$ key.	28. 109 COORD. STAKEOUT 29. 112 REM 30. 113 RESECTION 31. 119 DATA STORAGE 32. 200 MEMORY MANAGER SELECT
3	
The COORD. STAKEOUT can be accessed by pressing the [SELECT] at F5 key.	COORD.STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT

#### **2 ACCESSING THE SPECIAL FUNCTIONS**

### 2-3 ACCESSING BY 007

**Example: COORD. STAKEOUT** 



### **The PSF Command No. list**


Special Functions	007 Command
Distance Stakeout	101
RDM	103
Coordinates	104
Offset Shots	105
Coord. Stakeout	109
REM	112
Resection	113
Data Storage	119
MEMORY MANAGER	200

# 3 COORD, STAKEOUT


### **General pictures of measurement**

With COORD. STAKEOUT measurement, "Stakeout point coordinates" can be staked out in 3 dimensions based on the known "Station point coordinates" and the "Backsight point coordinates or Backsight point azimuth". The horizontal angle, horizontal distance and vertical distance to the stakeout point are automatically calculated as design values, and the differences between the measured values and design values are displayed as deviations. When the coordinate values of the Station point, Backsight point and Stakeout point are recorded on the instrument memory, designation of each measured point number makes it possible to omit the each time coordinates value input.

### **General pictures**



# **Design values and deviation**



#### 3 COORD. STAKEOUT

## **Detailed Operating procedures**

Access the COORD. STAKEOUT according to the "1. ACCESSING THE SPECIAL FUNCTIONS".

# 1. JOB NAME

### (1) JOB NAME input

Press the [ENT] key to view COORD. STAKEOUT screen.	COORD.STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT
Press the [ENT] key to view JOB NAME INPUT screen.  Press the [ENT] key to view JOB NAME screen.	JOB NAME INPUT  1.
Input the <b>JOB NAME</b> "XXXX" by pressing the <b>Alphanumeric keys and arrow key</b> .	JOB NAME  XXXX  BS CLEAR TO 123
Press the [ENT] key to enter.	STATION NUMBER LIST  1. 000 :

- Maximum 15 letters can be inputted on the JOB NAME input.
- When the same JOB NAME is already stored, the stored one is displayed after
  pressing the [ENT] key at the Operating procedure 3. "The same job name is
  found" is displayed.

### 3 COORD. STAKEOUT

# (2) JOB NAME selection

Press the [ENT] key.	COORD. STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT
2 For example, stored "3.BBBB" is selected.	JOB NAME INPUT  1. 2. XXXX 3. BBBB 4. CCCC 5. DDDD
Move the cursor to " <b>3. BBBB</b> " by pressing the [ $\Delta$ ], [ $\nabla$ ], [ $\uparrow$ ], [ $\downarrow$ ] keys and press the [ENT] key.	
Press the <b>[ENT]</b> key to enter.	JOB NAME INPUT  1. : 2.AAAA 3.BBBB 4. CCCC 5. DDDD
	COORD. STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT

● The **JOB NAME selection** is possible only when some **NAME** are already stored.

# 2. STATION SETUP

# (1) Station Coordinates

## a. Station Coordinates input

Move the cursor to 2. STATION SETUP.	COORD.STAKEOUT  1. JOB NAME  2. STATION SET UP  3. STAKEOUT
Press the [ENT] key to view the STATION NUMBER LIST screen.	STATION NUMBER LIST  1. 0000
Press the [ENT] key to view the POINT NUMBER screen.  For example "1234" is inputted.  Input the "1234" by pressing the numerical keys.	POINT NUMBER  1. 1234  CLEAR

### 3 COORD. STAKEOUT

STATION COORDINATES INPUT           2.DESCRIPTION :         3.X COORD. : 000000.000m           4.Y COORD. : 000000.000m         5.Z COORD. : 000000.000m           6.INST. H : 00.000m           STORE         SELECT
STATION COORDINATES INPUT
X COORD.
2.DESCRIPTION : 3.X COORD. : 000000.000m 4.Y COORD. : 000000.000m 5.Z COORD. : 000000.000m 6.INST. H -123456.890 m
CLEAR
STATION COORDINATES INPUT
STATION COORDINATES INPUT

The BACKSIGHT SELECTION screen is viewed.

BACKSIGHT SELECTION

1. COORDINATES INPUT

2. FORESIGHT COORD. (AZIMUTH) INPUT

- Articles marked by \* are not changed.
- **DESCRIPTION** input: Press the **[SELECT]** key, and input letters or marks.
- Maximum 8 letters can be inputted at the "DESCRIPTION".

### b. Search and call of the stored Station Coordinates

1	
Move the cursor to 2 STATION SETUP.	COORD.STAKEOUT  1. JOB NAME  2. STATION SET UP  3. STAKEOUT
Press the [ENT] key to view the STATION NUMBER LIST screen.	1. 0000 2. 1234 3. 0564 4. 0678
3 Stored "1234" is searched for example. Move the cursor to "2. 1234" by pressing the $[\Delta], [\nabla], [\uparrow], [\downarrow]$ keys and press the <b>[ENT]</b> key to view the <b>INSTRUMENT HEIGHT INPUT</b> screen. Pre-stored data in the Coordinate memory is displayed.	STATION NUMBER LIST

Confirm the called STATION P.
COORDINATES and then press the [ENT] key.
When the INSTR. H. change is needed, change the height value, and press the [ENT] key to view the BACKSIGHT SELECTION screen.

BACKSIGHT SELECTION

1. COORDINATES INPUT
2.FORESIGHT COORD.(AZIMUTH) INPUT

### (2) Backsight Selection

# a. Coordinates input

### ■ The Backsight Point Number and Coordinates input

1	
BACKSIGHT SELECTION	
1. COORDINATE 2.FORESIGHT C	S INPUT OORD.(AZIMUTH) INPUT
2	BACKSIGHT NUMBER LIST
Push the [ENT] key at "1.COORDINATES INPUT".	1. 0000
BACKSIGHT NUMBER LIST screen is viewed.	
3	POINT NUMBER
Press the <b>[ENT]</b> key to view the <b>POINT NUMBER</b> screen.	1. 0025
Input the <b>Backsight point number</b> according to the STATION P.NUMBER input.	CLEAR
Press the <b>[ENT]</b> key to view the <b>BACKSIGHT COORDONATES INPUT</b> screen.	

Input the Backsight Coordinates according to the COORDINATES input.	BACKSIGHT COORDONATES INPUT  1. POINT No. * 0025  2.DESCRIPTION : 3.X COORD. : -xxxxxx.xxx m 4.Y COORD.
Press the [ENT] key to view the FORESIGHT NUMBER LIST screen after aiming at the Backsight Point.	BACKSIGHT AIMING  After aiming the Backsight Point, push the ENT.
6	FORESIGHT NUMBER LIST  1. 0000 2. 1234 3. 0025

Maximum 4 digits can be inputted on the Backsight number input.

# ■ Search and Call of the stored Backsight Point Number

Press the [ENT] key on 1 COORDINATES INPUT to view the BACKSIGHT NUMBER LIST screen .	BACKSIGHT SELECTION  1. COORDINATES INPUT 2.FORESIGHT COORD.(AZIMUTH) INPUT
Move the cursor to your desired Backsight Point Number.	BACKSIGHT NUMBER LIST  1. 0000 2. 1234 3. 0025
Confirm the Backsight Point Coordinates and press the [ENT] key.  After aiming at the Backsight Point, push the [ENT] key to view the FORESIGHT NUMBER LIST screen.	BACKSIGHT AIMING  After aiming the Back Sight Point, push the ENT

4	FORESIGHT NUMBER LIST
	1. 0000 2. 1234 3. 0025

# b. Azimuth angle input


Move the cursor to 2. FORESIGHT COORD. (AZIMUTH) INPUT and press the [ENT] key, and go to the Operating procedures 2 of 3. STAKEOUT.	1. COORDINATES INPUT 2.FORESIGHT COORD.(AZIMUTH) INPUT
	FORESIGHT NUMBER LIST  1. 0000 2. 1234 3. 0025

# 3. STAKEOUT

## (1) Input and Stakeout of Foresight Point Number and Coordinates


Move the cursor to 3. STAKEOUT.	COORD. STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT
Press the [ENT] key.	FORESIGHT NUMBER LIST  1. 0000 2. 1234 3. 0025

<sup>■</sup> The Azimuth angle input is performed at the Operating procedures 1) - 3) of BACKSIGHT SELECTION screen in 3. STAKEOUT.



### "BACKSIGHT SELECTION" screen explanation:

- Go to Input or Call of BACKSIGHT NUMBER LIST in case of 1. COORDINATES INPUT selection of the BACKSIGHT SELECTION screen.
- Go to the Operating procedures 2. FORESIGHT NUMBER LIST of 3. STAKEOUT in case of 2. FORESIGHT COORD. (AZIMUTH) INPUT selection of the BACKSIGHT SELECTION screen.



#### **PSF Software Ver.365**

3) Press the [ENT] key.	ANGLE COMPARE  DESIGN 90° 00' 00"  H.angle 0° 00' 00"  DEVIATE - 90° 00' 00"  H.INPUT 0 SET ANG/DIST
Rotate the instrument horizontally and stop it where the displayed <b>DEVIATE</b> becomes <b>0</b> and fix the horizontal rotation.	ANGLE COMPARE  DESIGN 90° 00' 00"  H.angle 90° 00' 00"  DEV.IATE 00° 00' 00"  H.INPUT 0 SET ANG/DIST
7 Press the [ANG/DIST] at F4 key.	DIST. COMPARE  H.dst DESIGN 360.555 m Z coord.DESIGN 0.000 m H.dst DEVIAT Z coord.DEVIAT S.dst  MEAS TRACK TARGET ANG/DST
Move the prism toward the aiming direction of a telescope, and press the [TRACK] at F2 key and aim at the prism.	DIST. COMPARE  H.dst DESIGN 360.555 m Z coord. DESIGN 0.000 m H.dst DEVIAT -2.835 m Z coord. DEVIAT -0.242 m S.dst 378.452 m  MEAS TRACK TARGET ANG/DIST
The DEVIATE value approaches to 0, and then press the [MEAS] at F1 key. Find a place where the DEVIATE value becomes <b>exactly 0</b> , and the place is the STAKEOUT POINT. The STAKEOUT of the first STAKEOUT POINT is completed.	H.dst DESIGN 360.555 m Z coord. DESIGN 0.000 m H.dst DEVIAT 0.000 m Z coord. DEVIAT 0.000 m S.dst 378.452 m  MEAS TRACK TARGET ANG/DST
Press the <b>[ENT]</b> key. The <b>Stakeout</b> of the second or third Stakeout point is performed in the same way.	FORESIGHT NUMBER LIST  1. 0000

#### **PSF Software Ver.365**

- At the procedure 6, the 00" of the DEVIATE.value can be easily got if the minimum count is set to 1 ".
- At the procedure 8, a prism can be easily tracked if a position is searched using the [TRACK] function and then using the [MEAS] function.

## (2) Search and Call of the stored Foresight Point Number


Move the cursor to 3. STAKEOUT	COORD.STAKEOUT  1. JOB NAME 2. STATION SET UP 3. STAKEOUT	
Press the [ENT] key.	FORESIGHT NUMBER LIST  1. 0000 2. 1234 3. 0025	
3 Search for the desired Foresight point number.		
Confirm the called Foresight Coordinates and press [ENT] key. If the prism height change is necessary, press the [ENT] key after the change.	ANGLE COMPARE  DESIGN 90° 00' 00"  H.angle 0° 00' 00"  DEVIATE 90° 00' 00"  H.INPUT 0 SET ANG/DIST	

# **4 DISTANCE STAKEOUT**


# **General pictures of measurement**

With DISANCE STAKEOUT measurement, the deviation between the input design values (specified distance) and the distance to the prism is displayed, making it easier to stake a point.

# **General pictures**



# **Design values and deviation**




#### **4 DISTANCE STAKEOUT**

### **Detailed Operating procedures**

Access the DISTANCE STAKEOUT according to "1. ACCESSING THE SPECIAL FUNCTIONS".


Step 1 Selecting the distance to be displayed and inputting the design values.



Input the S.dist. and V.dist. in the same way.

#### Step 2 STAKEOUT start

- (1) TRACK / MEAS → Move the prism to the ground point where the deviation is "0"
- (2) Use the ground point where the deviation is "0" as the STAKEOUT point





 A prism can be easily tracked if a position is searched by using a [TRACK] function and then using a [MEAS] function.

# 5 RDM

# **General pictures of measurement**

With RDM measurement, the horizontal distance, the slope distance, difference in height and the percentage of slope between the reference point and the observation point are measured. The distance between one observation point and another observation point is measured as well.





### **Detailed Operating procedures**


Access the RDM according to "1. ACCESSING THE SPECIAL FUNCTIONS".


### Step 1 Observation of the reference point


(1) PRISM H → INPUT PRIZM H → ENT → MEAS → Display the distance to the Reference Point


ENT → Go to Step 2

### Step 2 Observation of the target point (P1)










\*Use [DIST] key to change the distance display (REF-P/P-P)






\* Use [DIST] key to change the distance display (REF-P/P-P)

- The slope that can be calculated and displayed with the RDM function is within +/-200.00 %.
- The difference in height is indicated in +/-.

### **General pictures of measurement**

Any desired Target coordinates can be determined and stored by setting a Station Point as an original point and inputting the Backsight coordinate in COORDINATES measurement. The coordinates values from Original coordinates point can be determined by the Station coordinates input even if the Station Point is not set as original point. Coordinates values input can be omitted by designating the Station Point No. whenever the Station coordinates are stored in the internal memory.

### **General pictures**



# **Detailed Operating procedures**

Access the COORDINATES according to " ACCESSING THE SPECIAL FUNCTIONS ".

# 1. JOB NAME

- (1) JOB NAME input (Selection keys: ←,⇒,↑,↓)
   1.JOB NAME → ENT → COORDINATE JOB NAME INPUT → ENT
   → JOB NAME input by pressing selection keys → ENT
- (2) JOB NAME selection (Selection keys: ∆, ∇, ↑, ↓)
   1. JOB NAME → ENT → COORDINATES JOB NAME INPUT
   → Select the JOB NAME by shift keys → ENT → To the primary screen of the COORDINATES
- The JOB NAME can be selected only when the JOB NAMES are already stored.

### 2. STATION SETUP

#### (1) STATION COORDINATES

a. STATION COORDINATES input

```
2. STATION SETUP → ENT → STATION PNUMBER LIST → STATION PNUMBER INPUT

→ ENT → STATION COORDINATES INPUT → 2. DESCRIPTION → SELECT → DESCRIPTION INPUT

→ ENT → X COORDINATE → SELECT

→ Input X COORDINATE → ENT → Y COORDINATE → SELECT

→ Input Y COORDINATE → ENT → Z COORDINATE → SELECT

→ Input Z COORDINATE → ENT → INSTR. H. → SELECT

→ Input INSTR. H. → ENT

→ STORE → BACKSIGHT SELECTION

ENT
```

- Maximum 4 digits can be inputted at STATION P.NUMBER.
- Please press the [STORE] key to store the input data.
- Maximum 8 letters can be inputted at the "DESCRIPTION".

#### b. Search and call of stored STATION COORDINATES

The INSTR.H. can be changed.

#### (2) BACKSIGHT SELECTION

- a. COORDINATES INPUT
- BACKSIGHT P. NUMBER and COORDINATES input

```
BACKSIGHT SELECTION → 1 . COORDINATES INPUT → ENT


BACKSIGHT P. NUMBER LIST → ENT → Input the P.No → ENT

BACKSIGHT COORDINATES INPUT → 2.DESCRIPTION → SELECT → DESCRIPTION INPUT → ENT

→ X COORDINATE → SELECT → Input X COORDINATE → ENT

→ Y COORDINATE → SELECT → Input Y COORDINATE → ENT

→ Z COORDINATE → SELECT → Input Y COORDINATE → ENT
```



- Maximum 4 digits can be inputted at the BACKSIGHT P. NUMBER.
- Please press the STORE key to store the input data.

#### ■ Search and call of the stored BACKSIGHT P. NUMBER

• Shift keys:  $(\Delta, \nabla, \uparrow), \downarrow$ )

#### b. AZIMUTH input

• "Aim at the Backsight point" is not displayed.

# 3. SURVEY

- (1) 3. SURVEY → ENT → Press the [POINT] key → MEASURED POINT 1.POINT No. 2.DESCRIPTION 3.PRISM H
- → 1. POINT No. → SELECT → POINT No. input → ENT
- → 2. DESCRIPTION → SELECT → DESCRIPTION INPUT → ENT
- $\rightarrow$  3. PRISM H.  $\rightarrow$  SELECT  $\rightarrow$  PRISM H. input  $\rightarrow$  ENT  $\rightarrow$  ENT
- → Measure the P1 → XYZ COORDINATES are displayed → STORE / ENT
  - Maximum 4 digits can be inputted at the POINT NUMBER.
  - Please press the [STORE] key to store the measured data.
  - The PRISM H. can be changed.
- (2) POINT P2 P3, P4, -Px are measured in the same way.
- (3) SURVEY is completed by ESC key. → If necessary, repeat the measurement.
  - The COORDINATES is completed by pressing the ESC key.


# **7 OFFSET SHOTS**


## **General pictures of measurement**

OFFSET SHOTS can be used when the Prism cannot be positioned because of an obstacle in the way. With this type of measurement, the Target coordinates are measured and stored indirectly. Coordinates values input can be omitted by designating the Station point number whenever the Station coordinates are stored in the internal memory.

### **General pictures**

#### D, C and H are offset value.





### **Detailed Operating procedures**

### 1. JOB NAME

(1) JOB NAME input (Selection keys:  $\Leftarrow, \Rightarrow, \uparrow, \downarrow$ )

1. JOB NAME → ENT → COORDINATE JOB NAME INPUT Screen → ENT

→ JOB NAME input by pressing selection keys → ENT → STATION P. NUMBER LIST Screen

→ ENT → P No → ENT

(2) JOB NAME selection (Selection keys:  $\Leftarrow, \Rightarrow, \uparrow, \downarrow$ )

1. JOB NAME → ENT → COORDINATE JOB NAME INPUT Screen

- → Select the JOB NAME by shift keys → ENT → To the primary screen of OFFSET SHOTS
  - The JOB NAME can be selected only when it is already stored.

## 2. STATION SETUP

(1) STATION COORDINATES

a. STATION COORDINATES input

- $2. \, STATION \, SETUP \, \rightarrow \, \boxed{ENT} \, \rightarrow \, \boxed{STATION \, P. \, NUMBER \, LIST \, Screen} \, \rightarrow \, \boxed{ENT} \, \rightarrow \, \boxed{P. \, No \, input}$
- → ENT → STATION COORDINATES INPUT Screen → 2. DESCRIPTION → SELECT
- $\rightarrow$  DESCRIPTION INPUT  $\rightarrow$  ENT  $\rightarrow$  X COORDINATE  $\rightarrow$  SELECT
- $\rightarrow$  Input Y COORDINATE  $\rightarrow$  ENT  $\rightarrow$  Y COORDINATE  $\rightarrow$  SELECT
- → Input Z COORDINATE → ENT → Z COORDINATE → SELECT
- → Input INSTR. H. → ENT



- Maximum 4 digits can be inputted at STATION P. NUMBER.
- Please press the [STORE] key to store the input data.
- Maximum 8 letters can be inputted at the "DESCRIPTION".


#### b. Search and call of the stored STATION COORDINATES

- 2. STATION SETUP → ENT → STATION P. NUMBER LIST Screen
- → SELECT the NUMBER by shift keys → ENT → Confirm the STATION COORDINATES values
- → INSTR. H. → SELECT → INPUT INSTR. H. → ENT
- → BACKSIGHT SELECTION Screen

• The INSTR. H, can be changed.

#### (2) BACKSIGHT COORDINATES

- a. COORDINATES input
- BACKSIGHT COORDINATES input



- Maximum 4 digits can be inputted at the BACKSIGHT P. NUMBER.
- Please press the [STORE] key to store the input data.
- Search and call of the stored BACKSIGHT COORDINATES

• Shift keys:  $(\Delta, \nabla, \uparrow, \downarrow)$ 

#### b. AZIMUTH input

#### 7 OFFSET SHOTS

# 3. SURVEY

#### a. Offset point survey

Place an Offset point at the place where the measurement from the Station point is possible.

#### a. Target point survey


Value D,C and H are measured by using a tape measure.

# 8 REM

### **General pictures of measurement**


With REM measurement, a prism (Reference point) is set approximately directly below the place to be measured, and by measuring the prism, the height to the target object can be measured. This makes it easy to determine the heights of electric power lines, bridge suspension cables, and other large items used in construction.


## **General pictures**




### **Detailed Operating procedures**

Access the REM according to "1 . ACCESSING THE SPECIAL FUNCTIONS".





# **Step 2** Observing the target




# 9 RESECTION

With RESECTION, two known points or three known points are measured in order to determine the coordinates of the Station Point.

When the coordinates values of point A, B and C are stored in the internal memory, each coordinate input can be omitted by designating the each point number.

# **General pictures**



# **Detailed Operating procedures**

Access the RESECTION according to "ACCESSING THE SPECIAL FUNCTIONS".

# 1. JOB NAME

- (1) JOB NAME input (Selection keys: ←,⇒,↑,↓)
   1. JOB NAME → ENT → COORDINATE JOB NAME INPUT Screen → ENT
  - → JOB NAME input by pressing selection keys → ENT → STATION POINT INPUT
  - Maximum 15 characters can be inputted at JOB NAME.
- (2) Stored JOB NAME selection (Selection keys:  $\Leftarrow,\Rightarrow,\uparrow,\downarrow$ )

1. JOB NAME → ENT → COORDINATE JOB NAME INPUT Screen

→ Select the stored JOB NAME by shift keys → ENT → To the primary screen

The JOB NAME can be selected only when it is already stored.

# 2. STATION SETUP

- 2. STATION SETUP → STATION POINT INPUT → 1. STATION No. → SELECT
- → STATION No, input → ENT → 2. DESCRIPTION → SELECT
- → DESCRIPTION INPUT → ENT → 3. INSTR. H. → SELECT
- → INSTR H Input → ENT → ENT → To AP. NUMBER LIST Screen
  - Maximum 8 letters can be inputted at the "DESCRIPTION".

# 3. SURVEY

- (1) 2 known points survey
- a. Known coordinates input
- Point A survey
  - 3. SURVEY → ENT → AP. NUMBER LIST Screen → ENT → P No input

    → ACOORDINATES INPUT Screen → 2. DESCRIPTION → SELECT → DESCRIPTION INRUT → ENT

    → X → SELECT → X input → ENT → Y → SELECT → Y input → ENT

    → Z → SELECT → Z input → ENT → PRIZM H. Screen → SELECT

    → PRISM H. input → ENT → STORE / ENT → A SURVEY Screen → MEAS
  - → Point A distance is displayed → ENT → B P. NUMBER LIST Screen

## ■ Point B survey

- B P. NUMBER LIST Screen → ENT → P No input → ENT
- $\rightarrow {\tt BCOORDINATES\,INPUT\,Screen} \ \ \, \rightarrow \ \ \, {\tt 2.\,\,DESCRIPTION} \ \ \, \rightarrow \ \ \, {\tt DESCRIPTION\,INPUT} \ \ \,$
- $\rightarrow$  ENT  $\rightarrow$  X  $\rightarrow$  SELECT  $\rightarrow$  X input  $\rightarrow$  ENT
- $\rightarrow$  Y  $\rightarrow$  SELECT  $\rightarrow$  Y input  $\rightarrow$  ENT
- $\rightarrow$  Z  $\rightarrow$  SELECT  $\rightarrow$  Z input  $\rightarrow$  ENT  $\rightarrow$  PRISM H.  $\rightarrow$  SELECT
- → PRISM H. Screen → SELECT → PRISM H. Input → ENT → STORE/ENT
- → B SURVEY Screen → MEAS → Point B distance is displayed. → ENT
- → Calculated Station Point coordinates are displayed. → STORE/ ENT
  - b. Search and call of the stored known coordinates
  - Point A survey
    - 3. SURVEY → ENT → A P. NUMBER LIST Screen

#### 9 RESECTION

- → Search and shift to desired P No → ENT → Confirm point A coordinates
- → A PRISM HEIGHT INPUT Screen → SELECT
- → PRISM H. input → ENT → ENT → A SURVEY Screen → Aim at point A
- → MEAS → Point A distance is displayed → ENT
- → B P. NUMBER LIST Screen

## **■**Point B survey

- B P. NUMBER LIST Screen → Search and shift to desired P No → ENT
- → Confirm point B coordinates → B PRISM HEIGHT INPUT Screen
- $\rightarrow$  SELECT  $\rightarrow$  PRISM H. input  $\rightarrow$  ENT  $\rightarrow$  ENT  $\rightarrow$  B SURVEY Screen
- → Aim at point B → MEAS → Point B distance is displayed. → ENT
- → Calculated Station Point coordinates are displayed. → STORE / ENT

## (2) 3 known points survey

# a) Known coordinates input

## ■ Point A survey

- 3. SURVEY → ENT → A P. NUMBER LIST Screen → ENT → P No input
- → A COORDINATES INPUT Screen → 2. DESCRIPTION → SELECT → DESCRIPTION INPUT
- $\rightarrow$  ENT  $\rightarrow$  X  $\rightarrow$  SELECT  $\rightarrow$  X input  $\rightarrow$  ENT  $\rightarrow$  Y
- $\rightarrow$  SELECT  $\rightarrow$  Y input  $\rightarrow$  ENT  $\rightarrow$  Z  $\rightarrow$  SELECT  $\rightarrow$  Z input
- → ENT → PRISM H → SELECT
- → PRISM H. input → ENT → STORE / ENT → Aim at the point A
- → ENT

## ■ Point B survey

- B P. NUMBER LIST Screen → ENT → P No input → ENT
- → B COORDINATES INPUT Screen → 2. DESCRIPTION → SELECT → DESCRIPTION INPUT
- $\rightarrow$  ENT  $\rightarrow$  X  $\rightarrow$  SELECT  $\rightarrow$  X input
- $\rightarrow$  ENT  $\rightarrow$  Y  $\rightarrow$  SELECT  $\rightarrow$  Y input  $\rightarrow$  ENT
- → Z → SELECT → Z input → ENT → PRISM H. Screen → SELECT
- → PRISM H. input → ENT → STORE / ENT → Aim the point B → ENT

# **■**Point C survey

#### 9 RESECTION

- → CCOORDINATES INPUT Screen
   → 2. DESCRIPTION
   → SELECT
   → X input
   → ENT
   → Y
   → SELECT
   → Y input
   → ENT
   → Z → SELECT
   → Z input
   → ENT
   → PRISM H. Screen
   → SELECT
   → PRISM H. input
   → ENT
   → Aim the point C
   → ENT
   → Calculated station coordinates are displayed.
   → STORE / ENT
  - The 3 known points survey does not require the distance measurement.

#### b. Search and call of the stored known coordinates

# **■**Point A survey

## **■**Point B survey

## **■** Point C survey


The 3 known points survey does not require the distance measurement.

# 10 DATA STORAGE

# **General pictures of measurement**

With Data storage, the data of the JOB NAME a STATION is stored in the internal memory or the instrument.

# **General pictures**



# **Detailed Operating procedures**

Access the DATA STORAGE according to "ACCESSING THE SPECIAL FUNCTIONS".

# 1. JOB NAME

(1) JOB NAME input (Selection keys:  $\Leftarrow,\Rightarrow,\uparrow,\downarrow$ )

- → JOB NAME input by pressing selection keys → ENT → STATION POINT input
  - Maximum 15 letters can be inputted at JOB NAME.
- (2) JOB NAME selection (Selection keys:  $\Delta, \nabla, \hat{\uparrow}, \downarrow$ )
  - 1. JOB NAME → ENT → SURVEY JOB NAME
  - → Select JOB NAME by shift keys → ENT → To the STATION POINT input
    - The JOB NAME can be selected only when it is already stored.

#### 10 DATA STORAGE

# 2. STATION SETUP

- 2. STATION SETUP → ENT → STATION POINT INPUT → STATION No. → SELECT

  → STATION No. input → ENT → DESCRIPTION → SELECT

  → Input DESCRIPTION by Selection keys → ENT → INSTR. H. → SELECT
- $\rightarrow$  Input INSTR.H.  $\rightarrow$  ENT  $\rightarrow$  STORE
  - Maximum 4 digits can be inputted at STATION NUMBER.
  - Please press the STORE key to store the input data.
  - Maximum 15 letters can be inputted at the DESCRIPTION.

# 3. SURVEY

- 3. SURVEY → ENT → Press the POINT key → MEASURED POINT
  1. POINT No. 2. DESCRIPTION 3. PRISM H

  1. POINT No. → SELECT → POINT No. input → ENT

  2. DESCRIPTION → SELECT → DESCRIPTION INPUT → ENT

  3. PRISM H. → SELECT → PRISM H. input → ENT → ENT

  → Measure the P1 → STORE / ENT
  - Maximum 4 digits can be inputted at the POINT NUMBER.
  - Please press the STORE key to store the measured data.
  - The H. INPUT, O SET, HOLD of Horizontal angle is possible by pressing the F5 (2/2) key.
  - Maximum 8 letters can be inputted at the "DESCRIPTION".

With MEMORY MANAGER, following MEMORY MANAGEMENT of the instrument data can be performed.

**Coordinate data:** SEND, RECEIVE, EDIT, DELETE

**Survey data:** SEND, EDIT, DELETE

# **Detailed Operating procedures**

Access the MEMORY MANAGER according to the "I . ACCESSING TO THE SPECIAL FUNCTIONS".

## 1. COORDINATES SEND: DC1, AUX and CSV data can be transferred.

This function can send the stored Coordinates data into a personal computer etc.

# a. Send by input of the stored COORDINATES JOB NAME

```
1. COORDINATES SEND → ENT → JOB NAME INPUT Screen → ENT

Select and Input a stored JOB NAME (The same job name Is found) → ENT

COORDINATES SEND Screen → 1. COMMUNICATION SET UP → SELECT → 1. BAUD RATE

→ SELECT → Shift to desired value → ENT → 2. DATA LENGTH

→ SELECT → Shift to desired value → ENT → 3. PARITY BITS

→ SELECT → Shift to desired article → ENT → 4. STOP BITS

→ SELECT → Shift to desired value → ENT → 5. SIGNAL CONTROL

→ SELECT → Shift to ON/OFF → ENT → 6. XON/XOFF

→ SELECT → Shift to ON/OFF → ENT → ENT

→ 2. FORMAT → SELECT → Shift to desired FORMAT → ENT

→ 3. COORD AXIS → SELECT → Shift to desired COORD AXIS → ENT

→ ENT → SEND CONFIRMATION Screen

→ (JOB NAME---, After the push ENT key, Set the PC in com, mode) → ENT → SEND
```

## b. SEND by the search of stored COORDINATES JOB NAME

```
1. COORDINATES SEND → ENT → JOB NAME INPUT Screen → ENT

Shift to a desired JOB NAME → ENT

COORDINATES SEND Screen → COMMUNICATION SET UP → SELECT → 1. BAUD RATE

→ SELECT → Shift to desired value → ENT → 2. DATA LENGTH

→ SELECT → Shift to desired value → ENT → 3. PARITY BITS

→ SELECT → Shift to desired article → ENT → 4. STOP BITS

→ SELECT → Shift to desired value → ENT → 5. SIGNAL CONTROL

→ SELECT → Shift to ON/OFF → ENT → 6. XON/XOFF

→ SELECT → Shift to ON/OFF → ENT → ENT

→ 2. FORMAT → SELECT → Shift to desired FORMAT → ENT

→ 3. COORD AXIS → SELECT → Shift to desired COORD AXIS → ENT

→ ENT → SEND CONFIRMATION Screen

→ (JOB NAME---, After the push ENT key, Set the PC in com. mode) → ENT → SEND
```

#### 2. COORDINATES RECEIVE: DC1. AUX and CSV data can be transferred.

This function can receive the Coordinates data from a personal computer etc.

## 2. COORDINATES RECEIVE → ENT

```
COORDINATES RECEIVE → 1. COMMUNICATION SETUP → SELECT → 1. BAUD RATE

→ SELECT → Shift to desired value → ENT → 2. DATA LENGTH

→ SELECT → Shift to desired value → ENT → 3. PARITY BITS

→ SELECT → Shift to desired article → ENT → 4. STOP BITS

→ SELECT → Shift to desired value → ENT → 5. SIGNAL CONTROL

→ SELECT → Shift to ON/OFF → ENT → 6. XON/XOFF

→ SELECT → Shift to ON/OFF → ENT → ENT

→ 2. FORMAT → SELECT → Shift to desired FORMAT → ENT

→ 3. COORD AXIS → SELECT → Shift to desired COORD AXIS → ENT

→ ENT → RECEIVE CONFIRMATION Screen

→ (After the PC in com. Mode, push ENT key.) → ENT → RECEIVE
```

#### 3. COORDINATES EDIT

This function can edit the stored Coordinates data.

a. Edit by input & call of the COORDINATES JOB NAME and COORDINATES NUMBER

- 3. COORDINATES EDIT → ENT → JOB NAME INPUT → ENT
- → Input the stored JOB NAME → (The same job name is found) → ENT
- → POINT NUMBER INPUT → ENT
- → Input the P No → ENT → COORDINATES EDIT → 2. DESCRIPTION
- → SELECT → DESCRIPTION INPUT → ENT → X COORD.
- $\rightarrow$  SELECT  $\rightarrow$  Input the X COORD  $\rightarrow$  ENT  $\rightarrow$  Y COORD.
- $\rightarrow$  SELECT  $\rightarrow$  Input the Y COORD  $\rightarrow$  ENT  $\rightarrow$  Z COORD.
- → SELECT → Input the Z COORD → ENT → ENT → (OVER WRITE) → ENT

b. Edit by search & shift of the COORDINATES JOB NAME and COORDINATES NUMBER

- 3. COORDINATES EDIT  $\rightarrow$  ENT  $\rightarrow$  JOB NAME INPUT  $\rightarrow$  ENT
- → Search and shift to the JOB NAME → ENT → POINT NUMBER INPUT
- → Search & shift to the stored POINT NUMBER → ENT
- ightarrow Coordinates edit ightarrow 2. Description ightarrow Select ightarrow Description input ightarrow Ent
- $\rightarrow$  X COORD.  $\rightarrow$  SELECT  $\rightarrow$  Input the X COORD  $\rightarrow$  ENT
- → Y COORD. → SELECT → Input the Y COORD → ENT
- → Z COORD. → SELECT → Input the Z COORD → ENT
- → ENT → (OVER WRITE) → ENT

#### 4. COORDINATES DELETE

This function can delete the stored Coordinates data.

a. Delete by input of the COORDINATES JOB NAME

- 4. COORDINATES DELETE → ENT → JOB NAME INPUT Screen → ENT
- → Input the stored JOB NAME → (The same job name is found) → ENT
- → (JOB NAME---, Delete the job data. Are you sure ?) → ENT
- b. Delete by search of the COORDINATES JOB NAME

- 4. COORDINATES DELETE → ENT → JOB NAME INPUT Screen
- → Search & shift to stored JOB NAME → ENT
- → (JOB NAME---, Delete the job data. Are you sure ?) → ENT

## 5. SURVEY DATA SEND: DC1, AUX and SDR data can be transferred.

This function can send the stored Survey data into a personal computer etc.

# a. Send by input of the SURVEY JOB NAME

# b. Send by search & call of the SURVEY JOB NAME

```
5. SURVEY DATA SEND → ENT → JOB NAME INPUT Screen

→ Search a stored JOB NAME → ENT

SURVEY DATA SEND Screen → 1. COOMUNICATION SET UP → SELECT → 1. BAUD RATE

→ SELECT → Shift to desired value → ENT → 2. DATA LENGTH

→ SELECT → Shift to desired value → ENT → 3. PARITY BITS

→ SELECT → Shift to desired article → ENT → 4. STOP BITS

→ SELECT → Shift to desired value → ENT → 5. SIGNAL CONTROL

→ SELECT → Shift to ON/OFF → ENT → 6. XON/XOFF

→ SELECT → Shift to ON/OFF → ENT → ENT

→ 2. FORMAT → SELECT → Shift to desired FORMAT → ENT

→ ENT → SEND CONFIRMATION Screen
```

→ (JOB NAME---, After the push ENT key, Set the PC in com, mode) → ENT → SEND

#### 6. SURVEY DATA EDIT

This function can edit the stored Survey data.

# a. Edit by input & call of the SURVEY JOB NAME & SURVEY POINT NUMBER

- 6. SURVEY DATA EDIT → ENT → JOB NAME INPUT → ENT

  → Input the stored JOB NAME → (The same job name is found) → ENT

  → POINT NUMBER INPUT Screen → ENT → Input the P No → ENT

  → STATION(POINT) EDIT Screen → 1. STATION(POINT) No. → input → SELECT → ENT

  → 2. DESCRIPTION → SELECT → Input → ENT → 3. INST. (PRISM) HEIGHT

  → SELECT → Input → ENT → (OVER WRITE) → ENT
- b. Edit by search & call of the SURVEY JOB NAME & SURVEY POINT NUMBER

```
6. SURVEY DATA EDIT → ENT → JOB NAME INPUT Screen

→ Search & shift to the stored JOB NAME → ENT → POINT NUMBER INPUT Screen

→ ENT → Search & shift to the stored (STATION) → ENT

→ STATION (POINT) EDIT Screen

→ 1. STATION (POINT) No. → SELECT → Input → ENT

→ 2. DESCRIPTION → SELECT → input → ENT → 3. INST. (PRISM) HEIGHT
```

 $\rightarrow$  SELECT  $\rightarrow$  Input  $\rightarrow$  ENT  $\rightarrow$  (OVER WRITE)  $\rightarrow$  ENT

# 7. SURVEY DATA DELETE

This function can delete the stored Survey data.

a. Delete by input and call of the SURVEY JOB NAME

b. Delete by search and call of the SURVEY JOB NAME

# 12 DataLink DL- 01 Software

DataLink DL01 Software allows you to send collected data by R-300 to other devices, to receive coordinates data, and to convert the resulting files into a number of common formats.

## a) Recommendation for "PN"

It is recommended that "PN" (Point Name) data should consist of less or equal to 4 (one-byte) numeric characters to convert files with DL-01. Because, it may not be converted properly if alphabetic characters or more than 5 (one-byte) numeric characters are used for the "PN".

## b) Notes for the data transferring.

Please, be careful about following items for the data transfer with "DL-01".

#### b-1 Notes for unit.

If you are requested to select unit when you convert data on DL-01, please select unit according to the settings on R-300.

#### b-2 Limitation for each format.

Please, use "CSV" or "DC1( DC-1Z) " format to transfer data to/from R-300.

#### Limitation for the "CSV" format.

With the "CSV" format, "PN" and "PC" (Point Code) data consist of less or equal to 8 (one-byte) characters can be transferred.

## Limitations for the "DC1 (DC-1Z)" format.

With "DC1 (DC-1Z)" format, the length of "PN" data should consist of less or equal to 8 (one-byte) characters. And with the "DC1 (DC-1Z)" format "PC" data cannot be transferred.

#### b-3 Recommended communication settings on R-300.

Recommended settings for "COMMUNICAYTION SETUP" on R-300 special function is as follows.

#### R-300⇒PC(DL-01) for "COORDINATES SEND"

1.BAUD RATÉ: 1200 2.DATA LENGTH: 8 3.PARITY BITS: NIL 4.STOP BITS: 1 5.SIGNAL CONTROL: OFF 6.XON/XOFF: OFF

#### R-300⇒PC(DL-01) for "SURVEY DATA SEND"

1.BAUD RATE: 1200-9600

2.DATA LENGTH: 8
3.PARITY BITS: NIL
4.STOP BITS: 1
5.SIGNAL CONTROL: OFF
6.XON/XOFF: OFF

#### PC(DL-01) R-300 for "COORDINATES RECEIVE"


1.BAÚD RATE: 1200 2.DATA LENGTH: 8 3.PARITY BITS: NIL 4.STOP BITS: 1 5.SIGNAL CONTROL: OFF 6.XON/XOFF: OFF

Please note that these settings should be common with DL-01's.

## b-4 Recommended communication settings on DL-01

To configure DL-01 Communication setting, please read "Configuring the software" in the Help topics of DL-01. And select values as follows.

For setting "Type of Device" in the "Settings" panel (Menu—"Edit"--"Settings"), select "PCS-300/R-100(PCS)/R-300(PSF)" for "R-300 PentaxSpecificationFunction" and other setting should be as follows.



(Please note that these settings should be common with R-300's. And if the selection of "Type of Device" is not collect it may result in missing some data.)

R-300⇒PC(DL-01)

Bits per second: 1200 (1200-9600 for sending "SURVEY DATA")

Databits: 8
Parity: None
Stop bits: 1

PC(DL-01)⇒ R-300

Bits per second: 1200
Databits: 8
Parity: None
Stop bits: 1

## c) Note for the Memory capacity

Data transfer failure from DL01 to R-300 may cause reduction of memory capacity. If memory capacity becomes less, please back up required data first, and then initialize coordinates data. To initialize coordinates data, turn on the instrument while pressing [F2]+[F5]+[ON/OFF] keys, and take your finger off from [ON/OFF] again.

After you see the message "COORD. DATA INITIAL", press [F5] key. Then the message "Please,

wait" is displayed. When it is completed, the panel of Electronic Vial is displayed.

# d) Difference between CSV format on "PentaxSpecialFunction" and "PowerTopoLite"

CSV file format from R-300 "PentaxSpecialFunction" version is slightly different from "PowerTopoLite" version as follows.


Type of software version		Format
R-300	"PentaxSpecialFunction"	PN,X,Y,Z,Code
version		
R-300 "PowerTopoLite" version		PN,X,Y,Z,Code,

At the end of each line of CSV file output by "PowerTopoLite", there is "," as shown above.

# e) Note on converting CSV file

When you attempt to convert CSV file from R-300 by DL-01, please note that it may not succeed if CSV data type is not correct.

After [CONVERT] button is clicked on DL-01 then "CSV files from PCS/R-100 (\*.\*)"is selected for the type of file, "CSV Import Option" will be appear.



In the case of CSV data doesn't have "CODE" field, please select "PN XY" or "PN XYZ" from following four types for the "type" of data on the "CSV Import Option" panel.

PN XY (Code)

PN XYZ(Code)

PN XY

PN XYZ

f) For more information to work with DL-01, please refer to the "help" file after the installation.

# **PENTAX**

PENTAX Industrial Instruments Co., Ltd.

2-5-2, Higashi-Oizumi, Nerima-ku, Tokyo, 178-0086, Japan Tel:+81-3-5905-1222 Fax:+81-3-5905-1225

**CERTIFIED ISO 9001 & 14001** 

E-mail: international@piic.pentax.co.jp

Member symbol of the Japan Surveying Instruments Manufacturers' Association representing the high quality surveying products.



The CE marking assures that this product complies with the requirements of the EC directive for safety.



102002 Fi

First edition TS01101EB2