

# Troubleshooting Guide

Problem	Possible Cause	Possible Solution
<b>Oversize hole</b>	<ul style="list-style-type: none"> <li>a.) The reamer is running eccentric to the center line of the machine spindle</li> <li>b.) Excessive misalignment causing reamer to cut on back taper</li> <li>c.) Material build up on cutting edges</li> <li>d.) The reamer diameter is too large</li> </ul>	<ul style="list-style-type: none"> <li>a.) Use the Modular system with radial adjustment</li> <li>b.) Rectify misalignment</li> <li>c.) Replace the coolant or change the cutting speed</li> <li>d.) Use smaller reamer or regrind existing one</li> </ul>
<b>Undersize hole</b>	<ul style="list-style-type: none"> <li>a.) The reamer diameter is too small</li> <li>b.) The reamer diameter is worn</li> <li>c.) The coolant is not suitable</li> <li>d.) Stock allowance too small</li> <li>e.) The cutting speed is too low</li> </ul>	<ul style="list-style-type: none"> <li>a.) Use larger reamer</li> <li>b.) Expand, regrind or replace the reamer</li> <li>c.) Replace the coolant</li> <li>d.) Increase the stock allowance</li> <li>e.) Increase the cutting speed</li> </ul>
<b>Tapered hole</b>	<ul style="list-style-type: none"> <li>a.) Excessive misalignment</li> </ul>	<ul style="list-style-type: none"> <li>a.) Correct misalignment</li> </ul>
<b>Burr at the entry of the hole</b>	<ul style="list-style-type: none"> <li>a.) Excessive misalignment</li> </ul>	<ul style="list-style-type: none"> <li>a.) Correct misalignment</li> </ul>
<b>The hole is not straight</b>	<ul style="list-style-type: none"> <li>a.) Concentricity and alignment error between the workpiece and the tool</li> <li>b.) Asymmetrical cutting or angled surfaces</li> </ul>	<ul style="list-style-type: none"> <li>a.) Correct misalignment and use the modular system with radial adjustment</li> <li>b.) Create a chamfer on the lead-in</li> </ul>
<b>Poor hole finish</b>	<ul style="list-style-type: none"> <li>a.) One cutting edge is chipped</li> <li>b.) The lead-in is irregular</li> <li>c.) Back taper on the cutting edges too great</li> <li>d.) Excessive misalignment</li> <li>e.) Cutting data not correct</li> <li>f.) Poor chip evacuation</li> </ul>	<ul style="list-style-type: none"> <li>a.) Regrind the reamer</li> <li>b.) Regrind the reamer</li> <li>c.) Regrind the reamer</li> <li>d.) Correct misalignment or use the modular system with radial adjustment</li> <li>e.) Verify cutting data</li> <li>f.) Verify coolant volume and pressure or use through tool coolant</li> </ul>
<b>The reamer creates excessive torque loading</b>	<ul style="list-style-type: none"> <li>a.) Back taper on the cutting edges too small</li> <li>b.) The radially ground land is too wide</li> <li>c.) The coolant is not suitable</li> </ul>	<ul style="list-style-type: none"> <li>a.) Regrind the reamer</li> <li>b.) Regrind the reamer</li> <li>c.) Replace the coolant</li> </ul>