

Nuclear Gauge Testing Manual

Section 4

Operating Instructions

Testing - Asphalt

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N301

TEST PARAMETERS (ASPHALT)
TROXLER 3440**1 SET UP**

- ▶ Press

ON

 and allow the nuclear gauge to complete the self-test routine.

2 UNITS

When **<READY>** is displayed:

- ▶ Press

SHIFT X

- ▶ Press

SPECIAL
9

 and the following is displayed:

SPECIAL FUNCTION
YES - Next menu
1 - STAT TEST
2 - DRIFT TEST

- ▶ Press

YES EXIT

 repeatedly until the following is displayed:

YES – Next menu
9 – SET UNITS
10 – BAND RATE
11 – COMM PROTOCOL

- ▶ Press

SPECIAL
9

 and the following is displayed:

UNITS in XXX
Press 1 – PCF
2 – METRIC
ENTER – No change

- ▶ Press

DEPTH
2

 and the following is displayed:

UNITS IN METRIC

The display will return to **<READY>**.

3 COUNT TIME

- Press

TIME
-

 and the following is displayed:
- | |
|--|
| TIME: XX
1 – 15 sec
2 – 1 min
3 – 4 min |
|--|
- Press

DEPTH
2

 and the following will be displayed:
- | |
|-----------------------|
| -COUNT TIME-
1 min |
|-----------------------|

The display will return to <READY>.

4 ASPHALT MODE

- Press

SHIFT
X
- Press

MODE
8

 and the following is displayed:
- | |
|---|
| MODE: XXXX
Select: 1 – SOIL
2 – ASPHALT
(CE to exit) |
|---|
- Press

DEPTH
2

 and the following is displayed:
- | |
|--|
| ASPHALT: XXXX
Select: 1 – % MA
2 – 100% - % MA |
|--|
- Press

COUNT
1

 and the following is displayed:
- | |
|---|
| ASPHALT: % MA
Do you want to enable %
voids also? |
|---|
- Press

YES
EXIT

 and the following is displayed:
- | |
|--------------------------|
| ASPHALT: % MA
% VOIDS |
|--------------------------|
- OR
- Press

NO/CE
C/CE

 and the following is displayed:
- | |
|---------------|
| ASPHALT: % MA |
|---------------|

The display will return to <READY>.

- Press

SHIFT
X
- Press

MODE
8

 and the following is displayed:
- | |
|---|
| MODE: XXXX
Select: 1 – SOIL
2 – ASPHALT
(CE to exit) |
|---|
- Press

DEPTH
2

 and the following is displayed:
- | |
|--|
| ASPHALT: XXXX
Select: 1 – % MA
2 – 100% - % MA |
|--|
- Press

DEPTH
2

 and the following is displayed:
- | |
|---|
| ASPHALT: 100% MA
Do you want to enable %
voids? |
|---|
- Press

YES
EXIT

 and the following is displayed:
- | |
|-----------------------------|
| ASPHALT: 100% MA
% VOIDS |
|-----------------------------|
- OR
- Press

NO/CE
C/CE

 and the following is displayed:
- | |
|------------------|
| ASPHALT: 100% MA |
|------------------|

The display will return to <READY>.

5 MAXIMUM DENSITY

► Press

PROCTOR/ MARSHALL +

 and the following is displayed:

MA = XXXX kg/m3 PR = XXXX VD = XXXX Want to change?
--

To retain value, go to 5.1.

To change value, go to 5.2.

5.1 Retain the Value

► Press

NO/CE C/CE

 to retain the displayed value of MA.

The display will return to <READY>. Go to 6.

5.2 Change the Value

► Press

YES EXIT

 to change the displayed value of MA.

And the following will be displayed:

Select: 1 – MA 2 – PR 3 – Voidless

► Press

COUNT
1

 and the following is displayed:

Select source of Marshall value: 1 – Stored Value 2 – New Value
--

To enter a new value, go to 5.3.

To select a stored value, go to 5.4.

5.3 Enter a New Value

- Press

DEPTH
2

 and the following is displayed:

Marshall:
XXXX kg/m³
Press ENTER
when completed

- Use the numbered keys to enter the required value to the nearest 1kg/m³.

- Press

START/ ENTER
=

 and the following is displayed:

MA = XXXX kg/m³
Do you want to save this
value for later use?

If the value is not to be saved:

- Press

NO/CE
C/CE

 and the display will return to **<READY>**. Go to 6.

To save the displayed value:

- Press

YES
EXIT

 and the following is displayed:

Select Marshall
Memory Cell:
1:XX2:XX
3:XX4:XX

- Press the numbered key (1, 2, 3 or 4) to select a memory cell in which to store the value.

And the following will be displayed:

Marshall
XXXX kg/m³
ENABLED!
stored in cell X

The display will return to **<READY>**. Go to 6.

5.4 Select a Stored Value

- Press

COUNTS
1

 and the following is displayed:

Select desired Marshall: 1:XX2:XX 3:XX4:XX

- Press the numbered key (1, 2, 3 or 4) to select the required value:

And the following will be displayed:

Marshall XXXX kg/m3 ENABLED!

The display will return to <READY>.

6 VOIDLESS DENSITY

- Press

PROCTOR/ MARSHALL +

 and the following is displayed:

MA = XXXX kg/m3 PR = XXXX VD = XXXX Want to change?
--

- Press

YES EXIT

 and the following is displayed:

SELECT: 1 – MA 2 – PR 3 - VOIDLESS

- Press

CALC
3

 and the following is displayed:

Voidless Density XXXX kg/m3 Press enter when complete
--

- Use the numbered keys to enter the required value to the nearest 1kg/m^3 .

- Press

START/

ENTER
=

And the display will return to <READY>.

7 MATERIAL WET DENSITY BIAS

► Press

OFFSET
MR

 and following is displayed:

-OFFSET- Select:
1 – Dens. –ZZZ-
2 – Moist –ZZZ-
3 – Trench –ZZZ-

► Press

COUNTS
1

The following will be displayed:

Density Offset DISABLED Do you want to ENABLE?

OR

Density Offset ENABLED Do you want to DISABLE?

To disable the material wet density bias, go to 7.1.

To enable the material wet density bias, go to 7.2.

7.1 Disable Material Wet Density Bias

► Press

NO/CE
C/CE

 to confirm that the density offset is to remain disabled

OR

YES
EXIT


 to disable the density offset.

And the following will be displayed briefly:

Density Offset DISABLED

The display will return to <READY>.

7.2 Enable Material Wet Density Bias




The following will be displayed:

-Wet Density-Offset
XXXX kg/m3
Want to change?

To retain the value, go to 7.2.1.

To change the value, go to 7.2.2.

7.2.1 Retain the Value




The following will be displayed briefly:

Density Offset ENABLED!

The display will return to <READY>.

7.2.2 Change the Value




- WD Offset -
Select: + or -
1 = +
2 = -



WD Offset
Press enter when completed

- ▶ Use the numbered keys to enter the required value to the nearest 1kg/m^3 .



The following will be displayed:



Density Offset
ENABLED!

The display will return to **<READY>**.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N302

MEASUREMENT (ASPHALT)
TROXLER 3440**1 SET UP**

- Press ON and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT

When **<READY>** is displayed:

- Press START/
ENTER
=

The following will be displayed:

Depth: 0 mm
MA: XXX kg/m³
Time: XX sec.

OR

Depth: 0 mm
MA: XXX kg/m³
(WD Offset)
Time: XX sec.

(asphalt density
bias disabled)

(asphalt density
bias enabled)

At the end of the counting period, the following will be displayed:

% MA = XX.X %
WD = XXXX kg/m³
M = X.X % M = X.X
% VOIDS = XXX %

OR

% MA = XX.X %
WD = XXXX kg/m³
(WD Offset)
ENTER – More Info

(asphalt density
bias disabled)

(asphalt density
bias enabled)


If more information is required:



And following will be displayed:

M = XX %M = XX
%VOIDS = XX



Record WD as the **wet density**.



And following will be displayed:


Dens ct. = XXXX
Moist ct. = XX
SHIFT/RECALL to see Readings

Record Dens Ct as the **density count**.











OPERATING INSTRUCTION N303

TEST PARAMETERS (ASPHALT)
TROXLER 3430**1 SET UP**




- ▶ Press  and allow the nuclear gauge to complete the self-test routine.


2 UNITS

When <READY> is displayed





- ▶ Press  and the following is displayed: 
- ▶ Press  repeatedly until the following is displayed: 
- ▶ Press  and the following is displayed: 
- ▶ Press  to set the desired unit
- ▶ Press  and the display will return to <READY>.

3 COUNT TIME





- ▶ Press  and the following is displayed: 
- ▶ Press  to set the desired count time

- Press  and the display will return to <READY>.

4 DEPTH

- Press  and the following is displayed: 
- Press  repeatedly until the required test depth is displayed:
- Press  and the display will return to <READY>.

5 ASPHALT MODE AND MAXIMUM DENSITY

- Press  and the following is displayed: 
- Press  until “MA” is displayed. 

To retain the displayed value go to 5.1


To change the displayed value go to 5.2.

5.1 Retain the value

- Press  to retain the displayed value.

The display will return to <READY>. Go to 6.



5.2 Change the value

- Press  to change the display value of MA

The following will be displayed:








MA: XXXX
(↑↓ or ENTER)

For each digit:


- Press  repeatedly until the required number is displayed.
- Press  to confirm each number.

The display will return to <READY>.

6 ASPHALT DENSITY BIAS

- Press  and the following is displayed: 
- Press  repeatedly until the following is displayed: 
- Press  and the following is displayed: 
- Press 


The following will be displayed:




To disable the asphalt density bias, go to 6.1.

To enable the asphalt density bias, go to 6.2.

6.1 Disable Asphalt Density Bias




The following will be displayed briefly:




The display will return to <READY>. Go to 7.

6.2 Enable Asphalt Density Bias



And the following will be displayed:



To retain the display go to 6.2.1.

To change the display go to 6.2.2.

6.2.1 Retain the Value

► Press

START
ENTER

The following will be displayed:

Dens. Offset ON

The display will return to <READY>. Go to 7.

6.2.2 Change the Value

► Press



to enter a positive
asphalt density bias

OR



to enter a negative
asphalt density bias.

For each digit:

► Press



until the required number is displayed.

► Press

START
ENTER

to confirm each number.

The following will be displayed briefly:

Dens. Offset ON

The display will return to <READY>.

7 ASPHALT VOIDLESS DENSITY

► Press

SPECIAL

and the following is displayed:


- RECALL -
(↑↓ or ENTER)


► Press



repeatedly until the following is
displayed:

- VOIDLESS DENS -
(↑↓ or ENTER)

- Press  and the following is displayed:



For each digit:


- Press  until the required number is displayed.

- Press  to confirm each number.

The display will return to <**READY**>.


OPERATING INSTRUCTION N304

MEASUREMENT (ASPHALT)
TROXLER 3430**1 SET UP**

- Press  and allow the nuclear gauge to complete the self-test routine.


2 MEASUREMENT

When <**READY**> is displayed

- Press  and the following is displayed:

Depth: XX mm
Time: XX sec


At the end of the counting period:


- Press  repeatedly until the required values are displayed.

Record the following values as appropriate:

- WD as the **wet density** to the nearest 0.001 t/m³.
- D as the **density count**.

(To convert from kg/m³ to t/m³, divide the displayed value by 1000.)

- Press  and the display will return to <**READY**>.

- Press  if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N305

TEST PARAMETERS (ASPHALT)
TROXLER 3411B

1. Start-up

- ▶ Turn the PWR/TIME switch to “**NORM**”.



2. Depth

- ▶ Set the DEPTH switch to the “**BS**” position.

3. Maximum Wet Density

- ▶ Press   simultaneously.

- ▶ Set the +/- switch to – (i.e. set to decrease the displayed value).

- ▶ Hold  or press  repeatedly until the required value is obtained to the nearest 1 kg/m³.

(To convert from t/m³ to kg/m³, multiply the maximum dry density by 1000.)

The display will return to normal mode after a few seconds if no key is pressed.

4. Material Moisture Bias

- ▶ Set the MOISTURE CORRECTION switches to “**0**”.
- ▶ Turn the PWR/TIME switch to “**OFF**” if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N306

MEASUREMENT (ASPHALT)
TROXLER 3411B

1. Start-up

- ▶ Turn the PWR/TIME switch to “**NORM**” and allow the nuclear gauge to stabilise for at least 20 minutes before commencing the test.

2. Measurement

- ▶ Press

STD
MEA

At the end of the counting period, the following will be displayed:

XXXX

Record the displayed value as the **density count**.

- ▶ Press

%MAR
WD

 and record the **wet density** to the nearest 0.001 t/m³.

(To convert from kg/m³ to t/m³, divide the displayed value by 1000.)


- ▶ Turn the PWR/TIME switch to “**OFF**” if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK



OPERATING INSTRUCTION N307


TEST PARAMETERS
TROXLER 4640B


1. Start-up


- Press  and allow the nuclear gauge to complete the self-test routine.

2. Measurement Units

- Press   and the following will be displayed:
- SPECIAL FUNCTION
 YES - next menu
 1 - Surface Voids
 2 - Recover Erase

- Press  and the following will be displayed:
- Units in ZZZ
 Press: 1 - US
 2 - METRIC
 ENTER - no change




- Press  and the following will be displayed:
- Density in kg/m3
 Select: 1 - kg/m3
 2 - g/cm3
 Enter - no change

- Press  and the following will be displayed:
- UNITS - METRIC
 Density in g/cm3

(Units of g/cm³ are equivalent to t/m³.)



The display will return to <READY>.

3. Count Time

- ▶ Press  and the following will be displayed:
- Count Time-
XX min.
Do you want
to change?
- ▶ Press  and the following will be displayed:
- Sel: 1- 0.5 min.
2- 1 min.
3- 2 min.
4- 3 min.
- ▶ Press  and the following will be displayed:
- Count Time-
1 minutes!

The display will return to <READY>.

4. Layer Thickness

- ▶ Press  and the following will be displayed:
- Layer Thickness:
X.XX cm.
Input and
Press ENTER
- ▶ Use the numbered keys to enter the layer thickness to the nearest 0.1 cm
(The minimum value that can be set is 2.54 cm).
- ▶ Press  and the following will be displayed briefly:
- Layer Thickness:
X.XX cm.

The display will return to <READY>.

5. Marshall and Maximum (Voidless) Density

► Press



and the following will be displayed:

MA: X.XXX g/cm3
VD: X.XXX g/cm3
Do you want
to change?

If MA and VD values of "**0.000 g/cm³**" are displayed:

► Press



If values other than "**0.000 g/cm³**" are displayed:

► Press



and the following will be displayed:

MARSHALL
X.XXX g/cm3
Input and
Press ENTER

► Press



► Press



and the following will be displayed:

VOIDLESS DENSITY
X.XXX g/cm3
Input and
Press ENTER

► Press



► Press



and the display will return to **<READY>**.

6. Asphalt Density Bias

► Press

SHIFT
x

OFFSET
2

The following will be displayed:

Offset: DISABLED XX g/cm3 1 - Enable/Change 2 - Disable
--

OR

Offset: ENABLED XX g/cm3 1 - Enable/Change 2 - Disable

To disable the asphalt density bias, go to Step 6.1.

To enable the asphalt density bias, go to Step 6.2.

6.1 Disable Asphalt Density Bias

► Press

OFFSET
2

 and the following will be displayed briefly:

Offset DISABLED!

The display will return to <READY>.

6.2 Enable Asphalt Density Bias

► Press

SP. CAL.
1

 and the following will be displayed:

Offset: ENABLED XX g/cm3 Want to change offset value?
--

To retain the displayed value, go to Step 6.2.1.


To change the displayed value, go to Step 6.2.2.

6.2.1 Retain the Value



The display will return to <READY>.

6.2.2 Change the Value




Select source of Offset
1 - keyboard
2 - stored value


To enter a new value, go to Step 6.2.2.1.

To select a stored value, go to Step 6.2.2.2.

6.2.2.1 Enter a New Value




Offset value:
---- g/cm3
Select 1 = +
2 = -



The following will be displayed:


Offset value:
x ---- g/cm3
Input and press ENTER




- Press  and the following will be displayed:
- Offset: ENABLED
XXXXg/cm3
Do you want to
save this value?

Note: It is not necessary to save the displayed value to enable it.


If the value is not to be saved:

- Press  and the display will return to <READY>.

To save the displayed value:


- Press  and the following will be displayed:
- Enter permanent
Memory location
to save Offset:
(1 – 12)? - -
- Use the numbered keys to enter the memory location.

Note: Record the memory location and bias to facilitate subsequent retrieval of saved values.

- Press  and the following will be displayed briefly:
- Offset: ENABLED
x XX g/cm3
Saved in memory
location X

The display will return to <READY>.

6.2.2.2 Select a Stored Value

- Press  and the following will be displayed:
- Offset: # X -
XX g/cm3
1 – to select
2 – for next

► Press

OFFSET
2

 repeatedly until the required memory location and value is displayed.

► Press

SP. CAL.
1

 and the following will be displayed briefly:

Offset: ENABLED XX g/cm3

The display will return to <READY>.

► Press

OFF


 if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N308

MEASUREMENT (ASPHALT)
TROXLER 4640B

1. Start-up

- Press  and allow the nuclear gauge to complete the self-test routine.

2. Measurement

When <READY> is displayed:

- Press 

The following will be displayed:

MA: XXXX g/cm3
Thick: XX.XX cm
Avg: XX
Time: XX secs

OR

MA: XXXX g/cm3
Thick: XX.XX cm
Avg: XX, Offset
Time: XX secs.



(asphalt density
bias disabled)

(asphalt density
bias enabled)

At the end of the counting period, the following will be displayed:



Dens: XXXX kg/m3
%MA: XX.XX%
100-%MA: XXX.XX%
%VOID: X.XX%

Record Dens as the **wet density** to the nearest 0.001 t/m³.

- Press   and the following will be displayed:

Dens: XXX.X kg/m3
%MA: XX.XX%
%VOID: X.XX%
Cnts XXXX XXXX

Record Cnts as the **density count** values for System 1 and System 2.



- ▶ Press  and the display will return to <READY>.
- ▶ Press  if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N309

TEST PARAMETERS (ASPHALT) CPN MC3



1. Measurement Units

Pre- March 1998 Nuclear Gauge:

- ▶ Press   simultaneously until the density and moisture display is obtained.

- ▶ Press  until "**gcc**" is displayed.

Post-March 1998 Nuclear Gauge:

- ▶ Press   simultaneously.

- ▶ Press  until "**gcc**" is displayed.

- ▶ Press 

- ▶ Press  until "**Density**" is displayed.

- ▶ Press 

2. Count Time

▶ Press

TIME
0 BS

UNIT
1 AC

TIME
0 BS

TIME
0 BS

▶ Press

ENTER

3. Maximum Density

▶ Press

%COMP
.

 until "**Md**" is displayed.

▶ Press

MAX
4 A

 and use the numbered keys to enter "**0.0**"

▶ Press

ENTER

4. Asphalt Density Bias

▶ Press

D BIAS
5 B

To enter a positive bias:

▶ Press

ID
+

 and use the numbered keys to enter the asphalt density bias to the nearest 0.001 t/m³.

► Press

ENTER

To enter a negative bias:

► Press

ID
-

 and use the numbered keys to enter the asphalt density bias to the nearest 0.001 t/m³.

► Press

ENTER

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N310

MEASUREMENT (ASPHALT)
CPN MC3

1. Measurement

► Press

START

At the end of the counting period, the following will be displayed:

RXXX	XXX	XXX	XXXX
DaXX		ETOX:XX	T0X:XX
gcc	wet	h2o	dry
Dn	XXXX	XXXX	XXXX
Pr	XXXX	XXXX	XXXX
%		XXXX	XXXX
Md			XXXX
Bi	XXX	XXX	

Record Dn wet as the **wet density** to the nearest 0.001 t/m³.

Pre-March 1988 Nuclear Gauge:

► Press

STEP

UNIT
1 AC

 simultaneously.

Record Ct wet as the **density count**.






► Press

STEP






UNIT
1 AC

 simultaneously to return to the density display.

Post-March 1988 Nuclear Gauge:

- ▶ Press   simultaneously.
- ▶ Press 
- ▶ Press  repeatedly until "**Counts**" is displayed.
- ▶ Press 

Record Ct wet as the **density count**.

- ▶ Press   simultaneously to return to the density display.
- ▶ Press 
- ▶ Press  repeatedly until "**Density**" is displayed.
- ▶ Press 

OPERATING INSTRUCTION N311

TEST PARAMETERS (ASPHALT)
CPN MC1DR; MC1DR-P

* *The MC1DR has no keypad facility to set parameters*

1. **Asphalt Mode**

- ▶ Press

MAX

ENTER
- ▶ Press

STEP

▼

repeatedly until the following is displayed:

Marshall Test?
- ▶ Press

MAX

ENTER
- ▶ Press

STEP

▼

repeatedly until a value less than "**1.000 g/cm³**" is displayed (a value of "**0.0 g/cm³**" is preferred).
- ▶ Press

START

EXIT

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N312

MEASUREMENT (ASPHALT)
CPN MC1DR; MC1DR-P

1. Measurement



Press



At the end of the counting period,
the following will be displayed:

MC-1DR

Wet Den	X.XX
Moi Den	X.XX

MC-1DR-P

TotDen	X.XX
TotWater	X.XX

Record Wet Den or TotDen as the **wet density** to the nearest 0.001 t/m³.



Press



repeatedly until the following is
displayed:

Dcount	XXXXX
Mcount	XXXX

Record Dcount as the **density count**.

After 30 seconds, the display will turn off.



Press



to restore the display.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N313

TEST PARAMETERS (ASPHALT) HUMBOLDT 5001EZ

1. Start-up

- ▶ Press PWR and allow the nuclear gauge to complete the initialising routine.

The following will be displayed:

```
*DATA    XX/XX/XX
*SETUP   XX:XX:XX
*ENGINEERING
                                DEPTH=SAF
```

- ▶ Press F2 and the following will be displayed:

```
*SET UP 2
*SET MEASUREMENT MODES
*SET TRNCH COR.
*SET TARGETS
```

2. Measurement Units

- ▶ Press F1 and the following will be displayed:

```
*SET DATE
*SET TIME
*UNITS = PCF/SI
```

- ▶ Press F3 repeatedly until “SI” flashes.

- ▶ Press MAIN
MENU and the display will return to the main menu.

3. Count Time

► Press F2 F2

The following will be displayed:

MEAS	=FAST/NORM/SLOW
STD	=4MIN/16MIN
TYPE	=ASPH/SOIL/THIN
DEPTH	=AUTO/MANUAL

► Press F1 repeatedly until **“NORM”** flashes.

4. Asphalt Mode

► Press F3 repeatedly until **“ASPH”** flashes.

5. Depth

► Press F4 repeatedly until **“AUTO”** flashes.

► Press MAIN
MENU and the display will return to the main menu.

6. Maximum Density

► Press MAX
“D” and the following will be displayed:

MAXD =	XXXX
*INCREASE	
*DECREASE	

- ▶ Press **F4** to decrease the displayed value until a value of 900 kg/m³ is obtained.
- ▶ Press **MAIN MENU** and the display will return to the main menu.

7. Asphalt Density Bias

There is no facility to set an asphalt density bias using the keypad.

8. Material Moisture Bias

- ▶ Press **F2** and the following will be displayed:

*SET UP 2
 *SET MEASURE MODES
 *SET TRENCH COR.
 *SET TARGETS
- ▶ Press **F4** and the following will be displayed:


MAXD = XXXX LWD= XXXX
 KVAL = X.XXX SPG=X.XXX
 *INCREASE
 *DECREASE
- ▶ Press **F2** repeatedly until the **KVAL** value flashes.
- ▶ Press **F4** repeatedly until a displayed value of “0.0” is obtained.
- ▶ Press **MAIN MENU** and the display will return to the main menu.
- ▶ Press **PWR** if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N314

MEASUREMENT (ASPHALT)
HUMBOLDT 5001EZ

1. Start-up

- Press  and allow the nuclear gauge to complete the initialising routine.

2. Measurement

- Press  and the following will be displayed:

TAKING MEASUREMENT
TIME REMAINING X:XX
DC = X
MC = X DEPTH=BAC

At the end of the counting period,
the following will be displayed:

MEASURE ASPH RESULTS
WD = XXXX.X% %MA = XXX.X
AC = X.X MAXD = XXXX
*NEXTM DEPTH=BAC


Record WD as the **wet density** to the nearest 0.001 t/m³.


(To convert from kg/m³ to t/m³, divide the displayed value by 1000.)

- Press  and the following will be displayed:

DC = XXXX.X DS = XXXX.X
MC = XX.X MS = XXX.X
VR = XX.XX %AV = X.XX
*LAST MDEPTH=BAC

Record DC as the **density count**.

- Press  and the display will return to the main menu.




- Press  if the nuclear gauge is not required for further use.



THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N315



TEST PARAMETERS (ASPHALT) HUMBOLDT 5001C

1. Start-up


- ▶ Press  and allow the nuclear gauge to complete the initialising routine.
- ▶ Press   simultaneously until the following is displayed:






2. Asphalt Mode


- ▶ Press  repeatedly until “**ASPH**” is displayed.
- ▶ Press 

3. Maximum Density


- ▶ Press  and the following will be displayed:








If a value of “**0.0**” is displayed:

- ▶ Press  to retain the displayed value.

If a value other than “0.0” is displayed:

- ▶ Press and hold  and use the numbered keys to enter a value of “0.0”.

- ▶ Press 
 repeatedly until the following is displayed: 


4. Asphalt Density Bias

There is no facility to enter an asphalt density bias using the keypad.

- ▶ Press  if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N316

MEASUREMENT (ASPHALT)
HUMBOLDT 5001C

1. Start-up

- Press

ON

 and allow the nuclear gauge to complete the initialising routine.

2. Measurement

- Press

CLEAR

ENTER

SHIFT

 simultaneously until the following is displayed:

XXX

0:0
- Press

TRENCH

NORM

 and the following will be displayed:

C:XXX

1.00

At the end of the counting period, the following will be displayed:

XXX

XXXX

Record the displayed value as the **wet density** to the nearest 0.001 t/m³.

(To convert from kg/m³ to t/m³, divide the displayed value by 1000.)

- Press

7

DC

 and record the displayed value as the **density count**.
- Press

SHIFT

CLEAR

ENTER

 simultaneously until the following is displayed:

XXX

0:0
- Press

OFF


 if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK



OPERATING INSTRUCTION N317

TEST PARAMETERS (ASPHALT) HUMBOLDT 5001P

1. Start-up

- ▶ Press  and allow the nuclear gauge to complete the initialising routine.



2. Depth

- ▶ Press  **OR**  repeatedly until the required measurement depth is displayed.


3. Maximum Density


- ▶ Press 

If a value of "0.0" is displayed:

- ▶ Press   to retain the displayed value.

If a value other than "0.0" is displayed:

- ▶ Press and hold  and use the numbered keys to enter a value of "0.0".

- ▶ Press   to retain the displayed value.


4. Asphalt Density Bias

There is no facility to enter the asphalt density bias using the keypad.




5. Material Moisture Bias



If a value of "**0.0**" is displayed:




If a value other than "**0.0**" is displayed:






OPERATING INSTRUCTION N318

MEASUREMENT (ASPHALT)
HUMBOLDT 5001P

1. Start-up

- Press  and allow the nuclear gauge to stabilise for at least ten minutes before commencing the test.


2. Measurement

- Press  and the following will be displayed:
- 


At the end of the counting period, the following will be displayed:




Record the displayed value as the **density count**.

- Press  and record the displayed value as the **wet density** to the nearest 0.01 t/m^3 .


(To convert from kg/m^3 to t/m^3 , divide the displayed value by 1000.)

- Press  if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK









OPERATING INSTRUCTION N319

TEST PARAMETERS (ASPHALT)
INSTROTEK XPLOER 3500**1 START UP**





- ▶ Press  and allow the nuclear gauge to complete the self-test routine.


2 UNITS

When <READY> is displayed


- ▶ Press  and the following is displayed: 
- ▶ Press  repeatedly until the following is displayed: 
- ▶ Press  and the following is displayed: 
- ▶ Press  to set the desired unit.
- ▶ Press  and the display will return to <READY>.

3 COUNT TIME


- ▶ Press  and the following is displayed: 
- ▶ Press  to set the desired count time. 


- Press  and the display will return to <READY>.

4 DEPTH


- Press  the following is displayed:

DEPTH: XX mm
UP/DOWN or ENTER


- Press  repeatedly until the required test depth is displayed.

- Press  and the display will return to <READY>.

5 ASPHALT MODE AND MAXIMUM DENSITY

- Press  and the following is displayed:

ENTER selects PR
DOWN selects MA


- Press  and the following is displayed:

MA: XXXXX
Change value?

To retain the displayed value, go to 5.1.


To change the displayed value, go to 5.2.

5.1 Retain Value


- Press  to retain the displayed value.

The display will return to <READY>. Go to 6.

5.2 Change the Value



- Press  to change the displayed value of MA.

The following is displayed:












MA: XXXXX
UP/DOWN or ENTER

For each digit:

- Press  repeatedly until the required number is displayed.
- Press  to confirm each number.

The display will return to <READY>.

6 MATERIAL WET DENSITY BIAS

- Press  and the following is displayed: 
- Press  and the following is displayed: 
- Press  and the following is displayed: 
- Press  and the following is displayed: 
- OR
- 

To disable the material wet density bias, go to 6.1.

To enable the material wet density bias, go to 6.2.

6.1 Disable Material Wet Density Bias

► Press

ON
YES

 to disable the density offset.

OR

► Press

OFF
NO

 to confirm that the density offset is to remain disabled.

The following will be displayed:

Density Offset Disabled

The display will return to <READY>.

6.2 Enable Material Wet Density Bias

► Press

ON
YES

 to enable the density offset.

OR

► Press

OFF
NO

 to confirm that the density offset is to remain enabled.

The following will be displayed:

D Off = XXXX kg/m ³ UP/DOWN or ENTER
--

To retain the displayed value, go to 6.2.1.

To change the displayed value, go to 6.2.2.

6.2.1 Retain the Value

► Press

ON
YES

 and the following will be displayed:

Density Offset Enabled

The display will return to <READY>.

6.2.2 Change the Value

► Press

UP

 for a positive value.

OR

- ▶ Press DOWN for a negative value.

For each digit:

- ▶ Press DOWN until the required number is displayed.
- ▶ Press START
ENTER to confirm each number.

The following will be displayed briefly:


Density Offset
Enabled

The display will return to <**READY**>.

THIS PAGE IS INTENTIONALLY BLANK


OPERATING INSTRUCTION N320

MEASUREMENT (ASPHALT)
INSTROTEK XPLOER 3500**1 START UP**

- Press  and allow the nuclear gauge to complete the self-test routine.


2 MEASUREMENT

When <**READY**> is displayed

- Press  and the following is displayed:

Time = XX sec
Depth: XX mm


At the end of the counting period:


- Press  repeatedly until the required values are displayed.

Record the following values as appropriate:

- WD as the **wet density** to the nearest 0.001 t/m^3 .
- D Count as the **density count**.

(To convert from kg/m^3 to t/m^3 , divide the displayed value by 1000.)

- Press  and the display will return to <**READY**>.

- Press  if the nuclear gauge is not required for further use.

THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N321

TEST PARAMATERS (ASPHALT)
TROXLER 3440P**1 START UP**

- ▶ Turn the power switch on and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT UNITS

When **<READY>** is displayed

- ▶ Press SETUP

- ▶ Press 2

The following will be displayed:

- Units -

1. pcf
2. kg/m3
3. g/cm3

- ▶ Press 2

The following will be briefly displayed:

Metric Units
Kg/m3
ENABLED

The display will return to **<SETUP>**.

3 COUNT TIME

- ▶ Press SETUP

► Press

1

and the following is displayed:

TIME: XX
1 - 15 sec
2 - 1 min
3 - 4 min

► Press

2

The following will be briefly displayed:

COUNT TIME
1 min

The display will return to <READY>.

4 ASPHALT MODE

► Press

MODE

The following will be displayed:

MODE: XXXX
Select: 1 - ASPHALT
2 - SOIL
Press # to Select

► Press

1


The following will be displayed briefly:

Asphalt Mode
ENABLED


The display will return to <READY>.

5 MATERIAL WET DENSITY BIAS


► Press  the following is displayed:



-OFFSET-
1 - Dens. -OFF-
2 - Moist -OFF-
3 - Trench -OFF-

► Press 

The following will be displayed:



Density Offset
xx kg/m3
1. Enable 2. Disable
3. Change Offset

To disable the material wet density bias, go to Step 6.1.


To enable the material wet density bias, go to Step 6.2.

To change the material wet density bias, go to Step 6.3.

5.1 Disable Material Wet Density Bias

► Press 

The following will be displayed briefly:



Density Offset
DISABLED

The display will return to <READY>. Go to 7.

5.2 Enable Material Wet Density Bias

► Press 

The following will be displayed:

Density Offset
ENABLED

5.3 Change Material Wet Density Bias

- Press 3 the following is displayed:

Density Offset
xx kg/m³
Select (+/-)
Input and <ENTER>

- Use the numbered keys to enter the required value to the nearest 1 kg/m³.
(To convert from t/m³ to kg/m³, multiply the material wet density bias by 1000.)

- Press ENTER
START

The following will be displayed briefly:

Density Offset
ENABLED

The display will return to <READY>.

6 MATERIAL MOISTURE BIAS

- Press OFFSET the following is displayed:

-OFFSET--Select:
1 - Dens. -OFF-
2 - Moist. -OFF-
3 - Trench -OFF-

- Press 2

The following will be displayed:

Moisture Offset
1. xxxx 2. xxxx
3. xxxx 4. xxxx
5. New 6. Disable

6.1 Disable Material Moisture Bias

► Press

6

The following will be displayed:

Moisture Offset
DISABLED

The display will return to <READY>. Go to Step 8.

6.2 Enable the Material Moisture Bias

► Press the number corresponding to any of the stored values.

6.3 Change a Material Moisture Bias Value

► Press

5

the following is displayed:

Select Offset Source
1. Manual Entry
2. Gauge Derived

For manual entry:

► Press

1

the following is displayed:

True Moisture %
x.xx
Press <ENTER>

Use the numbered keys to enter the average oven dry moisture content to the nearest 0.01%.

► Press

ENTER
START

the following is displayed:

Gauge Moisture %
0.00%
Press <ENTER>

Use the numbered keys to enter the average standard blocks moisture content to the nearest 0.01%.

► Press ENTER
START the following is displayed:

K = xxxx
Do you want to save
this value for later use ?

To save the displayed value:

► Press YES the following is displayed:

Select Memory Cell
1. 2.
3. 4.
Press # to Select

► Press a numbered key (1, 2, 3 or 4) to select a memory location in which to save the value.

The following will be displayed briefly:

K x.xx
ENABLED

If the value is not to be displayed:

► Press NO

The display will return to <READY>.

For gauge derived:

► Press 2 the following is displayed:

True Moisture %
x.xx
Press <ENTER>

Use the numbered keys to enter the true moisture content to the nearest 0.01%.

► Press ENTER
START the following is displayed:

Place gauge on soil,
Lower rod and
Press any key

Place the gauge on the measurement site and press any key.

At the completion of the counting period the following will be displayed:

K: ##.##
Save This Value for
Later Use ?

To save the value:

► Press

YES

To enable the value without storing:

► Press

NO

7 TRENCH OFFSET

► Press

OFFSET

the following is displayed:

-OFFSET-
1 - Dens. -OFF-
2 - Moist. -OFF-
3 - Trench -OFF-

► Press

3

the following is displayed:

Trench Offset
M: 0 D: 0
1. Enable 2. Disable
3. Change Offset

To enable the trench offset:

► Press

1

The following is displayed:

Trench Offset
ENABLED

To disable the trench offset:

► Press

2

The following is displayed:

Trench Offset
DISABLED

To change the trench offset:

► Press

3

The following is displayed:

Place Gauge in
trench on Std.
Block in SAFE Pos.
Press <START>

► Press

ENTER
START

At the end of the counting period the display will return to <READY>.

► Turn the power switch off if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N322

MEASUREMENT (ASPHALT)
TROXLER 3440P**1 START UP**

- ▶ Turn the power switch on and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT

When <**READY**> is displayed

- ▶ Press  the following is displayed:




Depth: XX mm
PR: XXXX kg/m³
Time: XX sec.

In the manual depth mode the gauge will prompt for the source rod depth. In automatic mode the gauge software reads the depth strip on the source rod to determine the depth.

At the end of the counting period, the following will be displayed:

WD = xxxx
M = x %M = X.X

Record WD as the **wet density**:

- ▶ Press 
- ▶ Press 
- ▶ Press 

The following will be displayed:

DC = xxxx
MC = xx

Record the following values as appropriate:

- DC as the **density count**.
- MC as the **moisture count**.

▶ Press ESC and the display will return to <**READY**>.

▶ Turn the power switch off if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N323**TEST PARAMATERS (ASPHALT)
TROXLER 3430P****1 START UP**

- ▶ Turn the power switch on and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT UNITS

When **<READY>** is displayed

- ▶ Press

SETUP

- ▶ Press

2

The following will be displayed:

- Units -
1. pcf
2. kg/m3
3. g/cm3

- ▶ Press

2

The following will be briefly displayed:

Metric Units
Kg/m3
ENABLED

The display will return to **<SETUP>**.

3 COUNT TIME

- ▶ Press

SETUP

► Press

1

and the following is displayed:

TIME: XX
1 - 15 sec
2 - 1 min
3 - 4 min

► Press

2

The following will be briefly displayed:

COUNT TIME
1 min

The display will return to <READY>.

4 ASPHALT MODE

► Press

MODE

The following will be displayed:

MODE: XXXX
Select: 1 - ASPHALT
2 - SOIL
Press # to Select

► Press

1


The following will be displayed briefly:

Asphalt Mode
ENABLED

The display will return to <READY>.

5 MATERIAL WET DENSITY BIAS


► Press  the following is displayed:



-OFFSET-
1 - Dens. -OFF-
2 - Moist -OFF-
3 - Trench -OFF-

► Press 

The following will be displayed:



Density Offset
xx kg/m3
1. Enable 2. Disable
3. Change Offset

To disable the material wet density bias, go to Step 6.1.


To enable the material wet density bias, go to Step 6.2.

To change the material wet density bias, go to Step 6.3.

5.1 Disable Material Wet Density Bias

► Press 

The following will be displayed briefly:



Density Offset
DISABLED

The display will return to <READY>. Go to 7.

5.2 Enable Material Wet Density Bias

► Press 

The following will be displayed:

Density Offset
ENABLED

5.3 Change Material Wet Density Bias

- Press 3 the following is displayed:

Density Offset
xx kg/m³
Select (+/-)
Input and <ENTER>

- Use the numbered keys to enter the required value to the nearest 1 kg/m³.
(To convert from t/m³ to kg/m³, multiply the material wet density bias by 1000.)

- Press ENTER
START

The following will be displayed briefly:

Density Offset
ENABLED

The display will return to <READY>.

6 MATERIAL MOISTURE BIAS

- Press OFFSET the following is displayed:

-OFFSET--Select:
1 - Dens. -OFF-
2 - Moist. -OFF-
3 - Trench -OFF-

- Press 2

The following will be displayed:

Moisture Offset
1. xxxx 2. xxxx
3. xxxx 4. xxxx
5. New 6. Disable

6.1 Disable Material Moisture Bias

► Press

6

The following will be displayed:

Moisture Offset
DISABLED

The display will return to <READY>. Go to Step 8.

6.2 Enable the Material Moisture Bias

► Press the number corresponding to any of the stored values.

6.3 Change a Material Moisture Bias Value

► Press

5

the following is displayed:

Select Offset Source
1. Manual Entry
2. Gauge Derived

For manual entry:

► Press

1

the following is displayed:

True Moisture %
x.xx
Press <ENTER>

Use the numbered keys to enter the average oven dry moisture content to the nearest 0.01%.

► Press

ENTER
START

the following is displayed:

Gauge Moisture %
0.00%
Press <ENTER>

Use the numbered keys to enter the average standard blocks moisture content to the nearest 0.01%.

► Press ENTER
START the following is displayed:

K = xxxx
Do you want to save
this value for later use ?

To save the displayed value:

► Press YES the following is displayed:

Select Memory Cell
1. 2.
3. 4.
Press # to Select

► Press a numbered key (1, 2, 3 or 4) to select a memory location in which to save the value.

The following will be displayed briefly:

K x.xx
ENABLED

If the value is not to be displayed:

► Press NO

The display will return to <READY>.

For gauge derived:

► Press 2 the following is displayed:

True Moisture %
x.xx
Press <ENTER>

Use the numbered keys to enter the true moisture content to the nearest 0.01%.

► Press ENTER
START the following is displayed:

Place gauge on soil,
Lower rod and
Press any key

Place the gauge on the measurement site and press any key.

At the completion of the counting period the following will be displayed:

K: ##.##
Save This Value for
Later Use ?

To save the value:

► Press

YES

To enable the value without storing:

► Press

NO

7 TRENCH OFFSET

► Press

OFFSET

the following is displayed:

-OFFSET-
1 - Dens. -OFF-
2 - Moist. -OFF-
3 - Trench -OFF-

► Press

3

the following is displayed:

Trench Offset
M: 0 D: 0
1. Enable 2. Disable
3. Change Offset

To enable the trench offset:

► Press

1

The following is displayed:

Trench Offset
ENABLED

To disable the trench offset:

► Press

2

The following is displayed:

Trench Offset
DISABLED

To change the trench offset:

► Press

3

The following is displayed:

Place Gauge in
trench on Std.
Block in SAFE Pos.
Press <START>

► Press

ENTER
START

At the end of the counting period the display will return to <READY>.

► Turn the power switch off if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N324

MEASUREMENT (ASPHALT)
TROXLER 3430P**1 START UP**

- ▶ Turn the power switch on and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT

When <**READY**> is displayed

- ▶ Press  the following is displayed:




Depth: XX mm
PR: XXXX kg/m³
Time: XX sec.

In the manual depth mode the gauge will prompt for the source rod depth. In automatic mode the gauge software reads the depth strip on the source rod to determine the depth.

At the end of the counting period, the following will be displayed:

WD = xxxx
M = x %M = X.X

Record WD as the **wet density**:

- ▶ Press 
- ▶ Press 
- ▶ Press 

The following will be displayed:

DC = xxxx
MC = xx

Record the following values as appropriate:

- DC as the **density count**.
- MC as the **moisture count**.

▶ Press ESC and the display will return to <**READY**>.

▶ Turn the power switch off if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N325

TEST PARAMETERS (ASPHALT)
TROXLER 3450**1 SET UP**

- Press ON and allow the nuclear gauge to complete the self-test routine.

2 UNITS

When **<READY>** is displayed:

- Press

SPECIAL

- Press

4

To access the Gauge Setup menu.

1-	Set Time/Date	↑
2-	Print Set-Up	
3-	Depth Indicator	
4-	Set Beeper Level	

Scroll through the menu using the arrow keys.

- Press

8

and the following is displayed:

UNITS in XXX
1 – PCF
2 – kg/m ³
3 – g/cm ³

- Press

2

and the following is displayed:

UNITS IN kg/m ³

The display will return to the Gauge Setup menu.

3 COUNT TIME

► Press TIME and the following is displayed:

COUNT TIME: XX
1 – 15 sec
2 – 1 min
3 – 4 min

► Press 2 and the following is displayed:

-COUNT TIME-
60 sec

The display will return to <READY>.

4 ASPHALT MODE

► Press MODE and the following is displayed:

- MODE -
1 – Soil Mode
2 – Asphalt Mode
3 – Thin Layer Mode

► Press 2

And the following will be displayed briefly:

Asphalt Mode Enabled

The display will return to <READY>.

5 MATERIAL WET DENSITY BIAS

► Press OFFSET and the following is displayed:

OFFSET Select
1 – Wet Density OFF
2 – Moisture OFF
3 – Trench OFF



The following will be displayed:

Wet Density Offset:
xxxx kg/m³
1 – Enable 2 – Disable
3 – Change Offset

To disable the material wet density bias:



Wet Density Offset
DISABLED

To enable the material wet density bias:




Wet Density Offset
ENABLED

5.1.1 Change the Value



Wet Density Offset
xxxx kg/m³
Select (+/-)



- Use the numbered keys to enter the required value to the nearest 1kg/m^3 .

- Press

ENTER

The following will be displayed:

Density Offset

ENABLED

The display will return to <READY>.

6 MATERIAL MOISTURE BIAS

- Press

OFFSET

and following is displayed:

OFFSET Select:
1 – Wet Density OFF
2 – Moisture OFF
3 – Trench OFF

- Press

2

The following will be displayed:

Moisture Offset:

K = 0.00

1 – Enable 2 – Disable

3 – Change Offset

To disable the moisture offset:

- Press

2

and following is displayed:

Moisture Offset
DISABLED

To enable the moisture offset:

- Press 1 and following is displayed:

Moisture Offset
ENABLED

6.1.1 Change the Value

- Press 3 and the following is displayed:

Moisture Offset
1 – Stored Offset
2 – Gauge Derived
3 – Keypad Entry

To select a stored offset:

- Press 1 and the following is displayed:

Moisture Offset
Select K Value Cell:
1 – 0.00 2 – 0.00
3 – 0.00 4 – 0.00

- Use the numbered keys to enter the required value to the nearest 0.01%.

The display will return to <READY>.

6.1.2 Change to a Gauge-Derived Value

To change the moisture bias to a gauge-derived value:

- Press 3 and the following is displayed:

Moisture Offset
1 – Stored Offset
2 – Gauge Derived
3 – Keypad Entry

- Press 2 and the following is displayed:

Gauge Derived
Moisture Offset
1 – Measure Moisture
2 – Input True Moist

- Press 1 and the following is displayed:



Place Gauge On
Surface To Be Tested
Press START For 4
One – Minute Counts



The gauge displays the progress of the measurements. After each reading the gauge displays the results. To continue to the next measurement:



After the last measurement:



Moisture Offset
1 – Stored Partial
Moisture Offset
2 – Input True Moist

To enter the true moisture later:




To overwrite the partial offset:



To use the stored partial offset:



To enter the true moisture now:



Input True Moisture
xxxxx %
ENTER When Done

7 TRENCH OFFSET

► Press **OFFSET** and following is displayed:

OFFSET Select:
1 – Wet Density OFF
2 – Moisture OFF
3 – Trench OFF

► Press **3** and following is displayed:

Trench: TMO = xxxx
TDO = xxxx xxxx
1 – Enable 2 - Disable
3 – Change Offset

To disable the trench offset:

► Press **2** and following is displayed:

Trench Offset
DISABLED

To enable the trench offset:

► Press **1** and following is displayed:

Trench Offset
ENABLED

To create a new trench offset:

► Press **3** and following is displayed:

Set Rod To STD Pos
Press START For
1 Minute STD Count
In Trench

Position the gauge inside the trench and:

► Press **START**

The gauge will display the progress of the standard count operation.

After the standard count the gauge displays:

New Trench Offset
TMO = xxxx
TDO = xxxx xxxx
Want To Accept ?

To enable the new trench offset:

► Press

YES


To create another trench offset:

► Press

NO

OPERATING INSTRUCTION N326

MEASUREMENT (ASPHALT)
TROXLER 3450**1 SET UP**

- Press  and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT


When <**READY**> is displayed:

- Press 

In the manual depth mode the gauge will prompt for the source rod depth.

In the automatic depth mode the gauge software reads the depth strip on the source rod to determine the source rod depth.

At the end of the counting period, the following will be displayed:



%MA = xxxx %
WD = xxxx kg/m³
%VOIDS = xxxx

Record the following values:

- % MA as the **percent Marshall** to the nearest 0.1%.
- WD as the **wet density** to the nearest 0.001 t/m³.
- %VOIDS = 100 x 1-WD/VOIDLESS (when enabled).

(To convert from kg/m³ to t/m³, divide the displayed value by 1000.)

- Press 

And the following will be displayed:

- Counts -

DC: xxxxx xxxx

Record the following values as appropriate:

- DC for system 2 (upper right reading) as the **density count**.

- ▶ Press

ESC

 and the display will return to <READY>.

- ▶ Press

OFF

 if the nuclear gauge is not required for further use.

OPERATING INSTRUCTION N327

TEST PARAMETERS (ASPHALT)
CPN MC1 AND MC3 ELITE**1 SET UP**

- Press

ON YES

 and allow the nuclear gauge to complete the self-test routine.

2 UNITS

- Press

MENU

 the first screen will be:
- | |
|--------------------|
| 1. Recall |
| 2. Set depth |
| UP/DOWN for next |
| Select #, ESC exit |
-
- Press

DOWN

 the following is displayed:
- | |
|--------------------|
| 11. Auto scroll |
| 12. Set units |
| UP/DOWN for next |
| Select #, ESC exit |
-
- Press

12

 (button **1** then **2**)
- | |
|--------------------|
| 1. PCF |
| 2. kg/m3 |
| 3. GCC |
| Select #, ESC exit |
-
- After selecting the unit of measurement the gauge returns to the menu screen
- | |
|--------------------|
| 11. Auto scroll |
| 12. Set units |
| UP/DOWN for next |
| Select #, ESC exit |
-
- Press

ESC

 returns to ready screen
- | |
|-------------------------|
| GAUGE READY |
| COUNT TIME: # min |
| Depth: ### Offset: N |
| <date> <time> |

3 COUNT TIME

- Press



and the following is displayed:

Cnt Time: ## min.
UP/DOWN TO CHANGE
YES to Accept
ESC to Exit

- Press UP and DOWN to set the desired count time.

- Press



returns to ready screen

GAUGE READY
COUNT TIME: # min
Depth: ### Offset: N
<date> <time>

4 DEPTH

The Elite gauge is equipped with an automatic non-magnetic depth indicator. The depth is automatically read as you lower the source into the measure position and the appropriate constants are selected to calculate the density.

The gauge can be placed into manual depth mode by disabling the Automatic depth mode from the MENU functions.

5 ASPHALT MODE AND MAXIMUM DENSITY


- Press



and the following is displayed:


1. Proctor
2. Max. Dens
Select #, ESC exit

- Press



For Max Dens.

MA: #### PCF
Change value?
Press YES or NO
ESC to Exit




Enter value for
Max Dens: ### PCF
ENTER to accept
ESC to Exit

Use the number buttons to change the value. Once you have entered the PR value the gauge will return to ready screen.


THIS PAGE IS INTENTIONALLY BLANK

OPERATING INSTRUCTION N328**MEASUREMENT (ASPHALT)
CPN MC1 AND MC3 ELITE****1 SET UP**

- Press  and allow the nuclear gauge to complete the self-test routine.

2 MEASUREMENT


When the ready screen is displayed:


- Press  and the following is displayed:


Depth: XX mm

Time: XX sec

At the end of the counting period the gauge will display:

► 
M Count: ###
D Count: ###
MCR: ### DCR: ###
Press UP/DOWN

► 
WD: #### kg/m3
%MA: ####
%VOIDS: ####
Press UP/DOWN

► 
Moist: #### kg/m3
DD: #### kg/m3
% Mois: .# %PR: .#
Press UP/DOWN

Record the following values:

- WD as the **wet density** to the nearest 0.001 t/m^3 .
- D Count as the **density count**.

(To convert from kg/m^3 to t/m^3 , divide the displayed value by 1000.)

► Press

ON
YES

 and the display will return to the ready screen

► Press

OFF
NO

 if the nuclear gauge is not required for further use.