

SYSTEM 5000

USER MANUAL

PReset 5000

TABLE OF CONTENTS

1	General information	3
2	Introduction to PReset	4
2.1	System requirements	4
2.2	Installation	4
2.3	The PReset menu.....	5
2.4	Navigating in PReset.....	6
3	Menu bar	7
3.1	"File": Retrieve or store a file	7
3.2	"Product": Select product type.....	10
3.3	"Input": Select analog input	12
3.3.1	Thermocouple input	13
3.3.2	Pt100 and Ni100 input	16
3.3.3	Linear resistor.....	19
3.3.4	Voltage input	20
3.3.5	Current input.....	23
3.4	"Output" Select output	25
3.4.1	Analog output.....	26
3.4.2	Relay units	30
3.4.3	Relay output 1/2	30
3.4.4	Display setup	31
3.5	"Serialcom": Transmit or receive data.....	33
3.5.3	Monitor.....	35
3.5.4	Control.....	35
3.6	"Language" Select language	36
3.7	"Option" Select additional options in software.....	37
3.7.1	Front programming: Enable/disable front keys	38
3.7.2	Auto calibration: Enable/disable automatic calibration.....	38
3.7.3	Mains frequency: Select mains frequency	39
3.7.4	Tag no: Enter unit Tag number.....	39
3.7.5	Process calibration	40
3.7.6	Communication port: Select communication port.....	40
3.7.7	Base adjust: Base adjustment of SYSTEM 5000 units.....	41
3.7.8	Setup: Display of the internal data block	41
4	Linerisation	41
4.1	Linear interpolation	43
4.2	Polynomial linearisation	44
4.3	Coefficients.....	45
5	Process calibration	46
5.1	"Only 0% calibration"	46
5.2	"0%-100% & 0% calibration"	46
5.2.1	Ratio metric calibration.....	47
5.3	"Protect process calibration"	47
6	Sensor error	48
	APPENDIX A:Hot keys	49

1 General information

"PReset 5000" is an easy to use, menu driven application software facilitating parameter setup and setup-file management for SYSTEM 5000 units.

At present SYSTEM 5000 units comprise microprocessor based universal transmitters and displays.

Preset enables storage and retrieval of setup files from disk or from the SYSTEM 5000 units.

Printout of setup files including all parameters is available.

This manual is updated for PReset software version 1.02. For later versions please consult the READ.ME file on your PReset system diskette.

2 Introduction to PReset

2.1 System requirements

The PReset software is based on a standard presentation software that will operate on most IBM-compatible PCs with the following configuration:

Memory: min. 512 kB accessible memory
Display: CGA, HCG, EGA, or VGA
Operating system: DOS 3.1 or later versions
Printer (option): Epson or IBM compatible ASCII printer
Mouse (option): Microsoft compatible mouse (MOUSE.COM)

2.2 Installation

The diskette contains the following files:

READ.ME Latest changes
README.BAT Program for reading the READ.ME file
INSTALL.BAT PReset installation program
INSTALL.TXT Installation guide for DOS, WIN 3.xx and WIN 95
PRESET.ZIP PReset ZIP packed file

The program is a packed ZIP file format, and the command for the installation is the following:

```
C:\>A:INSTALL (Enter)
```

This will install PReset in the default directory C:\PRESET. If the program is to be installed in another directory, type the following:

```
C:\>A:INSTALL[DIR] (Enter)
```

where [DIR] is the path of the directory in which you wish to install PReset, i.e. C:\PROGRAMS.

NOTE: The directory must already exist.

PRreset is always installed in a directory of it's own, in this case C:\PROGRAMS\PRESET).

For installation and start-up guidance, please read install.txt under edit, notebook, or other text editor. After the installation all the necessary files are in the chosen directory (default directory: C:\PRESET)


The INI file is created the first time PReset is exited or transferred from the previous PReset installation:

PRESET.INI PReset initialisation file

Always remember to create a working copy of the PReset diskette before installation starts. Please consult your DOS-manual for copying procedure.

2.3 The PReset menu

To understand PReset, the illustration below may be useful:



The upper **menu bar** contains **the main menu**. Selecting a submenu causes the corresponding **pull-down menu** to appear.

Selecting a parameter from a pull-down menu often calls for a **dialog window** presenting additional information.

Entering non valid data causes an **Error window** to appear.

The **Info line** in the bottom of the screen contains helpful information like e.g.: Alt-X Exit.

When not covered by pull-down windows, dialog windows or error windows the main screen will contain transmitter data as shown below:

```

File Product Input Output SerialCom Language Option          21:21:04
-----
PreTrans 5111
Date:          1992-11-16
Serial no.:    0
Tag no.:       TAG-01

Analog input                                     Analog output

Input type:    100 DIN/IEC                        Output type:   Current
Input range:   0.00-100.00 °C                    Output range:  0.00- 20.00 mA
Connection:    2-wire                            Characteristic: Direct
Cold junction comp: -----                    Sensor error:  -----
External calib: Passive
Response time: 1.00 sec                          Linearisation: Yes

Relay output 1                                   Relay output 2

Setpoint:      15.00 mA                          Setpoint:     8.00 mA
Hysteresis:    2.00 mA                          Hysteresis:   1.00 mA
Action:        Increasing                        Action:        Decreasing
Delay:         1.00 sec                          Delay:         5.00 sec
Sensor error:  No                               Sensor error:  No
Relay contact: Normally closed                   Relay contact: Normally closed

Alt-F1 Help   F10 Menu   Alt-X Exit                                         V1.06

```

2.4 Navigating in PReset

There are several ways to move around in the PReset environment. For the inexperienced user a combination of the arrow keys and the Enter and Escape keys is recommended, whereas the experienced user will benefit from using the single letter commands, the hot-keys and, particularly, a mouse.

All four methods will be illustrated in the following example, but for the rest of the manual only the Arrow-Enter-Escape combination will be shown.

To select the English language option from the main status screen use one of the following methods:

- 1) Arrow keys
 - Press F10 to get to the menu bar
 - Move to the Language menu using the ← → arrows
 - Press Enter to activate the pull-down menu
 - Move to English using the ← → arrow keys
 - Press Enter to activate the English language
- 2) Single letter commands
 - Press Alt-L to open the language pull-down menu
 - Press E to activate the English language
- 3) Hot keys
 - Press Shift-F2 to activate the English language
- 4) Mouse
 - Click Language to open the language pull-down menu
 - Click English to activate the English language

A list of available hot keys is shown in appendix A.

3 Menu bar

All pull-down menus are listed in the menu bar in the top of the screen.

Pressing "F10" will indicate cursor position in the menu bar.

Move the cursor to the desired function by operating "← →".

Open the pull-down menu by pressing CR.

The cursor is moved to a function within the pull-down menu by operating "↑ ↓".

Main menu function may also be changed when the cursor is positioned in a pull-down menu by operating "← →".

Return to the menu bar by executing one of the functions in the pull-down menu and press "F10" again. To remove a pull-down menu press "Escape".

3.1 "File": Retrieve or store a file.

3.1.1. Delete - delete a specific setup file from disk.

Move the cursor to "Delete" and press CR. The dialog window "Delete a file" will appear.

Use "Tab" to select from menu options and press CR.

"Name" enter file name to be deleted or enter new directory name to change directory.

"Files" lists files of the current directory.
Select file by operating "↑ ↓".

"OK" deletes the file specified.

"Cancel" returns to the main screen.

"Help" Not implemented.

3.1.2. Open - retrieve a specific setup file from disk.

Move the cursor to "Open" and press CR. The dialog window "Open a file" will appear.

Use "TAB" to select from menu options and press CR.

"Name" enter file name to be retrieved or enter new directory name to change directory.

"Files" lists files of the current directory.
Select file by operating "↑ ↓".

"Open" opens the file specified. The main screen is updated.

"Cancel" return to the main screen.

"Help" not implemented.

3.1.3. Save - store current setup file.

Move the cursor to "Save" and press CR. The dialog window "Save a file" will appear.

Use "TAB" to select from menu options and press CR.

"Name" enter file name to be stored or enter new directory name to change directory.

"Files" lists files of the current directory.

Select file by operating "↑↓".

"OK" stores the current file and returns to main screen.

"Cancel" returns to main menu.

"Help" Not implemented.

3.1.4. Print - printout of all parameters in the current file.

3.1.5. Exit - return to DOS.

Delete file	F2		
Open file	F3		
Save file	F4		
Print setup	F5		
Exit	Alt-X	Analog output	

100 DIN/IEC Output type: Current

Input range: 0.00-100.00 °C Output range: 0.00- 20.00 mA

Connection: 2-wire Characteristic: Direct

Cold junction comp: ----- Sensor error: -----

External calib: Passive Linearisation: Yes

Response time: 1.00 sec

Relay output 1 Relay output 2

Setpoint: 15.00 mA Setpoint: 8.00 mA

Hysteresis: 2.00 mA Hysteresis: 1.00 mA

Action: Increasing Action: Decreasing

Delay: 1.00 sec Delay: 5.00 sec

Sensor error: No Sensor error: No

Relay contact: Normally closed Relay contact: Normally closed

Date: 1993-1-2

Serial nr.: [n] Delete a File

Tag no.:

Analog input	Name	*.SUP	Delete
Input type:	Files	TAG01.SUP	Cancel
Input range:		TAG02.SUP	
Connection		..\	
Cold junction			
External cali			
Response time			
Relay output			
Setpoint:			
Hysteresis:			
Action:			
Delay:			
Sensor error:			
Relay contact:			

C:\PRESET*.SUP Directory Dec 26, 1992 6:38pm

Relay contact: Normally closed Relay contact: Normally closed

Date: 1993-1-2

Serial nr.: [n] Open a File

Tag no.:

Analog input	Name	*.SUP	OK
Input type:	Files	TAG01.SUP	Cancel
Input range:		TAG02.SUP	
Connection		..\	
Cold junction			
External cali			
Response time			
Relay output			
Setpoint:			
Hysteresis:			
Action:			
Delay:			
Sensor error:			
Relay contact:			

C:\PRESET*.SUP Directory Dec 26, 1992 6:38pm

Relay contact: Normally closed Relay contact: Normally closed

```

File Product Input Output SerialCom Language Option 16:16:30
PRetrans 5111
Date: 1993-1-2
Serial nr.: [n]
Tag no.:
Analog input
Input type:
Input range:
connection
Cold junction
External cali
Response time
Relay output
Setpoint:
Hysteresis:
Action:
Delay:
Sensor error:
Relay contact: Normally closed

Save a File
Save file as *.SUP
Files
TAG01.SUP
TAG02.SUP
..\
C:\PRESET\*.SUP
Directory Dec 26, 1992 6:38pm
OK
Cancel

urrent
.00- 20.00 mA
irect
-----
es
.00 mA
.00 mA
creasing
.00 sec
o
Normally closed

```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

File Product Input Output SerialCom Language Option 14:21:24
PReView 5511
Date: 1993-11-9
Serial no.: 930742272
Tag no.:
Display scale 0% 0.00
Display scale 100% 50.00
Analog input
Input type:
Input range:
Connection:
Cold junction
External cali
Response time
Relay output
Setpoint:
Hysteresis:
Action:
Delay:
Sensor error:
Relay contact: Normally open

Printer report text
Printer report text
Print Cancel Delete

urrent
00- 20.00 mA
rect
-----
s
0.00
1.00
Increasing
0.00 sec
No
Normally open
Action:
Delay:
Sensor error:
Relay contact:
Increasing
0.00 sec
No
Normally open

```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

3.2 "Product": Select product type

The pull down window contains a list of the available product types. Move the cursor to product type and press CR. The main screen is updated accordingly.

1. PReTrans 5111
2. PReView 5511
3. PReView 5512

Press "F10" for menu bar access.

= PReView 5511					
Date	PReTrans 5111	ALT-1			
Seri	PReView 5511	ALT-2	Display scale	0%	0.00
Tag	PReView 5512	ALT-3	Display scale	100%	199.99
Analog input			Analog output		
Input type:	100 DIN/IEC		Output type:	Current	
Input range:	0.00-100.00 °C		Output range:	0.00- 20.00 mA	
Connection:	2-wire		Characteristic:	Direct	
Cold junction comp:	-----		Sensor error:	-----	
External calib:	Passive				
Responsetime:	1.00 sec		Linearisation:	Yes	
Relay output 1			Relay output 2		
Setpoint:	15.00 mA		Setpoint:	8.00 mA	
Hysteresis:	2.00 mA		Hysteresis:	1.00 mA	
Action:	Increasing		Action:	Decreasing	
Delay:	1.00 sec		Delay:	5.00 sec	
Sensor error:	No		Sensor error:	No	
Relay contact:	Normally closed		Relay contact:	Normally closed	

3.3 "Input": Select analog input

The pull-down window contains a list of all available input types, which can be handled by the transmitter.

The input types are grouped as follows;

1. Thermocouple.
2. Pt100 and Ni100 sensor.
3. Linear resistor.
4. Voltage (V).
5. Current (mA).

Move the cursor to the desired input type by operating the "↑↓" and press CR. The corresponding dialog window will appear.

Use the "TAB" key to get access to the individual parameters in the dialog window. The cursor highlights the current parameter which may be changed.

Certain parameters contain a list of options. Move the cursor to the desired option by operating the "←→" and press "TAB". Move the cursor to "OK" and press CR to accept the total input setup.

In case an input parameter is out of range an error window will appear and inform of the limits of the current input type.

Certain parameters will cause additional dialog windows to appear on the screen. Move the cursor by operating the "TAB" key and press CR.

```

File Product Input Output SerialCom Language Option 16:16:30
111
Date: Thermocouple - B Alt-B
Serial no: Thermocouple - E Alt-E
Tag no.: Thermocouple - J Alt-J
Thermocouple - K Alt-K
Analog input Thermocouple - L Alt-G
Thermocouple - N Alt-M
Input type: Thermocouple - R Alt-R
Input range: Thermocouple - S Alt-D
Connection: Thermocouple - T Alt-T
Cold junction Thermocouple - U Alt-U
External cali Pt 100 (DIN/IEC) Alt-C
Response time Pt 100 (JIS) Alt-Q
Ni 100 Alt-A
Relay output Linear resistor Alt-Z
Voltage input Alt-V
Current input Alt-Y
Setpoint:
Hysteresis:
Action: Increasing
Delay: 1.00 sec
Sensor error: No
Relay contact: Normally open
analog output
output type: Strøm
utput range: 0.00- 20.00 mA
harakteristic: Direct
ensor error: -----
inearisation: Yes
elay output 2
etpoint: 8.00 mA
ysteresis: 1.00 mA
Action: Decreasing
Delay: 5.00 sec
Sensor error: No
Relay contact: Normally closed
Alt-F1 Help F10 Menu Alt-X Exit V1.06
  
```

3.3.1 Thermocouple input

Move the cursor to the desired TC by operating the "↑↓" and press CR.

Enter Input temperature - 0%.

Enter Input temperature - 100%.

Response time:

Enter Response time in seconds.

Linearisation:

"Yes" the input signal will be linearised with respect to temperature.

"No" the input signal will not be linearised.

TC element mode:

"Standard" one TC is connected.

"Differential" two TCs in series are connected. This option will release an additional dialog window "Lowest reference temp.". Enter the lowest reference temperature.

Cold junction comp.:

"Int. CJC/Pt100" select Internal CJC/Pt100 when the CJC terminal with a built-in Pt100 sensor is connected to the transmitter.

"Ext. CJC/Pt100" select External CJC/Pt100 when the cold junction is placed remote from the transmitter. A Pt100 sensor is placed at the cold junction. This option will release an additional dialog window "Cable compensation". Select external calibration enable or enter fixed cable resistance to be compensated.

"Constant CJC" select constant CJC for fixed temperature at the cold junction. This option will release an additional dialog window "Constant CJC". Enter the cold junction temperature.

```

File Product Input Output SerialCom Language Option 14:23:11
PREView 5511
Date: [n] Thermocouple - B
Serial n 0
Tag no.: Input temperature 0% 4.000 °C 0
Analog i Input temperature 100% 850.00 °C 0
Input ty Response time: 1.000 sec 0.00 mA
Input ra
Connecti Linearisation: TC element mode
Cold jun (●) Yes (●) Standard ---
External ( ) Differential
Response
Relay ou Cold junction comp.
(●) Int. CJC / Pt100
( ) Ext. CJC / Pt100
Setpoint ( ) Constant CJC
Hysteres
Action:
Delay: Ok Cancel ing
Sensor e sec
Relay co y open

Alt-F1 Help F10 Menu Alt-X Exit V1.06
  
```

```

Date: [n] Termocoupler - B
Serie no:
Tag no.: Input temperature 0% 300.00ψ °C
Analog i Input temperature 100% 850.00ψ °C
Input ty Respons [n] Error
Input ra Linear Value must be from 400.000 - tial
Connecti (•) Yes 1820.000
Cold jun ( ) No
External
Response
Relay ou Cold ju OK
(•) Int
( ) Ext. CJC / Pt100
Hysteres ( ) Constant CJC
Action: Cancel
Delay:
Sensor e
Relay co (bryde)
    
```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

Date: 1993-1-2
Serial no: 0
Tag no.: TAG-01
Analog input Analog output
Input type: TC-B Output type: Current
Input range: [n] Constant CJC 00- 20.00 mA
Connection: Constant CJC 50.000 °C rect
Cold junction
External cali
Response time
Relay output
Setpoint: 15.00 mA Setpoint: 8.00 mA
Hysteresis: 2.00 mA Hysteresis: 1.00 mA
Action: Increasing Action: Decreasing
Dealy: 1.00 sec Delay: 5.00 sec
sensor error No Sensor error: No
Relay contact: Normally closed Relay contact: Normally open
    
```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

Date: 1993-11-9
Serial no.: 930742272 Display scale 0% 0.00
Tag no.: Display scale 100% 50.00
Analog input [n] Cable compensation
Input type: Enable external calib. rrent
Input range: ( ) Yes 00- 20.00 mA
Connection: (•) No rect
Cold junction
External cali
Response time Fixed cable resistance -5.000 Ω s
in 2 wires
Relay output
Setpoint:
Hysteresis:
Action:
Delay:
Sensor error: No Sensor error: No
Relay contact: Normally open Relay contact: Normally open
    
```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

===== PReTrans 5111 =====
Date:          1993-1-2
Serial no.:    0
Tag no.:      TAG-01
-----
Analog input          Analog output
Input type:         TC-B          Output type:         Current
Input range:  [n]==== Lowest reference temp.==== 00- 20.00 mA
Connection:  [n]==== rect
Cold Junction  Lowest reference temp.          400.00ψ °C  -----
External cali
Response time
Relay output
          Ok      ■          Cancel  ■
          ████████          ████████
Setpoint:         15.00 mA          Setpoint:         8.00 mA
Hysteresis:       2.00 mA          Hysteresis:       1.00 mA
Action:           Increasing        Action:           Decreasing
Delay:            1.00 sec          Delay:            5.00 sec
Sensor error:     No               Sensor error:     No
Relay contact:    Normally closed   Relay contact:    Normally open
-----

```

3.3.2 Pt100 and Ni100 input

Select desired RTD-sensor.

Enter Input temperature - 0%.

Enter Input temperature - 100%.

Response time:

Enter Response time in seconds.

Linearisation:

"Yes" the input signal will be linearised with respect to temperature.

"No" the input signal will not be linearised.

Number of Rtd's in series:

"1" one Pt100 sensor is connected.

"10" 10 Pt100 sensors are connected in series which equals one Pt1000 sensor.

"Specify" this option releases an additional dialog window "Number of Rtd's in series". Enter the number of Rtd's. The number must be within 1-25 or 1-0,25 for parallel connection.

Connection:

"2-wire system" 2-wire cable is connected. This option releases an additional dialog window "Cable compensation". Select external calibration enable/disable, or enter a fixed cable resistance for compensation.

"3-wire system" 3-wire cable is connected. Automatic cable compensation is performed.

"4-wire system" 4-wire cable is connected. Automatic cable compensation is performed.

"Differential" two Rtd's are connected for differential temperature measurement. This option releases an additional dialog window "Cable compensation". Select external calibration enable/disable, or enter a fixed cable resistance for compensation.

Date:	[n]	Pt 100 (DIN/IEC)	
Serial no.:			
Tag no.:	Input temperature	0%	0.000 °C
Analog input	Input temperature	100%	100.00 °C
Input type	Response time:		1.000 sec
Range:			0.00 mA
Connecti	Linearisation:	Number of Rtds in series	
Cold jun	(●) Yes	(●) 1	---
External		() 10	
Response		() Specify	
Relay ou	Connection		
	(●) 2-Wire system		
	() 3-Wire system		
Setpoint	() 4-Wire system		mA
Hysteres	() Differential		mA
Action:			e
Delay:	Ok	Cancel	sec
Sensor e			
Relay co			

Date:	1993-11-9	Display scale	0%	0.00
Serial no.:	930742272	Display scale	100%	50.00
Tag no.:				
Analog input	[n]	Cable compensation		
Input type:	Enable external calib.			rrent
Input range:	() Yes			00- 20.00 mA
Connection:	() No			rect
Cold junction				-----
External cali				
Response time	Fixed cable resistance	5.000	Ω	s
Relay output	in 2 wires			
	Ok	Cancel		
Setpoint:				0.00
Hysteresis:				1.00
Action:				creasing
Delay:				0.00 sec
Sensor error:	No	Sensor error:	No	
Relay contact:	Normally open	Relay contact:	Normally open	

Date:	1992-12-28		
Serial no.:	0		
Tag no.:	TAG-01		
Analog input	[n]	Cable compensation	
Input type:	Enable external Calib.		røm
Range:	(●) Yes		00- 20.00 mA
Connection:	() No		rekte
Cold junction			-----
External cali			
Response time	Fixed cable resistance	8.500	Ω
Relay output	in 2 wires		
	Ok	Cancel	
Setpoint:			8.00 mA
Hysteresis:			1.00 mA
Action:			ldgende
Delay:			5.00 sec
Sensor error:	No	Sensor error:	No
Relay contact:	Normally closed	Relay contact:	Normally open

```

===== PReTrans 5111 =====
Date:          1992-12-28
Serial no.:    0
Tag no.:      TAG-01
-----
Analog input          Analog output
Input type:         Pt 500 DIN/IEC      Output type:         Current
Input range:  [n]===== Number of Rtds in series ===== 00- 20.00 mA
Connection:  [-----]rect
Cold junction Number of Rtd's in series      5.000 [-----]
External cali
Response time  Ok      [█]          Cancel [█]
                [██████]          [██████]
Relay output
Setpoint:         15.00 mA              Setpoint:             8.00 mA
Hysteresis:       2.00 mA               Hysteresis:           1.00 mA
Action:           Increasing             Action:                Decreasing
Delay:            1.00 sec               Delay:                 5.00 sec
Sensor error:     No                    Sensor error:          No
Relay contact:    Normally closed        Relay contact:         Normally open
    
```

3.3.3 Linear resistor

Specify input resistance.

Enter Input resistance - 0%.

Enter Input resistance - 100%.

Response time:

Enter Response time in seconds.

Custom-defined linearisation:

"Yes", see section 4.

"No", output is resistance linear.

Number of R's in series:

"1" one resistor is connected.

"10" 10 resistors are connected in series.

"Specify" this option releases an additional dialog window "Number of R's in series". Enter the number of R's. The number must be within 1-25 or 1-0,25 for parallel connection.

Connection:

"2-wire system" 2-wire cable is connected. This option releases an additional dialog window "Cable compensation". Select external calibration enable/disable, or enter a fixed cable resistance for compensation.

"3-wire system" 3-wire cable is connected. Automatic cable compensation is performed.

"4-wire system" 4-wire cable is connected. Automatic cable compensation is performed.

"Differential" two R's are connected for Ω differential measurement. This option releases an additional dialog window "Cable compensation". Select external calibration enable/disable, or enter a fixed cable resistance for compensation.

Process calibration:

"Yes" see section 5.

"No" input range must be specified in PReset 5000.

```

File Product Input Output SerialCom Language Option 19:34:26
                                     PReTrans 5111
Date: [n] Linear resistance
Serial n
Tag no.: Min. resistance 0% 10.000  $\Omega$ 
Analog i Max. resistance 100% 250.00  $\Omega$ 
Input ty Response time: 1.000 sec
Range:
Connecti Custom-defined lin. Number of resistors in series
Cold jun ( ) Yes ( ) 1
External (•) No ( ) 10
Response (•) Specify
Relay ou Connection: Process calibration
(•) 2-wire system (•) Yes
( ) 3-wire system
Setpoint ( ) 4-wire system (•) No
Hysteres ( ) Differential
Action:
Delay: Ok Cancel
sensor e
Relay co
0.00 mA
---
mA
mA
e
sec
Alt-F1 Help F10 Menu Alt-X Exit V1.06
  
```

```

File Product Input Output Communication Language Option 19:30:05
----- PReTrans 5111 -----
Date: 1993-1-2
Serial no.: 0
Tag no.: TAG-01

Analog input Analog output
Input type: Linear R Output type: Current
Input range: [n]----- Number of resistors in series ----- 00- 20.00 mA
Connection: rect
Cold junction Number of resistors in series 8.000 -----
External cali Response time Ok Cancel j
Relay output

Setpoint: 15.00 mA Setpoint: 8.00 mA
Hysteresis: 2.00 mA Hysteresis: 1.00 mA
Action: Increasing Action: Decreasing
Delay: 1.00 sec Delay: 5.00 sec
Sensor error: No Sensor error: No
Relay contact: Normally closed Relay contact: Normally open

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

```

File Product Input Output SerialCom Language Option 13:20:30
----- PReTrans 5111 -----
Date: 1993-11-11
Serial no.: 930742272
Tag no.:

Analog input Analog output
Input type: [n]----- Procescalibration ----- rrent
Input range: Procescalibration 00- 20.00 mA
Connection: ( ) Only 0% calibration rect
Cold junction (•) 0%-100% & 0% calibration -----
External cali ( ) Protect processcalibratio
Response time

Relay output Ok Cancel

Setpoint: 0.00
Hysteresis: 1.00
Action: Increasing Action: Increasing
Delay: 0.00 sec Delay: 0.00 sec
Sensor error: No Sensor error: No
Relay contact: Normally open Relay contact: Normally open

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

3.3.4 Voltage input

Response time:

Enter Response time in seconds.

Voltage input:

"Specify" Enter any voltage input range not listed in the standard ranges. This option releases an additional dialog window "Voltage input":

Enter Input voltage - 0%

Enter Input voltage - 100%.

Input voltage must be within -250 to +250 Volts limits.

"Bridge input" Enter input voltage for bridge application. This option releases an additional dialog window "Voltage input".

Enter Input voltage - 0%
 Enter Input voltage - 100%.

Input voltage must be within the transmitters configuration limit.

- "Standard 0-1 VDC" input range 0-1V.
- "Standard 0-2.5 VDC" input range 0-2.5 V.
- "Standard 0-5 VDC" input range 0-5 V.
- "Standard 0-10 VDC" input range 0-10 V.
- "Standard 0.2-1 VDC" input range 0.2-1 V.
- "Standard 1-5 VDC" input range 1-5 V.
- "Standard 2-10 VDC" input range 2-10 V.
- "3-wire potentiometer" input range 0-2.5 V direct from potentiometer.

Custom-defined linearisation:

- "Yes" see section 4.
- "No" output is voltage linear.

Process calibration:

- "Yes" see section 5.
- "No" input range must be specified in PReset 5000.

```

File Product Input Output Communication Language Option 19:30:42
PreTrans 5111
Date: [n] Voltage input
Serial n
Tag no.: Response time: 1.000 sec
Analog i
Voltage input Custom-defined lin.
Input ty (•) Specify ( ) Yes
Input ra ( ) Bridge input (•) No 0.00 mA
Connecti ( ) Standard1 0 - 1 VDC
Cold Jun ( ) Standard2 0 - 2,5 VDC
External ( ) Standard3 0 - 5 VDC
Response ( ) Standard4 0 - 10 VDC
Relay ou ( ) Standard5 0,2 - 1 VDC
Setpoint ( ) Standard6 1 - 5 VDC
Hysteres ( ) Standard7 2 - 10 VDC
Action: ( ) Potmeter from 2,5 Vref
Delay:
Sensor e
Relay co
Ok Cancel
  
```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

File Product Input Output Communication Language Option 19:31:56
PreTrans 5111
Date: 1993-1-2
Serial no.: 0
Tag no.: TAG-01
Analog input Analog output
Input type: [n] Voltage input
Input range: Input voltage 0% 1.300000 V røm 00- 20.00 mA
Connection: Input voltage 100% 6.300000 V rekte
Cold junction
External cali
Reaktionstid: j
Relay output
Setpoint:
Hysteresis:
Action: Stigende Reaktion: Faldende
Delay: 1.00 sec Forsinkelse: 5.00 sec
Sensor error: No Føler fejl: Nej
Relay function: Normal (slutte) Relækontakt: Invert. (bryde)
Ok Cancel
  
```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```
===== PReTrans 5111 =====
| Date:          1993-11-11 |
| Serial no.:    930742272 |
| Tag no.:      |
|-----|
| Analog input          Analog output |
| [n]===== Procescalibration =====|
| Input type:         | rrent |
| Input range:        Procescalibration | 00- 20.00 mA |
| Connection:         ( ) Only 0% calibration | rect |
| Cold junction      (•) 0%-100% & 0% calibration | ----- |
| External cali      ( ) Protect processcalibratio |
| Response time |
| Relay output |
|           Ok      ■           Cancel      ■ |
|           ██████████           ██████████ |
| Setpoint:         | 0.00 |
| Hysteresis:      | 1.00 |
| Action:           Increasing      Action:           Increasing |
| Delay:            0.00 sec      Delay:            0.00 sec |
| Sensor error:     No      Sensor error:           No |
| Relay contact:    Normally open      Relay contact:    Normally open |
|-----|
```

3.3.5 Current input

Response time:

Enter Response time in seconds.

Current input:

"Specify" Enter any current input range not listed in the standard ranges. This option releases an additional dialog window "Current input":

Enter Input current - 0%

Enter Input current - 100%.

Input current must be within the transmitters configuration limits.

"Standard 0-20 mA" input range 0-20 mA.

"Standard 4-20 mA" input range 4-20 mA.

"Standard 0-5 mA" input range 0-5 mA.

"Standard 1-5 mA" input range 1-5 mA.

Custom-defined linearisation:

"Yes" see section 4.

"No" output is current linear.

Process calibration:

"Yes" see section 5.

"No" input range must be specified in PReset 5000.

Cable error detection limit:

For current input 4-20mA, cable error detection limit may be defined. Enter error detection limit in mA (value must be below 4mA).

If active sensor error detection on analog- or relay output will activate when input signal is below the error detection limit.

File	Product	Input	Output	SerialCom	Language	Option	19:01:42
				PRetrans	5111		
Date:	[n]	Current input					
Serial n		Response time:	1.000	sec			
Tag no.:							
Analog i		Current input			Custom-defined lin.		
Indgangs		(●) Specify			() Yes		
Range:		() Standard1	0 - 20	mA	(●) No	0.00 mA	
Connecti		() Standard2	4 - 20	mA			
Cold jun		() Standard3	0 - 5	mA			
External		() Standard4	1 - 5	mA	Process calibration	---	
Response						(●) Yes	
Relay ou						(●) No	
Setpoint		Cable error limit:	2.000	mA			
Hysteres		Ok			Cancel		
Action:							
Delay:							
Sensor e							
Relay co						(bryde)	

Alt-F1 Help F10 Menu Alt-X Exit

V1.06

```

PRerans 5111
Date          1993-1-2
Serial no.:   0
Tag no:       TAG-01

Analog input          Analog output
-----[n]----- Current input -----
Input type:          Input current 0%          2.300000 mA          rrent
Range:              Input current 100%        12.900000 mA          00- 20.00 mA
Connection:         rect
Cold junction      Input current 100%        12.900000 mA          -----
External cali
Response time
Relay output
                Ok      Cancel
                █      █
                ██████████ ██████████

Setpoint:          8.00 mA
Hysteresis:        1.00 mA
Action:            Increasing          Action:            Decreasing
Delay:             1.00 sec            Delay:             5.00 sec
Sensor error:     No                  Sensor error:     No
Relay contact:    Normally closed      Relay contact:    Normally open
    
```

Alt-F1 Help F10 Menu Alt-X Exit

V1.06

```

PRerans 5111
Date:          1993-11-11
Serial no.:    930742272
Tag no.:
Analog input          Analog output
-----[n]----- Procescalibration -----
Input type:          Procescalibration          rrent
Input range:         ( ) Only 0% calibration          00- 20.00 mA
Connection:         (•) 0%-100% & 0% calibration          rect
Cold junction      ( ) Protect processcalibratio          -----
External cali
Response time
Relay output
                Ok      Cancel
                █      █
                ██████████ ██████████

Setpoint:          0.00
Hysteresis:        1.00
Action:            Increasing          Action:            Increasing
Delay:             0.00 sec            Delay:             0.00 sec
Sensor error:     No                  Sensor error:     No
Relay contact:    Normally open        Relay contact:    Normally open
    
```

Alt-F1 Help F10 Menu Alt-X Exit

V1.06

3.4 "Output" Select output

The pull-down menu contains the outputs, to which the transmitter can be configured.

The output options are grouped as follows:

1. Analog output.
2. Relay units.
3. Relay output 1.
4. Relay output 2.
5. Display (PReview option only).

Move the cursor to the desired output type by operating "↑↓" and press CR. Hereafter a dialog window dedicated the selection occurs.

Use the "TAB" key to get access to the individual parameters in the dialog window. Only one function may be changed at a time. When the cursor is placed on the function, data can be changed.

Certain parameters contain a list of options, move the cursor to the desired option by operating the "↑↓" and press "TAB". Move the cursor to "OK" and press "CR" to accept the total input setup.

In case a measurement range is out of range an error window will appear and inform the limits of current output type.

Certain parameters will cause additional dialog windows to appear on the screen, move the cursor by operating the "TAB" key and press "CR".

File	Product	Input	Output	SerialCom	Language	Option	16:44:11
Date:	1992-12-		Analog output	Alt-F6			
Serial no.:			Relay units	ALT-F7	cale	0%	-50.00
Tag no.:	DISPL		Relay output 1	ALT-F8	cale	100%	150.00
			Relay output 2	ALT-F9			
			Display	ALT-F10	tput		
Analog input							
Input type:		Pt 100 DIN/IEC	Output type:		Voltage		
Range:		-50.00-150.00 °C	Range:		-2.50- 7.50 V		
Connection:		2-wire	Karakteristik:		Direct		
Cold junction:		-----	Sensor error:		120%		
External calib.:		Passive	Linearisation:		Yes		
Response time:		1.00 sec					
Relay output 1				Relay output 2			
Setpoint:		5.00 V	Setpoint:		1.50 V		
Hysteresis:		1.00 V	Hysteresis:		0.50 V		
Action:		Increasing	Action:		Decreasing		
Delay:		1.00 sec	Delay:		5.00 sec		
Sensor error:		No	Sensor error:		No		
Relay contact:		Normally open	Relay contact:		Normally closed		
Alt-F1 Help F10 Menu Alt-X Exit				V1.06			

3.4.1 Analog output

Define analoge output.

Output type:

"Voltage output" this option will release an additional dialog window "Voltage output". See section 0

"Current output" this option releases an additional dialog window "Current output". See section 0

Sensor error:

Sensor error (open circuit) on the following sensors may be detected: Thermocouple (TC), Pt100 and Ni100 (RTD), and linear resistor. In case of sensor error detection the analog output will react in one of the following ways:

"Off" no function.

"Upscale" output will upscale to 120% of max. value in case of sensor error.

"Downscale" output will downscale to 0% of min. value in case of sensor error.

"Hold" output will remain at the level present 3 updates old.

Lower and upper overload limits:

"Min. limit" Enter in % of span the amount the output signal may be below the defined 0% level, in case the input signal level is below its minimum level.

"Max. limit" Enter in % of span the amount the output may exceed the defined 100% level, in case the input signal level is above its maximum level.

```

File Product Input Output SerialCom Language Option 16:44:40
----- PReView 5511 -----
Date: 1992-12-28
Serial no.: [n] Analog output -50.00
Tag no.: 150.00
-----
Output type
Analog input (●) Voltage output
              ( ) Current output
Input type: 1tage
Range: Sensor error: 50- 7.50 V
Connection: ( ) Off rece
Cold junction (●) Upscale 0%
External cali ( ) Downscale
Response time ( ) Hold
Min. limit 0 % of span
Relay output
Max. limit 10 % of span
Setpoint: 1.50 V
Hysteresis: Ok ■ Cancel ■ 0.50 V
Action: ■ ■ reasing
Delay: 5.00 sec
Sensor error: No Sensor error: No
Relay contact: Normally open Relay contact: Normally closed
-----
Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

3.4.1.1 Voltage output

Voltage output is defined.

Voltage output:

"Specify" Enter any voltage output range not listed in the standard ranges. This option releases an additional dialog window "Voltage output":

Enter Output voltage - 0%
Enter Output voltage - 100%.

Output voltage must be within the transmitters configuration limits.

"Standard 0-1 VDC"	output voltage range 0-1 V.
"Standard 0-5 VDC"	output voltage range 0-5 V.
"Standard 0-10 VDC"	output voltage range 0-10 V.
"Standard 0.2-1 VDC"	output voltage range 0.2-1 V.
"Standard 1-5 VDC"	output voltage range 1-5 V.
"Standard 2-10 VDC"	output voltage range 2-10 V.
"Standard ±10 VDC"	output voltage range ± 10 V.

Any of the above options will release the "Information" window. Set the DIP-switches accordingly.

```

File Product Input Output SerialCom Language Option 16:45:14
----- PReView 5511 -----
Date: 1992-12-28
Serial no: [n] Voltage output -50.00
Tag no.: DI 150.00
-----
Voltage output
(•) Specify
( ) Standard1 0 - 1 VDC
( ) Standard3 0 - 5 VDC Voltage
( ) Standard4 0 - 10 VDC -2.50- 7.50 V
( ) Standard5 0.2 - 1 VDC Direct
( ) Standard6 1 - 5 VDC 120%
( ) Standard7 2 - 10 VDC
( ) Standard8 ± 10 VDC Ja
-----
Relay output
-----
Setpoint: Ok Cancel 1.50 V
Hysteresis: 0.50 V
Action: Decreasing
Dealy: 5.00 sec
sensor error: No Sensor error: No
Relay contact: Normally open Relay contact: Normally closed
-----
Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

```

File Product Input Output SerialCom Language Option 16:45:44
PREView 5511
Date: 1992-12-28
Serial no.: 0 Display scale 0% -50.00
Tag no.: DISPL01 Display scale 100% 150.00
-----
Analog input Analog output
Input type: [n] Voltage output
Range: Output voltage 0% -2.50000 V
Connection: Output voltage 100% 7.50000 V
Cold junction
External cali
Response time
Relay output
Setpoint:
Hysteresis:
Action: Increasing Action: Decreasing
Dealy: 1.00 sec Dealy: 5.00 sec
Sensor error: No Sensor error: No
Relay contact: Normally open Relay contact: Normally closed
-----
Ok Cancel
Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

```

File Product Input Output SerialCom Language Option 18:36:49
PREView 5511
Date: 1992-12-28
Serial no.: 0 Display scale 0% -50.00
Tag no.: DISPL01 Display scale 100% 150.00
-----
Analog input Analog output
Indgangstype: [n] Information
Område: Dpl contact 1,3,4 closed and 2
Tilslutning: open
Koldt loddested:
Extern kalibrering
Reaktionstid:
Relay output 1
Setpunkt: 5.00 V Setpunkt: 1.50 V
Hysterese: 1.00 V Hysterese: 0.50 V
Reaktion: Stigende Reaktion: Faldende
Forsinkelse: 1.00 sec Forsinkelse: 5.00 sec
Føler fejl: Nej Føler fejl: Nej
Relækontakt: Normal (slutte) Relækontakt: Invert. (bryde)
-----
OK
Alt-F1 Help F10 Menu Alt-X Exit V1.02

```

3.4.1.2 Current output

"Specify" Enter any current output range not listed in the standard ranges. This option releases an additional dialog window "Current output":

Enter Output current - 0%
 Enter Output current - 100%.

Output current must be within the transmitters configuration limits.

"Standard 0-20 mA"	output range 0-20 mA.
"Standard 4-20 mA"	output range 4-20 mA.
"Standard 0-5 mA"	output range 0-5 mA.
"Standard 1-5 mA"	output range 1-5 mA.
"Standard ± 20 mA"	output range ± 20 mA.

Any of the above options will release the "Information" window. Set the DIP-switches accordingly.

Date:	1992-12-28	[n] Current output		-50.00
Serial no.:				150.00
Tag no.:	DI			
Analog input	Current output (•) Specify () Standard1 0 - 20 mA () Standard2 4 - 20 mA () Standard3 0 - 5 mA () Standard4 1 - 5 mA () Standard5 ± 20 mA			Spænding -2.50- 7.50 V
Indgangstype:				Direkte
Område:				120%
Tilslutning:				Ja
Koldt loddested:				
Extern kalibrering				
Reaktionstid:				
Relay output 1				
Setpunkt:		Ok	Cancel	1.50 V
Hysteresese:				0.50 V
Reaktion:				Faldende
Forsinkelse:				5.00 sec
Føler fejl:	Nej		Føler fejl:	Nej
Relækontakt:	Normal (slutte)		Relækontakt:	Invert. (bryde)

Alt-F1 Help F10 Menu Alt-X Exit V1.02

Date:	1992-12-28	Display scale 0%	-50.00
Serial no.:	0	Display scale 100%	150.00
Tag no.:	DISPL01		
Analog input	[n] Current output		Analog output
Indgangstype:	Output current 0%	-5.00000 mA	røm
Område:			00- 15.00 mA
Tilslutning:	Output current 100%	15.00000 mA	rekte
Koldt loddest			0%
Extern kalibr			
Reaktionstid:			
Relay output			
Setpunkt:			3.00 mA
Hysteresese:			1.00 mA
Reaktion:	Stigende	Reaktion:	Faldende
Forsinkelse:	1.00 sec	Forsinkelse:	5.00 sec
Føler fejl:	Nej	Føler fejl:	Nej
Relækontakt:	Normal (slutte)	Relækontakt:	Invert. (bryde)

Alt-F1 Help F10 Menu Alt-X Exit V1.02

Date:	1992-12-28	Display scale 0%	-50.00
Serial no.:	0	Display scale 100%	150.00
Tag no.:	DISPL01		
Analog input	[n] Information		Analog output
Input type:	Dp1 contact 4 closed and 1,2,3 open		Strøm
Range:			-5.00- 15.00 mA
Connection:			Direkte
Cold junction:			120%
External calibrati			Ja
Response time:			
Relay output 1			
Setpoint:	10.00 mA	Setpoint:	3.00 mA
Hysteresis:	2.00 mA	Hysteresis:	1.00 mA
Action:	Increasing	Action:	Decreasing
Delay:	1.00 sec	Delay:	5.00 sec
Sensor error:	No	Sensor error:	No
Relay contact:	Normally open	Relay contact:	Normally closed


Alt-F1 Help F10 Menu Alt-X Exit V1.06

3.4.2 Relay units

These options are only available in SYSTEM 5000 units containing relay functions.

Select units and actual value for relay and hysteresis parameters. The following options are available:

- % of display (counts)
- % output span
- Analog input (°C, mA, V, Ω)
- Analog output (mA, V)



3.4.3 Relay output 1/2

The following relay output options are available for both relay outputs.

- "Relay setpoint" enter setpoint in the selected units.
- "Relay hysteresis" enter hysteresis in the selected units.
- "Relay delay" enter relay delay in seconds.

Relay action:

- "Increasing" relay action for increasing signal level.
- "Decreasing" relay action for decreasing signal level.
- "Sensor error" relay action for sensor error detection.
- "No function" disable relay function.

Relay contact:

- "Normally open" relay contact will make for action (N.O.).
- "Normally closed" relay contact will break for action (N.C.).

Sensor error action:

Sensor error (open circuit) on the following sensors may be detected: Thermocouple (TC), Pt100 and Ni100 (RTD), and linear resistor. In case of sensor error detection the relay output will react in one of the following ways:

- "No function" relay will not react upon sensor error.
- "Hold" relay will hold position valid 3 updates old upon sensor error.
- "High" if relay function is defined as N.O. relay will activate upon sensor error. If relay function is defined as N.C. relay will deactivate upon sensor error.
- "Low" if relay function is defined as N.O. relay will deactivate upon sensor error. If relay function is defined as N.C. relay will activate upon sensor error.

For further details please refer to section 6.0.

```

File Product Input Output SerialCom Language Option 21:55:00
PReView 5511
Date: [n] Relay output 1
Serial n:
Tag no.: Relay 1 setpoint 100.00 °C
Analog i: Relay 1 hysteresis 10.000 °C
Input ty: Relay 1 delay 1.000 sec
Range:
Conectio:
Cold jun:
External:
Response:
Relay ou:
Setpoint: °C
Hysteres: °C
Action: e
Delay: sec
Sensor e:
Relay co:

Relay 1 action          Relay 1 contact
(•) Increasing          (•) Normally open
( ) Decreasing         ( ) Normally closed
( ) Sensor error
( ) No function

Ok          Cancel

```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

```

File Product Input Output SerialCom Language Option 13:54:02
PReView 5511
Date: 1993-11-11
Serial no.: 930742272 Display scale 0% 0.00
Tag no.: Display scale 100% 50.00
Analog input Analog output
Input type: [n] Sensor error action
Input range: Sensor error action rrent
Connection: (•) Off 00- 20.00 mA
Cold junction ( ) Hold rect
External cali ( ) High
Response time ( ) Low
Relay output
Setpoint: 0.00 Ω
Hysteresis: 2.00 Ω
Action: Increasing Action: Increasing
Delay: 0.00 sec Delay: 0.00 sec
Sensor error: No Sensor error: No
Relay contact: Normally open Relay contact: Normally open

Ok          Cancel

```

Alt-F1 Help F10 Menu Alt-X Exit V1.06

3.4.4 Display setup

Scaling:

"Display scale 0%" Enter value in counts, to be displayed at 0% input, incl. decimal point.

"Display scale 100%" Enter value in counts, to be displayed at 100% input, incl. decimal point.

"2, 3, 4 or 5 digits" Enter number of digits in display.

"Display speed" Enter the interval between each display update in msec.

"LED intensity" Enter light intensity on a scale from 0 to 15. 15 is max intensity.

Resolution on least significant digit:

"0" Last digit is zero locked.

"0-9" all counts in last digit available.

"0/2/4/6/8" only even counts in last digit available.

"0/5" only 0 and 5 is available.

Zero blank:

"Blank zeros" zeroes in front of most significant digit are blanked.

"Display zeros" zeroes in front of most significant digit are shown.

"Units backlight" enable/disable the backlight of measurement units, only available on PReview 5511, LED version. Use space bar or mouse to disable/enable backlight.

```
File Product Input Output SerialCom Language Option 21:57:19
PReView 5511
Date: [n] Display setup
Serial n 0
Tag no.: Display scale 0% -50.00 counts 0
Analog i Display scale 100% 150.00 counts
Input: 2,3,4 or 5 digits 5 g
Range: 7.50 V
Connecti Display speed 300 msec
Cold jun
External LED intensity (0-15) 10
Response
Relay ou Resolution Lsd Leading zeros
( ) 0 (•) Blank zeros
(•) 0-9 ( ) Diplay zeros
Setpoint ( ) 0/2/4/6/8 °C
Hysteres ( ) 0/5 [X] Units backlight °C
Action: e
Delay: Ok ■ Cancel ■ sec
Sensor e
Relay co closed
Alt-F1 Help F10 Menu Alt-X Exit V1.062
```

3.5 "Serialcom": Transmit or receive data

1. Receive - enables configuration data to be retrieved from a transmitter to the PC for review and editing.
2. Transmit - enables configuration data to be transmitted from the PC to the transmitter.

Select option, move the cursor and press CR.

If communication is not successful an error message will appear.

```

File Product Input Output SerialCom Language Option                               20:37:41
-----
Date:          1993-1-4          Recieve data Ctrl-F1
Serial no.:    0                  Transmit data Ctrl-F2
Tag no.:      DISPL01           0%          -50.00
                                   0%          150.00

Analog input                               Analog output

Input type:          100 DIN/IEC          Output type:          Current
Input range:        0.00-100.00 °C       Output range:         0.00- 20.00 mA
Connection:         2-wire                Characteristic:       Direct
Cold junction comp: -----             Sensor error:        -----
External calib:     Passive
Response time:     1.00 sec              Linearisation:       Yes

Relay output 1                               Relay output 2

Setpoint:          15.00 mA              Setpoint:             8.00 mA
Hysteresis:        2.00 mA              Hysteresis:           1.00 mA
Action:            Increasing            Action:               Decreasing
Delay:             1.00 sec              Delay:                5.00 sec
Sensor error:      No                   Sensor error:         No
Relay contact:     Normally closed       Relay contact:        Normally closed

Alt-F1 Help   F10 Menu   Alt-X Exit                               V1.062
  
```

```

File Product Input Output SerialCom Language Option                               20:38:15
-----
Date:          1993-1-4          PReView 5511
Serial no.:    0                  Display scale 0%     -50.00
Tag no.:      DISPL01           Display scale 100%  150.00

Analog input                               Analog output

Indgangstype:    [n] Information
Område:
Tilslutning:
Koldt loddested:
Extern kalibrering
Reaktionstid:

Relay output 1

Setpunkt:        100.00 °C              Setpunkt:             30.00 °C
Hysteresese:     10.00 °C              Hysteresese:          2.00 °C
Reaktion:        Stigende                Reaktion:              Faldende
Forsinkelse:     1.00 sec              Forsinkelse:          5.00 sec
Føler fejl:      Nej                    Føler fejl:           Nej
Relækontakt:     Normal (slutte)       Relækontakt:          Invert. (bryde)

Spænding
-2.50- 7.50 V
Direkte
120%
Ja

OK          Cancel

Alt-F1 Help   F10 Menu   Alt-X Exit                               V1.02
  
```

Date:	1993-1-4	Recieve data Ctrl-F1		
Serial no.:	0	Transmit data Ctrl-F2	0%	-50.00
Tag no.:	DISPL01		0%	150.00
Analog input		Analog output		
Input type:	100 DIN/IEC	Output type:	Current	
Input range:	0.00-100.00 °C	Output range:	0.00- 20.00 mA	
Connection:	2-wire	Characteristic:	Direct	
Cold junction comp:	-----	Sensor error:	-----	
External calib:	Passive			
Response time:	1.00 sec	Linearisation:	Yes	
Relay output 1		Relay output 2		
Setpoint:	15.00 mA	Setpoint:	8.00 mA	
Hysteresis:	2.00 mA	Hysteresis:	1.00 mA	
Action:	Increasing	Action:	Decreasing	
Delay:	1.00 sec	Delay:	5.00 sec	
Sensor error:	No	Sensor error:	No	
Relay contact:	Normally closed	Relay contact:	Normally closed	

PReView 5511				
Date:	1993-11-11			
Serial no.:	930742272	Display scale 0%	0%	0.00
Tag no.:		Display scale 100%	100%	50.00
Analog input		Analog output		
Input type:			Current	
Input range:			0.00- 20.00 mA	
Connection:			Direct	
Cold junction comp			-----	
External calib.:			No	
Response time:				
Relay output 1				
Setpoint:	60.00 Ω	Setpoint:	80.00 Ω	
Hysteresis:	2.00 Ω	Hysteresis:	2.00 Ω	
Action:	Increasing	Action:	Increasing	
Delay:	0.00 sec	Delay:	0.00 sec	
Sensor error:	No	Sensor error:	No	
Relay contact:	Normally open	Relay contact:	Normally open	

[n] Warning

Overwrite Product setup?

Ok Cancel

3.5.3 Monitor

When Optolink 5901 is connected to a PC and the SYSTEM 5000 unit, the input and output values of the unit may be displayed on the PC screen.

Move the cursor to Monitor and press <Enter>.

To terminate the function move the cursor to Exit and press <Enter>.

3.5.4 Control

When Optolink 5901 is connected to a PC and the SYSTEM 5000 unit, it is possible to control the output values of the unit. Move the cursor to Control and press <Enter>. Move the cursor to select output type for control. To control the analog output enter the value from the keyboard. Active relay function is obtained by entering an "X" using the space key. For units including LED/LCD display the display value to be shown may be entered from the keyboard.

Move the cursor to Update and press <Enter> to send the output data to the unit.

To terminate the function move the cursor to Exit and press <Enter>.

3.6 "Language" Select language

The following languages are available:

1. Dansk all texts will be Danish.
2. English all texts will be English.
3. Deutch all texts will be German.
4. Français all texts will be in French.
5. Español all texts will be in Spanish.
6. Italiano all texts will be in Italian.
7. Nederlands all texts will be in Dutch.
8. Svenska all texts will be in Swedish.
9. Suomi all texts will be in Finnish.

Move the cursor to the desired language by operating the "↑↓" and press CR. The display will be updated accordingly.

```

File Product Input Output SerialCom Language Option                20:38:42
===== PReView 551
|| Date:          1993-1-4          | Dansk      Shift-F1 | | |
|| Serial no.:    0                 | English    Shift-F2 |
|| Tag no.:      DISPL01           | Deutch     Shift-F3 |
||-----|-----|-----|-----|
|| Analog input  | Anal       | Español    Shift-F5 |
||               |           | Italiano   Shift-F6 |
|| Indgangstype: Pt 100 DIN/IEC    | Udga       | Nederlands Shift-F7 |
|| Område:       -50.00-150.00 °C  | Områ       | Svenska    Shift-F8 | .50 V
|| Tilslutning:  2-leder           | Kara       | Suomi      Shift-F9 |
|| Koldt loddested: -----| Føle
|| Extern kalibrering: Passiv
|| Reaktionsid:   1.00 sec         | Linearisering: Ja
||
|| Relay output 1 |           | Relay output 2
||
|| Setpunkt:     100.00 °C         | Setpunkt:   30.00 °C
|| Hysterese:    10.00 °C         | Hysterese:  2.00 °C
|| Reaktion:     Stigende          | Reaktion:   Faldende
|| Forsinkelse:  1.00 sec         | Forsinkelse: 5.00 sec
|| Føler fejl:   Nej              | Føler fejl:  Nej
|| Relækontakt: Normal (slutte)   | Relækontakt: Invert. (bryde)
=====
Alt-F1 Help  F10 Menu  Alt-X Exit                                V1.02

```

3.7 "Option" Select additional options in software

The pull down menu offers the following options:

1. Front programming
2. Auto calibration
3. Mains frequency
4. Tag no
5. Communication port
6. Base adjust
7. Setup

Move the cursor to the desired option by operating the "↑↓" keys and press CR.

Use the "TAB" key to get access to the parameters in the dialog window.

The current parameter is indicated by the highlighted cursor.

If the dialog window contains several options, select desired option by operating the "↑↓" keys and press "TAB". Move the cursor to "OK" and press CR to confirm setup.

```
File Product Input Output SerialCom Language Option 20:39:11
===== PReView 5511 =====
|| Date:          1993-1-4          | Front programming  F6 | |
|| Serial no.:    0                  | Auto calibration  F7 |
|| Tag no.:      DISPL01            | Mains frequency  F8 |
||-----| Tag no.                  | F9 |
|| Analog input          | Analog u | Communication port  F10 |
||-----|-----|-----|
|| Indgangstype:      Pt 100 DIN/IEC | Udgangst | Base adjust      Ctrl-PgDn |
|| Område:           -50.00-150.00 °C | Område:  | Setup           Ctrl-PgUp  |
|| Tilslutning:      2-leder         | Karakter  |-----|
|| Koldt loddested:  -----          | Føler fejl:    120% |
|| Extern kalibrering: Passiv         |-----|
|| Reaktionsid:      1.00 sec         | Linearisering:  Ja  |
||-----|-----|-----|
|| Relay output 1          | Relay output 2 |
||-----|-----|-----|
|| Setpunkt:          100.00 °C       | Setpunkt:      30.00 °C |
|| Hysterese:         10.00 °C       | Hysterese:     2.00 °C |
|| Reaktion:          Stigende        | Reaktion:      Faldende |
|| Forsinkelse:       1.00 sec        | Forsinkelse:   5.00 sec |
|| Føler fejl:        Nej             | Føler fejl:    Nej |
|| Relækontakt:      Normal (slutte) | Relækontakt:   Invert. (bryde) |
||-----|-----|-----|
Alt-F1 Help F10 Menu Alt-X Exit V1.02
```

3.7.1 Front programming: Enable/disable front keys

Enable/disable programming from front keys in PReTrans and PReview including external calibration of cable resistance.

"Yes" Enable front key programming.

"No" Disable front key programming.

```

File Product Input Output SerialCom Language Option                22:15:18
                               PReView 5511
Date:      1993-1-4
Serial no.:      0          Display scale 0%      -50.00
Tag no.:      DISPL01      Display scale 100%     150.00

Analog input                                Analog output
Indgangstype:                                Spænding
Område:      [n]----- Front programming -----    -2.50- 7.50 V
Tilslutning:      Front programming
Koldt loddested:      (•) Yes
Extern kalibrering:      ( ) No
Reaktionstid:                                Direkte
                                                120%
Relay output 1                                Ja
Setpunkt:      100.00 °C          Setpunkt:      30.00 °C
Hysteresese:      10.00 °C        Hysteresese:      2.00 °C
Reaktion:      Stigende           Reaktion:      Faldende
Forsinkelse:      1.00 sec        Forsinkelse:      5.00 sec
Føler fejl:      Nej              Føler fejl:      Nej
Relækontakt:      Normal (slutte)  Relækontakt:      Invert. (bryde)

                               Ok          Cancel

Alt-F1 Help  F10 Menu  Alt-X Exit                                V1.02
  
```

3.7.2 Auto calibration: Enable/disable automatic calibration

The transmitters A/D converter is calibrated every 30 minutes. This calibration lasts for appr. 150 msec, which means that a minor discontinuity in the registration of slowly varying input signals is introduced during each calibration. If this facility interferes with your data acquisition, auto calibration may be disabled.

"Yes" Enable automatic calibration.

"No" Disable automatic calibration.

```

File Product Input Output SerialCom Language Option                22:15:52
                               PReView 5511
Date:      1993-1-4
Serial no.:      0          Display scale 0%      -50.00
Tag no.:      DISPL01      Display scale 100%     150.00

Analog input                                Analog output
Indgangstype:                                Spænding
Område:      [n]----- Auto calibration -----    -2.50- 7.50 V
Tilslutning:      Auto calibration
Koldt loddested:      (•) Yes
Extern kalibrering:      ( ) No
Reaktionstid:                                Direkte
                                                120%
Relay output 1                                Ja
Setpunkt:      100.00 °C          Setpunkt:      30.00 °C
Hysteresese:      10.00 °C        Hysteresese:      2.00 °C
Reaktion:      Stigende           Reaktion:      Faldende
Forsinkelse:      1.00 sec        Forsinkelse:      5.00 sec
Føler fejl:      Nej              Føler fejl:      Nej
Relækontakt:      Normal (slutte)  Relækontakt:      Invert. (bryde)

                               Ok          Cancel

Alt-F1 Help  F10 Menu  Alt-X Exit                                V1.02
  
```

3.7.3 Mains frequency: Select mains frequency

"50 Hz" software adapts for 50 Hz mains frequency filter.

"60 Hz" software adapts for 60 Hz mains frequency filter.

```

File Product Input Output SerialCom Language Option                22:16:19
                               PReView 5511
-----
Date:          1993-1-4
Serial no.:    0
Tag no.:       DISPL01
Display scale  0%      -50.00
Display scale 100%    150.00
-----
Analog input                               Analog output
-----
Indgangstype:                               Spænding
Område:                                       -2.50- 7.50 V
Tilslutning:                               Direkte
Koldt loddested:                           120%
Extern kalibrering                           Ja
Reaktionstid:
Relay output 1
-----
Setpunkt:          100.00 °C      Setpunkt:          30.00 °C
Hysterese:         10.00 °C      Hysterese:         2.00 °C
Reaktion:          Stigende       Reaktion:          Faldende
Forsinkelse:      1.00 sec       Forsinkelse:      5.00 sec
Føler fejl:       Nej            Føler fejl:       Nej
Relækontakt:     Normal (slutte)  Relækontakt:     Invert. (bryde)
-----
Alt-F1 Help  F10 Menu  Alt-X Exit                                V1.02
  
```

3.7.4 Tag no: Enter unit Tag number

Tag no:

The unit may be identified by tag numbering. The tag number including a maximum of 15 characters is displayed in the status window.

```

File Product Input Output SerialCom Language Option                22:16:45
                               PReView 5511
-----
Date:          1993-1-4
Serial no.:    0
Tag no.:       PX-4343-X19_3/2
Display scale  0%      -50.00
Display scale 100%    150.00
-----
Analog input                               Analog output
-----
Input type:                               Voltage
Range:                                       -2.50- 7.50 V
Connection:                               Direct
Cold junction:                           120%
External calib:                           Yes
Responsetime:
Relay output 1
-----
Setpoint:          100.00 °C      Setpoint:          30.00 °C
Hysteresis:        10.00 °C      Hysteresis:        2.00 °C
Action:            Increasing     Action:            Decreasing
Delay:             1.00 sec       Delay:             5.00 sec
Sensor error:     No            Sensor error:     No
Relay contact:    Normally open  Relay contact:    Normally closed
-----
Alt-F1 Help  F10 Menu  Alt-X Exit                                V1.06
  
```

3.7.5 Process calibration

Move the cursor to Process calibration and press <Enter>.

This function is very useful when the analog output need to be adjusted to the input signal, e.g. when the temperature sensor does not correspond with the ideal values for the selected temperature range. The result from this procedure depends on the accuracy of the equipment used for measuring the input/output signals. In the following a process calibration for temperature measurement is shown, however the principle is identical for other applications.

Setup: Input Pt100, 0 - 100 °C, Output 4 - 20 mA. Use a thermometer and a Ampere meter to measure input/output values. 0% value (Analog input x0) is measured at 10 °C corresponding (Analog output y0) 5.44 mA, 100% (Analog output x1) value is measured at 75 °C corresponding (Analog output y1) 16.15 mA. Enter these values:

```

Process calibration
-----
Analog input (x0)      10 °C
Analog output (y0)    5.44 mA
Analog input (x1)     75 °C
Analog output (y1)   16.15 mA
Ok                      Exit
    
```

The span is now changed accordingly from 0 - 100 °C to -1.26 - 101.72 °C. Transmit the process calibrated setup to the unit, which is now calibrated according to the sensor characteristics.

3.7.6 Communication port: Select communication port

"Com1" com port 1 is used for communication between PC and transmitter.

"Com2" com port 2 is used for communication between PC and transmitter.

```

File Product Input Output SeialCom Language Option                22:18:58
----- PReView 5511 -----
Date:          1993-1-4
Serial no.:    0
Tag no.:      DISPL01
Display scale 0%   -50.00
Display scale 100% 150.00
-----
Analog input
Indgangstype:
Område:
Tilslutning:
Koldt loddested:
Extern kalibrering
Reaktionstid:
Relay output 1
Setpunkt:      100.00 °C
Hysteres:     10.00 °C
Reaktion:     Stigende
Forsinkelse:   1.00 sec
Føler fejl:    Nej
Relækontakt:  Normal (slutte)

Analog output
Spænding
-2.50- 7.50 V
Direkte
120%
Ja
Setpunkt:      30.00 °C
Hysteres:     2.00 °C
Reaktion:     Faldende
Forsinkelse:   5.00 sec
Føler fejl:    Nej
Relækontakt:  Invert. (bryde)

[n]----- Communication port -----
Communication port
( ) Com1
(•) Com2
Ok          Cancel
    
```

Alt-F1 Help F10 Menu Alt-X Exit V1.02

3.7.7 Base adjust: Base adjustment of SYSTEM 5000 units

Access denied. PR electronics A/S' test department only.


3.7.8 Setup: Display of the internal data block

PR electronics' test department for diagnostic use only.

4 Linerization

SYSTEM 5000 units facilitate custom defined linerization for the following input types: linear resistance, voltage input and current input.

SYSTEM 5000 units operate on a polynomial fit principle. The programmed span is divided into 6 sections, each section is fitted by means of a third order polynomial, see figure.



PReset must calculate 4 coefficients a_0 , a_1 , a_2 and a_3 for all 6 sections including 5 section limits, indicating curve sections for 0 -100% of the input span. This means that PReset must transfer all together 5 section limits and 24 coefficients to PReTrans or PReview. These calculations are rather cumbersome, thus PReset offers three alternative ways to enter data:

1. Linear interpolation: Enter start- and end points of up to 7 straight lines.
2. Polynomial: Enter from 24 to 60 coordinates from any curvature. PReset will calculate a polynomial fit according to the least squares method.
3. Coefficients: Enter 24 coefficients and 5 limits directly.

For alternative 1 and 2: X_{min} , X_{max} , Y_{min} and Y_{max} must be included. Furthermore corresponding XY must be entered in the table.

Before coefficients are calculated all X and Y's are normalized to values between 0 and 1, according to the following equations: $X_{norm} = (X_n - X_{min}) / (X_{max} - X_{min})$ and $Y_{norm} = (Y_n - Y_{min}) / (Y_{max} - Y_{min})$.

Note: As linearisation is carried out on a normalized basis, all scaling must be performed in PReset input, output or display dialog windows.


```

===== PReView 5511 =====
|| Date:          1992-12-28
|| Serial no.:    0          Display scale 0%   -50.00
|| Tag no.:       DISPL01   Display scale 100%  150.00
||-----
|| Analog input          Analog output
|| [n]===== Custom-defined lin. =====
|| Indgangs||
|| Område:  || Custom-defined lin. ||g
|| Tilstlutn|| ( ) Linear interpolation ||7.50 V
|| Koldt lo|| (•) Polynomial
|| Extern k|| ( ) Coefficients
|| Reaktion||
||          ||          Ok          ■          Cancel          ■
|| Relay ou||          ■■■■■          ■■■■■
||-----
|| Setpunkt:      100.00 °C      Setpunkt:          30.00 °C
|| Hysterese:     10.00 °C      Hysterese:         2.00 °C
|| Reaktion:      Stigende      Reaktion:          Faldende
|| Forsinkelse:   1.00 sec      Forsinkelse:       5.00 sec
|| Føler fejl:    Nej          Føler fejl:       Nej
|| Relækontakt:   Normal (slutte) Relækontakt:      Invert. (bryde)
||-----

```

4.1 Linear interpolation

Enter from 2 to 7 corresponding sets of XY values, defining the start-/end points for 1 to 6 straight lines, see figure.



Note: Highest and lowest input values (Xmax and Xmin) plus highest and lowest output values (Ymax and Ymin) must be among the entered values as linearisation is scaled according to these values.

From the entered values PReset calculates the coefficients a0 and a1, defining the equation of each straight line section.

$$Y = a_0 + a_1 * X \quad (a_0 = \text{Y-axis interception, } a_1 = \text{slope})$$

(Coefficient a2 = a3 = 0)

or

$$\text{Output}_{(0-1)} = a_0 + a_1 * \text{input}_{(0-1)}$$

```


File Product  Input  Output  SerialCom  Language  Option  23:35:39
[n]-----
X (Input)    Y (Output)  Total of XY
1.0000000   2.0000000   7
2.0000000   7.0000000
3.0000000   9.0000000
4.0000000   19.0000000  ( ) Clear XY
5.0000000   22.0000000  ( ) Delete file
6.0000000   22.0000000  (•) Open file
7.0000000   8.0000000   ( ) Save file
10.0000000  23.0000000  ( ) Calc. coef.

          Ok          Cancel
          [ ]          [ ]

Alt-F1 Help  F10 Menu  Alt-X Exit  V1.02
  
```

4.2 Polynomial linearisation

If the function has the shape of a curve, the polynomial linearisation is the best choice. Enter from 24 to 60 corresponding sets of XY values from the curve, see figure.



Note: Highest and lowest input values (Xmax and Xmin) plus highest and lowest output values (Ymax and Ymin) must be among the entered values as linearisation is scaled according to these values.

PRreset divides the curve into the 6 sections. To ensure the best possible fit, most XY-values should be entered in the sections where the function is most curved.

The coefficients for a 3rd order polynomial are calculated for the 6 sections according to the least squares method. PRreset will adapt the coefficients, to minimize discrepancy from the entered values.

$$Y = a_0 + a_1 * X + a_2 * X^2 + a_3 * X^3$$

$$\text{or: } \text{Output}_{(0-1)} = a_0 + a_1 * \text{input}_{(0-1)} + a_2 * \text{input}_{(0-1)}^2 + a_3 * \text{input}_{(0-1)}^3$$

File	Product	Input	Output	SerialCom	Language	Option	23:08:09	
[n]				Polynomial				
X	Y	X	Y	X	Y	X	Y	
0.2500	0.0000	0.6400	0.2041	2.5000	0.5000	17.500	0.9200	
0.3000	0.0396	0.6600	0.2108	2.7500	0.5200	20.000	0.9500	
0.3500	0.0731	0.7300	0.2327	3.0000	0.5400	20.950	0.9600	
0.3750	0.0880	0.7500	0.2400	3.2000	0.5536	22.500	0.9800	
0.4000	0.1020	0.7700	0.2443	3.5000	0.5700	25.000	1.0000	
0.4200	0.1126	0.8300	0.2606	4.0000	0.6000	0.0000	0.0000	
0.4500	0.1276	0.8700	0.2707	4.5000	0.6300	0.0000	0.0000	
0.4750	0.1394	0.9600	0.2921	5.0000	0.6500	0.0000	0.0000	
0.4900	0.1461	1.0000	0.3000	6.0000	0.6900	0.0000	0.0000	
0.5000	0.1500	1.2500	0.3500	7.0000	0.7200	0.0000	0.0000	
0.5200	0.1590	1.4000	0.3740	8.0000	0.7500	0.0000	0.0000	
0.5400	0.1672	1.5000	0.3900	9.0000	0.7800	0.0000	0.0000	
0.5600	0.1751	1.7500	0.4225	10.000	0.8000	0.0000	0.0000	
0.5800	0.1827	2.0000	0.4500	12.500	0.8500	0.0000	0.0000	
0.6200	0.1972	2.2500	0.4800	15.000	0.8900	0.0000	0.0000	
Total of XY		50						
			Ok	Cancel		() Clear XY		
						() Delete file		
						(●) Open file		
						() Save file		
						() Calc. coef.		

Alt-F1 Help F10 Menu Alt-X Exit

V1.02

4.3 Coefficients

Coefficients may be entered directly:

Enter the 5 section limits, determining the sections of each set of coefficients. The coefficients must be between 0 and 1 (0-100% of input span).

Enter the coefficients a0, a1, a2 and a3 for the 3rd order polynomial

$$Y = a_0 + a_1 * X + a_2 * X^2 + a_3 * X^3$$

for each of the 6 sections. Coefficients could e.g. be calculated by means of the PC program Eureka.

Example: Linearisation $Y = X^2$ can be performed simply by entering the coefficients: $a_0 = a_1 = a_3 = 0$ and $a_2 = 1$.

Section limits are 1, that is $Y = X^2$ for 0-100 % of input span.

```

File Product Input Output Communication Language Option          23:10:07
-----[n]----- Coefficients -----
Limits      6025.0    10000.    17584.    24704.    31359.
            g0      g1      g2      g3      g4

a0 -2.41930    -2.42447    -2.46714    -2.47843    -2.70913    -2.78161
a1  2.22254     2.24526     2.38304     2.40633     2.66693     2.72046
a2  2.54037     2.24797     7.70647     6.12916     -3.73737    -4.88375
a3 -5.48733    -4.55668     7.07991     1.05983     2.31323     2.36950
            k0      k1      k2      k3      k4      k5

                Ok      ■      Cancel      ■

                                ( ) Clear XY
                                ( ) Delete file
                                (●) Open file
                                ( ) Save file
                                ( ) Calc. coef.

Alt-F1 Help  F10 Menu  Alt-X Exit          V1.02
  
```

5 Process calibration

5.1 "Only 0% calibration" allows for 0% process calibration (offset).

Enter the input range from the keyboard and select "Only 0% calibration". And transmit setup to the unit.

Proceed as follows:

PRetrans 5111:

1. Apply 0% input signal.
2. Remove front cover and activate the calibration button. LED will change from flashing to steady light.
3. Within 5 sec activate the calibration button once more. LED will return to flashing mode.

PReview 5511/5512:

1. Apply 0% input signal.
2. Select menu 6.5 **In 0** from the front keys.
3. Activate **e** for 0% input signal measuring. Enter 0% input signal by activating **↑** and **→** simultaneously.
4. Return to "Rum mode" by activating **↑** and then **e**.

5.2 "0%-100% & 0% calibration" allows for both 0% and 100% process calibration.

Enter the approximate input range from the keyboard and select "0%-100% & 0% calibration". Please ensure that the keyboard entered input range exceeds the process calibrated range. And transmit setup to the unit.

Proceed as follows:

PRetrans 5111:

1. Apply 0% input signal.
2. Remove front cover and activate the calibration button. LED will change from flashing to steady light.
3. Wait for 5 sec until LED switched off.
4. Apply 100% input signal and activate the calibration button once more. LED will return to flashing mode.

PReview 5511/5512:

1. Apply 0% input signal.
2. Select menu 6.5 **In LO** from the front keys.
3. Activate **e** for 0% input signal measuring. Enter 0% input signal by activating **↑** and **→** simultaneously.
4. Apply 100% input signal.
5. Select menu 6.4 **In HI** from the front keys.
6. Activate **e** for 100% input signal measuring. Enter 100% input signal by activating **↑** and **→** simultaneously.
7. Return to "Rum mode" by activating **↑** and then **e**.

5.2.1 Ratio metric calibration

Ratio metric calibration may be applied if only certain points of the input range can be simulated. E.g. 0% and 30% of the input range, useful in weighing system applications.

Enter the approximate input range from the keyboard and select "0%-100% & 0% calibration". Please ensure that the keyboard entered input range exceeds the process calibrated range and transmit setup to the unit.

Proceed as follows:

1. Apply 0% and 100% process calibration, see section 5.2.
2. Receive setup from unit.(The current setup contains the 0% and 100% input values in the simulated input range).
3. Calculate the actual 100% input value from the simulated 100% value applying this formula:

Actual 100% input value= $((\text{max} - \text{min}) \times \text{ratio}) + \text{min}$. input

max = simulated 100% input value at e.g. 30% input range.

min = simulated 0% input value at e.g. 0% input range.

ratio = actual 100% physical measure divided by the simulated physical measure

4. Enter the actual 100% input value from the keyboard.

5. Transmit the setup to the unit.

Example:

In case of a weighing system calibrated for 0-1000 kg physical measure, and only 300 kg is available for 100% calibration:

max = 6.4mV (simulated at 300 kg)

min = 1.6mV (simulated at 0 kg)

Actual 100% input value = $((6.4\text{mV} - 1.6\text{mV}) \times 100/30) + 1.6\text{mV} = 17.6\text{mV}$

5.3 "Protect process calibration"

Disables input parameters from previous process calibration procedure being updated unintentionally when transmitting setups from PReset to a unit. This function also disables process calibration procedure.

6 Sensor error

6.1 Input sensor error detection

The following input types includes sensor error detection option for action on analog output and relay output:

**Input type:Sensor error Test for detection:
error type:**

2-wire lin. RSensor + both cablesBreakage
3-wire lin. RSensorBreakage
4-wire lin. RSensor + all cablesBreakage
2-wire Pt100Sensor + both cablesBreakage + short circuit
3-wire Pt100SensorBreakage + short circuit
4-wire Pt100Sensor + all cablesBreakage + short circuit*
Differential inputSensor + all cablesBreakage
TC constant CJCSENSOR + both wiresBreakage
TC internal CJCSENSOR + both wiresBreakage
CJC-sensorBreakage + short circuit
TC external CJCSENSOR + both wiresBreakage
CJC-sensor + wiresBreakage + short circuit
Current 2 - 20mABoth cablesBreakage + (short circuit)

*Short circuit is detected between the following terminals: 41-43, 42-44, 41-43 and 41-44.

APPENDIX A: Hot keys

MENU BAR

ALT F	:	File
ALT P	:	Product
ALT I	:	Input
ALT O	:	Output
ALT S	:	Communication
ALT L	:	Language
ALT N	:	Option

FILE

F2	:	Delete
F3	:	Open
F4	:	Save
F5	:	Print status
ALT X	:	Return to DOS

PRODUCT

ALT 1	:	PRetrans 5111
ALT 2	:	PReview 5511
ALT 3	:	PReview 5512

INPUT

ALT B	:	TC B
ALT E	:	TC E
ALT J	:	TC J
ALT K	:	TC K
ALT G	:	TC L
ALT M	:	TC N
ALT R	:	TC R
ALT D	:	TC S
ALT T	:	TC T
ALT U	:	TC U
ALT C	:	Pt100 (DIN/IEC)
ALT Q	:	Pt100 (JIS)
ALT A	:	Ni100
ALT Z	:	Linear resistor
ALT V	:	Voltage input
ALT Y	:	Current input

OUTPUT

ALT F6	:	Analog output
ALT F7	:	Relay units
ALT F8	:	Relay output 1
ALT F9	:	Relay output 2
ALT F10	:	Display

COMMUNICATION

Ctrl F1	:	Receive data
Ctrl F2	:	Transmit data

LANGUAGE

Shift F1	:	Dansk
Shift F2	:	English
Shift F3	:	Deutsch
Shift F4	:	Français
Shift F5	:	Italiano
Shift F6	:	Nederlands
Shift F7	:	Svenska
Shift F8	:	Suomi
Shift F9	:	Norsk

OPTION

F6	:	Front programming
F7	:	Auto calibration
F8	:	Mains frequency
F9	:	Tag no.
F10	:	Communication port

STATUS LINE

ALT F1	:	Help (not implemented)
F10	:	Menu
ALT X	:	Exit (Return to DOS)