

Smootharc MMA 170

OPERATING MANUAL



Welcome to a better way of welding

Congratulations on purchasing the Smootharc MMA 170 welding machine.

The products in BOC's manual metal arc range perform with reliability and have the backing of one of South Pacific's leading welding suppliers.

This operating manual provides the basic knowledge required for MMA and DC TIG welding, as well as highlighting important areas of how to operate the Smootharc MMA 170 welding machine.

BOC equipment and technical support is available through our national BOC Customer Service Centre or contact your local Gas & Gear outlet.

Important Notice: This document has been prepared by BOC Limited ABN 95 000 029 729 ('BOC'), as general information and does not contain and is not to be taken as containing any specific instructions. The document has been prepared in good faith and is professional opinion only. Information in this document has been derived from third parties, and though BOC believes it to be reliable as at the time of printing, BOC makes no representation or warranty as to the accuracy, reliability or completeness of information in this document and does not assume any responsibility for updating any information or correcting any error or omission which may become apparent after the document has been issued. Neither BOC nor any of its agents has independently verified the accuracy of the information contained in this document. The information in this document is commercial in confidence and is not to be reproduced. The recipient acknowledges and agrees that it must make its own independent investigation and should consider seeking appropriate professional recommendation in reviewing and evaluating the information. This document does not take into account the particular circumstances of the recipient and the recipient should not rely on this document in making any decisions, including but not limited to business, safety or other operations decisions.

Except insofar as liability under any statute cannot be excluded, BOC and its affiliates, directors, employees, contractors and consultants do not accept any liability (whether arising in contract, tort or otherwise) for any error or omission in this document or for any resulting loss or damage (whether direct, indirect, consequential or otherwise) suffered by the recipient of this document or any other person relying on the information contained herein. The recipient agrees that it shall not seek to sue or hold BOC or their respective agents liable in any such respect for the provision of this document or any other information.

Contents

Welcome to a better way of welding	2	4.0 Machine Specifications and Contents	28
1.0 Recommended Safety Precautions	4	4.1 Operating Controls	28
1.1 Health Hazard Information	4	5.0 Operating Functions	29
1.2 Personal Protection	4	5.1 Welding selections	29
1.3 Electrical Shock	6	5.2 Earthing	29
1.4 User Responsibility	6	6.0 Technical Specifications	30
2.0 Manual Metal Arc Welding Process (MMAW)	7	7.0 Periodic Maintenance	31
2.1 Introduction	7	7.1 Daily Maintenance	31
2.2 Process	7	7.2 Troubleshooting	31
2.3 Welding Machine	7	8.0 Terms of Warranty	32
2.4 Welding Technique	8	8.1 Terms of Warranty	32
2.5 Electrode Selection	8	8.2 Limitations on Warranty	32
2.6 Types of Joints	11	8.3 Warranty Repairs	32
2.7 Fillet Welds	12	9.0 Recommended Safety Guidelines	33
2.8 Typical Defects Due to Faulty Technique	15		
3.0 Gas Tungsten Arc Welding (GTAW/TIG)	17		
3.1 Introduction	17		
3.2 Process	17		
3.3 Process Variables	18		
3.4 Welding Techniques	19		
3.5 Shielding Gas Selection	20		
3.6 Consumable Selection	21		
3.7 Typical Welding Joints for Gas Tungsten Arc Welding	25		

1.0 Recommended Safety Precautions

1.1 Health Hazard Information

The actual process of welding is one that can cause a variety of hazards. All appropriate safety equipment should be worn at all times, i.e. headwear, respiratory, hand and body protection. Electrical equipment should be used in accordance with the manufacturer’s recommendations.

Eyes:

The process produces ultra violet rays that can injure and cause permanent damage. Fumes can cause irritation.

Skin:

Arc rays are dangerous to uncovered skin.

Inhalation:

Welding fumes and gases are dangerous to the health of the operator and to those in close proximity. The aggravation of pre-existing respiratory or allergic conditions may occur in some workers. Excessive exposure may cause conditions such as nausea, dizziness, dryness and irritation of eyes, nose and throat.

1.2 Personal Protection

Respiratory

Confined space welding should be carried out with the aid of a fume respirator or air supplied respirator as per AS/NZS 1715 and AS/NZS 1716 Standards.

- You must always have enough ventilation in confined spaces. Be alert to this at all times.
- Keep your head out of the fumes rising from the arc.

- Fumes from the welding of some metals could have an adverse effect on your health. Don’t breathe them in. If you are welding on material such as stainless steel, nickel, nickel alloys or galvanised steel, further precautions are necessary.
- Wear a respirator when natural or forced ventilation is not good enough.

Eye protection

A welding helmet with the appropriate welding filter lens for the operation must be worn at all times in the work environment. The welding arc and the reflecting arc flash gives out ultraviolet and infrared rays. Protective welding screen and goggles should be provided for others working in the same area.

Clothing

Suitable clothing must be worn to prevent excessive exposure to UV radiation and sparks. An adjustable helmet, flameproof loose fitting cotton clothing buttoned to the neck, protective leather gloves, spats, apron and steel capped safety boots are highly recommended.


Recommended filter shades for arc welding

Less than 150 amps	Shade 10*
150 to 250 amps	Shade 11*
250 to 300 amps	Shade 12
300 to 350 amps	Shade 13
Over 350 amps	Shade 14

*Use one shade darker for aluminium

Cylinder Safety

- | | |
|---|---------------------------|
| 1 | Cylinder valve hand-wheel |
| 2 | Back-plug |
| 3 | Bursting disc |



Backview of typical cylinder valve

Operator wearing personal protective equipment (PPE) in safe position

Ten Points about Cylinder Safety	
1	Read labels and Material Safety Data Sheet (MSDS) before use.
2	Store upright and use in well ventilated, secure areas away from pedestrian or vehicle thoroughfare.
3	Guard cylinders against being knocked violently or being allowed to fall.
4	Wear safety shoes, glasses and gloves when handling and connecting cylinders.
5	Always move cylinders securely with an appropriate trolley. Take care not to turn the valve on when moving a cylinder.
6	Keep in a cool, well ventilated area, away from heat sources, sources of ignition and combustible materials, especially flammable gases.
7	Keep full and empty cylinders separate.
8	Keep ammonia-based leak detection solutions, oil and grease away from cylinders and valves.
9	Never use force when opening or closing valves.
10	Don't repaint or disguise markings and damage. If damaged, return cylinders to BOC immediately.


Cylinder Valve Safety

When working with cylinders or operating cylinder valves, ensure that you wear appropriate protective clothing – gloves, boots and safety glasses.

When moving cylinders, ensure that the valve is not accidentally opened in transit.

Before operating a cylinder valve:

- Ensure that the system you are connecting the cylinder into is suitable for the gas and pressure involved.
- Ensure that any accessories (such as hoses attached to the cylinder valve, or the system being connected to) are securely connected. A hose, for example, can potentially flail around dangerously if it is accidentally pressurised when not restrained at both ends.
- Stand to the side of the cylinder so that neither you nor anyone else is in line with the back of the cylinder valve. This is in case a back-plug is loose or a bursting disc vents. The correct stance is shown in the diagram above.



When operating the cylinder valve:

- Open it by hand by turning the valve hand-wheel anti-clockwise. Use only reasonable force.
- Ensure that no gas is leaking from the cylinder valve connection or the system to which the cylinder is connected. DO NOT use ammonia-based leak detection fluid as this can damage

the valve. Approved leak detection fluid, can be obtained from a BOC Gas & Gear™ centre.

- When finished with the cylinder, close the cylinder valve by hand by turning the valve hand-wheel in a clockwise direction. Use only reasonable force.

Remember NEVER tamper with the valve. If you suspect the valve is damaged, DO NOT use it. Report the issue to BOC and arrange for the cylinder to be returned to BOC.

1.3 Electrical Shock

- Never touch 'live' electrical parts.
- Always repair or replace worn or damaged parts.
- Disconnect power source before performing any maintenance or service.
- Earth all work materials.
- Never work in moist or damp areas.

Avoid electric shock by:

- Wearing dry insulated boots
- Wearing dry leather gloves
- Never changing electrodes with bare hands or wet gloves
- Never cooling electrode holders in water
- Working on a dry insulated floor where possible
- Never hold the electrode and holder under your arm.

1.4 User Responsibility

- Read the Operating Manual prior to installation of this machine.
- Unauthorised repairs to this equipment may endanger the technician and operator and will void your warranty. Only qualified personnel approved by BOC should perform repairs.

- Always disconnect mains power before investigating equipment malfunctions.
- Parts that are broken, damaged, missing or worn should be replaced immediately.
- Equipment should be cleaned periodically.

BOC stock a huge range of personal protective equipment. This combined with BOC's extensive Gas and Gear network ensures fast, reliable service throughout the South Pacific.



PLEASE NOTE that under no circumstances should any equipment or parts be altered or changed in any way from the standard specification without written permission given by BOC. To do so, will void the Equipment Warranty.

Further information can be obtained from Welding Institute of Australia (WTIA) Technical Note No.7 'Health and Safety Welding'
Published by WTIA,
PO Box 6165 Silverwater NSW 2128
Phone (02) 9748 4443.

2.0 Manual Metal Arc Welding Process (MMAW)


2.1 Introduction

Arc welding, although in the past principally the tool of tradesmen and fabricators, has in recent years found increasing usage with small workshops, farmers, handyman-hobbyists amongst others. This has been brought about by the introduction of low-cost portable arc welding machines and the ready availability of small diameter electrodes and thinner section construction materials. Provided the operator is familiar with the basic principles and techniques, arc welding can be a fast, efficient and safe method of joining metals.

The main purpose of this manual is to help the welder with limited experience to obtain a better understanding of the process, and to acquire a reasonable degree of proficiency in the least possible time. Even welders with some experience will benefit from the information in this manual.

2.2 Process

Manual Metal Arc welding is the process of joining metals where an electric arc is struck between the metal to be welded (parent metal) and a flux-coated filler wire (the electrode). The heat of the arc melts the parent metal and the electrode which mix together to form, on cooling, a continuous solid mass.



Before arc welding can be carried out, a suitable power source is required. Two types of power sources may be used for arc welding, direct current (DC) or alternating current (AC).


The essential difference between these two power sources is that, in the case of DC, the current remains constant in magnitude and flows in the same direction. Similarly, the voltage in the circuit remains constant in magnitude and polarity (i.e. positive or negative).

In the case of AC however, the current flows first in one direction and then the other. Similarly, the voltage in the circuit changes from positive to negative with changes in direction of current flow. This complete reversal is called a 'half cycle' and repeats as long as the current flows. The rate of change of direction of current flow is known as the 'frequency' of the supply and is measured by the number of cycles completed per second. The standard frequency of the AC supply in Australia is 50 Hz (Hertz).

2.3 Welding Machine

The most important consideration when contemplating the use of arc welding for the first time is the purchase of a suitable welding machine.

BOC supplies a popular range of arc welding machines. Machines range from small portable welders that operate from standard 240 Volt household power to heavy-duty welders used by the largest steel fabricators.



Basic Welding Machine and Cables

The choice of welding machine is based mostly on the following factors:

- primary voltage, e.g. 240 Volt or 380 Volt
- output amperage required, e.g. 140 amps
- output required, e.g. AC or DC +/-
- duty cycle required, e.g. 35% @ 140 amps
- method of cooling, e.g. air-cooled or oil-cooled method of output amperage control, e.g. tapped secondary lugs
- or infinitely variable control.

For example, the Smootharc 170 connects to 240 Volt supply (15 amps Input), has an output of 170 amps DC @ 50% duty cycle.

Having decided on a welding machine, appropriate accessories are required. These are items such as welding cables, clamps, electrode holder, chipping hammer, helmet, shaded and clear lenses, scull cap, gloves and other personal protective equipment.

BOC stocks a huge range of personal protective equipment. This combined with BOC's extensive network ensures fast reliable service throughout the South Pacific.

2.4 Welding Technique

Successful welding depends on the following factors:

- selection of the correct electrode
- selection of the correct size of the electrode for the job
- correct welding current
- correct arc length
- correct angle of electrode to work
- correct travel speed
- correct preparation of work to be welded.

2.5 Electrode Selection

As a general rule the selection of an electrode is straight forward, in that it is only a matter of selecting an electrode of similar composition to the parent metal. It will be found, however, that for some metals there is a choice of several electrodes, each of which has particular properties to suit specific classes of work. Often, one electrode in the group will be more suitable for general applications due to its all round qualities.

The table (page 9) shows just a few of the wide range of electrodes available from BOC with their typical areas of application.

For example, the average welder will carry out most fabrication using mild steel and for this material has a choice of various standard BOC electrodes, each of which will have qualities suited to particular tasks. For general mild steel work, however, BOC Smootharc 13 electrodes will handle virtually all applications. BOC Smootharc 13 is suitable for welding mild steel in all positions using AC or DC power sources. Its easy-striking characteristics and the tolerance it has for work where fit-up and plate surfaces are not considered good, make it the most attractive electrode of its class. Continuous development and improvement of BOC Smootharc 13 has provided in-built operating qualities which appeals to the beginner and experienced operator alike. For further recommendations on the selection of electrodes for specific applications, see table page 9.

Electrodes and Typical Applications

Name	AWS Classification	Application
BOC Smootharc 13	E6013	A premium quality electrode for general structural and sheet metal work in all positions including vertical down using low carbon steels
BOC Smootharc 24	E7024	An iron powder electrode for high speed welding for H-V fillets and flat butt joints. Medium to heavy structural applications in low carbon steels
BOC Smootharc 18	E7018-1	A premium quality all positional hydrogen controlled electrode for carbon steels in pressure vessel applications and where high integrity welding is required and for free-machining steels containing sulphur
BOC Smootharc S 308L	E308L	Rutile basic coated low carbon electrodes for welding austenitic stainless steel and difficult to weld material
BOC Smootharc S 316L	E316L	
BOC Smootharc S 309L	E309L	Rutile basic coated low carbon electrode for welding mild steel to stainless steel and difficult to weld material

Electrode Size

The size of the electrode is generally dependent on the thickness of the section being welded, and the larger the section the larger the electrode required. In the case of light sheet the electrode size used is generally slightly larger than the work being welded. This means that if 1.5 mm sheet is being welded, 2.0 mm diameter electrode is the recommended size. The following table gives the recommended maximum size of electrodes that may be used for various thicknesses of section.

Recommended Electrode Sizes

Average Thickness of Plate or Section	Maximum Recommended Electrode Diameter
≤1.5 mm	2.0 mm
1.5–2.0 mm	2.5 mm
2.0–5.0 mm	3.15 mm
5.0–8.0 mm	4.0 mm
≥8.0 mm	5.0 mm

Welding Current

Correct current selection for a particular job is an important factor in arc welding. With the current set too low, difficulty is experienced in striking and maintaining a stable arc. The electrode tends to stick to the work, penetration is poor and beads with a distinct rounded profile will be deposited.

Excessive current is accompanied by overheating of the electrode. It will cause undercut, burning through of the material, and give excessive spatter. Normal current for a particular job may be considered as the maximum which can be used without burning through the work, overheating the electrode or producing a rough spattered surface, i.e. the current in the middle of the range specified on the electrode package is considered to be the optimum.

In the case of welding machines with separate terminals for different size electrodes, ensure that the welding lead is connected to the correct terminal for the size electrode being used. When using machines with adjustable current, set on the current range specified.

The limits of this range should not normally be exceeded.

The following table shows the current ranges generally recommended for BOC Smootharc 13.

Generally Recommended Current Range for BOC Smootharc 13

Size of Electrode (mm)	Current Range (Amp)
2.5	60–95
3.2	110–130
4.0	140–165
5.0	170–260

Arc Length

To start the arc, the electrode should be gently scraped on the work until the arc is established. There is a simple rule for the proper arc length; it should be the shortest arc that gives a good surface to the weld. An arc too long reduces penetration, produces spatter and gives a rough surface finish to the weld. An excessively short arc will cause sticking of the electrode and rough deposits that are associated with slag inclusions.

For downhand welding, it will be found that an arc length not greater than the diameter of the core wire will be most satisfactory. Overhead welding requires a very short arc, so that a minimum of metal will be lost. Certain BOC electrodes have been specially designed for ‘touch’ welding. These electrodes may be dragged along the work and a perfectly sound weld is produced.

Electrode Angle

The angle which the electrode makes with the work is important to ensure a smooth, even transfer of metal. The recommended angles for use in the various welding positions are covered later.

Correct Travel Speed

The electrode should be moved along in the direction of the joint being welded at a speed that will give the size of run required. At the same time the electrode is fed downwards to keep the correct arc length at all times. As a guide for general applications the table below gives recommended run lengths for the downhand position.

Correct travel speed for normal welding applications varies between approximately 125–375 mm per minute, depending on electrode size, size of run required and the amperage used.

Excessive travel speeds lead to poor fusion, lack of penetration, etc. Whilst too slow a rate of travel will frequently lead to arc instability, slag inclusions and poor mechanical properties.

Run Length per Electrode – BOC Smootharc 13

Electrode Size (mm)	Electrode Length (mm)	Run Length (mm)	
		Minimum	Maximum
4.0	350	175	300
3.2	350	125	225
2.5	350	100	225

Correct Work Preparation


The method of preparation of components to be welded will depend on equipment available and relative costs. Methods may include sawing, punching, shearing, lathe cut-offs, flame cutting and others. In all cases edges should be prepared for the joints that suit the application. The following section describes the various joint types and areas of application.

2.6 Types of Joints

Butt Welds

A butt weld is a weld made between two plates so as to give continuity of section. Close attention must be paid to detail in a butt weld to ensure that the maximum strength of the weld is developed. Failure to properly prepare the edges may lead to the production of faulty welds, as correct manipulation of the electrode is impeded.

Butt Welding



Two terms relating to the preparation of butt welds require explanation at this stage. They are:

- **Root Face:** the proportion of the prepared edge that has not been bevelled.
- **Root Gap:** the separation between root faces of the parts to be joined.

Various types of butt welds are in common use and their suitability for different thickness of steel are described as follows:

Square Butt Weld



The edges are not prepared but are separated slightly to allow fusion through the full thickness of the steel. Suitable for plate up to 6 mm in thickness.

Single 'V' Butt Weld




This is commonly used for plate up to 16 mm in thickness and on metal of greater thickness where access is available from only one side.

Double 'V' Butt Weld




Used on plate of 12 mm and over in thickness when welding can be applied from both sides. It allows faster welding and greater economy of electrodes than a single 'V' preparation on the same thickness of steel and also has less of a tendency to distortion as weld contraction can be equalised.

Butt Weld with Backing Material




When square butt welds or single 'V' welds cannot be welded from both sides it is desirable to use a backing bar to ensure complete fusion.

Single 'U' Butt Weld




Used on thick plates an alternative to a single 'V' preparation. It has advantages as regards speed of welding. It takes less weld metal than a single 'V', there is less contraction and therefore a lessened tendency to distortion. Preparation is more expensive than in the case of a 'V', as machining is required. The type of joint is most suitable for material over 40 mm in thickness.

Double 'U' Butt Weld



For use on thick plate that is accessible for welding from both sides. For a given thickness it is faster, needs less weld metal and causes less distortion than a single 'U' preparation.

Horizontal Butt Weld



The lower member in this case is bevelled to approximately 15° and the upper member 45° , making an included angle of 60° . This preparation provides a ledge on the lower member, which tends to retain the molten metal.

General notes on Butt Welds

The first run in a prepared butt weld should be deposited with an electrode not larger than 4.0 mm. The angle of the electrode for the various runs in a butt weld is shown.

It is necessary to maintain the root gap by tacking at intervals or by other means, as it will tend to close during welding.




All single 'V', single 'U' and square butt welds should have a backing run deposited on the underside of the joint; otherwise 50% may be deducted from the permissible working stress of the joint.

Before proceeding with a run on the underside of a weld it is necessary to remove any surplus metal or under penetration that is evident on that side of the joint.

Butt welds should be overfilled to a certain extent by building up the weld until it is above the surface of the plate. Excessive build-up, however, should be avoided.

In multi-run butt welds it is necessary to remove all slag, and surplus weld metal before a start is made on additional runs; this is particularly important with the first run, which tends to form sharp corners that cannot be penetrated with subsequent runs. Electrodes larger than 4.0 mm are not generally used for vertical or overhead butt welds.


The diagrams following indicate the correct procedure for welding thick plate when using multiple runs.



2.7 Fillet Welds


A fillet weld is approximately triangular in section, joining two surfaces not in the same plane and forming a lap joint, tee joint or corner joint. Joints made with fillet welds do not require extensive edge preparation, as is the case with butt welded joints, since the weld does not necessarily penetrate the full thickness of either member. It is important that the parts to be joined be clean, close fitting, and that all the edges on which welding is to be carried out are square. On sheared plate it is advisable to entirely remove any 'false cut' on the edges prior to welding. Fillet welds are used in the following types of joints:

'T' Joints




A fillet weld may be placed either on one or both sides, depending on the requirements of the work. The weld metal should fuse into or penetrate the corner formed between the two members. Where possible the joint should be placed in such a position as to form a "Natural 'V' fillet" since this is the easiest and fastest method of fillet welding.

Lap Joints



In this case, a fillet weld may be placed either on one or both sides of the joint, depending on accessibility and the requirements of the joint. However, lap joints, where only one weld is accessible, should be avoided where possible and must never constitute the joints of tanks or other fabrications where corrosion is likely to occur behind the lapped plates. In applying fillet welds to lapped joints it is important that the amount of overlap of the plates be not less than five times the thickness of the thinner part. Where it is required to preserve the outside face or contour of a structure, one plate may be jogged.

Corner Joints



The members are fitted as shown, leaving a 'V'-shaped groove in which a fillet weld is deposited. Fusion should be complete for the full thickness of the metal. In practice it is generally necessary to have a gap or a slight overlap on the corner. The use of a 1.0–2.5 mm gap has the advantage of assisting penetration at the root, although setting up is a problem. The provision of an overlap largely overcomes the problem of setting up, but prevents complete penetration at the root and should therefore be kept to a minimum, i.e. 1.0–2.5 mm.

The following terms and definitions are important in specifying and describing fillet welds.

Leg Length

A fusion face of a fillet weld, as shown below. All specifications for fillet weld sizes are based on leg length.

Throat Thickness


A measurement taken through the centre of a weld from the root to the face, along the line that bisects the angle formed by the members to be joined.

Effective throat thickness is a measurement on which the strength of a weld is calculated. The effective throat thickness is based on a mitre fillet (concave Fillet Weld), which has a throat thickness equal to 70% of the leg length. For example, in the case of a 20 mm fillet, the effective throat thickness will be 14 mm.

Convex Fillet Weld


A fillet weld in which the contour of the weld metal lies outside a straight line joining the toes of the weld. A convex fillet weld of specified leg length has a throat thickness in excess of the effective measurement.

Convex Fillet Weld



Concave Fillet Weld

A fillet in which the contour of the weld is below a straight line joining the toes of the weld. It should be noted that a concave fillet weld of a specified leg length has a throat thickness less than the effective throat thickness for that size fillet. This means that when a concave fillet weld is used, the throat thickness must not be less than the effective measurement. This entails an increase in leg length beyond the specified measurement.



The size of a fillet weld is affected by the electrode size, welding speed or run length, welding current and electrode angle. Welding speed and run length have an important effect on the size and shape of the fillet, and on the tendency to undercut.

Insufficient speed causes the molten metal to pile up behind the arc and eventually to collapse. Conversely, excessive speed will produce a narrow irregular run having poor penetration, and where larger electrodes and high currents are used, undercut is likely to occur.

Fillet Weld Data

Nominal Fillet Size (mm)	Minimum Throat Thickness (mm)	Plate Thickness (mm)	Electrode Size (mm)
5.0	3.5	5.0–6.3	3.2
6.3	4.5	6.3–12	4.0
8.0	5.5	8.0–12 & over	4.0
10.0	7.0	10 & over	4.0

Selection of welding current is important. If it is too high the weld surface will be flattened, and undercut accompanied by excessive spatter is likely to occur. Alternatively, a current which is too low will produce a rounded narrow bead with poor penetration at the root. The first run in the corner of a joint requires a suitably high current to achieve maximum penetration at the root. A short arc length is recommended for fillet welding. The maximum size fillet which should be attempted with one pass of a large electrode is 8.0 mm. Efforts to obtain larger leg lengths usually result in collapse of the metal at the vertical plate and serious undercutting. For large leg lengths multiple run fillets are necessary. These are built up as shown below. The angle of the electrode for various runs in a downhand fillet weld is shown below.

Recommended Electrode Angles for Fillet Welds

1st Run	2nd Run
3rd Run	Multi-run Fillet

Multi-run horizontal fillets have each run made using the same run lengths (run length per electrode table). Each run is made in the same direction, and care should be taken with the shape of each, so that it has equal leg lengths and the contour of the completed fillet weld is slightly convex with no hollows in the face.


Vertical fillet welds can be carried out using the upwards or downwards technique. The characteristics of each are: upwards – current used is low, penetration is good, surface is slightly convex and irregular. For multiple run fillets large single pass weaving runs can be used. Downwards – current used is medium, penetration is poor, each run is small, concave and smooth (only BOC Smootharc 13 is suitable for this position).

The downwards method should be used for making welds on thin material only. Electrodes larger than 4.0 mm are not recommended for vertical down welding. All strength joints in vertical plates 10.0 mm thick or more should be welded using the upward technique. This method is used because of its good penetration and weld metal quality. The first run of a vertical up fillet weld should be a straight sealing run made with 3.15 mm or 4.0 mm diameter electrode. Subsequent runs for large fillets may be either numerous straight runs or several wide weaving runs.

Correct selection of electrodes is important for vertical welding.

In overhead fillet welds, careful attention to technique is necessary to obtain a sound weld of good profile. Medium current is required for best results. High current will cause undercutting and bad shape of the weld, while low current will cause slag inclusions. To produce a weld having good penetration and of good profile, a short arc length is necessary. Angle of electrode for overhead fillets is illustrated above.

Recommended Angles for Overhead Fillet Welds



2.8 Typical Defects Due to Faulty Technique

Shielded metal arc welding, like other welding processes, has welding procedure problems that may develop which can cause defects in the weld. Some defects are caused by problems with the materials. Other welding problems may not be foreseeable and may require immediate corrective action. A poor welding technique and improper choice of welding parameters can cause weld defects. Defects that can occur when using the shielded metal arc welding process are slag inclusions, wagon tracks, porosity, wormhole porosity, undercutting, lack of fusion, overlapping, burn through, arc strikes, craters, and excessive weld spatter. Many of these welding technique problems weaken the weld and can cause cracking. Other problems that can occur which can reduce the quality of the weld are arc blow, finger nailing, and improper electrode coating moisture contents.

Defects caused by welding technique

Slag Inclusions



SLAG INCLUSIONS


Slag inclusions occur when slag particles are trapped inside the weld metal which produces a weaker weld. These can be caused by:

- erratic travel speed
- too wide a weaving motion
- slag left on the previous weld pass
- too large an electrode being used
- letting slag run ahead of the arc.

This defect can be prevented by:

- a uniform travel speed
- a tighter weaving motion
- complete slag removal before welding
- using a smaller electrode
- keeping the slag behind the arc which is done by shortening the arc, increasing the travel speed, or changing the electrode angle.

Undercutting



UNDERCUTTING

Undercutting is a groove melted in the base metal next to the toe or root of a weld that is not filled by the weld metal. Undercutting causes a weaker joint and it can cause cracking.

This defect is caused by:

- excessive welding current
- too long an arc length
- excessive weaving speed
- excessive travel speed.


On vertical and horizontal welds, it can also be caused by too large an electrode size and incorrect electrode angles. This defect can be prevented by:

- choosing the proper welding current for the

type and size of electrode and the welding position

- holding the arc as short as possible
- pausing at each side of the weld bead when a weaving technique is used
- using a travel speed slow enough so that the weld metal can completely fill all of the melted out areas of the base metal.

Lack of Fusion



LACK OF FUSION

Lack of fusion is when the weld metal is not fused to the base metal. This can occur between the weld metal and the base metal or between passes in a multiple pass weld. Causes of this defect can be:

- excessive travel speed
- electrode size too large
- welding current too low
- poor joint preparation
- letting the weld metal get ahead of the arc.

Lack of fusion can usually be prevented by:

- reducing the travel speed
- using a smaller diameter electrode
- increasing the welding current
- better joint preparation
- using a proper electrode angle.


3.0 Gas Tungsten Arc Welding (GTAW/TIG)

3.1 Introduction

The Tungsten Inert Gas, or TIG process, uses the heat generated by an electric arc struck between a non-consumable tungsten electrode and the workpiece to fuse metal in the joint area and produce a molten weld pool. The arc area is shrouded in an inert or reducing gas shield to protect the weld pool and the non-consumable electrode. The process may be operated autogenously, that is, without filler, or filler may be added by feeding a consumable wire or rod into the established weld pool.

3.2 Process

1	Shielding gas
2	Arc
3	TIG filler rod
4	Weld pool
5	Collet
6	Tungsten Electrode
7	Workpiece



Schematic of the TIG welding process

Direct or alternating current power sources with constant current output characteristics are normally employed to supply the welding current. For DC operation the tungsten may be connected to either output terminal, but is most often connected to the negative pole. The output characteristics of the power source can have an effect on the quality of the welds produced.

Shielding gas is directed into the arc area by the welding torch and a gas lens within the torch distributes the shielding gas evenly over the weld area. In the torch the welding current is transferred to the tungsten electrode from the copper conductor. The arc is then initiated by one of several methods between the tungsten and the workpiece.

During TIG welding, the arc can be initiate by several means:

Scratch Start

With this method, the tungsten electrode is physically scratched on the surface of the workpiece and the arc is initiated at the full amperage set by the operator. The incidence of the tungsten melting at the high initiation amperage is high and tungsten inclusions in the weld metal are quite common.

High Frequency Start

During High Frequency start, the arc will ‘jump’ towards the workpiece if a critical distance is reached. With this method, there is no incidence of tungsten inclusions happening. High Frequency is only available on certain types of machines and it can affect nearby electronic equipment.

Lift Arc™

During this method of arc initiation, the tungsten is actually touching the workpiece. This occurs at very low amperage that is only sufficient to pre-heat, not melt the tungsten. As the tungsten is moved off the plate, the arc is established. With this method, there is little chance of tungsten inclusion occurring.

3.3 Process Variables

DCEN

When direct-current electrode-negative (straight polarity) is used:

- Electrons strike the part being welded at a high speed.
- Intense heat on the base metal is produced.
- The base metal melts very quickly.
- Ions from the inert gas are directed towards the negative electrode at a relatively slow rate.
- Direct current with straight polarity does not require post-weld cleaning to remove metal oxides.

Use of DCEN


For a given diameter of tungsten electrode, higher amperage can be used with straight polarity. Straight polarity is used mainly for welding:

- Carbon steels
- Stainless steels
- Copper alloys

The increased amperage provides:

- Deeper penetration
- Increased welding speed
- A narrower, deeper, weld bead.

DCEN - Narrow bead - Deep penetration



DCEP


The DCEP (reverse polarity) are different from the DCEN in following ways:

- High heat is produced on the electrode rather than on the base metal.
- The heat melts the tungsten electrode tip.
- The base metal remains relatively cool compared to sing straight polarity.
- Relatively shallow penetration is obtained.
- An electrode whose diameter is too large will reduce visibility and increase arc instability.

Use of DCEP


- Intense heat means a larger diameter of electrode must be used with DCEP.
- Maximum welding amperage should be relatively low (approximately six times lower than with DCEN).

DCEP - Wide bead - Shallow penetration



3.4 Welding Techniques


Welding techniques




The suggested electrode and welding rod angles for welding a bead on plate. The same angles are used when making a butt weld. The torch is held 60–75° from the metal surface. This is the same as holding the torch 15–30° from the vertical. Take special note that the rod is in the shielding gas during the welding process.

Torch and filler metal manual control guidelines

Flat position (1G)




Horizontal position (2G)



Vertical position (3G)

Upwards progression



A = Torch travel angle – forehand technique
– push angle 10–20° (to the vertical)

B = Work angle: 90°

C = Filler metal feed angle: 10–20°

D = Arc length: 1–1.5 x electrode diameter

3.5 Shielding Gas Selection

Brass	With argon, the arc is stable and there is little smoke.
Cobalt-based alloys	Argon provides a stable, easy-to-control arc.
Copper nickel (Monel)	Argon gives a stable, easy-to-control arc. Also used for welding copper nickel to steel.
Deoxidised copper	Helium is preferred as it helps greatly in counteracting thermal conductivity of copper. A mixture of 75% helium and 25% argon (Alushield Heavy) produces a stable arc, less heat than an arc produced with helium alone.
Nickel alloys (Inconel)	Argon produces a very stable arc. Helium is recommended for automatic welding at high speeds.
Mild steel	For manual welding, argon is recommended. Successful welding depends on the skill of the welder. Helium is preferred for: • high speed automatic welding • where deeper penetration than with argon is required • small HAZ
Magnesium alloys	Argon recommended with continuous high frequency AC. Produces good arc stability and good cleaning action
0.5% Molybdenum	Pure argon or helium is recommended. For good welding ductility, welding must be carried out in a draught-free area.
Silicon bronze	Argon decreases internal tension in base metal and in the weld since there is less penetration with this gas compared to helium.
Stainless steel	Argon is the most commonly used gas for stainless steel. Helium can be used if better penetration is required.
Titanium alloys	Argon produces a stable arc. Helium is recommended for high speed welding.

3.6 Consumable Selection

a) Welding wire

The following table includes the recommended welding consumable for the most commonly welded materials.

Base Material	BOC Consumable
C-Mn and low Carbon steels	BOC Mild steel TIG wire
Low Alloy steels	
1.25Cr/0.5Mo	Comweld CrMo1
2.5Cr/1Mo	Comweld CrMo2
Stainless Steel	
304/304L	Profill 308
316/316L	Profill 316
309/309-C-Mn	Profill 309
321/Stabilised grades	Profill 347

Filler rod diameter (mm)	Thickness of metal (mm)
2	0.5–2
3	2–5
4	5–8
4 or 5	8–12
5 or 6	12 or more


b) Non consumable Tungstens

Tungsten Electrode Selector Chart				
Base metal type	Thickness range	Desired results	Welding current	Electrode type
Copper alloys, Cu-Ni alloys and Nickel alloys	All	General purpose	DCSP	2% Thoriated (EW-Th2)
				2% Ceriated (EW-Ce2)
	Only thin sections	Control penetration	ACHF	Zirconiated (EW-Zr)
	Only thick sections	Increase penetration or travel speed	DCSP	2% Ceriated (EW-Ce2)
Mild Steels, Carbon Steels, Alloy Steels, Stainless Steels and Titanium alloys	All	General purpose	DCSP	2% Thoriated (EW-Th2)
				2% Ceriated (EW-Ce2)
				2% Lanthanated (EWG-La2)
	Only thin sections	Control penetration	ACHF	Zirconiated (EW-Zr)
	Only thick sections	Increase penetration or travel speed	DCSP	2% Ceriated (EW-Ce2)
				2% Lanthanated (EWG-La2)

	Shielding gas	Tungsten performance characteristics
	75% Argon/ 25% Helium	Best stability at medium currents. Good arc starts. Medium tendency to spit. Medium erosion rate.
	75% Argon/ 25% Helium	Low erosion rate. Wide current range. AC or DC. No spitting. Consistent arc starts. Good stability.
	Argon	Use on lower currents only. Spitting on starts. Rapid erosion rates at higher currents.
	75% Argon/ 25% Helium	Low erosion rate. Wide current range. AC or DC. No spitting. Consistent arc starts. Good stability.
	75% Argon/ 25% Helium	Best stability at medium currents. Good arc starts. Medium tendency to spit. Medium erosion rate.
	75% Argon/ 25% Helium	Low erosion rate. Wide current range. AC or DC. No spitting. Consistent arc starts. Good stability.
	75% Argon/ 25% Helium	Lowest erosion rate. Widest current range on DC. No spitting. Best DC arc starts and stability.
	Argon	Use on lower current only. Spitting on starts. Rapid erosion rates at higher currents.
	75% Argon/ 25% Helium	Low erosion rate. Wide current range. No spitting. Consistent arc starts. Good stability.
	Helium	Lowest erosion rate. Highest current range. No spitting. Best DC arc starts and stability.

Tungsten tip preparation

DCSP (EN) or DCRP (EP)




ACHP General Purpose



Ball tip by arcing on clean metal at low current DCRP (EP) then slowly increase current to form the desired ball diameter. Return setting to AC.

Tungsten Grinding

Shape by grinding longitudinally (never radially). Remove the sharp point to leave a truncated point with a flat spot. Diameter of flat spot determines amperage capacity. (See below)




The included angle determines weld bead shape and size. Generally, as the included angle increases, penetration increases and bead width decreases.




Use a medium (60 grit or finer) aluminium oxide wheel.

Tungsten Extension

Standard Parts



Gas Lens Parts



Tungsten electrode tip shapes and current ranges


Thoriated, ceriated, and lanthanated tungsten electrodes do not ball as readily as pure or zirconiated tungsten electrodes, and as such are typically used for DCSP welding. These electrodes maintain a ground tip shape much better than the pure tungsten electrodes. If used on AC, thoriated and lanthanated electrodes often spit. Regardless of the electrode tip geometry selected, it is important that a consistent tip configuration be used once a welding procedure is established. Changes in electrode geometry can have a significant influence not only on the weld bead width, depth of penetration, and resultant quality, but also on the electrical characteristics of the arc. Below is a guide for electrode tip preparation for a range of sizes with recommended current ranges.

Electrode Diameter (mm)	Diameter at tip (mm)	Constant included angle, (degrees)	Current range (A)
1.0	0.125	12	2–15
1.0	0.250	20	5–30
1.6	0.500	25	8–50
1.6	0.800	30	10–70
2.3	0.800	35	12–90
2.3	1.100	45	15–150
3.2	1.100	60	20–200
3.2	1.500	90	25–250

3.7 Typical Welding Joints for Gas Tungsten Arc Welding


Butt welds

TIG welding is commonly combined with other faster filling processes such as MMA or MIG welding. It is therefore not uncommon to use the same weld preparations as would have been used for the filling process. When welding a butt joint, centre the weld pool on the adjoining edges. When finishing, decrease the heat (amperage) to aid in filling the crater.




Lap joint

For a lap weld, form the weld pool so that the edge of the overlapping piece and the flat surface of the second piece flow together. Since the edge will melt faster, dip the filler rod next to the edge and make sure you are using enough filler metal to complete the joint.




T-joint

When welding a T-joint, the edge and the flat surface are to be joined together, and the edge will melt faster. Angle the torch to direct more heat to the flat surface and extend the electrode beyond the cup to hold a shorter arc. Deposit the filler rod where the edge is melting.



Corner joint

For a corner joint, both edges of the adjoining pieces should be melted and the weld pool should be kept on the joint centre line. A convex bead is necessary for this joint, so a sufficient amount of filler metal is needed.




Troubleshooting guide		
Problem	Cause	Solution
Excessive electrode consumption	1. Inadequate gas flow 2. Improper size electrode for current required 3. Operating of reverse polarity 4. Electrode contamination 5. Excessive heating inside torch 6. Electrode oxidising during cooling 7. Shield gas incorrect	1. Increase gas flow 2. Use larger electrode 3. User larger electrode or change polarity 4. Remove contaminated portion, then prepare again 5. Replace collet. Try wedge collet or reverse collet. 6. Increase gas flow post time to 1 sec per 10 amps 7. Change to proper gas (no oxygen or CO₂)
Erratic Arc	1. Incorrect voltage (arc too long) 2. Current too low for electrode size 3. Electrode contaminated 4. Joint too narrow 5. Contaminated shield gas. Dark stains on the electrode or weld bead indicate contamination 6. Base metal is oxidised, dirty or oily	1. Maintain short arc length 2. Use smaller electrode or increase current 3. Remove contaminated portion, then prepare again 4. Open joint groove 5. The most common cause is moisture or aspirated air in gas stream. Use welding grade gas only. Find the source of the contamination and eliminate it promptly. 6. Use appropriate chemical cleaners, wire brush, or abrasives prior to welding
Inclusion of tungsten or oxides in weld	1. Poor lift starting technique 2. Excessive current for tungsten size used 3. Accidental contact of electrode with puddle 4. Accidental contact of electrode to filler rod 5. Using excessive electrode extension 6. Inadequate shielding or excessive drafts 7. Wrong gas 8. Heavy surface oxides not being removed	1. Many codes do not allow scratch starts. Use copper strike plate. 2. Reduce the current or use larger electrode 3. Maintain proper arc length 4. Maintain a distance between electrode and filler metal 5. Reduce the electrode extension to recommended limits 6. Increase gas flow, shield arc from wind, or use gas lens 7. Do not use ArO₂ or ArCO₂ GMAW (MIG) gases for TIG welding 8. Joint area needs to be cleaned prior to welding
Porosity in Weld Deposit	1. Entrapped impurities, hydrogen, air, nitrogen, water vapour 2. Defective gas hose or loose connection 3. Filler material is damp (particularly aluminium) 4. Filler material is oily or dusty	1. Do not weld on wet material. Remove condensation from line with adequate gas pre-flow time 2. Check hoses and connections for leaks 3. Dry filler metal in oven prior to welding 4. Replace filler metal

Troubleshooting guide		
Problem	Cause	Solution
Porosity in Weld Deposit	5. Alloy impurities in the base metal such as sulphur, phosphorous, lead and zinc 6. Excessive travel speed with rapid freezing of weld trapping gases before they escape 7. Contaminated shield gas	5. Change to a different alloy composition which is weldable. These impurities can cause a tendency to crack when hot. 6. Lower the travel speed 7. Replace the shielding gas
Cracking in Welds	1. Hot cracking in heavy section or with metals which are hot shorts 2. Crater cracks due to improperly breaking the arc or terminating the weld at the joint edge 3. Post weld cold cracking due to excessive joint restraint, rapid cooling or hydrogen embrittlement 4. Centreline cracks in single pass weld 5. Underbead cracking from brittle microstructure	1. Preheat. Increase weld bead cross-section size. Change weld bead contour. Use metal with fewer alloy impurities 2. Reverse direction and weld back into previous weld at edge. Use Amprak or foot control to manually down slope current 3. Preheat prior to welding. Use pure or non-contaminated gas. Increase the bead size. Prevent craters or notches. Change the weld joint design. 4. Increase bead size. Decrease root opening. Use preheat. Prevent craters. 5. Eliminate sources of hydrogen, joint restraint, and use preheat
Inadequate shielding	1. Gas flow blockage or leak in hoses or torch 2. Excessive travel speed exposes molten weld to atmospheric contamination 3. Wind or drafts 4. Excessive electrode stickout 5. Excessive turbulence in gas stream	1. Locate and eliminate the blockage or leak 2. Use slower travel speed or carefully increase the flow rate to a safe level below creating excessive turbulence. Use a trailing shield cup. 3. Set up screens around the weld area 4. Reduce electrode stickout. Use a larger size cup 5. Change to gas safer parts or gas lens parts
Arc Blow	1. Induced magnetic field from DC weld current 2. Arc is unstable due to magnetic influence	1. Rearrange the split ground connection 2. Reduce weld current and use arc length as short as possible
Short parts Life	1. Short water cooled leads life 2. Cup shattering or cracking in use 3. Short collet life 4. Short torch head life	1. Verify coolant flow direction. Return flow must be on the power cable lead 2. Change cup size or type. Change tungsten position 3. Ordinary style is split and twists or jams. Change to wedge style 4. Do not operate beyond rated capacity. Use water cooled model. Do not bend rigid torches


4.0 Machine Specifications and Contents

4.1 Operating Controls



1	Power indicator light
2	Overtemperature control indicator
3	Welding current regulator
4	On/Off switch
5	Process selector switch MMA/Lift TIG
6	Heavy duty 15A input plug
7	Negative '35' dinse connector
8	Positive '35' dinse connector

5.0 Operating Functions



1	Power indicator light
2	Overtemperature control indicator
3	Welding current regulator
4	On/Off switch
5	Process selector switch MMA/Lift TIG

Always switch the machine off at the supply switch. When changing electrode or return leads the machine's on/off switch **4** should be in the off position. The machine should then also be switched off at the mains supply plug and the plug removed from the supply socket.

The green power light **1** will illuminate when the machine is switched on using the on/off switch **4**.

The machine is fitted with a process selector switch **5** that will change the function of the machine from MMA to Lift TIG.

The machine will stop working if the temperature reaches a certain level. (Exceeds the units duty cycle). The overtemperature control indicator light **2** will illuminate.

5.1 Welding selections

Manual Metal Arc welding (MMA)

- Select the current as per the recommendations of the consumable manufacturer.
- Select the polarity of the electrode cable as per the recommendations (+/-)
- Select the process selector switch to MMA

DCTIG welding (Lift TIG)

- Select the current as per the recommendations of the consumable manufacturer.
- Connect the TIG torch to the negative (-) pole of the welding machine.
- Select the process selector switch to 'Lift TIG'
- When Lift TIG is selected the tungsten electrode can be touched onto the workpiece. The arc will be initiated as the electrode is moved upwards and the current will revert to the adjusted current.

5.2 Earthing

For the welding process to be most effective it is important to ensure that there is a solid connection between the work return clamp and the workpiece.

Always ensure that the return clamp is as close as practically possible to the area to be welded.

Ensure that the workpiece is clean and free from rust, scale paint or oil and grease before affixing the work return clamp.

6.0 Technical Specifications

		MMA170	
Part No.		MMA170P	
Input Voltage (V)		1PH AC240V±15%	
Frequency (Hz)		50/60	
Input Plug Requirement		Industrial Heavy duty 15A	
Rated Current (A)	MMA	27.5	
	TIG	20.3	
No-load Voltage (V)		65	
Output Current Range (A)		20-170	
Rated Output Voltage (V)		26.8	16.8
Duty Cycle (%)		35%	100%
	MMA	170A	132A
	TIG	170A	132A
No-load Loss (W)		40	
Efficiency (%)		80	
Power Factor		0.73	
Insulation Grade		F	
Housing Protection Grade		IP21	
Weight (kg)		7.5	
Dimension (mm)		430×185×306	

7.0 Periodic Maintenance

In maintenance of the unit, take into consideration the rate of use and the environment it is used in. When the unit is used properly and serviced regularly, you will avoid unnecessary disturbances in use and production.

7.1 Daily Maintenance

Perform the following maintenance daily:

- Clean electrode holder and TIG torch's gas nozzle. Replace damaged or worn parts.
- Check TIG torch's electrode. Replace or sharpen, if necessary.
- Check tightness of welding and earth cable connections.
- Check condition of mains and welding cables and replace damaged cables.
- See that there is enough space in front of and back of the unit for ventilation.

7.2 Troubleshooting

Main switch signal light is not lit.

Unit does not get electricity.

- Check mains fuses and replace if necessary.
- Check mains cable and plug, replace damaged parts.

Unit does not weld well.

Arc is uneven and goes off. Electrode gets stuck in weld pool.

- Check welding settings and adjust when necessary.
- Check that earth clamp is properly fixed and that contact surface is clean and the cable is undamaged.

Signal light for overheating is lit.

The unit has overheated. See 5.0 Operating Functions

- Check that there is ample space in front of and back of the unit for ventilation.
- Check welding settings. See 5.1 Welding Selections

If problems in use are not solved with above mentioned measures, please contact your local BOC representative.

8.0 Terms of Warranty

Warranty for Smootharc MMA170

8.1 Terms of Warranty

BOC provides a warranty for the Smootharc MMA170 sold by it against defects in manufacture and materials.

- Valid for 18 months from date of purchase.
- An authorised BOC Service Agent must carry out warranty repairs.
- Freight, packaging and insurance costs are to be paid for by the claimant.
- No additional express warranty is given unless in writing signed by an authorised manager of BOC.
- This warranty is in addition to any other legal rights you may have.
- Electrode holders are not covered.

8.2 Limitations on Warranty

The following conditions are not covered:

- Non compliance with operating and maintenance instructions such as connection to incorrect faulty voltage supply including voltage surges outside equipment specs, and incorrect overloading
- Natural wear and tear, and accidental damage
- Transport or storage damage.

8.3 Warranty Repairs

BOC or their Authorised Service Agent must be informed of the warranty defects, and the product returned within the warranty period.

- Before any warranty work is undertaken, the customer must provide proof of purchase and serial number of the equipment in order to validate the warranty.
- The parts replaced under the terms of the warranty remain the property of BOC.

9.0 Recommended Safety Guidelines

Some safety precautions BOC recommends are as follows:

- Repair or replace defective cables immediately.
- Never watch the arc except through lenses of the correct shade.
- In confined spaces, adequate ventilation and constant observation are essential.
- Leads and cables should be kept clear of passageways.
- Keep fire extinguishing equipment at a handy location in the shop.
- Keep primary terminals and live parts effectively covered.
- Never strike an electrode on any gas cylinder.
- Never use oxygen for venting containers.

Diagram and safety explanation		Diagram and safety explanation	
Electrical safety alert		Wear dry, insulated gloves	
Welding electrode causing electric shock		Insulate yourself from work and ground	
Fumes and gases coming from welding process		Disconnect input power before working on equipment	
Welding arc rays		Keep head out of fumes	
Read instruction manual		Use forced ventilation or local exhaust to remove fumes	
Become trained		Use welding helmet with correct shade of filter	



For more information on any BOC product or service call
the **BOC Customer Service Centre** on:

AUSTRALIA

131 262

Email: **contact@boc.com**

Website: **www.boc.com.au**

NEW ZEALAND

0800 111 333

Email: **customer-service-nz@boc.com**

Website: **www.boc.co.nz**

BOC Limited

ABN 95 000 029 729

Riverside Corporate Park

10 Julius Avenue

North Ryde, NSW 2113

AUSTRALIA

BOC Limited

970–988 Great South Road

Penrose, Auckland

NEW ZEALAND

