

#### **OPERATION & SERVICE MANUAL**

Models XTCII



#### **ABOUT THIS MANUAL AND MT EXPRESS**

Thank you for purchasing an MT Xpress product.

All of our equipment is assembled and packed with great care. If you should find any incorrect item, please contact your **Xpress** Dealer immediately.

MT Xpress products are Weights & Measures approved precision weighing instruments. However, you may want to obtain official certification through your supplier or local Weights & Measures office.

This **MT Xpress** product was developed, produced, and tested in a METTLER TOLEDO facility that has been audited and registered according to international ISO 9001 quality standards and ISO 14000 environment control program. Properly used and maintained, this product will provide years of accurate weighing. Handle it as you would any piece of fine electronic equipment.

Please READ this manual BEFORE operating or servicing this equipment. Follow the instructions carefully and save this manual for future reference.

We at **MT Xpress** want to make sure you received the product you expected. It is important to us that you are satisfied with your purchase. If there is anything we can help you with, or if you are not satisfied with either your product or the services received from the **Xpress** representative, let us know.

#### How can you reach us?

### **XPRESS CUSTOMER CARE CENTER, USA**

**24/7 Information and Support:** www.mt.com/xpress

xpress@mt.com

8 AM to 8 PM EST: Toll Free: 1-866-MTXPRESS

**Xpress** 

Mettler-Toledo, Inc. 60 Collegeview Westerville, OH 43081

#### **FCC APPROVAL**

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

# CONTENTS

SAFETY NOTICE	
PREPARING THE SCALE FOR USE	6
ENVIRONMENT	
UNPACKING AND ASSEMBLY	6
YOUR XPRESS SCALE AT A GLANCE	8
DISPLAY	8
KEYPAD	8
CURSORS (LED)	8
OPERATING YOUR SCALE	9
ZERO	9
TARE	9
COUNTING	
ACCUMULATION AND RECALL	11
ALARM	
SPECIAL MODES – SETUP MODE	
Entering setup mode	13
FUNCTION OF THE KEYS	13
CONFIGURATIONS	
CLEANING AND MAINTAINING YOUR SCALE	14
CLEANING AND MAINTENANCE	14
TROUBLESHOOTING	14
SERVICING YOUR SCALE	15
ENTERING SERVICE MODE	15
FUNCTION OF THE KEYS	15
CONFIGURATIONS	15
GRAVITY ADJUSTMENT	17
CALIBRATION	17
BATTERY REPLACEMENT	19
APPENDIX	21
ERROR MESSAGES	21
SPECIFICATIONS	22
GEO VALUE TABLE	23
PHYSICAL DIMENSIONS	24

#### **SAFETY NOTICE**









Product safety is a fundamental concern at MT Xpress. Use common sense and follow the simple precautions listed below to ensure your safety and to optimize the use and performance of this product.

- Read this manual before operating or servicing this product. Save this manual for future reference.
- Observe safety warnings located throughout this manual.
- Use caution when lifting or moving heavy equipment.
- This product should only be serviced by qualified personnel. Exercise care when moving, testing, or adjusting this product.
- Disconnect all power to this product before installing, servicing, or cleaning.
- Use only MT Xpress parts for repair.
- Observe electrostatic handling precautions for electronic components. Allow at least 30 seconds after power is disconnected to allow charges to dissipate before servicing any electronic components.
- Allow the product to adjust to room temperature before connecting the power source.

#### **Battery Notice**



When 'Lo' appears in the display window, the battery must be recharged or replaced by a new one. When connecting to an AC power supply, the battery can be automatically recharged. The charging cursor is "on" above the battery charging symbol . The charging time is usually 12 hours. If the charging is complete, the cursor will be off.



Never invert the positive and negative poles of battery. The red terminal is for the positive pole, the black terminal is for the black plug.



The battery must be taken out when the scale is not used for long periods of time. The battery should be recharged at least once every three months.



Do not use another type of battery to replace the one supplied with the scale.

FAILURE TO FOLLOW THESE PRECAUTIONS COULD RESULT IN DAMAGE TO OR DESTRUCTION OF THE EQUIPMENT, OR BODILY HARM.

#### PREPARING THE SCALE FOR USE

The **Xpress** XTCII is a new generation counting scale. With high internal and display resolution as well as a unique profile, the XTCII can widely be used in counting applications in the electronics, metals, plastics and other such industries. The **Xpress** XTCII is ready to use right out of the box.

This manual provides not only the detailed information on how to operate the scale, but also useful messages for service and maintenance.

Please read the manual thoroughly and familiarize yourself with all the safety requirements. All service procedures must only be performed by authorized personnel.

This chapter gives detailed instructions and important information regarding the successful installation of the **Xpress** Economy Counting Scale.

#### ENVIRONMENT

Before you install the scale, identify the best location for the equipment. The proper environment enhances its operation and longevity. Keep in mind the following factors, which might have a negative influence on the scale's operation:

**Vibration:** Vibration diminishes the scale's ability to measure accurately. Electrical machinery such as conveyors and drill presses can cause inaccurate and non-repeatable readings. The scale may also read inaccurately if it is not leveled properly.

**Air currents**: Moving air can cause the scale to read wind movement as an additional force and cause inconsistency in the weighing results.

**Friction**: A scale cannot measure accurately if an object is rubbing or pressing against the scale platform.

### UNPACKING AND ASSEMBLY

Please inspect the package immediately upon receipt. If the box is damaged, check for internal damage and file a freight claim with the carrier if necessary. If the container is undamaged, open the box, remove the scale and place it on a solid, flat surface. Please keep the packing material and shipping insert in case you need to return the scale to an MT Xpress representative.

Package contents for all **Xpress** Economy Counting Scales include:

#### <u>Product</u>

- XTCII Counting Scale
- Scale Pan
- Adapter 9 V / 500 mA
- Rubber gasket (4 pieces, only for 6 lb and 15 lb scale)
- Lead seal wire and lead


#### **Documents**


- Quick Start Guide
- Installation Instructions

#### CD-ROM


Operation & Service Manual


- 1. Place the scale on a flat surface.
- 2. Remove the protective screws (only for the 6 lb and 15 lb scales)






- 5. Connect the scale to the power outlet using the included adapter.
- 6. Level the scale by adjusting the four rubber feet until the leveling bubble is centered in the level indicator.
- 7. Turn on the scale.
- 8. The scale should be running for about fifteen (15) minutes before operation.







Proper alignment Improper alignment






The windows display from 0-9, the software version No. and '---'.
The cursors of stab and 0 are on.

# YOUR XPRESS SCALE AT A GLANCE

### DISPLAY





### **KEYPAD**


Key	Name	Function
$\odot$	Decimal	Enters a decimal point/Toggles alarm beep
<b>0</b> thru <b>9</b>	Numeric	Data entry (0-9)
SPL	Sample	Initiates sampling
APW	APW	Initiates Average Piece Weight (APW) entry
→0←	Zero	Zeroes the scale
<b>→T</b> ←	Tare	Subtracts tare value and switches from gross to net mode
M+	Accumulation	Adds the accumulator counts or recalls accumulation
MR	Recall	Recalls the accumulated quantity and times
ALM	Alarm	Sets the range for quantity or weight alarms
C	Clear	Clears data from the display
<b>P</b>	Enter/Setup	Confirms an operation or enters Setup Mode


### CURSORS (LED)

Key	Description
▷ Stab	Is lit when the weighing data is stable
⊳ 0	Is lit when the scale is at gross zero
▶ Net	Is lit when the scale displays a net weight
▶ <a> <a> <a> <a> <a> <a> <a> <a> <a> <a></a></a></a></a></a></a></a></a></a></a>	Is lit when the battery is being charged
⊳ M	Is lit when the value in the accumulator is <i>not</i> zero
⊳ Lo	Is lit when weight/quantity is less than the lower limit of alarm range
⊳ Hi	Is lit when weight/quantity exceeds the upper limit of alarm range

#### **OPERATING YOUR SCALE**









Press to capture a new center of zero if the scale is in gross weight mode and the weight on the scale is stable (e.g. 0.5000 lb, as above shown, the cursor **'Stab'** is on). The cursor **"O"** is lit when a new center of zero is captured.


### **TARE**

Pressing the key subtracts the weight of the object on the scale platform from subsequence indications of weight. Tare is most often used to subtract the weight an empty container. The key is used as well to clear a previously entered tare value if the scale is in net mode.

#### **Direct Tare**










Press the key in gross weight mode when the weight on the scale is above zero (e.g. 0.5000 lb as above shown) to tare the scale. If a net center of zero can be captured, the cursor 'Net' is on. By pressing the key again, the scale will be back in gross weight mode. The tare range is the full capacity of the scale.

### Input Tare (Digit Tare)








If the Function F3 in the Setup Mode is set to 1 (F3=1, see Setup Mode), the scale can be tared manually without weighing-in the tare value. Press the key to enter a tare value. The QTY window displays "InTare" to remind you to enter the tare. The input tare is displayed in the APW window and can be corrected by pressing the key if a wrong figure is entered. By pressing the key , you confirm the input tare value. The display shows the negative tar value in the weight window with the cursor "Net" on.

The input tare can be cleared by pressing the key again, and the scale is then back to gross weight mode.

### COUNTING

#### Counting by Sampling



Place the samples on the platter (e.g. 20 pieces weights 0.05 lb as shown above). Press the key sample. The QTY window displays SPL. Enter the sample quantity 20, and then press the key to confirm.


Press the key © to correct or clear the input figure.

The **Wt** window displays the sample Weight; the **APW** window displays Average Piece Weight of samples and the **QTY** displays the sample Quantity.


#### **APW Enhancement**

The APW (Average Piece Weight) enhancement can be activated in the Setup Mode (F5=1). This enhancement is used to get a more accurate APW. After a sampling is complete, the scale will automatically re-calculate the APW. However, the added quantity of pieces should be less than the quantity on the scale. The scale gives a 'beep' after every APW enhancement. The function is always available unless the added quantity of pieces is more than that the quantity on the scale.


#### For example:



Sampling with 20 pieces that weight 0.04 lb and an APW 0.002 lb.




If you add another 19 pieces to the scale ( $\leq$  20 pcs), a beep indicates that the APW is automatically recalculated to 0.0020115 lb.



If you add another 39 pieces to the scale ( $\leq$  39 pcs), again, a beep indicates that the APW is automatically recalculated to 0.0020208 lb.

If you know the APW. . .




If you know the APW of your goods, the APW can be entered directly instead of sampling.

Place the goods on the scale (e.g. 0.05 lb). Press the key and enter the APW (e.g. 0.002 lb) of one piece. The QTY window displays "Single" and the entered APW is displayed in the APW window. Press to confirm. The QTY window displays now the total quantity of pieces (e.g. 25).

You may press the key **C** to correct or clear the input figure.

#### ACCUMULATION AND RECALL



The key •• can be used to keep the quantity in the memory. The cursor 'M' is lit when the accumulated quantity is not zero. The Wt window displays 'Total' and the APW window displays accumulation times (e.g. 3 times). The QTY window displays the accumulated quantity (e.g. 1500 pcs).

Press to confirm, then the quantity of goods on the scale into memory (e.g. 500 pcs).

To clear the accumulation, press **C** and the cursor "M" will be off.

Press (e.g. 2000 pcs, 4 times). Press (b) to exit recall.

When the accumulated quantity is above 999,999, the QTY window displays "nnnnnn" to indicate that maximum number of accumulations has been reached.

If the weight on the scale hasn't been changed between two accumulations, the QTY window will display 'Again' to refuse the operation.

### <u>ALARM</u>

The alarm function includes a weight and a quantity alarm. Both alarms can either be set to sound within a defined range or over/under a defined range. The alarm function can be activated in the Setup Mode (F4/F4.1/F4.2/F4.3).


#### Temporarily Disable the Alarm Beep

For all functions, the alarm beep can be deactivated by pressing the key . Pressing . again will reactivate the alarm beep.

#### Weight Alarm within a Range


If weight alarm within a range is activated in the Setup Mode, press the key (1) to set the alarm range. The QTY window displays 'Lo 1' to remind you to enter the lower limit of the alarm range. The entered lower range is displayed in the APW window (e.g. 0.500 lb). Press the key (1) to confirm the lower limit. The QTY window now displays 'Hi 1' to remind you to enter the upper limit of the alarm range (e.g. 1.000 lb). Press (1) to complete the alarm range setting.

If the weight on the scale is within the alarm range (e.g. 0.800 lb on the scale, i.e.  $\geq$  0.500 lb and  $\leq$  0.1000 lb), the scale will beep continuously, and the cursors "Lo" and "Hi" will be lit. If the weight on the scale is less than the lower limit, the cursor 'Lo' will be on. The 'Hi' is on when the weight is higher than the upper limit.



#### Weight Alarm beyond a Range

If weight alarm beyond a range is activated in the Setup Mode, press (III) to set the alarm range. The QTY window displays 'Lo 1' to remind you to enter the lower limit of the alarm range. The entered lower range is displayed in the APW window (e.g. 0.5 lb). Press (III) to confirm the lower limit. The QTY window now displays 'Hi 1' to remind you to enter the upper limit of alarm range (e.g. 0.1000 lb). Press (III) to complete the alarm setting. If the weight on the scale is beyond the alarm range (e.g. 1.200 lb on the scale, i.e. < 0.500 lb or > 0.1000 lb) the scale will beep continuously. The cursor "Lo" will be on if the weight on the scale is less than the lower limit. The 'Hi' cursor is on when the weight is higher than the upper limit.



#### **Quantity Alarm**

The two quantity alarms (within a range/beyond a range) work the same way as the weight alarms. Instead of "Lo 1" and 'Hi 1', "Lo 2" and 'Lo 2' are indicated.

### **SPECIAL MODES – SETUP MODE**

### ENTERING SETUP MODE

Press and hold for three seconds to enter the Setup Mode. If you change the display resolution in the Setup Mode, the scale will perform its power-up process after exiting the Setup Mode. If the resolution remains unchanged, the scale will return to its previous state.

### FUNCTION OF THE KEYS

In the Setup Mode, the functions of the keys will be as follows:

Key	Function	Description
M+	Select	Switches between the parameters of 1 and 0
<b>₽</b>	Next	Confirm the choice and move forward
<b>→0</b> ←	Previous	Confirm the choice and steps backward

#### **CONFIGURATIONS**

Display	Parameter	Default
F1	Weighing unit 0 - weighing unit: lb 1 - weighing unit: kg	0
F2	Display resolution 0 - 3000 (6 lb=3000; 15 lb=3000; 30 lb=3000; 60 lb=3000) 1 - 6000/7500 (6 lb=6000; 15 lb=7500; 30 lb=6000; 60 lb=6000) 2 - 12,000/15,000 (6 lb=12,000; 15 lb=15,000; 30 lb=15,000; 60 lb=12,000) 3 - 30,000 (6 lb=30,000; 15 lb=prohibited; 30 lb=30,000; 60 lb=30,000)	2
F3	Input an advance tare O - disabled 1 — enable	0
F4	Alarm parameter change 0 - do not enter the alarm sub-menu 1 - enter the alarm sub-menu Note: If F4 is set 0, the scale will directly enter F5.	0
F4.1	Alarm function 0 - alarm is disabled 1 - alarm is available	0
F4.2	Weight alarm or quantity alarm 0 - weight alarm 1 - quantity alarm	Ö
F4.3	Alarm mode select 0 - alarm within a range 1 - alarm beyond a range	0
F5	APW enhancement 0 - disabled 1 - activated	0
F6	Automatic sleep 0 - disabled 1 - automatic sleep after 5 minutes if the weight on scale is not changed	Ö
F7	Zero capture range	3
F8	Push button zero range 0 – 20 % FS 1 – 2 % FS	0
E	Exit/Save 0 - do not save the change 1- save the changes	

#### **CLEANING AND MAINTAINING YOUR SCALE**



#### CLEANING AND MAINTENANCE

- DO NOT allow untrained personnel to operate, clean, inspect, maintain, service, or tamper with this
  equipment.
- DO NOT attempt to remove the cover or to perform service/maintenance on the internal parts of the scale.
- ALWAYS DISCONNECT this equipment from the power source before cleaning or performing maintenance.
- KEEP the scale clean. Periodically clean the keyboard and cover with a soft clean cloth that has been dampened with a mild window cleaner or detergent. DO NOT USE ANY TYPE OF INDUSTRIAL SOLVENT OR CHEMICALS. DO NOT SPRAY CLEANER DIRECTLY ONTO THE UNIT.
- DO NOT put the scale under water. You may use a damp cloth to clean the scale.

### **TROUBLESHOOTING**


If operational difficulties are encountered, first obtain as much information as possible regarding the problem. Failures and malfunctions can often be traced to simple causes such as loose connections, low battery power, or improper setup.

Your authorized **Xpress** representative can perform additional troubleshooting.

### **SERVICING YOUR SCALE**



For the following services, please contact your Xpress representative at www.mt.com/xpress.



# 

**DISCONNECT ALL POWER TO THIS UNIT** BEFORE INSTALLING, SERVICING, CLEANING, OR REMOVING THE FUSE. FAILURE TO DO SO COULD RESULT IN BODILY HARM AND/OR PROPERTY DAMAGE.



BEFORE CONNECTING OR DISCONNECTING ANY INTERNAL ELECTRONIC COMPONENTS OR INTERCONNECTING WIRING BETWEEN ELECTRONIC EQUIPMENT, ALWAYS REMOVE POWER AND WAIT AT LEAST THIRTY (30) SECONDS BEFORE ANY CONNECTIONS OR DISCONNECTION'S ARE MADE. FAILURE TO OBSERVE THESE PRECAUTIONS COULD RESULT IN DAMAGE TO OR DESTRUCTION OF THE EQUIPMENT, OR BODILY HARM.

### **ENTERING SERVICE MODE**

In the Service Mode, calibration and other system parameter settings can be accessed. In order to enter the Service Mode momentarily short the contacts of the switch J3 while the unit is powered up. J3 is located on the upper side of the PCB, where the keypad cable and the main PCB are connected. The normal position for the J3 jumpers is OFF.

After access of Service Mode, the Wt window displays S1 O. Then assemble the scale to enter set up as follows.

### **FUNCTION OF THE KEYS**

In the Service Mode, the functions of the keys will be as follows:

Key	Function	Description				
M+	Select	Switches between the parameter 1 and 0				
(P)	N ext	Confirms the choice and moves forward				
<b>→0</b> ←	Previous	Confirms the choice and steps backward				

### **CONFIGURATIONS**


Display	Parameter	Default
S1	Display mode O- normal display 1- advanced display	0
S2	Calibration units O- Ib 1- kg	0
S3	GEO code setting O- not setting 1- Resetting	0
S4	Enter calibration sub-menu O- no 1- yes	0
S4.1	Calibration mode select O- full range calibration 1 - linearity calibration	0
Е	Save changes  0- exit without saving 1- save changes	0

### **GRAVITY ADJUSTMENT**

This scale has built-in compensation provisions to allow factory calibration, with destination correction capabilities, to compensate for variances on gravitational forces. If the scale is subjected to a different gravitational force at its destination location, this can be compensated for electronically by adjusting the geo value. The GEO value has 32 settings. The GEO value for any world location can be found in the GEO Value Table in the Appendix of this manual (See page 19.) as long as the geographical coordinates and elevation above sea level is known.

Select S3=1 and press (b) to enter the GEO sub-menu. The GEO value can be changed as shown below by pressing (m+).


1b/1000



#### CALIBRATION

To enter the calibration sub-menu, select S4=1. The scale can be calibrated in two modes, the full range calibration and the linearity calibration.

#### Example: 6 lb full range calibration (S4.1=0)



#### Example: 6 lb linearity calibration (S4.1=1)




When the Wt window display S4.1 1, press the key to calibrate the scale in linearity.



The scale displays SP 6, where 6 means the capacity is 6 lb, Pressing \*\* selects the capacity. Press \*\* to continue.

The Wt window displays 2----. The scale will capture zero weight by pressing the key . The scale should count down from 5.



The Wt window displays L 3. Put 3 lb weight on the scale, press to calibrate in half range. The scale counts down from 5.



Remove the weight on the scale. The Wt window displays L---6. Put 6 lb weight on the scale. Press to calibrate in full range. The scale should count down from 5.



Display E O. Press (M+) to switch to E 1 and save the result. The calibration is complete and the scale restarts.




### BATTERY REPLACEMENT

# **A** CAUTION


RISK OF EXPLOSION IF BATTERY IS REPLACED BY AN INCORRECT TYPE OR CONNECTED IMPROPERLY. DISPOSE OF USED BATTERIES ACCORDING TO LOCAL LAWS AND REGULATIONS.

Please replace the battery follow below steps:


- 1. Switch off the scale.
- 2. Open and remove the plastic battery cover on the rear of the XTCII.



3. Loosen the four M4 x 8 screws and remove the protective cover.




4. Carefully remove the power harness from the battery, replace a new battery and connect the terminal to the plug correctly.



# 🗘 CAUTION

RISK OF EXPLOSION IF BATTERY IS REPLACED WITH WRONG TYPE OR CONNECTED IMPROPERLY. CONNECT RED WIRE TO POSITIVE (+) BATTERY TERMINAL AND BLACK WIRE TO NEGATIVE (-) BATTERY TERMINAL!

- 5. Reinstall the protective cover and the plastic battery cover.
- 6. Switch on the scale and test for proper operation.



# **APPENDIX**



### **ERROR MESSAGES**

The scale will display an error message if a problem or an incorrect keyboard entry is sensed. The error codes are:

Display	Possible Cause	Troubleshooting
The Wt window displays E11	RAM error	1. Restart the scale.
,		2. Recalibrate the scale.
		3. Change the main PCB.
The Wt window displays E16	ROM error	1. Restart the scale.
-		2. Recalibrate the scale.
		3. Change the main PCB.
The Wt window displays E18/E3	EPROM checksum error	1. Restart the scale.
		2. Recalibrate the scale.
		3. Change the main PCB.
The Wt window displays E7	A/D convert error	Change the main PCB.
The Wt window displays E35	Less weight when calibration	Recalibrate the scale with a specified weight.
The Wt window displays "nnnnn"	Over capacity	Take away some weight
The Wt window displays "uuuuu"	Under capacity	1. Put the scale pan on.
' '		2. Press the key ••• to zero scale.
The QTY window displays	Quantity is over 999,999	Ol H
"nnnnnn"		Clear the accumulator.
	Cannot capture zero	Restart the scale with no weight.
	•	2. Recalibrate the scale.
		3. Change the load cell or main PCB.

# **SPECIFICATIONS**

Model	XTCII- 1003	XTCII- 1103	XTCII- 2003	XTCII- 2103	XTCII- 3003	XTCII- 3103	XTCII- 4003	XTCII- 4103
Maximum capacity (lb)	6		15		30		60	
Verified resolution (lb)	0.0	002	0.0	005	0.01		0.02	
Display resolution (lb)	0.0002, 0.0005, 0.001, 0.002		0.001, 0.002, 0.005		0.001, 0.002, 0.005, 0.01		0.002, 0.005, 0.01, 0.02	
Recommend minimum APW (lb)	0.0002		0.0004		0.001		0.0	002
Power supply	AC	AC/DC	AC	AC/DC	AC	AC/DC	AC	AC/DC
Shipment weight (lb)	11	13.2	11	13.2	11	13.2	11	13.2
Display				Red	LED			
Temperature range				5°C -	35° C			
Relative humidity				< 9	0%			
Pan size	13.5″ x 9.5″ (L x W)							
Scale size	13.6" x 14" x 4.5" (L x W x H)							
Package size	18.3″ x 16.5″ x 8.7″ (L x W x H)							

Power supply DC uses 6V, 5Ah rechargeable battery.

Specifications are subject to change without notice.





### **GEO VALUE TABLE**

Use the following geo codes if you relocate your scale to a site other than the original location where it was calibrated.

Northern					Height abo	re sea-leve	el in meters	······		***************************************	
and	0	325	650	975	1300	1625	1950	2275	2600	2925	3250
Southern	325	650	975	1300	1625	1950	2275	2600	2925	3250	3575
latitude in		y				ove sea-le	vel in feet	,		·	
degrees and minutes	0	1060	2130	3200	4260	5330	6400	7460	8530	9600	10,660
	1060	2130	3200	4260	5330	6400	7460	8530	9600	10,660	11,730
0° 0′ — 5° 46′	5	4	4	3	3	2	2	]	1	0	0
5° 46′ — 9° 52′	5	5	4	4	3	3	2	2	1	]	0
9° 52′ — 12° 44′	6	5	5	4	4	3	3	2	2	]	1
12° 44′ — 15° 6′	6	6	5	5	4	4	3	3	2	2	1
15° 6′ — 17° 10′	7	6	6	5	5	4	4	3	3	2	2
17° 10′ — 19° 2′	7	7	6	6	5	5	4	4	3	3	2
19° 2′ — 20° 45′	8	b	7	7	6	5	5	4	4	3	3
20° 45′ — 22° 22′	8	8			6	6	5	5	4	4	3
22° 22′ — 23° 54′	9	8	8		7 7	6 7	6	5	5	4	4
23° 54′ — 25° 21′ 25° 21′ — 26° 45′	10	9 9	8	<u>8</u> 8	, 8		6 7	6	5 6	5 5	4
	ė	Էսոսուսուսուսուսուսուսուսում					<u> </u>	6		÷	5
26° 45′ — 28° 6′ 28° 6′ — 29° 25′	10	10 10	9	9	8	8	7	7	6 7	6 6	5
28° 6′ — 29° 25′ 29° 25′ — 30° 41′	11		10 10	10	9	<u>8</u> 9	8 8	7	7	7	6
30° 41′ — 31° 56′	12	11 11	10	10	9	9	8	8 8	8	7	6 7
<b>}</b>	12	12	11		å	10	9		8		7
31° 56′ — 33° 9′ 33° 9′ — 34° 21′	13	12	11	11	10	10		9		8 g	
33° 9′ — 34° 21′ 34° 21′ — 35° 31′	13	12	12	11 12	11	11	10 10	9 10	9	8 9	8 8
<b></b>	13	13		12	11 12		10		-	9	
	14	13	13 13	12	12	11 12	11	10	10 10	ф	9
	15	\$	13 14	13	φ	12	12	11	11	10 10	10
38° 58′ — 38° 58′ 38° 58′ — 40° 5′	15	14		14	13	13	12	11	11	ļ	
38° 58′ — 40° 5′ 40° 5′ — 41° 12′	16	15 15	14 15	14	13 14	13	13	12 12	12	11	10 11
41° 12′ — 42° 19′	16	16	15	15	14	14	13	13	12	12	11
42° 19′ — 43° 26′	17	16	16	15	15	14	14	13	13	12	12
43° 26′ — 44° 32′	17	17	16	16	15	15	14	13	13	13	12
44° 32′ — 45° 38′	18	17	17	16	16	15	15	14	14	13	13
45° 38′ — 46° 45′	18	18	17	17	16	16	15	15	14	13	13
46° 45′ — 47° 51′	19	18	18	17	17	16	16	15	15	14	14
47° 51′ — 48° 58′	19	19	18	18	17	17	16	16	15	15	14
48° 58′ — 50° 6′	20	19	19	18	18	17	17	16	16	15	15
50° 6′ — 51° 13′	20	20	19	19	18	18	17	17	16	16	15
51° 13′ — 52° 22′	21	20	20	19	19	18	18	17	17	16	16
52° 22′ — 53° 31′	21	21	20	20	19	19	18	18	17	17	16
53° 31′ — 54° 41′	22	21	21	20	20	19	19	18	18	17	17
54° 41′ — 55° 52′	22	22	21	21	20	20	19	19	18	18	17
55° 52′ — 57° 4′	23	22	22	21	21	20	20	19	19	18	18
57° 4′ — 58° 17′	23	23	22	22	21	21	20	20	19	19	18
58° 17′ — 59° 32′	24	23	23	22	22	21	21	20	20	19	19
59° 32′ — 60° 49′	24	24	23	23	22	22	21	21	20	20	19
60° 49′ — 62° 9′	25	24	24	23	23	22	22	21	21	20	20
62° 9′ — 63° 30′	25	25	24	24	23	23	22	22	21	21	20
63° 30′ — 64° 55′	26	25	25	24	24	23	23	22	22	21	21
64° 55′ — 66° 24′	26	26	25	25	24	24	23	23	22	22	21
66° 24′ — 67° 57′	27	26	26	25	25	24	24	23	23	22	22
67° 57′ — 69° 35′	27	27	26	26	25	25	24	24	23	23	22
69° 35′ — 71° 21′	28	27	27	26	26	25	25	24	24	23	23
71° 21′ — 73° 16′	28	28	27	27	26	26	25	25	24	24	23
73° 16′ — 75° 24′	29	28	28	27	27	26	26	25	25	24	24
75° 24′ — 77° 52′	29	29	28	28	27	27	26	26	25	25	24
77° 52′ — 80° 56′	30	29	29	28	28	27	27	26	26	25	25
80° 56′ — 85° 45′	30	30	29	29	28	28	27	27	26	26	25
85° 45′ — 90° 00′	31	30	30	29	29	28	28	27	27	26	26

## PHYSICAL DIMENSIONS





### Notes

### **Notes**

Xpress
Mettler-Toledo, Inc.
60 Collegeview Westerville, OH 43081

7/2004 MTX04-OM015.1E

**ECONOMY COUNTING SCALE** www.mt.com/xpress