



2730 Release Notes

for Software Version J200R05

Copyright Protected Material 2006-2007. All rights reserved.

R/Evolution, RAIDar, Simulcache, EcoStor, and AssuredSnap are trademarks or registered trademarks of Dot Hill Systems Corp.

All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and in other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc. U.S. Government Rights—Commercial use. Government users are subject to the Sun Microsystems, Inc. standard license agreement and applicable provisions of the FAR and its supplements.

Microsoft Windows is a registered trademark of Microsoft Inc.

All other trademarks and registered trademarks are proprietary to their respective owners.

The material in this document is for information only and is subject to change without notice. While reasonable efforts have been made in the preparation of this document to assure its accuracy, changes in the product design can be made without reservation and without notification to its users.



Adobe PostScript

Contents

Firmware Versions	6
What's New in This Release	6
Persistent IP Address	6
New Critical Events	7
RAID 6 Support	7
Independent Cache Mode	7
Point-to-Point Topology	7
SMI-S v.1.1	7
AssuredCopy	7
PHY Status	8
Scheduler	8
What's Changed in This Release	8
Changes in Firmware Update Procedures	8
Volume Names	8
Parity Error Discovery	8
License Management	9
Solaris MPxIO Volume Naming Structure	9
Updating RAID Controller Software	10
Recording IP Addresses	10
Retrieving Firmware from the Customer Resource Center	11
Updating the Controllers Using RAIDar	12
Resetting the IP Addresses	13
Completing the Upgrade	16

Updating Expansion Enclosure Firmware	17
Updating the Expansion Enclosure Using RAIDar	17
Related Documentation	18
Supported Systems	19
Supported Operating Systems	19
Supported Disk Drive Configurations	19
Supported Disk Drives	20
Supported Fibre Channel Switches	21
Supported HBAs and Operating Systems	22
Supported SFPs	26
Solaris Patches	26
Downloading/Installing the Solaris Patch Cluster	26
Software and Firmware Configuration	27
Virtual Disk Size	27
Snapshot Configuration	28
Known Issues	29
Persistent IP Address	29
Documentation Errata	29
Known Bugs	30

Release Notes

This document contains late-breaking information about requirements that affect installation and operation of the R/Evolution 2730 and R/Evolution 2730T (2730 Turbo) storage systems. It supplements the R/Evolution 2730 documentation set.

Note – In this document, unless otherwise stated, the term “R/Evolution 2730” refers to both the R/Evolution 2730 and R/Evolution 2730T products. Apart from the processor speed and performance increase associated with the R/Evolution 2730T, there are no functional differences between current versions of these two products.

A R/Evolution 2730 storage system includes a 2730 Fibre Channel (FC) controller enclosure and up to four SAS expansion enclosures.

Features of the R/Evolution 2730 storage system include:

- 2 Gbit/sec and 4-Gbit/sec Fibre Channel data rates
- 9-Tbyte base capacity scalable to 42 Tbyte
- Low-latency cache mirroring with SimulCache
- Built-in snapshot capability with AssuredSnap
- Battery-free cache backup with EcoStor
- Windows, Linux, and UNIX support (cluster-certified)
- Redundant hot-swap components
- Controller enclosure supports one or two RAID controller modules; expansion enclosure supports one or two expansion I/O modules
- RoHS-5 and WEEE compliance

Read these release notes before attempting to install, upgrade, or use a R/Evolution 2730 storage system.

Firmware Versions

These release notes describe the functionality of software package J200R05.

- Management Controller (MC) firmware version W420R09
- MC Loader version 12.013
- Storage Controller (SC) firmware version J200R05
- SC loader 15.010
- Memory Controller FPGA version F300R19
- Complex Programmable Logic Device (CPLD) version B110J27
- Expander Controller (EC) firmware version I200B41
- Power supply unit (PSU) firmware version T021
- Expansion Enclosure Controller firmware version O200B28

Note – The expansion enclosure controller firmware is not automatically updated to the version shown when the J200R05 software package is installed. Manually upgrade all connected expansion enclosures to Expansion Enclosure Controller firmware version O200B28.

What's New in This Release

In addition to the fixed bugs found in previous releases, the J200R05 release includes new functionality described in this section.

Persistent IP Address

In previous versions of the firmware, the IP address was stored in the flash memory of the controller. If it was necessary to replace a controller, you would have to update the IP address of the new controller. Beginning with the J200 release, the IP address is persistent. The IP address is stored on the midplane. When the controller is powered on, the firmware looks at the IP address in the midplane and stores this address in the controllers' flash memory. When you replace a controller with a new controller, the new controller will have the same IP address as the replaced controller.

New Critical Events

In adding support for a new critical event that signals the 2730 shutting down due to temperature problems, a new critical event type has been defined. The previous event types were informational, warning, and error. Because of this change, SNMP traps are now mapped to corresponding categories of informational, minor, major, and critical. "Error" events are mapped to "major" severity traps. Informational and minor traps are unchanged.

RAID 6 Support

An additional level of RAID is now supported. RAID 6 is the most fault tolerant of the RAID levels. A virtual disk needs a minimum of four disk drives to support RAID 6. If either one or two of the disk drives fail, the virtual disk can be reconstructed without data loss.

Independent Cache Mode

Independent cache mode provides improved performance for sequential writes in applications such as video streaming.

Point-to-Point Topology

In addition to loop topology, point-to-point topology is now supported. Point-to-point topology simplifies configuration for redundant host paths, and is supported for switch attach configurations only.

SMI-S v.1.1

Storage Management Initiative Specification (SMI-S) v. 1.1 – added support for LUN provisioning.

AssuredCopy

In addition to taking a snapshot of the data, volume copies are now supported.

PHY Status

Diagnostic information relating to SAS expander controller physical channels (PHY lanes) has been enhanced to include additional status information. Also, the fault isolation algorithm can now be enabled or disabled.

Scheduler

You can use the Scheduler feature to create tasks and define schedules at which the system will automatically perform those tasks. Using the Scheduler, you can create tasks to take a snapshot, reset a snapshot, or copy a volume. The schedule can be set to run repeatedly, for example, the first Monday of every month.

What's Changed in This Release

Changes in Firmware Update Procedures

This release incorporates changes to the update procedure from previous software versions. Refer to “Updating RAID Controller Software” on page 10 for the new instructions.

Volume Names

The number of characters in the volume name has been reduced from 20 to 17. If a volume name has more than 17 characters in a previous version of the firmware, the volume name will be truncated in J200. If you have volume names that are not unique in the first 17 characters, rename the volumes before upgrading to J200. Once J200 is loaded, when the controllers look at the volumes, you will get a “Duplicate Volume Names” error.

Parity Error Discovery

The storage system logs all parity and media errors it finds, but no longer attempts to correct those errors.

License Management

Virtual Disk Service (VDS) and Volume Shadow Copy Service (VSS) hardware providers are now enabled through a license certificate file.

Solaris MPxIO Volume Naming Structure

The Solaris MPxIO volume naming structure has changed in this release from the structure used in release J11x.

- J11x example: c1t600C0FF0000A491B36F061450A000000
- J200 example: c1t600C0FF0000A491BA43EB84601000000d0

Updating RAID Controller Software

It is important that you install and configure your J200R05 software package file carefully, following the instructions in this section.



Caution – Upgrading firmware from J110 or J111 to J200 is disruptive and must be performed off-line, with all host I/O stopped. Completing the upgrade requires a maintenance window of up to an hour.



Caution – This upgrade procedure can be used to upgrade from J110 to J200. If you have firmware older than J110, you must first upgrade to J110 before upgrading to J200.

Note – The terms software and firmware are used interchangeably in this document.

Recording IP Addresses



Caution – Upgrading firmware from J110 or J111 to J200 may reset the IP addresses for the controllers' Ethernet management ports.

Before you begin the upgrade procedure, record your network parameters.

1. Log in to RAIDar on controller A as a Manage user with the correct password.
2. Select Manage > General Config > LAN Configuration.
3. Record the following values for each controller:
 - Source for IP address
 - IP address
 - IP subnet mask
 - Gateway IP address

4. If the IP address source is DHCP, change it to Manual to preserve the current IP values.
 - a. Set Source For IP Address to Manual.
 - b. Click Change LAN Configuration.

When processing is complete, a message near the top of the page informs you that your change was successful.

Retrieving Firmware from the Customer Resource Center

1. Download the firmware from Dot Hill's Customer Resource Center at <http://crc.dothill.com>.
 - a. Using the menu on the left side of the web page, select R/Evolution Products > R/Evolution 2730 > J200 Documents & Firmware.

A list of articles describing available documents and downloadable firmware is displayed.
 - b. Click R/Evolution 2730 J200 Firmware.
 - c. Follow the instructions to download the `neptunesw-J200R05-01.zip` file.
2. Extract the `neptunesw-J200R05-01.bin` and `O200B28.bin` from the zip file to a location that your management host can access, such as `C:\` for Microsoft Windows or `/tmp` for UNIX operating systems.

Updating the Controllers Using RAIDar



Caution – Do not attempt to upgrade both controllers at the same time. It is not supported and will result in unpredictable failures and may yield unpredictable results.

Note – Enable pop-ups on your browser for each controller. The upgrade process will produce a pop-up window to show you the progress of downloading the code.

1. Stop all host I/O.
2. Log in to RAIDar on controller A as a Manage user with the correct password.
3. Disable the Partner Firmware Upgrade (PFU) feature.
 - a. Select Manage > General Config > System Configuration.
 - b. Set Partner Firmware Upgrade to Disabled.
 - c. Click Change System Configuration.

When processing is complete, a message near the top of the page informs you that your change was successful.
4. Select Manage > Update Software > Controller Software.
5. Click Browse and locate `neptunesw-J200R05-01.bin`.
6. Click Load Software Package File.

When processing is complete, the page shows the version of each software component that will be installed.
7. Click on Proceed With Code Update.

The update may take up to 10 minutes to complete.

To see the progress of the code load, refresh your browser frequently.

When you see the message “Storage Controller and Management Controller will reboot in 60 seconds,” the code load has completed. However, the controllers will not reboot.

Note – When the update is complete, controller B will kill controller A. This is normal. The firmware versions between the two controllers are not compatible.


8. Log in to RAIDar on controller B as a Manage user with the correct password.
The message area warns you that a code load is in progress. In this case, you can ignore the warning.
9. Select Manage > Update Software > Controller Software
10. Click Browse and locate `neptunesw-J200R05-01.bin`.
11. Click Load Software Package File
When processing is complete, the page shows the version of each software component that will be installed.
12. Click Proceed With Code Update.
The update may take up to 10 minutes to complete. When the process is complete, a message tells you that you have been logged out because you have just loaded new code.
13. Power off both controllers.
14. After 20 seconds, power on both controllers.
15. After two minutes, log in to RAIDar on controller A as a Manage user with the correct password.
 - If the login page is not found, continue with “Resetting the IP Addresses”.
 - If the login page is displayed, continue with “Completing the Upgrade” on page 16.

Resetting the IP Addresses

If you cannot remotely access the controller IP addresses, they might have changed. Unless you know what the IP addresses are, you will not be able to log in remotely.

The command-line interface (CLI) embedded in each controller module enables you to access the system using RS-232 communication and terminal emulation software. Use the CLI commands described in the steps below to set the IP address for the Ethernet management port on each controller module.

1. Refer to the list of network parameters that you recorded in Step 3 of “Recording IP Addresses” on page 10. You need the IP address, subnet mask, and gateway IP address for controller A and controller B.
2. Use the provided micro-DB9 serial cable to connect the management host to the CLI port on controller A.



Your installation package contents included a micro-DB9-to-DB9 serial cable. If necessary, use a DB9-to-DB25 adapter (not included) for connecting the serial cable to a DB25 serial port on the host computer.

3. Start and configure a terminal emulator, such as HyperTerminal or VT-100, using the display settings in Table 1 and the connection settings in Table 2.

Table 1 Terminal Emulator Display Settings

Parameter	Value
Terminal Emulation Mode	VT-100 or ANSI (for color support)
Font	Terminal
Translations	None
Columns	80

Table 2 Terminal Emulator Connection Settings

Parameter	Value
Connector	COM1 (typically)
Baud rate (bits/sec)	115,200
Data bits	8
Parity	None
Stop bits	1
Flow control	None

4. In the terminal emulator, connect to controller A.
5. Press Enter to display the CLI prompt (#).
6. At the prompt, type the following command to list the current settings:

```
show network-parameters
```

7. At the prompt, type the following command to set the values you recorded for each Ethernet management port, first for controller A and then for controller B:

```
set network-parameters ip address netmask netmask gateway gateway  
controller a|b
```

where:

- *address* is the IP address of the controller
- *netmask* is the subnet mask
- *gateway* is the IP address of the subnet router
- a|b specifies the controller whose network parameters you are setting

For example:

```
# set network-parameters ip 192.168.0.10 netmask 255.255.255.0  
gateway 192.168.0.1 controller a  
  
# set network-parameters ip 192.168.0.11 netmask 255.255.255.0  
gateway 192.168.0.1 controller b
```

8. Type the following command to verify the new IP addresses:

```
show network-parameters
```

9. In the host computer's command window, type the following command to verify Ethernet connectivity, first for controller A and then for controller B:

```
ping IP-address
```

10. If you are not able to ping the controller, you need to restart the Management Controllers.

a. Type the following command:

```
restart mc both
```

b. Confirm by typing Y.

c. Enter the ping command again.

11. Exit the emulator and disconnect from the CLI.

12. Log in to RAIDar on controller A as a Manage user with the correct password. The login page is displayed. Continue with “Completing the Upgrade”.

Completing the Upgrade

1. Select Monitor > Advanced Settings > Controller Versions and verify that all software components have been upgraded on both controllers.
2. Select Manage > General Config > LAN Configuration and verify that the LAN information has not changed.
3. If you were using DHCP prior to the upgrade, reset Source For IP Address to DHCP.
4. Enable the Partner Firmware Upgrade (PFU) feature.
 - a. Select Manage > General Config > System Configuration.
 - b. Set Partner Firmware Upgrade to Enable.
 - c. Click Change System Configuration.

When processing is complete, a message near the top of the page informs you that your change was successful.
5. Resume host I/O.

Updating Expansion Enclosure Firmware

If your RAID controllers are connected to expansion enclosures, after you have upgraded the firmware for the RAID controllers as shown in the previous instructions, update the expansion enclosure firmware for each connected expansion controller. You must update the firmware on each expansion enclosure individually. The upgrade process can take several minutes to complete.

Updating the Expansion Enclosure Using RAIDar

1. Stop host I/O if it is using virtual disks that are used by any of the drives in the expansion enclosure(s).
2. Using a browser, log in to RAIDar on controller A as a Manage user with the correct password.
3. Select Manage > Update Software > Enclosure Firmware > Update Firmware.
4. Select the type of enclosure to update.
5. Click Select Type And Continue.
6. Select the enclosure controller to update and click Continue.
7. Use Browse to select the file containing the `O200B28.bin` expansion enclosure firmware file that you extracted from the downloaded `neptunesw-J200R05-01.zip` file.
8. Click Load Device Firmware File.
The current version of expansion enclosure firmware and the version in the software package are displayed.
9. Click Start Firmware Update.
A page shows the update progress of each enclosure and indicates when the firmware update has completed successfully.
10. Confirm that all firmware versions are now up to date on the expansion enclosures by selecting Manage > Update Software > Enclosure Firmware > Show Enclosures.
11. Resume host I/O.

Note – Though the panel title that shows the version information is entitled “Displaying All Enclosure Processors,” it is actually only displaying information about all expansion enclosure processors. Version information about RAID controller enclosure processors is displayed when you select Manage > Update Software > Controller Software.

Related Documentation

These release notes supplement the documents shown below.

Table 3 R/Evolution Storage System Documentation

Application	Title	Part Number
Site planning information	<i>R/Evolution Storage System Site Planning Guide</i>	83-00004283
Installing and configuring hardware	<i>R/Evolution 2730 Getting Started Guide</i>	83-00004284
Configuring and managing storage	<i>R/Evolution 2000 Series Administrator's Guide</i>	83-00004289
Using the command-line interface (CLI)	<i>R/Evolution 2000 Series CLI Reference Manual</i>	83-00004288
Troubleshooting	<i>R/Evolution 2000 Series Troubleshooting Guide</i>	83-00004287
Recommendations for maximizing reliability, accessibility, and serviceability	<i>R/Evolution 2000 Series Best Practices Guide</i>	83-00004286

Supported Systems

The R/Evolution storage system has been verified as compatible with the software and hardware identified in the following subsections.

Supported Operating Systems

Operating systems supported in this release are shown below.

Table 4 Supported Operating Systems

Operating System	Versions or Required Patches
Windows 2003 Standard Edition	With Service Pack 1 or R2
Windows 2003 Enterprise Edition	With Service Pack 1 or R2
RedHat 4.0 Enterprise Linux AS	With update 1, 2, 3, or 4
RedHat 4.0 Enterprise Linux ES	With update 1, 2, 3, or 4
SUSE Linux Enterprise Server 9	With Service Pack 1, 2, or 3
Solaris 9	With patches 111847-08, 113046-01, 113049-01, 11309-13, 113040-11, 113041-11, 113042-14, 113043-12, 113044-05, 114476-07, 114477-03, 114478-07, 114878-10, 119914-08
Solaris 10	With patches 119130-31, 120222-14, 119470-10, 118833-24

Supported Disk Drive Configurations

Disk drive configurations supported in this release are shown below.

Table 5 Supported Disk Drive Configurations

Model	Number of Drives	Drive Type	Mixed Drive Types
Controller enclosure	12	SAS or SATA	Yes
Controller enclosure and up to four expansion enclosures	56 active slots with four inactive slots in fourth expansion enclosure	SAS or SATA	Yes

Supported Disk Drives

Disk drives supported in this release are shown below.

Table 6 Supported Disk Drives

Supplier	Model	Type	Capacity	RPM
Fujitsu	MAX3147RC	SAS	146GB	15K
Fujitsu	MAX3073RC	SAS	73GB	15K
Seagate	ST3146854SS	SAS	146GB	15K
Seagate	ST373454SS	SAS	73GB	15K
Seagate	ST3300655SS	SAS	300GB	15K
Seagate	ST3146855SS	SAS	146GB	15K
Seagate	ST373455SS	SAS	73GB	15K
Hitachi	HDS725050KLA360	SATA	500GB	7K
Hitachi	HDT722525DLA380	SATA	250GB	7K
Hitachi	HDT25025VLA380	SATA	250GB	7K
Seagate	ST3500641NS	SATA	500GB	7K
Seagate	ST3250824NS	SATA	250GB	7K
Seagate	ST3750640NS	SATA	750GB	7K
Seagate	ST3500630NS	SATA	500GB	7K
Seagate	ST3250620NS	SATA	250GB	7K
Maxtor	8J300S0	SAS	300GB	10K

Supported Fibre Channel Switches

Fibre Channel switches supported in this release are shown below.

Table 7 Supported Fibre Channel Switches

Switch	Firmware Version
Brocade Switches	
Brocade 3250	5.3.0
Brocade 3850	5.3.0
Brocade 3900	5.3.0
Brocade 4100	5.3.0
Brocade 4900	5.3.0
Brocade 200E	5.3.0
QLogic Switches	
SANbox 2-8	6.7.0.04
SANbox 2-16	6.7.0.04
SANbox 5200	6.7.0.04
SANbox 5600	6.7.0.04
McData Switches	
Sphereon 4400	9.03.01
Sphereon 4700	9.03.01

Supported HBAs and Operating Systems

The following tables list supported Fibre Channel HBAs by operating system.

Microsoft Windows 2003 Operating System HBA Support

Fibre Channel HBAs you can use with Microsoft Windows 2003 are shown below.

Table 8 Microsoft Windows 2003-Supported HBAs

HBA	Driver
Emulex LP1050	1.30a9 Storport or later
Emulex LP10000	1.30a9 Storport or later
Emulex LP 11002	1.30a9 Storport or later
Emulex LP 101	1.30a9 Storport or later
Emulex LPe11002	1.30a9 Storport or later
Qlogic QLA2340	9.1.4.15 Storport or later
Qlogic QLA2342	9.1.4.15 Storport or later
Qlogic QLA2462	9.1.4.15 Storport or later
Qlogic QLE2462	9.1.4.15 Storport or later

Using the Microsoft Storport Driver

To use the Storport driver, you must first either install Windows Server 2003 Service Pack 2, or download the hotfix. Information on downloading the hotfix is available at:

<http://support.microsoft.com/kb/932755/en-us>

As of July 20, 2006, the latest Windows 2003 hotfix is 932755. The executable name is `WindowsServer2003-KB932755-x86-ENU.exe` for 32-bit. There is also a 64-bit version `x64`, and an Itanium Processor version `ia64`. This Windows 2003 hotfix brings the `storport.sys` driver to 5.2.3790.2880.

Solaris 10 Operating System HBA Support

Fibre Channel HBAs you can use with Solaris 10 are shown below.

Table 9 Solaris 10-Supported HBAs

HBA	Driver
Emulex LP 11002	Solaris 10 Update 1 or later includes the needed driver
Qlogic QLA2462	Solaris 10 Update 1 or later includes the needed driver

The Solaris 10 operating system includes `fc` and `fcpl` drivers, which each have a timeout setting. The default for `fcpl_offline_delay` is 20 seconds. To avoid certain filesystem warning messages when a cable is removed or a controller is killed or shut down, you can change the timeout setting to 60 seconds by changing this line on Solaris 9 hosts in `/kernel/drv/fcp.conf`:

```
fcpl_offline_delay=60;
```

Note – One reboot of the host is necessary for this parameter to take effect.

In addition, Sun Microsystems has provided a patch for both x86 and SPARC platform editions of the Solaris 10 operating system that fixes the `fcpl_offline_delay` parameter issue. These patches are required with Solaris 10 Update 1 or Solaris 10 Update 2:

- Solaris 10 SPARC Platform Edition: 119130-32
- Solaris 10 x86 Platform Edition: 119131-32

Note – Solaris 10 Update 3 includes the `fcpl_offline_delay` parameter fix and does not require the patch.

Fibre Channel HBAs you can use with Solaris 9 are shown below.

Table 10 Solaris 9-Supported HBAs

HBA	Driver
Emulex LP 11002	Sun SAN Foundation Suite 4.4.12 or later includes the needed driver
Qlogic QLA2462	Sun SAN Foundation Suite 4.4.12 or later includes the needed driver

The Solaris SAN Foundation Kit includes `fp` and `fc` drivers, which each have a timeout setting. The default for `fc_offline_delay` is 20 seconds. To avoid certain filesystem warning messages when a cable is removed or a controller is killed or shut down, you can change the timeout setting to 60 seconds by changing this line on Solaris 9 hosts in `/kernel/drv/fcp.conf`:

```
fc_offline_delay=60;
```

Note – One reboot of the host is necessary for this parameter to take effect.

Red Hat Enterprise Linux HBA Support

Fibre Channel HBAs you can use with Red Hat Enterprise Linux 4.0 are shown below.

Table 11 RedHat 4.0-Supported HBAs

HBA	Driver
Emulex LP 11002	8.0.16.32 or later
Emulex LPe11002	8.0.16.32 or later
Qlogic QLA2462	8.01.07 or later
Qlogic QLE2462	8.01.07 or later

SUSE Linux HBA Support

Fibre Channel HBAs you can use with SUSE Linux 9.0 are shown below.

Table 12 SUSE 9.0-Supported HBAs

HBA	Driver
Emulex LP 11002	8.0.16.32 or later
Emulex LPe11002	8.0.16.32 or later
Qlogic QLA2462	8.01.07
Qlogic QLE2462	8.01.07

Recommended Settings for QLogic HBAs

Recommended settings for QLogic HBAs are shown below.

- Topology: Auto
- LinkSpeed: Auto
- ExecutionSpeed: Divide 64 by the number of initiators
- LinkDownTimeout: 60
- PortDownRetryCount: 60
- PortDownRetryDelay (Solaris only): 12

Recommended Settings for Emulex HBAs

To ensure reliability with all configurations, set the following values:

- NodeTimeOut = 60

When an Emulex HBA is connected directly to a R/Evolution storage system, set the following Emulex HBA parameters:

- Topology: 0 (Loop only)
- LinkSpeed: 4 Gbit/sec, if a 4-Gbit/sec HBA is used; otherwise, 2-Gbit/sec
- EnableFDMI: Disabled

When an Emulex HBA is connected to a switch, set the following Emulex HBA parameters:

- Topology: Auto
- LinkSpeed: Auto
- EnableFDMI: Disabled

Some other Emulex HBA parameters vary, depending on the host operating system, as shown in Table 13.

Table 13 OS-dependent Emulex HBA Parameters

Parameter	Windows 2003	Solaris 9 and Solaris 10	RedHat Linux	SUSE Linux
LinkTimeOut	60	60	N/A	N/A
QueueDepth	Divide 128 by the number of initiators	Divide 128 by the number of initiators	N/A	N/A

Table 13 OS-dependent Emulex HBA Parameters (Continued)

Parameter	Windows 2003	Solaris 9 and Solaris 10	RedHat Linux	SUSE Linux
QueueTarget	Enabled	N/A	N/A	N/A
Extra I/O Timeout	N/A	0	N/A	N/A
lpfc-scsi-req-tmo	N/A	N/A	60	60

Supported SFPs

Table 14 lists supported RoHS-compliant SFPs for use with a Fibre Channel (FC) controller enclosure.

Table 14 Supported 4-Gbit/sec SFPs

Vendor	Part Number
Avago Tech	AFBR-57R5APZ
Finisar	FTLF8524P2BNV
Intel	TXN31115D100000 TXN31115D200000
JDS	JSH-42S4AA1

Solaris Patches

Make sure the Solaris recommended patch cluster is installed on a Solaris host before connecting to host to the RAID controller enclosure.

Downloading/Installing the Solaris Patch Cluster

1. Log in to the host that you want to connect to the storage system.
2. Go to:
<http://www.sun.com/sunsolve>
3. Under Support Resources, click Patches and Updates.
4. Under Recommended and Security Patches, click Recommended Patch Clusters.
5. Find your version of Solaris 9 or Solaris 10 in the Recommended Solaris patch Clusters list, make sure the Readme checkbox is checked, and then click Go.

6. Print or save the README file from the browser window.
7. Click the browser's Back icon to return to the previous page.
8. Select the format you want in the row that begins Solaris 9, or Solaris 10 in the Recommended Solaris Patch Clusters list, click either Download HTTP or Download FTP, and then click Go.
9. In the File Download dialog box, click Save.
10. In the Save As dialog box, type a destination directory for the patch cluster, and then click OK.
11. Follow the procedure in the Installation Instructions section in the README file to install the patches.

Software and Firmware Configuration

Virtual Disk Size

The J200R05 release is designed to support up to a 32-Tbyte virtual disk. Actual virtual disk size is determined by the drive size and the maximum number of drives in a virtual disk as shown in Table 15.

For example, based on the current maximum drive size of 750 Gbyte, and a maximum number of 30 data disks with 2 parity disk drives, you can build a virtual disk on RAID 50 of 22.5 Tbyte.

Table 15 Maximum Number of Drives in a Virtual Disk

RAID Level	Maximum Drives
NRAID	1
0, 3, 5, 6	16
1	2
10	32
50	32

Snapshot Configuration

The basic snapshot license that comes with the R/Evolution 2730 provides a maximum of 16 snapshots. An optional license can be purchased that expands this capability to a maximum of 64 snapshots. When you purchase this license, you receive a license key along with instructions for installing it. The instructions can be found in a document called *Obtaining and Installing the License Certificate File*, part number 83-00004343. This document is available in the R/Evolution 2000 Series Current Documentation section at <http://crc.dothill.com>.

Table 16 lists maximum snapshot parameters supported by the J200R05 software. Actual supported parameters depend on purchased licenses and the options made available by OEM partners.

Table 16 Snapshot Default and Maximum Values

Snapshot Parameter	Default Value
Snapshots, per system	16 default, 64 with purchase of optional software license
Maximum number of master volumes, per controller	16
Maximum number of snap pools, per controller	16
Warning threshold (snap pool 75% full)	75%
Error threshold (snap pool 90% full)	90%
Critical threshold (snap pool 99% full)	99%
Warning Policy	Notify Only, not settable
Error policy	Delete Oldest
Critical policy	Delete All Snapshots

Note – If you have purchased and installed the optional software license to maximize the number of available snapshots, the license key you install is based on your enclosure’s chassis midplane serial number. If you subsequently replace the enclosure or chassis FRU, your snapshot functionality will revert to the default values. To regain the optional functionality you purchased, you will need to install a new license. When you send in your defective enclosure or chassis FRU with a Returned Merchandise Authorization (RMA), you will receive the information you need to install the new license.

Known Issues

The following sections describe known issues for this release.

Persistent IP Address

Beginning with the J200 release, the IP address is persistent. The IP address is stored on the midplane. When the controller is powered on, the firmware looks at the IP address in the midplane and stores this address in the controllers flash memory. When you replace a controller with a new controller, the new controller will have the same IP address as the old controller.

In previous versions of the firmware, the IP address was only stored in the flash memory of the controller. If it was necessary to replace a controller, you would have to update the IP address of the new controller.

This causes an incompatibility between previous versions of the firmware and the J200 firmware. When you upgrade to J200, the firmware looks at the midplane for the IP address. If there is an IP address, that address is written to the controller's Flash memory. If the location of the IP address on the midplane does not contain a valid IP address, then the IP address in the controller's Flash memory is used. This might cause you to lose connectivity during the upgrade process. As described in "Updating RAID Controller Software" on page 10, you must connect directly to the storage system in order to change the IP address.

Documentation Errata

- In the *CLI Reference Manual* and in CLI help, descriptions of the CLI commands `scrub vdisk` and `verify vdisk` incorrectly state that these commands correct errors that they find. In fact, the number of inconsistencies found is only reported in the "Vdisk verification complete" event (event code 21) in the event log. Such inconsistencies can indicate that a drive in the virtual disk is going bad.
- Similarly, in the *Administrator's Guide*, the topic "Verifying a Virtual Disk" incorrectly states that the Verify utility corrects errors that it finds. In fact, the number of inconsistencies found is only reported in the "Vdisk verification complete" event (event code 21) in the event log. Such inconsistencies can indicate that a drive in the virtual disk is going bad.
- Similarly, in the glossary, the definition of *verify* should state that errors are only reported, not corrected.

Known Bugs

Known bugs in the J200 release are described below:

- **4620: If a controller module is moved into another enclosure, stale licensing is presented in the WBI until a screen refresh is executed.** The CLI is correct.
- **4652: The CLI command `set system name` accepts 80 characters but only 79 are saved.** For example:

```
# set system name
RNUKvp80rLAIOSoQOfG8i3aIoAKIWU905YDDH1YUPkxcSJVxMMdXvFue3CY3iOu7
saQlSqrOn4AuxfVT
Success: Command completed successfully

# show system
System Information
-----
System Name      :
RNUKvp80rLAIOSoQOfG8i3aIoAKIWU905YDDH1YUPkxcSJVxMMdXvFue3CY3iOu7
saQlSqrOn4AuxfV <<----- missing 'T'
...
```

- **4761: The CLI command `set host-port-interconnects enable` had to be performed twice before it took effect on a system with HIM 0 boards installed.** After the first attempt the command returns success but the command never completed.
- **4828: When adding multiple drives as Global Spares using the `set global-spare disks` command, the CLI only displays a success message for the first drive in the list.** For example:

```
# set global-spare disks 4-7
Success: Disk 4 configured as a Global Spare.
```

- **4860:** During online creation of a vdisk with a single volume spanning the entire allowable size of the vdisk, the free-space column (Free) will display a value of “B” when a `show vdisk` command is executed. For example:

```
# show vdisk
Name                Size      Free      Own RAID   Dsk Spr Chk Stat
Jobs              Serial#
-----
RAID6.1             87.9GB   B         B  RAID6    6   0   64 CRIT
INIT 9%  00c0ff0a56710048c318cc4600000000
RAID6.2             87.9GB   B         B  RAID6    6   0   64 CRIT
INIT 8%  00c0ff0a56710048db18cc4600000000
RAID6.3             87.9GB   B         A  RAID6    6   0   64 CRIT
INIT 6%  00c0ff0a562700480d19cc4600000000
ID6.4              65.9GB  34.5GB   A  RAID6    5   0   64 CRIT
INIT 4%  00c0ff0a562700484519cc4600000000
```

- **4892:** The system allows the same nickname for different host WWNs. When using the `set host-wwn-name host` command only the first instance of the nickname will be changed. For example:

```
# show host-wwn-names
Host-ID/WWN        Name
-----
210100E08B370A14  bar
210000E08B170A14  bar
-----

# set host-wwn-name host bar foo
Success: Command completed successfully

# show host-wwn-names
Host-ID/WWN        Name
-----
210000E08B170A14  foo
210100E08B370A14  bar
-----
```

Workaround: Ensure the nickname is unique for each host WWN.

- **5028:** When using the WBI to disable a PHY on expander A, the corresponding PHY on expander B is also disabled, resulting in a failed disk drive.

- **5030: Help for the Verify Virtual Disk page incorrectly says to click the Verify & Update Virtual Disk Parity button, but the button's correct name is Verify Virtual Disk Parity.**
- **5035: Data corruption can occur upon a failover on SPARC Solaris 10 with Emulex HBAs and a Qlogic 5600 switch.** The cause is re-driving write I/Os to a switch port in which the WWNN of the target has changed due to the failover. The GPN_ID responses to the Sun box (after RSCN from the switch) report a new target (WWNN) as does the PLOGI response on re-login. However, the writes that are driven down this port are to the old target which causes corruption on all the LUNs. This occurs if the new target comes back up within the 4 GPN_ID retries that Solaris issues. If all four of these timeout, the host attempts a switch discovery process (GA_NXT sequences) and reroutes the pending I/Os correctly. A bug has been filed with Sun CR 6605700.
- **5040: While running the array at 35C ambient 50% humidity in an environmental chamber, the show enclosure-status command indicates Temp 01 as "Critical" at 51C.** However, the show sensor-status command reports the Upper-Ctrl A Temperature at 51C as a "Warning."
- **5049: show snap-pools will return incorrect data when "base 2" is selected. Workaround:** Ensure base 10 format is used when viewing snapshot information. For example:

```
# set cli-parameters base 10
```

- **5051: When a controller is shut down via the WBI, the Host Port Configuration page does not display the link speed option 4 GBit/Second.** Only the 2 GBit/Second option is displayed.
- **5065: Controllers became unresponsive after the following CLI command was issued while running an automated test script:**

```
# delete master-volume "mastervolume-10"
```

Workaround: Restart the controllers.

- **5088: Volume copy to a master volume which is larger than the snap pool will result in a restart of the system (both controllers).**