

USER'S GUIDE

Vaisala Humidity and Temperature Probe HMP60 and HMP110



PUBLISHED BY

Vaisala Oyj
P.O. Box 26
FI-00421 Helsinki
Finland

Phone (int.): +358 9 8949 1
Fax: +358 9 8949 2227

Visit our Internet pages at www.vaisala.com

© Vaisala 2010

No part of this manual may be reproduced in any form or by any means, electronic or mechanical (including photocopying), nor may its contents be communicated to a third party without prior written permission of the copyright holder.

The contents are subject to change without prior notice.

Please observe that this manual does not create any legally binding obligations for Vaisala towards the customer or end user. All legally binding commitments and agreements are included exclusively in the applicable supply contract or Conditions of Sale.

Table of Contents

CHAPTER 1

GENERAL INFORMATION	7
About This Manual	7
Contents of This Manual	7
Version Information	8
Related Manuals	8
Documentation Conventions	8
Safety	9
ESD Protection	9
Recycling	10
Regulatory Compliances	10
Patent Notice	10
Trademarks	11
License Agreement	11
Warranty	11

CHAPTER 2

PRODUCT OVERVIEW	13
Introduction to HMP60 and HMP110	13
Basic Features and Options	14
Filter Options	15
Installation Accessories (Optional)	16
Probe Mounting Clamp	16
Probe Mounting Flange	16
Loop Power Converter	17
Cables	18

CHAPTER 3

INSTALLATION	19
Dimensions	19
Mounting the Probe	20
Wiring	21
Wiring with the Loop Power Converter	22
Power Supply Requirements	23
Recommendations	23

CHAPTER 4

OPERATION	25
Getting Started	25
Serial Line Communication	25
Connecting to the Serial Interface	25
Installing the Driver for the USB Cable	27
Terminal Application Settings for Probes in RS-485 Mode	28

Terminal Application Settings for Probes in Analog Mode ..	30
List of Serial Commands	31
Device Information and Status	32
View Device Information	32
View Calibration Information	33
View Order Code	33
View Serial Number	33
View Software Version	34
Serial Line Output Commands	34
Start Measurement Output	34
Stop Measurement Output	34
Output the Measurement Message Once	35
Configuring Serial Line Operation	35
Set Serial Line Settings	35
Set Serial Interface Mode	36
Set Output Interval	37
Set Measurement Filtering	37
Set Probe Address	38
Set Serial Interface Delay	38
Set Measurement Units	39
Calibration Commands	39
Calibrate Humidity Measurement	39
Clear Adjustment of RH Measurement	40
Calibrate Temperature Measurement	40
Clear Adjustment of T Measurement	41
View User Adjustment Parameters	41
Other Commands	42
Display Command List	42
Display the Currently Active Errors	42
Connect to the Probe in POLL Mode	42
Close the Connection in POLL Mode	42
Reset the Probe	43
Restore Factory Settings	43

CHAPTER 5

MAINTENANCE	45
Periodic Maintenance	45
Cleaning	45
Changing the Filter	46
Calibration Procedure	46
Adjustment Procedure (HMP110)	47
One-point Adjustment of RH Measurement (HMP110)	47
Two-point Adjustment of RH Measurement (HMP110)	48
One-point Adjustment of T Measurement (HMP110)	50
Repair Maintenance	52
Changing the INTERCAP Sensor (HMP60)	52
Changing the HUMICAP 180R Sensor (HMP110)	53

CHAPTER 6

TROUBLESHOOTING	55
Solving Typical Problems	55
Technical Support	56

CHAPTER 7

TECHNICAL DATA	57
Specifications	57
Performance (HMP60)	57
Relative Humidity	57
Temperature.....	57
Dewpoint	57
Performance (HMP110)	58
Relative Humidity	58
Temperature.....	58
Dewpoint	58
Operating Environment	59
Inputs and Outputs	59
Mechanics	59
Options and Accessories	60

This page intentionally left blank.

List of Figures

Figure 1	HMP60 (left) and HMP110 (right).....	13
Figure 2	Filter Options	15
Figure 3	Probe Mounting Clamp in Use	16
Figure 4	Probe Mounting Flange	16
Figure 5	Loop Power Converter	17
Figure 6	Cable with Threaded Connector	18
Figure 7	USB Serial Interface Cable	18
Figure 8	HMP60 and HMP110 Dimensions	19
Figure 9	Installation with Plastic M12 Nuts, Dimensions.....	19
Figure 10	Wiring of Analog Output	21
Figure 11	Wiring of Digital Output	21
Figure 12	Wiring with the Loop Power Converter Module.....	22
Figure 13	PuTTY Terminal Application	29
Figure 14	Changing the Sensor.....	52

List of Tables

Table 1	Manual Revisions	8
Table 2	Related Manuals	8
Table 3	Quantities Measured by the HMP60 and HMP110	14
Table 4	Filter Properties	15
Table 5	Pinout of the Probe Connector	21
Table 6	Default Serial Communication Settings.....	26
Table 7	List of Serial Commands	31
Table 8	Additional Commands for Probes with RS-485 Output.....	31
Table 9	Troubleshooting Table.....	55
Table 10	HMP60 Options and Accessories	60
Table 11	HMP110 Options and Accessories	60

This page intentionally left blank.

CHAPTER 1

GENERAL INFORMATION

This chapter provides general notes for the manual and the product.

About This Manual

This manual provides information for installing, operating, and maintaining Vaisala Humidity and Temperature Probe HMP60 and HMP110.

Contents of This Manual

This manual consists of the following chapters:

- Chapter 1, General Information, provides general notes for the manual and the product.
- Chapter 2, Product Overview, introduces the product features and options.
- Chapter 3, Installation, provides you with information that is intended to help you install HMP60 and HMP110.
- Chapter 4, Operation, contains information that is needed to operate HMP60 and HMP110.
- Chapter 5, Maintenance, provides information that is needed in basic maintenance of HMP60 and HMP110.
- Chapter 6, Troubleshooting, describes common problems, their probable causes and remedies, and contact information for technical support.
- Chapter 7, Technical Data, provides the technical data of the HMP60 and HMP110.

Version Information

Table 1 **Manual Revisions**

Manual Code	Description
M211060EN-A	March 2010. This manual. First version.

Related Manuals

Table 2 **Related Manuals**

Manual Code	Manual Name
M211059EN	HMP60 and HMP110 Quick Guide
M211106EN	Loop Power Converter Quick Reference guide

Documentation Conventions

Throughout the manual, important safety considerations are highlighted as follows:

WARNING

Warning alerts you to a serious hazard. If you do not read and follow instructions very carefully at this point, there is a risk of injury or even death.

CAUTION

Caution warns you of a potential hazard. If you do not read and follow instructions carefully at this point, the product could be damaged or important data could be lost.

NOTE

Note highlights important information on using the product.

Safety

The product delivered to you has been tested for safety and approved as shipped from the factory. Note the following precautions:

WARNING	Ground the product, and verify outdoor installation grounding periodically to minimize shock hazard.
----------------	--

CAUTION	Do not modify the unit. Improper modification can damage the product or lead to malfunction.
----------------	--

ESD Protection

Electrostatic Discharge (ESD) can cause immediate or latent damage to electronic circuits. Vaisala products are adequately protected against ESD for their intended use. It is possible to damage the product, however, by delivering electrostatic discharges when touching, removing, or inserting any objects inside the equipment housing.

To make sure you are not delivering high static voltages yourself:

- Handle ESD sensitive components on a properly grounded and protected ESD workbench.
- When an ESD workbench is not available, ground yourself to the equipment chassis with a wrist strap and a resistive connection cord.
- If you are unable to take either of the above precautions, touch a conductive part of the equipment chassis with your other hand before touching ESD sensitive components.
- Always hold component boards by the edges and avoid touching the component contacts.

Recycling



Recycle all applicable material.



Dispose of batteries and the unit according to statutory regulations. Do not dispose of with regular household refuse.

Regulatory Compliances

The HMP60 and HMP110 are in conformity with the provisions of the following EU directive(s):

ROHS Directive (2002/95/EEC)

WEEE Directive (2002/96/EEC)

EMC Directive (2004/108/EC)

The electromagnetic compatibility of the HMP60 and HMP110 has been tested according to the following product family standards:

EN 61326-1:2006 Electrical equipment for measurement, control and laboratory use - EMC requirements - Basic immunity test requirements.

EN 55022:2006 + Am 1:2007 Information technology equipment - Radio disturbance characteristics - Limits and methods of measurement.
Class B.



Patent Notice

The HMP60 and HMP110 are protected by the following patents and patent applications and their corresponding national rights:

Finnish patent 98861, French patent 6650303, German patent 69418174, Japanese patent 3585973, UK patent 0665303, U.S. patent 5607564.

Trademarks

Vaisala INTERCAP® and Vaisala HUMICAP® are registered trademarks of Vaisala Oyj.

Windows® is a registered trademark of Microsoft Corporation in the United States and/or other countries.

License Agreement

All rights to any software are held by Vaisala or third parties. The customer is allowed to use the software only to the extent that is provided by the applicable supply contract or Software License Agreement.

Warranty

For certain products Vaisala normally gives a limited one-year warranty. Visit our Internet pages for more information and our standard warranty terms and conditions: www.vaisala.com/services/warranty.html.

Please observe that any such warranty may not be valid in case of damage due to normal wear and tear, exceptional operating conditions, negligent handling or installation, or unauthorized modifications. Please see the applicable supply contract or Conditions of Sale for details of the warranty for each product.

This page intentionally left blank.

CHAPTER 2

PRODUCT OVERVIEW

This chapter introduces the product features and options.

Introduction to HMP60 and HMP110

Vaisala Humidity and Temperature Probes HMP60 and HMP110 are simple and cost-effective humidity transmitters suitable for volume applications, integration into other manufacturers' equipment, incubators, glove boxes, greenhouses, fermentation chambers, and data loggers.

HMP60 uses the interchangeable Vaisala INTERCAP® sensor. No recalibration is required after sensor replacement.

HMP110 uses the Vaisala HUMICAP 180R® sensor for increased accuracy. The HMP110 requires calibration after sensor replacement. This can be done on the serial line using the optional Vaisala USB cable.



0912-101

Figure 1 HMP60 (left) and HMP110 (right)

Table 3 Quantities Measured by the HMP60 and HMP110

Quantity	Abbreviation	Metric Unit	Non Metric Unit
Relative humidity	RH	%RH	%RH
Dewpoint/Frostpoint temperature*	T _{d/f}	°C	°F
Temperature	T	°C	°F

* When the dewpoint is below 0 °C, the probe outputs frostpoint for T_d

Basic Features and Options

- Analog output mode: two analog output channels, selectable from 0 ... 1 V / 0 ... 2.5 V / 0 ... 5 V / 1 ... 5 V
- RS-485 output mode
- Small size
- Low power consumption
- IP65 aluminum body
- Options and accessories:
 - Filter options: plastic grid filter, membrane filter, and stainless steel sintered filter
 - One channel loop power converter 4 ... 20 mA (separate module, compatible with humidity accuracy only)
 - Shielded 0.3 m and 3.0 m connection cables with threaded connector for probe connection, open end wires on the other end
 - Plastic M12 installation nuts

Filter Options

The available filters for HMP60 and HMP110 are shown in Figure 2 below. For order codes, see section Options and Accessories on page 60.



Figure 2 **Filter Options**

Table 4 **Filter Properties**

No.	Filter	Diameter	Pore Size
1	Plastic grid filter (fastest response time)	12 mm	-
2	Membrane filter	12 mm	0.2 µm
3	Stainless steel sintered filter	12 mm	38 µm

Installation Accessories (Optional)

Probe Mounting Clamp

The optional mounting clamp makes it easy to install the probe on the wall of the measurement environment. The probe can be detached for calibration simply by loosening the lower screw.



1001-138

Figure 3 **Probe Mounting Clamp in Use**

Probe Mounting Flange

The probe mounting flange is a silicone flange can be used to hold the probe in a through-wall installation. The flange is a general purpose mounting accessory for Ø 12mm probes, and comes with a sealing plug for coaxial cables that is not needed when the flange is used with HMP60 and HMP110.



0911-109

Figure 4 **Probe Mounting Flange**

Loop Power Converter

The loop power converter is an open frame module that converts one 0 ... 2.5 VDC voltage output to a 4 ... 20 mA current output. To use the loop power converter module, the probe:

- must be in the analog output mode
- the desired quantity must be on channel 1
- channel 1 must be scaled to 0 ... 2.5 V

Wiring instructions are provided in section Wiring with the Loop Power Converter on page 22.



1001-001

Figure 5 **Loop Power Converter**

Cables

The probe cables have a standard M8 connector. Also other compatible M8 series cables can be used.



0910-135

Figure 6 Cable with Threaded Connector

The USB Serial Interface Cable uses a snap-on connector. The USB cable is intended for maintenance purposes only, not permanent installation.



0809-002


Figure 7 USB Serial Interface Cable

CHAPTER 3

INSTALLATION


This chapter provides you with information that is intended to help you install HMP60 and HMP110.

Dimensions



0912-103

Figure 8 HMP60 and HMP110 Dimensions



0912-102

Figure 9 Installation with Plastic M12 Nuts, Dimensions

Mounting the Probe

The HMP60 and HMP110 are designed to be mounted from the M12 thread on the probe body, or from the smooth part of the probe body. For a convenient installation, use the optional installation accessories:

- Use the plastic mounting nuts to hold the probe in a through-wall installation
- Use the probe mounting clamp to hold the probe on a wall

NOTE

Avoid placing the probe in a place where condensation can run onto the sensor.

Wiring

For secure connection to the probe, connect to the 4-pin M8 connector using a threaded connector.

Connect the shield if using a shielded cable. In the shielded cables supplied by Vaisala, the threaded connector connects the shield to the probe housing.




Figure 10 Wiring of Analog Output




Figure 11 Wiring of Digital Output

Table 5 Pinout of the Probe Connector

Pin	Analog output model	RS-485 output model	Wire color
1	VDC supply +	VDC supply +	Brown
2	Signal Channel 1	RS-485 - / B	White
3	GND	GND	Blue
4	Signal Channel 2	RS-485 + / A	Black


Wiring with the Loop Power Converter

To use the loop power converter module with HMP60 or HMP110, make sure that:

- The probe is in the analog output mode
- The desired quantity must be on channel 1
- Channel 1 is scaled to 0 ... 2.5 V

When using the loop power converter module, power the module with 8 ... 28 VDC. The operating voltage for the probe (5 VDC) is delivered by the module.

For more information, see the Loop Power Converter Quick Reference Guide.



0912-105

Figure 12 Wiring with the Loop Power Converter Module

Power Supply Requirements

The operating voltage for the HMP60 and HMP110 probes must be in the following range:

- 5 ... 28 VDC when using the 0 ... 1 V, 0 ... 2.5 V or RS-485 output
- 8 ... 28 VDC when using the 0 ... 5 V or 1 ... 5 V output

Current consumption is 1 mA on average, which makes the probes well suited for running on battery power. The maximum peak consumption is 5 mA.

Recommendations

- Continuous use over high operating voltage may cause heating. To conserve power and minimize the warming of the probe, use the lowest operating voltage in the allowed range.
- Using low impedance loads on the signal outputs increase the current consumption by up to 0.5 mA. High impedance loads are recommended to minimize warming of the probe.
- Frequent interrogation of the probe using the RS485 interface will also increase current consumption from the average value. More frequent interrogation than once per second is not recommended.

This page intentionally left blank.

CHAPTER 4

OPERATION

This chapter contains information that is needed to operate HMP60 and HMP110.

Getting Started

When the probe has been connected to a power supply, there is a short start-up delay before the measurement data is available through the selected output(s) - analog or RS-485. The delay depends on the operating voltage that is supplied to the probe:

- Operating voltage 5 ... 14 V: one second start-up delay
- Operating voltage 14 ... 28 V: four second start-up delay

Serial Line Communication

HMP60 and HMP110 support two-wire RS-485 communication. The RS-485 interface is non-isolated and offers a maximum communications rate of 57600 bits/s.

There is no internal termination for the RS-485 on the probe. Use of termination resistors is not recommended. If the resistors are used, the possible increase in current consumption should be taken into account.

Connecting to the Serial Interface

The connection to the serial interface is via the 4-pin connector on the probe; see connector pinout on page 20.

For temporary use of the serial interface (for example, calibration), you can use the optional USB cable (Vaisala order code: 219690). Before you can use the USB cable, you must install the provided USB driver on your PC, see Installing the Driver for the USB Cable on page 26.

NOTE

The Vaisala USB cable is not designed for permanent installation. When using the USB cable, no separate power unit is needed. The probe is powered through the USB port.

For permanent interfacing to a host system, use a shielded cable with a threaded connector. See list of available cables in section Options and Accessories on page 60.

You can change the serial settings and operate in RUN, STOP and POLL modes. The probe does not echo typed characters back to the terminal screen. To see the commands you type, you need to enable the "local echo" -setting in your terminal program.

A new command cannot be received while the probe is sending data out. Wait until the instrument has completed its response before entering the next command.

Table 6 Default Serial Communication Settings

Parameter	Value
Bauds	19200
Parity	None
Data bits	8
Stop bits	1
Flow control	None

After power-up the probe (in STOP-mode) outputs the software version and the command prompt.

In RUN mode a measurement output starts immediately after power-up.

In POLL mode, the probe does not output anything after power-up, see section Set Serial Line Settings on page 35.

Installing the Driver for the USB Cable

Before taking the USB cable into use, you must install the provided USB driver on your PC. When installing the driver, you must acknowledge any security prompts that may appear. The driver is compatible with Windows 2000, Windows XP, and Windows Vista.

1. Check that the USB cable is not connected. Disconnect the cable if you have already connected it.
2. Insert the media that came with the cable, or download the driver from www.vaisala.com.
3. Execute the USB driver installation program (setup.exe), and accept the installation defaults. The installation of the driver may take several minutes.
4. After the driver has been installed, connect the USB cable to a USB port on your PC. Windows will detect the new device, and use the driver automatically.
5. The installation has reserved a COM port for the cable. Verify the port number, and the status of the cable, using the **Vaisala USB Instrument Finder** program that has been installed in the Windows Start menu. The reserved ports are also visible in the **Ports** section of the Windows Device Manager.

Remember to use the correct port in the settings of your terminal program. Windows will recognize each individual cable as a different device, and reserve a new COM port.

There is no reason to uninstall the driver for normal use. However, if you wish to remove the driver files and all Vaisala USB cable devices, you can do so by uninstalling the entry for **Vaisala USB Instrument Driver** from the **Add or Remove Programs (Programs and Features)** in Windows Vista) in the Windows Control Panel.

Terminal Application Settings for Probes in RS-485 Mode

The steps below describe how to connect to the HMP60 and HMP110 using the PuTTY terminal application for Windows (available for download at www.vaisala.com) and the USB serial interface. The instructions assume that your probe has been ordered with the RS-485 output.

If your probe has been ordered without the RS-485 output, you can still connect to the serial line by following the instructions in section Terminal Application Settings for Probes in Analog Mode on page 30.


1. Connect the USB serial interface cable between your PC and the probe.
2. Start the PuTTY application.
3. Select the **Serial** settings category, and check that the correct COM port is selected in the **Serial line to connect to** field.

You can check which port the USB cable is using with the **Vaisala USB Instrument Finder** program that has been installed in the Windows Start menu.

4. Check that the other serial settings are correct for your connection, and change if necessary. Refer to Table 6 on page 26 for the default serial line settings of the probe.
5. Click the **Open** button to open the connection window and start using the serial line.

If PuTTY is unable to open the serial port you selected, it will show you an error message instead. If this happens, restart PuTTY and check the settings.

6. You may need to adjust the **Local echo** setting in the **Terminal** category to see what you are typing on the serial line. To access the configuration screen while a session is running, click the right mouse button over the session window, and select **Change Settings...** from the pop-up menu.



0810-070

Figure 13 PuTTY Terminal Application

Terminal Application Settings for Probes in Analog Mode

Follow the steps below to connect to the serial line on probes that have been ordered with analog outputs. You must use the Vaisala USB cable in this case.

1. Start the PuTTY application.
2. Connect the USB serial interface cable to your PC. Do not connect the other end to the probe yet.
3. Select the **Serial** settings category, and check that the correct COM port is selected in the **Serial line to connect to** field.

You can check which port the USB cable is using with the **Vaisala USB Instrument Finder** program that has been installed in the Windows Start menu.

4. Check that the other serial settings are set to the default settings of the HMP60 and HMP110. Refer to Table 6 on page 26.
5. Click the **Open** button to open the connection window and start using the serial line.
6. Connect the other end of the USB cable to the probe, and immediately press the **Enter** key a few times. This will cause the probe to start in RS-485 mode, using the default serial settings.

List of Serial Commands

All commands can be issued either in uppercase or lowercase. In the command examples, the keyboard input by the user is in **bold** type.

The notation <cr> refers to pressing the carriage return (**Enter**) key on your computer keyboard. Enter a <cr> to clear the command buffer before starting to enter commands.

Table 7 List of Serial Commands

Command	Description
?	Output information about the device
ADJD	View the adjustment date
CDATE	View the calibration date
CODE	View the order code of the probe
CRH	Calibrate and adjust RH measurement
CRHCLR	Clear adjustment of RH measurement
CT	Calibrate and adjust T measurement
CTCLR	Clear adjustment of T measurement
CTEXT	View the calibration information field
ERRS	List present probe errors
FILT [0.001 ... 1]	Set the result filtering
FRESTORE	Restore factory settings
HELP	List available commands
INTV [0 ... 255 S/MIN/H]	Set the continuous output interval (for RUN mode)
L	Displays user adjustment parameters
R	Start the continuous outputting
RESET	Reset the probe
S	Stop the continuous outputting
SDELAY[0 ... 255]	View or set serial line answer minimum delay
SEND [0 ... 99]	Output the reading once
SNUM	View the serial number of the probe
UNIT	Select metric or non-metric output units
VERS	View software version of the probe

Table 8 Additional Commands for Probes with RS-485 Output

Command	Description
??	Output information about the device in POLL mode
ADDR [0 ... 99]	Set the probe address (for POLL mode)
CLOSE	Close the temporary connection (Back to POLL mode)
OPEN [0 ... 99]	Open a temporary connection to a POLL mode device
SERI [baud p d s]	User Port settings (Default: 19200 N 8 1) baud: 300 ... 57600
SMODE [STOP/RUN/POLL]	Set the serial interface mode

Device Information and Status

View Device Information

The **?** command outputs a listing of device information.

?<cr>

Example:

```
?
HMP60 / 1.00.0
Serial number : E3950006
Batch number  : E3950006
Sensor number  : A0000000
Sensor model   : Intercap
Order code     :
Cal. date      : 20091201
Cal. info      : NONE
Time           : 00:00:24
Serial mode    : STOP
Baud P D S     : 19200 N 8 1
Output interval: 5 S
Serial delay   : 50
Analog delay   : 30 S
Address        : 0
Filter         : 1.000
Ch1 output     : 0 ... 5 V
Ch2 output     : 0 ... 5 V
Ch1 RH lo      : 0.00 %RH
Ch1 RH hi      : 100.00 %RH
Ch2 T lo       : -40.00 'C
Ch2 T hi       : 60.00 'C
```

If the probe is in poll mode, but a connection has not been opened using the **OPEN** command, issue the **??** command. For a description of the serial interface modes, see section Set Serial Line Settings on page 35.

??<cr>

View Calibration Information

Use the **CDATE** command to view the calibration date, **CTEXT** to view the calibration info text, and **ADJD** command to view the adjustment date. Date format for **CDATE** and **ADJD** is YYYYMMDD.

CDATE<cr>

CTEXT<cr>

ADJD<cr>

Examples:

cdate

Cal. date : 20091201

ctext

Cal. info : VAISALA/HELSINKI

adjd

Adj.date : 20091201

View Order Code

Use the **CODE** command to view the order code that has been stored in the probe. This command is useful if you need to order a new probe with the same options.

CODE<cr>

Example:

code

Order code : A12A01B0

View Serial Number

Use the **SNUM** command to view the serial number of the probe.

SNUM<cr>

Example:

snum

Serial number : E3950006

View Software Version

Use the **VERS** command to display the software version of the probe.

VERS<cr>

Example:

```
vers
HMP60 / 1.00.0
```

Serial Line Output Commands

Start Measurement Output

Use the **R** command to start the continuous outputting of measurement values as an ASCII text string to the serial line. The output always includes readings for temperature, RH and Td.

R<cr>

Example:

```
r
T= 22.6 'C RH= 22.8 %RH Td= 0.3 'C
T= 22.6 'C RH= 22.5 %RH Td= 0.2 'C
T= 22.6 'C RH= 22.5 %RH Td= 0.2 'C
...
```

Outputting the results continues in intervals issued with the command **INTV**. You can stop the output by entering the **S** command.

Stop Measurement Output

Use the **S** command to stop the continuous measurement output:

S<cr>

Output the Measurement Message Once

Use the **SEND** command to output the measurement values once. If the probe is in POLL mode and line is not open for commands, specify the address of the probe to receive the measurement message.

SEND [aaa]<cr>

where

aaa = Address of the probe, range 0 ... 254. Set with the **ADDR** command.

Example (probe in STOP mode, no address needed):

send

T= 22.7 'C RH= 20.0 %RH Td= -1.5 'C

Example (probe in POLL mode, with address 10):

send 10

T= 22.8 'C RH= 20.1 %RH Td= -1.3 'C

Configuring Serial Line Operation

Set Serial Line Settings

Use the **SERI** command to show or set the serial line settings. The new settings will be taken into use when the probe is reset or powered up.

SERI [b p d s]<cr>

where

b = baud rate
(300, 600, 1200, 2400, 4800, 9600, 19200, 38400, 57600)
p = parity (n = none, e = even, o = odd)
d = data bits (7 or 8)
s = stop bits (1 or 2)

Example (shows default settings):

```
seri  
Baud P D S      :    19200 N 8 1
```

Set Serial Interface Mode

SMODE [xxx]<cr>

where

xxx = STOP, RUN, or POLL

In STOP mode: outputting only when command is issued, any command can be used.

In RUN mode: outputting automatically, only command S can be used. In POLL mode: outputting only when command is issued, any command can be used after the line has been opened using the **OPEN** command.

The polling mode can be used when more than one probe is connected to one serial bus. When set to POLL state, the probes communicate one at a time when the specific address is called on the serial line. See descriptions of the commands **ADDR** on page 38 and **OPEN** on page 42.

Examples:

```
smode stop  
Serial mode    :    STOP
```

```
smode run  
Serial mode    :    RUN
```

```
smode poll  
Serial mode    :    POLL
```

NOTE

In the RUN mode, the probe may send the measurement data message right as you are typing the **S** command to stop the sending. Therefore, you may need to repeat the **S** command. This must be noted especially when designing computer programs to access the probe. You can also use the **Esc** key on your keyboard to stop the sending.

Set Output Interval

Use the **INTV** command to show or set the output interval of the serial line measurement messages (applies when **R** command or **RUN** mode is used). The shortest output interval is one second. This command has no effect on the operation of the analog output.

INTV [*n xxx*]<cr>

where

n = Time interval in range 1 ... 255
xxx = time unit = "S", "MIN", or "H"

Example:

```
intv 1 s
Value      : 1
Unit       : S
```

Set Measurement Filtering

Use the **FILT** command to view or set the speed at which the latest measurement result is integrated into the humidity and temperature readings. The command affects both analog output and serial line output.

FILT [*a.aaa*]<cr>

where

a.aaa = Range 0.1 ... 1.0.
 1.0 = No filtering, latest measurement is output without averaging
 0.5 = Average of last two measurements
 0.1 = Average of ca. 16 measurements

Example (default setting, no filtering):

```
filt
Filter      : 1.000 ?
```

Example (set filtering to 0.5):

```
filt 0.5
Filter      : 0.500
```

Set Probe Address

To operate in the POLL mode, the probe must have an address. If multiple probes share the same serial line, each probe must have a different address.

For a description of the serial interface modes, see section Set Serial Line Settings on page 35.

ADDR [*nn*]<cr>

where

nn = address (0 ... 99)

Example:

```
addr  
Address      :      0
```

Set Serial Interface Delay

User the **SDELAY** command to view or set the serial interface answer minimum delay.

SDELAY [*delay*]<cr>

where

delay = Range 0 ... 255. Value corresponds to four milliseconds (for example, 5 = 0.020 second minimum answer delay)

Example:

```
sdelay  
Serial delay :      30  
  
sdelay 50  
Serial delay :      50
```

Set Measurement Units

Use the UNIT command to view or set the measurement units that are used in the serial line measurement messages.

UNIT [M/N]<cr>

M is for metric units, N is for non-metric units.

Quantity	Metric Unit	Non-Metric Unit
RH	%RH	%RH
Td	°C	°F
T	°C	°F

Examples:

```
unit  
Units           : Metric
```

```
unit n  
Units           : Non metric
```

Calibration Commands

Calibrate Humidity Measurement

Use the **CRH** command to perform a one-point or two-point correction to the capacitance measurement of the probe. This command changes the offset and/or gain of the measurement, depending on the calibration and reference:

- one-point calibration with a single < 50 %RH reference will adjust the offset of the capacitance measurement
- one-point calibration with a single > 50 %RH reference will adjust the gain of the capacitance measurement
- two-point calibration will adjust both offset and gain. The first point requires a < 50 %RH humidity reference, the second point must be > 50 %RH. There must also be at least 30 percentage point difference between the references.

CRH [reference]<cr>

When performing a one-point calibration, you need to place the probe in the reference humidity and wait for 20 – 40 minutes for the humidity to stabilize. To apply the adjustment, enter the CRH command with the reference %RH as a parameter.

Example: one-point calibration (LiCl reference, 11 %RH):

```
crh 11  
OK
```

Example: one-point calibration with NaCl reference (75 %RH):

```
crh 75  
OK
```

Giving the command without parameters starts the two-point calibration. Remember to allow the humidity to stabilize for 20 - 40 minutes after changing the reference.

Example: two-point calibration with LiCl (11 %RH) and NaCl (75 %RH) references:

```
crh  
RH : 11.2684 1. ref ? 11  
Press any key when ready ...  
RH : 75.0612 2. ref ? 75  
OK
```

Clear Adjustment of RH Measurement

Use the **CRHCLR** command to clear the adjustment of RH measurement that has been done using the **CRH** command.

CRHCLR<cr>

Example:

```
crhclr  
OK
```

Calibrate Temperature Measurement

Use the CT command to perform a one-point or two-point temperature (T) calibration. One-point calibration adjusts the offset for the measurement, two-point calibration adjusts offset and gain.

CT [reference]<cr>

When performing a one-point calibration, you need to place the probe in a single temperature reference and wait for 20 – 40 minutes for the temperature to stabilize. To apply the adjustment, enter the **CT** command with the reference temperature as a parameter.

Example: one-point calibration

```
ct 23.5
OK
```

Giving the command without parameters starts the two-point calibration. Remember to allow the temperature to stabilize for 20 - 40 minutes after changing the reference. The first reference point must be smaller than the second point, and the difference between the reference points must be more than 30 °C. To update the measured value while the command is running, press enter without inputting a value.

Example: two-point calibration

```
ct
T   :   22.03 Ref1 ? 22
Press any key when ready ...
T   :   55.12 Ref2 ? 55
OK
```

Clear Adjustment of T Measurement

Use the **CTCLR** command to clear the adjustment of temperature measurement that has been done using the **CT** command.

CTCLR<cr>

Example:

```
ctclr
OK
```

View User Adjustment Parameters

Use the **L** command to view the current user adjustment parameters. This command is useful for checking the currently applied customer calibration.

L<cr>

The output values are as follows:

- Cp offset and gain: capacitance, calibrated using the CRH command
- T offset and gain: calibrated using the CT command

Example (shows default values, no user calibration done):

```
l
Cp offset : 0.00000000E+00
Cp gain   : 1.00000000E+00
T offset  : 0.00000000E+00
T gain    : 1.00000000E+00
```

Other Commands

Display Command List

Use the **HELP** command to display a list of the currently available commands.

HELP<cr>

Display the Currently Active Errors

Use the **ERRS** command to display the currently active error codes. For troubleshooting active errors, see Table 9 on page 55.

ERRS<cr>

Example (no active errors):

```
errs
0000h
No errors
```

Connect to the Probe in POLL Mode

Use the **OPEN** command to connect to a probe that is in POLL mode.

OPEN [aa]<cr>

Where

aa = address (0 ... 99)

Example:

```
open 1
HMP110    1 line opened for operator commands
```

Close the Connection in POLL Mode

The **CLOSE** command closes the connection to the probe.

CLOSE<cr>

Example:

```
close
line closed
```

Reset the Probe

Use the **RESET** command to reset the probe. Upon reset or power-up, the probe enters the serial mode that has been set with the **SMODE** command.

RESET<cr>

Example (probe set to serial mode STOP, will output probe model and software version at reset):

```
reset  
HMP60 / 1.00.0
```

Example (probe set to serial mode RUN, will start to output measurement messages at reset):

```
reset  
T= 23.6 'C RH= 20.2 %RH Td= -0.5 'C  
T= 23.6 'C RH= 20.2 %RH Td= -0.5 'C  
T= 23.3 'C RH= 20.2 %RH Td= -0.8 'C  
...
```

Restore Factory Settings

Use the **FRESTORE** command to restore the factory settings to the probe. All user settings, including the user-performed calibration corrections, will be lost. The probe will revert back to the factory calibrated settings.

FRESTORE<cr>

Example:

```
frestore  
Factory settings restored
```

This page intentionally left blank.

CHAPTER 5

MAINTENANCE

This chapter provides information that is needed in basic maintenance of HMP60 and HMP110.

Periodic Maintenance

The measurement accuracy of the HMP60 and HMP110 should be calibrated yearly. When calibration indicates that accuracy is not within specification:

- HMP60: change the INTERCAP® Sensor.
- HMP110: adjust the measurement, or have a Vaisala Service Center adjust it for you.

Light cleaning and filter replacement should be done only when necessary.

Cleaning

The probe body can be wiped clean with a soft, lint-free cloth moistened with mild detergent. Do not use solvents or compressed air.

Note that wiping the membrane filter or stainless steel sintered filter may block its pores and/or deposit residue on the filter. If the filter is heavily contaminated, replace it.

Changing the Filter

The filter on the probe should be replaced when it is damaged or dirty.

1. Turn the filter counter-clockwise to loosen it.
2. Remove the filter from the probe. Be careful not to touch the sensors with the filter. Without the filter in place, the sensors are easily damaged – handle the probe carefully.
3. Install a new filter on the probe, and tighten it so it is finger-tight. Make sure the filter sits straight and meets the threads properly.

New filters can be ordered from Vaisala. For available filters, see section Filter Options on page 15. The order codes of the filters are listed in section Options and Accessories on page 60.

Calibration Procedure

To calibrate your probe, you need a known stable humidity or temperature reference, and a way to read the output of the probe (analog or serial). As a humidity reference you can use, for example, the Vaisala Humidity Calibrator HMK15.

Refer to chapter Technical Data on page 57 for accuracy specifications of the probes.

1. Connect the power/signal cable to the probe, but do not power it up yet.
2. Place the probe in the reference environment. For example, you can use a NaCl salt chamber (75 %RH) as the humidity reference.
3. Wait for 20 – 40 minutes for the reading to stabilize.
4. Power up the probe and wait for one minute.
5. Check the measurement reading, and compare it with the reading that the reference should produce.

Adjustment Procedure (HMP110)

NOTE

If you are adjusting a HMP110 probe that is in the analog output mode, see section Terminal Application Settings for Probes in Analog Mode on page 30 for instructions on how to start the probe in RS-485 mode.

One-point Adjustment of RH Measurement (HMP110)

To perform a one-point adjustment to the capacitance measurement of the HMP110 you need:

- The Vaisala USB cable (Vaisala order code: 219690)
- PC with a terminal application.
- One humidity reference. One-point calibration with a single < 50 %RH reference will adjust the offset of the measurement. One-point calibration with a single > 50 %RH reference will adjust the gain of the measurement

The procedure below uses the HMK15 Humidity Calibrator. LiCl salt (11 %RH) is used as the reference point.

1. Connect the USB cable to the PC, but do not connect it to the probe yet.
2. Insert the probe in the LiCl salt chamber of the humidity calibrator (11 %RH).
3. Start a terminal application and set the correct connection settings. The default serial settings are **19200 8 N 1**. Remember to check which COM port the USB cable is using.
4. Wait for 20 – 40 minutes for the humidity to stabilize.
5. Start the terminal session and connect the USB cable to the probe. If your probe is in the analog output mode, you need to press Enter a few times to start it in RS-485 mode.
6. Verify that the connection works by giving the ? command:

?

If the probe does not respond with device information:

- Disconnect the USB cable from the probe and retry. If your probe is in the analog output mode, press Enter a few times immediately after connecting the USB cable.
- Try the ?? command in case the probe is in POLL state, open the line using **OPEN** command if necessary
- Check your serial line settings and cable connections

7. When your serial connection is working, use the **L** command to see the current user adjustment parameters.

1

8. Use the **ERRS** command to see that no errors are active:

errs

9. Give the **CRH** command, with the %RH value of the reference as a parameter (in this case 11 for LiCl):

crh 11
OK

10. Check with the **L** command that the user adjustment parameters have changed.

If you wish to remove the effects of RH calibration (returning the RH measurement of the HMP110 to the factory calibrated state), see section Clear Adjustment of RH Measurement on page 40.

Two-point Adjustment of RH Measurement (HMP110)

To perform a two-point adjustment to the capacitance measurement of the HMP110 you need:

- The Vaisala USB cable (Vaisala order code: 219690)
- PC with a terminal application.
- Two humidity references. The first point requires a < 50 %RH humidity reference, the second point must be > 50 %RH. There must also be at least 30 percentage point difference between the references.

The procedure below uses the HMK15 Humidity Calibrator. LiCl salt (11 %RH) is used as the first reference point, NaCl (75 %RH) as the second.

1. Connect the USB cable to the PC, but do not connect it to the probe yet.
2. Insert the probe in the LiCl salt chamber of the humidity calibrator (11 %RH).
3. Start a terminal application and set the correct connection settings. The default serial settings are **19200 8 N 1**. Remember to check which COM port the USB cable is using.
4. Wait for 20 – 40 minutes for the humidity to stabilize.
5. Start the terminal session and connect the USB cable to the probe. If your probe is in the analog output mode, you need to press Enter a few times to start it in RS-485 mode.

6. Verify that the connection works by giving the **?** command:

?

If the probe does not respond with device information:

- Disconnect the USB cable from the probe and retry. If your probe is in the analog output mode, press Enter a few times immediately after connecting the USB cable.
- Try the **??** command in case the probe is in POLL state, open the line using **OPEN** command if necessary
- Check your serial line settings and cable connections

7. When your serial connection is working, use the **L** command to see the current user adjustment parameters.

l

8. Use the **ERRS** command to see that no errors are active:

errs

9. Use the **SEND** command to verify the currently measured RH value:

send

T= 22.9 'C RH= 11.1 %RH Td= -8.0 'C

10. Give the **CRH** command with the RH value of the humidity reference as a parameter:

crh 11

OK

11. After entering the correction, unplug the USB cable from the probe. Insert the probe in the NaCl salt chamber (75 %RH) and wait for 20 – 40 minutes for humidity and temperature to stabilize.

12. Connect the USB cable to the probe and use the **SEND** command to see the currently measured value.

13. Give the **CRH** command with the RH value of the humidity reference as a parameter:

crh 75

OK

14. Check with the **L** command that the user adjustment parameters have changed.

If you wish to remove the effects of RH calibration (returning the RH measurement of the HMP110 to the factory calibrated state), see section Clear Adjustment of RH Measurement on page 40.

One-point Adjustment of T Measurement (HMP110)

To perform a one-point adjustment to the temperature measurement of the HMP110 you need:

- The Vaisala USB cable (Vaisala order code: 219690)
 - PC with a terminal application.
 - One known and stable temperature reference.
1. Connect the USB cable to the PC, but do not connect it to the probe yet.
 2. Insert the probe in the temperature reference.
 3. Start a terminal application and set the correct connection settings. The default serial settings are **19200 8 N 1**. Remember to check which COM port the USB cable is using.
 4. Wait for 20 – 40 minutes for the temperature to stabilize.
 5. Start the terminal session and connect the USB cable to the probe. If your probe is in the analog output mode, you need to press Enter a few times to start it in RS-485 mode.
 6. Verify that the connection works by giving the **?** command:

?

If the probe does not respond with device information:

- Disconnect the USB cable from the probe and retry. If your probe is in the analog output mode, press Enter a few times immediately after connecting the USB cable.
 - Try the **??** command in case the probe is in POLL state, open the line using OPEN command if necessary
 - Check your serial line settings and cable connections
7. When your serial connection is working, use the **L** command to see the current user adjustment parameters.

1

8. Use the ERRS command to see that no errors are active:

errs

9. Give the CT command, with the temperature value of the reference as a parameter:

ct 23.5
OK

10. Check with the **L** command that the user adjustment parameters have changed.

If you wish to remove the effects of T calibration (returning the T measurement of the HMP110 to the factory calibrated state), see section Clear Adjustment of T Measurement on page 41.


Repair Maintenance

Changing the INTERCAP Sensor (HMP60)

This procedure restores the humidity measurement accuracy of the HMP60. No adjustment after the sensor change is needed.

To perform this procedure, you need a new INTERCAP sensor. It is also recommended that you replace the filter with a new one. For order codes, see section Options and Accessories on page 60.

1. Remove the filter from the probe by turning it counter-clockwise.
2. Pull out the old INTERCAP sensor (the larger of the two sensors inside the probe) and insert a new one. Refer to Figure 14 on page 52. Handle the new sensor by the plastic socket. **DO NOT TOUCH THE SENSOR PLATE.**
3. Attach a new filter on the probe.



0912-097

Figure 14 **Changing the Sensor**

Changing the HUMICAP 180R Sensor (HMP110)

NOTE

Replacing the humidity sensor of the HMP110 is not necessary in normal operation. If the accuracy of the probe does not seem to be within specification, it is likely that the accuracy can be restored by performing the adjustment procedure. See section Two-point Adjustment of RH Measurement (HMP110) on page 48.

Follow this procedure to replace the humidity sensor of the HMP110 in case it has been damaged, or normal adjustment is not sufficient to restore the measurement accuracy. Calibration and adjustment of the humidity measurement is required after the sensor change.

To perform this procedure, you need a new HUMICAP 180R sensor. It is also recommended that you replace the filter with a new one. For order codes, see section Options and Accessories on page 60.

1. Remove the filter from the probe by turning it counter-clockwise.
2. Pull out the old HUMICAP 180R sensor (the larger of the two sensors inside the probe) and insert a new one. Refer to Figure 14 on page 52. Handle the new sensor by the plastic socket. **DO NOT TOUCH THE SENSOR PLATE.**
3. Perform a two-point adjustment of the RH measurement as instructed in section Two-point Adjustment of RH Measurement (HMP110) on page 48.
4. Attach a new filter on the probe.

This page intentionally left blank.

CHAPTER 6

TROUBLESHOOTING

This chapter describes common problems, their probable causes and remedies, and contact information for technical support.

Solving Typical Problems

You can check the error message via the serial interface by using the **ERRS** command. If you are unable to remove the errors, contact Vaisala technical support. See section Technical Support on page 56.

Table 9 Troubleshooting Table

Problem or message	Likely causes and solutions
Measurement not working. any of the following errors active: - T meas error - RH meas error	- Sensor(s) damaged or missing. Open the filter and check. - Calibration is not done. Calibrate the probe (HMP110) or change the sensor (HMP60). - Check the supply voltage of the probe. - Check the output mode of the probe using serial line.
Humidity measurement appears to be wrong.	- Check for condensation on the probe and sensor. - Use the L command to check the currently applied calibration correction. - Calibrate and adjust the probe (HMP110). - Calibrate the probe and change the sensor if necessary(HMP60).
The probe is not responding to any serial commands.	- Disconnect the USB cable from the probe and retry. If your probe is in the analog output mode, press ENTER a few times immediately after connecting the USB cable. - Try the ?? command in case the probe is in POLL state, open the line using OPEN command if necessary. - Check your serial line settings and cable connections.
The following error is active: - Voltage error	- Operating voltage out of range. Correct voltage and reset probe.

Problem or message	Likely causes and solutions
Any check sum error is active. For example: - Program flash check sum error - Parameter flash check sum error	Internal error. Perform the following steps: 1. Return the probe to factory settings using the FRESTORE command. Check again. 2. If the error is still active, contact Vaisala technical support.

Technical Support

For technical questions, contact the Vaisala technical support by e-mail at helpdesk@vaisala.com.

For contact information of Vaisala Service Centers, see www.vaisala.com/services/servicecenters.html.

CHAPTER 7

TECHNICAL DATA

This chapter provides the technical data of the HMP60 and HMP110.

Specifications

Performance (HMP60)

Relative Humidity

Measurement range	0 ... 100 %RH
Typical accuracy	
temperature range +0 ... +40 °C	
0 ... 90 %RH	±3 %RH
90 ... 100 %RH	±5 %RH
temperature range -40 ... 0 °C	
and +40 ... +60 °C	
0 ... 90 %RH	±5 %RH
90 ... 100 %RH	±7 %RH
Humidity sensor	Vaisala INTERCAP®

Temperature

Measurement range	-40 ... +60 °C
Accuracy over temperature range	
-40 ... +60 °C	±0.6 °C

Dewpoint

Measurement range	-40 ... +60 °C
Typical accuracy	
temperature range 0 ... +40 °C	
when temperature - dewpoint	
< 15 °C	±2 °C
temperature range -40 ... 0 °C	
and +40 ... +60 °C when	
temperature - dewpoint < 10 °C	±3 °C

Performance (HMP110)

Relative Humidity

Measurement range	0 ... 100 %RH
Accuracy (incl. non-linearity, hysteresis and repeatability)	
temperature range +0 ... +40 °C	
0 ... 90 %RH	±1.7 %RH
90 ... 100 %RH	±2.5 %RH
temperature range -40 ... 0 °C and +40 ... +80 °C	
0 ... 90 %RH	±3.0 %RH
90 ... 100 %RH	±4.0 %RH
Factory calibration uncertainty (+20 °C)	±1.5 %RH
Humidity sensor	Vaisala HUMICAP® 180R

Temperature

Measurement range	-40 ... +80 °C
Accuracy over temperature range	
0 ... +40 °C	±0.2 °C
-40 ... 0 °C, +40 ... +80 °C	±0.4 °C
Temperature sensor	Pt1000 RTD 1/3 Class B IEC 751

Dewpoint

Measurement range	-40 ... +80 °C
Accuracy (incl. non-linearity, hysteresis and repeatability)	
temperature range 0 ... +40 °C	
when temperature - dewpoint < 15 °C	±1 °C
15 ... 25 °C	±2 °C
temperature range -40 ... 0 °C and +40 ... +80 °C when temperature - dewpoint < 15 °C	±2 °C

Operating Environment

Operating temperature range (HMP60)	-40 ... +60 °C
Operating temperature range (HMP110)	-40 ... +80 °C
Operating humidity range	0 ... 100 %RH, non-condensing
Electromagnetic compatibility	EN 61326-1:2006 Electrical equipment for measurement, control and laboratory use - EMC requirements - Basic immunity test requirements. EN 55022:2006 + Am 1:2007 Information technology equipment - Radio disturbance characteristics - Limits and methods of measurement. Class B.

Inputs and Outputs

Operating voltage	
with 0...1 V / 2.5 V or RS-485	5 ... 28 V
with 0...5 V / 1 ... 5 V	8 ... 28 V
Current consumption	
typical average	1 mA
max peak	5 mA
Start-up time	1 s at operating voltage < 14 VDC 4 s at operating voltage > 14 VDC
Outputs	
analog output channels	2
analog output types	0 ... 1 VDC / 2.5 VDC / 5VDC, 1 ... 5 VDC
with loop power converter	4 ... 20 mA (separate module, compatible with humidity accuracy only)
digital output (optional)	RS-485 two-wire half-duplex
External loads	
0 ... 1	R _L min 10 kΩ
0 ... 2.5 / 0 ... 5 / 1 ... 5 V	R _L min 50 kΩ

Mechanics

Materials	
body	chrome coated aluminum
grid filter	chrome coated ABS plastic
cable	Polyurethane
Housing classification	IP65
Body thread	M12x1 / 10 mm
Cable connector	4-pin M8 (IEC 60947-5-2)
Cable lengths	0.32 and 3 m
Weight	
probe	12 g
probe with 0.3 m cable	23 g

Options and Accessories

Table 10 HMP60 Options and Accessories

Description	Item code
Vaisala INTERCAP sensor	15778HM
Vaisala INTERCAP sensor, 10 pcs	INTERCAPSET-10PCS
Probe mounting flange	226061
Probe mounting clamps, 10 pcs	226067
Sensor protection	
Plastic grid filter	DRW010522
Membrane filter	DRW010525
Stainless steel sintered filter	HM46670SP
Loop power converter (4 ... 20 mA)	UI-CONVERTER-1
Mounting bracket with lid for loop power converter	225979
Plastic M12 installation nuts, pair	18350SP
Shielded cable, 0.32 m	HMP50Z032
Shielded cable, 3 m	HMP50Z30A
FEP cable (+180 °C), 3 m	226902SP
USB serial interface cable	219690

Table 11 HMP110 Options and Accessories

Description	Item code
Vaisala HUMICAP 180R sensor	HUMICAP180R
Probe mounting flange	226061
Probe mounting clamps, 10 pcs	226067
Sensor protection	
Plastic grid filter	DRW010522
Membrane filter	DRW010525
Stainless steel sintered filter	HM46670SP
Loop power converter (4 ... 20 mA)	UI-CONVERTER-1
Mounting bracket with lid for loop power converter	225979
Plastic M12 installation nuts, pair	18350SP
Shielded cable, 0.32 m	HMP50Z032
Shielded cable, 3 m	HMP50Z30A
Shielded cable (+80 °C), 1.5 m	225777SP
Shielded cable (+80 °C), 3 m	225229SP
FEP cable (+180 °C), 3 m	226902SP
USB serial interface cable	219690



www.vaisala.com

