



ABOUT THIS MANUAL AND MT XPRESS

Thank you for purchasing an **MT Xpress** product.

All of our equipment is assembled and packed with great care. If you should find any incorrect item, please contact your **Xpress** dealer immediately.

MT Xpress products are Weights & Measures approved precision weighing instruments. However, you may want to obtain official certification through your supplier or local Weights & Measures office.

This **MT Xpress** product was developed, produced, and tested in a METTLER TOLEDO facility that has been audited and registered according to international ISO 9001 quality standards and ISO 14000 environment control program. Properly used and maintained, this product will provide years of accurate weighing. Handle it as you would any piece of fine electronic equipment.

Please READ this manual BEFORE operating or servicing this equipment. Follow the instructions carefully and save this manual for future reference.

We at **MT Xpress** want to make sure you received the product you expected. It is important to us that you are satisfied with your purchase. If there is anything we can help you with, or if you are not satisfied with either your product or the services received from the **Xpress** representative, let us know.

How can you reach us?

XPRESS CUSTOMER CARE CENTER, USA

24/7 Information and Support: www.mt.com/xpress
xpress@mt.com

8 AM to 8 PM EST Toll Free: 1-866-MTXPRESS

Xpress

Mettler-Toledo, Inc.
60 Collegeview
Westerville, OH 43081

FCC Approval

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

CONTENTS

| | |
|--|----------|
| PREPARING THE SCALE FOR USE | |
| UNPACKING AND ASSEMBLY | 5 |
| POWERING UP THE INDICATOR | 6 |
| YOUR XPRESS SCALE AT A GLANCE | 7 |
| DISPLAY | 7 |
| KEYPAD | 7 |
| CURSORS (LED) | 7 |
| OPERATING YOUR SCALE | |
| STRAIGHT WEIGHING | 8 |
| TARE FUNCTION | 8 |
| POWERING UP AND SELF-CHECKING | 8 |
| SPECIAL MODES – SETUP MODE | 9 |
| ACCESSING SETUP MODE | 9 |
| CLEANING & MAINTAINING YOUR SCALE | |
| CLEANING AND REGULAR MAINTENANCE | 10 |
| BATTERY CHECK | 10 |
| BATTERY REPLACEMENT | 11 |
| SERVICING YOUR SCALE | |
| ACCESSING THE SERVICE MODE | 12 |
| REMOVING OLD LOAD CELLS | 14 |
| INSTALLING NEW LOAD CELLS | 14 |
| SHIFT TEST AND ADJUSTMENT | 16 |
| SETUP SCALE CAPACITY | 16 |
| DEFLECTION TEST | 16 |
| APPENDIX | |
| TROUBLESHOOTING | 17 |
| ERROR MESSAGES | 17 |
| CORRECTIVE STEPS | 17 |
| MODEL SPECIFICATIONS | 18 |
| TECHNICAL DATA | 18 |
| WIRING | 18 |
| GEO VALUE TABLE | 19 |
| PHYSICAL DIMENSIONS | 20 |

PREPARING THE SCALE FOR USE

UNPACKING AND ASSEMBLY

Thank you for purchasing an **MT Xpress** product. Please inspect the package immediately upon receipt. If the box is damaged, check for internal damage and file a freight claim with the carrier if necessary. If the container is undamaged, open the box, remove the scale and place it on a solid, flat surface. Please keep the packing material and shipping insert in case you need to return the scale to an **MT Xpress** representative.

Package contents for all **MT Xpress** Economy Bench Scale units include:

Product

- **Xpress** Economy Bench scale
- **Xpress** Column indicator
- AC-DC power adapter
- Accessory bag (including 4 socket head screws, 4 flat washers, 4 spring washers, 1 cable clamp, 1 cable protective baffle, 1 Allen key, 1 seal screws, 1 lead seal wire, 1 lead, “kg” sticker)


Documents

- Quick Start Guide
- Installation Instructions


CD-ROM

- Operation & Service Manual


1. Open the box and take out the scale. Remove the packing material from each side of the scale. Set the unit on a sturdy workplace.




2. Attach the column bracket beneath the bottom scale frame by tightening the four socket head screws.



3. Coil the excess load cell cable and insert it into the column. A small length of tape applied to the ends of the coils allows the cable to slide into the column easier. Mount the indicator onto the column. Adjust the indicator to the proper angle and fasten the bolt.



4. Apply power to the scale using adapter or six "C" cell batteries.



5. Level the scale by turning the adjustable feet. It is leveled correctly when the bubble indicator is in the center of the circle.

level



not level



POWERING UP THE INDICATOR


Plug in the indicator to an electrical outlet. Turn the on/off button gently. The indicator will automatically run a self-test when powered up.

- All segments of the display will light. Operator should check that the display is lit.
- Detect the memory of the indicator. If an error message is displayed during the powering up process, refer to the Error Code table in the Appendix.



YOUR XPRESS SCALE AT A GLANCE

■ DISPLAY



The display of the indicator is made up of six red LED, 0.56" digits. Five of the digits are for weight and the sixth digit is for displaying a negative/minus sign, which indicates motion. Two cursors indicate gross zero and net weight separately. This display is used for showing weighing data, prompting the operator, and coding errors. The indicator has two buttons: "Zero/ON-OFF" and "Tare".



■ KEYPAD

| Key | Name | Function |
|---|-------------------|---|
|  | Zero – On/Off Key | On/Off: Turn power on and off Zero: Zeroes the scale |
|  | Tare Key | Tare: Tares the scale and clears the tare value |

■ CURSORS (LED)

| Cursor | Description |
|--|---|
|  ZERO | Illuminates when weight is gross zero (0) |
| NET  | Illuminates when weight is in net weight. |

OPERATING YOUR SCALE

STRAIGHT WEIGHING

Zero/ON-OFF button: this button turns the power OFF and ON and zeros the scale. When you want to turn off the power, hold down this button for 3-5 seconds until the display shows "OFF". Then close the indicator.

TARE FUNCTION

Tare button: In gross weighing mode, the displayed weight will be recorded as a tare value by pressing this button. The displayed net weight will be zero. In net weight mode, pressing this button and returning to gross mode will clear the tare value.

When you press both the Zero/ON-OFF and Tare buttons at the same time, the indicator will enter service mode and parameter setup.

POWERING UP AND SELF-CHECKING


When you press the Zero/ON-OFF button, the indicator powers up and the scale will self-check RAM and ROM before entering the normal operation mode. The self-checking process includes lighting all display segments, displaying software part numbers/versions, and capturing zero.

SPECIAL MODES – SETUP MODE

Several parameters in the scale can be changed to enable you to Setup the scale to your individual needs.

■ ACCESSING SETUP MODE

When in Normal Weighing Mode, press down and hold the TARE button for three seconds. The display will show the example given below, indicating that the scale has entered into user setup mode.



Zero/ON-OFF button: Press this button to accept the current selected parameter and to move on to the next setup.

Tare button: Press this button to select the set up parameter.

Operation Parameter Configuration

| Configuration | Parameter |
|-----------------------------|---|
| F1 – Increment selection | 0 = Disable 1 = Enable, press the TARE button to select the increment needed than press the ZERO/ON-OFF button to confirm. |
| F2 – Push-button zero range | 0 = $\pm 2\%$ FS 1 = $\pm 20\%$ FS |
| E - End of setup | 0 = Give up amendment 1 = Save |

CLEANING & MAINTAINING YOUR SCALE



CLEANING AND REGULAR MAINTENANCE


Periodically clean the faceplate of the terminal with a soft, damp cloth and a mild cleaner. DO NOT use industrial solvent to clean the keyboard or display panel. DO NOT spray cleaner directly onto the unit.

BATTERY CHECK

When the battery power is low the display will show:

| Weight (kg) | |
|---------------------|--------------------|
| L | 0 |
| <small>ZERO</small> | <small>NET</small> |

BATTERY REPLACEMENT



Replace the batteries in time. To change the batteries:

1. Open the battery door on the rear of the XID terminal enclosure.
2. Carefully remove the six "C" cell batteries.
3. Contact the manufacturer or seller of the batteries to find out how they should be recycled or recharged.



4. Insert six new or recharged "C" cell batteries as illustrated on the battery housing. This arrangement is shown below.




Figure: Shown With Rear Battery Panel Removed

5. Reinstall the rear cover over the batteries and press into place.
6. Test for proper operation.

SERVICING YOUR SCALE

For the following services, please contact your Xpress representative at www.mt.com/xpress.

| | |
|--|---|
|  |  WARNING |
| | <p>DISCONNECT ALL POWER TO THIS UNIT BEFORE INSTALLING, SERVICING, CLEANING, OR REMOVING THE FUSE. FAILURE TO DO SO COULD RESULT IN BODILY HARM AND/OR PROPERTY DAMAGE.</p> |

| |
|---|
|  CAUTION |
| <p>BEFORE CONNECTING OR DISCONNECTING ANY INTERNAL ELECTRONIC COMPONENTS OR INTERCONNECTING WIRING BETWEEN ELECTRONIC EQUIPMENT, ALWAYS REMOVE POWER AND WAIT AT LEAST THIRTY (30) SECONDS BEFORE ANY CONNECTIONS OR DISCONNECTIONS ARE MADE. FAILURE TO OBSERVE THESE PRECAUTIONS COULD RESULT IN DAMAGE TO OR DESTRUCTION OF THE EQUIPMENT, OR BODILY HARM.</p> |

■ ACCESSING THE SERVICE MODE

Open the indicator enclosure and short jumper J5 on controller PCB, then open the circuit and enter setup mode. The display shows:

| | |
|---------------------|--------------------|
| Weight (kg) | |
| S1 | 0 |
| <small>ZERO</small> | <small>NET</small> |

Zero/ON-OFF button: Press this button to accept the current selected parameter and to move on to the next setup.

Tare button: Press this button to select the set up parameter.

Parameter Configuration

Setup Item

S1 - Expanded display

S3 – Geo code setup

S4 - Calibration

E - End of setup mode

Optional Value

0 = Normal display

1 = Expand display (show internal counts)

0 = Disable

1 = Enable, default is 12. Change GEO code using the TARE button, and then press the ZERO/ON-OFF button to confirm that selected value.

0 = Skip calibration


1 = Enter calibration

0 = Give up amendment

1 = Save


CALIBRATION SEQUENCE

Step 1: Display the scale capacity and then enter the calibration




Display default capacity 100 kg. Then press the TARE button successively and the display will show 100 kg, 150 kg, 200 kg, 300 kg, 500 kg, 600 kg, 750 kg, 1000 kg, 2000 kg, 3000 kg, 5000 kg, 10,000 kg, 15 kg, 20 kg, 30 kg, 50 kg, 60 kg, 75 kg. Select a desired capacity and then press the ZERO/ON-OFF button to choose. Then enter the next step.

Step 2: Select the increment




The default setting is 0.02 kg, if 100 kg is selected. Press the TARE button to select other increments if needed, then press the ZERO/ON-OFF button to verify each selected value. Enter the next step.

Step 3: Clear the scale calibration




Remove all the items from the scale platter and press the ZERO/ON-OFF button. The display will automatically count down from five to zero to calibrate zero. If any motion is detected during the process the calibration will restart. When you finish the calibration, go on to the next step.

Step 4: Select the calibration weight



Select the calibration weight value that you want by pressing the TARE button. Press the ZERO/ON-OFF button to confirm the selected value and enter into SPAN calibration shown as Step 5: (if 100%FS is selected)

Step 5: SPAN Calibration




Place a test weight on the scale platter for the selected capacity.

Note: Do not change the loaded test weight at discretion.

Press the ZERO/ON-OFF button and the display will begin counting down from five to zero, indicate SPAN calibration. If any motion is detected during this process, restart SPAN calibration. When completing calibration, then enter next step automatically.

Step 6: Final Option

When calibration is completed, the indicator will show as below:



Here "0" indicates giving up the above amendment and calibration. Use [TARE] button to select "0" or "1". To save all amendment and calibration, then select "1".

Press [ZERO/ON-OFF] button to save the selected parameter and the result of calibration. Then enter normal weighing mode after auto self-testing.

REMOVING OLD LOAD CELLS

- Remove the scale platter and put it on a level surface.
- Loosen the tightening bolt of load cell on the base of the scale by using an inner hex spanner.
- Remove the top base of the scale.
- Loosen the tightening bolt for the load cell on the bottom base of scale.
- Remove the load cell.

INSTALLING NEW LOAD CELLS

Install the load cell on the bottom of the base of the scale using four screws, washers, and flats.

- Make sure load direction of the load cell.
- Tighten the load cell bolt (see NM moment on the chart below).

Install overload stop screw B:

- Install two overload stop bolts with nut on both side of the load cell on the bottom base of scale.

Install overload stop screw A:

- Install four overload stop bolts with nuts in the corner position on the bottom base of scale

Install the top base of scale:

- Mount the load cell on the top base of the scale using four screws, washers, and flats.

Requirement


The scale should stay parallel from top to bottom and right to left.

Tighten the load cell bolt according to the chart below:

| Model | Moment N.m |
|-------------|------------|
| XBL30R-XID | 10 N.m |
| XBL60R-XID | 10 N.m |
| XBL60L-XID | 25 N.m |
| XBL150L-XID | 25 N.m |
| XBL300L-XID | 30 N.m |

Adjust the space of middle overload stop bolt. (See figure below.)

Adjust the space of spacing bolt on both ends. (See figure below.)




| Position | XBL30R-XID Overload protective gap | XBL60R-XID Overload protective gap | XBL60L-XID Overload protective gap | XBL150L-XID Overload protective gap | XBL300L-XID Overload protective gap |
|----------|--|--|--|---|---|
| A | 0.08 in. (2 mm) | 0.08 in. (2 mm) | 0.1 in. (2.5 mm) | 0.14 in. (3.5 mm) | 0.2 in. (5 mm) |
| B | 0.02 in. (0.5 mm) | 0.02in.(0.5 mm) | 0.02 in. (0.5 mm) | 0.03 in. (0.70 mm) | 0.04 in. (1 mm) |

■ SHIFT TEST AND ADJUSTMENT

The XID indicator – load cell connect and power up:

- Make connection according to this manual. Connect to indicator by power cable.
- Open the indicator enclosure.
- Set the jumper according to the manual instruction.

Make the platter of the scale upside down on the scale base, place test weight (equal to 1/3 F.S) on the four corners as in the figure shown below.



Verify the tolerance of four corners and make adjustment for shift, if necessary.

■ SETUP SCALE CAPACITY

Set the jumper according to the manual. Use a proper test weight (70% Max F.S) to setup the scale to Weighing Mode.

■ DEFLECTION TEST

Place the test weight of 1/3 F.S (maximum) on 1, 2, 3, and 4 positions successively as above figure indicates. Refer to the following tolerance table.

Note: Do NOT allow the AMZ to function during the test process.



Tolerance Table

| Model Number | Capacity | Calibrate Increment Value (e) | Tolerance |
|--------------|----------|-------------------------------|-----------|
| XBL30R-XMC | 60 lb | 0.02 lb | ± 0.02 lb |
| XBL60R-XMC | 150 lb | 0.05 lb | ± 0.05 lb |
| XBL60L-XMC | 150 lb | 0.05 lb | ± 0.05 lb |
| XBL150L-XMC | 300 lb | 0.1 lb | ± 0.1 lb |
| XBL300L-XMC | 600 lb | 0.2 lb | ± 0.2 lb |

APPENDIX

■ TROUBLESHOOTING

The XBL-XID series bench scale uses high-accuracy load cells and an indicator with stable quality and durability. If you should encounter operational difficulties, check the indicator first. Look at the error message displayed and take the suggested action referred to in the section below.

| | |
|---|--|
|  |  WARNING |
| <p>Only permitted, qualified personnel should service this equipment.</p> | |

■ ERROR MESSAGES

The XBL-XID provides self-diagnostic actions for common operational problems. The error messages detailed below will be shown when trouble or incorrect operation occurs.

| Error Message | Description | Probable Action |
|--------------------|--|---|
| E11 | RAM Error | 1. Power down the unit, then power it back up to reset the unit. 2. Replace the Controller PCB. |
| E16 | ROM Error | |
| E18 | EPROM Data Incorrect | 1. Power down the unit, then power it back up to reset the unit. 2. Replace the Controller PCB. |
| nnnnnn or nnnnn | Overload (weight on scale exceeds 9d of FS) | Remove some goods till the error message disappears. |
| uuuuu | Underload (weight on scale is below 9d of FS) | Level the scale platter, then press the ZERO/ON-OFF button. This action should return the scale to gross zero. |
| ----- | Can not capture zero | 1. Turn off the indicator and then turn it back on again when the scale is empty. 2. Recalibrate scale. 3. Replace the load cell or controller PCB. |

■ CORRECTIVE STEPS

Test Sequence

Test the adapter. The output voltage of the adapter should be 10-14VDC with no load on the scale.

Test Q1. Press down the ZERO/ON-OFF button. The IC Q1 and the pole voltage shall be 8-13VDC.

Test triode regulator. Its output should be 5DVDC.

Test the output solder bracket of triode regulator on PCB. The bracket shall short to ground.

LED on the controller PCB shall light.

Disconnect the rear display harness. The display should show OK when you turn on the unit.

Disconnect the load cell harness. The output resistance of load cell should be 350+/-4 ohm and the input resistance is 408+/-10 ohm.

Proper Action

If not, replace the adapter.

If not, replace Q1.

If not, disconnect the output pin of this triode regulator.

If not, replace this part.

If not, replace the CPU.

Replace the rear display PCB, if display not OK.

If not, replace load cell.

MODEL SPECIFICATIONS

| Model Number (Order No.) | Capacity x Increment | Platform size (inch) | Load Cell Capacity (kg) | Column Height (inch) | Shipping Weight (lb) |
|-----------------------------|-------------------------------------|-------------------------|-------------------------------|-------------------------|----------------------------|
| XBL30R-XMC | 60 lb x 0.02 lb 30 kg x 0.01 kg | 12 × 14 × 4.5 | 60 kg | 14 | 26.4 |
| XBL60R-XMC | 150 lb x 0.05 lb 60 kg x 0.02 kg | 12 × 14 × 4.5 | 150 kg | 14 | 26.4 |
| XBL60L-XMC | 150 lb x 0.05 lb 60 kg x 0.02 kg | 17 × 22 × 5.3 | 150 kg | 27 | 41.8 |
| XBL150L-XMC | 300 lb x 0.1 lb 150 kg x 0.05 kg | 17 × 22 × 5.3 | 300 kg | 27 | 41.8 |
| XBL300L-XMC | 600 lb x 0.2 lb 300 kg x 0.1 kg | 17 × 22 × 5.3 | 500 kg | 27 | 41.8 |

TECHNICAL DATA

Accuracy Grade: Designed to meet NTEP 3000d requirements.

Operation Temperature: 32°F-104°F (0° C to +40° C)

Relative Humidity: 10 to 90% humidity, non-condensing

Maximum Safe Overload: 125% F.S

Display Resolution: Up to 10000d

Power Supply: AC/DC auto conversion

AC (power adapter) Input: 120 VAC -15% to 10%

Output: 9 VDC ± 10% / 0.5 A

DC: Six C cell batteries

WIRING

9 pins D-sub for load cell is assigned as below:


| 9 Pins D-sub | Signal |
|--------------|---------------|
| 1 | - EXC (Black) |
| 2 | |
| 3 | SHIELD |
| 4 | + EXC (Red) |
| 5 | |
| 6 | |
| 7 | +SIG (Green) |
| 8 | -SIG (Yellow) |
| 9 | |

GEO VALUE TABLE


Use the following geo codes if you relocate the XBL-XID to a site other than the original location where it was calibrated.

| Northern and Southern latitude in degrees and minutes | Height above sea-level in meters | | | | | | | | | | |
|---|----------------------------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|---------------|----------------|
| | 0 325 | 325 650 | 650 975 | 975 1300 | 1300 1625 | 1625 1950 | 1950 2275 | 2275 2600 | 2600 2925 | 2925 3250 | 3250 3575 |
| | Height above sea-level in feet | | | | | | | | | | |
| | 0 1060 | 1060 2130 | 2130 3200 | 3200 4260 | 4260 5330 | 5330 6400 | 6400 7460 | 7460 8530 | 8530 9600 | 9600 10660 | 10660 11730 |
| 0° 0' — 5° 46' | 5 | 4 | 4 | 3 | 3 | 2 | 2 | 1 | 1 | 0 | 0 |
| 5° 46' — 9° 52' | 5 | 5 | 4 | 4 | 3 | 3 | 2 | 2 | 1 | 1 | 0 |
| 9° 52' — 12° 44' | 6 | 5 | 5 | 4 | 4 | 3 | 3 | 2 | 2 | 1 | 1 |
| 12° 44' — 15° 6' | 6 | 6 | 5 | 5 | 4 | 4 | 3 | 3 | 2 | 2 | 1 |
| 15° 6' — 17° 10' | 7 | 6 | 6 | 5 | 5 | 4 | 4 | 3 | 3 | 2 | 2 |
| 17° 10' — 19° 2' | 7 | 7 | 6 | 6 | 5 | 5 | 4 | 4 | 3 | 3 | 2 |
| 19° 2' — 20° 45' | 8 | 7 | 7 | 6 | 6 | 5 | 5 | 4 | 4 | 3 | 3 |
| 20° 45' — 22° 22' | 8 | 8 | 7 | 7 | 6 | 6 | 5 | 5 | 4 | 4 | 3 |
| 22° 22' — 23° 54' | 9 | 8 | 8 | 7 | 7 | 6 | 6 | 5 | 5 | 4 | 4 |
| 23° 54' — 25° 21' | 9 | 9 | 8 | 8 | 7 | 7 | 6 | 6 | 5 | 5 | 4 |
| 25° 21' — 26° 45' | 10 | 9 | 9 | 8 | 8 | 7 | 7 | 6 | 6 | 5 | 5 |
| 26° 45' — 28° 6' | 10 | 10 | 9 | 9 | 8 | 8 | 7 | 7 | 6 | 6 | 5 |
| 28° 6' — 29° 25' | 11 | 10 | 10 | 9 | 9 | 8 | 8 | 7 | 7 | 6 | 6 |
| 29° 25' — 30° 41' | 11 | 11 | 10 | 10 | 9 | 9 | 8 | 8 | 7 | 7 | 6 |
| 30° 41' — 31° 56' | 12 | 11 | 11 | 10 | 10 | 9 | 9 | 8 | 8 | 7 | 7 |
| 31° 56' — 33° 9' | 12 | 12 | 11 | 11 | 10 | 10 | 9 | 9 | 8 | 8 | 7 |
| 33° 9' — 34° 21' | 13 | 12 | 12 | 11 | 11 | 10 | 10 | 9 | 9 | 8 | 8 |
| 34° 21' — 35° 31' | 13 | 13 | 12 | 12 | 11 | 11 | 10 | 10 | 9 | 9 | 8 |
| 35° 31' — 36° 41' | 14 | 13 | 13 | 12 | 12 | 11 | 11 | 10 | 10 | 9 | 9 |
| 36° 41' — 37° 50' | 14 | 14 | 13 | 13 | 12 | 12 | 11 | 11 | 10 | 10 | 9 |
| 37° 50' — 38° 58' | 15 | 14 | 14 | 13 | 13 | 12 | 12 | 11 | 11 | 10 | 10 |
| 38° 58' — 40° 5' | 15 | 15 | 14 | 14 | 13 | 13 | 12 | 12 | 11 | 11 | 10 |
| 40° 5' — 41° 12' | 16 | 15 | 15 | 14 | 14 | 13 | 13 | 12 | 12 | 11 | 11 |
| 41° 12' — 42° 19' | 16 | 16 | 15 | 15 | 14 | 14 | 13 | 13 | 12 | 12 | 11 |
| 42° 19' — 43° 26' | 17 | 16 | 16 | 15 | 15 | 14 | 14 | 13 | 13 | 12 | 12 |
| 43° 26' — 44° 32' | 17 | 17 | 16 | 16 | 15 | 15 | 14 | 14 | 13 | 13 | 12 |
| 44° 32' — 45° 38' | 18 | 17 | 17 | 16 | 16 | 15 | 15 | 14 | 14 | 13 | 13 |
| 45° 38' — 46° 45' | 18 | 18 | 17 | 17 | 16 | 16 | 15 | 15 | 14 | 14 | 13 |
| 46° 45' — 47° 51' | 19 | 18 | 18 | 17 | 17 | 16 | 16 | 15 | 15 | 14 | 14 |
| 47° 51' — 48° 58' | 19 | 19 | 18 | 18 | 17 | 17 | 16 | 16 | 15 | 15 | 14 |
| 48° 58' — 50° 6' | 20 | 19 | 19 | 18 | 18 | 17 | 17 | 16 | 16 | 15 | 15 |
| 50° 6' — 51° 13' | 20 | 20 | 19 | 19 | 18 | 18 | 17 | 17 | 16 | 16 | 15 |
| 51° 13' — 52° 22' | 21 | 20 | 20 | 19 | 19 | 18 | 18 | 17 | 17 | 16 | 16 |
| 52° 22' — 53° 31' | 21 | 21 | 20 | 20 | 19 | 19 | 18 | 18 | 17 | 17 | 16 |
| 53° 31' — 54° 41' | 22 | 21 | 21 | 20 | 20 | 19 | 19 | 18 | 18 | 17 | 17 |
| 54° 41' — 55° 52' | 22 | 22 | 21 | 21 | 20 | 20 | 19 | 19 | 18 | 18 | 17 |
| 55° 52' — 57° 4' | 23 | 22 | 22 | 21 | 21 | 20 | 20 | 19 | 19 | 18 | 18 |
| 57° 4' — 58° 17' | 23 | 23 | 22 | 22 | 21 | 21 | 20 | 20 | 19 | 19 | 18 |
| 58° 17' — 59° 32' | 24 | 23 | 23 | 22 | 22 | 21 | 21 | 20 | 20 | 19 | 19 |
| 59° 32' — 60° 49' | 24 | 24 | 23 | 23 | 22 | 22 | 21 | 21 | 20 | 20 | 19 |
| 60° 49' — 62° 9' | 25 | 24 | 24 | 23 | 23 | 22 | 22 | 21 | 21 | 20 | 20 |
| 62° 9' — 63° 30' | 25 | 25 | 24 | 24 | 23 | 23 | 22 | 22 | 21 | 21 | 20 |
| 63° 30' — 64° 55' | 26 | 25 | 25 | 24 | 24 | 23 | 23 | 22 | 22 | 21 | 21 |
| 64° 55' — 66° 24' | 26 | 26 | 25 | 25 | 24 | 24 | 23 | 23 | 22 | 22 | 21 |
| 66° 24' — 67° 57' | 27 | 26 | 26 | 25 | 25 | 24 | 24 | 23 | 23 | 22 | 22 |
| 67° 57' — 69° 35' | 27 | 27 | 26 | 26 | 25 | 25 | 24 | 24 | 23 | 23 | 22 |
| 69° 35' — 71° 21' | 28 | 27 | 27 | 26 | 26 | 25 | 25 | 24 | 24 | 23 | 23 |
| 71° 21' — 73° 16' | 28 | 28 | 27 | 27 | 26 | 26 | 25 | 25 | 24 | 24 | 23 |
| 73° 16' — 75° 24' | 29 | 28 | 28 | 27 | 27 | 26 | 26 | 25 | 25 | 24 | 24 |
| 75° 24' — 77° 52' | 29 | 29 | 28 | 28 | 27 | 27 | 26 | 26 | 25 | 25 | 24 |
| 77° 52' — 80° 56' | 30 | 29 | 29 | 28 | 28 | 27 | 27 | 26 | 26 | 25 | 25 |
| 80° 56' — 85° 45' | 30 | 30 | 29 | 29 | 28 | 28 | 27 | 27 | 26 | 26 | 25 |
| 85° 45' — 90° 00' | 31 | 30 | 30 | 29 | 29 | 28 | 28 | 27 | 27 | 26 | 26 |

PHYSICAL DIMENSIONS



Model: XBL30R-XID, XBL60R-XID



Model: XBL60L-XID, XBL150L-XID, XBL300L-XID

Notes

Notes

Xpress

Mettler-Toledo, Inc.
60 Collegeview
Westerville, OH 43081

5/2004

MTX04-OM044.1E