Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course! Shop online at www.omega.com

ł

- **TEMPERATURE** Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies Wine: Thermocouple, RTD & Thermistor Wine: Thermocouple, RTD & Thermistor Recorders, Controllers & Process Monitors Recorders, Controllers & Process Monitors Infrared Pyrometers

- PRESSURE, STRAIN AND FORCE Parasducers & Strain Gages Parad Cells & Pressure Gages Poispacement Transducers Poispacement Transducers Paratory Instrumentation & Accessories

- FLOW/LEVEL Renameters, Gas Mass Flowmeters & Flow
- Computers Air Velocity Indicators Turbine/Paddlewheel Systems Pr Totalizers & Batch Controllers

Ψ

- pH/CONDUCTIVITY Per pH Electrodes, Testers & Accessories Ge Benchtsp:/Laboratory.Meters Ge Controllers, calibandors, Simulators & Pumps Ge Controllers, calibandors, Simulators & Pumps Ge Industrial pH & Conductivity Equipment
- DATA ACQUISITION Data Acquisition & Engineering Software Communications-Based Acquisition Systems Phug-in Cards for Apple, IBM & Compatibles Datalogging Systems P Datalogging Systems Recorders, Printers & Plotters

- HEATERS P. Heating Cable P. Cartridge & Ship Heaters P. Immersion & Band Heaters P. Flexible Heaters P. Laboratory Heaters

- ENVIRONMENTAL MONITORING AND CONTROL Refractionates Refractioneters Air, Soil & Water Monitors Ir Industrial Water & Wastewater Treatment Ir Industrial Water & Wastewater Treatment Prindustrial Water & Wastewater Streatment Prindustrial Water & Wastewater Treatment Prindustrial Water & Wastewater Treatment

Type K Thermometer

M3652/0401

ļ

2



-(

CONTENTS

4.8 Low Battery Condition	4.7 Auto Power Off	4.6 MAX/MIN/AVG Operation7	4.5 Relative Operation6	4.4 Data-Hold Operation6	4.3 Selecting the Temperature Unit	4.2 Connection the Thermocouples	4.1 Power-Up 6	IV. Operation Instructions	Location	lll. Symbol Definition and Button	II. Specifications	I. Introduction	TITLE P
			6			6				'n	3	З	PAGE

I. Introduction:

THERMOMETER

This instrument is a digital thermometer for use with any K-type thermoccuple as temperature sensor. Temperature indication follows National Bureau of Standards and IEC584 temperature/voltage table for K-type thermoccuples.

II. Specifications: Resolution: -200°C - 200°C 0.1°C ; 200°C -1370°C 1°C -200°F - 200°F 0.1°F ; 200°F -2498°F 1°F Maximum Voltage at Thermocoupie Input: 60V DC, or 24Vrms AC Environmental: Operating Temperature and Humidity; 0°C -50°C (32°F - 122°F); 0 ~ 80% RH Storage Temperature and Humidity: -10°C to 60°C (14°F - 140°F); 0 ~ 80% RH Altitude up to 2000 meters.

Dimension: 164×54×34mm Sample Rate: 0.6 times per second Weight: Approx.180g

Power requirement: 9 Volt Battery, NEDA 1604 or JIS 006P or IEC6F22 Approx. 150hrs with alkaline battery Battery Life: K Type Bead Probe, Battery, Instruction Menu Accessory:

ŝ

بر بر

.

•

THERMOMETER

THERMOMETER

Accuracy: at (23 ± 5°C)

Range	Accuracy
-200°C ~ 200°C	±(0.3% reading + 1*C)
200°C ~ 400°C	±(0.5% reading + 1°C)
400°C-1370°C	±(0.3% reading + 1*C)
-328°F ~ -200°F	±(0.5% reading + 2°F)
-200°F ~ 200°F	±(0.3% reading + 2°F)
200°F ~ 400°F	±(0.5% reading + 2°F)
400°F ~ 2498°F	±(0.3% reading + 2*F)

Temperature Coefficient:

spec. 0.01% of reading + 0.03°C (0.01% of reading + 0.06°F) For ambient temperatures from $0^{\circ}C \sim 18^{\circ}C$ and $28^{\circ}C \sim 50^{\circ}C$, for each °C ambient below $18^{\circ}C$ or above 28°C add the following tolerance into the accuracy

∆ Note:

The basic accuracy Specification does not include the error of the probe please refer to the probe accuracy specification for additional details.

Ill. Symbol Definition and Button Location:





9 T1 K type temperature sensor connector
9 T2 K type temperature sensor connector
9 LCD display
4 ON/OFF button
9 MAX MIN Average control button
9 HOLD button

⑦ Relative readout button

"C, "F control button
 "

Offset calibration screw

Battery cabinet cover

S

4

×.

.

IV. Operation Instructions:

4.1 Power-Up

- Press the ① key to turn the thermometer On or OFF. 4.2 Connection the Thermocouples
- For measurement, plug the thermocouple into the input connectors.
- 4.3 Selecting the Temperature Unit When the meter was power on, the default
- When the meter was power on, the default unit is Celsius (°C) scale. The user may change it to Fahrenheit (°F) by pressing ' •C/°F ' button and vice versa to Celsius.

4.4 Data-Hold Operation

The user may hold the present reading and keep it on the display by pressing the "HOLD" button. When the hold data is no longer needed, one may release the data-hold operation by pressing "HOLD" button again. When the meter is under Data Hold operation, the "∆REL",MAXJMIN and - "C/"F" button are disabled.

4.5 Relative Operation:

When one press the "AREL" button, the meter will memorize the present reading and the difference between the new reading and the memorized data will be shown on the display. Press the "AREL" button again to exit the Relative operation.

4.6 MAX/MIN Operation:

When one press the MAX/MIN button the meter will enter the MAX/MIN mode. Under this mode the maximum value and minimum value is kept in the memory simultaneously and updated with every new data.

When the MAX symbol is display, the Maximum is shown on the display.

Press MAX/MIN again, then the MIN symbol is on the display and also the minimum reading.

resplay and asso the minimum reading. Press MAX/MIN again, MAX, MIN will blink together. This means that all these data is updated in the

> mode among these options. When the meter is under MAX/MIN operation, "∆ REL" and " "C/"F" are disabled.

memory and the reading is the present temperature. One may press MAX/MIN to circulate the display

THERMOMETER

To exit the MAX/MIN mode, one may press and hold MAX/MIN for two seconds.

4.7 Auto Power Off:

By default, when the meter is powered on, it is under auto power off mode. The meter will power lisself off after 30 minutes if no key operation is performed. Key combination at power on can disable auto power off. One may press and hold "HOLD" button and then power on the meter and auto power off symbol will disappear to indicate that auto power off is disabled.

4.8 Low Battery Condition

When the battery voltage is under proper operation requirement, the **CD** symbol will show on the LCD and the battery need to be replaced with new one.

4.9 Calibration Point:

 Room Temperature 23 ± 3°C

 Input
 Adjust VR
 tolerance

 0 °C
 VR3
 ± 0.1 °C

 190 °C
 VR2
 ± 0.1 °C

 1000 °C
 VR1
 ± 1 °C

 190 °F
 VR4
 ± 0.1 °F

 Normally, performing offset Calibration with thermal stabled ice water through VR3 will give a very good calibration result.
 very good

9

-

omega.com

		1
WWW.omera.com	OMEGAnet [#] On-Line Service	
info@omega.com	Internet e-mail	

Servicing North America:

Canada:	USA: ISO 9001 Centified	
976 Bergar	One Omega Drive, Box 4047 Stamford CT 06907-0047 Tel: (202) 359-1660 e-mail: info@omega.com	

Tel: (514) 856-6928	Laval (Quebec) H7L 5A1	976 Bergar
FAX: (514) 856-6886		

For immediate technical or application assistance: e-mail: info@omega.ca

USA and Canada: Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA* Customer Service: 1-800-822-8278 / 1-800-622-8EST Engineering Service: 1-800-822-9456 / 1-800-USA-WTEN TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

En Español: (001) 203-359-7803 e-mail: espanol@omega.com FAX: (001) 203-359-7807 info@omega.com.mx

Servicing Europe:

Postbus 8034, 1180 LA Amstelveen. The Netherlands Tel: +31 (0)20 3472121 Tel: +31 (0)20 3472121 Toll Free in Benelucu: 0800 0993344 e-mail: nl@omega.com

۱

Benelux:

Mexico:

France: Czech Republic: Rudé armády 1868, 733 01 Karviná 8 Tel: +420 (0)69 6311899 FAX: +420 (0)69 6311114 Toll Free: 0800-1-66342 e-mail: czech@omega.com 9, neu Ennis Papin, 78190 Trappes Tel: +33 (0)130 621 400 FAX: +33 (0)130 699 120 Toll Free in France: 0800-406342 e-mail: france@comega.com

Germany/Austria: Daimkerstrasse 26, D-75392 Deckenpfronn, Germany Tel:+ 49 (0)7056 9398-0 FAX: +49 (0)7056 9398-29 Toll Free in Germany: 0800 639 7678 e-mail: germany@omega.com

United Kingdom: One Omega Drive, River Bend Technology Centre ISO 9002 Centred M44 58D United Kingdom Tel: +44 (0)161 777 6611 FAX: +44 (0)161 777 6622 Toll Free in United Kingdom: (800)-488-488 e-mail: sales@omega.co.uk

It is the policy of CMEGA to comply with all worldwide safety and EMCEMI regulations that European New Apcontainty further that the CE mark to every appropriate device upon certification. OMEGA will add the CE mark to every appropriate device upon certification. The information contained in this document is believed to be correct, but OMEGA Engineering, inc. accepts no liability for any errors it contains, and veenvest the right to alter specifications whole more than a should not be used to patient to alter specifications whole more than a should not be used NUMAG. These products are not designed for use in, and should not be used to patientic connected applications:

OMEGA ENGINEERING, INC, warrans this unit to be free of defects in mannials and workmanning for a period of 13 months from date of purchase. OMEGA: VIARANYY acids an additional core (1) months from date of the normal one (1) year product warrance to cover handling and hipping line. The ensure that OMEGA's customer reserve maximum overage on each product that OMEGA's customer reserve maximum overage on each product **WARRANTY/DISCLAIMER**

The unit vince of a service Department will insue an unitarity vince.
Office unit vunce is a service Department will insue an unitarity department will insue an unitarity of the unita

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor with all to be used; (1) as a "Basic Component" under (1) CFR 21 (MRC), used in or with any nuclear installation or sethity; or (2) in medical septiations or used on homans. Should application, used on homans, or muthany michael installation or sethity; or advanta application, used on homans, or muthany michael installation or sethity; or regional application, used on homans, or muthany and the set of the set of the or septimentary of the set of the production of any liability of damage whatseever areing out of the use of the Production in such a memorie.

Direct all warranty and repair requestivinguities to the OMECA Customer Service. Department, BEFORE RETUNNING ANY PRODUCTIST TO OMEGA. PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (UR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEFARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The savigned AR number should than be maked on the outside of the return package and on any correspondence. The purchaser is responsible for ehipping charges, freight, insurance and proper packaging to prevent breakage in transit. **** RETURN REQUESTS / INQUIRIES ****

FOR **WAARAANTY** RETURNS, please have the following information available BEFORE contacting OMEGA: by problems relative to the product. 2. Model and serial number of the problems relative to the product. 3. Repair instructions and/or specific problems relative to the product.

OMEGA"s policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering. OMEGA is registered trademark of OMEGA EGINEERING, INC. OMEGA is registered trademark of OMEGA EGINEERING, INC. © Copyright 2000 OMEGA ENGLOEERING, INC. All rights reserved. This docu-ment may not be copied, photocopied, reproduced, translated, or reduced to any sectoric mediumer machine-adable form in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.