# User manual ALFA 71 spec. Thermostat.



 VDH doc. 080882
 Version: v1.0
 Date: 13-06-2008

 Software: ALFA71S1
 File: Do080882.WPD
 Range: -50/+50,0°C

#### \* Installation.

On the upperside of the **ALFA 71 spec.** is shown how the sensor, supply, relays and the analogue output have to be connected.

After power up a self test is started. After this self test is completed the **ALFA 71 spec.** will show the measured temperature.

#### \* Control.

The **ALFA 71 spec** thermostat can de controlled by four push buttons on the front.

**SET** - viewing / changing the adjusted value and reset alarm.

UP - raise the adjusted value.

DOWN - lower the adjusted value.

°C - hidden key above the SET key.

#### \* Viewing the set point.

By pushing the **SET** key the adjusted set point will be shown. A few seconds after releasing the **SET** key the measured value will be shown again.

#### \* Changing the set point.

Push the **SET** key so the set point will appear on the display. Release the **SET** key. By pushing the **SET** key again simultaneously with the **UP** or **DOWN** key the adjusted set point can be changed. A few seconds after releasing the keys the measured value will be shown again.

#### \* Status from the Relays.

By pushing the °C key the display shows the status of the relays. Each digit shows the status of one relay output, showing 0=off and 1=on. The code 110 means relay 1 and 2 are on and relay 3 is off.

#### \* Adjusting internal parameters.

Next to the adjustment of the set point, internal settings can be made like differential, sensor offset, set point range and the functions of the thermostat.

Push the **DOWN** key for more than 10 seconds, to enter the 'Internal Programming Menu'. In the left display the upper and lower segment are blinking. Over the **UP** and **DOWN** keys the required parameter can be selected (see table for the parameters).

If the required parameter is selected, the value can be read-out by pushing the **SET** key. Pushing the **UP** or **DOWN** key to change the value of this parameter.

If 20 seconds no key is pushed, the ALFA 71 spec. changes to the normal operation mode.



#### \* Adjusting the sensor.

The sensor can be adjusted by using the Sensor Offset parameter 05. Indicates a Sensor e.g. 2°C to much, the according Sensor Offset has to be decreased with 2°C.

#### \* Error codes.

On the display from the **ALFA 71 spec.** can appear the following error codes:

LO - Minimum alarm. HI - Maximum alarm.

**E1** - Sensor failure. Solution:

- Check if the sensor is connected well. - Check the sensor (1000 $\Omega$ /25°C).

- Replace the sensor.

**EEE** - Adjustments are lost. Solution:

- Reprogram the adjustments.

#### Working Alarm.

If an error code occurs it can be reset with the **SET** key. The function from this key depends on parameter P37.

#### \* Technical details.

Type : ALFA 71 spec. Thermostat

Range : -50/+50,0°C, above -10°C read out per 0,1°C

Supply : 12Vac 50/60Hz (-5/+10%) Read out : 3-digit 7-segments display

Status Led : LED 'SET'

Relays : Ry1= SPST(NO) 250V/8A ( $\cos \phi = 1$ ) of 250V/5A ( $\cos \phi = 0.4$ )

Ry2= SPST(NO) 250V/8A ( $\cos \varphi$ =1) of 250V/5A ( $\cos \varphi$ =0.4) Ry3= SPDT(NO/NC) 250V/8A ( $\cos \varphi$ =1) of 250V/5A ( $\cos \varphi$ =0.4)

Relays have one common (C). : Through push buttons on the front.

Control : Through push button Front : Polycarbonate IP65

Sensor : SM 811/2m (PTC  $1000\Omega/25^{\circ}$ C). Analogue output : 0...10Vdc measure output. Dimensions :  $35 \times 77 \times 71,5$ mm (hwd)

Panel cut out : 28 x 70mm (hw) Accuracy : ± 0,5% from the range.

- Provided with memory protection during power failure.
- Connections with screw terminals on the back side.
- Equipped with sensor failure detection.
- Special versions on request available.




# \* Parameters ALFA 71 spec.


Para-	Description Parameter	Range	Default
Meter			value
01	Function Relay 1	1=Cooling	1
		2=Heating	_
		3=Alarm	
00	For this Palace O		•
02	Function Relay 2	1=Cooling	2
		2=Heating	
		3=Alarm	
03	Function Relay 3	1=Cooling	3
		2=Heating	
		3=Alarm	
05	Offset temperature sensor 1	-15.0+15.0°C	0.0
06	Analogue output 0V at temperature	-50+50°C	-50.0
07	Analogue output 10V at temperature	-50+50°C	+50.0
07	Analogue output 10v at temperature	-30+30 C	+50.0
10	Switching stage 2 on	0=Temperature	0
		1=Time	
11	Switching stage 3 on	0=Temperature	0
		1=Time	
12	Switch on delay stage 2	099 min.	15
13	Switch on delay stage 3	099 min.	15
14	Switching differential relay 1	0.115.0	0.5
15	Offset relay 1	-15+15	0.0
16	Switching differential relay 2	0.115.0	0.5
17	Offset relay 2		
		-15+15	0.0
18	Switching differential relay 3	0.115.0	0.5
19	Offset relay 3	-15+15	0.0
20	Switch on delay cooling	099	0
21	Switch off delay cooling	099	0
22	Parameter 20/21 in sec. of min.	0=seconds	0
		1=minutes	
23	Minimum on time cooling	099 min.	0
24	Minimum off time cooling	099 min.	0
25	Minimum adjustable set point	-50.0+50.0°C	-50
26	Maximum adjustable set point	-50.0+50.0°C	+50
27	Read out above -10°C on whole degrees	0= No	0
		1= Yes	
30	Type Alarm	0= Non	1
		1= Absolute	
		2= Relative	
31	Minimum alarm set point	-50.0+50.0°C	-50
32	Maximum alarm set point	-50.0+50.0°C	+50
33	Time delay minimum alarm	099 min.	0
34	Time delay maximum alarm	099 min.	0
35	Relay function alarm relay	0= fail safe alarm	0
		1= control alarm	
36	Reset alarm relay after recovering alarm	0= No	0
		1= Yes	
37	Reset alarm relay after manual reset	0= No	0
		1= Yes	
40	Control delay after power failure	099 min.	0
41	Forced relay function at sensor failure	0= Non	Ö
		1= Cooling	_
		2= Heating	
0.5	Software version	0255	
95			0
	Production year	0099	0
96		1	
97	Production week	152	1
		152 0255 0999	1 0 0




## \* <u>Dimensions.</u>



# \* connections.





## \* Address.

VDH Products BV Produktieweg 1 9301 ZR Roden The Netherlands Tel: +31 (0)50 - 30 28 900 Fax: +31 (0)50 - 30 28 980 Email: info@vdhproducts.nl Internet: www.vdhproducts.nl

