

Table of Contents

C	hapter 1 Introduction	1
	Downhole Corrosion Monitoring System (DCMS)	1
	Downhole Tool (DHT)	1
	Instrument Body	5
	Instrument Tube Assembly	5
	Probe Assembly	5
	Probe Shield	5
	Probe Adapter	
	Mounting Head Adapter	5
	Battery Assembly	
	CORRDATA® Mate	6
	Mate Reprogramming Utility	7
	CORRDATA® Plus Software	
	Battery Depassivation Instrument	8
	Probe Monitor	
	Cross-Flow Adapter	
	Running Tools	
C	hapter 2 Specification	
	Downhole Tool Specification	
	Battery Assembly Specification	
	DHT Operating Duration:	
C	hapter 3 DHT Operational Pretest	
	Assembly Sequence	
	Disassembly Sequence	22
C	hapter 4 DHT Assembly	25
	Recommended Tools	25
	Assembly Sequence	26
	Disassembly Sequence	
A	ppendix A Lithium Thionyl Chloride Batteries: Handling, Storage, MSDS	
	Emergency Procedures	43
	Emergency Conditions	43
	Causes of Hazardous Conditions	
	Electrical and Physical	43
	Safe Storage	
	Safe Incoming Inspection	
	Safe Testing	44
	Safe Transportation	45
	Safe Disposal	46

Figures and Drawings

Figure					
Figure 1.1	Cross-Sectional View of Fully Assembled DHT	2			
Figure 1.2	DHT Carrying Case Layout	4			
	DCMS Tool Kit				
Figure 4.1	DHT Assembly Drawing	26			
	Mounting Head Adapter O-Ring and Back-Up Ring Placement				
Figure 4.3	Probe Adapter O-Ring and Back-Up Ring Placement	28			
Figure 4.4	Probe Assembly Attached to Probe Adapter	30			

Chapter 1 Introduction

Downhole Corrosion Monitoring System (DCMS)

The RCS Downhole Corrosion Monitoring System (DCMS) is the only system which provides continuous corrosion history of downhole tubing. The DCMS is a specific adaptation of the CORRDATA system for the severe downhole environment and provides an accurate means of determining corrosion rates at various depths within a well bore. The corrosion data provided by the DCMS permits quantitative evaluation of inhibitors and treatment regimes for the most cost-effective results.

The DCMS consists of the following major components:

Downhole Tool (DHT)
CORRDATA Mate
CORRDATA® Plus Software
DHT Communications Adapter
Battery Depassivation Instrument
Probe Monitor Instrument
Cross-Flow Adapter (Customer Supplied)

Downhole Tool (DHT)

The Downhole Tool (DHT) is a tubular electronic instrument, as shown in Figure 1.1, that is designed to be run and retrieved by wire line operation into the production tubing of a well for an extended period of time. The DHT uses a CORROSOMETER Probe Element to determine the rate of metal loss within the well bore. The Probe Element is electrically isolated from the rest of the tool and the well bore to prevent galvanic corrosion from influencing measurement data. The Probe Element is made from the same or similar type material as the well bore being monitored. The DHT itself with 1.25" diameter provides a very small percentage restriction in the pipe. The Cross-Flow adapter and tubing lock from which the DHT is suspended provides the main flow restriction of approximately 50% area on the pipe. An RTD temperature sensor, internal to the DHT provides temperature data.

The DHT electronically measures the Probe Assembly and temperature sensor at user programmable intervals, and stores each reading in nonvolatile memory. Upon retrieval of




Figure 1.1 Cross-Sectional View of Fully Assembled DHT

the DHT, corrosion and temperature data may be downloaded to the CORRDATA Mate. The data may then be transferred from the Mate to a personal computer, containing the CORRDATA Plus Software, for analysis.

The DHT consists of the following major components:

Instrument Body
Instrument Tube Assembly
Probe Assembly
Probe Shield
Probe Adapter
Mounting Head Adapter
Battery Assembly

When not in use, the DHT and other DCMS components may be stored in a protective carrying case. The arrangement of the carrying case is shown in Figure 1.2.




Figure 1.2 DHT Carrying Case Layout

Instrument Body

The Instrument Body is normally a 17-4 PH ferritic stainless steel tube designed to contain and protect the main components of the DHT from the hostile environment of the well.

Instrument Tube Assembly

The Instrument Tube Assembly is a stainless steel tube approximately 1.25"dia. x 18"L. It has a large probe connector at one end and a small battery connector at the other end. The Instrument Tube Assembly contains electronic circuitry which accurately measures the Probe Element and internal temperature sensor.

Probe Assembly

The Probe Assembly is a specially modified CORROSOMETER probe. The Probe Assembly contains an element made from the same or similar material as the well bore. A reference element of the same material is contained within the Probe Assembly to compensate for resistance changes due to temperature. Since the Probe Assembly is very delicate, care must be taken to avoid damage.

<u>WARNING!</u> The tip of the Probe Assembly is extremely sharp. Handle with care to avoid injury or damage.

Probe Shield

The Probe Shield is used to protect the Probe Assembly from damage and debris in the well, and provide as smooth a flow as possible over the Probe Element surface. The Probe Shield slides over the Probe Assembly and is threaded onto the Probe Adapter.

Probe Adapter

The Probe Adapter is a fitting used to adapt the Probe Assembly to the Instrument Body.

Mounting Head Adapter

The Mounting Head Adapter is a fitting equipped with a 5/8" API sucker rod connection (Spec. 11B). The Mounting Head Adapter is used to attach the Cross-Flow Adapter to the Instrument Body.

Battery Assembly

<u>WARNING!</u> Violent explosion, fire and severe burn hazards. Do not short circuit, recharge, disassemble, overheat, incinerate, or expose contents to water. Refer to Appendix A for handling and storage information.

<u>CAUTION!</u> An internal fuse in the Battery Assembly may open if the Battery Assembly terminals are short circuited or if current in excess of 1 Amp is otherwise produced externally.

CAUTION! A new Battery Assembly must be depassivated immediately prior to use.

The Battery Assembly is a custom engineered, lithium thionyl chloride battery used to provide easy assembly and long life downhole. The Battery Assembly contains a coaxial connector which mates directly with the small connector on the Instrument Tube Assembly.

A new, depassivated Battery Assembly must be used before installing the DHT in a well. Battery Assemblies are **not rechargeable!** Do not attempt to defeat the safety connector at the end of a Battery Assembly. Battery Assemblies are protected with an internal fuse, but **may explode** if either recharged or short circuited, **especially at high temperatures!**

Be sure to read the paragraph titled "Battery Depassivation Instrument" in Chapter 3 before installing the battery pack. Also refer to Appendix A at the end of this manual for safe handling and storage of lithium thionyl chloride batteries.


CORRDATA® Mate

Operation of the CORRDATA Mate (herein referred as simply "Mate") with the DHT is almost identical to that with an RDC. The Mate's baud rate must be set to 300 to communicate with the DHT and then reset to 9600 baud to communicate with the PC. A DHT Communications Adapter is supplied as part of the DCMS to allow data transfer between the DHT and the Mate.


To change the Mate baud rate, switch **ON** the Mate. After the self test screen clears and the main menu appears.

ROHRBACK COSASCO SYSTEMS


Read Disp Dump SetUp



Press **Read** (F1); **MODE** (F2) to display the screen.



Press Baud (F2) to display.



Press **300** (F1) for the DHT. The Mate will automatically shut off and restart with the Baud rate changed.

CAUTION! Remember to repeat the procedure and set the Baud rate to 9600 to communicate with the PC.

Mate Reprogramming Utility

This reprogramming utility is only required if for any reason the Mate software program has become corrupted. This program utility in the CORRDATA Plus installation disk operates

through the normal connection cables to the Mate to reload the Mate software program.

To run this utility, plug the Mate into the PC with the serial adapter cable (P/N 748063). Run the CORRDATA Plus Installation CD by inserting it into the CD-ROM. Click the "Mate Programming Utility" link and choose "Install". Follow the PC prompts to install the utility. Once the utility is successfully installed, run the application from **Start** → **All Programs** → **Rohrback Cosasco Systems** → **Mate Programming Utility**. The PC will display the instructions of keys to press on the Mate. In most cases, the user will be able to successfully re-program the Mate using the "Quick Mode." This re-programs the Mate without losing any of the stored data.

NOTE: If the Mate program has been severely corrupted, "Complete Mode" must be run. In this case, repeat above steps and select "Complete Mode" and follow the wizard instructions to complete the programming.

CORRDATA® Plus Software

The CORRDATA Plus Software is supplied with the Mate. Please refer to the CORRDATA Plus Corrosion Management Solutions Manual on the CD-ROM for details.

Battery Depassivation Instrument

A new Battery Assembly must be depassivated just prior to use in order to remove a passivation layer that naturally inhibits energy transfer from the Battery Assembly to the DHT electronics. The depassivation procedure requires that a Battery Depassivation Instrument (P/N 724023) be connected to the Battery Assembly for a period of time.

The Battery Depassivation Instrument initially loads the Battery Assembly to begin depassivation. It then monitors the output voltage of the Battery Assembly, under load, until it rises to an acceptable level. While the Battery Assembly is being depassivated a yellow lamp on top of the Battery Depassivation Instrument will remain illuminated. When the depassivation process is complete, the yellow lamp will extinguish and a flashing green lamp will illuminate. The Battery Assembly is now ready for immediate use. The depassivation procedure should not last more than 60 minutes. The Battery Depassivation Instrument provides test terminals to monitor the battery voltage with an external voltmeter.

Probe Monitor

To confirm that the Downhole Tool (DHT) is functioning correctly, after complete assembly, a non-intrusive Probe Monitor (P/N 724024) has been designed. The Probe Monitor continuously monitors the voltage across the Probe Element and detects when the probe is energized. Counting these events provides high confidence that the DHT is functioning

properly. Since the DHT performs periodic measurements based on a programmed cycle time, a countdown timer has been provided in the Probe Monitor to indicate when the next probe measurement will be made.

When the DHT performs a measurement of the Probe Assembly, the probe is actually energized for two consecutive intervals, each lasting about 3 seconds. There is about 5 seconds duration between these intervals where the probe is not energized. The two intervals have been named CYCLE ONE and CYCLE TWO. The Probe Monitor indicates which cycle is presently occurring during the measurement. Both cycles must be measured before the Instrument will decrement the countdown timer.

The countdown timer should be accurate to within a few seconds of actual DHT measurements as long as the cycle time for the Probe Monitor is the same as the DHT configured cycle time. The Probe Monitor is powered by a 9V battery. Alkaline or lithium batteries are recommended. The Probe Monitor will operate for approximately 24 hours continuously with a fresh alkaline battery (longer with a lithium battery). The Probe Monitor may not store the total number of DHT measurements made if the battery is completely depleted.


Cross-Flow Adapter

A Cross-Flow Adapter is attached to the Mounting Head Adapter end of the DHT. While holding the DHT in the center of the production tubing, the Cross-Flow Adapter serves to transfer the well bore flow from the outside of the DHT to the inside of the lock mandrel. The Cross-Flow Adapter must minimize pressure drop as well as provide the strength required to support the DHT. Typically, a Cross-Flow Adapter will drop only a few psi. The DHT is capable of mounting on a variety of lock systems. The lock mandrel and Cross-Flow Adapter are usually customer specific items, and are chosen or manufactured to be compatible with the wire line running tools to be used.

Running Tools

Running Tools and running procedures are critical to the successful operation of the DCMS system. Consultations between RCS, the customer, and the wire line company are required to ensure correct tools are available and correct running procedures are used.

RCS offers a custom DCMS Tool Kit (P/N: 724005) to provide for the complete assembly and disassembly of the DHT. In addition to mechanical tools, four custom electronic instruments are included which are necessary to setup and monitor the DHT. The contents and layout of the DCMS' Tool Kit are shown in Figure 1.3.



Figure

Chapter 2 Specification

Downhole Tool Specification

◆ Environment: Oil, Gas, Water production (Sweet or Sour Service subject to

running tool specifications)

◆ Shock: 30 G's Max

♦ Random Vibration: 30 to 300 Hz at 2.22 G²/Hz, 25 G rms

♦ Temperature: 285°F (140°C) maximum

♦ Pressure: 10,000 psi (69 MPa) maximum

◆ Flow Velocity: 90 feet per second maximum gas flow, 20 feet per second

maximum liquid flow

♦ Body Material (Standard): UNS S17400 (17-4 S.S.) Conforming to NACE MR0175

CORROSOMETER Probe Assembly:

Repeatability: ± 0.5% of Span Resolution: 0.1% of Span

♦ Temperature Sensor: Accuracy: ± 3°F

Repeatability: ± 3°F Resolution: 0.1°F

Memory Capacity: 1024 Measurements via CORRDATA Mate

Measurement Intervals (programmable):

15 min., 30 min., 1 hr., 2 hr., 4 hr.

◆ Thread Attachment: 5/8" API Sucker Rod Connection

Spec. 11B

Battery Assembly Specification

◆ RCS Part No.: 724088

◆ Type: Lithium Thionyl Chloride

◆ Li Weight: 7.4 grams

♦ Voltage: 7.32 Voc (open circuit)

◆ Operating Temp: +20 °C to +180 °C

♦ Shock: 250 G's Max at 150 °C

◆ Random Vibration: 30 to 300 Hz at 2.22 G²/Hz

25 Grms

DHT Operating Duration:

DHT Programmed Measurement Interval	Approximate Operating Time (with a new Battery Assembly)
1 hr.	60 days
2 hr.	65 days
4 hr.	70 days

Chapter 3 DHT Operational Pretest

The user may wish to determine that the Instrument Tube Assembly, Probe Assembly and Battery Assembly are operational before complete assembly of the DHT. A Pretest may be performed by following the steps below:

<u>WARNING!</u> Always perform a Pretest at "room temperature". Do not perform a Pretest at temperatures above 125 °F.

It is highly recommended that new batteries are used on the DHT Communications Adaptor and the Probe Monitoring Tool before a new session.

Assembly Sequence

Step 1: Depassivate New Battery Assembly:

<u>WARNING!</u> Use only the RCS supplied Depassivation Instrument (P/N 724023) to depassivate the battery and verify voltage.

<u>NOTE:</u> The Battery Depassivation Instrument is used in this step. It automatically monitors the Battery Assembly output voltage while applying a nominal load. The Battery Depassivation Instrument will remove the load when the output voltage of the Battery Assembly reaches a value which indicates that the passivation has been adequately removed.

<u>WARNING!</u> A new Battery Assembly must be depassivated less than four hours prior to connecting it with the Instrument Tube Assembly. Refer to Chapter 1 and Appendix A for Battery Assembly warnings and cautions.

- 1. Verify that the ambient temperature and the Battery Assembly Temperature is greater than or equal to 21 °C (70 °F).
- 2. If desired, monitor the voltage between the red and black terminals on the Battery Depassivation Instrument with a high impedance voltmeter.
- Connect the Battery Assembly to the Battery Depassivation Instrument. The yellow lamp will illuminate immediately. Depending on the degree of battery passivation, the battery voltage may initially drop below 5.0V.

<u>CAUTION!</u> If no status lamps on the Battery Depassivation Instrument are illuminated while the Battery Assembly is connected, then the Battery Assembly is either excessively passivated or depleated and should not be used.

4. Monitor the Battery Depassivation Instrument status lamps until the yellow lamp extinguishes and the green lamp begins to flash. Depassivation may take from several minutes to one hour.


CAUTION! If the green lamp doesn't flash within one hour of connecting the Battery Assembly, then the Battery Assembly is either excessively passivated or depleated and should not be used.

5. Disconnect the Battery Assembly from the Battery Depassivation Instrument. The Battery Assembly is now ready for immediate use.


Step 2: Program Instrument Tube Assembly.

<u>WARNING!</u> The Instrument Tube Assembly must NOT be programmed while connected to the Battery Assembly.

- Program the Mate from the PC with the probe configuration required or set up the
 configuration on the Mate manually. Refer to the CORRDATA Plus Corrosion Management
 Solutions Manual for details on setting up the Mate via PC (It is the recommended to
 CLEAR the Mate memory prior to programming, this WILL erase all previously saved data
 on the Mate). Follow the steps below to set up the Mate manually.
 - I. Turn the Mate **ON** and wait for the main display is shown below;



II. Click **SetUp** (F4) to advance to the **Configuration Options** display depicted below:



III. Choose **Mate** (F1) to enter the following **Mate Configuration** screen:

Mate Configuration

AUTO MAN NEW

CONF CONF PROBE EXIT

IV. Choose MAN CONF (F2) and enter the Manual Configuration screen below:

MANUAL CONFIGURATION

CONF SET CLR
ID TIME MEM EXIT

V. Choose CLR MEM (F3) and select CLEAR (F1) to clear the memory.

<u>WARNING!</u> This is the recommended method to successfully configure the DHT. Performing the CLEAR <u>WILL</u> erase all previously saved data on the Mate. Transfer needed data to CORRDATA Plus prior to erasing memory.

- VI. Once the previously stored settings are cleared, the Mate will return back to the **MANUAL CONFIGURATION** screen. Follow the instructions below to configure the Mate.
 - i. Choose **CONF ID** (F1) to proceed.
 - ii. Enter the ID number for the DHT and press Enter (F1).
 - iii. Enter the rest of the information such as the Probe Tag, the appropriate Time Interval for the DHT to perform readings, Probe Alloy and finish the setup process.

NOTE: A one (1) hour reading interval is most commonly used. The Probe Assembly type is **D** (cylindrical) with a 5 mil span for "T10" model or a 10 mil span for "T20" model and the probe is a **Corrotemp** type.


<u>CAUTION!</u> The minimum read time interval for the DHT is 15 minutes. User may set up the read time to 15 or 30 minutes, or 1, 2, or 4 hour increments. If an increment other than the above is chosen, the DHT will default the read time interval to the nearest valid time increment.

- VII. Check the setup configuration
 - I. From the main display of the Mate, press **Disp** (F2) followed by **ID** (F2).


- II. Type in the ID number and press **Enter** (F1).
- III. Check the configuration values to make the desired values are set.
- IV. Press the **More** F(1) check other values.
- 2. Set the Mate for a data rate of 300 BAUD by pressing: **Read** (F1); **MODE** (F2); **Baud** (F2); and **300** (F1). See Chapter 1 **CORRDATA Mate** section for more details.

NOTE: Communication between the Mate and the Instrument Tube Assembly occurs at 300 BAUD. This causes data transfer to be fairly slow. Configuration may take up to 30 seconds.

- 3. Connect the Mate to the DHT Communications Adapter.
- 4. Connect the Instrument Tube Assembly to the DHT Communications Adapter.
- 5. Program the Instrument Tube Assembly with the desired configuration by following the steps below:
 - I. Turn the Mate **ON** and wait for the main display is shown below;



II. Click **SetUp** (F4) to advance to the **Configuration Options** display depicted below:



III. Choose **RDC** (F2) to enter the following screen:

Enter ID# > < 1-50
ENTER CLR BkSp EXIT

IV. Enter the ID number from the above step 1 and press **Enter** (F1). The following display will appear.

RDC Configuration
Connect Mate to RDC

DATE CONF TEST
TIME RDC MODE EXIT

V. Choose **DATE TIME** (F1) and choose **SET** (F2). The hour is set on the military 24 hour clock, where 00.00 hours depict midnight at the start of the day and 12:00 is mid-day. See below for the display:

Set RDC Date & Time
YYMMDDHHMMSS
> <

ENTER CLR BkSp EXIT

<u>WARNING!</u> This will reset the DHT Date and Time and erase all the previously stored data on the DHT. This <u>MUST</u> be done to accurately date and time stamp the readings.

Set the time to be about ten minutes later than the present time (for reasons explained below) and press **ENTER** (F1). The date and time display that follows is an actual read-back of the values presently stored in the DHT Instrument.

NOTE: The Instrument Tube Assembly does NOT contain a real-time clock. Therefore, the date/time setting does NOT change with time. Instead, the date/time setting is purely a reference time to denote when the Instrument Tube Assembly actually begins recording data. Whenever the Battery Assembly is connected, the Instrument Tube Assembly collects readings at the programmed interval and time stamp the readings starting from the user programmed time. This is the reason for setting the time 10 minutes later than the present time, to let the user finish the rest of the steps and have enough time to begin the readings at the current time.

VI. Press **Exit** (F4) to return to the RDC Configuration screen. Choose **CONF RDC** (F2). Following display will appear:

Connect Mate to RDC - CO SET NEW START MUX PROBE EXIT

- VII. Press **START** (F1) to begin configuring the DHT. Press **EXIT** (F4) when the configuration is complete.
- 6. **Disconnect** the Instrument Tube Assembly and the Mate from the DHT Communications Adapter.
- 7. Turn off the Mate.

Step 3: Attach Probe Assembly to Instrument Tube Adapter.

- 1. Lay the Instrument Tube Assembly and the Probe Assembly on a table or other flat, horizontal surface.
- 2. Connect the Probe Assembly to the Instrument Tube Assembly by mating the connector end of the Probe Assembly to the large connector on the Instrument Tube Assembly.
- 3. Carefully rotate the Probe Assembly until the connector keys are aligned and then push in the connectors together as far as possible.

Step 4: Attach Battery Assembly to Instrument Tube Assembly.

<u>WARNING!</u> Always use a new Battery Assembly and depassivate immediately before use.

- 1. Maintain the Probe Assembly, Instrument Tube Assembly and the Battery Assembly on a table or other flat, horizontal surface.
- 2. When the present time is equal to the time value entered in Step 5 (sub-step V) above, slide the small connector on the Instrument Tube Assembly into the Battery Assembly connector as far as possible.
- 3. Once the Battery Assembly is connected to the Instrument Tube Assembly, it is energized and will take the first Probe Element reading after about 12 minutes, 30 seconds. This will be the first stored reading in the non-volatile memory. Next reading will commence at the specified interval from this reading. It is possible for the user to validate the performance of the DHT by using the Probe Monitoring Tool (see step below).

CAUTION! DHT can store a maximum of 1024 readings on its non-volatile memory. Once this limit is met, the DHT will not store anymore readings.

Step 5: Test DHT Operation with Probe Monitor.

Use the DHT Probe Monitor (P/N 724024) as described below to determine if the DHT is operational.

NOTE: Regardless of the preprogrammed time setting, the DHT will take the first Probe Element reading about 12 minutes, 30 seconds after the Battery Assembly is connected to the Instrument Tube Assembly. This allows sufficient time for final assembly of the DHT and attachment of the Probe Monitor to catch the first reading made by the Instrument Tube Assembly.

- 1. Connect the **RED** lead to the exposed metal surface of the Probe Element near the Probe Wrench-Flats.
- 2. Connect the **BLACK** lead to the exposed metal surface of the Probe Element near the probe tip. The best sensitivity is achieved when the BLACK and RED leads are spaced as far apart as possible while making positive electrical contact to the Probe Element.
- 3. Press the **ON** key. Wait for the display prompt "Ready to Test DHT"
- 4. Press the **CONFIG** key. If the cycle time, which is expressed in minutes, is correct, proceed to step 6.
- 5. If the cycle time is not correct, press the **EDIT** key followed by the **UP** and **DOWN** arrow keys to correctly program the cycle time. When the cycle time is correct, press the **EDIT** key again to store the reading (the old value will be lost) or press the **CONFIG** key to abort (no changes will occur).

NOTE: It is suggest setting the cycle time with few extra minutes compared to the actual reading interval to avoid and erroneous timeouts.

- 6. Press the **DISPLAY** key to determine how many measurements were made. This will be zero for initial use.
- 7. Press the **MEAS** key to initiate monitoring the Probe Element. It may be necessary to let the Probe Monitor warm up for a couple of minutes before performing measurements. The countdown timer will be activated, counting from the cycle time down toward zero. If zero is reached before a Probe Element measurement is detected, a time-out message is displayed.

- 8. Press any key to stop the measurement process. If the **MEAS** key is pressed again, the number of measurements will be initialized to zero and the measurement process will start over. If the **OFF** key is selected, the number of measurements will be saved to be viewed the next time the Probe Monitor is turned on.
- 9. When the DHT Probe Element is read, the display of the Probe Monitor will first show "CYCLE ONE", and shortly thereafter change to "CYCLE TWO" to account for the two energization cycles of one DHT Probe Element reading. Immediately following each Probe Element reading, the Probe Monitor will display the current tally of Probe Element readings (ie. "DHT = N", where N = the total number of Probe Element readings) and the countdown timer will be reset to its programmed value.

NOTE: A typical DHT Probe Element reading takes a total time period of about 4 minutes including a warm-up period and a post-processing period. Allow the Instrument Tube Assembly to operate long enough to collect the desired number of readings before proceeding with the Disassembly Sequence below.

Disassembly Sequence

Step 1: Remove Battery Assembly from Instrument Tube Assembly.

- 1. Maintain the Probe Assembly, Instrument Tube Assembly and Battery Assembly on a flat, horizontal surface.
- 2. **Disconnect** the Battery Assembly from the Instrument Tube Assembly.

NOTE: Due to the short duration of the pretest, the Battery Assembly can still considered "new" and should be saved for future use.

Step 2: Detach Probe Assembly from Instrument Tube Adapter.

1. **Disconnect** the Probe Assembly from the Instrument Tube Assembly by pulling the Probe Assembly connecter from the Instrument Tube Assembly.

Step 3: Read Data from Instrument Tube Assembly.

<u>WARNING!</u> Disconnect Battery Assembly prior to downloading Data from the Instrument Tube Assembly.

- 1. Turn on the Mate.
- 2. Clear the memory of the Mate. See **Chapter 3 Assembly Sequence <u>Step 2:</u> Program Instrument Tube Assembly** for more details on this procedure.

<u>WARNING!</u> This <u>WILL</u> erase all previously saved data on the Mate. Transfer needed data to CORRDATA Plus prior to erasing memory.

- 3. Set the Mate for a data rate of 300 BAUD by pressing: **Read** (F1); **MODE** (F2); **Baud** (F2); and **300** (F1). See Chapter 1 **CORRDATA Mate** section for more details.
- 4. Connect the Mate to the DHT Communications Adapter.
- 5. Connect the Instrument Tube Assembly to the DHT Communications Adapter.
- 6. Read data from the Instrument Tube Assembly by following the steps below:
 - I. Turn the Mate **ON** and wait for the main display is shown below;

ROHRBACK COSASCO SYSTEMS Read Disp Dump SetUp

II. Press Read (F1) to advance to the What to Read? display shown below:

What to Read?

PROBE MODE RDC EXIT

III. Choose **RDC** (F3) to enter the following screen:

Connect Mate to RDC
START EXIT

VIII. Press **START** (F1) to collect the data. When the data collection is completed, **EXIT** (F4) to return to the main display.

NOTE: Due to the low data communication rate, the Mate requires about 4 minutes to read data from the Instrument Tube Assembly.

- 7. Disconnect the Instrument Tube Assembly and the Mate from the DHT Communications Adapter. The number of readings taken and the value of the last reading may be read back directly from the Mate by using the Display Mode: **Disp** (F2), **CURR PROBE** (F1), for reading values; and **MORE** (F1) for number of readings.
- 8. To transfer data from the Mate to a personal computer, a "Mate to PC" interface cable (P/N 748063) and CORRDATA Plus software are required. Set the Mate to 9600 Baud for data transfer to the PC, by pressing: Read (F1); MODE (F2); Baud (F2); and 9600 (F3) (see Chapter 1 CORRDATA Mate section for more details). Follow the standard procedure for data transfer from the Mate to the PC.

NOTE: The data may now be downloaded to the CORRDATA Plus software to be viewed graphically to check its validity.

9. Turn off the Mate

Chapter 4 DHT Assembly

Recommended Tools

The DCMS Tool Kit (P/N: 724005) is required for the proper assembly set up, disassembly and data retrieval of the DHT.

<u>WARNING!</u> Use of tools other than those listed may result in damage to DHT components which may impact seal integrity, pressure rating, and accuracy. DO NOT hold any portion of the DHT with a vice or common pipe wrench!

The following tools are contained in the DCMS Tool Kit:

ITEM	QTY	UNIT	PART NUMBER	DESCRIPTION
1	1	EA	724101	Girtharip Pipewrench Assembly, 1,25" O.D.
2	1	EA	000490	Torque Wrench, 5 to 75 ft-lbs. " Drive
3	1	EA	000491	Torque Wrench. 100-600 ft-lbs. ¾" Drive
4	1	EA	000492	Crowfoot Wrench. 1". ½" Drive
5	1	EA	000493	Crowfoot Wrench. 1". " Drive
6	1	EA	000494	Crowfoot Wrench, 13/16", " Drive
7	1	EA	000466	Adapter. ¾" Female X ½" Male
8	1	EA	000495	Open End Wrench. 1"
9	1	EA	000496	Open End Wrench, 13/16"
10	1	EA	000497	Open End Wrench. "
11	1	EA	028050-8021-36.00	Cheater Bar. 36" Long (for open end wrench)
12	1	EA	660045-S31600-36.00	Cheater Bar. 36" Long (for girthgrip wrench)
13	1	EA	000498	Hex Kev Handle. 1/16"
14	1	SET	000499	Hex Kev Blade. 1/16"
15	1	SET	129341	O-rina Pick Set
16	1	EA	724100	DHT Tool Kit Case
17	1	EA	724020	DHT-to-MATE Communications Adapter
18	1	EA	724023	Battery Depassivation Instrument
19	1	EA	724024	Probe Monitor Instrument
20	1	EA	723101-5	CORRDATA MATE
21	1	EA	011422	MATE-to-RDC Adapter Cable

Assembly Sequence

Prior to assembly, be sure to thoroughly clean all threads (inner and outer) and O-ring grooves. The following Steps refer to the DHT Assembly Drawing of Figure 4.1.




Figure 4.1 DHT Assembly Drawing

<u>CAUTION!</u> Leave on the protective paper that covers the Probe Element until instructed to remove. This prevents grease from contaminating the Probe Element.

Step 1: Inspect Installation of O-Rings and Back-up Rings.

<u>WARNING!</u> To avoid damage to O-rings and O-ring grooves, only use an O-ring Pick Set to install or replace O-rings and Back-up Rings.

1. On the Mounting Head Adapter, there are two grooves between the fine threaded end and the wrench flats. A new O-ring and a new Back-up Ring must be placed in each groove before each downhole run. The Back-up Ring in each groove must be positioned nearest the threads, as shown in Figure 4.2.




Figure 4.2 Mounting Head Adapter O-Ring and Back-Up Ring Placement

<u>WARNING!</u> Never use O-Rings or Back-up Rings for more than one downhole run to prevent leakage and damage to the DHT internals. Make sure that O-Rings and Back-up rings are positioned as shown in FIGURE 4.2 for the Mounting Head Adapter and FIGURE 4.3 for the Probe Adapter.

2. In the Probe Adapter, there are two grooves between one threaded end and the wrench flats. A new O-ring and a new Back-up Ring must be placed in each groove before each downhole run. The Back-up Ring in each groove must be positioned nearest the threads, as shown in Figure 4.3.




Figure 4.3 Probe Adapter O-Ring and Back-Up Ring Placement

Step 2: Depassivate New Battery Assembly:

NOTE: The Battery Depassivation Instrument is used in this step. It automatically monitors the Battery Assembly output voltage while applying a nominal load. The Battery Depassivation Instrument will remove the load when the output voltage of the Battery Assembly reaches a value which indicates that the passivation has been adequately removed.

<u>WARNING!</u> Use only the RCS supplied Depassivation Instrument (P/N 724023) to depassivate the battery and verify voltage.

<u>WARNING!</u> A new Battery Assembly must be depassivated less than four hours prior to connecting it with the Instrument Tube Assembly. Refer to Chapter 1 and Appendix A for Battery Assembly warnings and cautions.

- 1. Verify that the ambient temperature and the Battery Assembly Temperature is greater than or equal to 21 °C (70 °F).
- 2. If desired, monitor the voltage between the red and black terminals on the Battery Depassivation Instrument with a high impedance voltmeter.
- 3. Connect the Battery Assembly to the Battery Depassivation Instrument. The yellow lamp will illuminate immediately. Depending on the degree of battery passivation, the battery voltage may initially drop below 5.0V.

CAUTION! If no status lamps on the Battery Depassivation Instrument are illuminated while the Battery Assembly is connected, then the Battery Assembly is either excessively passivated or depleated and should not be used.

 Monitor the Battery Depassivation Instrument status lamps until the yellow lamp extinguishes and the green lamp begins to flash. Depassivation may take from several minutes to one hour.

CAUTION! If the green lamp doesn't flash within one hour of connecting the Battery Assembly, then the Battery Assembly is either excessively passivated or depleated and should not be used.

Disconnect the Battery Assembly from the Battery Depassivation Instrument. The Battery Assembly is now ready for immediate use.

Step 3: Attach Probe Assembly to Probe Adapter. (See Figure 4.4)

CAUTION! Be careful not to get any lubricant on the Probe Element.

1. Check that the protective paper is over the Probe Element.




Figure 4.4 Probe Assembly Attached to Probe Adapter

- 2. Lubricate the entire Probe Sleeve with a thin coat of High-Temperature Silicone Grease (P/N128371).
- 3. Slide the threaded end of the Probe Assembly through the Probe Adapter, opposite the O-ring end.
- 4. Lubricate one Insulating Washer (P/N 724046) and one Load Washer (P/N 724045) with High-Temperature Silicone Grease.
- 5. Place the Insulating Washer over the threaded end of the Probe Assembly.
- 6. Place the Load Washer over the threaded end of the Probe Assembly.
- 7. Coat the Probe Assembly threads with High-Purity Goop (P/N 006308). This is an antigalling agent.
- 8. Install the Seal Loading Nut on the threaded end of the Probe Assembly.
- 9. Hold the flat portion of the Probe Assembly with a 5/8" open end wrench, then torque the Seal Loading Nut to 30 foot-pounds with a 13/16" open end torque wrench (30 lbs on a 12" wrench).

Step 4: Temporarily Install Probe Shield.


1. Check that the protective paper is over the Probe Element.

- 2. Verify that the Probe Shield Set Screws are backed out enough to clear the threads.
- 3. Carefully install the Probe Shield over the Probe Assembly and screw onto the Probe Adapter. It is not necessary to install the Probe Tip Insulator at this time.
- 4. Install the Probe Shield hand tight to protect the Probe Element during the following operations. **DO NOT** tighten either the Probe Shield or the Set Screws at this time.


Step 5: Program Instrument Tube Assembly.

<u>WARNING!</u> The Instrument Tube Assembly must NOT be programmed while connected to the Battery Assembly.

- Program the Mate from the PC with the probe configuration required or set up the
 configuration on the Mate manually. Refer to the CORRDATA Plus Corrosion Management
 Solutions Manual for details on setting up the Mate via PC (It is the recommended to
 CLEAR the Mate memory prior to programming, this WILL erase all previously saved data
 on the Mate). Follow the steps below to set up the Mate manually.
 - I. Turn the Mate **ON** and wait for the main display is shown below;



II. Click **SetUp** (F4) to advance to the **Configuration Options** display depicted below:



III. Choose **Mate** (F1) to enter the following **Mate Configuration** screen:

Mate Configuration

AUTO MAN NEW

CONF CONF PROBE EXIT

IV. Choose MAN CONF (F2) and enter the Manual Configuration screen below:

MANUAL CONFIGURATION

CONF SET CLR

ID TIME MEM EXIT

V. Choose **CLR MEM** (F3) and select **CLEAR** (F1) to clear the memory.

<u>WARNING!</u> This is the recommended method to successfully configure the DHT. Performing the CLEAR <u>WILL</u> erase all previously saved data on the Mate. Transfer needed data to CORRDATA Plus prior to erasing memory.

- VI. Once the previously stored settings are cleared, the Mate will return back to the **MANUAL CONFIGURATION** screen. Follow the instructions below to configure the Mate.
 - i. Choose **CONF ID** (F1) to proceed.
 - ii. Enter the ID number for the DHT and press Enter (F1).
 - iii. Enter the rest of the information such as the Probe Tag, the appropriate Time Interval for the DHT to perform readings, Probe Alloy and finish the setup process.


NOTE: A one (1) hour reading interval is most commonly used. The Probe Assembly type is **D** (cylindrical) with a 5 mil span for "T10" model or a 10 mil span for "T20" model and the probe is a **Corrotemp** type.

CAUTION! The minimum read time interval for the DHT is 15 minutes. User may set up the read time to 15 or 30 minutes, or 1, 2, or 4 hour increments. If an increment other than the above is chosen, the DHT will default the read time interval to the nearest valid time increment.


- VII. Check the setup configuration
 - I. From the main display of the Mate, press **Disp** (F2) followed by **ID** (F2).
 - II. Type in the ID number and press Enter (F1).
 - III. Check the configuration values to make the desired values are set.
 - IV. Press the **More** F(1) check other values.
- 2. Set the Mate for a data rate of 300 BAUD by pressing: **Read** (F1); **MODE** (F2); **Baud** (F2); and **300** (F1). See Chapter 1 **CORRDATA Mate** section for more details.

NOTE: Communication between the Mate and the Instrument Tube Assembly occurs at 300 BAUD. This causes data transfer to be fairly slow. Configuration may take up to 30 seconds.


- 3. Connect the Mate to the DHT Communications Adapter.
- 4. Connect the Instrument Tube Assembly to the DHT Communications Adapter.
- 5. Program the Instrument Tube Assembly with the desired configuration by following the steps below:
 - I. Turn the Mate **ON** and wait for the main display is shown below;



II. Click **SetUp** (F4) to advance to the **Configuration Options** display depicted below:



III. Choose **RDC** (F2) to enter the following screen:



IV. Enter the ID number from the above step 1 and press **Enter** (F1). The following display will appear.

RDC Configuration
Connect Mate to RDC

DATE CONF TEST TIME RDC MODE EXIT

V. Choose **DATE TIME** (F1) and choose **SET** (F2). The hour is set on the military 24 hour clock, where 00.00 hours depict midnight at the start of the day and 12:00 is midday. See below for the display:

Set RDC Date & Time
YYMMDDHHMMSS
> <

ENTER CLR BkSp EXIT

<u>WARNING!</u> This will reset the DHT Date and Time and erase all the previously stored data on the DHT. This <u>MUST</u> be done to accurately date and time stamp the readings.

Set the time to be about ten minutes later than the present time (for reasons explained below) and press **ENTER** (F1). The date and time display that follows is an actual read-back of the values presently stored in the DHT Instrument.

<u>NOTE:</u> The Instrument Tube Assembly does <u>NOT</u> contain a real-time clock. Therefore, the date/time setting does <u>NOT</u> change with time. Instead, the date/time setting is purely a reference time to denote when the Instrument Tube Assembly actually begins recording data. Whenever the Battery Assembly is connected, the Instrument Tube Assembly collects readings at the programmed interval and time stamp the readings starting from the user programmed time. This is the reason for setting the time 10 minutes later than the present time, to let the user finish the rest of the steps and have enough time to begin the readings at the current time.

VI. Press **Exit** (F4) to return to the RDC Configuration screen. Choose **CONF RDC** (F2). Following display will appear:

Connect Mate to RDC - CO

SET NEW
START MUX PROBE EXIT

VII. Press START (F1) to begin configuring the DHT. Press EXIT (F4) when the

configuration is complete.

- 6. **Disconnect** the Instrument Tube Assembly and the Mate from the DHT Communications Adapter.
- 7. Turn off the Mate.

Step 6: Attach Probe Assembly to Instrument Tube Assembly.

- 1. Verify that the Seal Loading Nut Set Screws are backed out enough to clear the connector opening.
- 2. Connect the Probe Assembly to the Instrument Tube Assembly by sliding the Seal Loading Nut end of the Probe Assembly over the large connector on the Instrument Tube Assembly.
- 3. Carefully rotate the Probe Assembly until the connector keys are aligned and then push the connectors together as far as possible.
- 4. Torque the Seal Loading Set Screws to 10 inch-pounds with a 1/16" Allen torque wrench, or as tight as a standard 1/16" Allen key will allow.

Step 7: Attach Battery Assembly to Instrument Tube Assembly.

<u>WARNING!</u> Always use a new Battery Assembly and depassivate immediately before use (Refer to Step 2 above). A battery that was used in a DHT Operational Pretest, as described in Chapter 3, is considered a "new" battery.

NOTE: Once the Battery Assembly is connected to the Instrument Tube Assembly, the Instrument Tube Assembly is energized and will take the first Probe Element reading after about 12 minutes, 30 seconds.

- 1. Lay the Instrument Tube Assembly and the Battery Assembly on a table or other flat, horizontal surface.
- 2. Coat the Probe Adapter threads, near the O-rings, with High-Purity Goop and the O-rings themselves, with High-Temperature Silicone Grease.
- 3. When the present time is equal to the preset time value entered in Step 5 above, immediately slide the small connector on the Instrument Tube Assembly into the Battery Assembly connector as far as possible.
- 4. Once the Battery Assembly is connected, the Instrument Tube Assembly is powered and will take its first Probe Element reading after about 12 minutes, 30 seconds.

Step 8: Place Instrument Tube Assembly / Battery Assembly into Instrument Body.

- 1. Lay the Instrument Body on the same flat, horizontal surface as the Instrument Tube / Battery Assembly.
- 2. If not already done, coat the Probe Adapter threads, near the O-rings, with High-Purity Goop and the O-rings themselves, with High-Temperature Silicone Grease.
- 3. Support the Battery Assembly to keep it in line with the Instrument Tube Assembly (to avoid connector damage), then carefully slide these two items into the Instrument Body.
- 4. Carefully screw the Probe Adapter into the Instrument Body, until shouldered, being careful not to lift the end so high that the Battery Assembly might become disconnected inside the Instrument Tube Assembly.
- 5. Maintain the whole assembly as horizontal as possible.

Step 9: Install Spring Assembly and Mounting Head Adapter.

- 1. Insert the Spring Assembly into the open end of the Instrument Body such that the outward end extends beyond the Instrument Body threads by no more than ¼". If the spring assembly extends further than this, check that the battery is still correctly engaged.
- 2. Coat the Mounting Head Adapter threads, near the O-rings, with High-Purity Goop and the O-rings themselves, with High-Temperature Silicone Grease.
- 3. Insert the Mounting Head Adapter behind the Spring Assembly.
- 4. Gently push the Mounting Head Adapter against the Spring Assembly and maintain pressure while starting to screw the Mounting Head Adapter into the Instrument Body. Once the threads have engaged, use a 1" open end wrench to tighten the Mounting Head Adapter until shouldered.

Step 10: Tighten Adapter Seals.

- 1. Use a girthgrip wrench to hold the Instrument Body.
- 2. With a 1" open end torque wrench, tighten the Probe Adapter into the Instrument Body to 175 ft-lbs torque minimum.
- 3. Use a 1" open end torque wrench to tighten the Mounting Head Adapter into the Instrument Body to 175 ft-lbs torque minimum.

Alternate Method

- 1. Place a 1" open end wrench on the Probe Adapter.
- 2. Place a 1" open end torque wrench on the Mounting Head adapter.
- 3. Tighten to 175 ft-lbs minimum.

Step 11: Remove Probe Shield.

- 1. Carefully remove the Probe Shield from the Probe Adapter.
- 2. Carefully remove the protective paper from the Probe Element.

Step 12: Test DHT Operation With Probe Monitor.

Use the DHT Probe Monitor (P/N 724024) as described below to determine if the DHT is operational.

NOTE: Regardless of the preprogrammed time setting, the DHT will take the first Probe Element reading about 12 minutes, 30 seconds after the Battery Assembly is connected to the Instrument Tube Assembly. This allows sufficient time for final assembly of the DHT and attachment of the Probe Monitor to catch the first reading made by the Instrument Tube Assembly.

- 1. Connect the **RED** lead to the exposed metal surface of the Probe Element near the Probe Wrench-Flats.
- 2. Connect the **BLACK** lead to the exposed metal surface of the Probe Element near the probe tip. The best sensitivity is achieved when the BLACK and RED leads are spaced as far apart as possible while making positive electrical contact to the Probe Element.
- 3. Press the **ON** key. Wait for the display prompt "Ready to Test DHT"
- 4. Press the **CONFIG** key. If the cycle time, which is expressed in minutes, is correct, proceed to step 6.
- If the cycle time is not correct, press the EDIT key followed by the UP and DOWN arrow keys to correctly program the cycle time. When the cycle time is correct, press the EDIT

key again to store the reading (the old value will be lost) or press the **CONFIG** key to abort (no changes will occur).

NOTE: It is suggest setting the cycle time with few extra minutes compared to the actual reading interval to avoid and erroneous timeouts.

- 6. Press the **DISPLAY** key to determine how many measurements were made. This will be zero for initial use.
- 7. Press the **MEAS** key to initiate monitoring the Probe Element. It may be necessary to let the Probe Monitor warm up for a couple of minutes before performing measurements. The countdown timer will be activated, counting from the cycle time down toward zero. If zero is reached before a Probe Element measurement is detected, a time-out message is displayed.
- 8. Press any key to stop the measurement process. If the **MEAS** key is pressed again, the number of measurements will be initialized to zero and the measurement process will start over. If the **OFF** key is selected, the number of measurements will be saved to be viewed the next time the Probe Monitor is turned on.
- 9. When the DHT Probe Element is read, the display of the Probe Monitor will first show "CYCLE ONE", and shortly thereafter change to "CYCLE TWO" to account for the two energization cycles of one DHT Probe Element reading. Immediately following each Probe Element reading, the Probe Monitor will display the current tally of Probe Element readings (ie. "DHT = N", where N = the total number of Probe Element readings) countdown timer will be reset to its programmed value.

Step 13: Install Probe Shield.

CAUTION! Do **NOT** handle or get any lubricant on the Probe Element.

- 1. Remove the protective paper from the Probe Element.
- 2. Install the Probe Tip Insulator on the tip of the Probe Element.
- 3. Coat the exposed threads of the Probe Adapter with High-Purity Goop.
- 4. Carefully install the Probe Shield over the Probe Assembly and screw onto the Probe Adapter.
- 5. Place a 1" open end torque wrench on the Probe Adapter and a girthgrip wrench on the Probe Shield.
- 6. Torque the Probe Shield to 30 ft-lbs.

- 7. Torque the Probe Shield Set Screws to 10 inch-pounds with a 1/16" Allen torque wrench or as tight as a standard 1/16" Allen key will allow.
- 8. The DHT is now ready to be attached to Cross-Flow adapter and tubing lock and run into the well.

Step 14: Attach DHT to Cross-Flow Adapter.

CAUTION! The DHT should only be attached to the running tools immediately prior to running into the well by wireline.

- 1. Attach the 5/8" API sucker rod connection on the DHT's Mounting Head Adapter to the Cross-Flow Adapter on the running tools immediately prior to running into the well.
- 2. Torque the connection to 175 ft-lbs minimum.

<u>WARNING!</u> During this time the temperature of the tool should be kept above 21°C (70°F).

Disassembly Sequence

Step 1: Detach DHT from Cross-Flow Adapter.

CAUTION! Clean the DHT thoroughly with an appropriate solvent prior to disassembly.

1. Detach the 5/8" API sucker rod connection on the DHT's Mounting Head Adapter from the Cross-Flow Adapter of the running tool immediately after removal from the well.

Step 2: Remove Mounting Head Adapter and Spring Assembly.

<u>WARNING!</u> Wear safety glasses, cover the joint, and carefully unscrew the Mounting Head Adapter during this step of disassembly in case any high pressure gas and/or liquid has been trapped in the Instrument Body while the DHT was downhole.

- 1. Use a girthgrip wrench to hold the Instrument Body.
- 2. With a 1" open end wrench, carefully remove the Mounting Head Adapter.
- 3. Remove the Spring Assembly, if possible. The Spring Assembly need not be removed at this time.

Step 3: Remove Instrument Tube Assembly / Battery Assembly from Instrument Body.

- 1. Lay the Instrument Body on a flat, horizontal surface.
- 2. Use a girthgrip wrench to hold the Instrument Body.
- 3. With a 1" open end wrench, remove the Probe Head Adapter from the Instrument Body.
- 4. Carefully slide the Instrument Tube Assembly / Battery Assembly completely out of the Instrument Body.
- 5. **Disconnect** the Battery Assembly from the Instrument Tube Assembly.
- 6. Mark the Battery Assembly with tape or a label to identify it as being "used" and handle in accordance with Appendix A of this manual.
- 7. Remove the Spring Assembly if not already done.

Step 4: Detach Probe Assembly from Instrument Tube Assembly.

- 1. Use a 1/16" Allen wrench to back out the Seal Loading Nut Set Screws enough to clear the connector opening.
- 2. **Disconnect** the Probe Assembly from the Instrument Tube Assembly by sliding the Seal Loading Nut end of the Probe Assembly away from the Instrument Tube Assembly.

Step 5: Read Data from Instrument Tube Assembly.

<u>WARNING!</u> Disconnect Battery Assembly prior to downloading Data from the Instrument Tube Assembly.

- 1. Turn on the Mate.
- 2. Clear the memory of the Mate. See Chapter 3 Assembly Sequence <u>Step 2:</u> Program Instrument Tube Assembly for more details on this procedure.
- 3. Set the Mate for a data rate of 300 BAUD by pressing: **Read** (F1); **MODE** (F2); **Baud** (F2); and **300** (F1). See Chapter 1 **CORRDATA Mate** section for more details.
- 4. Connect the Mate to the DHT Communications Adapter.

- 5. Connect the Instrument Tube Assembly to the DHT Communications Adapter.
- 6. Read data from the Instrument Tube Assembly by following the steps below:
 - I. Turn the Mate **ON** and wait for the main display is shown below;

ROHRBACK COSASCO SYSTEMS Read Disp Dump SetUp

II. Press Read (F1) to advance to the What to Read? display shown below:

What to Read?

PROBE MODE RDC EXIT

III. Choose **RDC** (F3) to enter the following screen:

Connect Mate to RDC
START EXIT

IV. Press **START** (F1) to collect the data. When the data collection is completed, **EXIT** (F4) to return to the main display.

NOTE: Due to the low data communication rate, the Mate requires about 4 minutes to read data from the Instrument Tube Assembly.

- 7. Disconnect the Instrument Tube Assembly and the Mate from the DHT Communications Adapter. The number of readings taken and the value of the last reading may be read back directly from the Mate by using the Display Mode: **Disp** (F2), **CURR PROBE** (F1), for reading values; and **MORE** (F1) for number of readings.
- 8. To transfer data from the Mate to a personal computer, a "Mate to PC" interface cable (P/N 748063) and CORRDATA Plus software are required. Set the Mate to 9600 Baud for data transfer to the PC, by pressing: **Read** (F1); **MODE** (F2); **Baud** (F2); and **9600** (F3) (see Chapter 1 **CORRDATA Mate** section for more details). Follow the standard procedure for data transfer from the Mate to the PC.

NOTE: The data may now be downloaded to the CORRDATA Plus software to be viewed graphically to check its validity.

9. Turn off the Mate.

Step 6: Remove Probe Shield.

- 1. Back out the Probe Shield Set Screws with a 1/16" Allen wrench so that they clear the threads of the Probe Adapter.
- 2. Place a 1" open end wrench on the Probe Adapter and a girthgrip wrench on the Probe Shield.
- 3. Carefully remove the Probe Shield from the Probe Adapter.
- 4. Remove the Probe Tip Insulator from the tip of the Probe Element.

CAUTION! A new Probe Tip Insulator should be fitted each time the Probe Shield is attached. A new Probe Tip Insulator is included as part of the Probe Assembly.

Step 7: Detach Probe Assembly from Probe Adapter.

- 1. Hold the flat portion of the Probe Assembly with a 5/8" open end wrench, then detach the Seal Loading Nut with a 13/16" open end wrench.
- 2. Remove and keep the Load Washer from the threaded end of the Probe Assembly.

<u>CAUTION!</u> To establish a reliable seal, a new Insulating Washer and Probe Sleeve must be used each time the Probe Assembly is attached to the Seal Loading Nut. Both Insulating Washer and Probe Sleeve are included as part of the Probe Assembly.

- 3. Remove and discard the Insulating Washer from the threaded end of the Probe Assembly.
- 4. Slide the Probe Assembly out of the Probe Adapter and keep for further analysis.

NOTE: The Probe Assembly is preweighed so that it may also be used as a "coupon". See the data supplied with the Probe Assembly for weight details. A serial number is marked on one of the Probe Assembly wrench flats as well as on the protective cardboard tube packaging.

Appendix A Lithium Thionyl Chloride Batteries: Handling, Storage, MSDS

Emergency Procedures

IN THE UNLIKELY EVENT OF VIOLENT BATTERY BEHAVIOR, the area should be evacuated immediately. Personnel should stay away from the area for 15 minutes rather than trying to correct the situation. Burning or fuming batteries should be left isolated until expert handling can correct the condition. Lithium fires should only be extinguished using "Lith-X" or a Class D fire extinguisher. The Material Safety Data Sheets for each cell of the DHT battery pack (2 cells per pack) as well as the main ingredient, Thionyl Chloride, are included in this section.

IN CASE OF LEAKAGE, leaking batteries should be isolated from all personnel and equipment. Since the electrolyte can be neutralized with common baking soda, leaking batteries should be placed in sealed plastic bags containing baking soda. The bags should be placed in a sealed drum with vermiculite. Personal protection devices should always be used around leaking batteries.

Emergency Conditions

Because of the high energy density inherent in lithium / thionyl chloride batteries, the potential for hazardous situations does exist. Most hazards are due to internal or external heating of a hermetically sealed battery. Overheating causes liquid electrolyte to expand, increasing hydrostatic pressure inside the can, which might cause the battery to burst. Further heating can cause the lithium anode to melt which, in turn, will react spontaneously with the electrolyte and bring about explosive behavior.

Causes of Hazardous Conditions- Electrical and Physical

Hazardous electrical conditions include recharging, short circuiting and forced discharging (voltage reversal). Battery Engineering, Inc.'s bobbin and moderate rate anode batteries are generally not capable of hazardous behavior unless external power is applied or they are short circuited at elevated temperatures.

Hazardous physical conditions include external heating due to uncontrolled storage,

incineration and physical destruction of the battery case via crushing, puncturing and disassembly. Excessive heating can cause explosive behavior with any type of battery. Physical destruction can result in leakage of toxic and highly corrosive electrolyte.

For further information about the safe handling and storage of lithium / thionyl chloride batteries, contact a Battery Engineering, Inc. Applications Engineer at 1-800-685-4844.

Safe Storage

Shelf

Batteries should be stored in their original shipping containers, if possible, to keep them isolated from each other, preventing connector damage and potential short circuits. Do not store batteries loosely, and do not place batteries on metal surfaces. Batteries should be stored on end with the connector end pointing upward.

Temperature and Environment

Batteries should be stored in a cool, dry, well-ventilated area with an optimal storage temperature range of 0-25°C. If prolonged storage is anticipated, batteries should be protected from excessive humidity.

Hazard Consideration

Lithium battery storage areas should be clearly marked and provided with "Lith-X" or a Class D fire extinguisher. Batteries may burst if subjected to excessive heating. In the event of fire only "Lith-X" or a Class D fire extinguishers should be used. DO NOT USE WATER, since water will cause exposed lithium to ignite. Signs should clearly state that water is not to be used in case of fire.

Safe Incoming Inspection

The proposed flow of batteries throughout the facility should be thoroughly reviewed by plant safety personnel to identify and eliminate potential sources of electrical and physical damage to the batteries. Conditions that can short circuit, recharge, over discharge, puncture, crush or overheat the batteries must be avoided, and all personnel involved in the handling should be properly trained.

Safe Testing

Physical dimensioning should be performed with all-plastic calipers and no electrical test should be performed without first consulting RCS engineering.

If testing batteries at elevated temperatures, the temperature chamber MUST HAVE reliable over temperature protection. DO NOT SHORT CIRCUIT batteries that are heated above 25°C. Batteries that have been heated above 100°C have been known to explode when short circuited for less than one minute.

NOTE: The batteries used in the DHT are custom built with an integral 1A safety fuse. The fuse will open the circuit if the battery is short circuited.

Safe Transportation

Because the shipping regulations are very complex, shippers of lithium batteries are urged to obtain copies of the 49 CFR (DOT regulations) and the IATA regulations. These regulations also explain how the paperwork is to be filled out.

All lithium/thionyl chloride batteries with a lithium content of greater than 0.5 grams and less than 12 grams are restricted, and they are subject to DOT (49 CFR) and International Air Transport Association (IATA) shipping regulations. Batteries that contain less than 0.5 grams lithium are unrestricted, and may be shipped by any means (ref. IATA section 4.5A45). Batteries with a lithium content of 12 grams must be individually approved by the governing authority, and cannot be shipped under these regulations.

NOTE: The Battery Assembly used in the DHT contains 7.4 grams of lithium when new.

The proper shipping name for lithium / thionyl chloride batteries is LITHIUM BATTERIES, LIQUID CATHODE (UN3090). The hazard class is CLASS 9 (Miscellaneous) and the packing group is PACKING GROUP II.

The regulations state that the batteries have to be separated to prevent external short circuits, and they have to be packed in inner fiberboard container (no more than 500 grams of lithium per inner container). The containers can then be packed with at least one inch of non-combustible packing material (such as vermiculite) separating each inner package in UN approved fiberboard boxes, steel drums, fiber drums, or wooden boxes. These packages have to be printed with a United Nations Marking Symbol (section 6.0 of IATA shipping regulations).

For cargo aircraft transportation, each package must have a gross weight no more than 35 kgs. A 24 hour emergency response number must be provided on the shipping papers in order to provide instructions if an emergency condition arises during transport. The batteries can be shipped by motor freight, rail freight, water, or Cargo Aircraft only. Lithium / thionyl chloride batteries cannot be carried aboard passenger-carrying aircraft. Boxes must be labeled with a MISCELLANEOUS (CLASS 9) label. If the batteries are to be shipped by air ,

then the package has to have a CARGO AIRCRAFT ONLY label attached. Also, boxes must be marked with the proper shipping name and the UN number near the shipping labels.

NOTE: Save the shipping packaging in which the batteries are received, since this packaging meets these requirements and may be re-used for returning batteries to RCS or a disposal facility.

Safe Disposal

Lithium / thionyl chloride batteries must be disposed of properly in accordance with 49 CFR. Lithium batteries for disposal are classified a WASTE LITHIUM BATTERIES FOR DISPOSAL, and they are shipped with the same regulations as those for new lithium / thionyl chloride batteries.

There is no long lasting contamination as a result of disposal of lithium / thionyl chloride batteries; there are only hazards associated with the neutralization and disposal process. The end products of lithium / thionyl chloride battery deactivation are not toxic, once neutralized. Lithium / thionyl chloride batteries should be disposed of by professional disposal companies. Contact Battery Engineering, Inc. for a recommendation of companies that can perform this disposal.

Because each state has different disposal regulations, contact your local environmental agency for instructions on how to dispose of lithium batteries.



MATERIAL SAFETY DATA SHEET

Battery Engineering, Inc.

Date Prepared: November 27, 1995

1636 Hyde Park Ave. Hyde Park MA 02136

Tel (617) 361-7555 Fax (617) 361-1835

24 Hour Emergency Telephone - (Chem-Tel) 1-800-255-3924

Section 1 - IDENTIFICATION

Product Name:

Hazardous Components (Approx %)

Thionyl Chloride

39.5 %

Aluminum Chloride

6.5%

Lithium Chloride

2%

LITHIUM THIONYL CHLORIDE CELL

25-102-180MR

Non-Hazardous Components (Approx %)

Stainless Steel 42.5% Nickel 0.4 % Paper 0.4 % Carbon 4.7%

Lithium Content: 4.7 grams

SECTION 2 - PHYSICAL / CHEMICAL CHARACTERISTICS

Boiling Point:

Thionyl Chloride: 77°C

Vapor Pressure:

Thionyl Chloride: 92mm @ 20°C

Vapor Density:

Thionyl Chloride: 4.1

Solubility in Water:

Thionyl Chloride: Decomposes Thionyl Chloride: 1.63

Specific Gravity: Melting Point:

Thionyl Chloride: -105°C

Evaporation Rate:

N/A

Water Reactive:

Thionyl Chloride hydrolyzes to form SO, and HCL

Appearance and Odor: Thionyl Chloride - Colorless to pale yellow; sharp, pungent odor.

SECTION 3 - FIRE AND EXPLOSION HAZARD DATA

Flash Point: N/A

Auto-Ignition Temp: N/A

Flammable Limits: N/A

Extinguisher Media: Dry Lithium Chloride, Graphite Powder, Pyrene G-1, Lith-X, Class D

Special Fire Fighting Procedures: Cover with dry lithium chloride, graphite powder, Lith-X powder or Class D fire extinguisher. DO NOT USE WATER, moist sand, carbon dioxide or soda ash extinguisher. Wear protective breathing apparatus.

Unusual Fire and Explosion Hazards: Do not short circuit, recharge, overdischarge, puncture, crush or expose to temperatures above 180°C.

SECTION 4 - REACTIVITY HAZARD DATA

Stability: Stable

Conditions to Avoid: Temperatures in excess of 180°C. High humidity for extended periods.

Incompatibility: N/A

Hazardous Decomposition Products: Sulfur Dioxide, Hydrogen Chloride

Hazardous Polymerization: Will not occur.

Other: N/A

SECTION 5 - HEALTH HAZARD DATA

Primary Routes of Entry: Inhalation. Carcinogen Listed in: Not listed.

Health Hazards: Acute - Vapors very irritating to skin, eyes, and mucous membranes.

Chronic - Overexposure can cause symptoms of nonfibrotic lung injury.

Signs and Symptoms of Exposure: Eye and mucous membrane irritation.

Medical Conditions Generally Aggravated by Exposure: Asthma, other respiratory disorders, skin allergies,

eczema.

Emergency First Aid Procedures: Seek medical assistance for further treatment.

Eye Contact: Flush with running water for at least 15 minutes. Hold eyelids apart. Seek immediate medical

treatment.

Skin Contact: Rinse with large amounts of running water. If burns develop, seek medical treatment.

Inhalation: Remove to fresh air. If breathing is difficult, administer oxygen and seek medical treatment.

Ingestion: Seek medical treatment.

SECTION 6 - CONTROL AND PROTECTIVE MEASURES

Respiratory Protection: Acid Gas Filter Mask. Protective Gloves: Butyl Rubber Gloves. Eye Protection: Chemical Worker Safety Glasses. Ventilation To Be Used: Local Exhaust.

Other Protective Clothing and Equipment: Chemical Laboratory Safety Glasses and Chemical Apron.

Hygienic Work Practices: N/A

SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be Taken if Material is Spilled or Released: Do not breathe vapors or touch liquid with bare hands. Waste Disposal Methods: Neutralize spill with soda lime, seal leaking battery and soda lime in plastic bag and dispose of as hazardous waste.

Precautions to be Taken in Handling and Storage: Do not short circuit or expose to temperatures above 180 °C. Do not recharge, overdischarge, puncture, or crush.

Other Precautions and/or Special Hazards: Do not store batteries in high humidity environments for long periods.

SECTION 8 - TRANSPORTATION INFORMATION

US DOT (per 49 CFR 172.101) and IATA/ICAO Proper Shipping Name: Lithium Batteries, Liquid Cathode.

UN Number: UN 3090

Hazard Classification: Class 9 (Miscellaneous)

Packing Group: II

Labels Required: MISCELLANEOUS Other: CARGO AIRCRAFT ONLY

Non-Hazardous Batteries (per IATA): If the batteries contain less than 0.5 gram of lithium (see front of MSDS),

they are not restricted for shipping purposes.

SECTION 9 - DISPOSAL INFORMATION

Proper Shipping Name: Waste Lithium Batteries

UN Number: UN 3090

Hazard Classification: Class 9 (Miscellaneous)

Packing Group: II

Labels Required: MISCELLANEOUS, HAZARDOUS WASTE

Waste Disposal Code: D003

Other: All lithium thionyl chloride batteries should be disposed of by a proper disposal facility.

Page 2 of Type: 25-102-180MR



MATERIAL SAFETY DATA SHEET

BAYER CORPORATION PRODUCT SAFETY & REGULATORY AFFAIRS 100 Bayer Road Pittsburgh, PA 15205-9741

TRANSPORTATION EMERGENCY

CALL CHEMTREC: (800) 424-9300 BAYER EMERGENCY PHONE...: (412) 923-1800

NON-TRANSPORTATION

DISTRICT OF COLUMBIA: (202) 483-7616 BAYER INFORMATION PHONE.: (800) 662-2927 _____

PRODUCT IDENTIFICATION:

PRODUCT NAME...... Thionyl Chloride

PRODUCT CODE..... v405

CHEMICAL NAME.....: Thionyl Chloride

SYMONYMS..... Sulfurous Oxychloride: Sulfur Oxychloride

CAS MUMBER..... 7719-09-7 FORMULA..... SOC12

II. HAZARDOUS INGREDIENTS:

INGREDIENT NAME

/CAS NUMBER

EXPOSURE LIMITS

CONCENTRATION (X)

minimum 99.6 %

Y Not Noted

Y Not Noted

Thionyl Chloride

7719-09-7

OSHA: 1.000 ppm Cailing

5.000 mg/m3 Coiling

ACGIH:

1.000 ppm Cailing 5.000 mg/m3 Cailing

------Hydrochloric Acid, Sulfur Dioxide, Chlorine and Sulfur Chloride may be released by hydrolysis or thermal decomposition of Thionyl Chloride and may be encountered when Thionyl Chloride comes in contact with moisture in the air.

Hydrochloric Acid

7647-01-0 OSMA :

5.000 ppm Ceiling

7.000 mg/m3 Cailing

ACGIH: 5.000 ppm Cailing 7.500 mg/m3 Cailing

Sulfur Dioxide

7446-09-5 OSHA:

2.000 ppm TWA

5.000 mg/m3 TWA

5.000 ppm STEL 10.000 mg/m3 STEL

ACCIDE:

2,000 ppm TWA 5.200 mg/m3 TWA

5.000 ppm STEL 13.000 mg/m3 STEL

Product Code: V405 Approval date: 11/08/95

MSDS Page 1 Continued on next page

INGREDIENT NA /CAS NUMBER	ME		
	EXPOS	SURE LIMITS	CONCENTRATION (1)
Chlorine			
7782-50-5	OSHA I	.500 pps TWA	I Not Noted
		1,500 mg/m3 TMA	
		1,000 ppm STEL	
		3,000 mg/m3 STEL	
	ACCUL	.500 ppm TMA	
		1.500 mg/m3 TWA	
		1.000 ppm STEL	
		2.900 mr/m3 STEL	
		The state of the s	
sulfur Chlorid			
10025-67-9	OSHA :	1,000 ppm Ceiling	I Not Noted
100000000000000000000000000000000000000		6.000 mg/m3 Ceiling	
	ACCURA	1.000 ppm Ceiling	
	MAY SHILL	5.500 mg/m3 Ceiling	
		J. Joo agras Certing	
	L PROPERT	ES:	
DOOR	20T	: Colorless to slightly yellow : Sharp, irritating : 119	4 () 4 ()
The Residence of the second		: Not Applicable	
MOILING POINT.		: Approx. 169 F (76 C)	
MOILING POINT.	ING POINT	1 Appres156 F (-104.5 C)	
MOILING POINT. MELTING/PREEZI VISCOSITY	ING POINT.	: Approx156 F (-104.5 C) : Approx. 0.6 mPas @ 77 F (25 C)	
MOILING POINT. MELTING/PREEZI VISCOSITY	ING POINT.	: Approx156 F (-104.5 C) : Approx. 0.6 mPas @ 77 F (25 C)	
SOILING POINT. MELTING/PREEZI VISCOSITY SOLUBILITY IN	MATER	: Approx156 F (-104.5 C) : Approx. 0.6 mPas @ 77 F (25 C)	
BOILING FOINT. MELTING/FREEZI VISCOSITY SOLUBILITY IN SPECIFIC GRAYI	MATER	: Approx156 F (-104.5 C) : Approx. 0.6 mPas @ 77 F (25 C) : Reacts : 1.64 @ 77 F (25 C)	
SOILING POINT. MELTING/PREEZI VISCOSITY SOLUBILITY IN SPECIFIC GRAYI MULK DENSITY	WATER	: Approx156 F (-104.5 C) : Approx. 0.6 mPas @ 77 F (25 C) : Reacts : 1.64 @ 77 F (25 C) : Not Established	
SOILING POINT. MELTING/FREEZI VISCOSITY SOLUBILITY IN SPECIFIC GRAYI BULK DENSITY I VOLATILE BY	MATER VOLUME	: Approx156 F (-104.5 C) : Approx. 0.6 mPas @ 77 F (25 C) : Reacts : 1.64 @ 77 F (25 C) : Not Established	
MOILING POINT. MELTING/PREEZ! PISCOSITY SOLUBILITY IN SPECIFIC GRAY: MULK DENSITY I VOLATILE BY PAPOR PRESSURE IV. FIRE AN	WATER ITY VOLUME	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C)	
MOILING POINT. MELTING/PREEZ! PISCOSITY SOLUBILITY IN SPECIFIC GRAY: MULK DENSITY I VOLATILE BY PAPOR PRESSURE IV. FIRE AN	WATER ITY VOLUME	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 wmHg @ 68 F (20 C)	
MOILING POINT. MELTING/PREEZI VISCOSITY MISCOSITY IN MICH DENSITY MICH DENSITY MICH DENSITY MAPOR PRESSURE IV. FIRE AN	WATER ITY VOLUME KD EXPLOSIV	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 wmHg @ 68 F (20 C) ON DATA:	
MOILING POINT. MELTING/FREEZI VISCOSITY MISCOSITY IN MOLETIC GRAY: MULK DENSITY I VOLATILE BY VAPOR PRESSURE IV. FIRE AN PLASH POINT MITO-IGNITION	WATER TO VOLUME KD EXPLOSIVE	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 wmHg @ 68 F (20 C) ON DATA:: Not Applicable. EC: Not Established.	
MOILING POINT. MELTING/FREEZI VISCOSITY MOLUBILITY IN SPECIFIC GRAYI MULK DENSITY I VOLATILE BY VAPOR PRESSURI IV. FIRE AN PLASH POINT MUTO-IGNITION EXTINGUISHING	WATER TO VOLUME TEMPERATUR MEDIA	: Approx156 F (-104.5 C): Approx. 0.6 mFas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 wmHg @ 68 F (20 C) ON DATA: Not Established: Not Established.	cal
MOILING POINT. MELTING/FREEZI VISCOSITY MOLUBILITY IN SPECIFIC GRAYI MULK DENSITY I VOLATILE BY VAPOR PRESSURI IV. FIRE AN PLASH POINT MUTO-IGNITION EXTINGUISHING	WATER TO VOLUME TEMPERATUR MEDIA	: Approx156 F (-104.5 C): Approx. 0.6 mFas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 wmHg @ 68 F (20 C) ON DATA: Not Established: Not Established.	cal
MOILING POINT. MELTING/FREEZI PISCOSITY MISCOSITY IN SPECIFIC GRAYI MULK DENSITY I WOLATILE BY MAPOR PRESSURE IV. FIRE AN PLASH POINT MITO-IGNITION EXTINGUISHING SPECIAL FIRE	WATER TO VOLUME TEMPERATUR NEDIA FIGHTING P	: Approx156 F (-104.5 C): Approx. 0.6 mFas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C) ON DATA: Not Established: Carbon Dioxide; Dry Chemicoccourses: Thionyl Chloride is not contents.	cal
MOTLING POINT. MELTING/FREEZI MISCOSITY MISCOSITY IN SPECIFIC GRAY: MULK DENSITY I WOLATILE BY MAPOR PRESSURE FLASH POINT MITO-IGNITION EXTINGUISHING SPECIAL FIRE IN HOWEVER, I	WATER TY VOLUME TEMPERATUR NEDIA FIGHTING P	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C) ON DATA: Not Established: KE: Not Established. ROCEDURES: Thionyl Chloride is not controlled is involved in a fire, use	cal ombustible. carbon dioxide or
MOTLING POINT. MELTING/FREEZI FISCOSITY FISCOSITY IN SOLUBILITY IN SPECIFIC GRAY: MULK DENSITY I WOLATILE BY MAPOR PRESSURE FLASH POINT AUTO-IGNITION EXTINGUISHING SPECIAL FIRE IN HOWEVER, in dry chemic	WATER TY VOLUME TEMPERATUR NEDIA FIGHTING PI	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 1001: Approx. 97 mmHg @ 68 F (20 C) ON DATA: ON DATA: Carbon Dioxide: Dry Chemi- ROCEDURES: Thionyl Chloride is not controlled is involved in a fire, use efighters should wear full protective	cal ombustible. carbon dioxide or e clothing includin
FLASH POINT VIASH POINT VIASH POINT VIASH POINT VIASH POINT AUTO-IGNITION EXTINGUISHING SPECIAL FIRE A HOWEVER, i dry chemic a self-com	WATER TY VOLUME TEMPERATUR NEDIA FIGHTING PI If thionyl tals. Fire	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C) ON DATA: ON DATA: Carbon Dioxide: Dry Chemi- ROCEDURES: Thionyl Chloride is not controlled is involved in a fire, use efighters should wear full protective eathing apparatus. Toxic and irrite	cal ombustible. carbon dioxide or e clothing includin ting gases may be
FLASH POINT FIRE AN FLASH POINT FULL BY FLASH POINT FLASH POINT AUTO-IGNITION EXTINGUISHING SPECIAL FIRE IN However, in dry chemic a self-compresent in	WATER WATER TY VOLUME. TEMPERATUR NEDIA. FIGHTING PI If thionyl tals. Fire	: Approx156 F (-104.5 C): Approx. 0.6 mFas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 1001: Approx. 97 mmHg @ 68 F (20 C) ON DATA: ON DATA: Carbon Dioxide: Dry Chemi- ROCEDURES: Thionyl Chloride is not controlled is involved in a fire, use efighters should wear full protective eathing apparatus. Toxic and irritarydrochloric soid, sulfur dioxide, ch	cal ombustible. carbon dinkide or e clothing includin ting gases may be lorine, sulfur
CILING POINT. GELTING/FREEZI VISCOSITY VISCOSITY IN INCLUBILITY IN INPECIFIC GRAYI WILK DENSITY I VOLATILE BY VAPOR PRESSURI IV. FIRE AN FLASH POINT WITO-IGNITION EXTINGUISHING SPECIAL FIRE IN However, in dry chemic a self-com present in chloride of	WATER TY VOLUME. TEMPERATUR NEDIA. FIGHTING PI If thionyl tals. Fire	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C) ON DATA: ON DATA: Carbon Dioxide: Dry Chemi- ROCEDURES: Thionyl Chloride is not controlled is involved in a fire, use efighters should wear full protective eathing apparatus. Toxic and irrite	cal ombustible. carbon dinmide or e clothing includin ting gases may be lorine, sulfur tures can runture
FLASH POINT FLASH POINT	TEMPERATURE PICTURE PI	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C) ON DATA: ON DATA: Carbon Dioxide: Dry Chemi- ROCEDURES: Thionyl Chloride is not controlled is involved in a fire, use efighters should wear full protective eathing apparatus. Toxic and irritarydrochloric soid, sulfur dioxide, ch Drums exposed to excessive tempera	cal ombustible. carbon dioxide or e clothing includin ting gases may be lorine, sulfur tures can rupture Il react with
FLASH POINT. AUTO-IGNITION EXTING/FREEZI FISCOSITY FOLUBILITY IN SOLUBILITY IN SPECIFIC GRAY: WILK DENSITY VAPOR PRESSURE IV. FIRE AN FLASH POINT AUTO-IGNITION EXTINGUISHING SPECIAL FIRE IN HOWEVER, in dry chemic a self-com present in chloride of	TEMPERATUR MEDIA FIGHTING PROTECTION OF CHARACTER P	: Approx156 F (-104.5 C): Approx. 0.6 mPas @ 77 F (25 C): Reacts: 1.64 @ 77 F (25 C): Not Established: 100%: Approx. 97 mmHg @ 68 F (20 C) ON DATA: On Dat	cal ombustible. carbon dioxide or e clothing includin ting gases may be lorine, sulfur tures can rupture

IV. FIRE AND EXPLOSION DATA (Continued)

thionyl chloride generating irritating gases. However, water spray should be used to keep fire exposed containers cool and to help scrub said gases from the air.

V. HUMAN HEALTH DATA:

ROUTE(S) OF ENTRY...... Eye Contact; Skin Contact; Inhalation

HUMAN EFFECTS AND SYMPTOMS OF OVEREXPOSURE:

ACUTE EFFECTS OF EXPOSURE.....: Direct contact with thionyl chloride can cause burns. It is corresive to the skin, eyes and mucous membranes. The vapors of thionyl chloride are strong irritants to the eyes and respiratory tract. Symptoms of exposure include a burning sensation in the eyes and violent coughing. In contact with humid air, hydrogen chloride (HC1) and sulfur dioxide (SO2) are produced which are themselves irritating. Significant overexposure to thionyl chloride vapors and its related decomposition products (which could occur if a person is trapped or sprayed) may cause delayed pulmonary edema.

CHRONIC EFFECTS OF EXPOSURE...: Chronic overexposure to thionyl chloride can cause symptoms of nonfibratic lung injury similar to other irritating vanors.

CARCINOGENICITY..... This product is not listed by NTP, IARC or regulated as a carcinogen by OSHA.

MEDICAL CONDITIONS

VI. EMERGENCY AND FIRST AID PROCEDURES:

FIRST AID FOR EYES.....: Immediately flush eyes with running water for at least 15 minutes. To assure thorough flushing of all eye tissue, the eyelids should be held apart during irrigation. Fernament eye injury can occur, particularly if rinsing is delayed. Immediately refer to a physician, preferably an eye specialist, for medical treatment.

PIRST AID FOR SKIN.....: Rinse immediately with large amounts of cool, running water. Avoid using hot water and hard rubbing. When splashed with thionyl chloride, immediately proceed to an emergency shower and begin removing all contaminated clothing while rinsing. Flushing the body with large amounts of water should continue until all of the thionyl chloride is removed. If the eyes are not contaminated, do not remove safety goggles to avoid washing thionyl chloride into the eyes. If contact is extensive or burns develop, a physician should be contacted immediately.

Product Code: V405 Approval date: 11/08/95 MSDS Page 3 Continued on next page

VI. FIRST AID PROCEDURES (Continued)

FIRST AID FOR INHALATION: Remove to fresh air. Keep person calm and avoid any unnecessary exertion or movement. Trained persons should administer exygen if breathing is difficult. If not breathing, give artificial respiration. Immediately contact a physician.

FIRST AID FOR INGESTION.: In case of ingestion, drink copious amounts of water (if available, give several glasses of milk). Do not induce vomiting. NEVER GIVE ANYTHING BY MOUTH TO AN UNCONSCIOUS PERSON. If vomiting occurs spentaneously, keep airway clear and give more water. Immediately call a physician.

VII. EMPLOYEE PROTECTION RECOMMENDATIONS:

EYE PROTECTION REQUIREMENTS.....: Chemical worker safety glasses and full face shield.

SKIN PROTECTION REQUIREMENTS.....: Neoprene, PVC, Polyethylene or Viton (R) gloves, boots and aprons as appropriate for exposure conditions.

RESPIRATOR REQUIREMENTS...... NIOSH approved for soid gases. Do not exceed the use limits of the respirator.

VENTILATION REQUIREMENTS...... Use local exhaust or general room ventilation sufficient to prevent overexposure.

ADDITIONAL PROTECTIVE MEASURES.....: Full body acid resistant suits and positive pressure, self-contained breathing apparatus should be available in case of large spills or other similar emergencies. Emergency showers and eyewash fountains should be located in areas where thionyl chloride is handled. Educate and train employees in the safe use and handling of this product.

VIII. REACTIVITY DATA:

STABILITY..... This is a stable material.

HAZARDOUS POLYMERIZATION ...: Will not occur.

INCOMPATIBILITIES..........: Reacts violently with water. Avoid contact with reducing agents and organic matter. May react vigorously with Antimony, Sedium, Aluminum, Magnesium and Titanium. Iron and Zinc may catalyze violent reactions of Thionyl Chloride mixtures with organic chemicals. Thionyl Chloride mixtures with organic chemicals must be stored in containers free of iron and zinc and must be equipped with a pressure relief device. Refer to Section X (special precautions & storage data).

INSTABILITY CONDITIONS....: Excessive temperatures.

DECOMPOSITION TEMPERATURE..: Decomposition begins at 284 F (140 C).

DECOMPOSITION PRODUCTS.....: By thermal decomposition: Chlorine, Sulfur Dioxide, Sulfur Chloride. In contact with water: Hydrochloric Acid, Sulfur Dioxide.

Product Code: V405 Approval date: 11/08/95

MSDS Page 4 Continued on next page

IX. SPILL AND LEAK PROCEDURES:

SPILL OR LEAK PROCEDURES....: Evacuate area and stay upwind. If it is safe to do so, trained personnel should attempt to stop or reduce loak. Large spills should be contained and pumped into salvage drums or other appropriate containers. Full acid resistant suits and self-contained breathing apparatus should be worn during emergency operations. Vapor clouds formed by reaction of the spilled thionyl chloride with atmospheric moisture can be controlled by water fog or water spray. After bulk of material is removed, large quantities of soda ash, lime or a combination of these can be used to soak up and neutralize the remaining thionyl chloride. Small spills can be handled by absorption and reacted with large amounts of dry alkali (soda ash and/or lime). Shovel into appropriate container for disposal.

WASTE DISPOSAL METHOD......: Maste disposal must be in accordance with federal, state and local environment control regulations.

X. SPECIAL PRECAUTIONS & STORAGE DATA:

STORAGE TEMPERATURE (MIN/MAX): Ambient/122 F (50 C).

SHELF LIFE..... Unlimited in closed containers and in the absence of moisture. In drums - one year maximum.

XI. SHIPPING INFORMATION:

TECHNICAL SHIPPING NAME.....: Thionyl Chloride FREIGHT CLASS BULK.....: Thionyl Chloride PREIGHT CLASS PACKAGE.....: Thionyl Chloride PRODUCT LABEL.....: Thionyl Chloride

Product Code: V405 Approval date: 11/08/95

MSDS Page 5 Continued on next page

SHIPPING INFORMATION (Continued) XI. ______

DOT (DOMESTIC SURFACE)

PROPER SHIPPING NAME..... Thionyl Chloride HAZARD CLASS OR DIVISION: 8: 6.1 UN/NA NUMBER..... UN1836 PACKAGING GROUP PG I DOT PRODUCT RQ 1bs (kgs).....: None HAZARD LABEL(s)..... Corresive; Poison HAZARD PLACARD(s)..... Corresive; Poison

INO / INDG CODE (OCEAN)

PROPER SHIPPING NAME..... Thiomyl Chloride HAZARD CLASS DIVISION NUMBER...: 8 UN NUMBER..... UN1836 PACKAGING GROUP..... I HAZARD LABEL(s)..... Corresive; Toxic HAZARD PLACARD(s)..... Corrosive; Toxic

ICAO / IATA (AIR)

HAZARD CLASS DIVISION NUMBER...: Forbidden

ANIMAL TOXICITY DATA:

TOXICITY DATA FOR: Thionyl Chloride

ACUTE TOXICITY

ORAL LD50..... Bata not established for product. DERMAL LD50.....: Data not established for product. IMHALATION LC50....: 1,274 ppm (Rat - 1 hour); 558 ppm (Rat - 4 hour). (1); 736 ppm (Rat - 1 hour). (2) - EYE EFFECIS..... Corrosive

SKIN EFFECTS..... Corrosive

SENSITIZATION....: Data not established for product. SUBCHRONIC TOXICITY...: Data not established for product. CHRONIC TOXICITY.....: Data not established for product. OTHER TOXICITY DATA...: (Mutagenic, Teratogenic, Reproductive Tests): Data not established for product. AQUATIC TOXICITY.....: Do not allow to enter waters, wastewater or soil.

- 1 Tests conducted at the Institute for Toxicology of Bayer AG.
- 2 Bushy Run Research Center, October, 1993.

Product Code: V405 Approval date: 11/08/95

MSDS Page 6 Continued on next page PEDERAL RECULATORY INFORMATION:

OSHA STATUS...... This product is hazardous under the criteria of

the Federal OSHA Hazard Communication Standard 29

CFR 1910.1200.

TSCA STATUS..... On TSCA Inventory

CERCLA REPORTABLE QUANTITY ..: Nome.

SARA TITLE III:

SECTION 302 EXTREMELY

HAZARDOUS SUBSTANCES..: Nome.

SECTION 311/312

HAZARD CATEGORIES.....; Immediate Health Hazard; Delayed Health Hazard;

Reactive Hagard

SECTION 313

TOXIC CHEMICALS.....: Nome.

RCRA STATUS..... then discarded in its purchased form, this

product meet the criteria of corrosivity (EPA Hazardous Waste Number D002) and reactivity (EPA

Hagardous Waste Number D003) under 40 CFR

(261, 20-24).

OTHER REGULATORY INFORMATION: XIV.

The following chemicals are specifically listed by individual states; other product specific health and safety data in other sections of the MSDS may also be applicable for state requirements. For details on your regulatory. requirements you should contact the appropriate agency in your state.

COMPONENT NAME

/CAS NUMBER

CONCENTRATION STATE CODE

Thionyl Chloride

7719-09-7 minimum 99.6 % PA1, MA, NJ3

MA - Massachusetts Hagardous Substance List

NJ3 - New Jersey Special Health Hazardous Substance List

PA1 - Pennsylvania Hagardous Substance List

CALIFORNIA PROPOSITION 65

To the best of our knowledge, this product contains no levels of listed substances, which the state of California has found to cause cancer, birth defects or other reproductive effects.

Product Code: V405 Approval date: 11/08/95

MSDS Page 7 Continued on next page

XV. APPROVALS:

REASON FOR ISSUE...... Revise Sections XI, XII (IMO) and XIV

PREPARED BY..... D. P. Kelly
APPROVED BY..... J. M. Mostowy
APPROVAL DATE...... 11/08/95
SUPERSEDES DATE...... 09/28/93
MSDS MUMBER..... 01987

This information is furnished without warranty, expressed or implied, except that it is accurate to the best knowledge of Bayer Corporation. The data on this sheet relates only to the specific material designated herein. Bayer Corporation assumes no legal responsibility for use or reliance upon these data.

Product Code: V405 Approval date: 11/08/95

MSDS Page 8 Last page